

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2870
SCHOOL NAME: Brighton Park School
ADDRESS OF SCHOOL: 3825 S. Washtenaw
CITY: Chicago, IL, 60632

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 9/22/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 3/20/2025 ENROLLMENT 306
IDPH INSPECTOR LICENSE NUMBER: 100-20751
IDPH LICENSED INSPECTOR NAME (Please Print): Daniel Akim
IDPH MP LICENSE NUMBER: 100-20634
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jackson Montgomery

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 4/18/2025

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Brighton Park School

3825 S. Washtenaw
Chicago, IL, 60632

Unit: 26451
Building ID: 7470

IDPH ID Number: 14-016-2990-2870

REPORT DATE:
Friday, April 18, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

04/18/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 26451 Region: 04 IDPH ID: 14-016-2990-2870

School: Brighton Park School Building ID: 7470

Address: 3825 S. Washtenaw

Chicago, IL, 60632

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date: 3/20/2025

Review Date: 04/18/2025

Inspector: Daniel Akim

Inspector IDPH License: 100-20751

Management Planner: Jackson Montgomery

Management Planner IDPH License: 100-20634

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Jackson Montgomery
100-20634

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: April 18, 2025

RE: Brighton Park School, Unit 26451
3825 S. Washtenaw
Chicago, IL, 60632

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Brighton Park School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Brighton Park School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Brighton Park School Unit: 26451 Region: 04
Address: 3825 S. Washtenaw Chicago, IL, 60632
IDPH ID: 14-016-2990-2870 Building ID: 7470
Contact: Phone:

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: No of Floors:
Current Occupancy: 306

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Daniel Akim

Inspector IDPH license # 100-20751 Signature:
Reinspection Date: 3/20/2025 Date: 3/20/2025

6. Management Planner

Management Planner Name: Jackson Montgomery

Management Planner IDPH license # 100-20634

Jackson Montgomery
Signature:
Date: 04/18/2025

7. Review Date: 04/18/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Richard J. Schleyer
Signature: Date: 4/18/2025

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Brighton Park School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 7470:

1	2' x 4' Ceiling Panels
14	12" x 12" Light Brown/Off-White Floor Tile
16	12" x 12" Light Brown/Off-White Floor Tile Mastic
19	Insulation Inside Of Fire Door
20	Drywall
26	1" x 1" White Ceramic Wall Tile Grout
52	Exterior Brick - Non-AHERA
57	12" x 12" White w/ Blue and Yellow Floor Tile Mastic
59	12" x 12" Blue Floor Tile Mastic

61	12" x 12" Yellow Floor Tile Mastic
65	12" x 12" Brown Floor Tile Mastic
67	12" x 12" Beige Floor Tile Mastic
69	Floor Tile Beneath 12" x 12" Floor Tile
70	Floor Tile Beneath 12" x 12" Floor Tile Mastic
72	2' x 4' Ceiling Panels
74	Drywall
75	Drywall Compound
77	12" x 12" Aqua Floor Tile
78	12" x 12" Aqua Floor Tile Mastic
79	12" x 12" Beige Floor Tile
80	12" x 12" Beige Floor Tile Mastic
81	4" Green Vinyl Baseboard
82	4" Green Vinyl Baseboard Adhesive
83	Spray on Insulation
84	Vibration Collars
85	Chalk Board/Marker Board Adhesive
86	Chalk Board/Marker Board Adhesive
87	Core in Green Pads
88	2' x 4' Smooth Ceiling Panels
89	12" x 12" Green and White Floor Tile
90	12" x 12" Green and White Floor Tile Mastic
91	Beige Marbled Vinyl Flooring
92	Blue Textured Vinyl Flooring

- 93 12" x 12" Gray Mottled Floor Tile
- 94 12" x 12" Gray Mottled Floor Tile Mastic
- 95 1' x 1' Pinhole & Gouges Ceiling Tile
- F Aircell Lag

B. The following new homogenous areas have been identified for Building 7470:

- 95 1' x 1' Pinhole & Gouges Ceiling Tile
- 96 2' x 4' Pinhole Ceiling Tile (Replacement Tiles)
- 97 12" x 12" Peach w/ White Streaks (Replacement Tile)

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

14	12" x 12" Light Brown/Off-White Floor Tile
19	Insulation Inside Of Fire Door
23	12" x 12" Floor Tile
24	12" x 12" Floor Tile Mastic
4	4" x 4" Red and Black Floor Tile
5	4' x 10' Ceiling Panels
51	Pegboard
56	12" x 12" White w/ Blue, Red, & Yellow Floor Tile
58	12" x 12" Blue Floor Tile
60	12" x 12" Yellow Floor Tile
64	12" x 12" Brown Floor Tile
66	12" x 12" Beige Floor Tile
68	2' x 4' Lay-in Ceiling Panels
69	Floor Tile Beneath 12" x 12" Floor Tile
70	Floor Tile Beneath 12" x 12" Floor Tile Mastic
71	Blue Carpet Adhesive
72	2' x 4' Ceiling Panels
73	Green Carpet Adhesive
74	Drywall
75	Drywall Compound
76	Sink Undercoat
77	12" x 12" Aqua Floor Tile
78	12" x 12" Aqua Floor Tile Mastic
79	12" x 12" Beige Floor Tile
80	12" x 12" Beige Floor Tile Mastic
81	4" Green Vinyl Baseboard
82	4" Green Vinyl Baseboard Adhesive
83	Spray on Insulation
84	Vibration Collars
85	Chalk Board/Marker Board Adhesive
86	Chalk Board/Marker Board Adhesive
87	Core in Green Pads
88	2' x 4' Smooth Ceiling Panels
89	12" x 12" Green and White Floor Tile
90	12" x 12" Green and White Floor Tile Mastic
91	Beige Marbled Vinyl Flooring
92	Blue Textured Vinyl Flooring
93	12" x 12" Gray Mottled Floor Tile
94	12" x 12" Gray Mottled Floor Tile Mastic
95	1' x 1' Pinhole & Gouges Ceiling Tile
96	2' x 4' Pinhole Ceiling Tile (Replacement Tiles)
97	12" x 12" Peach w/ White Streaks (Replacement

A

Tile)
Boiler Lag

The following areas were deemed to be inaccessible:

16	12" x 12" Light Brown/Off-White Floor Tile Mastic
19	Insulation Inside Of Fire Door
69	Floor Tile Beneath 12" x 12" Floor Tile
70	Floor Tile Beneath 12" x 12" Floor Tile Mastic
78	12" x 12" Aqua Floor Tile Mastic
80	12" x 12" Beige Floor Tile Mastic
82	4" Green Vinyl Baseboard Adhesive
85	Chalk Board/Marker Board Adhesive
86	Chalk Board/Marker Board Adhesive
90	12" x 12" Green and White Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Daniel Akim, IDPH License # 100-20751. The Management Plan was updated by Jackson Montgomery, IDPH License # 100-20634. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Brighton Park School Building 7470 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Brighton Park School **Unit** 26451 **Building ID** 7470
Address 3825 S. Washtenaw **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	2' x 4' Ceiling Panels			Classrooms of Original Building	NO_ACBM	MISC					Yes			
14	12" x 12" Light Brown/Off-White Floor Tile	4,000	SF	Hallways, and Office	ASSUMED	MISC	N	NONE			Yes	ACBM with potential for significant damage		LOW
16	12" x 12" Light Brown/Off-White Floor Tile Mastic	4,000	SF	Hallways, and Office	CHR	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
19	Insulation Inside Of Fire Door	35	SF	Boiler Room	ASSUMED	TSI	N	NONE			Yes	ACBM with the potential for damage		LOW
2	1' x 1' Ceiling Tiles			Classrooms and Hallways of Original Building	NO_ACBM	MISC					No			
20	Drywall			Classrooms	NO_ACBM	MISC					Yes			
22	Transite Panels	500	SF	Behind Grills On Both Sides of Gym	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
23	12" x 12" Floor Tile			Entrance Foyer of Gym Building	ASSUMED	MISC								
24	12" x 12" Floor Tile Mastic			Entrance Foyer of Gym Building	ASSUMED	MISC								
25	Floor Tile Mastic			ABATED	ABATED	MISC								
26	1" x 1" White Ceramic Wall Tile Grout			Girls Gym Bathroom	NO_ACBM	MISC					Yes			
27	1" x 1" Light Brown Ceramic Floor Tile Grout			Girls Gym Bathroom	NO_ACBM	MISC					No			
28	1" x 1" Brown Ceramic Floor Tile Grout			Boys Gym Bathroom	NO_ACBM	MISC					No			
29	Ceramic Wall Tile Grout			Boys Gym Bathroom	NO_ACBM	MISC					No			
30	Terrazzo Flooring			Landing Between Bathrooms by Gym, Addition Corridors, 3rd Floor Bathrooms 2001 Addition,	NO_ACBM	MISC					No			
31	2' x 4' Lay-in Ceiling Panels			Girls and Boys Gym Bathrooms	NO_ACBM	MISC					No			
32	Interior Brick			Gym	NO_ACBM	MISC					No			
33	Interior Brick Mortar			Gym	NO_ACBM	MISC					No			
34	Block			Gym	NO_ACBM	MISC					No			
35	Block Mortar			Gym	NO_ACBM	MISC					No			
36	Cementitious Patching Material			Boys Gym Bathroom Vestibule Windows	NO_ACBM	MISC					No			
37	Window Grout			Bleachers in Gym	NO_ACBM	MISC					No			
38	Green Wall Tile Caulk			Girls and Boys Bathrooms- Original	NO_ACBM	MISC					No			

Chicago Public Schools

School Brighton Park School **Unit** 26451 **Building ID** 7470
Address 3825 S. Washtenaw **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Building										
39	Green Terrazzo Flooring			Girls and Boys Bathrooms- Original Building	NO_ACBM	MISC					No			
4	4" x 4" Red and Black Floor Tile			Girls and Boys Bathrooms - Gym Building	ASSUMED	MISC								
40	Wall Tile Adhesive			Girls and Boys Bathrooms- Original Building	NO_ACBM	MISC					No			
41	1' x 1' Ceiling Tiles Adhesive			Throughout Original Building	NO_ACBM	MISC					No			
42	Terrazzo			Stairways and Landings in Original Building	NO_ACBM	MISC					No			
43	Interior Brick			Throughout Original Building	NO_ACBM	MISC					No			
44	Interior Brick Mortar			Throughout Original Building	NO_ACBM	MISC					No			
45	Terrazzo Wall Panels			Girls Bathroom- Original Building	NO_ACBM	MISC					No			
46	Gray Baseboard			Rooms 106, 107, 108	NO_ACBM	MISC					No			
47	Gray Baseboard Mastic			Rooms 106, 107, 108	NO_ACBM	MISC					No			
48	Brown Baseboard			Rooms 110, 111, 204 & 205	NO_ACBM	MISC					No			
49	Brown Baseboard Mastic			Rooms 110, 111, 204 & 205	NO_ACBM	MISC					No			
5	4' x 10' Ceiling Panels			Gym	ASSUMED	MISC								
50	Ceiling Material			Garage	NO_ACBM	MISC					No			
51	Pegboard			Room 211	ASSUMED	MISC								
52	Exterior Brick - Non-AHERA			Original Building	NO_ACBM	MISC					Yes			
53	Exterior Brick Mortar - Non-AHERA			Original Building	NO_ACBM	MISC					No			
54	Exterior Door Grout - Non-AHERA			Original Building	NO_ACBM	MISC					No			
55	Fire Block			Basement Stairs	NO_ACBM	MISC					No			
56	12" x 12" White w/ Blue, Red, & Yellow Floor Tile	2,000	SF	Library, Entrance Women's Library, Multi-purpose Room & Entrance	ASSUMED	MISC	N	NONE			No	ACBM with potential for significant damage		LOW
57	12" x 12" White w/ Blue and Yellow Floor Tile Mastic			Library, Entrance Women's Library, Multi-purpose Room & Entrance	NO_ACBM	MISC					Yes			

Chicago Public Schools

School Brighton Park School **Unit** 26451 **Building ID** 7470
Address 3825 S. Washtenaw **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
58	12" x 12" Blue Floor Tile	2,000	SF	Library,145	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
59	12" x 12" Blue Floor Tile Mastic			Library 145	NO_ACBM	MISC					Yes			
60	12" x 12" Yellow Floor Tile	2,500	SF	Cafeteria	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
61	12" x 12" Yellow Floor Tile Mastic			Library	NO_ACBM	MISC					Yes			
62	4" Blue Vinyl Baseboard			Library	NO_ACBM	MISC					No			
63	4" Blue Vinyl Baseboard Adhesive			Library	NO_ACBM	MISC					No			
64	12" x 12" Brown Floor Tile	4,500	SF	Classrooms - Original Building With the Exception of 224 & 225	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
65	12" x 12" Brown Floor Tile Mastic			Classrooms - Original Building With the Exception of 224 & 225	NO_ACBM	MISC					Yes			
66	12" x 12" Beige Floor Tile	4,500	SF	Classrooms-Original Building With the Exception of 224 & 225,	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
67	12" x 12" Beige Floor Tile Mastic			Classrooms - Original Building With the Exception of 224 & 225	NO_ACBM	MISC					Yes			
68	2' x 4' Lay-in Ceiling Panels	544	SF	Rear Room in Library, Kitchen	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
69	Floor Tile Beneath 12" x 12" Floor Tile	9,400	SF	All Rooms of Original Building Except Rooms 224 and 225	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
70	Floor Tile Beneath 12" x 12" Floor Tile Mastic	9,400	SF	All Rooms of Original Building Except Rooms 224 and 225	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
71	Blue Carpet Adhesive			Room 229	ASSUMED	MISC								
72	2' x 4' Ceiling Panels	24,250	SF	Rooms 224, 225, & the 2001 Addition Classrooms and Corridors	ASSUMED	MISC	Y	LOC	8	SF	Yes	Damaged or significantly damaged friable misc. ACBM	9	LOW
73	Green Carpet Adhesive			2001 Addition, Office, Rooms 105, 107, 109, 111, 205	ASSUMED	MISC								
74	Drywall	25,000	SF	2001 Addition	ASSUMED	MISC	Y	NONE			Yes	Any remaining friable		LOW

Chicago Public Schools

School Brighton Park School **Unit** 26451 **Building ID** 7470
Address 3825 S. Washtenaw **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
											ACBM or friable suspect ACBM			
75	Drywall Compound	25,000	SF	2001 Addition	ASSUMED	MISC	Y	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
76	Sink Undercoat			Office, Room 101	ASSUMED	SURFACE								
77	12" x 12" Aqua Floor Tile	9,507	SF	2001 Addition Classrooms, 208 Storage, Addition Gym Office, 215 MDF Room, 137, Cafeteria, 130	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
78	12" x 12" Aqua Floor Tile Mastic	9,532	SF	2001 Addition Classrooms, 205, 208 Storage Addition Gym Office, 215 MDF Room 137, Cafeteria	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
79	12" x 12" Beige Floor Tile	12,447	SF	2001 Addition Classrooms, 208 Storage, Addition Gym Office, 215 MDF Room, 137, Cafeteria	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
80	12" x 12" Beige Floor Tile Mastic	12,447	SF	2001 Addition Classrooms, 208 Storage Addition Gym Office, 215 MDF Room, 137, Cafeteria	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
81	4" Green Vinyl Baseboard	1,300	LF	2001 Addition	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
82	4" Green Vinyl Baseboard Adhesive	1,300	LF	2001 Addition	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
83	Spray on Insulation	12,000	SF	2001 Addition, 215 MDF Room, 133 Electrical Room	ASSUMED	TSI	Y	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
84	Vibration Collars	100	LF	2001 Addition	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
85	Chalk Board/Marker Board Adhesive	2,000	SF	Original Building	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
86	Chalk Board/Marker Board Adhesive	2,400	SF	2001 Addition	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
87	Core in Green Pads	2,520	SF	2001 Gym	ASSUMED	MISC	N	NONE			Yes	ACBM with the		LOW

Chicago Public Schools

School Brighton Park School **Unit** 26451 **Building ID** 7470
Address 3825 S. Washtenaw **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
88	2' x 4' Smooth Ceiling Panels	1,368	SF	Kitchen and Serving Area	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
89	12" x 12" Green and White Floor Tile	3,500	SF	Cafeteria	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
90	12" x 12" Green and White Floor Tile Mastic	3,500	SF	Cafeteria	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
91	Beige Marbled Vinyl Flooring	4,000	SF	Addition Gym	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
92	Blue Textured Vinyl Flooring	30	SF	Multi-purpose Room	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
93	12" x 12" Gray Mottled Floor Tile	900	SF	Room 144	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
94	12" x 12" Gray Mottled Floor Tile Mastic	900	SF	Room 144	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
95	1' x 1' Pinhole & Gouges Ceiling Tile	550	SF	1st Floor South Hallway by Multipurpose Room, 2nd Floor South Hallway	ASSUMED	MISC	Y	LOC	50	SF	Yes	Damaged or significantly damaged friable misc. ACBM	10	LOW
96	2' x 4' Pinhole Ceiling Tile (Replacement Tiles)	23	SF	3rd Floor Stairway 2, 131	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
97	12" x 12" Peach w/ White Streaks (Replacement Tile)	16	SF	Room 235 Old Building	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
A	Boiler Lag	50	SF	Boiler Room	ASSUMED	TSI	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		LOW
F	Aircell Lag	10	LF	Girls Bathroom Vestibule in Gym Building	CHR	TSI	Y	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Brighton Park School Unit 26451 Building ID 7470
Address 3825 S. Washtenaw Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date <u>3/20/2025</u>
Inspector Name <u>Daniel Akim</u>
<u>100-20751</u> <u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
1	
14	
16	
19	
2	1 SF Damage in South Hallway
20	
22	
23	Material not observed - 2025
24	Material not observed - 2025
25	Material not observed - 2025
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	

Chicago Public Schools

School Brighton Park School **Unit** 26451 **Building ID** 7470
Address 3825 S. Washtenaw **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
4	Material not observed - 2025
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
5	Material not observed - 2025
50	
51	Material not observed - 2025
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	

Chicago Public Schools

School Brighton Park School **Unit** 26451 **Building ID** 7470
Address 3825 S. Washtenaw **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
67	
68	
69	
70	
71	Material not observed - 2025
72	Damage in: Room 210 inside Gym 2001 Building, 2nd floor gym NE stairway 3
73	Material not observed - 2025
74	
75	
76	Material not observed - 2025
77	
78	
79	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
90	
91	
92	Currently the multipurpose room
93	
94	
95	Damage in: 1st floor South Hallway by multipurpose room

Chicago Public Schools

School Brighton Park School **Unit** 26451 **Building ID** 7470
Address 3825 S. Washtenaw **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
96	
97	
A	
F	

Table II
Management Planner's Review

Chicago Public Schools

School Brighton Park School

Unit 26451

Building ID 7470

Address 3825 S. Washtenaw

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	2' x 4' Ceiling Panels			Classrooms of Original Building	No ACBM	MISC					
14	12" x 12" Light Brown/Off-White Floor Tile	4,000	SF	Hallways, and Office	Assumed	MISC	No		SF	5 ACBM with potential for significant damage	Follow O&M Plan
16	12" x 12" Light Brown/Off-White Floor Tile Mastic	4,000	SF	Hallways, and Office	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Insulation Inside Of Fire Door	35	SF	Boiler Room	Assumed	TSI	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
2	1' x 1' Ceiling Tiles			Classrooms and Hallways of Original Building	No ACBM	MISC					
20	Drywall			Classrooms	No ACBM	MISC					
22	Transite Panels	500	SF	Behind Grills On Both Sides of Gym	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12" x 12" Floor Tile			Entrance Foyer of Gym Building	Assumed	MISC					
24	12" x 12" Floor Tile Mastic			Entrance Foyer of Gym Building	Assumed	MISC					
25	Floor Tile Mastic			ABATED	Abated	MISC					
26	1" x 1" White Ceramic Wall Tile Grout			Girls Gym Bathroom	No ACBM	MISC					
27	1" x 1" Light Brown Ceramic Floor Tile Grout			Girls Gym Bathroom	No ACBM	MISC					
28	1" x 1" Brown Ceramic Floor Tile Grout			Boys Gym Bathroom	No ACBM	MISC					
29	Ceramic Wall Tile Grout			Boys Gym Bathroom	No ACBM	MISC					
30	Terrazzo Flooring			Landing Between Bathrooms by Gym, Addition Corridors, 3rd Floor Bathrooms 2001 Addition,	No ACBM	MISC					
31	2' x 4' Lay-in Ceiling Panels			Girls and Boys Gym Bathrooms	No ACBM	MISC					
32	Interior Brick			Gym	No ACBM	MISC					
33	Interior Brick Mortar			Gym	No ACBM	MISC					
34	Block			Gym	No ACBM	MISC					
35	Block Mortar			Gym	No ACBM	MISC					
36	Cementitious Patching Material			Boys Gym Bathroom Vestibule Windows	No ACBM	MISC					
37	Window Grout			Bleachers in Gym	No ACBM	MISC					
38	Green Wall Tile Caulk			Girls and Boys Bathrooms- Original Building	No ACBM	MISC					
39	Green Terrazzo Flooring			Girls and Boys Bathrooms- Original Building	No ACBM	MISC					
4	4" x 4" Red and Black Floor Tile			Girls and Boys Bathrooms - Gym Building	Assumed	MISC					
40	Wall Tile Adhesive			Girls and Boys Bathrooms- Original Building	No ACBM	MISC					

Chicago Public Schools

School Brighton Park School

Unit 26451

Building ID 7470

Address 3825 S. Washtenaw

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
41	1' x 1' Ceiling Tiles Adhesive			Throughout Original Building	No ACBM	MISC					
42	Terrazzo			Stairways and Landings in Original Building	No ACBM	MISC					
43	Interior Brick			Throughout Original Building	No ACBM	MISC					
44	Interior Brick Mortar			Throughout Original Building	No ACBM	MISC					
45	Terrazzo Wall Panels			Girls Bathroom- Original Building	No ACBM	MISC					
46	Gray Baseboard			Rooms 106, 107, 108	No ACBM	MISC					
47	Gray Baseboard Mastic			Rooms 106, 107, 108	No ACBM	MISC					
48	Brown Baseboard			Rooms 110, 111, 204 & 205	No ACBM	MISC					
49	Brown Baseboard Mastic			Rooms 110, 111, 204 & 205	No ACBM	MISC					
5	4' x 10' Ceiling Panels			Gym	Assumed	MISC					
50	Ceiling Material			Garage	No ACBM	MISC					
51	Pegboard			Room 211	Assumed	MISC					
52	Exterior Brick - Non-AHERA			Original Building	No ACBM	MISC					
53	Exterior Brick Mortar - Non-AHERA			Original Building	No ACBM	MISC					
54	Exterior Door Grout - Non-AHERA			Original Building	No ACBM	MISC					
55	Fire Block			Basement Stairs	No ACBM	MISC					
56	12" x 12" White w/ Blue, Red, & Yellow Floor Tile	2,000	SF	Library, Entrance Women's Library, Multi-purpose Room & Entrance	Assumed	MISC	No		SF	5 ACBM with potential for significant damage	Follow O&M Plan
57	12" x 12" White w/ Blue and Yellow Floor Tile Mastic			Library, Entrance Women's Library, Multi-purpose Room & Entrance	No ACBM	MISC					
58	12" x 12" Blue Floor Tile	2,000	SF	Library,145	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
59	12" x 12" Blue Floor Tile Mastic			Library 145	No ACBM	MISC					
60	12" x 12" Yellow Floor Tile	2,500	SF	Cafeteria	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
61	12" x 12" Yellow Floor Tile Mastic			Library	No ACBM	MISC					
62	4" Blue Vinyl Baseboard			Library	No ACBM	MISC					
63	4" Blue Vinyl Baseboard Adhesive			Library	No ACBM	MISC					
64	12" x 12" Brown Floor Tile	4,500	SF	Classrooms - Original Building With the Exception of 224 & 225	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
65	12" x 12" Brown Floor Tile Mastic			Classrooms - Original Building With the Exception of 224 & 225	No ACBM	MISC					
66	12" x 12" Beige Floor Tile	4,500	SF	Classrooms- Original Building With the Exception of 224 & 225,	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
67	12" x 12" Beige Floor Tile Mastic			Classrooms - Original Building With the Exception of 224 & 225	No ACBM	MISC					

Chicago Public Schools

School Brighton Park School

Unit 26451

Building ID 7470

Address 3825 S. Washtenaw

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
68	2' x 4' Lay-in Ceiling Panels	544	SF	Rear Room in Library, Kitchen	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
69	Floor Tile Beneath 12" x 12" Floor Tile	9,400	SF	All Rooms of Original Building Except Rooms 224 and 225	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
70	Floor Tile Beneath 12" x 12" Floor Tile Mastic	9,400	SF	All Rooms of Original Building Except Rooms 224 and 225	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
71	Blue Carpet Adhesive			Room 229	Assumed	MISC					
72	2' x 4' Ceiling Panels	24,250	SF	Rooms 224, 225, & the 2001 Addition Classrooms and Corridors	Assumed	MISC	Yes	8	SF	4 Damaged or significantly damaged friable misc. ACBM	Remove
73	Green Carpet Adhesive			2001 Addition, Office, Rooms 105, 107, 109, 111, 205	Assumed	MISC					
74	Drywall	25,000	SF	2001 Addition	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
75	Drywall Compound	25,000	SF	2001 Addition	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
76	Sink Undercoat			Office, Room 101	Assumed	SURFACE					
77	12" x 12" Aqua Floor Tile	9,507	SF	2001 Addition Classrooms, 208 Storage, Addition Gym Office, 215 MDF Room, 137, Cafeteria, 130	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
78	12" x 12" Aqua Floor Tile Mastic	9,532	SF	2001 Addition Classrooms, 205, 208 Storage Addition Gym Office, 215 MDF Room 137, Cafeteria	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
79	12" x 12" Beige Floor Tile	12,447	SF	2001 Addition Classrooms, 208 Storage, Addition Gym Office, 215 MDF Room, 137, Cafeteria	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
80	12" x 12" Beige Floor Tile Mastic	12,447	SF	2001 Addition Classrooms, 208 Storage Addition Gym Office, 215 MDF Room, 137, Cafeteria	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
81	4" Green Vinyl Baseboard	1,300	LF	2001 Addition	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
82	4" Green Vinyl Baseboard Adhesive	1,300	LF	2001 Addition	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
83	Spray on Insulation	12,000	SF	2001 Addition, 215 MDF Room, 133 Electrical Room	Assumed	TSI	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
84	Vibration Collars	100	LF	2001 Addition	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
85	Chalk Board/Marker Board Adhesive	2,000	SF	Original Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
86	Chalk Board/Marker Board Adhesive	2,400	SF	2001 Addition	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
87	Core in Green Pads	2,520	SF	2001 Gym	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Brighton Park School

Unit 26451

Building ID 7470

Address 3825 S. Washtenaw

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
88	2' x 4' Smooth Ceiling Panels	1,368	SF	Kitchen and Serving Area	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
89	12" x 12" Green and White Floor Tile	3,500	SF	Cafeteria	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
90	12" x 12" Green and White Floor Tile Mastic	3,500	SF	Cafeteria	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
91	Beige Marbled Vinyl Flooring	4,000	SF	Addition Gym	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
92	Blue Textured Vinyl Flooring	30	SF	Multi-purpose Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
93	12" x 12" Gray Mottled Floor Tile	900	SF	Room 144	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
94	12" x 12" Gray Mottled Floor Tile Mastic	900	SF	Room 144	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
95	1' x 1' Pinhole & Gouges Ceiling Tile	550	SF	1st Floor South Hallway by Multipurpose Room, 2nd Floor South Hallway	Assumed	MISC	Yes	50	SF	4 Damaged or significantly damaged friable misc. ACBM	Remove
96	2' x 4' Pinhole Ceiling Tile (Replacement Tiles)	23	SF	3rd Floor Stairway 2, 131	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
97	12" x 12" Peach w/ White Streaks (Replacement Tile)	16	SF	Room 235 Old Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Boiler Lag	50	SF	Boiler Room	Assumed	TSI	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	Aircell Lag	10	LF	Girls Bathroom Vestibule in Gym Building	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Chicago Public Schools

School Brighton Park School

Unit 26451

Building ID 7470

Address 3825 S. Washtenaw

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	4/18/2025
Manager Planner Name	Jackson Montgomery
100-20634	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
14	Sample to determine ACM content prior to disturbance.
16	
19	Sample to determine ACM content prior to disturbance.
2	Repair non-ACBM material.
20	
22	
23	If identified, continue O&M
24	If identified, continue O&M
25	If identified, continue O&M
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	

Chicago Public Schools

School Brighton Park School

Unit 26451

Building ID 7470

Address 3825 S. Washtenaw

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
36	
37	
38	
39	
4	If identified, continue O&M
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
5	If identified, continue O&M
50	
51	If identified, continue O&M
52	
53	
54	
55	
56	Sample to determine ACM content prior to disturbance.
57	
58	Sample to determine ACM content prior to disturbance.
59	
60	Sample to determine ACM content prior to disturbance.

Chicago Public Schools

School Brighton Park School

Unit 26451

Building ID 7470

Address 3825 S. Washtenaw

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
61	
62	
63	
64	Sample to determine ACM content prior to disturbance.
65	
66	Sample to determine ACM content prior to disturbance.
67	
68	Sample to determine ACM content prior to disturbance.
69	Sample to determine ACM content prior to disturbance.
70	Sample to determine ACM content prior to disturbance.
71	If identified, continue O&M
72	Sample to determine ACM content, remove and replace damaged material.
73	If identified, continue O&M
74	Sample to determine ACM content prior to disturbance.
75	Sample to determine ACM content prior to disturbance.
76	If identified, continue O&M
77	Sample to determine ACM content prior to disturbance.
78	Sample to determine ACM content prior to disturbance.
79	Sample to determine ACM content prior to disturbance.
80	Sample to determine ACM content prior to disturbance.
81	Sample to determine ACM content prior to disturbance.
82	Sample to determine ACM content prior to disturbance.
83	Sample to determine ACM content prior to disturbance.
84	Sample to determine ACM content prior to disturbance.
85	Sample to determine ACM content prior to disturbance.
86	Sample to determine ACM content prior to disturbance.
87	Sample to determine ACM content prior to disturbance.

Chicago Public Schools

School Brighton Park School

Unit 26451

Building ID 7470

Address 3825 S. Washtenaw

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
88	Sample to determine ACM content prior to disturbance.
89	Sample to determine ACM content prior to disturbance.
90	Sample to determine ACM content prior to disturbance.
91	Sample to determine ACM content prior to disturbance.
92	Sample to determine ACM content prior to disturbance.
93	Sample to determine ACM content prior to disturbance.
94	Sample to determine ACM content prior to disturbance.
95	Sample to determine ACM content, remove and replace damaged material.
96	Sample to determine ACM content prior to disturbance.
97	Sample to determine ACM content prior to disturbance.
A	Sample to determine ACM content prior to disturbance.
F	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Panels**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms of Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Panels**

MATERIAL LOCATION: **Classrooms of Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	12" x 12" Light Brown/Off-White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Deterioration		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallways, and Office		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12" x 12" Light Brown/Off-White Floor Tile**

MATERIAL LOCATION: **Hallways, and Office**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	12" x 12" Light Brown/Off-White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallways, and Office		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **12" x 12" Light Brown/Off-White Floor Tile Mastic**

MATERIAL LOCATION: **Hallways, and Office**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	Insulation Inside Of Fire Door		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	35	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Insulation Inside Of Fire Door**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **35** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tiles**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms and Hallways of Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **1 SF Damage in South Hallway**

Inspector's Signature: _____ Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tiles**

MATERIAL LOCATION: **Classrooms and Hallways of Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Repair non-ACBM material.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Drywall**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	Transite Panels		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Behind Grills On Both Sides of Gym		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Transite Panels**

MATERIAL LOCATION: **Behind Grills On Both Sides of Gym**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23	
MATERIAL DESCRIPTION:	12" x 12" Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Entrance Foyer of Gym Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **12" x 12" Floor Tile**

MATERIAL LOCATION: **Entrance Foyer of Gym Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24	
MATERIAL DESCRIPTION:	12" x 12" Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Entrance Foyer of Gym Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **12" x 12" Floor Tile Mastic**

MATERIAL LOCATION: **Entrance Foyer of Gym Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **1" x 1" White Ceramic Wall Tile Grout**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Girls Gym Bathroom**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **1" x 1" White Ceramic Wall Tile Grout**

MATERIAL LOCATION: **Girls Gym Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **1" x 1" Light Brown Ceramic Floor Tile Grout**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Girls Gym Bathroom**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **1" x 1" Light Brown Ceramic Floor Tile Grout**

MATERIAL LOCATION: **Girls Gym Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **1" x 1" Brown Ceramic Floor Tile Grout**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boys Gym Bathroom**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **1" x 1" Brown Ceramic Floor Tile Grout**

MATERIAL LOCATION: **Boys Gym Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29	
MATERIAL DESCRIPTION:	Ceramic Wall Tile Grout	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boys Gym Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Ceramic Wall Tile Grout**

MATERIAL LOCATION: **Boys Gym Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 30
MATERIAL DESCRIPTION: Terrazzo Flooring
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Landing Between Bathrooms by Gym, Addition Corridors, 3rd Floor Bathrooms 2001 Addition,

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Terrazzo Flooring**

MATERIAL LOCATION: **Landing Between Bathrooms by Gym, Addition Corridors, 3rd Floor Bathrooms 2001 Addition,**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **2' x 4' Lay-in Ceiling Panels**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Girls and Boys Gym Bathrooms**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **2' x 4' Lay-in Ceiling Panels**

MATERIAL LOCATION: **Girls and Boys Gym Bathrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Interior Brick**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Interior Brick**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 33
MATERIAL DESCRIPTION: Interior Brick Mortar
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Gym

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34	
MATERIAL DESCRIPTION:	Block	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Block**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Block Mortar**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Block Mortar**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36	
MATERIAL DESCRIPTION:	Cementitious Patching Material	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boys Gym Bathroom Vestibule Windows**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Cementitious Patching Material**

MATERIAL LOCATION: **Boys Gym Bathroom Vestibule Windows**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Window Grout**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Bleachers in Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Window Grout**

MATERIAL LOCATION: **Bleachers in Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 38
MATERIAL DESCRIPTION: Green Wall Tile Caulk
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Girls and Boys Bathrooms- Original Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Green Wall Tile Caulk**

MATERIAL LOCATION: **Girls and Boys Bathrooms- Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 39
MATERIAL DESCRIPTION: Green Terrazzo Flooring
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Girls and Boys Bathrooms- Original Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Green Terrazzo Flooring**

MATERIAL LOCATION: **Girls and Boys Bathrooms- Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	4	
MATERIAL DESCRIPTION:	4" x 4" Red and Black Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Girls and Boys Bathrooms - Gym Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature: _____ Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **4" x 4" Red and Black Floor Tile**

MATERIAL LOCATION: **Girls and Boys Bathrooms - Gym Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Wall Tile Adhesive**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Girls and Boys Bathrooms- Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Wall Tile Adhesive**

MATERIAL LOCATION: **Girls and Boys Bathrooms- Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tiles Adhesive**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Original Building**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tiles Adhesive**

MATERIAL LOCATION: **Throughout Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Stairways and Landings in Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **Stairways and Landings in Original Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Interior Brick**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Interior Brick**

MATERIAL LOCATION: **Throughout Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **Throughout Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 45
MATERIAL DESCRIPTION: Terrazzo Wall Panels
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Girls Bathroom- Original Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Terrazzo Wall Panels**

MATERIAL LOCATION: **Girls Bathroom- Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Gray Baseboard**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 106, 107, 108**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Gray Baseboard**

MATERIAL LOCATION: **Rooms 106, 107, 108**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Gray Baseboard Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 106, 107, 108**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Gray Baseboard Mastic**

MATERIAL LOCATION: **Rooms 106, 107, 108**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Brown Baseboard**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 110, 111, 204 & 205**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Brown Baseboard**

MATERIAL LOCATION: **Rooms 110, 111, 204 & 205**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Brown Baseboard Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 110, 111, 204 & 205**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Brown Baseboard Mastic**

MATERIAL LOCATION: **Rooms 110, 111, 204 & 205**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	5		
MATERIAL DESCRIPTION:	4' x 10' Ceiling Panels		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Gym

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **4' x 10' Ceiling Panels**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Ceiling Material**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Garage**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Ceiling Material**

MATERIAL LOCATION: **Garage**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 51

MATERIAL DESCRIPTION: Pegboard

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 211

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Pegboard**

MATERIAL LOCATION: **Room 211**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52	
MATERIAL DESCRIPTION:	Exterior Brick - Non-AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **Exterior Brick - Non-AHERA**

MATERIAL LOCATION: **Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53	
MATERIAL DESCRIPTION:	Exterior Brick Mortar - Non-AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Non-AHERA**

MATERIAL LOCATION: **Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54	
MATERIAL DESCRIPTION:	Exterior Door Grout - Non-AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Exterior Door Grout - Non-AHERA**

MATERIAL LOCATION: **Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Fire Block**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Stairs**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Fire Block**

MATERIAL LOCATION: **Basement Stairs**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	56		
MATERIAL DESCRIPTION:	12" x 12" White w/ Blue, Red, & Yellow Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Deterioration		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Library, Entrance Women's Library, Multi-purpose Room & Entrance		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **12" x 12" White w/ Blue, Red, & Yellow Floor Tile**

MATERIAL LOCATION: **Library, Entrance Women's Library, Multi-purpose Room & Entrance**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	57	
MATERIAL DESCRIPTION:	12" x 12" White w/ Blue and Yellow Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Library, Entrance Women's Library, Multi-purpose Room & Entrance

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **12" x 12" White w/ Blue and Yellow Floor Tile Mastic**

MATERIAL LOCATION: **Library, Entrance Women's Library, Multi-purpose Room & Entrance**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Library,145		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**

MATERIAL LOCATION: **Library,145**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library 145**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**

MATERIAL LOCATION: **Library 145**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	60		
MATERIAL DESCRIPTION:	12" x 12" Yellow Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Cafeteria		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	61	
MATERIAL DESCRIPTION:	12" x 12" Yellow Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile Mastic**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **4" Blue Vinyl Baseboard**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **4" Blue Vinyl Baseboard**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	63	
MATERIAL DESCRIPTION:	4" Blue Vinyl Baseboard Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **4" Blue Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	64		
MATERIAL DESCRIPTION:	12" x 12" Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms - Original Building With the Exception of 224 & 225		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**

MATERIAL LOCATION: **Classrooms - Original Building With the Exception of 224 & 225**

MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms - Original Building With the Exception of 224 & 225**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**

MATERIAL LOCATION: **Classrooms - Original Building With the Exception of 224 & 225**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	66		
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms- Original Building With the Exception of 224 & 225,		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**

MATERIAL LOCATION: **Classrooms- Original Building With the Exception of 224 & 225,**

MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	67	
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms - Original Building With the Exception of 224 & 225**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**

MATERIAL LOCATION: **Classrooms - Original Building With the Exception of 224 & 225**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	68		
MATERIAL DESCRIPTION:	2' x 4' Lay-in Ceiling Panels		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rear Room in Library, Kitchen		
MATERIAL QUANTITY:	544	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **2' x 4' Lay-in Ceiling Panels**

MATERIAL LOCATION: **Rear Room in Library, Kitchen**

MATERIAL QUANTITY: **544** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	69		
MATERIAL DESCRIPTION:	Floor Tile Beneath 12" x 12" Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	All Rooms of Original Building Except Rooms 224 and 225		
MATERIAL QUANTITY:	9400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **Floor Tile Beneath 12" x 12" Floor Tile**

MATERIAL LOCATION: **All Rooms of Original Building Except Rooms 224 and 225**

MATERIAL QUANTITY: **9400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	70		
MATERIAL DESCRIPTION:	Floor Tile Beneath 12" x 12" Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	All Rooms of Original Building Except Rooms 224 and 225		
MATERIAL QUANTITY:	9400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **Floor Tile Beneath 12" x 12" Floor Tile Mastic**

MATERIAL LOCATION: **All Rooms of Original Building Except Rooms 224 and 225**

MATERIAL QUANTITY: **9400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **Blue Carpet Adhesive**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 229**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **Blue Carpet Adhesive**

MATERIAL LOCATION: **Room 229**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	72		
MATERIAL DESCRIPTION:	2' x 4' Ceiling Panels		
HISTORICAL AHERA DAMAGE CATEGORY	4 Damaged or significantly damaged friable misc. ACBM		
HISTORICAL DAMAGE REASON:	Vibration		
HISTORICAL RESPONSE ACTION:	Remove		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON:	Vibration		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 224, 225, & the 2001 Addition Classrooms and Corridors		
MATERIAL QUANTITY:	24250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in: Room 210 inside Gym 2001 Building, 2nd floor gym NE stairway 3		

Inspector's Signature: _____ Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Panels**

MATERIAL LOCATION: **Rooms 224, 225, & the 2001 Addition Classrooms and Corridors**

MATERIAL QUANTITY: **24250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **8** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Sample to determine ACM content, remove and replace damaged material.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 73
MATERIAL DESCRIPTION: Green Carpet Adhesive
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 2001 Addition, Office, Rooms 105, 107, 109, 111, 205

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **Green Carpet Adhesive**

MATERIAL LOCATION: **2001 Addition, Office, Rooms 105, 107, 109, 111, 205**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	74		
MATERIAL DESCRIPTION:	Drywall		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2001 Addition		
MATERIAL QUANTITY:	25000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **2001 Addition**

MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	75		
MATERIAL DESCRIPTION:	Drywall Compound		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2001 Addition		
MATERIAL QUANTITY:	25000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **Drywall Compound**

MATERIAL LOCATION: **2001 Addition**

MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	76	
MATERIAL DESCRIPTION:	Sink Undercoat	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Office, Room 101

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **Sink Undercoat**

MATERIAL LOCATION: **Office, Room 101**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	77		
MATERIAL DESCRIPTION:	12" x 12" Aqua Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2001 Addition Classrooms, 208 Storage, Addition Gym Office, 215 MDF Room, 137, Cafeteria, 130		
MATERIAL QUANTITY:	9507	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **12" x 12" Aqua Floor Tile**

MATERIAL LOCATION: **2001 Addition Classrooms, 208 Storage, Addition Gym Office, 215 MDF Room, 137, Cafeteria, 130**

MATERIAL QUANTITY: **9507** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	78		
MATERIAL DESCRIPTION:	12" x 12" Aqua Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW	MATERIAL UNITS:	SF
MATERIAL LOCATION:	2001 Addition Classrooms, 205, 208 Storage Addition Gym Office, 215 MDF Room 137, Cafeteria		
MATERIAL QUANTITY:	9532	DAMAGE UNITS:	SF
DAMAGE QUANTITY:		COMMENTS:	

Inspector's Signature: _____ Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **12" x 12" Aqua Floor Tile Mastic**

MATERIAL LOCATION: **2001 Addition Classrooms, 205, 208 Storage Addition Gym Office, 215 MDF Room 137, Cafeteria**

MATERIAL QUANTITY: **9532** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	79		
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2001 Addition Classrooms, 208 Storage, Addition Gym Office, 215 MDF Room, 137, Cafeteria		
MATERIAL QUANTITY:	12447	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**

MATERIAL LOCATION: **2001 Addition Classrooms, 208 Storage, Addition Gym Office, 215 MDF Room, 137, Cafeteria**

MATERIAL QUANTITY: **12447** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	80		
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2001 Addition Classrooms, 208 Storage Addition Gym Office, 215 MDF Room, 137, Cafeteria		
MATERIAL QUANTITY:	12447	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**

MATERIAL LOCATION: **2001 Addition Classrooms, 208 Storage Addition Gym Office, 215 MDF Room, 137, Cafeteria**

MATERIAL QUANTITY: **12447** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	81		
MATERIAL DESCRIPTION:	4" Green Vinyl Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2001 Addition		
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **4" Green Vinyl Baseboard**

MATERIAL LOCATION: **2001 Addition**

MATERIAL QUANTITY: **1300** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	82		
MATERIAL DESCRIPTION:	4" Green Vinyl Baseboard Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2001 Addition		
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **4" Green Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **2001 Addition**

MATERIAL QUANTITY: **1300** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	83		
MATERIAL DESCRIPTION:	Spray on Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2001 Addition, 215 MDF Room, 133 Electrical Room		
MATERIAL QUANTITY:	12000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **Spray on Insulation**

MATERIAL LOCATION: **2001 Addition, 215 MDF Room, 133 Electrical Room**

MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	84		
MATERIAL DESCRIPTION:	Vibration Collars		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2001 Addition		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **Vibration Collars**

MATERIAL LOCATION: **2001 Addition**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	85		
MATERIAL DESCRIPTION:	Chalk Board/Marker Board Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Original Building		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **85**

MATERIAL DESCRIPTION: **Chalk Board/Marker Board Adhesive**

MATERIAL LOCATION: **Original Building**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	86		
MATERIAL DESCRIPTION:	Chalk Board/Marker Board Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2001 Addition		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **86**

MATERIAL DESCRIPTION: **Chalk Board/Marker Board Adhesive**

MATERIAL LOCATION: **2001 Addition**

MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	87		
MATERIAL DESCRIPTION:	Core in Green Pads		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2001 Gym		
MATERIAL QUANTITY:	2520	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **87**

MATERIAL DESCRIPTION: **Core in Green Pads**

MATERIAL LOCATION: **2001 Gym**

MATERIAL QUANTITY: **2520** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	88		
MATERIAL DESCRIPTION:	2' x 4' Smooth Ceiling Panels		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen and Serving Area		
MATERIAL QUANTITY:	1368	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **2' x 4' Smooth Ceiling Panels**

MATERIAL LOCATION: **Kitchen and Serving Area**

MATERIAL QUANTITY: **1368** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	89		
MATERIAL DESCRIPTION:	12" x 12" Green and White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Cafeteria		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **89**

MATERIAL DESCRIPTION: **12" x 12" Green and White Floor Tile**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	90		
MATERIAL DESCRIPTION:	12" x 12" Green and White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Cafeteria		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **12" x 12" Green and White Floor Tile Mastic**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	91		
MATERIAL DESCRIPTION:	Beige Marbled Vinyl Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Addition Gym		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **91**

MATERIAL DESCRIPTION: **Beige Marbled Vinyl Flooring**

MATERIAL LOCATION: **Addition Gym**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	92		
MATERIAL DESCRIPTION:	Blue Textured Vinyl Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Multi-purpose Room		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Currently the multipurpose room		

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **Blue Textured Vinyl Flooring**

MATERIAL LOCATION: **Multi-purpose Room**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	93		
MATERIAL DESCRIPTION:	12" x 12" Gray Mottled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 144		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **93**

MATERIAL DESCRIPTION: **12" x 12" Gray Mottled Floor Tile**

MATERIAL LOCATION: **Room 144**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	94		
MATERIAL DESCRIPTION:	12" x 12" Gray Mottled Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 144		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **94**

MATERIAL DESCRIPTION: **12" x 12" Gray Mottled Floor Tile Mastic**

MATERIAL LOCATION: **Room 144**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A		
MATERIAL DESCRIPTION:	Boiler Lag		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Boiler Lag**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F		
MATERIAL DESCRIPTION:	Aircell Lag		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Girls Bathroom Vestibule in Gym Building**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature:

Date: **03/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Aircell Lag**

MATERIAL LOCATION: **Girls Bathroom Vestibule in Gym Building**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	97		
MATERIAL DESCRIPTION:	12" x 12" Peach w/ White Streaks (Replacement Tile)		
MATERIAL LOCATION:	Room 235 Old Building		
MATERIAL QUANTITY:	16	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUILDING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **97**

MATERIAL DESCRIPTION: **12" x 12" Peach w/ White Streaks (Replacement Tile)**

MATERIAL LOCATION: **Room 235 Old Building**

MATERIAL QUANTITY: **16** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	95			
MATERIAL DESCRIPTION:	1' x 1' Pinhole & Gouges Ceiling Tile			
MATERIAL LOCATION:	1st Floor South Hallway by Multipurpose Room, 2nd Floor South Hallway			
MATERIAL QUANTITY:	550	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	Yes	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	Damaged	
AHERA DAMAGE CATEGORY:	4 Damaged or significantly damaged friable misc. ACBM			
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:		
DAMAGE QUANTITY:	50	DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	

COMMENTS:

Damage in: 1st floor South Hallway by multipurpose room

Inspector's Signature:

Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26451** BUIDLING ID: **7470**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Brighton Park School** REVIEW DATE: **4/18/2025**

ADDRESS: **3825 S. Washtenaw** IDPH LICENSE NO: **100-20751**

HOMOGENEOUS AREA: **95**

MATERIAL DESCRIPTION: **1' x 1' Pinhole & Gouges Ceiling Tile**

MATERIAL LOCATION: **1st Floor South Hallway by Multipurpose Room, 2nd Floor South Hallway**

MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content, remove and replace damaged material.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Daniel Akim		
SCHOOL NAME:	Brighton Park School	INSPECTION DATE:	3/20/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	96		
MATERIAL DESCRIPTION:	2' x 4' Pinhole Ceiling Tile (Replacement Tiles)		
MATERIAL LOCATION:	3rd Floor Stairway 2, 131		
MATERIAL QUANTITY:	23	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	Yes
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	7 Any remaining friable ACBM or friable suspect ACBM		
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 03/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26451	BUIDLING ID:	7470
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Brighton Park School	REVIEW DATE:	4/18/2025		
ADDRESS:	3825 S. Washtenaw	IDPH LICENSE NO:	100-20751		

HOMOGENEOUS AREA: **96**

MATERIAL DESCRIPTION: **2' x 4' Pinhole Ceiling Tile (Replacement Tiles)**

MATERIAL LOCATION: **3rd Floor Stairway 2, 131**

MATERIAL QUANTITY: **23** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

APPENDIX B

Inspector and Management Planner Licenses



OCCUPATIONAL TRAINING & SUPPLY, INC. **2025**

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Daniel Akim

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 2/20/2025

Exam Date: 2/20/2025

Expiration Date: 2/20/2026


Certificate Number: BIR2502200709

Course Credit Hours: BIR 4 Hours

Kristina Miczek, Training Manager

Daniel Akim

Illinois Licensed Building Inspector, Air Sampling Professional, Asbestos Project Manager



ENDORSEMENTS

INSPECTOR

TC EXPIRES

2/20/2026

PROJECT MANAGER
AIR SAMPLING PROFESSIONAL





4/7/2026

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



Jackson Montgomery

Illinois Licensed Building Inspector, Air Sampling Professional, Management Planner





2200 Vandalia Street, Collinsville, IL 62234 * Phone: 618-855-8764

Environmental and Occupational Safety & Health Training

Does hereby certify

Jackson Montgomery

600 W. Van Buren St., Suite 500, Chicago, IL 60607



*Has successfully completed and passed the course examination with at least
70% for accreditation under AHERA (Title II)*

Asbestos Management Planner Initial

Class Date: 10/28-29/2024

Examination Date: 10/29/2024

STC Certificate Number: STC-20241029-000101AMPI

Certification Expiration: 10/29/2025

A handwritten signature in black ink that reads 'David M. Mendoza'.

David M. Mendoza – President/Training Director

Certified Environmental Specialist

OSHA Authorized Instructor

This training course is accredited by the Illinois Department of Public Health and the Missouri Department of Natural Resources

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed