

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2882  
SCHOOL NAME: Marshall Middle School  
ADDRESS OF SCHOOL: 3900 N Lawndale Avenue  
CITY: Chicago, IL, 60618

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 10/10/2022

If the address on this form is different than the address of the building, submit a written explanation.

**SECTION II** *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 4/1/2025 ENROLLMENT 1179  
IDPH INSPECTOR LICENSE NUMBER: 100-18790  
IDPH LICENSED INSPECTOR NAME (Please Print): Allizon Brooks  
IDPH MP LICENSE NUMBER: 100-07342  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

*Richard J. Schleyer* 5/1/2025  
Signature of Designated Person Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_  
School has been closed. Date closed: \_\_\_\_\_  
School building has been demolished. Date: \_\_\_\_\_  
School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Marshall Middle School**

3900 N Lawndale Avenue  
Chicago, IL, 60618

Unit: 26921  
Building ID: 7520

IDPH ID Number: 14-016-2990-2882

**REPORT DATE:**  
Thursday, May 01, 2025

**Prepared for:**  
**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**  
**Specialty Consulting, Inc.**

2942 W. Van Buren Street

Chicago, IL, 60612

Phone (312) 319-7575

Fax (312) 319-7580

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

05/01/2025

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Specialty Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299      Unit: 41081      Region: 01      IDPH ID: 14-016-2990-2882

School: Marshall Middle School      Building ID: 7520

Address: 3900 N Lawndale Avenue

Chicago, IL, 60618

Building Contact: Hefner, Scott      Contact Phone: 7734901019

Current Building Owners: Chicago Public Schools

Reinspection Date: 4/1/2025

Review Date: 05/01/2025

Inspector: Allizon Brooks

Inspector IDPH License: 100-18790

Management Planner: Jigar Shah

Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at (312) 319-7575

Sincerely,  
Specialty Consulting, Inc.



Jigar Shah  
100-07342

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: May 01, 2025

RE: Marshall Middle School, Unit 26921  
3900 N Lawndale Avenue  
Chicago, IL, 60618

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Marshall Middle School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Marshall Middle School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Marshall Middle School      Unit: 41081      Region: 01  
Address: 3900 N Lawndale Avenue      Chicago, IL, 60618  
IDPH ID: 14-016-2990-2882      Building ID: 7520  
Contact: Hefner, Scott      Phone: 7734901019

### 2. Description of Facility

Original Construction: 1956      Additional Construction: 1924,1952  
Total Square Footage: 31184      No of Floors: 4  
Current Occupancy: 1179

### 3. LEA Designated Person

Contact: Richard J.Schleyer      Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: Specialty Consulting, Inc.  
Contact: Jigar Shah  
Address 2942 W. Van Buren Street  
Phone: (312) 319-7575      Fax: (312) 319-7580

### 5. Inspector

Inspector Name: Allizon Brooks

Inspector IDPH license # 100-18790      Signature:  
Reinspection Date: 4/1/2025      Date: 4/1/2025

### 6. Management Planner

Management Planner Name: Jigar Shah

Management Planner IDPH license # 100-07342      Signature:  
Date: 05/01/2025

### 7. Review Date: 05/01/2025

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:

*Richard J. Schleyer*

Date: 5/1/2025

Name: Richard J.Schleyer

## **II. EXECUTIVE SUMMARY**

Specialty Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Marshall Middle School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

- A. The following HAs have changed assessment categories for Building 7520:

B. The following new homogenous areas have been identified for Building 7520:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

100	1' x 1' Tan Ceiling Tile
100A	1' x 1' Ceiling Tile Mastic Pucks
101	Decorative Plaster
102	1' x 1' Ceiling Tile
102A	1' x 1' Ceiling Tile Mastic Pucks
103	2' x 4' Ceiling Tile
104	2' x 4' Ceiling Tile
108	12"x12" Lt. Yellow VFT
108A	12"x12" Lt. Yellow VFT Mastic
109	12"x12" Blue VFT
109A	12"x12" Blue VFT Mastic
110	12"x12" White w/ gray specks VFT
110A	12"x12" White w/ gray specks VFT Mastic
111	Drywall system
112	12"x12" Lt. Gray speckled VFT
112A	12"x12" Lt. Gray speckled VFT Mastic
113	12"x12" Dark gray w/white & gray speckles VFT
113A	12"x12" Dark gray w/white & gray speckles VFT Mastic
114	2' x 2' Ceiling Tile
115	Carpet Mastic
116	12"x12" Black w/white specks VFT
116A	12"x12" Black w/white specks VFT Mastic
117	12"x12" Lt. Yellow VFT
117A	12"x12" Lt. Yellow VFT Mastic
118	12"x12" Blue VFT
118A	12"x12" Blue VFT Mastic
119	12"x12" White w/gray specks VFT
119A	12"x12" White w/gray specks VFT Mastic
120	12"x12" Black w/white specks VFT
121	12"x12" Black w/white specks VFT Mastic
122	Off white linoleum flooring
122A	Off white Linoleum flooring adhesive
123	Gray Linoleum flooring
123A	Gray Linoleum flooring adhesive
14	9"x 9" Green w/ White Streaks VFT Mastic
43	9"x 9" White w/ Green & Red Waves VFT
44	9"x 9" White w/ Green & Red Waves VFT Mastic
45	9"x 9" Green w/ White & Green Waves VFT
46	9"x 9" Green w/ White & Green Waves VFT Mastic
47	9"x 9" Red w/ White Waves VFT
48	9"x 9" Red w/ White Waves VFT Mastic

51	9"x 9" White w/ Brown Specks VFT
52	9"x 9" White w/ Brown Specks VFT Mastic
56	12"x 12" Tan w/ Tan, Brn, & White Strks VFT Mastic
67	12"x 12" Brown w/ Brown & White Streaks VFT
70	9"x 9" Brown w/ Drk Brown & Tan Streaks VFT Mastic
72	9"x 9" Dark Tan w/ Brown & Tan Streaks VFT Mastic
81	12"x 12' Green w/ White Streaks VFT
82	12"x 12' Green w/ White Streaks VFT Mastic
83	Brown w/ Colored Waves Linoleum
84	Brown w/ Colored Waves Linoleum Mastic
85	12" x 12" White w/ Light Tan Streaks VFT
86	12" x 12" White w/ Light Tan Streaks VFT Mastic
87	12"x12" Lt. Tan w/ Tan specks VFT
87A	12"x12" Lt. Tan w/ Tan specks VFT Mastic
88	12"x12" Off White w/ Tan specks VFT
88A	12"x12" Off White w/ Tan specks VFT Mastic
89	12"x12" White w/ Blue Specks VFT
89A	12"x12" Off White w/ Tan specks VFT Mastic
90	12"x12" Lt. Tan w/ Tan specks VFT
90A	12"x12" Lt. Tan w/ Tan specks VFT Mastic
95	Terrazzo
96	Terrazzo
97	Cardboard Pipe Insulation
98	Stage's Fire Curtain
99	9" x 9" Tan Ceiling Tile
99A	9" x 9" Tan Ceiling Tile Mastic Pucks

The following areas were deemed to be inaccessible:

100	1' x 1' Tan Ceiling Tile
100A	1' x 1' Ceiling Tile Mastic Pucks
101	Decorative Plaster
114	2' x 2' Ceiling Tile
115	Carpet Mastic
75	9"x 9" Dark Brown w/ Black & Tan Waves VFT
76	9"x 9" Dark Brown w/ Black & Tan Waves VFT Mastic
77	9"x 9" Beige w/ Brown & Dark Brown Waves VFT
78	9"x 9" Beige w/ Brown & Drk Brown Waves VFT Mastic
81	12"x 12' Green w/ White Streaks VFT
82	12"x 12' Green w/ White Streaks VFT Mastic
99A	9" x 9" Tan Ceiling Tile Mastic Pucks

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Allizon Brooks, IDPH License # 100-18790. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Marshall Middle School Building 7520 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

Chicago Public Schools

**School** Marshall Middle School **Unit** 41081 **Building ID** 7520  
**Address** 3900 N Lawndale Avenue **Region** 01

## **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

## Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC) Specialty Consulting, Inc.**

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

***Inspector's Comments are Summarized at the End of the Report***

# Chicago Public Schools

**School** Marshall Middle School **Unit** 41081 **Building ID** 7520  
**Address** 3900 N Lawndale Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Addition										
107	Yellow Linoleum Flooring - Abated			4th Floor Library Office Storage Room - 1923 Bldg.	ABATED	MISC								
108	12"x12" Lt. Yellow VFT	1,200	SF	Rooms (204 and 206 under carpet tiles) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
108A	12"x12" Lt. Yellow VFT Mastic	1,200	SF	Rooms (204 and 206 under carpet tile) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
109	12"x12" Blue VFT	1,100	SF	Rooms (204 and 206 under carpet tile) 402, 404, 406, 408, 410, 411 -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
109A	12"x12" Blue VFT Mastic	1,100	SF	Rooms (204 and 206 under carpet tile) 402, 404, 406, 408, 410, 411 -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	9"x 9" Gray w/ Yellow & Green Streaks VFT	1,170	SF	4th Floor Corridor, 1953	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
110	12"x12" White w/ gray specks VFT	4,900	SF	Rooms (204 and 206 under carpet tile) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
110A	12"x12" White w/ gray specks VFT Mastic	4,900	SF	Rooms (204 and 206 under carpet tile) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
111	Drywall system	6,500	SF	Rooms 402, 404, 406, 408, 410 -1923 Bldg	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
112	12"x12" Lt. Gray speckled VFT	150	SF	Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
112A	12"x12" Lt. Gray speckled VFT Mastic	150	SF	Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Marshall Middle School **Unit** 41081 **Building ID** 7520  
**Address** 3900 N Lawndale Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
113	12"x12" Dark gray w/white & gray speckles VFT	100	SF	Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
113A	12"x12" Dark gray w/white & gray speckles VFT Mastic	100	SF	Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
114	2' x 2' Ceiling Tile	1,000	SF	Rooms 404, 406 -1923 Bldg	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
115	Carpet Mastic	3,500	SF	4th fl library, 302, 304, 306 -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
116	12"x12" Black w/white specks VFT	450	SF	Auditorium -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
116A	12"x12" Black w/white specks VFT Mastic	450	SF	Auditorium -1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
117	12"x12" Lt. Yellow VFT	1,000	SF	Rooms 216, 316, 420, offices 133,134, conference 128, main office -1953 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
117A	12"x12" Lt. Yellow VFT Mastic	1,000	SF	Rooms 216, 316, 420, offices 133,134, conference 128, main office -1953 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
118	12"x12" Blue VFT	700	SF	Work room 132, main office hall, Rooms 216, 316, 420 -1953 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
118A	12"x12" Blue VFT Mastic	700	SF	Work room 132, main office hall, Rooms 216, 316, 420 -1953 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
119	12"x12" White w/gray specks VFT	3,200	SF	Work room 132, main office hall, Rooms 216, 316, 420, conference room 128, offices 133 & 134 -1953 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
119A	12"x12" White w/gray specks VFT Mastic	3,200	SF	Work room 132, main office hall, Rooms 216, 316, 420, conference room 128, offices	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Marshall Middle School **Unit** 41081 **Building ID** 7520  
**Address** 3900 N Lawndale Avenue **Region** 01

## **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

## Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC) Specialty Consulting, Inc.**

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

## ***Inspector's Comments are Summarized at the End of the Report***

Chicago Public Schools

**School** Marshall Middle School **Unit** 41081 **Building ID** 7520  
**Address** 3900 N Lawndale Avenue **Region** 01

## **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

## Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

## ***Inspector's Comments are Summarized at the End of the Report***

# Chicago Public Schools

**School** Marshall Middle School **Unit** 41081 **Building ID** 7520  
**Address** 3900 N Lawndale Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
41	9"x 9" Beige VFT - Abated			Carpet), 1923	ABATED	MISC								
42	9"x 9" Beige VFT Mastic - Abated			Room 400 (Under Carpet), 1923	ABATED	MISC								
43	9"x 9" White w/ Green & Red Waves VFT	120	SF	Room 433 office --1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
44	9"x 9" White w/ Green & Red Waves VFT Mastic	120	SF	Room 433 office --1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	9"x 9" Green w/ White & Green Waves VFT	120	SF	Room 433 office, 414, 416 --1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	9"x 9" Green w/ White & Green Waves VFT Mastic	120	SF	Room 433 office --1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	9"x 9" Red w/ White Waves VFT	70	SF	Room 433 office --1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
48	9"x 9" Red w/ White Waves VFT Mastic	70	SF	Room 433 office --1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	9"x 9" Brown w/ White & Brown Streaks VFT - Abated			Room 411, 1923	ABATED	MISC								
50	9"x 9" Brown w/ White & Brown Streaks VFT Mastic - Abated			Room 411, 1923	ABATED	MISC								
51	9"x 9" White w/ Brown Specks VFT	2,900	SF	Rooms 304 (under HA# 88 & 88A), 306 (under carpet), 1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
52	9"x 9" White w/ Brown Specks VFT Mastic	2,900	SF	Rooms 304 (under HA# 88 & 88A), 306 (under carpet) --1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	12"x 12" White w/ Black & Gray Streaks VFT - REMOVED			Room 210 (Hardwood Floor), 1923	ABATED									
54	12"x 12" White w/ Black & Gray Streaks VFT Mastic - REMOVED			Room 210 (Hardwood Floor), 1923	ABATED									
55	12"x 12" Tan w/ Tan, Brown, & White Streaks VFT	850	SF	Room 303 (under HA# 87 & 87A), 1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
56	12"x 12" Tan w/ Tan, Brn, & White Strks VFT Mastic	850	SF	Room 303 (under HA# 87 & 87A), 1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	9"x 9" Gray VFT	850	SF	Room 302 (Under HA# 88 & 88A), 202 (HA# 88 &	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

# Chicago Public Schools

**School** Marshall Middle School **Unit** 41081 **Building ID** 7520  
**Address** 3900 N Lawndale Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				88A), 1923										
58	9"x 9" Gray VFT Mastic	850	SF	Room 302 (Under HA# 88 & 88A), 202 (HA# 88 & 88A), 1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	12"x 12" White w/ Brown Specks VFT - ABATED			Room 203, 205, 207, 1923	ABATED									
60	12"x 12" White w/ Brown Specks VFT Mastic (ABATED)			Room 203, 205, 207, 1923	ABATED									
61	9"x 9" Brown w/ Orange & Brown Streaks VFT	5,000	SF	Auditorium, 1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
62	9"x 9" Brown w/ Orange & Brown Streaks VFT Mastic	5,000	SF	Auditorium, 1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	9"x 9" White w/ Green & Brown Streaks VFT	1,000	SF	Auditorium, 1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
64	9"x 9" White w/ Green & Brown Streaks VFT Mastic	1,000	SF	Auditorium, 1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
65	9"x 9" Black w/ White Streaks VFT	1,000	SF	Auditorium --1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
66	9"x 9" Black w/ White Streaks VFT Mastic	1,000	SF	Auditorium --1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
67	12"x 12" Brown w/ Brown & White Streaks VFT	600	SF	Room 109 (kitchen) --1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
68	12"x 12" Brown w/ Brown & White Streaks VFT Mastic	600	SF	Room 109 (kitchen) --1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69	9"x 9" Brown w/ Dark Brown & Tan Streaks VFT	600	SF	Room 101 and Closet (Under HA# 88 & 88A), 1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
70	9"x 9" Brown w/ Drk Brown & Tan Streaks VFT Mastic	600	SF	Room 101 and Closet (Under HA# 88 & 88A), 1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
71	9"x 9" Dark Tan w/ Brown & Tan Streaks VFT	600	SF	Room 101 and Closet (Under HA# 88 & 88A), 1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
72	9"x 9" Dark Tan w/ Brown & Tan Streaks VFT Mastic	600	SF	Room 101 and Closet (Under HA# 88 & 88A), 1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
73	9"x 9" Light Tan w/ Tan Streaks VFT	200	SF	Room 101 and Closet (Under HA# 88 & 88A), 1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
74	9"x 9" Light Tan w/ Tan Streaks VFT Mastic	200	SF	Room 101 and Closet (Under HA# 88 & 88A), 1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
75	9"x 9" Dark Brown w/ Black & Tan Waves	450	SF	Room 102 (under)	CHR	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

**School** Marshall Middle School **Unit** 41081 **Building ID** 7520  
**Address** 3900 N Lawndale Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	VFT			HA#79 & 80) --1923								potential for damage		
76	9"x 9" Dark Brown w/ Black & Tan Waves VFT Mastic	450	SF	Room 102 (under HA#79 & 80) --1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
77	9"x 9" Beige w/ Brown & Dark Brown Waves VFT	450	SF	Room 102 (under HA#79 & 80) --1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
78	9"x 9" Beige w/ Brown & Drk Brown Waves VFT Mastic	450	SF	Room 102 (under HA#79 & 80) --1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
79	12"x 12" Beige w/ Brown Specks VFT	1,500	SF	Room 102, 104 --1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
80	12"x 12" Beige w/ Brown Specks VFT Mastic	1,500	SF	Room 102, 104 --1923	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
81	12"x 12" Green w/ White Streaks VFT	600	SF	Room 104 (under existing VFT) --1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
82	12"x 12" Green w/ White Streaks VFT Mastic	600	SF	Room 104 (under existing VFT) --1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
83	Brown w/ Colored Waves Linoleum	300	SF	Dressing Room (Stage), 1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
84	Brown w/ Colored Waves Linoleum Mastic	300	SF	Dressing Room (Stage), 1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
85	12" x 12" White w/ Light Tan Streaks VFT	600	SF	Room 104, 1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
86	12" x 12" White w/ Light Tan Streaks VFT Mastic	600	SF	Room 104, 1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
87	12"x12" Lt. Tan w/ Tan specks VFT	6,500	SF	Rooms 310, 309, 308, 305, 303, 205, 203, 202, 201 (1923 bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
87A	12"x12" Lt. Tan w/ Tan specks VFT Mastic	6,500	SF	Rooms 310, 309, 308, 305, 303, 205, 203, 202, 201 (1923 bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
88	12"x12" Off White w/ Tan specks VFT	3,200	SF	Rooms 307, 101, 302 (304 under carpet) --1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
88A	12"x12" Off White w/ Tan specks VFT Mastic	3,200	SF	Rooms 307, 101, 302 (304 under carpet) --1923	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Marshall Middle School **Unit** 41081 **Building ID** 7520  
**Address** 3900 N Lawndale Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Bldg										
89	12"x12" White w/ Blue Specks VFT	3,900	SF	(Bsmt Lunchroom, elevator lobby & hall), Serving Room (003A), Room 005A, 004, 002, 001 --1953 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
89A	12"x12" Off White w/ Tan specks VFT Mastic	3,900	SF	(Bsmt Lunchroom, elevator lobby & hall), Serving Room (003A), Room 005A, 004, 002, 001 --1953 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
90	12"x12" Lt. Tan w/ Tan specks VFT	3,200	SF	Rooms 223, 221, 219, Bsmt Kitchen (1953 bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
90A	12"x12" Lt. Tan w/ Tan specks VFT Mastic	3,200	SF	Rooms 223, 221, 219, Bsmt Kitchen (1953 bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
91	12"x12" Brown VFT - Abated			4th Floor Book Storage by Library (1923 bldg)	ABATED	MISC								
91A	12"x12" Brown VFT Mastic - Abated			4th Floor Book Storage by Library (1923 bldg)	ABATED	MISC								
92	12"x12" Beige VFT - Abated			4th Floor Book Storage by Library (1923 bldg)	ABATED	MISC								
92A	12"x12" Beige VFT Mastic - Abated			4th Floor Book Storage by Library (1923 bldg)	ABATED	MISC								
93	9"x9" Gray w/ Pink & White Streaks VFT - Abated			Room 428 (1923 bldg)	ABATED	MISC								
93A	9"x9" Gray w/ Pink & White Streaks VFT Mastic - Abated			Room 428 (1923 bldg)	ABATED	MISC								
94	9"x9" Maroon w/ White Streaks VFT - Abated			Room 428 (1923 bldg)	ABATED	MISC								
94A	9"x9" Maroon w/ White Streaks VFT Mastic - Abated			Room 428 (1923 bldg)	ABATED	MISC								
95	Terrazzo	10,000	SF	Corridors, Stairwells (bsmt - 4th fl.), Toilets (all floors), Rm 311, Janitor's Closets, Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

# Chicago Public Schools

**School** Marshall Middle School **Unit** 41081 **Building ID** 7520  
**Address** 3900 N Lawndale Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Main Entrance (1923 bldg)										
96	Terrazzo	5,000	SF	Corridors (bsmt - 3rd fl.), Stairwells (bsmt - 4th fl) (1953 bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
97	Cardboard Pipe Insulation	80	LF	Auditorium Balcony (behind plaster wall) - 1923 Bldg	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
98	Stage's Fire Curtain	1,000	SF	Auditorium Stage - 1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
99	9" x 9" Tan Ceiling Tile	1,500	SF	Auditorium Balcony - 1923 Bldg	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
99A	9" x 9" Tan Ceiling Tile Mastic Pucks	1,500	SF	Auditorium Balcony - 1923 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Marshall Middle School **Unit** 41081 **Building ID** 7520  
**Address** 3900 N Lawndale Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date 4/1/2025  
Inspector Name Allizon Brooks  
**100-18790** 5/15/2026  
Inspector's IDPH License Number / Expiration Date

#### Inspector's Comments

HA Number:	Inspector Comments:
01	
02	
03	
04	
05	
06	
07	
08	
09	
10	
100	
100A	
101	
102	
102A	
103	
104	
105	
106	
107	
108	
108A	
109	
109A	

# Chicago Public Schools

**School** Marshall Middle School **Unit** 41081 **Building ID** 7520  
**Address** 3900 N Lawndale Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
11	
110	
110A	
111	
112	
112A	
113	
113A	
114	
115	
116	
116A	
117	
117A	
118	
118A	
119	
119A	
12	
120	
121	
122	
122A	
123	
123A	
13	
14	
15	
16	

# Chicago Public Schools

**School** Marshall Middle School **Unit** 41081 **Building ID** 7520  
**Address** 3900 N Lawndale Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	

# Chicago Public Schools

**School** Marshall Middle School **Unit** 41081 **Building ID** 7520  
**Address** 3900 N Lawndale Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	

# Chicago Public Schools

**School** Marshall Middle School **Unit** 41081 **Building ID** 7520  
**Address** 3900 N Lawndale Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
75	
76	
77	
78	
79	
80	
81	
82	
83	
84	
85	
86	
87	
87A	
88	
88A	
89	
89A	
90	
90A	
91	
91A	
92	
92A	
93	
93A	
94	
94A	
95	

# Chicago Public Schools

**School** Marshall Middle School **Unit** 41081 **Building ID** 7520  
**Address** 3900 N Lawndale Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
96	
97	
98	
99	
99A	

**Table II**  
**Management Planner's Review**

---

# Chicago Public Schools

**School** Marshall Middle School

**Unit** 41081

**Building ID** 7520

**Address** 3900 N Lawndale Avenue

Chicago, IL, 60618

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	12"x 12" Beige w/ Blue & Orange Streaks VFT (Removed)			Lunchroom, Room 002, 1953	Abated						
02	12"x 12" Beige w/ Blue & Orange Streaks VFT Mastic (Removed)			Lunchroom, Room 002, 1953	Abated						
03	9"x 9" Brown w/ Orange & White Streaks VFT	4,500	SF	Room 217, 315, 319, 323, Basement Vestibule, 1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	9"x 9" Brown w/ Orange & White Streaks VFT Mastic	4,500	SF	Room 217, 315, 319, 323, Basement Vestibule, 1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	9"x 9" Tan w/ White & Brown Streaks VFT	200	SF	Basement Vestibule, 1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	9"x 9" Tan w/ White & Brown Streaks VFT Mastic	200	SF	Basement Vestibule, 1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	9"x 9" Gray w/ Black & White Streaks VFT	600	SF	Room 422 (storage), art room office (414) -1953 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	9"x 9" Gray w/ Black & White Streaks VFT Mastic	600	SF	Room 422 (storage), art room office (414) -1953 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	12"x 12" Blue VFT (Abated)			Room 002, 1953	Abated						
10	12"x 12" Blue VFT Mastic (Abated)			Room 002, 1953	Abated						
100	1' x 1' Tan Ceiling Tile	4,500	SF	Auditorium - 1923 Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
100A	1' x 1' Ceiling Tile Mastic Pucks	4,500	SF	Auditorium - 1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	Decorative Plaster	1,800	SF	Auditorium and Balcony - 1923 Bldg	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102	1' x 1' Ceiling Tile	9,500	SF	1st - 4th Floor Corridors, 304, 306, 103, 105, 107 -1923 Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102A	1' x 1' Ceiling Tile Mastic Pucks	9,500	SF	1st - 4th Floor Corridors, 304, 306, 103, 105, 107 -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	2' x 4' Ceiling Tile	1,600	SF	Room 311, 213 -1923 Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104	2' x 4' Ceiling Tile	15,000	SF	Throughout -1953 Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105	Fume Hood Panels (Abated)			Rooms 216-1953 Addition	Abated	MISC					
106	Lab Counter Tops - Abated			Rooms 318, 318A, 316A, 316B - 1953 Addition	Abated	MISC					
107	Yellow Linoleum Flooring - Abated			4th Floor Library Office Storage Room - 1923 Bldg.	Abated	MISC					
108	12"x12" Lt. Yellow VFT	1,200	SF	Rooms (204 and 206 under carpet tiles) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
108A	12"x12" Lt. Yellow VFT Mastic	1,200	SF	Rooms (204 and 206 under carpet tile) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Marshall Middle School

**Unit** 41081

**Building ID** 7520

**Address** 3900 N Lawndale Avenue

Chicago, IL, 60618

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
109	12"x12" Blue VFT	1,100	SF	Rooms (204 and 206 under carpet tile) 402, 404, 406, 408, 410, 411 -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
109A	12"x12" Blue VFT Mastic	1,100	SF	Rooms (204 and 206 under carpet tile) 402, 404, 406, 408, 410, 411 -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	9"x 9" Gray w/ Yellow & Green Streaks VFT	1,170	SF	4th Floor Corridor, 1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
110	12"x12" White w/ gray specks VFT	4,900	SF	Rooms (204 and 206 under carpet tile) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
110A	12"x12" White w/ gray specks VFT Mastic	4,900	SF	Rooms (204 and 206 under carpet tile) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
111	Drywall system	6,500	SF	Rooms 402, 404, 406, 408, 410 -1923 Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112	12"x12" Lt. Gray speckled VFT	150	SF	Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112A	12"x12" Lt. Gray speckled VFT Mastic	150	SF	Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113	12"x12" Dark gray w/white & gray speckles VFT	100	SF	Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113A	12"x12" Dark gray w/white & gray speckles VFT Mastic	100	SF	Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114	2' x 2' Ceiling Tile	1,000	SF	Rooms 404, 406 -1923 Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
115	Carpet Mastic	3,500	SF	4th fl library, 302, 304, 306 -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
116	12"x12" Black w/white specks VFT	450	SF	Auditorium -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
116A	12"x12" Black w/white specks VFT Mastic	450	SF	Auditorium -1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
117	12"x12" Lt. Yellow VFT	1,000	SF	Rooms 216, 316, 420, offices 133,134, conference 128, main office -1953 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
117A	12"x12" Lt. Yellow VFT Mastic	1,000	SF	Rooms 216, 316, 420, offices 133,134, conference 128, main office -1953 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
118	12"x12" Blue VFT	700	SF	Work room 132, main office hall, Rooms 216, 316, 420 -1953 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
118A	12"x12" Blue VFT Mastic	700	SF	Work room 132, main office hall,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Marshall Middle School

**Unit** 41081

**Building ID** 7520

**Address** 3900 N Lawndale Avenue

Chicago, IL, 60618

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
119	12"x12" White w/gray specks VFT	3,200	SF	Rooms 216, 316, 420 -1953 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
119A	12"x12" White w/gray specks VFT Mastic	3,200	SF	Work room 132, main office hall, Rooms 216, 316, 420, conference room 128, offices 133 & 134 -1953 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	9"x 9" Gray w/ Yellow & Green Streaks VFT Mastic	1,170	SF	4th Floor Corridor, 1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
120	12"x12" Black w/white specks VFT	500	SF	Assembly hall -1953 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
121	12"x12" Black w/white specks VFT Mastic	500	SF	Assembly hall -1953 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
122	Off white linoleum flooring	2,200	SF	Room 318, work room & storage, 281 & 218 prep-room - 1953 bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
122A	Off white Linoleum flooring adhesive	2,200	SF	Room 318, work room & storage, 281 & 218 prep-room - 1953 bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
123	Gray Linoleum flooring	80	SF	Room 218 - 1953 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
123A	Gray Linoleum flooring adhesive	80	SF	Room 218 - 1953 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	9"x 9" Green w/ White Streaks VFT	7,100	SF	Rooms 215, 317, 321, 414/416, 415, 417, 421, 425, 429 -1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	9"x 9" Green w/ White Streaks VFT Mastic	7,100	SF	Rooms 215, 317, 321, 414/416, 415, 417, 421, 425, 429 -1953	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	9"x 9" Black w/ White Streaks VFT	2,800	SF	Assembly Hall, Rooms 419, 423, 427, 431 -1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	9"x 9" Black w/ White Streaks VFT Mastic	2,800	SF	Assembly Hall, Rooms 419, 423, 427, 431 -1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	9"x 9" Khaki w/ White Streaks VFT	100	SF	Room 422(storage) --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	9"x 9" Khaki w/ White Streaks VFT Mastic	100	SF	Room 422(storage) --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	9"x 9" Aqua VFT	800	SF	Rooms 414/416 --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	9"x 9" Aqua VFT Mastic	800	SF	Rooms 414/416 --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	12"x 12" White w/ Gray Specks VFT			Room 420, 1953	Abated	MISC					
22	12"x 12" White w/ Gray Specks VFT Mastic			Room 420, 1953	Abated	MISC					
23	9"x 9" Gray VFT	1,000	SF	Rooms 124, 116, 418 --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	9"x 9" Gray VFT Mastic	1,000	SF	Rooms 124, 116, 418 --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	9"x 9" Orange VFT	180	SF	Rooms 124, 116, 418 --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	9"x 9" Orange VFT Mastic	180	SF	Rooms 124, 116, 418 --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	9"x 9" White w/ Black Streaks VFT	200	SF	4th Floor Toilet by Rm 415 and storage across from 419 --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Marshall Middle School

**Unit** 41081

**Building ID** 7520

**Address** 3900 N Lawndale Avenue

Chicago, IL, 60618

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
28	9"x 9" White w/ Black Streaks VFT Mastic	200	SF	4th Floor Toilet by Rm 415 and storage across from 419 --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	9"x 9" Pink w/ Brown & White Streaks VFT	600	SF	Rooms 415 --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	9"x 9" Pink w/ Brown & White Streaks VFT Mastic	600	SF	Rooms 415 --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12"x 12" Beige w/ Thin Black Streaks VFT (ABATED)			Room 316, 1953	Abated	MISC					
32	12"x 12" Beige w/ Thin Black Streaks VFT Mastic (ABATED)			Room 316, 1953	Abated	MISC					
33	9"x 9" Aqua w/ White Streaks VFT	80	SF	Janitor's closet (131) and adjacent toilet --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	9"x 9" Aqua w/ White Streaks VFT Mastic	80	SF	Janitor's closet (131) and adjacent toilet --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	9"x 9" Black w/ Pink & White Streaks VFT	50	SF	1st Floor North Toilet by office 134 --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	9"x 9" Black w/ Pink & White Streaks VFT Mastic	50	SF	1st Floor North Toilet by office 134 --1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	9"x 9" Tan VFT	1,700	SF	Assembly Hall, 1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	9"x 9" Tan VFT Mastic	1,700	SF	Assembly Hall, 1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	9"x 9" Brown VFT - Abated			Room 400 (Under Carpet), 1923	Abated	MISC					
40	9"x 9" Brown VFT Mastic - Abated			Room 400 (Under Carpet), 1923	Abated	MISC					
41	9"x 9" Beige VFT - Abated			Room 400 (Under Carpet), 1923	Abated	MISC					
42	9"x 9" Beige VFT Mastic - Abated			Room 400 (Under Carpet), 1923	Abated	MISC					
43	9"x 9" White w/ Green & Red Waves VFT	120	SF	Room 433 office --1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	9"x 9" White w/ Green & Red Waves VFT Mastic	120	SF	Room 433 office --1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	9"x 9" Green w/ White & Green Waves VFT	120	SF	Room 433 office, 414, 416 --1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	9"x 9" Green w/ White & Green Waves VFT Mastic	120	SF	Room 433 office --1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	9"x 9" Red w/ White Waves VFT	70	SF	Room 433 office --1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	9"x 9" Red w/ White Waves VFT Mastic	70	SF	Room 433 office --1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	9"x 9" Brown w/ White & Brown Streaks VFT - Abated			Room 411, 1923	Abated	MISC					
50	9"x 9" Brown w/ White & Brown Streaks VFT Mastic - Abated			Room 411, 1923	Abated	MISC					
51	9"x 9" White w/ Brown Specks VFT	2,900	SF	Rooms 304 (under HA# 88 & 88A), 306 (under carpet), 1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	9"x 9" White w/ Brown Specks VFT Mastic	2,900	SF	Rooms 304 (under HA# 88 & 88A), 306 (under carpet) --1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Marshall Middle School

**Unit** 41081

**Building ID** 7520

**Address** 3900 N Lawndale Avenue

Chicago, IL, 60618

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
53	12"x 12" White w/ Black & Gray Streaks VFT - REMOVED			Room 210 (Hardwood Floor), 1923	Abated						
54	12"x 12" White w/ Black & Gray Streaks VFT Mastic - REMOVED			Room 210 (Hardwood Floor), 1923	Abated						
55	12"x 12" Tan w/ Tan, Brown, & White Streaks VFT	850	SF	Room 303 (under HA# 87 & 87A), 1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	12"x 12" Tan w/ Tan, Brn, & White Strks VFT Mastic	850	SF	Room 303 (under HA# 87 & 87A), 1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	9"x 9" Gray VFT	850	SF	Room 302 (Under HA# 88 & 88A), 202 (HA# 88 & 88A), 1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	9"x 9" Gray VFT Mastic	850	SF	Room 302 (Under HA# 88 & 88A), 202 (HA# 88 & 88A), 1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	12"x 12" White w/ Brown Specks VFT - ABATED			Room 203, 205, 207, 1923	Abated						
60	12"x 12" White w/ Brown Specks VFT Mastic (ABATED)			Room 203, 205, 207, 1923	Abated						
61	9"x 9" Brown w/ Orange & Brown Streaks VFT	5,000	SF	Auditorium, 1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	9"x 9" Brown w/ Orange & Brown Streaks VFT Mastic	5,000	SF	Auditorium, 1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	9"x 9" White w/ Green & Brown Streaks VFT	1,000	SF	Auditorium, 1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	9"x 9" White w/ Green & Brown Streaks VFT Mastic	1,000	SF	Auditorium, 1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	9"x 9" Black w/ White Streaks VFT	1,000	SF	Auditorium --1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	9"x 9" Black w/ White Streaks VFT Mastic	1,000	SF	Auditorium --1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	12"x 12" Brown w/ Brown & White Streaks VFT	600	SF	Room 109 (kitchen) --1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	12"x 12" Brown w/ Brown & White Streaks VFT Mastic	600	SF	Room 109 (kitchen) --1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	9"x 9" Brown w/ Dark Brown & Tan Streaks VFT	600	SF	Room 101 and Closet (Under HA# 88 & 88A), 1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	9"x 9" Brown w/ Drk Brown & Tan Streaks VFT Mastic	600	SF	Room 101 and Closet (Under HA# 88 & 88A), 1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	9"x 9" Dark Tan w/ Brown & Tan Streaks VFT	600	SF	Room 101 and Closet (Under HA# 88 & 88A), 1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	9"x 9" Dark Tan w/ Brown & Tan Streaks VFT Mastic	600	SF	Room 101 and Closet (Under HA# 88 & 88A), 1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	9"x 9" Light Tan w/ Tan Streaks VFT	200	SF	Room 101 and Closet (Under HA# 88 & 88A), 1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	9"x 9" Light Tan w/ Tan Streaks VFT Mastic	200	SF	Room 101 and Closet (Under HA# 88 & 88A), 1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Marshall Middle School

**Unit** 41081

**Building ID** 7520

**Address** 3900 N Lawndale Avenue

Chicago, IL, 60618

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
75	9"x 9" Dark Brown w/ Black & Tan Waves VFT	450	SF	Room 102 (under HA#79 & 80) --1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	9"x 9" Dark Brown w/ Black & Tan Waves VFT Mastic	450	SF	Room 102 (under HA#79 & 80) --1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	9"x 9" Beige w/ Brown & Dark Brown Waves VFT	450	SF	Room 102 (under HA#79 & 80) --1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	9"x 9" Beige w/ Brown & Drk Brown Waves VFT Mastic	450	SF	Room 102 (under HA#79 & 80) --1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	12"x 12" Beige w/ Brown Specks VFT	1,500	SF	Room 102, 104 --1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80	12"x 12" Beige w/ Brown Specks VFT Mastic	1,500	SF	Room 102, 104 --1923	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	12"x 12" Green w/ White Streaks VFT	600	SF	Room 104 (under existing VFT) --1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
82	12"x 12" Green w/ White Streaks VFT Mastic	600	SF	Room 104 (under existing VFT) --1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
83	Brown w/ Colored Waves Linoleum	300	SF	Dressing Room (Stage), 1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
84	Brown w/ Colored Waves Linoleum Mastic	300	SF	Dressing Room (Stage), 1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
85	12" x 12" White w/ Light Tan Streaks VFT	600	SF	Room 104, 1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
86	12" x 12" White w/ Light Tan Streaks VFT Mastic	600	SF	Room 104, 1923	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
87	12"x12" Lt. Tan w/ Tan specks VFT	6,500	SF	Rooms 310, 309, 308, 305, 303, 205, 203, 202, 201 (1923 bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
87A	12"x12" Lt. Tan w/ Tan specks VFT Mastic	6,500	SF	Rooms 310, 309, 308, 305, 303, 205, 203, 202, 201 (1923 bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
88	12"x12" Off White w/ Tan specks VFT	3,200	SF	Rooms 307, 101, 302 (304 under carpet) --1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
88A	12"x12" Off White w/ Tan specks VFT Mastic	3,200	SF	Rooms 307, 101, 302 (304 under carpet) --1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
89	12"x12" White w/ Blue Specks VFT	3,900	SF	(Bsmr Lunchroom, elevator lobby & hall), Serving Room (003A), Room 005A, 004, 002, 001 --1953 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
89A	12"x12" Off White w/ Tan specks VFT Mastic	3,900	SF	(Bsmr Lunchroom, elevator lobby & hall), Serving Room (003A), Room 005A, 004, 002, 001 --1953 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
90	12"x12" Lt. Tan w/ Tan specks VFT	3,200	SF	Rooms 223, 221, 219, Bsmr Kitchen (1953 bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
90A	12"x12" Lt. Tan w/ Tan specks VFT Mastic	3,200	SF	Rooms 223, 221, 219, Bsmr Kitchen (1953 bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
91	12"x12" Brown VFT - Abated			4th Floor Book Storage by Library (1923 bldg)	Abated	MISC					

# Chicago Public Schools

**School** Marshall Middle School

**Unit** 41081

**Building ID** 7520

**Address** 3900 N Lawndale Avenue

Chicago, IL, 60618

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
91A	12"x12" Brown VFT Mastic - Abated			4th Floor Book Storage by Library (1923 bldg)	Abated	MISC					
92	12"x12" Beige VFT - Abated			4th Floor Book Storage by Library (1923 bldg)	Abated	MISC					
92A	12"x12" Beige VFT Mastic - Abated			4th Floor Book Storage by Library (1923 bldg)	Abated	MISC					
93	9"x9" Gray w/ Pink & White Streaks VFT - Abated			Room 428 (1923 bldg)	Abated	MISC					
93A	9"x9" Gray w/ Pink & White Streaks VFT Mastic - Abated			Room 428 (1923 bldg)	Abated	MISC					
94	9"x9" Maroon w/ White Streaks VFT - Abated			Room 428 (1923 bldg)	Abated	MISC					
94A	9"x9" Maroon w/ White Streaks VFT Mastic - Abated			Room 428 (1923 bldg)	Abated	MISC					
95	Terrazzo	10,000	SF	Corridors, Stairwells (bsmt - 4th fl.), Toilets (all floors), Rm 311, Janitor's Closets, Auditorium Main Entrance (1923 bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
96	Terrazzo	5,000	SF	Corridors (bsmt - 3rd fl.), Stairwells (bsmt - 4th fl) (1953 bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
97	Cardboard Pipe Insulation	80	LF	Auditorium Balcony (behind plaster wall) - 1923 Bldg	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
98	Stage's Fire Curtain	1,000	SF	Auditorium Stage - 1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99	9" x 9" Tan Ceiling Tile	1,500	SF	Auditorium Balcony - 1923 Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99A	9" x 9" Tan Ceiling Tile Mastic Pucks	1,500	SF	Auditorium Balcony - 1923 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Marshall Middle School

**Unit** 41081

**Building ID** 7520

**Address** 3900 N Lawndale Avenue

Chicago, IL, 60618

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

*Management Planner's Comments Summarized at the End of the Report*

Review Date	5/1/2025
Manager Planner Name	Jigar Shah
100-07342	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
03	
04	
05	
06	
07	
08	
09	
10	
100	
100A	
101	
102	
102A	
103	

# Chicago Public Schools

**School** Marshall Middle School

**Unit** 41081

**Building ID** 7520

**Address** 3900 N Lawndale Avenue

Chicago, IL, 60618

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
104	
105	
106	
107	
108	
108A	
109	
109A	
11	
110	
110A	
111	
112	
112A	
113	
113A	
114	
115	
116	
116A	
117	
117A	
118	
118A	
119	
119A	
12	

# Chicago Public Schools

**School** Marshall Middle School

**Unit** 41081

**Building ID** 7520

**Address** 3900 N Lawndale Avenue

Chicago, IL, 60618

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
120	
121	
122	
122A	
123	
123A	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	

# Chicago Public Schools

**School** Marshall Middle School

**Unit** 41081

**Building ID** 7520

**Address** 3900 N Lawndale Avenue

Chicago, IL, 60618

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	

# Chicago Public Schools

**School** Marshall Middle School

**Unit** 41081

**Building ID** 7520

**Address** 3900 N Lawndale Avenue

Chicago, IL, 60618

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
80	
81	
82	
83	
84	
85	
86	
87	

# Chicago Public Schools

**School** Marshall Middle School

**Unit** 41081

**Building ID** 7520

**Address** 3900 N Lawndale Avenue

Chicago, IL, 60618

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
87A	
88	
88A	
89	
89A	
90	
90A	
91	
91A	
92	
92A	
93	
93A	
94	
94A	
95	
96	
97	
98	
99	
99A	

## APPENDIX A

---

### Assessment Sheets, Drawings and Photos

**Chicago Public Schools**

**Specialty Consulting, Inc.**

***2025 AHERA REINSPECTION***

# Chicago Public Schools

Specialty Consulting, Inc.

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Allizon Brooks</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	INSPECTION DATE:	<b>4/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **12"x 12" Beige w/ Blue & Orange Streaks VFT (Removed)**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom, Room 002, 1953**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUILDING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **12"x 12" Beige w/ Blue & Orange Streaks VFT (Removed)**

MATERIAL LOCATION: **Lunchroom, Room 002, 1953**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**

MATERIAL DESCRIPTION: **12"x 12" Beige w/ Blue & Orange Streaks VFT Mastic (Removed)**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: \_\_\_\_\_

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom, Room 002, 1953**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **02**

MATERIAL DESCRIPTION: **12"x 12" Beige w/ Blue & Orange Streaks VFT Mastic (Removed)**

MATERIAL LOCATION: **Lunchroom, Room 002, 1953**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03		
MATERIAL DESCRIPTION:	9"x 9" Brown w/ Orange & White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Room 217, 315, 319, 323, Basement Vestibule, 1953</b>		
MATERIAL QUANTITY:	<b>4500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **9"x 9" Brown w/ Orange & White Streaks VFT**

MATERIAL LOCATION: **Room 217, 315, 319, 323, Basement Vestibule, 1953**

MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	04		
MATERIAL DESCRIPTION:	9"x 9" Brown w/ Orange & White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 217, 315, 319, 323, Basement Vestibule, 1953		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **9"x 9" Brown w/ Orange & White Streaks VFT Mastic**

MATERIAL LOCATION: **Room 217, 315, 319, 323, Basement Vestibule, 1953**

MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05		
MATERIAL DESCRIPTION:	9"x 9" Tan w/ White & Brown Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement Vestibule, 1953		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUILDING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **9"x 9" Tan w/ White & Brown Streaks VFT**

MATERIAL LOCATION: **Basement Vestibule, 1953**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06		
MATERIAL DESCRIPTION:	9"x 9" Tan w/ White & Brown Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement Vestibule, 1953		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUILDING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **9"x 9" Tan w/ White & Brown Streaks VFT Mastic**

MATERIAL LOCATION: **Basement Vestibule, 1953**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07		
MATERIAL DESCRIPTION:	9"x 9" Gray w/ Black & White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 422 (storage), art room office (414) -1953 Bldg		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **07**

MATERIAL DESCRIPTION: **9"x 9" Gray w/ Black & White Streaks VFT**

MATERIAL LOCATION: **Room 422 (storage), art room office (414) -1953 Bldg**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08		
MATERIAL DESCRIPTION:	9"x 9" Gray w/ Black & White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 422 (storage), art room office (414) -1953 Bldg		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **9"x 9" Gray w/ Black & White Streaks VFT Mastic**

MATERIAL LOCATION: **Room 422 (storage), art room office (414) -1953 Bldg**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **12"x 12" Blue VFT (Abated)**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 002, 1953**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **12"x 12" Blue VFT (Abated)**

MATERIAL LOCATION: **Room 002, 1953**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **12"x 12" Blue VFT Mastic (Abated)**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 002, 1953**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **12"x 12" Blue VFT Mastic (Abated)**

MATERIAL LOCATION: **Room 002, 1953**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	100		
MATERIAL DESCRIPTION:	1' x 1' Tan Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium - 1923 Bldg		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **100**

MATERIAL DESCRIPTION: **1' x 1' Tan Ceiling Tile**

MATERIAL LOCATION: **Auditorium - 1923 Bldg**

MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	100A		
MATERIAL DESCRIPTION:	1' x 1' Ceiling Tile Mastic Pucks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium - 1923 Bldg		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **100A**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile Mastic Pucks**

MATERIAL LOCATION: **Auditorium - 1923 Bldg**

MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	101		
MATERIAL DESCRIPTION:	Decorative Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium and Balcony - 1923 Bldg		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **101**

MATERIAL DESCRIPTION: **Decorative Plaster**

MATERIAL LOCATION: **Auditorium and Balcony - 1923 Bldg**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	102		
MATERIAL DESCRIPTION:	1' x 1' Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st - 4th Floor Corridors, 304, 306, 103, 105, 107 -1923 Bldg		
MATERIAL QUANTITY:	9500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **102**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**

MATERIAL LOCATION: **1st - 4th Floor Corridors, 304, 306, 103, 105, 107 -1923 Bldg**

MATERIAL QUANTITY: **9500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	102A		
MATERIAL DESCRIPTION:	1' x 1' Ceiling Tile Mastic Pucks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st - 4th Floor Corridors, 304, 306, 103, 105, 107 -1923 Bldg		
MATERIAL QUANTITY:	9500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **102A**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile Mastic Pucks**

MATERIAL LOCATION: **1st - 4th Floor Corridors, 304, 306, 103, 105, 107 -1923 Bldg**

MATERIAL QUANTITY: **9500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	103		
MATERIAL DESCRIPTION:	2' x 4' Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 311, 213 -1923 Bldg		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **103**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**

MATERIAL LOCATION: **Room 311, 213 -1923 Bldg**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	104		
MATERIAL DESCRIPTION:	2' x 4' Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout -1953 Bldg		
MATERIAL QUANTITY:	15000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **104**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**

MATERIAL LOCATION: **Throughout -1953 Bldg**

MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	105		
MATERIAL DESCRIPTION:	Fume Hood Panels (Abated)		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 216- 1953 Addition

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **105**

MATERIAL DESCRIPTION: **Fume Hood Panels (Abated)**

MATERIAL LOCATION: **Rooms 216- 1953 Addition**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**

MATERIAL DESCRIPTION: **Lab Counter Tops - Abated**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 318, 318A, 316A, 316B - 1953 Addition**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUILDING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **106**

MATERIAL DESCRIPTION: **Lab Counter Tops - Abated**

MATERIAL LOCATION: **Rooms 318, 318A, 316A, 316B - 1953 Addition**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 107

MATERIAL DESCRIPTION: Yellow Linoleum Flooring - Abated

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 4th Floor Library Office Storage Room - 1923 Bldg.

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **107**

MATERIAL DESCRIPTION: **Yellow Linoleum Flooring - Abated**

MATERIAL LOCATION: **4th Floor Library Office Storage Room - 1923 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	108		
MATERIAL DESCRIPTION:	12"x12" Lt. Yellow VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Rooms (204 and 206 under carpet tiles) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **108**

MATERIAL DESCRIPTION: **12"x12" Lt. Yellow VFT**

MATERIAL LOCATION: **Rooms (204 and 206 under carpet tiles) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	108A		
MATERIAL DESCRIPTION:	12"x12" Lt. Yellow VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms (204 and 206 under carpet tile) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **108A**

MATERIAL DESCRIPTION: **12"x12" Lt. Yellow VFT Mastic**

MATERIAL LOCATION: **Rooms (204 and 206 under carpet tile) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	109		
MATERIAL DESCRIPTION:	12"x12" Blue VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Rooms (204 and 206 under carpet tile) 402, 404, 406, 408, 410, 411 -1923 Bldg		
MATERIAL QUANTITY:	1100	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **109**

MATERIAL DESCRIPTION: **12"x12" Blue VFT**

MATERIAL LOCATION: **Rooms (204 and 206 under carpet tile) 402, 404, 406, 408, 410, 411 -1923 Bldg**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	109A		
MATERIAL DESCRIPTION:	12"x12" Blue VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms (204 and 206 under carpet tile) 402, 404, 406, 408, 410, 411 -1923 Bldg		
MATERIAL QUANTITY:	1100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **109A**

MATERIAL DESCRIPTION: **12"x12" Blue VFT Mastic**

MATERIAL LOCATION: **Rooms (204 and 206 under carpet tile) 402, 404, 406, 408, 410, 411 -1923 Bldg**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	9"x 9" Gray w/ Yellow & Green Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>4th Floor Corridor, 1953</b>		
MATERIAL QUANTITY:	<b>1170</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **9"x 9" Gray w/ Yellow & Green Streaks VFT**

MATERIAL LOCATION: **4th Floor Corridor, 1953**

MATERIAL QUANTITY: **1170** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	110		
MATERIAL DESCRIPTION:	12"x12" White w/ gray specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Rooms (204 and 206 under carpet tile) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg		
MATERIAL QUANTITY:	4900	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **110**

MATERIAL DESCRIPTION: **12"x12" White w/ gray specks VFT**

MATERIAL LOCATION: **Rooms (204 and 206 under carpet tile) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg**

MATERIAL QUANTITY: **4900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	110A		
MATERIAL DESCRIPTION:	12"x12" White w/ gray specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms (204 and 206 under carpet tile) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg		
MATERIAL QUANTITY:	4900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **110A**

MATERIAL DESCRIPTION: **12"x12" White w/ gray specks VFT Mastic**

MATERIAL LOCATION: **Rooms (204 and 206 under carpet tile) 213, 402, 404, 406, 408, 410, 411 -1923 Bldg**

MATERIAL QUANTITY: **4900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	111		
MATERIAL DESCRIPTION:	Drywall system		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Rooms 402, 404, 406, 408, 410 -1923 Bldg		
MATERIAL QUANTITY:	6500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **111**

MATERIAL DESCRIPTION: **Drywall system**

MATERIAL LOCATION: **Rooms 402, 404, 406, 408, 410 -1923 Bldg**

MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	112		
MATERIAL DESCRIPTION:	12"x12" Lt. Gray speckled VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **112**

MATERIAL DESCRIPTION: **12"x12" Lt. Gray speckled VFT**

MATERIAL LOCATION: **Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	112A		
MATERIAL DESCRIPTION:	12"x12" Lt. Gray speckled VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **112A**

MATERIAL DESCRIPTION: **12"x12" Lt. Gray speckled VFT Mastic**

MATERIAL LOCATION: **Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	113		
MATERIAL DESCRIPTION:	12"x12" Dark gray w/white & gray speckles VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **113**

MATERIAL DESCRIPTION: **12"x12" Dark gray w/white & gray speckles VFT**

MATERIAL LOCATION: **Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	113A		
MATERIAL DESCRIPTION:	12"x12" Dark gray w/white & gray speckles VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **113A**

MATERIAL DESCRIPTION: **12"x12" Dark gray w/white & gray speckles VFT Mastic**

MATERIAL LOCATION: **Elevator lobby 2nd, 3rd and 4th floor -1923 Bldg**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	114		
MATERIAL DESCRIPTION:	2' x 2' Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 404, 406 -1923 Bldg		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **114**

MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile**

MATERIAL LOCATION: **Rooms 404, 406 -1923 Bldg**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	115		
MATERIAL DESCRIPTION:	Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	4th fl library, 302, 304, 306 -1923 Bldg		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **115**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **4th fl library, 302, 304, 306 -1923 Bldg**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	116		
MATERIAL DESCRIPTION:	12"x12" Black w/white specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Auditorium -1923 Bldg</b>		
MATERIAL QUANTITY:	<b>450</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **116**

MATERIAL DESCRIPTION: **12"x12" Black w/white specks VFT**

MATERIAL LOCATION: **Auditorium -1923 Bldg**

MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	116A		
MATERIAL DESCRIPTION:	12"x12" Black w/white specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium -1923 Bldg		
MATERIAL QUANTITY:	450	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **116A**

MATERIAL DESCRIPTION: **12"x12" Black w/white specks VFT Mastic**

MATERIAL LOCATION: **Auditorium -1923 Bldg**

MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	117		
MATERIAL DESCRIPTION:	12"x12" Lt. Yellow VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Rooms 216, 316, 420, offices 133,134, conference 128, main office -1953 Bldg		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **117**

MATERIAL DESCRIPTION: **12"x12" Lt. Yellow VFT**

MATERIAL LOCATION: **Rooms 216, 316, 420, offices 133,134, conference 128, main office -1953 Bldg**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	117A		
MATERIAL DESCRIPTION:	12"x12" Lt. Yellow VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 216, 316, 420, offices 133,134, conference 128, main office -1953 Bldg		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **117A**

MATERIAL DESCRIPTION: **12"x12" Lt. Yellow VFT Mastic**

MATERIAL LOCATION: **Rooms 216, 316, 420, offices 133,134, conference 128, main office -1953 Bldg**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	118		
MATERIAL DESCRIPTION:	12"x12" Blue VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Work room 132, main office hall, Rooms 216, 316, 420 -1953 Bldg		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **118**

MATERIAL DESCRIPTION: **12"x12" Blue VFT**

MATERIAL LOCATION: **Work room 132, main office hall, Rooms 216, 316, 420 -1953 Bldg**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	118A		
MATERIAL DESCRIPTION:	12"x12" Blue VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Work room 132, main office hall, Rooms 216, 316, 420 -1953 Bldg		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **118A**

MATERIAL DESCRIPTION: **12"x12" Blue VFT Mastic**

MATERIAL LOCATION: **Work room 132, main office hall, Rooms 216, 316, 420 -1953 Bldg**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	119		
MATERIAL DESCRIPTION:	12"x12" White w/gray specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Work room 132, main office hall, Rooms 216, 316, 420, conference room 128, offices 133 & 134 -1953 Bldg		
MATERIAL QUANTITY:	3200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA:	<b>119</b>				
MATERIAL DESCRIPTION:	<b>12"x12" White w/gray specks VFT</b>				
MATERIAL LOCATION:	<b>Work room 132, main office hall, Rooms 216, 316, 420, conference room 128, offices 133 &amp; 134 -1953 Bldg</b>				
MATERIAL QUANTITY:	<b>3200</b>	MATERIAL UNITS:	<b>SF</b>		
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	119A		
MATERIAL DESCRIPTION:	12"x12" White w/gray specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Work room 132, main office hall, Rooms 216, 316, 420, conference room 128, offices 133 & 134 -1953 Bldg**

MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **119A**

MATERIAL DESCRIPTION: **12"x12" White w/gray specks VFT Mastic**

MATERIAL LOCATION: **Work room 132, main office hall, Rooms 216, 316, 420, conference room 128, offices 133 & 134 -1953 Bldg**

MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12		
MATERIAL DESCRIPTION:	9"x 9" Gray w/ Yellow & Green Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	4th Floor Corridor, 1953		
MATERIAL QUANTITY:	1170	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **9"x 9" Gray w/ Yellow & Green Streaks VFT Mastic**

MATERIAL LOCATION: **4th Floor Corridor, 1953**

MATERIAL QUANTITY: **1170** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	120		
MATERIAL DESCRIPTION:	12"x12" Black w/white specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Assembly hall -1953 Bldg		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **120**

MATERIAL DESCRIPTION: **12"x12" Black w/white specks VFT**

MATERIAL LOCATION: **Assembly hall -1953 Bldg**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	121		
MATERIAL DESCRIPTION:	12"x12" Black w/white specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Assembly hall -1953 Bldg		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **121**

MATERIAL DESCRIPTION: **12"x12" Black w/white specks VFT Mastic**

MATERIAL LOCATION: **Assembly hall -1953 Bldg**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	122		
MATERIAL DESCRIPTION:	Off white linoleum flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Room 318, work room & storage, 281 & 218 prep-room - 1953 bldg		
MATERIAL QUANTITY:	2200	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **122**

MATERIAL DESCRIPTION: **Off white linoleum flooring**

MATERIAL LOCATION: **Room 318, work room & storage, 281 & 218 prep-room - 1953 bldg**

MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	122A		
MATERIAL DESCRIPTION:	Off white Linoleum flooring adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 318, work room & storage, 281 & 218 prep-room - 1953 bldg		
MATERIAL QUANTITY:	2200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **122A**

MATERIAL DESCRIPTION: **Off white Linoleum flooring adhesive**

MATERIAL LOCATION: **Room 318, work room & storage, 281 & 218 prep-room - 1953 bldg**

MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	123		
MATERIAL DESCRIPTION:	Gray Linoleum flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Room 218 - 1953 Bldg		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **123**

MATERIAL DESCRIPTION: **Gray Linoleum flooring**

MATERIAL LOCATION: **Room 218 - 1953 Bldg**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	123A		
MATERIAL DESCRIPTION:	Gray Linoleum flooring adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 218 - 1953 Bldg		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **123A**

MATERIAL DESCRIPTION: **Gray Linoleum flooring adhesive**

MATERIAL LOCATION: **Room 218 - 1953 Bldg**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	9"x 9" Green w/ White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Rooms 215, 317, 321, 414/416, 415, 417, 421, 425, 429 -1953		
MATERIAL QUANTITY:	7100	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **9"x 9" Green w/ White Streaks VFT**

MATERIAL LOCATION: **Rooms 215, 317, 321, 414/416, 415, 417, 421, 425, 429 -1953**

MATERIAL QUANTITY: **7100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	9"x 9" Green w/ White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 215, 317, 321, 414/416, 415, 417, 421, 425, 429 -1953		
MATERIAL QUANTITY:	7100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **9"x 9" Green w/ White Streaks VFT Mastic**

MATERIAL LOCATION: **Rooms 215, 317, 321, 414/416, 415, 417, 421, 425, 429 -1953**

MATERIAL QUANTITY: **7100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	9"x 9" Black w/ White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Assembly Hall, Rooms 419, 423, 427, 431 -1953		
MATERIAL QUANTITY:	2800	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **9"x 9" Black w/ White Streaks VFT**

MATERIAL LOCATION: **Assembly Hall, Rooms 419, 423, 427, 431 -1953**

MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	9"x 9" Black w/ White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Assembly Hall, Rooms 419, 423, 427, 431 -1953		
MATERIAL QUANTITY:	2800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **9"x 9" Black w/ White Streaks VFT Mastic**

MATERIAL LOCATION: **Assembly Hall, Rooms 419, 423, 427, 431 -1953**

MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	9"x 9" Khaki w/ White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Room 422(storage) --1953		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **9"x 9" Khaki w/ White Streaks VFT**

MATERIAL LOCATION: **Room 422(storage) --1953**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18		
MATERIAL DESCRIPTION:	9"x 9" Khaki w/ White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 422(storage) --1953		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **9"x 9" Khaki w/ White Streaks VFT Mastic**

MATERIAL LOCATION: **Room 422(storage) --1953**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	9"x 9" Aqua VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Rooms 414/416 --1953		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **9"x 9" Aqua VFT**

MATERIAL LOCATION: **Rooms 414/416 --1953**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	9"x 9" Aqua VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 414/416 --1953		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **9"x 9" Aqua VFT Mastic**

MATERIAL LOCATION: **Rooms 414/416 --1953**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 21

MATERIAL DESCRIPTION: 12"x 12" White w/ Gray Specks VFT

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 420, 1953

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **12"x 12" White w/ Gray Specks VFT**

MATERIAL LOCATION: **Room 420, 1953**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 22

MATERIAL DESCRIPTION: 12"x 12" White w/ Gray Specks VFT Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 420, 1953

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **12"x 12" White w/ Gray Specks VFT Mastic**

MATERIAL LOCATION: **Room 420, 1953**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	9"x 9" Gray VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Rooms 124, 116, 418 --1953		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **9"x 9" Gray VFT**

MATERIAL LOCATION: **Rooms 124, 116, 418 --1953**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	9"x 9" Gray VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 124, 116, 418 --1953		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **9"x 9" Gray VFT Mastic**

MATERIAL LOCATION: **Rooms 124, 116, 418 --1953**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	9"x 9" Orange VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Rooms 124, 116, 418 --1953		
MATERIAL QUANTITY:	180	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **9"x 9" Orange VFT**

MATERIAL LOCATION: **Rooms 124, 116, 418 --1953**

MATERIAL QUANTITY: **180** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	9"x 9" Orange VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 124, 116, 418 --1953		
MATERIAL QUANTITY:	180	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **9"x 9" Orange VFT Mastic**

MATERIAL LOCATION: **Rooms 124, 116, 418 --1953**

MATERIAL QUANTITY: **180** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	9"x 9" White w/ Black Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	4th Floor Toilet by Rm 415 and storage across from 419 --1953		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **9"x 9" White w/ Black Streaks VFT**

MATERIAL LOCATION: **4th Floor Toilet by Rm 415 and storage across from 419 --1953**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	9"x 9" White w/ Black Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	4th Floor Toilet by Rm 415 and storage across from 419 --1953		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **9"x 9" White w/ Black Streaks VFT Mastic**

MATERIAL LOCATION: **4th Floor Toilet by Rm 415 and storage across from 419 --1953**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	9"x 9" Pink w/ Brown & White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Rooms 415 --1953		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **9"x 9" Pink w/ Brown & White Streaks VFT**

MATERIAL LOCATION: **Rooms 415 --1953**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	9"x 9" Pink w/ Brown & White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 415 --1953		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **9"x 9" Pink w/ Brown & White Streaks VFT Mastic**

MATERIAL LOCATION: **Rooms 415 --1953**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 31

MATERIAL DESCRIPTION: 12"x 12" Beige w/ Thin Black Streaks VFT (ABATED)

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 316, 1953

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12"x 12" Beige w/ Thin Black Streaks VFT (ABATED)**

MATERIAL LOCATION: **Room 316, 1953**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32

MATERIAL DESCRIPTION: 12"x 12" Beige w/ Thin Black Streaks VFT Mastic (ABATED)

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 316, 1953

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **12"x 12" Beige w/ Thin Black Streaks VFT Mastic (ABATED)**

MATERIAL LOCATION: **Room 316, 1953**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	9"x 9" Aqua w/ White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Janitor's closet (131) and adjacent toilet --1953		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **9"x 9" Aqua w/ White Streaks VFT**

MATERIAL LOCATION: **Janitor's closet (131) and adjacent toilet --1953**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	9"x 9" Aqua w/ White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Janitor's closet (131) and adjacent toilet --1953		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **9"x 9" Aqua w/ White Streaks VFT Mastic**

MATERIAL LOCATION: **Janitor's closet (131) and adjacent toilet --1953**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	9"x 9" Black w/ Pink & White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor North Toilet by office 134 --1953		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **9"x 9" Black w/ Pink & White Streaks VFT**

MATERIAL LOCATION: **1st Floor North Toilet by office 134 --1953**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	9"x 9" Black w/ Pink & White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor North Toilet by office 134 --1953		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **9"x 9" Black w/ Pink & White Streaks VFT Mastic**

MATERIAL LOCATION: **1st Floor North Toilet by office 134 --1953**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	9"x 9" Tan VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Assembly Hall, 1953		
MATERIAL QUANTITY:	1700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **9"x 9" Tan VFT**

MATERIAL LOCATION: **Assembly Hall, 1953**

MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	9"x 9" Tan VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Assembly Hall, 1953		
MATERIAL QUANTITY:	1700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **9"x 9" Tan VFT Mastic**

MATERIAL LOCATION: **Assembly Hall, 1953**

MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 39

MATERIAL DESCRIPTION: 9"x 9" Brown VFT - Abated

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 400 (Under Carpet), 1923

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **9"x 9" Brown VFT - Abated**

MATERIAL LOCATION: **Room 400 (Under Carpet), 1923**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 40

MATERIAL DESCRIPTION: 9"x 9" Brown VFT Mastic - Abated

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 400 (Under Carpet), 1923

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUILDING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **9"x 9" Brown VFT Mastic - Abated**

MATERIAL LOCATION: **Room 400 (Under Carpet), 1923**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 41

MATERIAL DESCRIPTION: 9"x 9" Beige VFT - Abated

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 400 (Under Carpet), 1923

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUILDING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **9"x 9" Beige VFT - Abated**

MATERIAL LOCATION: **Room 400 (Under Carpet), 1923**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 42

MATERIAL DESCRIPTION: 9"x 9" Beige VFT Mastic - Abated

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 400 (Under Carpet), 1923

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUILDING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **9"x 9" Beige VFT Mastic - Abated**

MATERIAL LOCATION: **Room 400 (Under Carpet), 1923**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	9"x 9" White w/ Green & Red Waves VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Room 433 office --1923		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **9"x 9" White w/ Green & Red Waves VFT**

MATERIAL LOCATION: **Room 433 office --1923**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	9"x 9" White w/ Green & Red Waves VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 433 office --1923		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **9"x 9" White w/ Green & Red Waves VFT Mastic**

MATERIAL LOCATION: **Room 433 office --1923**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	9"x 9" Green w/ White & Green Waves VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 433 office, 414, 416 --1923		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **9"x 9" Green w/ White & Green Waves VFT**

MATERIAL LOCATION: **Room 433 office, 414, 416 --1923**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	9"x 9" Green w/ White & Green Waves VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 433 office --1923		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **9"x 9" Green w/ White & Green Waves VFT Mastic**

MATERIAL LOCATION: **Room 433 office --1923**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47		
MATERIAL DESCRIPTION:	9"x 9" Red w/ White Waves VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Room 433 office --1923		
MATERIAL QUANTITY:	<b>70</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **9"x 9" Red w/ White Waves VFT**

MATERIAL LOCATION: **Room 433 office --1923**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	9"x 9" Red w/ White Waves VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 433 office --1923		
MATERIAL QUANTITY:	70	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **9"x 9" Red w/ White Waves VFT Mastic**

MATERIAL LOCATION: **Room 433 office --1923**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 49

MATERIAL DESCRIPTION: 9"x 9" Brown w/ White & Brown Streaks VFT - Abated

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 411, 1923

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUILDING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **9"x 9" Brown w/ White & Brown Streaks VFT - Abated**

MATERIAL LOCATION: **Room 411, 1923**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **9"x 9" Brown w/ White & Brown Streaks VFT Mastic - Abated**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 411, 1923**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **9"x 9" Brown w/ White & Brown Streaks VFT Mastic - Abated**

MATERIAL LOCATION: **Room 411, 1923**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	9"x 9" White w/ Brown Specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Rooms 304 (under HA# 88 & 88A), 306 (under carpet), 1923		
MATERIAL QUANTITY:	2900	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **9"x 9" White w/ Brown Specks VFT**

MATERIAL LOCATION: **Rooms 304 (under HA# 88 & 88A), 306 (under carpet), 1923**

MATERIAL QUANTITY: **2900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	9"x 9" White w/ Brown Specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 304 (under HA# 88 & 88A), 306 (under carpet) --1923		
MATERIAL QUANTITY:	2900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **9"x 9" White w/ Brown Specks VFT Mastic**

MATERIAL LOCATION: **Rooms 304 (under HA# 88 & 88A), 306 (under carpet) --1923**

MATERIAL QUANTITY: **2900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53	
MATERIAL DESCRIPTION:	12"x 12" White w/ Black & Gray Streaks VFT - REMOVED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 210 (Hardwood Floor), 1923

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **12"x 12" White w/ Black & Gray Streaks VFT - REMOVED**

MATERIAL LOCATION: **Room 210 (Hardwood Floor), 1923**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 54

MATERIAL DESCRIPTION: 12"x 12" White w/ Black & Gray Streaks VFT Mastic - REMOVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 210 (Hardwood Floor), 1923

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUILDING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **12"x 12" White w/ Black & Gray Streaks VFT Mastic - REMOVED**

MATERIAL LOCATION: **Room 210 (Hardwood Floor), 1923**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55		
MATERIAL DESCRIPTION:	12"x 12" Tan w/ Tan, Brown, & White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Room 303 (under HA# 87 & 87A), 1923		
MATERIAL QUANTITY:	850	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **12"x 12" Tan w/ Tan, Brown, & White Streaks VFT**

MATERIAL LOCATION: **Room 303 (under HA# 87 & 87A), 1923**

MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	56		
MATERIAL DESCRIPTION:	12"x 12" Tan w/ Tan, Brn, & White Strks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 303 (under HA# 87 & 87A), 1923		
MATERIAL QUANTITY:	850	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **12"x 12" Tan w/ Tan, Brn, & White Strks VFT Mastic**

MATERIAL LOCATION: **Room 303 (under HA# 87 & 87A), 1923**

MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	57		
MATERIAL DESCRIPTION:	9"x 9" Gray VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Room 302 (Under HA# 88 & 88A), 202 (HA# 88 & 88A), 1923		
MATERIAL QUANTITY:	<b>850</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **9"x 9" Gray VFT**

MATERIAL LOCATION: **Room 302 (Under HA# 88 & 88A), 202 (HA# 88 & 88A), 1923**

MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	9"x 9" Gray VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 302 (Under HA# 88 & 88A), 202 (HA# 88 & 88A), 1923		
MATERIAL QUANTITY:	850	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **9"x 9" Gray VFT Mastic**

MATERIAL LOCATION: **Room 302 (Under HA# 88 & 88A), 202 (HA# 88 & 88A), 1923**

MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 59

MATERIAL DESCRIPTION: 12"x 12" White w/ Brown Specks VFT - ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 203, 205, 207, 1923

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUILDING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **12"x 12" White w/ Brown Specks VFT - ABATED**

MATERIAL LOCATION: **Room 203, 205, 207, 1923**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 60

MATERIAL DESCRIPTION: 12"x 12" White w/ Brown Specks VFT Mastic (ABATED)

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 203, 205, 207, 1923

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUILDING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **12"x 12" White w/ Brown Specks VFT Mastic (ABATED)**

MATERIAL LOCATION: **Room 203, 205, 207, 1923**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	61		
MATERIAL DESCRIPTION:	9"x 9" Brown w/ Orange & Brown Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Auditorium, 1923</b>		
MATERIAL QUANTITY:	<b>5000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **9"x 9" Brown w/ Orange & Brown Streaks VFT**

MATERIAL LOCATION: **Auditorium, 1923**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	62		
MATERIAL DESCRIPTION:	9"x 9" Brown w/ Orange & Brown Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium, 1923		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **9"x 9" Brown w/ Orange & Brown Streaks VFT Mastic**

MATERIAL LOCATION: **Auditorium, 1923**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	63		
MATERIAL DESCRIPTION:	9"x 9" White w/ Green & Brown Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Auditorium, 1923</b>		
MATERIAL QUANTITY:	<b>1000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **9"x 9" White w/ Green & Brown Streaks VFT**

MATERIAL LOCATION: **Auditorium, 1923**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	64		
MATERIAL DESCRIPTION:	9"x 9" White w/ Green & Brown Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium, 1923		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **9"x 9" White w/ Green & Brown Streaks VFT Mastic**

MATERIAL LOCATION: **Auditorium, 1923**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	65		
MATERIAL DESCRIPTION:	9"x 9" Black w/ White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Auditorium --1923</b>		
MATERIAL QUANTITY:	<b>1000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **9"x 9" Black w/ White Streaks VFT**

MATERIAL LOCATION: **Auditorium --1923**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	66		
MATERIAL DESCRIPTION:	9"x 9" Black w/ White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium --1923		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **9"x 9" Black w/ White Streaks VFT Mastic**

MATERIAL LOCATION: **Auditorium --1923**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	67		
MATERIAL DESCRIPTION:	12"x 12" Brown w/ Brown & White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Room 109 (kitchen) --1923		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **12"x 12" Brown w/ Brown & White Streaks VFT**

MATERIAL LOCATION: **Room 109 (kitchen) --1923**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	68		
MATERIAL DESCRIPTION:	12"x 12" Brown w/ Brown & White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 109 (kitchen) --1923		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **12"x 12" Brown w/ Brown & White Streaks VFT Mastic**

MATERIAL LOCATION: **Room 109 (kitchen) --1923**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	69		
MATERIAL DESCRIPTION:	9"x 9" Brown w/ Dark Brown & Tan Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 101 and Closet (Under HA# 88 & 88A), 1923		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **9"x 9" Brown w/ Dark Brown & Tan Streaks VFT**

MATERIAL LOCATION: **Room 101 and Closet (Under HA# 88 & 88A), 1923**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	70		
MATERIAL DESCRIPTION:	9"x 9" Brown w/ Drk Brown & Tan Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 101 and Closet (Under HA# 88 & 88A), 1923		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **9"x 9" Brown w/ Drk Brown & Tan Streaks VFT Mastic**

MATERIAL LOCATION: **Room 101 and Closet (Under HA# 88 & 88A), 1923**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	71		
MATERIAL DESCRIPTION:	9"x 9" Dark Tan w/ Brown & Tan Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 101 and Closet (Under HA# 88 & 88A), 1923		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **9"x 9" Dark Tan w/ Brown & Tan Streaks VFT**

MATERIAL LOCATION: **Room 101 and Closet (Under HA# 88 & 88A), 1923**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	72		
MATERIAL DESCRIPTION:	9"x 9" Dark Tan w/ Brown & Tan Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 101 and Closet (Under HA# 88 & 88A), 1923		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **9"x 9" Dark Tan w/ Brown & Tan Streaks VFT Mastic**

MATERIAL LOCATION: **Room 101 and Closet (Under HA# 88 & 88A), 1923**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	73		
MATERIAL DESCRIPTION:	9"x 9" Light Tan w/ Tan Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 101 and Closet (Under HA# 88 & 88A), 1923		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **9"x 9" Light Tan w/ Tan Streaks VFT**

MATERIAL LOCATION: **Room 101 and Closet (Under HA# 88 & 88A), 1923**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	74		
MATERIAL DESCRIPTION:	9"x 9" Light Tan w/ Tan Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 101 and Closet (Under HA# 88 & 88A), 1923		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **9"x 9" Light Tan w/ Tan Streaks VFT Mastic**

MATERIAL LOCATION: **Room 101 and Closet (Under HA# 88 & 88A), 1923**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	75		
MATERIAL DESCRIPTION:	9"x 9" Dark Brown w/ Black & Tan Waves VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 102 (under HA#79 & 80) --1923		
MATERIAL QUANTITY:	450	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **9"x 9" Dark Brown w/ Black & Tan Waves VFT**

MATERIAL LOCATION: **Room 102 (under HA#79 & 80) --1923**

MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	76		
MATERIAL DESCRIPTION:	9"x 9" Dark Brown w/ Black & Tan Waves VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 102 (under HA#79 & 80) --1923		
MATERIAL QUANTITY:	450	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUILDING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **9"x 9" Dark Brown w/ Black & Tan Waves VFT Mastic**

MATERIAL LOCATION: **Room 102 (under HA#79 & 80) --1923**

MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	77		
MATERIAL DESCRIPTION:	9"x 9" Beige w/ Brown & Dark Brown Waves VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 102 (under HA#79 & 80) --1923		
MATERIAL QUANTITY:	450	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **9"x 9" Beige w/ Brown & Dark Brown Waves VFT**

MATERIAL LOCATION: **Room 102 (under HA#79 & 80) --1923**

MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	78		
MATERIAL DESCRIPTION:	9"x 9" Beige w/ Brown & Drk Brown Waves VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 102 (under HA#79 & 80) --1923		
MATERIAL QUANTITY:	450	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **9"x 9" Beige w/ Brown & Drk Brown Waves VFT Mastic**

MATERIAL LOCATION: **Room 102 (under HA#79 & 80) --1923**

MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	79		
MATERIAL DESCRIPTION:	12"x 12" Beige w/ Brown Specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Room 102, 104 --1923		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **12"x 12" Beige w/ Brown Specks VFT**

MATERIAL LOCATION: **Room 102, 104 --1923**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	80		
MATERIAL DESCRIPTION:	12"x 12" Beige w/ Brown Specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 102, 104 --1923		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **12"x 12" Beige w/ Brown Specks VFT Mastic**

MATERIAL LOCATION: **Room 102, 104 --1923**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	81		
MATERIAL DESCRIPTION:	12"x 12' Green w/ White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 104 (under existing VFT) --1923		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **12"x 12' Green w/ White Streaks VFT**

MATERIAL LOCATION: **Room 104 (under existing VFT) --1923**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	82		
MATERIAL DESCRIPTION:	12"x 12' Green w/ White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 104 (under existing VFT) --1923		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **12"x 12' Green w/ White Streaks VFT Mastic**

MATERIAL LOCATION: **Room 104 (under existing VFT) --1923**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	83		
MATERIAL DESCRIPTION:	Brown w/ Colored Waves Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Dressing Room (Stage), 1923		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **Brown w/ Colored Waves Linoleum**

MATERIAL LOCATION: **Dressing Room (Stage), 1923**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	84		
MATERIAL DESCRIPTION:	Brown w/ Colored Waves Linoleum Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Dressing Room (Stage), 1923		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **Brown w/ Colored Waves Linoleum Mastic**

MATERIAL LOCATION: **Dressing Room (Stage), 1923**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	85		
MATERIAL DESCRIPTION:	12" x 12" White w/ Light Tan Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Room 104, 1923</b>		
MATERIAL QUANTITY:	<b>600</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **85**

MATERIAL DESCRIPTION: **12" x 12" White w/ Light Tan Streaks VFT**

MATERIAL LOCATION: **Room 104, 1923**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	86		
MATERIAL DESCRIPTION:	12" x 12" White w/ Light Tan Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 104, 1923		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUILDING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **86**

MATERIAL DESCRIPTION: **12" x 12" White w/ Light Tan Streaks VFT Mastic**

MATERIAL LOCATION: **Room 104, 1923**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	87		
MATERIAL DESCRIPTION:	12"x12" Lt. Tan w/ Tan specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Rooms 310, 309, 308, 305, 303, 205, 203, 202, 201 (1923 bldg)		
MATERIAL QUANTITY:	6500	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **87**

MATERIAL DESCRIPTION: **12"x12" Lt. Tan w/ Tan specks VFT**

MATERIAL LOCATION: **Rooms 310, 309, 308, 305, 303, 205, 203, 202, 201 (1923 bldg)**

MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	87A		
MATERIAL DESCRIPTION:	12"x12" Lt. Tan w/ Tan specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 310, 309, 308, 305, 303, 205, 203, 202, 201 (1923 bldg)		
MATERIAL QUANTITY:	6500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **87A**

MATERIAL DESCRIPTION: **12"x12" Lt. Tan w/ Tan specks VFT Mastic**

MATERIAL LOCATION: **Rooms 310, 309, 308, 305, 303, 205, 203, 202, 201 (1923 bldg)**

MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	88		
MATERIAL DESCRIPTION:	12"x12" Off White w/ Tan specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Rooms 307, 101, 302 (304 under carpet) --1923 Bldg		
MATERIAL QUANTITY:	3200	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **12"x12" Off White w/ Tan specks VFT**

MATERIAL LOCATION: **Rooms 307, 101, 302 (304 under carpet) --1923 Bldg**

MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	88A		
MATERIAL DESCRIPTION:	12"x12" Off White w/ Tan specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 307, 101, 302 (304 under carpet) --1923 Bldg		
MATERIAL QUANTITY:	3200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **88A**

MATERIAL DESCRIPTION: **12"x12" Off White w/ Tan specks VFT Mastic**

MATERIAL LOCATION: **Rooms 307, 101, 302 (304 under carpet) --1923 Bldg**

MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUILDING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allison Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	89		
MATERIAL DESCRIPTION:	12"x12" White w/ Blue Specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	(Bsmt Lunchroom, elevator lobby & hall), Serving Room (003A), Room 005A, 004, 002, 001 --1953 Bldg		
MATERIAL QUANTITY:	3900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUILDING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **89**

MATERIAL DESCRIPTION: **12"x12" White w/ Blue Specks VFT**

MATERIAL LOCATION: **(Bsmt Lunchroom, elevator lobby & hall), Serving Room (003A), Room 005A, 004, 002, 001 --1953 Bldg**

MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUILDING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allison Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	89A		
MATERIAL DESCRIPTION:	12"x12" Off White w/ Tan specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	(Bsmt Lunchroom, elevator lobby & hall), Serving Room (003A), Room 005A, 004, 002, 001 --1953 Bldg		
MATERIAL QUANTITY:	3900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **89A**

MATERIAL DESCRIPTION: **12"x12" Off White w/ Tan specks VFT Mastic**

MATERIAL LOCATION: **(Bsmt Lunchroom, elevator lobby & hall), Serving Room (003A), Room 005A, 004, 002, 001 --1953 Bldg**

MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	90		
MATERIAL DESCRIPTION:	12"x12" Lt. Tan w/ Tan specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Rooms 223, 221, 219, Bsmt Kitchen (1953 bldg)		
MATERIAL QUANTITY:	3200	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **12"x12" Lt. Tan w/ Tan specks VFT**

MATERIAL LOCATION: **Rooms 223, 221, 219, Bsmt Kitchen (1953 bldg)**

MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	90A		
MATERIAL DESCRIPTION:	12"x12" Lt. Tan w/ Tan specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 223, 221, 219, Bsmt Kitchen (1953 bldg)		
MATERIAL QUANTITY:	3200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **90A**

MATERIAL DESCRIPTION: **12"x12" Lt. Tan w/ Tan specks VFT Mastic**

MATERIAL LOCATION: **Rooms 223, 221, 219, Bsmt Kitchen (1953 bldg)**

MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 91

MATERIAL DESCRIPTION: 12"x12" Brown VFT - Abated

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 4th Floor Book Storage by Library (1923 bldg)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **91**

MATERIAL DESCRIPTION: **12"x12" Brown VFT - Abated**

MATERIAL LOCATION: **4th Floor Book Storage by Library (1923 bldg)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 91A

MATERIAL DESCRIPTION: 12"x12" Brown VFT Mastic - Abated

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 4th Floor Book Storage by Library (1923 bldg)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **91A**

MATERIAL DESCRIPTION: **12"x12" Brown VFT Mastic - Abated**

MATERIAL LOCATION: **4th Floor Book Storage by Library (1923 bldg)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **12"x12" Beige VFT - Abated**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **4th Floor Book Storage by Library (1923 bldg)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **12"x12" Beige VFT - Abated**

MATERIAL LOCATION: **4th Floor Book Storage by Library (1923 bldg)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **92A**

MATERIAL DESCRIPTION: **12"x12" Beige VFT Mastic - Abated**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **4th Floor Book Storage by Library (1923 bldg)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **92A**

MATERIAL DESCRIPTION: **12"x12" Beige VFT Mastic - Abated**

MATERIAL LOCATION: **4th Floor Book Storage by Library (1923 bldg)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 93

MATERIAL DESCRIPTION: 9"x9" Gray w/ Pink & White Streaks VFT - Abated

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 428 (1923 bldg)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **93**

MATERIAL DESCRIPTION: **9"x9" Gray w/ Pink & White Streaks VFT - Abated**

MATERIAL LOCATION: **Room 428 (1923 bldg)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 93A

MATERIAL DESCRIPTION: 9"x9" Gray w/ Pink & White Streaks VFT Mastic - Abated

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 428 (1923 bldg)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **93A**

MATERIAL DESCRIPTION: **9"x9" Gray w/ Pink & White Streaks VFT Mastic - Abated**

MATERIAL LOCATION: **Room 428 (1923 bldg)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 94

MATERIAL DESCRIPTION: 9"x9" Maroon w/ White Streaks VFT - Abated

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 428 (1923 bldg)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUILDING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **94**

MATERIAL DESCRIPTION: **9"x9" Maroon w/ White Streaks VFT - Abated**

MATERIAL LOCATION: **Room 428 (1923 bldg)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 94A

MATERIAL DESCRIPTION: 9"x9" Maroon w/ White Streaks VFT Mastic - Abated

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 428 (1923 bldg)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUILDING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **94A**

MATERIAL DESCRIPTION: **9"x9" Maroon w/ White Streaks VFT Mastic - Abated**

MATERIAL LOCATION: **Room 428 (1923 bldg)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	95		
MATERIAL DESCRIPTION:	Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Corridors, Stairwells (bsmt - 4th fl.), Toilets (all floors), Rm 311, Janitor's Closets, Auditorium Main Entrance (1923 bldg)		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUILDING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **95**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **Corridors, Stairwells (bsmt - 4th fl.), Toilets (all floors), Rm 311, Janitor's Closets, Auditorium Main Entrance (1923 bldg)**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	96		
MATERIAL DESCRIPTION:	Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Corridors (bsmt - 3rd fl.), Stairwells (bsmt - 4th fl) (1953 bldg)		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **96**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **Corridors (bsmt - 3rd fl.), Stairwells (bsmt - 4th fl) (1953 bldg)**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	97		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium Balcony (behind plaster wall) - 1923 Bldg		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **97**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **Auditorium Balcony (behind plaster wall) - 1923 Bldg**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	98		
MATERIAL DESCRIPTION:	Stage's Fire Curtain		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium Stage - 1923 Bldg		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **98**

MATERIAL DESCRIPTION: **Stage's Fire Curtain**

MATERIAL LOCATION: **Auditorium Stage - 1923 Bldg**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	99		
MATERIAL DESCRIPTION:	9" x 9" Tan Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium Balcony - 1923 Bldg		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **99**

MATERIAL DESCRIPTION: **9" x 9" Tan Ceiling Tile**

MATERIAL LOCATION: **Auditorium Balcony - 1923 Bldg**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41081	BUIDLING ID:	7520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Marshall Middle School	INSPECTION DATE:	4/1/2025		
ADDRESS:	3900 N Lawndale Avenue	IDPH LICENSE NO:	100-18790		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	99A		
MATERIAL DESCRIPTION:	9" x 9" Tan Ceiling Tile Mastic Pucks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium Balcony - 1923 Bldg		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41081</b>	BUIDLING ID:	<b>7520</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Marshall Middle School</b>	REVIEW DATE:	<b>5/1/2025</b>		
ADDRESS:	<b>3900 N Lawndale Avenue</b>	IDPH LICENSE NO:	<b>100-18790</b>		

---

HOMOGENEOUS AREA: **99A**

MATERIAL DESCRIPTION: **9" x 9" Tan Ceiling Tile Mastic Pucks**

MATERIAL LOCATION: **Auditorium Balcony - 1923 Bldg**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/01/2025**

**Chicago Public Schools**

**Specialty Consulting, Inc.**

***2025 AHERA REINSPECTION***

## APPENDIX B

---

### Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Illinois



ASBESTOS  
PROFESSIONAL  
LICENSE

ID NUMBER  
100 - 18790

ISSUED  
4/5/2024

EXPIRES  
05/15/2025

ALLIZON L BROOKS  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

Environmental Health



ALLIZON L BROOKS  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/5/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 18790

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License


Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 18790	ISSUED 4/5/2024	EXPIRES 05/15/2025	INSPECTOR	1/27/2025
ALLIZON L BROOKS 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			PROJECT MANAGER AIR SAMPLING PROFESSIONAL	6/12/2024
			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES  
*Nationally Accredited by PHAB*



ENDORSEMENTS	TC EXPIRES
INSPECTOR	1/4/2026
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	6/1/2025
<b>Alteration of this license shall result in legal action</b>	
This license issued under authority of the State of Illinois	
Department of Public Health	
This license is valid only when accompanied by a valid	
training course certificate.	

# CERTIFICATE OF ACHIEVEMENT

## ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ALLIZON L. BROOKS  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 01/04/2025 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • [www.public-health-safety.com](http://www.public-health-safety.com)

01/04/2025

Course Dates:

01/04/2026

Expires:

2501BIR02

Certificate Number:

*N. Penef*

Phone: 312-491-0081

Director of Training

Nicholas J. Penef

Doctor of Public Health

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

JIGAR M SHAH  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

6/9/2025

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER <b>100 - 07342</b>	ISSUED <b>6/9/2025</b>	EXPIRES <b>05/15/2026</b>	INSPECTOR PROJECT DESIGNER MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL	3/7/2026 1/27/2026 3/7/2026 4/7/2026
JIGAR M SHAH 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES  
*Nationally Accredited by PHAB*

7233 S. Adams Street | Willowbrook, IL 60527  
(630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2023



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 2/23/2023


Exam Date: 2/23/2023

Expiration Date: 2/23/2024

Certificate Number: MPR2302230560

*Kathy DeSalvo*

Kathy DeSalvo, Director



# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022


Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: MPR2203090714

A handwritten signature in black ink that reads "Kathy DeSalvo".

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022

Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: BIR2203090705

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761



ASBESTOS  
PROFESSIONAL  
LICENSE

ID NUMBER  
100 - 07342

ISSUED  
4/1/2022

EXPIRES  
05/15/2023

JIGAR M SHAH  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

Environmental Health



JIGAR M SHAH  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/1/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	3/9/2023
PROJECT DESIGNER	3/24/2023
MANAGEMENT PLANNER	3/9/2023
PROJECT MANAGER	3/2/2023
AIR SAMPLING PROFESSIONAL	
<b>Alteration of this license shall result in legal action</b>	
This license issued under authority of the State of Illinois	
Department of Public Health	
This license is valid only when accompanied by a valid	
training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB



525-535 West Jefferson Street • Springfield, Illinois



ASBESTOS  
PROFESSIONAL  
LICENSE

ID NUMBER  
100 - 07342

ISSUED  
4/8/2024

EXPIRES  
05/15/2025

JIGAR M SHAH  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

Environmental Health



JIGAR M SHAH  
2942 W VAN BUREN ST  
CHICAGO, IL 60612


4/8/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	3/8/2025
PROJECT DESIGNER	3/7/2025
MANAGEMENT PLANNER	3/8/2025
PROJECT MANAGER	3/25/2024
AIR SAMPLING PROFESSIONAL	
<p><b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH. IMPROVING LIVES

*Nationally Accredited by PHAB*



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2024

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 3/8/2024

Exam Date: 3/8/2024

Expiration Date: 3/8/2025

Certificate Number: MPR2403081126

Course Credit Hours: MPR 4 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

Kristina Miczek, Training Manager



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2025

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 3/7/2025

Exam Date: 3/7/2025

Expiration Date: 3/7/2026

Certificate Number: MPR2503070948

Course Credit Hours: MPR 4 Hours

---

Kristina Miczek, Training Manager

## APPENDIX C

---

### **Laboratory Accreditations**

## APPENDIX D

---

### Laboratory Results

## APPENDIX E

---

### Chain of Custody Forms

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>	Loc	Localized
	Dist	Distributed