

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-3740  
SCHOOL NAME: Galileo Academy  
ADDRESS OF SCHOOL: 820 S. Carpenter  
CITY: Chicago, IL, 60607

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 9/15/2022

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 7/28/2025 ENROLLMENT 540  
IDPH INSPECTOR LICENSE NUMBER: 100-03175  
IDPH LICENSED INSPECTOR NAME (Please Print): Marcos Iwankiw  
IDPH MP LICENSE NUMBER: 100-20634  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jackson Montgomery

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

*Richard J. Schleyer* 8/7/2025

*Signature of Designated Person*

*Date*

**SECTION III**

**PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.**

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Galileo Academy**

820 S. Carpenter  
Chicago, IL, 60607

Unit: 29141  
Building ID: 4160

IDPH ID Number: 14-016-2990-3740

**REPORT DATE:**  
Thursday, August 07, 2025

**Prepared for:**  
**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**  
**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

08/07/2025

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299      Unit: 29141      Region: 03      IDPH ID: 14-016-2990-3740

School: Galileo Academy      Building ID: 4160

Address: 820 S. Carpenter

Chicago, IL, 60607

Building Contact: Gonzalez, Armin      Contact Phone: 7737095963

Current Building Owners: Chicago Public Schools

Reinspection Date: 7/28/2025

Review Date: 08/07/2025

Inspector: Marcos Iwankiw

Inspector IDPH License: 100-03175

Management Planner: Jackson Montgomery

Management Planner IDPH License: 100-20634

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates



Jackson Montgomery  
100-20634

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: August 07, 2025

RE: Galileo Academy, Unit 29141  
820 S. Carpenter  
Chicago, IL, 60607

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Galileo Academy , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Galileo Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Galileo Academy      Unit: 29141      Region: 03  
Address: 820 S. Carpenter      Chicago, IL, 60607  
IDPH ID: 14-016-2990-3740      Building ID: 4160  
Contact: Gonzalez, Armin      Phone: 7737095963

### 2. Description of Facility

Original Construction: 1893      Additional Construction: 1909  
Total Square Footage: 42469      No of Floors: 3  
Current Occupancy: 540

### 3. LEA Designated Person

Contact: Richard J.Schleyer      Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Doug McCormick  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900      Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Marcos Iwankiw

Inspector IDPH license # 100-03175  
Reinspection Date: 7/28/2025

Signature:   
Date: 7/28/2025

### 6. Management Planner

Management Planner Name: Jackson Montgomery

Management Planner IDPH license # 100-20634

Signature:   
Date: 08/07/2025

### 7. Review Date: 08/07/2025

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 8/7/2025

Name: Richard J.Schleyer

## **II. EXECUTIVE SUMMARY**

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Galileo Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

- A. The following HAs have changed assessment categories for Building 4160:

B. The following new homogenous areas have been identified for Building 4160:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

100	4" Black Vinyl Baseboard
101	4" Black Vinyl Baseboard Adhesive
14	12" x 12" Cream w/ Tan Specks Floor Tile
15	12" x 12" Pale Brown w/ Cream & Dark Brown Specks Floor Tile
16	12" x 12" Cream w/ Tan Specks and Pale Brown w/ Cream & Dark Brown Specks Floor Tile Mastic
29	12" x 12" Multi-Cream w/ Tan Specks Floor Tile
3	Wains Coat Molding
31	2' x 4' Lay-in Ceiling Panels
32	Drywall & Joint Compound
33	2' x 4' Black Border Floor Tile
34	2' x 4' Black Border Floor Tile Mastic
35	12" x 12" White w/ Charcoal Streaks Floor Tile
4	Wains Coat Molding
45	Sink Caulk
48	Boiler Gaskets
49	Boiler Gaskets
5	9" x 9" Light Green w/ White Marbling Floor Tile
50	Spray on Fireproofing on Ceiling
52	Blue Carpet Mastic
53	Man Hole & Hand Hole Boiler Gaskets
54	Man Hole & Hand Hole Boiler Gaskets
55	Fire Brick
56	Fire Brick
57	Insulation Inside Of Vault Door
58	12" x 12" Off-White w/ Blue Specks Vinyl Floor Tile
59	12" x 12" Off-White w/ Blue Specks Vinyl Floor Tile Mastic
6	9" x 9" Dark Green w/ White Marbling Floor Tile
60	12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile
61	12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile Mastic
62	12" x 12" Off-White w/ Blue & Gray Streaks Vinyl Floor Tile
63	12" x 12" Off-White w/ Blue & Gray Streaks Vinyl Floor Tile Mastic
64	12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile
65	12" x 12" Off-White w/ Blue & Gray Specks Vinyl

	Floor Tile Mastic
66	12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile
67	12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile Mastic
68	12" x 12" Off-White w/ Black Specks Vinyl Floor Tile
69	12" x 12" Off-White w/ Black Specks Vinyl Floor Tile Mastic
7	9" x 9" Dark Green & Light Green w/ White Marbling Floor Tile Mastic
70	Sink Undercoating
71	6" x 6" Brown Quarry Tile
72	6" x 6" Brown Quarry Tile Mastic
73	12" x 12" Off-White w/ Gray & Blue Specks Floor Tile
74	12" x 12" Off-White w/ Gray & Blue Specks Floor Tile Mastic
75	12" x 12" White w/ Gray Streaks Floor Tile
76	12" x 12" White w/ Gray Streaks Floor Tile Mastic
77	12" x 12" White w/ Blue Streaks Floor Tile
78	12" x 12" White w/ Blue Streaks Floor Tile Mastic
79	12" x 12" Black w/ White Streaks Floor Tile
8	9" x 9" Black Floor Tile
80	12" x 12" Black w/ White Streaks Floor Tile Mastic
81	12" x 12" White w/ Blue Streaks Floor Tile
82	12" x 12" White w/ Blue Streaks Floor Tile Mastic
83	Brown Vinyl Sheet Flooring
84	Blue Carpet Mastic
85	Tongue and Groove Wood Flooring
86	12" x 12" White w/ Tan Specks Floor Tile
87	12" x 12" White w/ Tan Specks Floor Tile Mastic
88	4" Beige Baseboard
89	4" Beige Baseboard Adhesive
9	9" x 9" Red Floor Tile
90	12" x 12" Off-White w/ Tan Specks Floor Tile
91	12" x 12" Off-White w/ Tan Specks Floor Tile Mastic
92	24" x 24" Blue Streaked Floor Tile
93	24" x 24" Gray Streaked Floor Tile
94	24" x 24" White Streaked Floor Tile
95	24" x 24" Blue, Gray and White Streaked Floor Tile Mastic
96	Wavy Gray Vinyl Flooring
97	Adhesive Associated w/ Wavy Gray Vinyl Flooring
98	Wavy Gray Vinyl Stair Tread
99	Adhesive Associated w/ Wavy Gray Vinyl Stair Tread

B	Cardboard Pipe Insulation
D	Pipe Cover
E	Mag Block Insulation on Boiler
F	Cementitious Joint Insulation on Cardboard Lagging
G	Boiler Gaskets
U	Duct Insulation

The following areas were deemed to be inaccessible:

16	12" x 12" Cream w/ Tan Specks and Pale Brown w/ Cream & Dark Brown Specks Floor Tile Mastic
22	9" x 9" Coffee w/ Cream Specks Floor Tile Mastic
30	12" x 12" Multi-Cream w/ Tan Specks Floor Tile Mastic
50	Spray on Fireproofing on Ceiling
57	Insulation Inside Of Vault Door
59	12" x 12" Off-White w/ Blue Specks Vinyl Floor Tile Mastic
61	12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile Mastic
63	12" x 12" Off-White w/ Blue & Gray Streaks Vinyl Floor Tile Mastic
65	12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile Mastic
67	12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile Mastic
69	12" x 12" Off-White w/ Black Specks Vinyl Floor Tile Mastic
72	6" x 6" Brown Quarry Tile Mastic
74	12" x 12" Off-White w/ Gray & Blue Specks Floor Tile Mastic
78	12" x 12" White w/ Blue Streaks Floor Tile Mastic
80	12" x 12" Black w/ White Streaks Floor Tile Mastic
82	12" x 12" White w/ Blue Streaks Floor Tile Mastic
88	4" Beige Baseboard
89	4" Beige Baseboard Adhesive
91	12" x 12" Off-White w/ Tan Specks Floor Tile Mastic
99	Adhesive Associated w/ Wavy Gray Vinyl Stair Tread

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Marcos Iwankiw, IDPH License # 100-03175. The

Management Plan was updated by Jackson Montgomery, IDPH License # 100-20634. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Galileo Academy Building 4160 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

Chicago Public Schools

**School** Galileo Academy **Unit** 29141 **Building ID** 4160  
**Address** 820 S. Carpenter **Region** 03

## **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

## Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

## ***Inspector's Comments are Summarized at the End of the Report***

Chicago Public Schools

**School** Galileo Academy **Unit** 29141 **Building ID** 4160  
**Address** 820 S. Carpenter **Region** 03

## **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

## Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

## ***Inspector's Comments are Summarized at the End of the Report***

# Chicago Public Schools

**School** Galileo Academy **Unit** 29141 **Building ID** 4160  
**Address** 820 S. Carpenter **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Building										
44	Cinder Block Mortar			Throughout 1895 Building	NO_ACBM	MISC								
45	Sink Caulk			Boys & Girls Basement Bathrooms	ASSUMED	MISC								
46	Window Caulk			Throughout Facility	NO_ACBM	MISC								
47	Door Caulk			East and West Basement Entry Doors	NO_ACBM	MISC								
48	Boiler Gaskets	15	LF	Boiler #1 - Replaced	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
49	Boiler Gaskets	15	LF	Boiler #2 - Replaced	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
5	9" x 9" Light Green w/ White Marbling Floor Tile			Basement Store Room	ASSUMED	MISC								
50	Spray on Fireproofing on Ceiling	320	SF	Boiler Room & Tank Room	ASSUMED	SURFACE	Y	NONE			Any remaining friable ACBM or friable suspect ACBM		LOW	
51	Purple Carpet Mastic			ABATED	ABATED	MISC								
52	Blue Carpet Mastic			MATERIAL REMOVED	ASSUMED	MISC								
53	Man Hole & Hand Hole Boiler Gaskets			MATERIAL REMOVED	ASSUMED	MISC								
54	Man Hole & Hand Hole Boiler Gaskets			MATERIAL REMOVED	ASSUMED	MISC								
55	Fire Brick			MATERIAL REMOVED	ASSUMED	MISC								
56	Fire Brick			MATERIAL REMOVED	ASSUMED	MISC								
57	Insulation Inside Of Vault Door	30	SF	Main Office	ASSUMED	TSI	N	NONE			ACBM with the potential for damage		LOW	
58	12" x 12" Off-White w/ Blue Specks Vinyl Floor Tile	2,500	SF	Principal's Office, Main Office, Library, Storage by 202, 2nd Floor Storage Between Girls and Boys Bathrooms	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
59	12" x 12" Off-White w/ Blue Specks Vinyl Floor Tile Mastic	2,500	SF	Principal's Office, Main Office, Library, Storage by 202, 2nd Floor Storage Between	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	

# Chicago Public Schools

**School** Galileo Academy **Unit** 29141 **Building ID** 4160  
**Address** 820 S. Carpenter **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Girls and Boys Bathrooms										
6	9" x 9" Dark Green w/ White Marbling Floor Tile			Basement Store Room	ASSUMED	MISC								
60	12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile	925	SF	Rooms 113/114	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
61	12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile Mastic	925	SF	Rooms 113/114	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
62	12" x 12" Off-White w/ Blue & Gray Streaks Vinyl Floor Tile	1,418	SF	Rooms 102/103 Principal's Office	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
63	12" x 12" Off-White w/ Blue & Gray Streaks Vinyl Floor Tile Mastic	1,418	SF	Rooms 102/103 Principal's Office	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
64	12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile	172	SF	Teachers' Bathroom	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
65	12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile Mastic	172	SF	Teachers' Bathroom	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
66	12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile	1,215	SF	Room 107	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
67	12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile Mastic	1,215	SF	Room 107	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
68	12" x 12" Off-White w/ Black Specks Vinyl Floor Tile	400	SF	1st Floor Corridor - 1895 Building, Storage by 202, 2nd Floor Storage Between Girls and Boys Bathrooms	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
69	12" x 12" Off-White w/ Black Specks Vinyl Floor Tile Mastic	400	SF	1st Floor Corridor - 1895 Building, Storage by 202, 2nd Floor Storage Between Girls and Boys Bathrooms	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
7	9" x 9" Dark Green & Light Green w/ White Marbling Floor Tile Mastic			Basement Store Room	ASSUMED	MISC								
70	Sink Undercoating	5	SF	Room 106	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
71	6" x 6" Brown Quarry Tile	2,313	SF	Kitchen, Teachers' Lunchroom and Lunchroom	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
72	6" x 6" Brown Quarry Tile Mastic	2,313	SF	Kitchen, Teachers' Lunchroom and Lunchroom	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
73	12" x 12" Off-White w/ Gray & Blue Specks Floor Tile	700	SF	Principal's Office	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	

# Chicago Public Schools

**School** Galileo Academy **Unit** 29141 **Building ID** 4160  
**Address** 820 S. Carpenter **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
74	12" x 12" Off-White w/ Gray & Blue Specks Floor Tile Mastic	700	SF	Principal's Office	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
75	12" x 12" White w/ Gray Streaks Floor Tile			MATERIAL REMOVED	ASSUMED	MISC								
76	12" x 12" White w/ Gray Streaks Floor Tile Mastic			MATERIAL REMOVED	ASSUMED	MISC								
77	12" x 12" White w/ Blue Streaks Floor Tile	2,308	SF	School Elevators, Nurse Office, Rooms 314, 306, 114, 113, 010	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
78	12" x 12" White w/ Blue Streaks Floor Tile Mastic	2,308	SF	School Elevators, Nurse Office, Rooms 314, 306, 114, 113, 010	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
79	12" x 12" Black w/ White Streaks Floor Tile	5,370	SF	1895 Building Basement Corridor and 1909 Building Basement Corridor, Kiln Room	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
8	9" x 9" Black Floor Tile			MATERIAL REMOVED	ASSUMED	MISC								
80	12" x 12" Black w/ White Streaks Floor Tile Mastic	5,370	SF	1895 Building Basement Corridor and 1909 Building Basement Corridor, Kiln Room	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
81	12" x 12" White w/ Blue Streaks Floor Tile	7,612	SF	Rooms 212 and 213, 2nd & 3rd Floor Teacher Rooms, Kitchen, Lunchroom, Basement Lunchroom, 1st Floor Principal's Office, 010	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
82	12" x 12" White w/ Blue Streaks Floor Tile Mastic	7,612	SF	Rooms 212 and 213, 2nd & 3rd Floor Teacher Rooms, Kitchen, Lunchroom, Basement Lunchroom, 1st Floor Principal's Office, 010	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
83	Brown Vinyl Sheet Flooring	100	SF	Room 107 Storage	ASSUMED	MISC	N	NONE				ACBM with the		LOW

# Chicago Public Schools

**School** Galileo Academy **Unit** 29141 **Building ID** 4160  
**Address** 820 S. Carpenter **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
84	Blue Carpet Mastic	200	SF	Room 107, Room 107 Office	ASSUMED	MISC	N	NONE				potential for damage		
85	Tongue and Groove Wood Flooring	4,000	SF	Room 109, 105, 112, 111, Auditorium, Auditorium Balcony, 211, 210, 201, 202, Corridor 1895 Building, 204, 204 Closet, 205 Closet, 208, 305 Closet, 304 Closet, 303, 302, 301, 313, 310, 312, 311	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
86	12" x 12" White w/ Tan Specks Floor Tile	900	SF	Rooms 106, 206	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
87	12" x 12" White w/ Tan Specks Floor Tile Mastic	900	SF	Rooms 106, 206	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
88	4" Beige Baseboard	350	LF	Gym	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
89	4" Beige Baseboard Adhesive	350	LF	Gym	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
9	9" x 9" Red Floor Tile			MATERIAL REMOVED	ASSUMED	MISC								
90	12" x 12" Off-White w/ Tan Specks Floor Tile	900	SF	Room 206	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
91	12" x 12" Off-White w/ Tan Specks Floor Tile Mastic	900	SF	Room 206	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
92	24" x 24" Blue Streaked Floor Tile	300	SF	Room 308, 309a, 309	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
93	24" x 24" Gray Streaked Floor Tile	300	SF	Room 308, 309a, 309	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
94	24" x 24" White Streaked Floor Tile	300	SF	Room 308, 309a, 309	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
95	24" x 24" Blue, Gray and White Streaked Floor Tile Mastic	900	SF	Room 308 309a, 309	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
96	Wavy Gray Vinyl Flooring	1,200	SF	West Stairwell Basement Womens3rd Floor	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
97	Adhesive Associated w/ Wavy Gray Vinyl Flooring	1,200	SF	West Stairwell, Basement, Women's 3rd Floor Bathroom	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
98	Wavy Gray Vinyl Stair Tread	800	SF	West Stairwell Basement	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Galileo Academy **Unit** 29141 **Building ID** 4160  
**Address** 820 S. Carpenter **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Womens3rd Floor										
99	Adhesive Associated w/ Wavy Gray Vinyl Stair Tread	800	SF	West Stairwell, Basement, Women's 3rd Floor Bathroom	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
A	Aircell Pipe Insulation			ABATED	ABATED	TSI								
B	Cardboard Pipe Insulation	75	LF	1909 Building - Basement Corridors, Boy's Play Room	ASSUMED	TSI	N	NONE				ACBM with the potential for damage		LOW
C	Cementitious Pipe Joint Insulation Off Fiberglass	150	LF	1909 Building - Basement Corridors, Boy's Play Room	CHR	TSI	N	NONE				ACBM with the potential for damage		LOW
D	Pipe Cover			1909 Building	ASSUMED	TSI								
E	Mag Block Insulation on Boiler			Boiler Room	ASSUMED	TSI								
F	Cementitious Joint Insulation on Cardboard Lagging	100	LF	1909 Building - Engine Room	ASSUMED	TSI	N	NONE				ACBM with the potential for damage		LOW
G	Boiler Gaskets			MATERIAL REMOVED	ASSUMED	TSI								
H	Aircell Pipe Insulation	500	LF	1895 Building - Basement Hallways, Tank Room Boiler Room	CHR	TSI	N	NONE				ACBM with the potential for damage		LOW
I	Cardboard Pipe Insulation	400	LF	1895 Building - Basement Corridor, Lunchroom	CHR	TSI	N	NONE				ACBM with the potential for damage		LOW
J	Cementitious Joint Insulation on Cardboard Lagging	1,500	LF	1895 Building - Basement Corridors	CHR	TSI	N	NONE				ACBM with the potential for damage		LOW
K	Mag Block Pipe Insulation	150	LF	1909 Building Engine Room, 1895 Building Engine Room	CHR	TSI	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		LOW
L	Felight Pipe Insulation				CHR	TSI								
M	Cementitious Joint Insulation on Felight Lagging				CHR	TSI								
N	Cementitious Joint Insulation on Felight Lagging				CHR	TSI								
O	Mag Block Pipe Insulation	150	LF	1909 Building - Engine Room	CHR	TSI	N	NONE				ACBM with the potential for damage		LOW
P	Mag Block Pipe Joint Insulation	20	LF	1895 Building - Engine Room	CHR	TSI	N	NONE				ACBM with the potential for damage		LOW
Q	Mag Block Pipe Joint Insulation	20	LF	1909 Building - Engine Room	CHR	TSI	N	NONE				ACBM with the potential for damage		LOW
R	Cementitious Joint Insulation on Aircell Lagging	200	LF	1895 Building - Boiler Room	CHR	TSI	N	NONE				ACBM with the potential for damage		LOW
S	Cementitious Joint Insulation on Aircell	50	LF	1909 Building -	CHR	TSI	N	NONE				ACBM with the		LOW

# Chicago Public Schools

**School** Galileo Academy **Unit** 29141 **Building ID** 4160  
**Address** 820 S. Carpenter **Region** 03

## **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

## Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

***Inspector's Comments are Summarized at the End of the Report***

# Chicago Public Schools

School Galileo Academy Unit 29141 Building ID 4160  
Address 820 S. Carpenter Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <u>7/28/2025</u>
Inspector Name <u>Marcos Iwankiw</u>
<u>100-03175</u> <u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date

#### Inspector's Comments

HA Number:	Inspector Comments:
1	
10	
100	
101	
11	
12	
14	
15	
16	
17	
18	
19	
2	
20	
21	Room 309 replaced with 24" x 24" blue, white, gray flooring (HA 92)
22	Room 309 replaced with 24" x 24" blue, white, gray flooring (HA 93)
23	
24	
25	
26	
27	
28	
29	
3	

# Chicago Public Schools

School Galileo Academy Unit 29141 Building ID 4160  
Address 820 S. Carpenter Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
30	
31	
32	
33	Material not observed - 2025
34	Material not observed - 2025
35	Material not observed - 2025
36	Material not observed - 2025
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	Material not observed - 2025
46	
47	
48	
49	
5	Material not observed - 2025
50	
51	
52	
53	
54	
55	
56	

# Chicago Public Schools

School Galileo Academy Unit 29141 Building ID 4160  
Address 820 S. Carpenter Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
57	
58	
59	
6	Material not observed - 2025
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
7	Material not observed - 2025
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
8	
80	
81	
82	

# Chicago Public Schools

School Galileo Academy Unit 29141 Building ID 4160  
Address 820 S. Carpenter Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
83	
84	
85	
86	
87	
88	
89	
9	
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
A	
B	
C	
D	Material not observed - 2025
E	Material not observed - 2025
F	
G	
H	
I	
J	
K	Not observed in Kitchen

# Chicago Public Schools

**School** Galileo Academy **Unit** 29141 **Building ID** 4160  
**Address** 820 S. Carpenter **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
L	Material not observed - 2025
M	Material not observed - 2025
N	Material not observed - 2025
O	
P	
Q	
R	
S	
T	
U	Material not observed - 2025

**Table II**  
**Management Planner's Review**

---

# Chicago Public Schools

**School** Galileo Academy  
**Address** 820 S. Carpenter

**Unit** 29141  
**Chicago, IL, 60607**

**Building ID** 4160  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	Hard Plaster			Throughout 1909 Building	No ACBM	SURFACE					
10	9" x 9" Red & Black Floor Tile Mastic			ABATED	Abated	MISC					
100	4" Black Vinyl Baseboard	600	LF	Basement East Corridor of 1895 Building, Basement East Corridor of 1909 Building	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
101	4" Black Vinyl Baseboard Adhesive	600	LF	Basement East Corridor of 1895 Building, Basement East Corridor of 1909 Building	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
11	9" x 9" Green w/ White Marbling Floor Tile			ABATED	Abated	MISC					
12	9" x 9" Green w/ White Marbling Floor Tile Mastic			ABATED	Abated	MISC					
14	12" x 12" Cream w/ Tan Specks Floor Tile	700	SF	Kitchen, 2nd & 3rd Floor Teachers' Rooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
15	12" x 12" Pale Brown w/ Cream & Dark Brown Specks Floor Tile	700	SF	Kitchen, 2nd & 3rd Floor Teachers' Rooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
16	12" x 12" Cream w/ Tan Specks and Pale Brown w/ Cream & Dark Brown Specks Floor Tile Mastic	1,400	SF	Kitchen, 2nd & 3rd Floor Teachers' Rooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12" x 12" Dark Brown w/ Cream & Red Floor Tile			ABATED	Abated	MISC					
18	12" x 12" Dark Brown w/ Cream & Red Floor Tile Mastic			ABATED	Abated	MISC					
19	12" x 12" Coffee w/ Cream Specks Floor Tile			ABATED	Abated	MISC					
2	Hard Plaster			Throughout 1895 Building	No ACBM	SURFACE					
20	12" x 12" Coffee w/ Cream Specks Floor Tile Mastic			ABATED	Abated	MISC					
21	9" x 9" Coffee w/ Cream Specks Floor Tile	3,012	SF	Rooms 104, 106, 205, 206, 207, 304, 305, 307	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
22	9" x 9" Coffee w/ Cream Specks Floor Tile Mastic	3,012	SF	Rooms 104, 106, 205, 206, 207, 304, 305, 307	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
23	9" x 9" Tan w/ Rust & Cream Marbling Floor Tile			DUPLICATE OF HA 21	Chrysotile	MISC					
24	9" x 9" Tan w/ Rust & Cream Marbling Floor Tile Mastic			DUPLICATE OF HA 22	Chrysotile	MISC					
25	9" x 9" Black w/ White Marbling Floor Tile			ABATED	Abated	MISC					
26	9" x 9" Black w/ White Marbling Floor Tile Mastic			ABATED	Abated	MISC					
27	9" x 9" Coffee w/ Cream Specks Floor Tile			ABATED	Abated	MISC					
28	9" x 9" Coffee w/ Cream Specks Floor Tile Mastic			ABATED	Abated	MISC					
29	12" x 12" Multi-Cream w/ Tan Specks Floor Tile	1,390	SF	Room 101	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
3	Wains Coat Molding	5,000	SF	Throughout 1909 Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Galileo Academy

**Unit** 29141

**Building ID** 4160

**Address** 820 S. Carpenter

Chicago, IL, 60607

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
30	12" x 12" Multi-Cream w/ Tan Specks Floor Tile Mastic	1,390	SF	Room 101	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
31	2' x 4' Lay-in Ceiling Panels	1,568	SF	Teachers' Bathroom & Lounge, Offices, 101, 102, 111, 112, 113, Main Office, Gym	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
32	Drywall & Joint Compound	1,600	SF	E&W Boys Playrooms, 1st Floor Teachers' Lounge & Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
33	2' x 4' Black Border Floor Tile			Lunchroom	Assumed	MISC					
34	2' x 4' Black Border Floor Tile Mastic			Lunchroom	Assumed	MISC					
35	12" x 12" White w/ Charcoal Streaks Floor Tile			Lunchroom	Assumed	MISC					
36	12" x 12" White w/ Charcoal Streaks Floor Tile Mastic			Lunchroom	Chrysotile	MISC					
37	Interior Brick			Throughout 1909 Building	No ACBM	MISC					
38	Interior Brick Mortar			Throughout 1909 Building	No ACBM	MISC					
39	Interior Brick			Throughout 1895 Building	No ACBM	MISC					
4	Wains Coat Molding	5,000	SF	Throughout 1895 Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
40	Interior Brick Mortar			Throughout 1895 Building	No ACBM	MISC					
41	Glazed Brick			Throughout 1895 Building	No ACBM	MISC					
42	Glazed Brick Mortar			Throughout 1895 Building	No ACBM	MISC					
43	Cinder Block			Throughout 1895 Building	No ACBM	MISC					
44	Cinder Block Mortar			Throughout 1895 Building	No ACBM	MISC					
45	Sink Caulk			Boys & Girls Basement Bathrooms	Assumed	MISC					
46	Window Caulk			Throughout Facility	No ACBM	MISC					
47	Door Caulk			East and West Basement Entry Doors	No ACBM	MISC					
48	Boiler Gaskets	15	LF	Boiler #1 - Replaced	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
49	Boiler Gaskets	15	LF	Boiler #2 - Replaced	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
5	9" x 9" Light Green w/ White Marbling Floor Tile			Basement Store Room	Assumed	MISC					
50	Spray on Fireproofing on Ceiling	320	SF	Boiler Room & Tank Room	Assumed	SURFACE	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
51	Purple Carpet Mastic			ABATED	Abated	MISC					
52	Blue Carpet Mastic			MATERIAL REMOVED	Assumed	MISC					
53	Man Hole & Hand Hole Boiler Gaskets			MATERIAL REMOVED	Assumed	MISC					
54	Man Hole & Hand Hole Boiler Gaskets			MATERIAL REMOVED	Assumed	MISC					
55	Fire Brick			MATERIAL REMOVED	Assumed	MISC					
56	Fire Brick			MATERIAL REMOVED	Assumed	MISC					

# Chicago Public Schools

**School** Galileo Academy

**Unit** 29141

**Building ID** 4160

**Address** 820 S. Carpenter

Chicago, IL, 60607

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
57	Insulation Inside Of Vault Door	30	SF	Main Office	Assumed	TSI	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
58	12" x 12" Off-White w/ Blue Specks Vinyl Floor Tile	2,500	SF	Principal's Office, Main Office, Library, Storage by 202, 2nd Floor Storage Between Girls and Boys Bathrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
59	12" x 12" Off-White w/ Blue Specks Vinyl Floor Tile Mastic	2,500	SF	Principal's Office, Main Office, Library, Storage by 202, 2nd Floor Storage Between Girls and Boys Bathrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
6	9" x 9" Dark Green w/ White Marbling Floor Tile			Basement Store Room	Assumed	MISC					
60	12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile	925	SF	Rooms 113/114	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
61	12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile Mastic	925	SF	Rooms 113/114	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
62	12" x 12" Off-White w/ Blue & Gray Streaks Vinyl Floor Tile	1,418	SF	Rooms 102/103 Principal's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
63	12" x 12" Off-White w/ Blue & Gray Streaks Vinyl Floor Tile Mastic	1,418	SF	Rooms 102/103 Principal's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
64	12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile	172	SF	Teachers' Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
65	12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile Mastic	172	SF	Teachers' Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
66	12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile	1,215	SF	Room 107	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
67	12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile Mastic	1,215	SF	Room 107	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
68	12" x 12" Off-White w/ Black Specks Vinyl Floor Tile	400	SF	1st Floor Corridor - 1895 Building, Storage by 202, 2nd Floor Storage Between Girls and Boys Bathrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
69	12" x 12" Off-White w/ Black Specks Vinyl Floor Tile Mastic	400	SF	1st Floor Corridor - 1895 Building, Storage by 202, 2nd Floor Storage Between Girls and Boys Bathrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
7	9" x 9" Dark Green & Light Green w/ White Marbling Floor Tile Mastic			Basement Store Room	Assumed	MISC					
70	Sink Undercoating	5	SF	Room 106	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
71	6" x 6" Brown Quarry Tile	2,313	SF	Kitchen, Teachers' Lunchroom and Lunchroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
72	6" x 6" Brown Quarry Tile Mastic	2,313	SF	Kitchen, Teachers' Lunchroom and	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Galileo Academy

**Unit** 29141

**Building ID** 4160

**Address** 820 S. Carpenter

Chicago, IL, 60607

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Lunchroom							
73	12" x 12" Off-White w/ Gray & Blue Specks Floor Tile	700	SF	Principal's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
74	12" x 12" Off-White w/ Gray & Blue Specks Floor Tile Mastic	700	SF	Principal's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
75	12" x 12" White w/ Gray Streaks Floor Tile			MATERIAL REMOVED	Assumed	MISC					
76	12" x 12" White w/ Gray Streaks Floor Tile Mastic			MATERIAL REMOVED	Assumed	MISC					
77	12" x 12" White w/ Blue Streaks Floor Tile	2,308	SF	School Elevators, Nurse Office, Rooms 314, 306, 114, 113, 010	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
78	12" x 12" White w/ Blue Streaks Floor Tile Mastic	2,308	SF	School Elevators, Nurse Office, Rooms 314, 306, 114, 113, 010	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
79	12" x 12" Black w/ White Streaks Floor Tile	5,370	SF	1895 Building Basement Corridor and 1909 Building Basement Corridor, Kiln Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
8	9" x 9" Black Floor Tile			MATERIAL REMOVED	Assumed	MISC					
80	12" x 12" Black w/ White Streaks Floor Tile Mastic	5,370	SF	1895 Building Basement Corridor and 1909 Building Basement Corridor, Kiln Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
81	12" x 12" White w/ Blue Streaks Floor Tile	7,612	SF	Rooms 212 and 213, 2nd & 3rd Floor Teacher Rooms, Kitchen, Lunchroom, Basement Lunchroom, 1st Floor Principal's Office, 010	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
82	12" x 12" White w/ Blue Streaks Floor Tile Mastic	7,612	SF	Rooms 212 and 213, 2nd & 3rd Floor Teacher Rooms, Kitchen, Lunchroom, Basement Lunchroom, 1st Floor Principal's Office, 010	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
83	Brown Vinyl Sheet Flooring	100	SF	Room 107 Storage	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
84	Blue Carpet Mastic	200	SF	Room 107, Room 107 Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
85	Tongue and Groove Wood Flooring	4,000	SF	Room 109, 105, 112, 111, Auditorium, Auditorium Balcony, 211, 210, 201, 202, Corridor 1895 Building, 204, 204 Closet, 205 Closet, 208, 305 Closet, 304 Closet, 303, 302, 301, 313, 310, 312, 311	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
86	12" x 12" White w/ Tan Specks Floor Tile	900	SF	Rooms 106, 206	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
87	12" x 12" White w/ Tan Specks Floor Tile Mastic	900	SF	Rooms 106, 206	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Galileo Academy  
**Address** 820 S. Carpenter

**Unit** 29141  
**Chicago, IL, 60607**

**Building ID** 4160  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
88	4" Beige Baseboard	350	LF	Gym	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
89	4" Beige Baseboard Adhesive	350	LF	Gym	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
9	9" x 9" Red Floor Tile			MATERIAL REMOVED	Assumed	MISC					
90	12" x 12" Off-White w/ Tan Specks Floor Tile	900	SF	Room 206	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
91	12" x 12" Off-White w/ Tan Specks Floor Tile Mastic	900	SF	Room 206	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
92	24" x 24" Blue Streaked Floor Tile	300	SF	Room 308, 309a, 309	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
93	24" x 24" Gray Streaked Floor Tile	300	SF	Room 308, 309a, 309	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
94	24" x 24" White Streaked Floor Tile	300	SF	Room 308, 309a, 309	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
95	24" x 24" Blue, Gray and White Streaked Floor Tile Mastic	900	SF	Room 308 309a, 309	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
96	Wavy Gray Vinyl Flooring	1,200	SF	West Stairwell Basement Womens3rd Floor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
97	Adhesive Associated w/ Wavy Gray Vinyl Flooring	1,200	SF	West Stairwell, Basement, Women's 3rd Floor Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
98	Wavy Gray Vinyl Stair Tread	800	SF	West Stairwell Basement Womens3rd Floor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
99	Adhesive Associated w/ Wavy Gray Vinyl Stair Tread	800	SF	West Stairwell, Basement, Women's 3rd Floor Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Aircell Pipe Insulation			ABATED	Abated	TSI					
B	Cardboard Pipe Insulation	75	LF	1909 Building - Basement Corridors, Boy's Play Room	Assumed	TSI	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
C	Cementitious Pipe Joint Insulation Off Fiberglass	150	LF	1909 Building - Basement Corridors, Boy's Play Room	Chrysotile	TSI	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
D	Pipe Cover			1909 Building	Assumed	TSI					
E	Mag Block Insulation on Boiler			Boiler Room	Assumed	TSI					
F	Cementitious Joint Insulation on Cardboard Lagging	100	LF	1909 Building - Engine Room	Assumed	TSI	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
G	Boiler Gaskets			MATERIAL REMOVED	Assumed	TSI					
H	Aircell Pipe Insulation	500	LF	1895 Building - Basement Hallways, Tank Room Boiler Room	Chrysotile	TSI	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
I	Cardboard Pipe Insulation	400	LF	1895 Building - Basement Corridor, Lunchroom	Chrysotile	TSI	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
J	Cementitious Joint Insulation on Cardboard Lagging	1,500	LF	1895 Building - Basement Corridors	Chrysotile	TSI	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
K	Mag Block Pipe Insulation	150	LF	1909 Building Engine Room, 1895	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable	Follow O&M Plan

# Chicago Public Schools

**School** Galileo Academy

**Unit** 29141

**Building ID** 4160

**Address** 820 S. Carpenter

Chicago, IL, 60607

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Building Engine Room						suspect ACBM	
L	Felight Pipe Insulation				Chrysotile	TSI					
M	Cementitious Joint Insulation on Felight Lagging				Chrysotile	TSI					
N	Cementitious Joint Insulation on Felight Lagging				Chrysotile	TSI					
O	Mag Block Pipe Insulation	150	LF	1909 Building - Engine Room	Chrysotile	TSI	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
P	Mag Block Pipe Joint Insulation	20	LF	1895 Building - Engine Room	Chrysotile	TSI	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
Q	Mag Block Pipe Joint Insulation	20	LF	1909 Building - Engine Room	Chrysotile	TSI	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
R	Cementitious Joint Insulation on Aircell Lagging	200	LF	1895 Building - Boiler Room	Chrysotile	TSI	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
S	Cementitious Joint Insulation on Aircell Lagging	50	LF	1909 Building - Engine Room	Chrysotile	TSI	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
T	Cementitious Joint Insulation on Fiberglass Pipes	1,000	LF	1895 Building - Basement Corridor, Engine Room	Chrysotile	TSI	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
U	Duct Insulation			Engine Room	Assumed	TSI					

# Chicago Public Schools

**School** Galileo Academy

**Unit** 29141

**Building ID** 4160

**Address** 820 S. Carpenter

Chicago, IL, 60607

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

***Management Planner's Comments Summarized at the End of the Report***

Review Date	8/7/2025
Manager Planner Name	Jackson Montgomery
100-20634	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10	
100	
101	
11	
12	
14	
15	
16	
17	
18	
19	
2	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
3	

# Chicago Public Schools

**School** Galileo Academy

**Unit** 29141

**Building ID** 4160

**Address** 820 S. Carpenter

Chicago, IL, 60607

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
5	
50	
51	
52	
53	
54	

# Chicago Public Schools

**School** Galileo Academy

**Unit** 29141

**Building ID** 4160

**Address** 820 S. Carpenter

Chicago, IL, 60607

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
55	
56	
57	
58	
59	
6	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
7	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	

# Chicago Public Schools

**School** Galileo Academy

**Unit** 29141

**Building ID** 4160

**Address** 820 S. Carpenter

Chicago, IL, 60607

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
8	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
9	
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
A	
B	
C	
D	
E	

# Chicago Public Schools

**School** Galileo Academy

**Unit** 29141

**Building ID** 4160

**Address** 820 S. Carpenter

Chicago, IL, 60607

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
F	
G	
H	
I	
J	
K	
L	
M	
N	
O	
P	
Q	
R	
S	
T	
U	

## APPENDIX A

---

### Assessment Sheets, Drawings and Photos

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2025 AHERA REINSPECTION***

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **Hard Plaster**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **Hard Plaster**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **9" x 9" Red & Black Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **9" x 9" Red & Black Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>100</b>		
MATERIAL DESCRIPTION:	<b>4" Black Vinyl Baseboard</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement East Corridor of 1895 Building, Basement East Corridor of 1909 Building**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **100**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard**

MATERIAL LOCATION: **Basement East Corridor of 1895 Building, Basement East Corridor of 1909 Building**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>101</b>		
MATERIAL DESCRIPTION:	<b>4" Black Vinyl Baseboard Adhesive</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement East Corridor of 1895 Building, Basement East Corridor of 1909 Building**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **101**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Basement East Corridor of 1895 Building, Basement East Corridor of 1909 Building**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 11  
MATERIAL DESCRIPTION: 9" x 9" Green w/ White Marbling Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **9" x 9" Green w/ White Marbling Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 12

MATERIAL DESCRIPTION: 9" x 9" Green w/ White Marbling Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **9" x 9" Green w/ White Marbling Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	12" x 12" Cream w/ Tan Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen, 2nd & 3rd Floor Teachers' Rooms		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12" x 12" Cream w/ Tan Specks Floor Tile**

MATERIAL LOCATION: **Kitchen, 2nd & 3rd Floor Teachers' Rooms**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>15</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Pale Brown w/ Cream &amp; Dark Brown Specks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Kitchen, 2nd &amp; 3rd Floor Teachers' Rooms</b>		
MATERIAL QUANTITY:	<b>700</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **12" x 12" Pale Brown w/ Cream & Dark Brown Specks Floor Tile**

MATERIAL LOCATION: **Kitchen, 2nd & 3rd Floor Teachers' Rooms**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	12" x 12" Cream w/ Tan Specks and Pale Brown w/ Cream & Dark Brown Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen, 2nd & 3rd Floor Teachers' Rooms**

MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **12" x 12" Cream w/ Tan Specks and Pale Brown w/ Cream & Dark Brown Specks Floor Tile Mastic**

MATERIAL LOCATION: **Kitchen, 2nd & 3rd Floor Teachers' Rooms**

MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 17

MATERIAL DESCRIPTION: 12" x 12" Dark Brown w/ Cream & Red Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **12" x 12" Dark Brown w/ Cream & Red Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12" x 12" Dark Brown w/ Cream & Red Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12" x 12" Dark Brown w/ Cream & Red Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **12" x 12" Coffee w/ Cream Specks Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **12" x 12" Coffee w/ Cream Specks Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 2  
MATERIAL DESCRIPTION: Hard Plaster  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout 1895 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **Hard Plaster**

MATERIAL LOCATION: **Throughout 1895 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 20

MATERIAL DESCRIPTION: 12" x 12" Coffee w/ Cream Specks Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **12" x 12" Coffee w/ Cream Specks Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>21</b>		
MATERIAL DESCRIPTION:	<b>9" x 9" Coffee w/ Cream Specks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Rooms 104, 106, 205, 206, 207, 304, 305, 307</b>		
MATERIAL QUANTITY:	<b>3012</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Room 309 replaced with 24" x 24" blue, white, gray flooring (HA 92)</b>		

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **9" x 9" Coffee w/ Cream Specks Floor Tile**

MATERIAL LOCATION: **Rooms 104, 106, 205, 206, 207, 304, 305, 307**

MATERIAL QUANTITY: **3012** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>22</b>		
MATERIAL DESCRIPTION:	<b>9" x 9" Coffee w/ Cream Specks Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with potential for significant damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 104, 106, 205, 206, 207, 304, 305, 307</b>		
MATERIAL QUANTITY:	<b>3012</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Room 309 replaced with 24" x 24" blue, white, gray flooring (HA 93)</b>		

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **9" x 9" Coffee w/ Cream Specks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 104, 106, 205, 206, 207, 304, 305, 307**

MATERIAL QUANTITY: **3012** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>23</b>	
MATERIAL DESCRIPTION:	<b>9" x 9" Tan w/ Rust &amp; Cream Marbling Floor Tile</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **DUPLICATE OF HA 21**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **9" x 9" Tan w/ Rust & Cream Marbling Floor Tile**

MATERIAL LOCATION: **DUPLICATE OF HA 21**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>24</b>	
MATERIAL DESCRIPTION:	<b>9" x 9" Tan w/ Rust &amp; Cream Marbling Floor Tile Mastic</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **DUPLICATE OF HA 22**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **9" x 9" Tan w/ Rust & Cream Marbling Floor Tile Mastic**

MATERIAL LOCATION: **DUPLICATE OF HA 22**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUILDING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 25  
MATERIAL DESCRIPTION: 9" x 9" Black w/ White Marbling Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **9" x 9" Black w/ White Marbling Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUILDING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **9" x 9" Black w/ White Marbling Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **9" x 9" Black w/ White Marbling Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUILDING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 27  
MATERIAL DESCRIPTION: 9" x 9" Coffee w/ Cream Specks Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **9" x 9" Coffee w/ Cream Specks Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28

MATERIAL DESCRIPTION: 9" x 9" Coffee w/ Cream Specks Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **9" x 9" Coffee w/ Cream Specks Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>29</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Multi-Cream w/ Tan Specks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 101</b>		
MATERIAL QUANTITY:	<b>1390</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **12" x 12" Multi-Cream w/ Tan Specks Floor Tile**

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY: **1390** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>3</b>		
MATERIAL DESCRIPTION:	<b>Wains Coat Molding</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Throughout 1909 Building</b>		
MATERIAL QUANTITY:	<b>5000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **Wains Coat Molding**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>30</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Multi-Cream w/ Tan Specks Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 101</b>		
MATERIAL QUANTITY:	<b>1390</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **12" x 12" Multi-Cream w/ Tan Specks Floor Tile Mastic**

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY: **1390** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>31</b>		
MATERIAL DESCRIPTION:	<b>2' x 4' Lay-in Ceiling Panels</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Teachers' Bathroom & Lounge, Offices, 101, 102, 111, 112, 113, Main Office, Gym**

MATERIAL QUANTITY: **1568** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **2' x 4' Lay-in Ceiling Panels**

MATERIAL LOCATION: **Teachers' Bathroom & Lounge, Offices, 101, 102, 111, 112, 113, Main Office, Gym**

MATERIAL QUANTITY: **1568** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>32</b>		
MATERIAL DESCRIPTION:	<b>Drywall &amp; Joint Compound</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>E&amp;W Boys Playrooms, 1st Floor Teachers' Lounge &amp; Bathroom</b>		
MATERIAL QUANTITY:	<b>1600</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Drywall & Joint Compound**

MATERIAL LOCATION: **E&W Boys Playrooms, 1st Floor Teachers' Lounge & Bathroom**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUILDING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 33  
MATERIAL DESCRIPTION: 2' x 4' Black Border Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Lunchroom

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **2' x 4' Black Border Floor Tile**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUILDING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 34  
MATERIAL DESCRIPTION: 2' x 4' Black Border Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Lunchroom

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **2' x 4' Black Border Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUILDING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 35  
MATERIAL DESCRIPTION: 12" x 12" White w/ Charcoal Streaks Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Lunchroom

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **12" x 12" White w/ Charcoal Streaks Floor Tile**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUILDING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36	
MATERIAL DESCRIPTION:	12" x 12" White w/ Charcoal Streaks Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Lunchroom

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **12" x 12" White w/ Charcoal Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 37  
MATERIAL DESCRIPTION: Interior Brick  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout 1909 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Interior Brick**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 38  
MATERIAL DESCRIPTION: Interior Brick Mortar  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout 1909 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 39  
MATERIAL DESCRIPTION: Interior Brick  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout 1895 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Interior Brick**

MATERIAL LOCATION: **Throughout 1895 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>4</b>		
MATERIAL DESCRIPTION:	<b>Wains Coat Molding</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Throughout 1895 Building</b>		
MATERIAL QUANTITY:	<b>5000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **Wains Coat Molding**

MATERIAL LOCATION: **Throughout 1895 Building**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 40  
MATERIAL DESCRIPTION: Interior Brick Mortar  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout 1895 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **Throughout 1895 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Glazed Brick**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1895 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Glazed Brick**

MATERIAL LOCATION: **Throughout 1895 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **Glazed Brick Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1895 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Glazed Brick Mortar**

MATERIAL LOCATION: **Throughout 1895 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 43  
MATERIAL DESCRIPTION: Cinder Block  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout 1895 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Cinder Block**

MATERIAL LOCATION: **Throughout 1895 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 44  
MATERIAL DESCRIPTION: Cinder Block Mortar  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout 1895 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

MATERIAL LOCATION: **Throughout 1895 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 45

MATERIAL DESCRIPTION: Sink Caulk

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boys & Girls Basement Bathrooms

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Sink Caulk**

MATERIAL LOCATION: **Boys & Girls Basement Bathrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 46  
MATERIAL DESCRIPTION: Window Caulk  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Facility

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Window Caulk**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Door Caulk**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **East and West Basement Entry Doors**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Door Caulk**

MATERIAL LOCATION: **East and West Basement Entry Doors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>48</b>		
MATERIAL DESCRIPTION:	<b>Boiler Gaskets</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Boiler #1 - Replaced</b>		
MATERIAL QUANTITY:	<b>15</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Boiler Gaskets**

MATERIAL LOCATION: **Boiler #1 - Replaced**

MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>49</b>		
MATERIAL DESCRIPTION:	<b>Boiler Gaskets</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Boiler #2 - Replaced</b>		
MATERIAL QUANTITY:	<b>15</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Boiler Gaskets**

MATERIAL LOCATION: **Boiler #2 - Replaced**

MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>5</b>		
MATERIAL DESCRIPTION:	<b>9" x 9" Light Green w/ White Marbling Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with potential for significant damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Store Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **9" x 9" Light Green w/ White Marbling Floor Tile**

MATERIAL LOCATION: **Basement Store Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>50</b>		
MATERIAL DESCRIPTION:	<b>Spray on Fireproofing on Ceiling</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Damaged friable surfacing ACBM</b>		
HISTORICAL DAMAGE REASON:	<b>Physical Damage</b>		
HISTORICAL RESPONSE ACTION:	<b>Remove</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Boiler Room &amp; Tank Room</b>		
MATERIAL QUANTITY:	<b>320</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Spray on Fireproofing on Ceiling**

MATERIAL LOCATION: **Boiler Room & Tank Room**

MATERIAL QUANTITY: **320** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUILDING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 51  
MATERIAL DESCRIPTION: Purple Carpet Mastic  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Purple Carpet Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **MATERIAL REMOVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **Blue Carpet Mastic**

MATERIAL LOCATION: **MATERIAL REMOVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53	
MATERIAL DESCRIPTION:	Man Hole & Hand Hole Boiler Gaskets	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: MATERIAL REMOVED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **Man Hole & Hand Hole Boiler Gaskets**

MATERIAL LOCATION: **MATERIAL REMOVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54	
MATERIAL DESCRIPTION:	Man Hole & Hand Hole Boiler Gaskets	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: MATERIAL REMOVED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Man Hole & Hand Hole Boiler Gaskets**

MATERIAL LOCATION: **MATERIAL REMOVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **Fire Brick**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **MATERIAL REMOVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Fire Brick**

MATERIAL LOCATION: **MATERIAL REMOVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **Fire Brick**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **MATERIAL REMOVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **Fire Brick**

MATERIAL LOCATION: **MATERIAL REMOVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>57</b>		
MATERIAL DESCRIPTION:	<b>Insulation Inside Of Vault Door</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Main Office</b>		
MATERIAL QUANTITY:	<b>30</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **Insulation Inside Of Vault Door**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	12" x 12" Off-White w/ Blue Specks Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Deterioration		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Principal's Office, Main Office, Library, Storage by 202, 2nd Floor Storage Between Girls and Boys Bathrooms		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Blue Specks Vinyl Floor Tile**

MATERIAL LOCATION: **Principal's Office, Main Office, Library, Storage by 202, 2nd Floor Storage Between Girls and Boys Bathrooms**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	59		
MATERIAL DESCRIPTION:	12" x 12" Off-White w/ Blue Specks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Principal's Office, Main Office, Library, Storage by 202, 2nd Floor Storage Between Girls and Boys Bathrooms**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Blue Specks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Principal's Office, Main Office, Library, Storage by 202, 2nd Floor Storage Between Girls and Boys Bathrooms**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>6</b>		
MATERIAL DESCRIPTION:	<b>9" x 9" Dark Green w/ White Marbling Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Store Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **9" x 9" Dark Green w/ White Marbling Floor Tile**

MATERIAL LOCATION: **Basement Store Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>60</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Off-White w/ Blue &amp; Gray Specks Vinyl Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 113/114</b>		
MATERIAL QUANTITY:	<b>925</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile**

MATERIAL LOCATION: **Rooms 113/114**

MATERIAL QUANTITY: **925** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>61</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Off-White w/ Blue &amp; Gray Specks Vinyl Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 113/114</b>		
MATERIAL QUANTITY:	<b>925</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 113/114**

MATERIAL QUANTITY: **925** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	62		
MATERIAL DESCRIPTION:	12" x 12" Off-White w/ Blue & Gray Streaks Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 102/103 Principal's Office		
MATERIAL QUANTITY:	1418	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Blue & Gray Streaks Vinyl Floor Tile**

MATERIAL LOCATION: **Rooms 102/103 Principal's Office**

MATERIAL QUANTITY: **1418** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>63</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Off-White w/ Blue &amp; Gray Streaks Vinyl Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 102/103 Principal's Office**

MATERIAL QUANTITY: **1418** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Blue & Gray Streaks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 102/103 Principal's Office**

MATERIAL QUANTITY: **1418** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>64</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Off-White w/ Blue &amp; Gray Specks Vinyl Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Teachers' Bathroom</b>		
MATERIAL QUANTITY:	<b>172</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile**

MATERIAL LOCATION: **Teachers' Bathroom**

MATERIAL QUANTITY: **172** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>65</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Off-White w/ Blue &amp; Gray Specks Vinyl Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Teachers' Bathroom</b>		
MATERIAL QUANTITY:	<b>172</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Teachers' Bathroom**

MATERIAL QUANTITY: **172** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>66</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Off-White w/ Blue &amp; Gray Specks Vinyl Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 107</b>		
MATERIAL QUANTITY:	<b>1215</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile**

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY: **1215** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>67</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Off-White w/ Blue &amp; Gray Specks Vinyl Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 107</b>		
MATERIAL QUANTITY:	<b>1215</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Blue & Gray Specks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY: **1215** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	68		
MATERIAL DESCRIPTION:	12" x 12" Off-White w/ Black Specks Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Corridor - 1895 Building, Storage by 202, 2nd Floor Storage Between Girls and Boys Bathrooms**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29141** BUILDING ID: **4160**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Galileo Academy** REVIEW DATE: **8/7/2025**

ADDRESS: **820 S. Carpenter** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Black Specks Vinyl Floor Tile**

MATERIAL LOCATION: **1st Floor Corridor - 1895 Building, Storage by 202, 2nd Floor Storage Between Girls and Boys Bathrooms**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	69		
MATERIAL DESCRIPTION:	12" x 12" Off-White w/ Black Specks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Corridor - 1895 Building, Storage by 202, 2nd Floor Storage Between Girls and Boys Bathrooms**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29141** BULDING ID: **4160**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Galileo Academy** REVIEW DATE: **8/7/2025**

ADDRESS: **820 S. Carpenter** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Black Specks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **1st Floor Corridor - 1895 Building, Storage by 202, 2nd Floor Storage Between Girls and Boys Bathrooms**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>7</b>	
MATERIAL DESCRIPTION:	<b>9" x 9" Dark Green &amp; Light Green w/ White Marbling Floor Tile Mastic</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Store Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **9" x 9" Dark Green & Light Green w/ White Marbling Floor Tile Mastic**

MATERIAL LOCATION: **Basement Store Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>70</b>		
MATERIAL DESCRIPTION:	<b>Sink Undercoating</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 106</b>		
MATERIAL QUANTITY:	<b>5</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **Sink Undercoating**

MATERIAL LOCATION: **Room 106**

MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	71		
MATERIAL DESCRIPTION:	6" x 6" Brown Quarry Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen, Teachers' Lunchroom and Lunchroom		
MATERIAL QUANTITY:	2313	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **6" x 6" Brown Quarry Tile**

MATERIAL LOCATION: **Kitchen, Teachers' Lunchroom and Lunchroom**

MATERIAL QUANTITY: **2313** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>72</b>		
MATERIAL DESCRIPTION:	<b>6" x 6" Brown Quarry Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Kitchen, Teachers' Lunchroom and Lunchroom</b>		
MATERIAL QUANTITY:	<b>2313</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **6" x 6" Brown Quarry Tile Mastic**

MATERIAL LOCATION: **Kitchen, Teachers' Lunchroom and Lunchroom**

MATERIAL QUANTITY: **2313** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	73		
MATERIAL DESCRIPTION:	12" x 12" Off-White w/ Gray & Blue Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Principal's Office		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Gray & Blue Specks Floor Tile**

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>74</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Off-White w/ Gray &amp; Blue Specks Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Principal's Office</b>		
MATERIAL QUANTITY:	<b>700</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Gray & Blue Specks Floor Tile Mastic**

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 75  
MATERIAL DESCRIPTION: 12" x 12" White w/ Gray Streaks Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: MATERIAL REMOVED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Streaks Floor Tile**

MATERIAL LOCATION: **MATERIAL REMOVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 76

MATERIAL DESCRIPTION: 12" x 12" White w/ Gray Streaks Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: MATERIAL REMOVED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Streaks Floor Tile Mastic**

MATERIAL LOCATION: **MATERIAL REMOVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>77</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" White w/ Blue Streaks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>School Elevators, Nurse Office, Rooms 314, 306, 114, 113, 010</b>		
MATERIAL QUANTITY:	<b>2308</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **12" x 12" White w/ Blue Streaks Floor Tile**

MATERIAL LOCATION: **School Elevators, Nurse Office, Rooms 314, 306, 114, 113, 010**

MATERIAL QUANTITY: **2308** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>78</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" White w/ Blue Streaks Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>School Elevators, Nurse Office, Rooms 314, 306, 114, 113, 010</b>		
MATERIAL QUANTITY:	<b>2308</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **12" x 12" White w/ Blue Streaks Floor Tile Mastic**

MATERIAL LOCATION: **School Elevators, Nurse Office, Rooms 314, 306, 114, 113, 010**

MATERIAL QUANTITY: **2308** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>79</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Black w/ White Streaks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1895 Building Basement Corridor and 1909 Building Basement Corridor, Kiln Room**

MATERIAL QUANTITY: **5370** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **12" x 12" Black w/ White Streaks Floor Tile**

MATERIAL LOCATION: **1895 Building Basement Corridor and 1909 Building Basement Corridor, Kiln Room**

MATERIAL QUANTITY: **5370** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 8

MATERIAL DESCRIPTION: 9" x 9" Black Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: MATERIAL REMOVED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile**

MATERIAL LOCATION: **MATERIAL REMOVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>80</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Black w/ White Streaks Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1895 Building Basement Corridor and 1909 Building Basement Corridor, Kiln Room**

MATERIAL QUANTITY: **5370** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **12" x 12" Black w/ White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **1895 Building Basement Corridor and 1909 Building Basement Corridor, Kiln Room**

MATERIAL QUANTITY: **5370** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	81		
MATERIAL DESCRIPTION:	12" x 12" White w/ Blue Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 212 and 213, 2nd & 3rd Floor Teacher Rooms, Kitchen, Lunchroom, Basement Lunchroom, 1st Floor Principal's Office, 010**

MATERIAL QUANTITY: **7612** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29141** BULDING ID: **4160**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Galileo Academy** REVIEW DATE: **8/7/2025**

ADDRESS: **820 S. Carpenter** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **12" x 12" White w/ Blue Streaks Floor Tile**

MATERIAL LOCATION: **Rooms 212 and 213, 2nd & 3rd Floor Teacher Rooms, Kitchen, Lunchroom, Basement  
Lunchroom, 1st Floor Principal's Office, 010**

MATERIAL QUANTITY: **7612** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUILDING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	82		
MATERIAL DESCRIPTION:	12" x 12" White w/ Blue Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 212 and 213, 2nd & 3rd Floor Teacher Rooms, Kitchen, Lunchroom, Basement Lunchroom, 1st Floor Principal's Office, 010**

MATERIAL QUANTITY: **7612** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **12" x 12" White w/ Blue Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 212 and 213, 2nd & 3rd Floor Teacher Rooms, Kitchen, Lunchroom, Basement  
Lunchroom, 1st Floor Principal's Office, 010**

MATERIAL QUANTITY: **7612** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	83		
MATERIAL DESCRIPTION:	Brown Vinyl Sheet Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 107 Storage		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **Brown Vinyl Sheet Flooring**

MATERIAL LOCATION: **Room 107 Storage**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>84</b>		
MATERIAL DESCRIPTION:	<b>Blue Carpet Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 107, Room 107 Office</b>		
MATERIAL QUANTITY:	<b>200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **Blue Carpet Mastic**

MATERIAL LOCATION: **Room 107, Room 107 Office**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>85</b>		
MATERIAL DESCRIPTION:	<b>Tongue and Groove Wood Flooring</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 109, 105, 112, 111, Auditorium, Auditorium Balcony, 211, 210, 201, 202, Corridor 1895 Building, 204, 204 Closet, 205 Closet, 208, 305 Closet, 304 Closet, 303, 302, 301, 313, 310, 312, 311**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **85**

MATERIAL DESCRIPTION: **Tongue and Groove Wood Flooring**

MATERIAL LOCATION: **Room 109, 105, 112, 111, Auditorium, Auditorium Balcony, 211, 210, 201, 202, Corridor 1895 Building, 204, 204 Closet, 205 Closet, 208, 305 Closet, 304 Closet, 303, 302, 301, 313, 310, 312, 311**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>86</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" White w/ Tan Specks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 106, 206</b>		
MATERIAL QUANTITY:	<b>900</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **86**

MATERIAL DESCRIPTION: **12" x 12" White w/ Tan Specks Floor Tile**

MATERIAL LOCATION: **Rooms 106, 206**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>87</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" White w/ Tan Specks Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 106, 206</b>		
MATERIAL QUANTITY:	<b>900</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **87**

MATERIAL DESCRIPTION: **12" x 12" White w/ Tan Specks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 106, 206**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>88</b>		
MATERIAL DESCRIPTION:	<b>4" Beige Baseboard</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Gym</b>		
MATERIAL QUANTITY:	<b>350</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **4" Beige Baseboard**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	89		
MATERIAL DESCRIPTION:	4" Beige Baseboard Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	350	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **89**

MATERIAL DESCRIPTION: **4" Beige Baseboard Adhesive**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**  
MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **MATERIAL REMOVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile**

MATERIAL LOCATION: **MATERIAL REMOVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>90</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Off-White w/ Tan Specks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 206</b>		
MATERIAL QUANTITY:	<b>900</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Tan Specks Floor Tile**

MATERIAL LOCATION: **Room 206**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>91</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Off-White w/ Tan Specks Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 206</b>		
MATERIAL QUANTITY:	<b>900</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **91**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Tan Specks Floor Tile Mastic**

MATERIAL LOCATION: **Room 206**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>92</b>		
MATERIAL DESCRIPTION:	<b>24" x 24" Blue Streaked Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 308, 309a, 309</b>		
MATERIAL QUANTITY:	<b>300</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **24" x 24" Blue Streaked Floor Tile**

MATERIAL LOCATION: **Room 308, 309a, 309**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>93</b>		
MATERIAL DESCRIPTION:	<b>24" x 24" Gray Streaked Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 308, 309a, 309</b>		
MATERIAL QUANTITY:	<b>300</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **93**

MATERIAL DESCRIPTION: **24" x 24" Gray Streaked Floor Tile**

MATERIAL LOCATION: **Room 308, 309a, 309**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>94</b>		
MATERIAL DESCRIPTION:	<b>24" x 24" White Streaked Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 308, 309a, 309</b>		
MATERIAL QUANTITY:	<b>300</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **94**

MATERIAL DESCRIPTION: **24" x 24" White Streaked Floor Tile**

MATERIAL LOCATION: **Room 308, 309a, 309**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>95</b>		
MATERIAL DESCRIPTION:	<b>24" x 24" Blue, Gray and White Streaked Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 308 309a, 309</b>		
MATERIAL QUANTITY:	<b>900</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **95**

MATERIAL DESCRIPTION: **24" x 24" Blue, Gray and White Streaked Floor Tile Mastic**

MATERIAL LOCATION: **Room 308 309a, 309**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>96</b>		
MATERIAL DESCRIPTION:	<b>Wavy Gray Vinyl Flooring</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>West Stairwell Basement Womens3rd Floor</b>		
MATERIAL QUANTITY:	<b>1200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **96**

MATERIAL DESCRIPTION: **Wavy Gray Vinyl Flooring**

MATERIAL LOCATION: **West Stairwell Basement Womens3rd Floor**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>97</b>		
MATERIAL DESCRIPTION:	<b>Adhesive Associated w/ Wavy Gray Vinyl Flooring</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>West Stairwell, Basement, Women's 3rd Floor Bathroom</b>		
MATERIAL QUANTITY:	<b>1200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **97**

MATERIAL DESCRIPTION: **Adhesive Associated w/ Wavy Gray Vinyl Flooring**

MATERIAL LOCATION: **West Stairwell, Basement, Women's 3rd Floor Bathroom**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	98		
MATERIAL DESCRIPTION:	Wavy Gray Vinyl Stair Tread		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	West Stairwell Basement Womens3rd Floor		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **98**

MATERIAL DESCRIPTION: **Wavy Gray Vinyl Stair Tread**

MATERIAL LOCATION: **West Stairwell Basement Womens3rd Floor**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>99</b>		
MATERIAL DESCRIPTION:	<b>Adhesive Associated w/ Wavy Gray Vinyl Stair Tread</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>West Stairwell, Basement, Women's 3rd Floor Bathroom</b>		
MATERIAL QUANTITY:	<b>800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **99**

MATERIAL DESCRIPTION: **Adhesive Associated w/ Wavy Gray Vinyl Stair Tread**

MATERIAL LOCATION: **West Stairwell, Basement, Women's 3rd Floor Bathroom**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUILDING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: A

MATERIAL DESCRIPTION: Aircell Pipe Insulation

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>B</b>		
MATERIAL DESCRIPTION:	<b>Cardboard Pipe Insulation</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1909 Building - Basement Corridors, Boy's Play Room</b>		
MATERIAL QUANTITY:	<b>75</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **1909 Building - Basement Corridors, Boy's Play Room**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>C</b>		
MATERIAL DESCRIPTION:	<b>Cementitious Pipe Joint Insulation Off Fiberglass</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1909 Building - Basement Corridors, Boy's Play Room</b>		
MATERIAL QUANTITY:	<b>150</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Cementitious Pipe Joint Insulation Off Fiberglass**

MATERIAL LOCATION: **1909 Building - Basement Corridors, Boy's Play Room**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUILDING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: D  
MATERIAL DESCRIPTION: Pipe Cover  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1909 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Pipe Cover**

MATERIAL LOCATION: **1909 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Mag Block Insulation on Boiler**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Mag Block Insulation on Boiler**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>F</b>		
MATERIAL DESCRIPTION:	<b>Cementitious Joint Insulation on Cardboard Lagging</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1909 Building - Engine Room</b>		
MATERIAL QUANTITY:	<b>100</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Cementitious Joint Insulation on Cardboard Lagging**

MATERIAL LOCATION: **1909 Building - Engine Room**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Boiler Gaskets**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **MATERIAL REMOVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Boiler Gaskets**

MATERIAL LOCATION: **MATERIAL REMOVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>H</b>		
MATERIAL DESCRIPTION:	<b>Aircell Pipe Insulation</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1895 Building - Basement Hallways, Tank Room Boiler Room</b>		
MATERIAL QUANTITY:	<b>500</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **1895 Building - Basement Hallways, Tank Room Boiler Room**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>I</b>		
MATERIAL DESCRIPTION:	<b>Cardboard Pipe Insulation</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1895 Building - Basement Corridor, Lunchroom</b>		
MATERIAL QUANTITY:	<b>400</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **1895 Building - Basement Corridor, Lunchroom**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>J</b>		
MATERIAL DESCRIPTION:	<b>Cementitious Joint Insulation on Cardboard Lagging</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1895 Building - Basement Corridors</b>		
MATERIAL QUANTITY:	<b>1500</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Cementitious Joint Insulation on Cardboard Lagging**

MATERIAL LOCATION: **1895 Building - Basement Corridors**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>K</b>		
MATERIAL DESCRIPTION:	<b>Mag Block Pipe Insulation</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1909 Building Engine Room, 1895 Building Engine Room</b>		
MATERIAL QUANTITY:	<b>150</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:			
COMMENTS:	<b>Not observed in Kitchen</b>		

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**

MATERIAL LOCATION: **1909 Building Engine Room, 1895 Building Engine Room**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Felight Pipe Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Chrysotile** FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Felight Pipe Insulation**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Cementitious Joint Insulation on Felight Lagging**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Cementitious Joint Insulation on Felight Lagging**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>N</b>		
MATERIAL DESCRIPTION:	<b>Cementitious Joint Insulation on Felight Lagging</b>		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Cementitious Joint Insulation on Felight Lagging**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>O</b>		
MATERIAL DESCRIPTION:	<b>Mag Block Pipe Insulation</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1909 Building - Engine Room</b>		
MATERIAL QUANTITY:	<b>150</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **O**

MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**

MATERIAL LOCATION: **1909 Building - Engine Room**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>P</b>		
MATERIAL DESCRIPTION:	<b>Mag Block Pipe Joint Insulation</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1895 Building - Engine Room**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **Mag Block Pipe Joint Insulation**

MATERIAL LOCATION: **1895 Building - Engine Room**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>Q</b>		
MATERIAL DESCRIPTION:	<b>Mag Block Pipe Joint Insulation</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1909 Building - Engine Room</b>		
MATERIAL QUANTITY:	<b>20</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **Q**

MATERIAL DESCRIPTION: **Mag Block Pipe Joint Insulation**

MATERIAL LOCATION: **1909 Building - Engine Room**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>R</b>		
MATERIAL DESCRIPTION:	<b>Cementitious Joint Insulation on Aircell Lagging</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1895 Building - Boiler Room</b>		
MATERIAL QUANTITY:	<b>200</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **R**

MATERIAL DESCRIPTION: **Cementitious Joint Insulation on Aircell Lagging**

MATERIAL LOCATION: **1895 Building - Boiler Room**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>S</b>		
MATERIAL DESCRIPTION:	<b>Cementitious Joint Insulation on Aircell Lagging</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1909 Building - Engine Room</b>		
MATERIAL QUANTITY:	<b>50</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **S**

MATERIAL DESCRIPTION: **Cementitious Joint Insulation on Aircell Lagging**

MATERIAL LOCATION: **1909 Building - Engine Room**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	29141	BUIDLING ID:	4160
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Galileo Academy	INSPECTION DATE:	7/28/2025		
ADDRESS:	820 S. Carpenter	IDPH LICENSE NO:	100-03175		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	T		
MATERIAL DESCRIPTION:	Cementitious Joint Insulation on Fiberglass Pipes		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1895 Building - Basement Corridor, Engine Room		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 07/28/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **T**

MATERIAL DESCRIPTION: **Cementitious Joint Insulation on Fiberglass Pipes**

MATERIAL LOCATION: **1895 Building - Basement Corridor, Engine Room**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUIDLING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Marcos Iwankiw</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	INSPECTION DATE:	<b>7/28/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **U**

MATERIAL DESCRIPTION: **Duct Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engine Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **07/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>29141</b>	BUILDING ID:	<b>4160</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Galileo Academy</b>	REVIEW DATE:	<b>8/7/2025</b>		
ADDRESS:	<b>820 S. Carpenter</b>	IDPH LICENSE NO:	<b>100-03175</b>		

---

HOMOGENEOUS AREA: **U**

MATERIAL DESCRIPTION: **Duct Insulation**

MATERIAL LOCATION: **Engine Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/07/2025**

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2025 AHERA REINSPECTION***

## APPENDIX B

---

### Inspector and Management Planner Licenses



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2024

## Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

### Marcos Iwankiw

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. This course is accredited by the State of Wisconsin, Department of Health Services under ch. DHS 159, Wis. Admin. Code, The Illinois Department of Public Health and The Indiana Department of Environmental Management, under 326 IAC 18. Training was in accordance with requirements listed under EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Location: 12304 75th Street  
Kenosha, WI 53142

Certificate Number: BIRWI2410112747  
Course Date: 10/11/2024  
Exam Date: 10/11/2024  
Expiration Date: 10/11/2025



Issue Date: 10/11/2024


3  
Tyler Nicholson, Authorized Signer

Course Credit Hours: BIR WI 4 Hours

# Marcos Iwankiw

---

Illinois Licensed Building Inspector, Air Sampling Professional, Asbestos Project Manager



**ENDORSEMENTS**

INSPECTOR

**TC EXPIRES**

10/11/2025

PROJECT MANAGER  
AIR SAMPLING PROFESSIONAL



1/2/2026

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.



# Jackson Montgomery

Illinois Licensed Building Inspector, Air Sampling Professional, Management Planner



**ENDORSEMENTS**

INSPECTOR

**TC EXPIRES**

2/22/2025

**ENDORSEMENTS**

**TC EXPIRES**

10/29/2025

**AIR SAMPLING PROFESSIONAL**

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.



2200 Vandalia Street, Collinsville, IL 62234 \* Phone: 618-855-8764

## Environmental and Occupational Safety & Health Training

*Does hereby certify*

**Jackson Montgomery**

600 W. Van Buren St., Suite 500, Chicago, IL 60607



*Has successfully completed and passed the course examination with at least  
70% for accreditation under AHERA (Title II)*

## **Asbestos Management Planner Initial**

*Class Date:* 10/28-29/2024

*Examination Date:* 10/29/2024

*STC Certificate Number:* STC-20241029-000101AMPI

*Certification Expiration:* 10/29/2025

A handwritten signature in black ink that reads 'David M. Mendoza'.

*David M. Mendoza – President/Training Director*

*Certified Environmental Specialist*

*OSHA Authorized Instructor*

*This training course is accredited by the Illinois Department of Public Health and the Missouri Department of Natural Resources*

## APPENDIX C

---

### **Laboratory Accreditations**

## APPENDIX D

---

### Laboratory Results

## APPENDIX E

---

### Chain of Custody Forms

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>	Loc	Localized
	Dist	Distributed