

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2470
SCHOOL NAME: Stockton School
ADDRESS OF SCHOOL: 4420 N Beacon Street
CITY: Chicago, IL, 60640

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 1/10/2023

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 1/29/2025 ENROLLMENT 256
IDPH INSPECTOR LICENSE NUMBER: 100-20221
IDPH LICENSED INSPECTOR NAME (Please Print): Charles Brown
IDPH MP LICENSE NUMBER: 100-04019
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Arturo Saenz

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 3/3/2025

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Stockton School

4420 N Beacon Street
Chicago, IL, 60640

Unit: 30141
Building ID: 6060

IDPH ID Number: 14-016-2990-2470

REPORT DATE:
Monday, March 03, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
Specialty Consulting, Inc.

2942 W. Van Buren Street
Chicago, IL, 60612
Phone (312) 319-7575
Fax (312) 319-7580

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

03/03/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Specialty Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 25501 Region: 01 IDPH ID: 14-016-2990-2470

School: Stockton School Building ID: 6060

Address: 4420 N Beacon Street

Chicago, IL, 60640

Building Contact: Nesse, Cameron Contact Phone: 7737096997

Current Building Owners: Chicago Public Schools

Reinspection Date: 1/29/2025

Review Date: 03/03/2025

Inspector: Charles Brown

Inspector IDPH License: 100-20221

Management Planner: Arturo Saenz

Management Planner IDPH License: 100-04019

If you have any questions or comments, please contact us at (312) 319-7575

Sincerely,
Specialty Consulting, Inc.



Arturo Saenz
100-04019

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: March 03, 2025

RE: Stockton School, Unit 30141
4420 N Beacon Street
Chicago, IL, 60640

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Stockton School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Stockton School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Stockton School Unit: 25501 Region: 01
Address: 4420 N Beacon Street Chicago, IL, 60640
IDPH ID: 14-016-2990-2470 Building ID: 6060
Contact: Nesse, Cameron Phone: 7737096997

2. Description of Facility

Original Construction: 1925 Additional Construction: 1965
Total Square Footage: 92490 No of Floors: 3
Current Occupancy: 256

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Specialty Consulting, Inc.
Contact: Jigar Shah
Address 2942 W. Van Buren Street
Phone: (312) 319-7575 Fax: (312) 319-7580

5. Inspector

Inspector Name: Charles Brown

Inspector IDPH license # 100-20221
Reinspection Date: 1/29/2025



Signature:
Date: 1/29/2025

6. Management Planner

Management Planner Name: Arturo Saenz

Management Planner IDPH license # 100-04019



Signature:
Date: 03/03/2025

7. Review Date: 03/03/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.


Signature: Date: 3/3/2025

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Specialty Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Stockton School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

- A. The following HAs have changed assessment categories for Building 6060:

B. The following new homogenous areas have been identified for Building 6060:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	Hard Coat Plaster
02	2'x4' Ceiling Tile
03	2'x2' Ceiling Tile
06	1'x1' Ceiling Tile
08	Orange Linoleum - NOT OBSERVED
09	Spray-on Fireproofing
09B	Spray-on Fireproofing
11	Smooth Plaster
18	12"x12" White w/Beige Streaks VFT
20	12"x12" Gray w/Dark Gray Streaks VFT
22B	9" x 9" Orange w/ Gray Streaks VFT
23B	9" x 9" Orange w/ Gray Streaks VFT Mastic
30	12"x12" Blue VFT
31	12"x12" Blue VFT Mastic
32	12"x12" Tan & Beige VFT
33	12"x12" Tan & Beige VFT Mastic
34	2'x4' Dot/Wave Ceiling Tile
35	12"x12" Gray VFT
36	12"x12" Gray VFT Mastic
37	12"X12" White w/Tan Specks VFT
39	Terrazzo
40	Decorative Plaster
41	Stucco Plaster
42	Terrazzo
43	Fire doors
44	12"x12" Gray w/ black specs VFT
44A	12"x12" Gray w/ black specs VFT Mastic
45	12"x12" Tan w/ white and brown streaks VFT
45A	12"x12" Tan w/ white and brown streaks VFT Mastic
46	12"x12" White with tan specs VFT
46A	12"x12" White with tan specs VFT Mastic
47	Carpet Mastic
48	2'x4' Ceiling Tiles with Grooves
49	12"X12" Light Gray w/ gray streaks VFT
49A	12"x12" Light Gray and Gray Streaks VFT Mastic
50	12"x12" Blue VFT
50A	12"x12" Blue VFT Mastic
51	Linoleum w/ tan, gray, and black specs
51A	Linoleum w/ tan, gray, and black specs mastic
52	12" x 12" Gray w/ White Streaks VFT
52A	12" x 12" Gray w/ White Streaks VFT Mastic

53	12" x 12" Black w/ Gray Streaks VFT
53A	12" x 12" Black w/ Gray Streaks VFT Mastic
54	12" x 12" Light Gray w/ Gray Streaks VFT
54A	12" x 12" Light Gray w/ Gray Streaks VFT Mastic
8M	Orange Linoleum Mastic - NOT OBSERVED
F	MJP E/F/V on Fiberglass Pipe Insulation
M	Gray duct sealant
N	Carpet mastic

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Charles Brown, IDPH License # 100-20221. The Management Plan was updated by Arturo Saenz, IDPH License # 100-04019. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Stockton School Building 6060 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Stockton School **Unit** 25501 **Building ID** 6060
Address 4420 N Beacon Street **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	Hard Coat Plaster	40,000	SF	Throughout - 1924 Bldg.	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		MODERATE
02	2'x4' Ceiling Tile	1,200	SF	Room 311 and 211 - 1924 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
03	2'x2' Ceiling Tile	1,200	SF	Lunchroom - 1924 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
04	Acoustic Sprayed Plaster	420	SF	AV Room/Teachers Lunchroom - 1924 Bldg.	CHR	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
06	1'x1' Ceiling Tile	600	SF	Room 210 - 1924 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
07	12"x12" Brown VFT	7,750	SF	Corridors, Main Office & Vault; Room 103A - 1924 Bldg.	CHR	MISC	N	LOC	19		No	ACBM with the potential for damage	3	MODERATE
08	Orange Linoleum - NOT OBSERVED	1,200	SF	Lunchroom - 1924 Bldg. NOT OBSERVED	ASSUMED	MISC	N		0		No	ACBM with the potential for damage		MODERATE
09	Spray-on Fireproofing	20,000	SF	Throughout - 1965 Bldg.	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
09B	Spray-on Fireproofing	50	SF	Boiler Room - 1924 Bldg.	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
11	Smooth Plaster	10,000	SF	Hallways, Toilets, Janitor's Closet & Store Rooms - 1965 Bldg.	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		MODERATE
13	12"x12" Brown VFT Mastic	7,750	SF	Corridors, Main Office & Vault - 1924 Bldg.	CHR	MISC	N	LOC	19		No	ACBM with the potential for damage	3	LOW
18	12"x12" White w/Beige Streaks VFT	1,200	SF	Rooms 108 (Abated), 111, 210, 307 Under the Carpet, Clinic - 1924 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
19	12"x12" White w/Beige Streaks VFT Mastic	1,200	SF	Rooms 108 (Abated), 111, 210, 307 under carpet), Clinic - 1924 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	12"x12" Gray w/Dark Gray Streaks VFT	300	SF	Teachers Lounge Room Under Existing VFT- 1924 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
21	12"x12" Gray w/Dark Gray Streaks VFT Mastic	450	SF	Teachers Lounge Room Under	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Stockton School **Unit** 25501 **Building ID** 6060
Address 4420 N Beacon Street **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Existing VFT										
22	12"x12" Orange w/Gray Streaks VFT	1,108	SF	Kitchen - 1924 Bldg. - NOT OBSERVED	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
22B	9"x 9" Orange w/ Gray Streaks VFT	800	SF	Kitchen & Storage Entry - 1924 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
23	12"x12" Orange w/Gray Streaks VFT Mastic	1,108	SF	Kitchen - 1924 Bldg. - NOT OBSERVED	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23B	9"x 9" Orange w/ Gray Streaks VFT Mastic	800	SF	Kitchen & Storage Entry - 1924 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	12"x12" White w/Gray Streaks VFT	370	SF	1st Floor Men's & Women's Toilets, Gym Coach Office - 1924 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
25	12"x12" White w/Gray Streaks VFT Mastic	370	SF	1st Floor Men's & Women's Toilets, Gym Coach Office - 1924 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	9"x9" Green VFT	20	SF	Closets across from Room 111 - 1924 Bldg. - NOT OBSERVED	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
27	9"x9" Green VFT Mastic	20	SF	Closets across from Room 111 - 1924 Bldg. - NOT OBSERVED	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	9"x9" Gray VFT	20	SF	Closets across from Room 111 - 1924 Bldg. - NOT OBSERVED	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
29	9"x9" Gray VFT Mastic	20	SF	Closets across from Room 111 - 1924 Bldg. - NOT OBSERVED	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	12"x12" Blue VFT	500	SF	Room 124 and 224 - 1965 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
31	12"x12" Blue VFT Mastic	12,000	SF	Room 124 and 224 - 1965 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	12"x12" Tan & Beige VFT	7,500	SF	1st Floor Men Bathroom, Corridors, 2nd Floor Women Bathroom, 1st & 2nd Floor JC's - 1965	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
33	12"x12" Tan & Beige VFT Mastic	7,500	SF	1st Floor Men	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Stockton School **Unit** 25501 **Building ID** 6060
Address 4420 N Beacon Street **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Bathroom, Corridors, 2nd Floor Women Bathroom, 1st & 2nd Floor JC's - 1965 Bldg.							potential for damage			
34	2'x4' Dot/Wave Ceiling Tile	12,000	SF	Throughout - 1965 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
35	12"x12" Gray VFT	100	SF	Gym Office - 1924 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
36	12"x12" Gray VFT Mastic	100	SF	Gym Office - 1924 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	12"X12" White w/Tan Specks VFT	600	SF	1st Floor Teachers Lounge - 1924 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
38	12"X12" Off-white w/Tan Specks VFT			Room 207 (Abated) - 1924 Bldg	ABATED	MISC								
38A	12"X12" Off-white w/Tan Specks VFT Mastic			Room 207 (Abated) - 1924 Bldg	ABATED	MISC								
39	Terrazzo	10,000	SF	All Corridors That Border All Floors, All Stairwells, All Floors - 1924 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
40	Decorative Plaster	1,000	SF	Auditorium - 1924 Bldg	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		MODERATE
41	Stucco Plaster	2,000	LF	Auditorium - 1924 Bldg. (Upper Balony)	ASSUMED	SURFACE	N	LOC	60		No	Damaged friable surfacing ACBM	10	MODERATE
42	Terrazzo	400	SF	Stairwell - 1965 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
43	Fire doors	10	EA	Auditorium, stage, projector room, balcony - 1924 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	12"x12" Gray w/ black specs VFT	1,100	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
44A	12"x12" Gray w/ black specs VFT Mastic	1,100	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	12"x12" Tan w/ white and brown streaks VFT	150	SF	Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
45A	12"x12" Tan w/ white and brown streaks VFT Mastic	150	SF	Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	12"x12" White with tan specs VFT	700	SF	Rooms 115, 113, 103 and 105 - 1924 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
46A	12"x12" White with tan specs VFT Mastic	700	SF	Rooms 115, 113, 103 and 105 - 1924	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Stockton School **Unit** 25501 **Building ID** 6060
Address 4420 N Beacon Street **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Bldg.										
47	Carpet Mastic	4,000	SF	Auditorium aisles, Rooms 211, 210, 204, 206 - 1924 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	2'x4' Ceiling Tiles with Grooves	400	SF	Room 211	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
49	12"x12" Light Gray w/ gray streaks VFT	4,500	SF	Room 307, magic room, 203, 207, 209 and 108 - 1924 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
49A	12"x12" Light Gray and Gray Streaks VFT Mastic	4,500	SF	Room 307, magic room, 203, 207, 209 and 108 - 1924 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	12"x12" Blue VFT	190	SF	Rooms 203, 207, 209	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
50A	12"x12" Blue VFT Mastic	190	SF	Rooms 203, 207, 209	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	Linoleum w/ tan, gray, and black specs	1,200	SF	Lunchroom- 1924 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
51A	Linoleum w/ tan, gray, and black specs mastic	1,200	SF	Lunchroom- 1924 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	12" x 12" Gray w/ White Streaks VFT	1,600	SF	1st and 2nd Floor Corridors - 1965 Bldg.	ASSUMED	MISC	N	LOC	10		No	ACBM with the potential for damage		LOW
52A	12" x 12" Gray w/ White Streaks VFT Mastic	1,600	SF	1st and 2nd Floor Corridors - 1965 Bldg	ASSUMED	MISC	N	LOC	10		No	ACBM with the potential for damage		LOW
53	12" x 12" Black w/ Gray Streaks VFT	200	SF	1st and 2nd Floor Main Corridors (Borders)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
53A	12" x 12" Black w/ Gray Streaks VFT Mastic	200	SF	1st and 2nd Floor Main Corridors (Borders)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	12" x 12" Light Gray w/ Gray Streaks VFT	11,500	SF	Rooms 222, 223 & Restroom, 225, 117, 118, 119, 120, 121, 123 & Restroom, 122 and 125 - 1965 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
54A	12" x 12" Light Gray w/ Gray Streaks VFT Mastic	11,500	SF	Rooms 222, 223 & Restroom, 225, 117, 118, 119, 120, 121,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Stockton School **Unit** 25501 **Building ID** 6060
Address 4420 N Beacon Street **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				123 & Restroom, 122 and 125 - 1965 Annex										
8M	Orange Linoleum Mastic - NOT OBSERVED	1,200	SF	Lunchroom - 1924 Bldg. - NOT OBSERVED	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Mag Block Pipe Insulation - Abated			Boiler & N. Fan Room - 1924 Bldg. - Abated	ABATED	TSI								
B	MJP E/F/V on Mag Block Pipe Insulation - Abated			Boiler & N. Fan Room - 1924 Bldg. - Abated	ABATED	TSI								
C	Boiler Insulation - Abated			Boiler Room - 1924 Bldg. - Abated	ABATED	TSI								
D	Aircell Pipe Insulation - Not Observed	1,090	LF	Throughout - 1924 Bldg. - Not Observed	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
F	MJP E/F/V on Fiberglass Pipe Insulation	8	FITTING	W. Unex., Boiler Room, Pump Room, N. Fan Room, 3rd Floor Boys Toilet - 1924 Bldg.	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
G	Cardboard Pipe Insulation--NOT OBSERVED	1,150	LF	Throughout - 1924 Bldg. -NOT OBSERVED	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
J	MJP E/F/V on Fiberglass Pipe Insulation--NOT OBSERVED	150	FITTING	Tunnel/Unexcavated Areas - 1965 Bldg.-- NOT OBSERVED	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
K	MJP E/F/V on Paperwrap Pipe Insulation--NOT OBSERVED	95	FITTING	Throughout - 1924 Bldg. NOT OBSERVED	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
L	MJP E/F/V on Aircell Pipe Insulation--NOT OBSERVED	100	FITTING	Throughout - 1924 Bldg. -NOT OBSERVED	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
M	Gray duct sealant	12	LF	Air tunnel	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		MODERATE
N	Carpet mastic	120	SF	Main office reception area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Stockton School Unit 25501 Building ID 6060
Address 4420 N Beacon Street Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

Reinspection Date <u>1/29/2025</u>
Inspector Name <u>Charles Brown</u>
<u>100-20221</u> <u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01	
02	
03	
04	
06	
07	
08	
09	
09B	
11	
13	
18	
19	
20	
21	
22	
22B	
23	
23B	
24	
25	
26	
27	
28	

Chicago Public Schools

School Stockton School **Unit** 25501 **Building ID** 6060
Address 4420 N Beacon Street **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
38A	
39	
40	
41	
42	
43	
44	
44A	
45	
45A	
46	
46A	
47	
48	
49	
49A	
50	
50A	
51	

Chicago Public Schools

School Stockton School **Unit** 25501 **Building ID** 6060
Address 4420 N Beacon Street **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
51A	
52	
52A	
53	
53A	
54	
54A	
8M	
A	
B	
C	
D	
F	
G	
J	
K	
L	
M	
N	

Table II
Management Planner's Review

Chicago Public Schools

School Stockton School

Unit 25501

Building ID 6060

Address 4420 N Beacon Street

Chicago, IL, 60640

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	Hard Coat Plaster	40,000	SF	Throughout - 1924 Bldg.	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02	2'x4' Ceiling Tile	1,200	SF	Room 311 and 211 - 1924 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03	2'x2' Ceiling Tile	1,200	SF	Lunchroom - 1924 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	Acoustic Sprayed Plaster	420	SF	AV Room/Teachers Lunchroom - 1924 Bldg.	Chrysotile	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	1'x1' Ceiling Tile	600	SF	Room 210 - 1924 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	12"x12" Brown VFT	7,750	SF	Corridors, Main Office & Vault, Room 103A - 1924 Bldg.	Chrysotile	MISC	No	19	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	Orange Linoleum - NOT OBSERVED	1,200	SF	Lunchroom - 1924 Bldg. NOT OBSERVED	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	Spray-on Fireproofing	20,000	SF	Throughout - 1965 Bldg.	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09B	Spray-on Fireproofing	50	SF	Boiler Room - 1924 Bldg.	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	Smooth Plaster	10,000	SF	Hallways, Toilets, Janitor's Closet & Store Rooms - 1965 Bldg.	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	12"x12" Brown VFT Mastic	7,750	SF	Corridors, Main Office & Vault - 1924 Bldg.	Chrysotile	MISC	No	19	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12"x12" White w/Beige Streaks VFT	1,200	SF	Rooms 108 (Abated), 111, 210, 307 Under the Carpet, Clinic - 1924 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12"x12" White w/Beige Streaks VFT Mastic	1,200	SF	Rooms 108 (Abated), 111, 210, 307 under carpet), Clinic - 1924 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	12"x12" Gray w/Dark Gray Streaks VFT	300	SF	Teachers Lounge Room Under Existing VFT- 1924 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	12"x12" Gray w/Dark Gray Streaks VFT Mastic	450	SF	Teachers Lounge Room Under Existing VFT	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12"x12" Orange w/Gray Streaks VFT	1,108	SF	Kitchen - 1924 Bldg. - NOT OBSERVED	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22B	9" x 9" Orange w/ Gray Streaks VFT	800	SF	Kitchen & Storage Entry - 1924 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12"x12" Orange w/Gray Streaks VFT Mastic	1,108	SF	Kitchen - 1924 Bldg. - NOT OBSERVED	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23B	9" x 9" Orange w/ Gray Streaks VFT Mastic	800	SF	Kitchen & Storage Entry - 1924 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12"x12" White w/Gray Streaks VFT	370	SF	1st Floor Men's & Women's Toilets, Gym Coach Office - 1924 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12"x12" White w/Gray Streaks VFT Mastic	370	SF	1st Floor Men's & Women's Toilets, Gym Coach Office - 1924 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	9"x9" Green VFT	20	SF	Closets across from Room 111 - 1924 Bldg. - NOT OBSERVED	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	9"x9" Green VFT Mastic	20	SF	Closets across from Room 111 - 1924 Bldg. - NOT OBSERVED	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Stockton School

Unit 25501

Building ID 6060

Address 4420 N Beacon Street

Chicago, IL, 60640

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
28	9"x9" Gray VFT	20	SF	Closets across from Room 111 - 1924 Bldg. - NOT OBSERVED	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	9"x9" Gray VFT Mastic	20	SF	Closets across from Room 111 - 1924 Bldg. - NOT OBSERVED	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12"x12" Blue VFT	500	SF	Room 124 and 224 - 1965 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12"x12" Blue VFT Mastic	12,000	SF	Room 124 and 224 - 1965 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	12"x12" Tan & Beige VFT	7,500	SF	1st Floor Men Bathroom, Corridors, 2nd Floor Women Bathroom, 1st & 2nd Floor JC's - 1965	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	12"x12" Tan & Beige VFT Mastic	7,500	SF	1st Floor Men Bathroom, Corridors, 2nd Floor Women Bathroom, 1st & 2nd Floor JC's - 1965 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	2"x4" Dot/Wave Ceiling Tile	12,000	SF	Throughout - 1965 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	12"x12" Gray VFT	100	SF	Gym Office - 1924 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12"x12" Gray VFT Mastic	100	SF	Gym Office - 1924 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12"X12" White w/Tan Specks VFT	600	SF	1st Floor Teachers Lounge - 1924 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	12"X12" Off-white w/Tan Specks VFT			Room 207 (Abated) - 1924 Bldg	Abated	MISC					
38A	12"X12" Off-white w/Tan Specks VFT Mastic			Room 207 (Abated) - 1924 Bldg	Abated	MISC					
39	Terrazzo	10,000	SF	All Corridors That Border All Floors, All Stairwells, All Floors - 1924 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	Decorative Plaster	1,000	SF	Auditorium - 1924 Bldg	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Stucco Plaster	2,000	LF	Auditorium - 1924 Bldg. (Upper Balony)	Assumed	SURFACE	No	60	LF	2 Damaged friable surfacing ACBM	Follow O&M Plan
42	Terrazzo	400	SF	Stairwell - 1965 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	Fire doors	10	EA	Auditorium, stage, projector room, balcony - 1924 Bldg.	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
44	12"x12" Gray w/ black specs VFT	1,100	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44A	12"x12" Gray w/ black specs VFT Mastic	1,100	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	12"x12" Tan w/ white and brown streaks VFT	150	SF	Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45A	12"x12" Tan w/ white and brown streaks VFT Mastic	150	SF	Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	12"x12" White with tan specs VFT	700	SF	Rooms 115, 113, 103 and 105 - 1924 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46A	12"x12" White with tan specs VFT Mastic	700	SF	Rooms 115, 113, 103 and 105 - 1924 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	Carpet Mastic	4,000	SF	Auditorium aisles, Rooms 211, 210, 204, 206 - 1924 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Stockton School

Unit 25501

Building ID 6060

Address 4420 N Beacon Street

Chicago, IL, 60640

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
48	2'x4' Ceiling Tiles with Grooves	400	SF	Room 211	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	12"X12" Light Gray w/ gray streaks VFT	4,500	SF	Room 307, magic room, 203, 207, 209 and 108 - 1924 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49A	12"x12" Light Gray and Gray Streaks VFT Mastic	4,500	SF	Room 307, magic room, 203, 207, 209 and 108 - 1924 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	12"x12" Blue VFT	190	SF	Rooms 203, 207, 209	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50A	12"x12" Blue VFT Mastic	190	SF	Rooms 203, 207, 209	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	Linoleum w/ tan, gray, and black specs	1,200	SF	Lunchroom- 1924 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51A	Linoleum w/ tan, gray, and black specs mastic	1,200	SF	Lunchroom -1924 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	12" x 12" Gray w/ White Streaks VFT	1,600	SF	1st and 2nd Floor Corridors - 1965 Bldg.	Assumed	MISC	No	10	SF	6 ACBM with the potential for damage	Follow O&M Plan
52A	12" x 12" Gray w/ White Streaks VFT Mastic	1,600	SF	1st and 2nd Floor Corridors - 1965 Bldg	Assumed	MISC	No	10	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	12" x 12" Black w/ Gray Streaks VFT	200	SF	1st and 2nd Floor Main Corridors (Borders)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53A	12" x 12" Black w/ Gray Streaks VFT Mastic	200	SF	1st and 2nd Floor Main Corridors (Borders)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	12" x 12" Light Gray w/ Gray Streaks VFT	11,500	SF	Rooms 222, 223 & Restroom, 225, 117, 118, 119, 120, 121, 123 & Restroom, 122 and 125 - 1965 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54A	12" x 12" Light Gray w/ Gray Streaks VFT Mastic	11,500	SF	Rooms 222, 223 & Restroom, 225, 117, 118, 119, 120, 121, 123 & Restroom, 122 and 125 - 1965 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8M	Orange Linoleum Mastic - NOT OBSERVED	1,200	SF	Lunchroom - 1924 Bldg. - NOT OBSERVED	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Mag Block Pipe Insulation - Abated			Boiler & N. Fan Room - 1924 Bldg. - Abated	Abated	TSI					
B	MJP E/F/V on Mag Block Pipe Insulation - Abated			Boiler & N. Fan Room - 1924 Bldg. - Abated	Abated	TSI					
C	Boiler Insulation - Abated			Boiler Room - 1924 Bldg. - Abated	Abated	TSI					
D	Aircell Pipe Insulation - Not Observed	1,090	LF	Throughout - 1924 Bldg. - Not Observed	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
F	MJP E/F/V on Fiberglass Pipe Insulation	8	FITTING	W. Unex., Boiler Room, Pump Room, N. Fan Room, 3rd Floor Boys Toliet - 1924 Bldg.	Assumed	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
G	Cardboard Pipe Insulation--NOT OBSERVED	1,150	LF	Throughout - 1924 Bldg. -NOT OBSERVED	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Stockton School

Unit 25501

Building ID 6060

Address 4420 N Beacon Street

Chicago, IL, 60640

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
J	MJP E/F/V on Fiberglass Pipe Insulation--NOT OBSERVED	150	FITTING	Tunnel/Unexcavated Areas - 1965 Bldg.--NOT OBSERVED	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
K	MJP E/F/V on Paperwrap Pipe Insulation--NOT OBSERVED	95	FITTING	Throughout - 1924 Bldg. NOT OBSERVED	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
L	MJP E/F/V on Aircell Pipe Insulation--NOT OBSERVED	100	FITTING	Throughout - 1924 Bldg. --NOT OBSERVED	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
M	Gray duct sealant	12	LF	Air tunnel	Assumed	MISC	No		LF	6 ACBM with the potential for damage	
N	Carpet mastic	120	SF	Main office reception area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Stockton School

Unit 25501

Building ID 6060

Address 4420 N Beacon Street

Chicago, IL, 60640

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

Review Date	3/3/2025
Manager Planner Name	Arturo Saenz
100-04019	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
03	
04	
06	
07	
08	
09	
09B	
11	
13	
18	
19	
20	
21	
22	
22B	
23	
23B	
24	
25	
26	
27	
28	
29	
30	

Chicago Public Schools

School Stockton School

Unit 25501

Building ID 6060

Address 4420 N Beacon Street

Chicago, IL, 60640

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
31	
32	
33	
34	
35	
36	
37	
38	
38A	
39	
40	
41	sample, repair damaged plaster if ACM
42	
43	
44	
44A	
45	
45A	
46	
46A	
47	
48	
49	
49A	
50	
50A	
51	

Chicago Public Schools

School Stockton School

Unit 25501

Building ID 6060

Address 4420 N Beacon Street

Chicago, IL, 60640

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
51A	
52	
52A	
53	
53A	
54	
54A	
8M	
A	
B	
C	
D	
F	
G	
J	
K	
L	
M	
N	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Specialty Consulting, Inc.

2025 AHERA REINSPECTION

Chicago Public Schools

Specialty Consulting, Inc.

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	01		
MATERIAL DESCRIPTION:	Hard Coat Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Throughout - 1924 Bldg.		
MATERIAL QUANTITY:	40000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **Hard Coat Plaster**

MATERIAL LOCATION: **Throughout - 1924 Bldg.**

MATERIAL QUANTITY: **40000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	02		
MATERIAL DESCRIPTION:	2'x4' Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 311 and 211 - 1924 Bldg.		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **02**

MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**

MATERIAL LOCATION: **Room 311 and 211 - 1924 Bldg.**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03		
MATERIAL DESCRIPTION:	2'x2' Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom - 1924 Bldg.		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **2'x2' Ceiling Tile**

MATERIAL LOCATION: **Lunchroom - 1924 Bldg.**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	04		
MATERIAL DESCRIPTION:	Acoustic Sprayed Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	AV Room/Teachers Lunchroom - 1924 Bldg.		
MATERIAL QUANTITY:	420	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **Acoustic Sprayed Plaster**

MATERIAL LOCATION: **AV Room/Teachers Lunchroom - 1924 Bldg.**

MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06		
MATERIAL DESCRIPTION:	1'x1' Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 210 - 1924 Bldg.		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **1'x1' Ceiling Tile**

MATERIAL LOCATION: **Room 210 - 1924 Bldg.**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07		
MATERIAL DESCRIPTION:	12"x12" Brown VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Deterioration		
HISTORICAL RESPONSE ACTION:	Remove		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:	Deterioration		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Corridors, Main Office & Vault, Room 103A - 1924 Bldg.		
MATERIAL QUANTITY:	7750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **07**

MATERIAL DESCRIPTION: **12"x12" Brown VFT**

MATERIAL LOCATION: **Corridors, Main Office & Vault, Room 103A - 1924 Bldg.**

MATERIAL QUANTITY: **7750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **19** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08		
MATERIAL DESCRIPTION:	Orange Linoleum - NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Lunchroom - 1924 Bldg. NOT OBSERVED		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **Orange Linoleum - NOT OBSERVED**

MATERIAL LOCATION: **Lunchroom - 1924 Bldg. NOT OBSERVED**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09		
MATERIAL DESCRIPTION:	Spray-on Fireproofing		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout - 1965 Bldg.		
MATERIAL QUANTITY:	20000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **Spray-on Fireproofing**

MATERIAL LOCATION: **Throughout - 1965 Bldg.**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09B		
MATERIAL DESCRIPTION:	Spray-on Fireproofing		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room - 1924 Bldg.		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **09B**

MATERIAL DESCRIPTION: **Spray-on Fireproofing**

MATERIAL LOCATION: **Boiler Room - 1924 Bldg.**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	Smooth Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Hallways, Toilets, Janitor's Closet & Store Rooms - 1965 Bldg.		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Smooth Plaster**

MATERIAL LOCATION: **Hallways, Toilets, Janitor's Closet & Store Rooms - 1965 Bldg.**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	12"x12" Brown VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Deterioration		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Corridors, Main Office & Vault - 1924 Bldg.		
MATERIAL QUANTITY:	7750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **12"x12" Brown VFT Mastic**

MATERIAL LOCATION: **Corridors, Main Office & Vault - 1924 Bldg.**

MATERIAL QUANTITY: **7750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **19** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18		
MATERIAL DESCRIPTION:	12"x12" White w/Beige Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Rooms 108 (Abated), 111, 210, 307 Under the Carpet, Clinic - 1924 Bldg.		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12"x12" White w/Beige Streaks VFT**

MATERIAL LOCATION: **Rooms 108 (Abated), 111, 210, 307 Under the Carpet, Clinic - 1924 Bldg.**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	12"x12" White w/Beige Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 108 (Abated), 111, 210, 307 under carpet), Clinic - 1924 Bldg.		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **12"x12" White w/Beige Streaks VFT Mastic**

MATERIAL LOCATION: **Rooms 108 (Abated), 111, 210, 307 under carpet), Clinic - 1924 Bldg.**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	12"x12" Gray w/Dark Gray Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Teachers Lounge Room Under Existing VFT- 1924 Bldg.		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **12"x12" Gray w/Dark Gray Streaks VFT**

MATERIAL LOCATION: **Teachers Lounge Room Under Existing VFT- 1924 Bldg.**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	12"x12" Gray w/Dark Gray Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Teachers Lounge Room Under Existing VFT		
MATERIAL QUANTITY:	450	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **12"x12" Gray w/Dark Gray Streaks VFT Mastic**

MATERIAL LOCATION: **Teachers Lounge Room Under Existing VFT**

MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	12"x12" Orange w/Gray Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Kitchen - 1924 Bldg.- NOT OBSERVED		
MATERIAL QUANTITY:	1108	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **12"x12" Orange w/Gray Streaks VFT**

MATERIAL LOCATION: **Kitchen - 1924 Bldg.- NOT OBSERVED**

MATERIAL QUANTITY: **1108** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22B		
MATERIAL DESCRIPTION:	9" x 9" Orange w/ Gray Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Kitchen & Storage Entry - 1924 Bldg.		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **22B**

MATERIAL DESCRIPTION: **9" x 9" Orange w/ Gray Streaks VFT**

MATERIAL LOCATION: **Kitchen & Storage Entry - 1924 Bldg.**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	12"x12" Orange w/Gray Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen - 1924 Bldg.- NOT OBSERVED		
MATERIAL QUANTITY:	1108	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **12"x12" Orange w/Gray Streaks VFT Mastic**

MATERIAL LOCATION: **Kitchen - 1924 Bldg.- NOT OBSERVED**

MATERIAL QUANTITY: **1108** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23B		
MATERIAL DESCRIPTION:	9" x 9" Orange w/ Gray Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen & Storage Entry - 1924 Bldg.		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **23B**

MATERIAL DESCRIPTION: **9" x 9" Orange w/ Gray Streaks VFT Mastic**

MATERIAL LOCATION: **Kitchen & Storage Entry - 1924 Bldg.**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	12"x12" White w/Gray Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1st Floor Men's & Women's Toilets, Gym Coach Office - 1924 Bldg.		
MATERIAL QUANTITY:	370	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **12"x12" White w/Gray Streaks VFT**

MATERIAL LOCATION: **1st Floor Men's & Women's Toilets, Gym Coach Office - 1924 Bldg.**

MATERIAL QUANTITY: **370** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	12"x12" White w/Gray Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Men's & Women's Toilets, Gym Coach Office - 1924 Bldg.		
MATERIAL QUANTITY:	370	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **12"x12" White w/Gray Streaks VFT Mastic**

MATERIAL LOCATION: **1st Floor Men's & Women's Toilets, Gym Coach Office - 1924 Bldg.**

MATERIAL QUANTITY: **370** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	9"x9" Green VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Closets across from Room 111 - 1924 Bldg.- NOT OBSERVED		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **9"x9" Green VFT**

MATERIAL LOCATION: **Closets across from Room 111 - 1924 Bldg.- NOT OBSERVED**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	9"x9" Green VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Closets across from Room 111 - 1924 Bldg.- NOT OBSERVED		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **9"x9" Green VFT Mastic**

MATERIAL LOCATION: **Closets across from Room 111 - 1924 Bldg.- NOT OBSERVED**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	9"x9" Gray VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Closets across from Room 111 - 1924 Bldg. - NOT OBSERVED		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **9"x9" Gray VFT**

MATERIAL LOCATION: **Closets across from Room 111 - 1924 Bldg. - NOT OBSERVED**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	9"x9" Gray VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Closets across from Room 111 - 1924 Bldg. - NOT OBSERVED		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **9"x9" Gray VFT Mastic**

MATERIAL LOCATION: **Closets across from Room 111 - 1924 Bldg. - NOT OBSERVED**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	12"x12" Blue VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 124 and 224 - 1965 Bldg.		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **12"x12" Blue VFT**

MATERIAL LOCATION: **Room 124 and 224 - 1965 Bldg.**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31		
MATERIAL DESCRIPTION:	12"x12" Blue VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 124 and 224 - 1965 Bldg.		
MATERIAL QUANTITY:	12000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12"x12" Blue VFT Mastic**

MATERIAL LOCATION: **Room 124 and 224 - 1965 Bldg.**

MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32		
MATERIAL DESCRIPTION:	12"x12" Tan & Beige VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **1st Floor Men Bathroom, Corridors, 2nd Floor Women Bathroom, 1st & 2nd Floor JC's - 1965**

MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **12"x12" Tan & Beige VFT**

MATERIAL LOCATION: **1st Floor Men Bathroom, Corridors, 2nd Floor Women Bathroom, 1st & 2nd Floor JC's - 1965**

MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	12"x12" Tan & Beige VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Men Bathroom, Corridors, 2nd Floor Women Bathroom, 1st & 2nd Floor JC's - 1965 Bldg.		
MATERIAL QUANTITY:	7500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **12"x12" Tan & Beige VFT Mastic**

MATERIAL LOCATION: **1st Floor Men Bathroom, Corridors, 2nd Floor Women Bathroom, 1st & 2nd Floor JC's - 1965 Bldg.**

MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	2'x4' Dot/Wave Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout - 1965 Bldg.		
MATERIAL QUANTITY:	12000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **2'x4' Dot/Wave Ceiling Tile**

MATERIAL LOCATION: **Throughout - 1965 Bldg.**

MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	12"x12" Gray VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Gym Office - 1924 Bldg.		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **12"x12" Gray VFT**

MATERIAL LOCATION: **Gym Office - 1924 Bldg.**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	12"x12" Gray VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym Office - 1924 Bldg.		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **12"x12" Gray VFT Mastic**

MATERIAL LOCATION: **Gym Office - 1924 Bldg.**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	12"X12" White w/Tan Specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1st Floor Teachers Lounge - 1924 Bldg		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **12"X12" White w/Tan Specks VFT**

MATERIAL LOCATION: **1st Floor Teachers Lounge - 1924 Bldg**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	12"X12" Off-white w/Tan Specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 207 (Abated) - 1924 Bldg

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **12"X12" Off-white w/Tan Specks VFT**

MATERIAL LOCATION: **Room 207 (Abated) - 1924 Bldg**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38A		
MATERIAL DESCRIPTION:	12"X12" Off-white w/Tan Specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 207 (Abated) - 1924 Bldg

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **38A**

MATERIAL DESCRIPTION: **12"X12" Off-white w/Tan Specks VFT Mastic**

MATERIAL LOCATION: **Room 207 (Abated) - 1924 Bldg**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39		
MATERIAL DESCRIPTION:	Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	All Corridors That Border All Floors, All Stairwells, All Floors - 1924 Bldg		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **All Corridors That Border All Floors, All Stairwells, All Floors - 1924 Bldg**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	Decorative Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Auditorium - 1924 Bldg		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Decorative Plaster**

MATERIAL LOCATION: **Auditorium - 1924 Bldg**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41		
MATERIAL DESCRIPTION:	Stucco Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	2 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **2. Damaged friable surfacing ACBM**

DAMAGE REASON:	Water		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Auditorium - 1924 Bldg. (Upper Balony)		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Stucco Plaster**

MATERIAL LOCATION: **Auditorium - 1924 Bldg. (Upper Balony)**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **60** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

sample, repair damaged plaster if ACM

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42		
MATERIAL DESCRIPTION:	Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Stairwell - 1965 Bldg		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **Stairwell - 1965 Bldg**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	Fire doors		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium, stage, projector room, balcony - 1924 Bldg.		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	EA
DAMAGE QUANTITY:		DAMAGE UNITS:	EA
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Fire doors**

MATERIAL LOCATION: **Auditorium, stage, projector room, balcony - 1924 Bldg.**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	12"x12" Gray w/ black specs VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Kitchen		
MATERIAL QUANTITY:	1100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **12"x12" Gray w/ black specs VFT**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44A		
MATERIAL DESCRIPTION:	12"x12" Gray w/ black specs VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen		
MATERIAL QUANTITY:	1100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **44A**

MATERIAL DESCRIPTION: **12"x12" Gray w/ black specs VFT Mastic**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	12"x12" Tan w/ white and brown streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Engineer's Office		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **12"x12" Tan w/ white and brown streaks VFT**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45A		
MATERIAL DESCRIPTION:	12"x12" Tan w/ white and brown streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **45A**

MATERIAL DESCRIPTION: **12"x12" Tan w/ white and brown streaks VFT Mastic**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	12"x12" White with tan specs VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Rooms 115, 113, 103 and 105 - 1924 Bldg.		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **12"x12" White with tan specs VFT**

MATERIAL LOCATION: **Rooms 115, 113, 103 and 105 - 1924 Bldg.**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46A		
MATERIAL DESCRIPTION:	12"x12" White with tan specs VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 115, 113, 103 and 105 - 1924 Bldg.		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **46A**

MATERIAL DESCRIPTION: **12"x12" White with tan specs VFT Mastic**

MATERIAL LOCATION: **Rooms 115, 113, 103 and 105 - 1924 Bldg.**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47		
MATERIAL DESCRIPTION:	Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium aisles, Rooms 211, 210, 204, 206 - 1924 Bldg.		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Auditorium aisles, Rooms 211, 210, 204, 206 - 1924 Bldg.**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	2'x4' Ceiling Tiles with Grooves		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 211		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **2'x4' Ceiling Tiles with Grooves**

MATERIAL LOCATION: **Room 211**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	12"X12" Light Gray w/ gray streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 307, magic room, 203, 207, 209 and 108 - 1924 Bldg.		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **12"X12" Light Gray w/ gray streaks VFT**

MATERIAL LOCATION: **Room 307, magic room, 203, 207, 209 and 108 - 1924 Bldg.**

MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49A		
MATERIAL DESCRIPTION:	12"x12" Light Gray and Gray Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 307, magic room, 203, 207, 209 and 108 - 1924 Bldg.		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **49A**

MATERIAL DESCRIPTION: **12"x12" Light Gray and Gray Streaks VFT Mastic**

MATERIAL LOCATION: **Room 307, magic room, 203, 207, 209 and 108 - 1924 Bldg.**

MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	12"x12" Blue VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Rooms 203, 207, 209		
MATERIAL QUANTITY:	190	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **12"x12" Blue VFT**

MATERIAL LOCATION: **Rooms 203, 207, 209**

MATERIAL QUANTITY: **190** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50A		
MATERIAL DESCRIPTION:	12"x12" Blue VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 203, 207, 209		
MATERIAL QUANTITY:	190	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **50A**

MATERIAL DESCRIPTION: **12"x12" Blue VFT Mastic**

MATERIAL LOCATION: **Rooms 203, 207, 209**

MATERIAL QUANTITY: **190** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	Linoleum w/ tan, gray, and black specs		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Lunchroom- 1924 Bldg.		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Linoleum w/ tan, gray, and black specs**

MATERIAL LOCATION: **Lunchroom- 1924 Bldg.**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51A		
MATERIAL DESCRIPTION:	Linoleum w/ tan, gray, and black specs mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom -1924 Bldg.		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **51A**

MATERIAL DESCRIPTION: **Linoleum w/ tan, gray, and black specs mastic**

MATERIAL LOCATION: **Lunchroom -1924 Bldg.**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	12" x 12" Gray w/ White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Remove		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st and 2nd Floor Corridors - 1965 Bldg.		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ White Streaks VFT**

MATERIAL LOCATION: **1st and 2nd Floor Corridors - 1965 Bldg.**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52A		
MATERIAL DESCRIPTION:	12" x 12" Gray w/ White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Remove		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st and 2nd Floor Corridors - 1965 Bldg		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **52A**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ White Streaks VFT Mastic**

MATERIAL LOCATION: **1st and 2nd Floor Corridors - 1965 Bldg**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	12" x 12" Black w/ Gray Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1st and 2nd Floor Main Corridors (Borders)		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **12" x 12" Black w/ Gray Streaks VFT**

MATERIAL LOCATION: **1st and 2nd Floor Main Corridors (Borders)**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53A		
MATERIAL DESCRIPTION:	12" x 12" Black w/ Gray Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st and 2nd Floor Main Corridors (Borders)		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **53A**

MATERIAL DESCRIPTION: **12" x 12" Black w/ Gray Streaks VFT Mastic**

MATERIAL LOCATION: **1st and 2nd Floor Main Corridors (Borders)**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	12" x 12" Light Gray w/ Gray Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 222, 223 & Restroom, 225, 117, 118, 119, 120, 121, 123 & Restroom, 122 and 125 - 1965 Annex**

MATERIAL QUANTITY: **11500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Gray Streaks VFT**

MATERIAL LOCATION: **Rooms 222, 223 & Restroom, 225, 117, 118, 119, 120, 121, 123 & Restroom, 122 and 125 - 1965 Annex**

MATERIAL QUANTITY: **11500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54A		
MATERIAL DESCRIPTION:	12" x 12" Light Gray w/ Gray Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 222, 223 & Restroom, 225, 117, 118, 119, 120, 121, 123 & Restroom, 122 and 125 - 1965 Annex**

MATERIAL QUANTITY: **11500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **54A**

MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Gray Streaks VFT Mastic**

MATERIAL LOCATION: **Rooms 222, 223 & Restroom, 225, 117, 118, 119, 120, 121, 123 & Restroom, 122 and 125 - 1965 Annex**

MATERIAL QUANTITY: **11500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8M		
MATERIAL DESCRIPTION:	Orange Linoleum Mastic - NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom - 1924 Bldg. - NOT OBSERVED		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **8M**

MATERIAL DESCRIPTION: **Orange Linoleum Mastic - NOT OBSERVED**

MATERIAL LOCATION: **Lunchroom - 1924 Bldg. - NOT OBSERVED**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A		
MATERIAL DESCRIPTION:	Mag Block Pipe Insulation - Abated		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler & N. Fan Room - 1924 Bldg.
- Abated

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Mag Block Pipe Insulation - Abated**

MATERIAL LOCATION: **Boiler & N. Fan Room - 1924 Bldg.
- Abated**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	B		
MATERIAL DESCRIPTION:	MJP E/F/V on Mag Block Pipe Insulation - Abated		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler & N. Fan Room - 1924 Bldg. - Abated

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation - Abated**

MATERIAL LOCATION: **Boiler & N. Fan Room - 1924 Bldg. - Abated**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	Boiler Insulation - Abated		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room - 1924 Bldg. - Abated

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Boiler Insulation - Abated**

MATERIAL LOCATION: **Boiler Room - 1924 Bldg. - Abated**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation - Not Observed		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout - 1924 Bldg. - Not Observed		
MATERIAL QUANTITY:	1090	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation - Not Observed**

MATERIAL LOCATION: **Throughout - 1924 Bldg. - Not Observed**

MATERIAL QUANTITY: **1090** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F		
MATERIAL DESCRIPTION:	MJP E/F/V on Fiberglass Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	W. Unex., Boiler Room, Pump Room, N. Fan Room, 3rd Floor Boys Toliet - 1924 Bldg.		
MATERIAL QUANTITY:	8	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:		DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **W. Unex., Boiler Room, Pump Room, N. Fan Room, 3rd Floor Boys Toliet - 1924 Bldg.**

MATERIAL QUANTITY: **8** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation--NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout - 1924 Bldg. -NOT OBSERVED		
MATERIAL QUANTITY:	1150	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation--NOT OBSERVED**

MATERIAL LOCATION: **Throughout - 1924 Bldg. -NOT OBSERVED**

MATERIAL QUANTITY: **1150** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	J		
MATERIAL DESCRIPTION:	MJP E/F/V on Fiberglass Pipe Insulation--NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Tunnel/Unexcavated Areas - 1965 Bldg.--NOT OBSERVED		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **01/29/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation--NOT OBSERVED**

MATERIAL LOCATION: **Tunnel/Unexcavated Areas - 1965 Bldg.--NOT OBSERVED**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	K		
MATERIAL DESCRIPTION:	MJP E/F/V on Paperwrap Pipe Insulation--NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout - 1924 Bldg. NOT OBSERVED		
MATERIAL QUANTITY:	95	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:		DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **MJP E/F/V on Paperwrap Pipe Insulation--NOT OBSERVED**

MATERIAL LOCATION: **Throughout - 1924 Bldg. NOT OBSERVED**

MATERIAL QUANTITY: **95** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	L		
MATERIAL DESCRIPTION:	MJP E/F/V on Aircell Pipe Insulation--NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout - 1924 Bldg. --NOT OBSERVED		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:		DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation--NOT OBSERVED**

MATERIAL LOCATION: **Throughout - 1924 Bldg. --NOT OBSERVED**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	M		
MATERIAL DESCRIPTION:	Gray duct sealant		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Air tunnel		
MATERIAL QUANTITY:	12	MATERIAL UNITS:	LF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Gray duct sealant**

MATERIAL LOCATION: **Air tunnel**

MATERIAL QUANTITY: **12** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUIDLING ID:	6060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Charles Brown		
SCHOOL NAME:	Stockton School	INSPECTION DATE:	1/29/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	N		
MATERIAL DESCRIPTION:	Carpet mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main office reception area		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/29/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25501	BUILDING ID:	6060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Stockton School	REVIEW DATE:	3/3/2025		
ADDRESS:	4420 N Beacon Street	IDPH LICENSE NO:	100-20221		

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Carpet mastic**

MATERIAL LOCATION: **Main office reception area**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

Chicago Public Schools

Specialty Consulting, Inc.

2025 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Ill.

CHARLES F BROWN
2942 W. Van Buren St.
CHICAGO, IL 60612

4/30/20

**ASBESTOS
PROFESSIONAL
LICENSE**

ISSUED **4/30/2025** EXPIRES **05/15/2026**

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 20221

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 20221	ISSUED 4/30/2025	EXPIRES 05/15/2026	
CHARLES F BROWN 2942 W. Van Buren St. CHICAGO, IL 60612 Environmental Health	 <div style="display: flex; justify-content: space-between;"> <div> PROJECT MANAGER AIR SAMPLING PROFESSIONAL </div> <div>1/11/2026</div> </div> <p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>		

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

CHARLES F BROWN
8020 S. EBERHART
CHICAGO, IL 60619

6/12/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 20221

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

Front of License		Back of License	
	ASBESTOS PROFESSIONAL LICENSE	ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 20221	ISSUED 6/12/2024	EXPIRES 05/15/2025	PROJECT MANAGER AIR SAMPLING PROFESSIONAL
CHARLES F BROWN 8020 S. EBERHART CHICAGO, IL 60619 Environmental Health			Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that CHARLES F. BROWN
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 01/04/2025 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

01/04/2025

Course Dates:

01/04/2026

Expires:

2501BIR03

Certificate Number:

N. Peneff, PhD

Phone: 312-491-0081

Director of Training

Nicholas J. Peneff

Doctor of Public Health

FORM # A-010B



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that
Arturo Saenz

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012562

Kathy DeSalvo
Kathy DeSalvo, Director



Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that
Arturo Saenz

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012583

Kathy DeSalvo
Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

ARTURO SAENZ
2942 W VAN BUREN ST
CHICAGO, IL 60612

7/8/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 04019	ISSUED 7/8/2024	EXPIRES 05/15/2025	INSPECTOR	5/6/2025
ARTURO SAENZ 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			MANAGEMENT PLANNER	5/6/2025
			AIR SAMPLING PROFESSIONAL Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



OCCUPATIONAL TRAINING & SUPPLY, INC.
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2024

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Arturo Saenz

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 5/6/2024

Exam Date: 5/6/2024

Expiration Date: 5/6/2025

Certificate Number: MPR2405061823


Course Credit Hours: MPR 8 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

Kristina Miczek, Training Manager



525-535 West Jefferson Street • Springfield, Illinois



ARTURO SAENZ
2942 W VAN BUREN ST
CHICAGO, IL 60612


2/28/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	11/1/2022
MANAGEMENT PLANNER	11/1/2022
AIR SAMPLING PROFESSIONAL	
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB



525-535 West Jefferson Street • Springfield, Ill

ARTURO SAENZ
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/30/2026



ASBESTOS
PROFESSIONAL
LICENSE

ID NUMBER
100 - 04019

ISSUED
4/30/2025

EXPIRES
05/15/2026

ARTURO SAENZ
2942 W VAN BUREN ST
CHICAGO, IL 60612

Environmental Health




ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	5/6/2025
MANAGEMENT PLANNER	4/2/2026
AIR SAMPLING PROFESSIONAL	
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB

**Reliable
Environmental
Solutions, Inc. R E S**

This is to certify that **Arturo Saenz**

*has on 4/2/25, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Refresher Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: April 2, 2025

COURSE LENGTH: 4 HOURS

Examination Date: April 2, 2025

Expiration Date: April 2, 2026

Certificate Number: MPR/0560



Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois 217.787.9800 www.ReliableEnv.com

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed