

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2147  
SCHOOL NAME: Crown Academy  
ADDRESS OF SCHOOL: 2128 S. St. Louis  
CITY: Chicago, IL, 60623

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 10/6/2022

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 3/24/2025 ENROLLMENT 103  
IDPH INSPECTOR LICENSE NUMBER: 100-09969  
IDPH LICENSED INSPECTOR NAME (Please Print): Dionne Carey Walker  
IDPH MP LICENSE NUMBER: 100-18488  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Mike Serio

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

*Richard J. Schleyer* 4/18/2025

*Signature of Designated Person*

*Date*

**SECTION III**

**PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.**

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Crown Academy**

2128 S. St. Louis  
Chicago, IL, 60623

Unit: 31041  
Building ID: 2940

IDPH ID Number: 14-016-2990-2147

**REPORT DATE:**  
Friday, April 18, 2025

**Prepared for:**  
**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**  
**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

04/18/2025

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299      Unit: 31041      Region: 03      IDPH ID: 14-016-2990-2147

School: Crown Academy      Building ID: 2940

Address: 2128 S. St. Louis

Chicago, IL, 60623

Building Contact: Zackavec, Christopher      Contact Phone: 3123308517

Current Building Owners: Chicago Public Schools

Reinspection Date: 3/24/2025

Review Date: 04/18/2025

Inspector: Dionne Carey Walker

Inspector IDPH License: 100-09969

Management Planner: Mike Serio

Management Planner IDPH License: 100-18488

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates



Mike Serio  
100-18488

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: April 18, 2025

RE: Crown Academy, Unit 31041  
2128 S. St. Louis  
Chicago, IL, 60623

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Crown Academy, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Crown Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J. Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074.

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

## 1. School Information

School: Crown Academy Unit: 31041 Region: 03  
Address: 2128 S. St. Louis Chicago, IL, 60623  
IDPH ID: 14-016-2990-2147 Building ID: 2940  
Contact: Zackavec, Christopher Phone: 3123308517

## 2. Description of Facility

Original Construction: 1961 Additional Construction:  
Total Square Footage: 63352 No of Floors: 3  
Current Occupancy: 103

### 3. LEA Designated Person

#### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Doug McCormick  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900 Fax: (312) 782-5145

## 5. Inspector

Inspector Name: Dionne Carey Walker

Inspector IDPH license # 100-09969  
Reinspection Date: 3/24/2025

Signature:   
Date: 3/24/2025

## 6. Management Planner

Management Planner Name: Mike Serio

Management Planner IDPH license # 100-18488

Signature: 

7. Review Date: 04/18/2025

## 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: Richard J. Schleyer

Date: 4/18/2025

Name: Richard J. Schleyer

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Crown Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2940:

1	9" x 9" Gray Floor Tile
10	12" x 12" Brown Floor Tile Mastic
15	12" x 12" White w/ Gray Specks Floor Tile Mastic
17	12" x 12" White Floor Tile
18	12" x 12" White Floor Tile Mastic
19	12" x 12" Black Floor Tile
2	9" x 9" Brown Floor Tile
21	Gray Vinyl Tread Cover
22	Gray Vinyl Tread Cover Adhesive

23	12" x 12" Yellow Floor Tile
24	12" x 12" Yellow Floor Tile Mastic
25	12" x 12" Gray Floor Tile
26	12" x 12" Gray Floor Tile Mastic
27	9" x 9" Black Floor Tile
28	9" x 9" Black Floor Tile Mastic
29	9" x 9" Dark Gray Floor Tile
3	12" x 12" Brown Floor Tile
30	9" x 9" Dark Gray Floor Tile Mastic
34	12" x 12" Dark Blue Floor Tile
35	12" x 12" Light Blue Floor Tile
36	12" x 12" Dark/Light Blue Floor Tile Mastic
37	2' x 2' Ceiling Tile
5	1' x 1' Fissured Ceiling Tile
7	2' x 2' Transite Ceiling Panels
8	9" x 9" Gray Floor Tile Mastic
9	9" x 9" Brown Floor Tile Mastic
B	Cardboard Pipe Wrap
D	Transite Flue Pipe
E	Breaching Insulation
M	9" x 9" Beige w/ White Streaks Vinyl Floor Tile
O	Vibration Gasket
Q	Brown Baseboard
R	Brown Baseboard Mastic

T 1' x 1' Dotted Ceiling Tile Mastic

U Terrazzo Light Tan Floor

V Sink Insulation

B. The following new homogenous areas have been identified for Building 2940:

37                    2' x 2' Ceiling Tile

38                    Lab Table

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

14	12" x 12" White w/ Gray Specks Floor Tile
15	12" x 12" White w/ Gray Specks Floor Tile Mastic
16	Liner in Vault Door
17	12" x 12" White Floor Tile
18	12" x 12" White Floor Tile Mastic
19	12" x 12" Black Floor Tile
20	12" x 12" Black Floor Tile Mastic
21	Gray Vinyl Tread Cover
22	Gray Vinyl Tread Cover Adhesive
23	12" x 12" Yellow Floor Tile
24	12" x 12" Yellow Floor Tile Mastic
25	12" x 12" Gray Floor Tile
26	12" x 12" Gray Floor Tile Mastic
27	9" x 9" Black Floor Tile
28	9" x 9" Black Floor Tile Mastic
29	9" x 9" Dark Gray Floor Tile
30	9" x 9" Dark Gray Floor Tile Mastic
31	12" x 12" Yellow Floor Tile
32	12" x 12" White w/ Blue Specks Floor Tile
33	12" x 12" Yellow & White w/ Blue Specks Floor Tile Mastic
34	12" x 12" Dark Blue Floor Tile
35	12" x 12" Light Blue Floor Tile
36	12" x 12" Dark/Light Blue Floor Tile Mastic
37	2' x 2' Ceiling Tile
38	Lab Table
I	12" x 12" Green w/ Dark Green Streaks Vinyl Floor Tile
J	12" x 12" Green w/ Dark Green Streaks Vinyl Floor Tile Mastic
K	12" x 12" Blue w/ Dark Blue Streaks Vinyl Floor Tile
M	9" x 9" Beige w/ White Streaks Vinyl Floor Tile
N	9" x 9" Beige w/ White Streaks Vinyl Floor Tile Mastic
O	Vibration Gasket
P	Curtain Wall Panels
Q	Brown Baseboard
R	Brown Baseboard Mastic
S	Drywall
T	1' x 1' Dotted Ceiling Tile Mastic
U	Terrazzo Light Tan Floor

V	Sink Insulation
W	Brown Carpet Mastic

The following areas were deemed to be inaccessible:

15	12" x 12" White w/ Gray Specks Floor Tile Mastic
18	12" x 12" White Floor Tile Mastic
22	Gray Vinyl Tread Cover Adhesive
24	12" x 12" Yellow Floor Tile Mastic
26	12" x 12" Gray Floor Tile Mastic
37	2' x 2' Ceiling Tile
8	9" x 9" Gray Floor Tile Mastic
9	9" x 9" Brown Floor Tile Mastic
J	12" x 12" Green w/ Dark Green Streaks Vinyl Floor Tile Mastic
L	12" x 12" Blue w/ Dark Blue Streaks Vinyl Floor Tile Mastic
M	9" x 9" Beige w/ White Streaks Vinyl Floor Tile
N	9" x 9" Beige w/ White Streaks Vinyl Floor Tile Mastic
R	Brown Baseboard Mastic
T	1' x 1' Dotted Ceiling Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Dionne Carey Walker, IDPH License # 100-09969. The Management Plan was updated by Mike Serio, IDPH License # 100-18488. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Crown Academy Building 2940 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

**School** Crown Academy **Unit** 31041 **Building ID** 2940  
**Address** 2128 S. St. Louis **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
005	9" x 9" Dark Brown Floor Tile	175	SF	1960 Building, Rooms 215, 220, 210 and Lunchroom Areas, Food Storage., 300, 301, 302, 303, 304, 305, 306, 307, 310, 208, 207, 206, 205, 204, 203, 202, 201, 200	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
1	9" x 9" Gray Floor Tile	25,000	SF	Kitchen, Room 109, 2nd and 3rd Floor Halls and Womens Lounge	CHR	MISC	N	DIST	50	SF	Yes	ACBM with potential for significant damage	5	LOW
10	12" x 12" Brown Floor Tile Mastic			ABATED	ABATED	MISC					Yes			
11	Window Caulk			Throughout	NO_ACBM	MISC					No			
12	Door Caulk			Throughout	NO_ACBM	MISC					No			
13	Hard Plaster Ceiling			Gym	NO_ACBM	SURFACE					No			
14	12" x 12" White w/ Gray Specks Floor Tile	8,000	SF	1st Floor Hall, Stair Landings, Room 111	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
15	12" x 12" White w/ Gray Specks Floor Tile Mastic	8,000	SF	1st Floor Hall, Stair Landings, Room 111	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
16	Liner in Vault Door			Office	ASSUMED	MISC								
17	12" x 12" White Floor Tile	1,200	SF	Northwest Stairwell 2nd Floor, Womens Bathroom 3rd Floor	ASSUMED	MISC	N	LOC	5	SF	Yes	ACBM with the potential for damage	5	LOW
18	12" x 12" White Floor Tile Mastic	1,200	SF	Northwest Stairwell 2nd Womens Bathroom 3rd Floor	ASSUMED	MISC	N	LOC	200	SF	Yes	ACBM with the potential for damage	5	LOW
19	12" x 12" Black Floor Tile	300	SF	All Classrooms Around Univents	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
2	9" x 9" Brown Floor Tile	21,000	SF	Classrooms	CHR	MISC	N	DIST	120	SF	Yes	ACBM with the potential for damage	5	LOW
20	12" x 12" Black Floor Tile Mastic			All Classrooms Around Univents	ASSUMED	MISC								
21	Gray Vinyl Tread Cover	350	SF	Stairwells	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
22	Gray Vinyl Tread Cover Adhesive	350	SF	Stairwells	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
23	12" x 12" Yellow Floor Tile	150	SF	All Vestibules, 109, 113	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
24	12" x 12" Yellow Floor Tile Mastic	150	SF	All Vestibules, 109, 113	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
25	12" x 12" Gray Floor Tile	1,350	SF	Main Office, Principal's Office	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Crown Academy **Unit** 31041 **Building ID** 2940  
**Address** 2128 S. St. Louis **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
26	12" x 12" Gray Floor Tile Mastic	1,350	SF	Main Office, Principal's Office	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
27	9" x 9" Black Floor Tile	20	SF	Room 305	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
28	9" x 9" Black Floor Tile Mastic	20	SF	Room 305	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
29	9" x 9" Dark Gray Floor Tile	20	SF	2nd Floor Corridor	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
3	12" x 12" Brown Floor Tile			ABATED	ABATED	MISC					Yes			
30	9" x 9" Dark Gray Floor Tile Mastic	20	SF	2nd Floor Corridor	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
31	12" x 12" Yellow Floor Tile			Room 109	ASSUMED	MISC								
32	12" x 12" White w/ Blue Specks Floor Tile			Room 109	ASSUMED	MISC								
33	12" x 12" Yellow & White w/ Blue Specks Floor Tile Mastic			Room 109	ASSUMED	MISC								
34	12" x 12" Dark Blue Floor Tile	300	SF	Room 111, assembly	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
35	12" x 12" Light Blue Floor Tile	300	SF	Room 111	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
36	12" x 12" Dark/Light Blue Floor Tile Mastic	600	SF	Room 111	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
37	2' x 2' Ceiling Tile	800	SF	Rooms 111, 113	ASSUMED	MISC	Y	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		MODERATE
38	Lab Table	16	SF	Room 203	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
4	1' x 1' Dotted Ceiling Tiles			Room 300, 200, and Outside Room 307, Nurses Office, Main Office	NO_ACBM	MISC					No			
5	1' x 1' Fissured Ceiling Tile			First Floor Hall, Nurses Office	NO_ACBM	MISC					Yes			
6	Hard Plaster			Kitchen, 3rd Floor Womens Bathroom, Room 200	NO_ACBM	SURFACE					No			
7	2' x 2' Transite Ceiling Panels	600	SF	Hall Outside Gym	CHR	MISC	N	LOC	1	SF	Yes	ACBM with the potential for damage	5	LOW
8	9" x 9" Gray Floor Tile Mastic	21,300	SF	Halls, Kitchen, Rooms 109, 119, and Auditorium, 2nd and 3rd Floor Halls	CHR	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
9	9" x 9" Brown Floor Tile Mastic	21,000	SF	Classrooms	CHR	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
A	Elbows on Fiberglass Pipe Runs	3	LF	2nd Floor Boys	CHR	TSI	Y	NONE				Any remaining friable		LOW

# Chicago Public Schools

**School** Crown Academy **Unit** 31041 **Building ID** 2940  
**Address** 2128 S. St. Louis **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Janitor Closet								ACBM or friable suspect ACBM		
B	Cardboard Pipe Wrap			ABATED	ABATED	TSI					Yes			
C	Elbows on Cardboard Pipe Wrap			ABATED	ABATED	TSI								
D	Transite Flue Pipe			Boiler Room	CHR	MISC					Yes			
E	Breaching Insulation			ABATED	ABATED	TSI					Yes			
F	Help Room Tank Insulation			ABATED	ABATED	TSI					No			
G	Tank Insulation			ABATED	ABATED	TSI					No			
H	Boiler Gaskets			Boiler Room	NO_ACBM	MISC					No			
I	12" x 12" Green w/ Dark Green Streaks Vinyl Floor Tile	900	SF	Faculty Lunchroom, Conference Area, Counselling Office, Nurses Office	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
J	12" x 12" Green w/ Dark Green Streaks Vinyl Floor Tile Mastic	900	SF	Faculty Lunchroom, Conference Area, Counselling Office, Nurses Office	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
K	12" x 12" Blue w/ Dark Blue Streaks Vinyl Floor Tile	180	SF	All Vestibule Border Tile	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
L	12" x 12" Blue w/ Dark Blue Streaks Vinyl Floor Tile Mastic	180	SF	All Vestibule Border Tile	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
M	9" x 9" Beige w/ White Streaks Vinyl Floor Tile	100	SF	Northwest Stairwell 2nd Floor, Womens Bathroom 3rd Floor, 2nd and 3rd Floors by Fountains	ASSUMED	MISC	N	LOC	2	SF	Yes	ACBM with the potential for damage	5	LOW
N	9" x 9" Beige w/ White Streaks Vinyl Floor Tile Mastic	100	SF	Northwest Stairwell 2nd Floor, Womens Bathroom 3rd Floor, 2nd and 3rd Floors by Fountains	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
O	Vibration Gasket	30	SF	Storeroom A, Stage	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
P	Curtain Wall Panels			Throughout Classrooms	ASSUMED	MISC								
Q	Brown Baseboard	100	LF	Room 201	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
R	Brown Baseboard Mastic	100	LF	Room 201	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
S	Drywall			Room 201	ASSUMED	MISC								
T	1' x 1' Dotted Ceiling Tile Mastic	5,000	SF	Throughout	ASSUMED	MISC	N	DIST	50	SF	Yes	ACBM with the potential for damage	5	LOW
U	Terrazzo Light Tan Floor	900	SF	1, 2, 3, Floor Boys and Girls Bathroom	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Crown Academy **Unit** 31041 **Building ID** 2940  
**Address** 2128 S. St. Louis **Region** 03

## **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

## Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

## *Inspector's Comments are Summarized at the End of the Report*

# Chicago Public Schools

School Crown Academy Unit 31041 Building ID 2940  
Address 2128 S. St. Louis Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <u>3/24/2025</u>
Inspector Name <u>Dionne Carey Walker</u>
<u>100-09969</u> <u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date

#### Inspector's Comments

HA Number:	Inspector Comments:
005	
1	Not observed in auditorium, damage on 2nd floor near Janitor's closet
10	
11	
12	
13	
14	Not observed in lunchroom or kitchen
15	Not observed in lunchroom or kitchen
16	Material not observed - 2025
17	Damage in Northwest stairwell, tile loose
18	Stairwell tile is loose
19	
2	Damage in Room 309 and 306
20	Material not observed - 2025
21	
22	
23	
24	
25	
26	
27	
28	
29	
3	

# Chicago Public Schools

**School** Crown Academy **Unit** 31041 **Building ID** 2940  
**Address** 2128 S. St. Louis **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
30	
31	Material not observed - 2025
32	Material not observed - 2025
33	Material not observed - 2025
34	
35	
36	
37	
38	
4	
5	
6	
7	Damaged observed in gym hallway
8	
9	
A	
B	
C	
D	Material not observed - 2025
E	
F	
G	
H	
I	
J	
K	
L	
M	Damaged 3rd floor water fountain
N	

# Chicago Public Schools

**School** Crown Academy **Unit** 31041 **Building ID** 2940  
**Address** 2128 S. St. Louis **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
O	
P	Material not observed - 2025
Q	
R	
S	Material not observed - 2025
T	Damage in Teachers lounge
U	
V	
W	Material not observed - 2025

**Table II**  
**Management Planner's Review**

---

# Chicago Public Schools

**School** Crown Academy

**Unit** 31041

**Building ID** 2940

**Address** 2128 S. St. Louis

Chicago, IL, 60623

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
005	9" x 9" Dark Brown Floor Tile	175	SF	1960 Building, Rooms 215, 220, 210 and Lunchroom Areas, Food Storage., 300, 301, 302, 303, 304, 305, 306, 307, 310, 208, 207, 206, 205, 204, 203, 202, 201, 200	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
1	9" x 9" Gray Floor Tile	25,000	SF	Kitchen, Room 109, 2nd and 3rd Floor Halls and Womens Lounge	Chrysotile	MISC	No	50	SF	5 ACBM with potential for significant damage	Remove
10	12" x 12" Brown Floor Tile Mastic			ABATED	Abated	MISC					
11	Window Caulk			Throughout	No ACBM	MISC					
12	Door Caulk			Throughout	No ACBM	MISC					
13	Hard Plaster Ceiling			Gym	No ACBM	SURFACE					
14	12" x 12" White w/ Gray Specks Floor Tile	8,000	SF	1st Floor Hall, Stair Landings, Room 111	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
15	12" x 12" White w/ Gray Specks Floor Tile Mastic	8,000	SF	1st Floor Hall, Stair Landings, Room 111	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
16	Liner in Vault Door			Office	Assumed	MISC					
17	12" x 12" White Floor Tile	1,200	SF	Northwest Stairwell 2nd Floor, Womens Bathroom 3rd Floor	Assumed	MISC	No	5	SF	6 ACBM with the potential for damage	Remove
18	12" x 12" White Floor Tile Mastic	1,200	SF	Northwest Stairwell 2nd Womens Bathroom 3rd Floor	Assumed	MISC	No	200	SF	6 ACBM with the potential for damage	Remove
19	12" x 12" Black Floor Tile	300	SF	All Classrooms Around Univents	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
2	9" x 9" Brown Floor Tile	21,000	SF	Classrooms	Chrysotile	MISC	No	120	SF	6 ACBM with the potential for damage	Remove
20	12" x 12" Black Floor Tile Mastic			All Classrooms Around Univents	Assumed	MISC					
21	Gray Vinyl Tread Cover	350	SF	Stairwells	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Gray Vinyl Tread Cover Adhesive	350	SF	Stairwells	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12" x 12" Yellow Floor Tile	150	SF	All Vestibules, 109, 113	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12" x 12" Yellow Floor Tile Mastic	150	SF	All Vestibules, 109, 113	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12" x 12" Gray Floor Tile	1,350	SF	Main Office, Principal's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12" x 12" Gray Floor Tile Mastic	1,350	SF	Main Office, Principal's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
27	9" x 9" Black Floor Tile	20	SF	Room 305	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
28	9" x 9" Black Floor Tile Mastic	20	SF	Room 305	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
29	9" x 9" Dark Gray Floor Tile	20	SF	2nd Floor Corridor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
3	12" x 12" Brown Floor Tile			ABATED	Abated	MISC					
30	9" x 9" Dark Gray Floor Tile Mastic	20	SF	2nd Floor Corridor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12" x 12" Yellow Floor Tile			Room 109	Assumed	MISC					

# Chicago Public Schools

**School** Crown Academy

**Unit** 31041

**Building ID** 2940

**Address** 2128 S. St. Louis

Chicago, IL, 60623

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
32	12" x 12" White w/ Blue Specks Floor Tile			Room 109	Assumed	MISC					
33	12" x 12" Yellow & White w/ Blue Specks Floor Tile Mastic			Room 109	Assumed	MISC					
34	12" x 12" Dark Blue Floor Tile	300	SF	Room 111, assembly	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
35	12" x 12" Light Blue Floor Tile	300	SF	Room 111	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12" x 12" Dark/Light Blue Floor Tile Mastic	600	SF	Room 111	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
37	2' x 2' Ceiling Tile	800	SF	Rooms 111, 113	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
38	Lab Table	16	SF	Room 203	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
4	1' x 1' Dotted Ceiling Tiles			Room 300, 200, and Outside Room 307, Nurses Office, Main Office	No ACBM	MISC					
5	1' x 1' Fissured Ceiling Tile			First Floor Hall, Nurses Office	No ACBM	MISC					
6	Hard Plaster			Kitchen, 3rd Floor Womens Bathroom, Room 200	No ACBM	SURFACE					
7	2' x 2' Transite Ceiling Panels	600	SF	Hall Outside Gym	Chrysotile	MISC	No	1	SF	6 ACBM with the potential for damage	Repair
8	9" x 9" Gray Floor Tile Mastic	21,300	SF	Halls, Kitchen, Rooms 109, 119, and Auditorium, 2nd and 3rd Floor Halls	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
9	9" x 9" Brown Floor Tile Mastic	21,000	SF	Classrooms	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Elbows on Fiberglass Pipe Runs	3	LF	2nd Floor Boys Janitor Closet	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
B	Cardboard Pipe Wrap			ABATED	Abated	TSI					
C	Elbows on Cardboard Pipe Wrap			ABATED	Abated	TSI					
D	Transite Flue Pipe			Boiler Room	Chrysotile	MISC					
E	Breaching Insulation			ABATED	Abated	TSI					
F	Help Room Tank Insulation			ABATED	Abated	TSI					
G	Tank Insulation			ABATED	Abated	TSI					
H	Boiler Gaskets			Boiler Room	No ACBM	MISC					
I	12" x 12" Green w/ Dark Green Streaks Vinyl Floor Tile	900	SF	Faculty Lunchroom, Conference Area, Counselling Office, Nurses Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
J	12" x 12" Green w/ Dark Green Streaks Vinyl Floor Tile Mastic	900	SF	Faculty Lunchroom, Conference Area, Counselling Office, Nurses Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
K	12" x 12" Blue w/ Dark Blue Streaks Vinyl Floor Tile	180	SF	All Vestibule Border Tile	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
L	12" x 12" Blue w/ Dark Blue Streaks Vinyl Floor Tile Mastic	180	SF	All Vestibule Border Tile	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
M	9" x 9" Beige w/ White Streaks Vinyl Floor Tile	100	SF	Northwest Stairwell 2nd Floor, Womens	Assumed	MISC	No	2	SF	6 ACBM with the potential for damage	Remove

# Chicago Public Schools

**School** Crown Academy

**Unit** 31041

**Building ID** 2940

**Address** 2128 S. St. Louis

Chicago, IL, 60623

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Bathroom 3rd Floor, 2nd and 3rd Floors by Fountains							
N	9" x 9" Beige w/ White Streaks Vinyl Floor Tile Mastic	100	SF	Northwest Stairwell 2nd Floor, Womens Bathroom 3rd Floor, 2nd and 3rd Floors by Fountains	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
O	Vibration Gasket	30	SF	Storeroom A, Stage	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
P	Curtain Wall Panels			Throughout Classrooms	Assumed	MISC					
Q	Brown Baseboard	100	LF	Room 201	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
R	Brown Baseboard Mastic	100	LF	Room 201	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
S	Drywall			Room 201	Assumed	MISC					
T	1' x 1' Dotted Ceiling Tile Mastic	5,000	SF	Throughout	Assumed	MISC	No	50	SF	6 ACBM with the potential for damage	Remove
U	Terrazzo Light Tan Floor	900	SF	1, 2, 3, Floor Boys and Girls Bathroom & 1 Floor Teacher Bathrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
V	Sink Insulation	70	SF	Rooms 100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110	Assumed	SURFACE	No		SF	5 ACBM with potential for significant damage	Follow O&M Plan
W	Brown Carpet Mastic			111 - Media Center	Assumed	MISC					

# Chicago Public Schools

**School** Crown Academy

**Unit** 31041

**Building ID** 2940

**Address** 2128 S. St. Louis

Chicago, IL, 60623

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

***Management Planner's Comments Summarized at the End of the Report***

Review Date	4/18/2025
Manager Planner Name	Mike Serio
100-18488	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
005	
1	Remove or repair damaged material.
10	
11	
12	
13	
14	Sample to determine ACM content prior to disturbance.
15	Sample to determine ACM content prior to disturbance.
16	If identified, continue O&M
17	Sample to determine ACM content, remove and replace damaged material.
18	Sample to determine ACM content, remove or repair damaged material.
19	Sample to determine ACM content prior to disturbance.
2	Remove or repair damaged material.
20	If identified, continue O&M
21	Sample to determine ACM content prior to disturbance.
22	Sample to determine ACM content prior to disturbance.
23	Sample to determine ACM content prior to disturbance.
24	Sample to determine ACM content prior to disturbance.
25	Sample to determine ACM content prior to disturbance.
26	Sample to determine ACM content prior to disturbance.
27	Sample to determine ACM content prior to disturbance.
28	Sample to determine ACM content prior to disturbance.

# Chicago Public Schools

**School** Crown Academy

**Unit** 31041

**Building ID** 2940

**Address** 2128 S. St. Louis

Chicago, IL, 60623

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
29	Sample to determine ACM content prior to disturbance.
3	
30	Sample to determine ACM content prior to disturbance.
31	If identified, continue O&M
32	If identified, continue O&M
33	If identified, continue O&M
34	Sample to determine ACM content prior to disturbance.
35	Sample to determine ACM content prior to disturbance.
36	Sample to determine ACM content prior to disturbance.
37	Sample to determine ACM content prior to disturbance.
38	Sample to determine ACM content prior to disturbance.
4	
5	
6	
7	Remove or repair damaged material.
8	
9	
A	
B	
C	
D	If identified, continue O&M
E	
F	
G	
H	
I	Sample to determine ACM content prior to disturbance.
J	Sample to determine ACM content prior to disturbance.

# Chicago Public Schools

**School** Crown Academy

**Unit** 31041

**Building ID** 2940

**Address** 2128 S. St. Louis

Chicago, IL, 60623

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
K	Sample to determine ACM content prior to disturbance.
L	
M	Sample to determine ACM content, remove and replace damaged material.
N	Sample to determine ACM content prior to disturbance.
O	Sample to determine ACM content prior to disturbance.
P	If identified, continue O&M
Q	Sample to determine ACM content prior to disturbance.
R	Sample to determine ACM content prior to disturbance.
S	If identified, continue O&M
T	Sample to determine ACM content, remove and replace damaged material.
U	Sample to determine ACM content prior to disturbance.
V	Sample to determine ACM content prior to disturbance.
W	If identified, continue O&M

## APPENDIX A

---

### Assessment Sheets, Drawings and Photos

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2025 AHERA REINSPECTION***

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA RE/INSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUIDLING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	005		
MATERIAL DESCRIPTION:	9" x 9" Dark Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	1960 Building, Rooms 215, 220, 210 and Lunchroom Areas, Food Storage., 300, 301, 302, 303, 304, 305, 306, 307, 310, 208, 207, 206, 205, 204, 203, 202, 201, 200		
MATERIAL QUANTITY:	175	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUIDLING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **005**

MATERIAL DESCRIPTION: **9" x 9" Dark Brown Floor Tile**

MATERIAL LOCATION: **1960 Building, Rooms 215, 220, 210 and Lunchroom Areas, Food Storage., 300, 301, 302, 303, 304, 305, 306, 307, 310, 208, 207, 206, 205, 204, 203, 202, 201, 200**

MATERIAL QUANTITY: **175** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 04/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>1</b>		
MATERIAL DESCRIPTION:	<b>9" x 9" Gray Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>5 ACBM with potential for significant damage</b>		
HISTORICAL DAMAGE REASON:	<b>Physical Damage</b>		
HISTORICAL RESPONSE ACTION:	<b>Remove</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	<b>Physical Damage</b>		
DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Kitchen, Room 109, 2nd and 3rd Floor Halls and Womens Lounge</b>		
MATERIAL QUANTITY:	<b>25000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Not observed in auditorium, damage on 2nd floor near Janitor's closet</b>		

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile**

MATERIAL LOCATION: **Kitchen, Room 109, 2nd and 3rd Floor Halls and Womens Lounge**

MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Remove or repair damaged material.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUIDLING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUILDING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 11  
MATERIAL DESCRIPTION: Window Caulk  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Window Caulk**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUIDLING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Door Caulk**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Door Caulk**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUIDLING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 13  
MATERIAL DESCRIPTION: Hard Plaster Ceiling  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Gym

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Hard Plaster Ceiling**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>14</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" White w/ Gray Specks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1st Floor Hall, Stair Landings, Room 111</b>		
MATERIAL QUANTITY:	<b>8000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Not observed in lunchroom or kitchen</b>		

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Specks Floor Tile**

MATERIAL LOCATION: **1st Floor Hall, Stair Landings, Room 111**

MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>15</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" White w/ Gray Specks Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1st Floor Hall, Stair Landings, Room 111</b>		
MATERIAL QUANTITY:	<b>8000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Not observed in lunchroom or kitchen</b>		

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUIDLING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Specks Floor Tile Mastic**

MATERIAL LOCATION: **1st Floor Hall, Stair Landings, Room 111**

MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>16</b>	
MATERIAL DESCRIPTION:	<b>Liner in Vault Door</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Liner in Vault Door**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>17</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" White Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	<b>Physical Damage</b>		
DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Northwest Stairwell 2nd Floor, Womens Bathroom 3rd Floor</b>		
MATERIAL QUANTITY:	<b>1200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Damage in Northwest stairwell, tile loose</b>		

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**

MATERIAL LOCATION: **Northwest Stairwell 2nd Floor, Womens Bathroom 3rd Floor**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content, remove and replace damaged material.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUIDLING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>18</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" White Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:	<b>Physical Damage</b>		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	<b>Physical Damage</b>		
DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Northwest Stairwell 2nd Womens Bathroom 3rd Floor</b>		
MATERIAL QUANTITY:	<b>1200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Stairwell tile is loose</b>		

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**

MATERIAL LOCATION: **Northwest Stairwell 2nd Womens Bathroom 3rd Floor**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **200** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content, remove or repair damaged material.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>19</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Black Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>All Classrooms Around Univents</b>		
MATERIAL QUANTITY:	<b>300</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile**

MATERIAL LOCATION: **All Classrooms Around Univents**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUIDLING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>2</b>		
MATERIAL DESCRIPTION:	<b>9" x 9" Brown Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	<b>Physical Damage</b>		
DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Classrooms</b>		
MATERIAL QUANTITY:	<b>21000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Damage in Room 309 and 306</b>		

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile**

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY: **21000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **120** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Remove or repair damaged material.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUILDING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20	
MATERIAL DESCRIPTION:	12" x 12" Black Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: All Classrooms Around Univents

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUIDLING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile Mastic**

MATERIAL LOCATION: **All Classrooms Around Univents**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>21</b>		
MATERIAL DESCRIPTION:	<b>Gray Vinyl Tread Cover</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Stairwells</b>		
MATERIAL QUANTITY:	<b>350</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Gray Vinyl Tread Cover**

MATERIAL LOCATION: **Stairwells**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUIDLING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>22</b>		
MATERIAL DESCRIPTION:	<b>Gray Vinyl Tread Cover Adhesive</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Stairwells</b>		
MATERIAL QUANTITY:	<b>350</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Gray Vinyl Tread Cover Adhesive**

MATERIAL LOCATION: **Stairwells**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUIDLING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>23</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Yellow Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>All Vestibules, 109, 113</b>		
MATERIAL QUANTITY:	<b>150</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile**

MATERIAL LOCATION: **All Vestibules, 109, 113**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUIDLING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>24</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Yellow Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>All Vestibules, 109, 113</b>		
MATERIAL QUANTITY:	<b>150</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile Mastic**

MATERIAL LOCATION: **All Vestibules, 109, 113**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUIDLING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	12" x 12" Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office, Principal's Office		
MATERIAL QUANTITY:	1350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile**

MATERIAL LOCATION: **Main Office, Principal's Office**

MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUIDLING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	12" x 12" Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office, Principal's Office		
MATERIAL QUANTITY:	1350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile Mastic**

MATERIAL LOCATION: **Main Office, Principal's Office**

MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUIDLING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	9" x 9" Black Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 305		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile**

MATERIAL LOCATION: **Room 305**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUIDLING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	9" x 9" Black Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 305		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile Mastic**

MATERIAL LOCATION: **Room 305**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>29</b>		
MATERIAL DESCRIPTION:	<b>9" x 9" Dark Gray Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>2nd Floor Corridor</b>		
MATERIAL QUANTITY:	<b>20</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **9" x 9" Dark Gray Floor Tile**

MATERIAL LOCATION: **2nd Floor Corridor**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUIDLING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 3  
MATERIAL DESCRIPTION: 12" x 12" Brown Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUIDLING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>30</b>		
MATERIAL DESCRIPTION:	<b>9" x 9" Dark Gray Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>2nd Floor Corridor</b>		
MATERIAL QUANTITY:	<b>20</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **9" x 9" Dark Gray Floor Tile Mastic**

MATERIAL LOCATION: **2nd Floor Corridor**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>31</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Yellow Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 109**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile**

MATERIAL LOCATION: **Room 109**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>32</b>	
MATERIAL DESCRIPTION:	<b>12" x 12" White w/ Blue Specks Floor Tile</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 109**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **12" x 12" White w/ Blue Specks Floor Tile**

MATERIAL LOCATION: **Room 109**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>33</b>	
MATERIAL DESCRIPTION:	<b>12" x 12" Yellow &amp; White w/ Blue Specks Floor Tile Mastic</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 109**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **12" x 12" Yellow & White w/ Blue Specks Floor Tile Mastic**

MATERIAL LOCATION: **Room 109**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUIDLING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	12" x 12" Dark Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 111, assembly		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **12" x 12" Dark Blue Floor Tile**

MATERIAL LOCATION: **Room 111, assembly**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUIDLING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	12" x 12" Light Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 111		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **12" x 12" Light Blue Floor Tile**

MATERIAL LOCATION: **Room 111**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUIDLING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>36</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Dark/Light Blue Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 111</b>		
MATERIAL QUANTITY:	<b>600</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **12" x 12" Dark/Light Blue Floor Tile Mastic**

MATERIAL LOCATION: **Room 111**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUIDLING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 4

MATERIAL DESCRIPTION: 1' x 1' Dotted Ceiling Tiles

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 300, 200, and Outside Room 307, Nurses Office, Main Office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **1' x 1' Dotted Ceiling Tiles**

MATERIAL LOCATION: **Room 300, 200, and Outside Room 307, Nurses Office, Main Office**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUIDLING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 5

MATERIAL DESCRIPTION: 1' x 1' Fissured Ceiling Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: First Floor Hall, Nurses Office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **1' x 1' Fissured Ceiling Tile**

MATERIAL LOCATION: **First Floor Hall, Nurses Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUIDLING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **Hard Plaster**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen, 3rd Floor Womens Bathroom, Room 200**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **Hard Plaster**

MATERIAL LOCATION: **Kitchen, 3rd Floor Womens Bathroom, Room 200**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUIDLING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>7</b>		
MATERIAL DESCRIPTION:	<b>2' x 2' Transite Ceiling Panels</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:	<b>Physical Damage</b>		
HISTORICAL RESPONSE ACTION:	<b>Repair</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	<b>Physical Damage</b>		
DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Hall Outside Gym</b>		
MATERIAL QUANTITY:	<b>600</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Damaged observed in gym hallway</b>		

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **2' x 2' Transite Ceiling Panels**

MATERIAL LOCATION: **Hall Outside Gym**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **1** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Remove or repair damaged material.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>8</b>		
MATERIAL DESCRIPTION:	<b>9" x 9" Gray Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Halls, Kitchen, Rooms 109, 119, and Auditorium, 2nd and 3rd Floor Halls</b>		
MATERIAL QUANTITY:	<b>21300</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile Mastic**

MATERIAL LOCATION: **Halls, Kitchen, Rooms 109, 119, and Auditorium, 2nd and 3rd Floor Halls**

MATERIAL QUANTITY: **21300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>9</b>		
MATERIAL DESCRIPTION:	<b>9" x 9" Brown Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Classrooms</b>		
MATERIAL QUANTITY:	<b>21000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile Mastic**

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY: **21000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUILDING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A		
MATERIAL DESCRIPTION:	Elbows on Fiberglass Pipe Runs		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Boys Janitor Closet		
MATERIAL QUANTITY:	3	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Elbows on Fiberglass Pipe Runs**

MATERIAL LOCATION: **2nd Floor Boys Janitor Closet**

MATERIAL QUANTITY: **3** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 04/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUIDLING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Cardboard Pipe Wrap**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUIDLING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Cardboard Pipe Wrap**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUILDING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	Elbows on Cardboard Pipe Wrap		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Abated	FRIABLE:	

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Elbows on Cardboard Pipe Wrap**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>D</b>		
MATERIAL DESCRIPTION:	<b>Transite Flue Pipe</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Transite Flue Pipe**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUIDLING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Breaching Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Breaching Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUIDLING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: F

MATERIAL DESCRIPTION: Help Room Tank Insulation

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Help Room Tank Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUILDING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Tank Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Tank Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUILDING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: H

MATERIAL DESCRIPTION: Boiler Gaskets

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Boiler Gaskets**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUILDING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	I		
MATERIAL DESCRIPTION:	12" x 12" Green w/ Dark Green Streaks Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Faculty Lunchroom, Conference Area, Counselling Office, Nurses Office		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **12" x 12" Green w/ Dark Green Streaks Vinyl Floor Tile**

MATERIAL LOCATION: **Faculty Lunchroom, Conference Area, Counselling Office, Nurses Office**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUILDING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	J		
MATERIAL DESCRIPTION:	12" x 12" Green w/ Dark Green Streaks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Faculty Lunchroom, Conference Area, Counselling Office, Nurses Office		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **12" x 12" Green w/ Dark Green Streaks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Faculty Lunchroom, Conference Area, Counselling Office, Nurses Office**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUIDLING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	K		
MATERIAL DESCRIPTION:	12" x 12" Blue w/ Dark Blue Streaks Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	All Vestibule Border Tile		
MATERIAL QUANTITY:	180	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **12" x 12" Blue w/ Dark Blue Streaks Vinyl Floor Tile**

MATERIAL LOCATION: **All Vestibule Border Tile**

MATERIAL QUANTITY: **180** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUILDING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	L		
MATERIAL DESCRIPTION:	12" x 12" Blue w/ Dark Blue Streaks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	All Vestibule Border Tile		
MATERIAL QUANTITY:	180	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **12" x 12" Blue w/ Dark Blue Streaks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **All Vestibule Border Tile**

MATERIAL QUANTITY: **180** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUILDING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	M		
MATERIAL DESCRIPTION:	9" x 9" Beige w/ White Streaks Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Northwest Stairwell 2nd Floor, Womens Bathroom 3rd Floor, 2nd and 3rd Floors by Fountains		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damaged 3rd floor water fountain		

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **9" x 9" Beige w/ White Streaks Vinyl Floor Tile**

MATERIAL LOCATION: **Northwest Stairwell 2nd Floor, Womens Bathroom 3rd Floor, 2nd and 3rd Floors by Fountains**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content, remove and replace damaged material.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUILDING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	N		
MATERIAL DESCRIPTION:	9" x 9" Beige w/ White Streaks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Northwest Stairwell 2nd Floor, Womens Bathroom 3rd Floor, 2nd and 3rd Floors by Fountains		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **9" x 9" Beige w/ White Streaks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Northwest Stairwell 2nd Floor, Womens Bathroom 3rd Floor, 2nd and 3rd Floors by Fountains**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>O</b>		
MATERIAL DESCRIPTION:	<b>Vibration Gasket</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Storeroom A, Stage</b>		
MATERIAL QUANTITY:	<b>30</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **O**

MATERIAL DESCRIPTION: **Vibration Gasket**

MATERIAL LOCATION: **Storeroom A, Stage**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>P</b>		
MATERIAL DESCRIPTION:	<b>Curtain Wall Panels</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Classrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **Curtain Wall Panels**

MATERIAL LOCATION: **Throughout Classrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>Q</b>		
MATERIAL DESCRIPTION:	<b>Brown Baseboard</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 201</b>		
MATERIAL QUANTITY:	<b>100</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **Q**

MATERIAL DESCRIPTION: **Brown Baseboard**

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUILDING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	R		
MATERIAL DESCRIPTION:	Brown Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 201		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **R**

MATERIAL DESCRIPTION: **Brown Baseboard Mastic**

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>S</b>		
MATERIAL DESCRIPTION:	<b>Drywall</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **S**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>T</b>		
MATERIAL DESCRIPTION:	<b>1' x 1' Dotted Ceiling Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	<b>Physical Damage</b>		
DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Throughout</b>		
MATERIAL QUANTITY:	<b>5000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Damage in Teachers lounge</b>		

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **T**

MATERIAL DESCRIPTION: **1' x 1' Dotted Ceiling Tile Mastic**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content, remove and replace damaged material.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUIDLING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>U</b>		
MATERIAL DESCRIPTION:	<b>Terrazzo Light Tan Floor</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1, 2, 3, Floor Boys and Girls Bathroom &amp; 1 Floor Teacher Bathrooms</b>		
MATERIAL QUANTITY:	<b>900</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **U**

MATERIAL DESCRIPTION: **Terrazzo Light Tan Floor**

MATERIAL LOCATION: **1, 2, 3, Floor Boys and Girls Bathroom & 1 Floor Teacher Bathrooms**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Crown Academy</b>	INSPECTION DATE:	<b>3/24/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>V</b>		
MATERIAL DESCRIPTION:	<b>Sink Insulation</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>5 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:	<b>Deterioration</b>		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 100 , 101, 102, 103, 104, 105, 106, 107, 108, 109, 110</b>		
MATERIAL QUANTITY:	<b>70</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/24/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **V**

MATERIAL DESCRIPTION: **Sink Insulation**

MATERIAL LOCATION: **Rooms 100 , 101, 102, 103, 104, 105, 106, 107, 108, 109, 110**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUIDLING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: W  
MATERIAL DESCRIPTION: Brown Carpet Mastic  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 111 - Media Center

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31041</b>	BUILDING ID:	<b>2940</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Crown Academy</b>	REVIEW DATE:	<b>4/18/2025</b>		
ADDRESS:	<b>2128 S. St. Louis</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **W**

MATERIAL DESCRIPTION: **Brown Carpet Mastic**

MATERIAL LOCATION: **111 - Media Center**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUIDLING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	2' x 2' Ceiling Tile		
MATERIAL LOCATION:	Rooms 111, 113		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	Yes
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	7 Any remaining friable ACBM or friable suspect ACBM		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31041** BUIDLING ID: **2940**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Crown Academy** REVIEW DATE: **4/18/2025**

ADDRESS: **2128 S. St. Louis** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile**

MATERIAL LOCATION: **Rooms 111, 113**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31041	BUIDLING ID:	2940
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Crown Academy	INSPECTION DATE:	3/24/2025		
ADDRESS:	2128 S. St. Louis	IDPH LICENSE NO:	100-09969		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	Lab Table		
MATERIAL LOCATION:	Room 203		
MATERIAL QUANTITY:	16	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/24/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31041** BUIDLING ID: **2940**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Crown Academy** REVIEW DATE: **4/18/2025**

ADDRESS: **2128 S. St. Louis** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Lab Table**

MATERIAL LOCATION: **Room 203**

MATERIAL QUANTITY: **16** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/18/2025

## APPENDIX B

---

### Inspector and Management Planner Licenses



**OCCUPATIONAL TRAINING & SUPPLY, INC. 2024**  
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

## Asbestos Abatement Supervisor Refresher

Occupational Training & Supply, Inc. certifies that

**Dionne L.C. Walker**

has successfully completed the Asbestos Abatement Supervisor Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 10/14/2024

Exam Date: 10/14/2024

Expiration Date: 10/14/2025

Certificate Number: ASR2410142781

Course Credit Hours: ASR 8 Hours

*Kristina Miczek*

Kristina Miczek, Training Manager

# Dionne Walker

---

Asbestos Project Manager, Illinois Licensed Building Inspector, Air Sampling Professional



**ASBESTOS  
PROFESSIONAL  
LICENSE**

ID NUMBER  
100 - 09969

ISSUED  
4/28/2025

EXPIRES  
05/15/2026

**DIONNE L CAREY WALKER**  
211 SOMERSET DRIVE  
STREAMWOOD, IL 60107

Environmental Health



**ENDORSEMENTS**

INSPECTOR

**TC EXPIRES**

10/11/2025

PROJECT MANAGER  
AIR SAMPLING PROFESSIONAL

10/14/2025

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.





OCCUPATIONAL TRAINING & SUPPLY, INC. **2024**  
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

---

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Michael Serio**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/18/2024

Exam Date: 11/18/2024

Expiration Date: 11/18/2025

Certificate Number: MPR2411183328

Course Credit Hours: MPR 4 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

---

Kristina Miczek, Training Manager

## APPENDIX C

---

### **Laboratory Accreditations**

## APPENDIX D

---

### Laboratory Results

## APPENDIX E

---

### Chain of Custody Forms

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>	Loc	Localized
	Dist	Distributed