

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2289
SCHOOL NAME: Pilsen Academy
ADDRESS OF SCHOOL: 1420 W. 17th St.
CITY: Chicago, IL, 60608

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 10/26/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 4/8/2025 ENROLLMENT 214
IDPH INSPECTOR LICENSE NUMBER: 100-09969
IDPH LICENSED INSPECTOR NAME (Please Print): Dionne Carey Walker
IDPH MP LICENSE NUMBER: 100-20634
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jackson Montgomery

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 4/29/2025

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Pilsen Academy

1420 W. 17th St.
Chicago, IL, 60608

Unit: 31141
Building ID: 4210

IDPH ID Number: 14-016-2990-2289

REPORT DATE:
Tuesday, April 29, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

04/29/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 31141 Region: 03 IDPH ID: 14-016-2990-2289

School: Pilsen Academy Building ID: 4210

Address: 1420 W. 17th St.

Chicago, IL, 60608

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date: 4/8/2025

Review Date: 04/29/2025

Inspector: Dionne Carey Walker

Inspector IDPH License: 100-09969

Management Planner: Jackson Montgomery

Management Planner IDPH License: 100-20634

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Jackson Montgomery
100-20634

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: April 29, 2025

RE: Pilsen Academy, Unit 31141
1420 W. 17th St.
Chicago, IL, 60608

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Pilsen Academy , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Pilsen Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Pilsen Academy Unit: 31141 Region: 03
Address: 1420 W. 17th St. Chicago, IL, 60608
IDPH ID: 14-016-2990-2289 Building ID: 4210
Contact: Phone:

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: No of Floors:
Current Occupancy: 214

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Dionne Carey Walker

Inspector IDPH license # 100-09969
Reinspection Date: 4/8/2025

Signature: 
Date: 4/8/2025

6. Management Planner

Management Planner Name: Jackson Montgomery

Management Planner IDPH license # 100-20634

Signature: 
Date: 04/29/2025

7. Review Date: 04/29/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 4/29/2025

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Pilsen Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4210:

01	Plaster
02	2' x 4' Ceiling Panels
03F	12" x 12" Brown Floor Tile
03H	12" x 12" Beige Floor Tile
03I	12" x 12" Off-White Floor Tile
03J	12" x 12" Tan Floor Tile
04	9" x 9" Floor Tile
05	1' x 1' Ceiling Tile
12	12" x 12" Brown Floor Tile Mastic

14	12" x 12" Beige Floor Tile Mastic
15	12" x 12" Off-White Floor Tile Mastic
16	12" x 12" Tan Floor Tile Mastic
17	Interior Brick
26	Yellow and Gray Ceramic Tile Grout
28	Beige Ceramic Tile Grout
29	4" Black Baseboards
35	6" Baseboard
49	Carpet Mastic
50	Carpet Mastic
51	Carpet Mastic
52	Carpet Mastic
55	Exterior Block
63	Skylight Caulk/Glazing
64	Plastic Wall Laminate Adhesive
65	Chalk Board/Poster Board Adhesive
66	12" x 12" Tan w/ Specks Floor Tile
66M	12" x 12" Tan w/ Specks Floor Tile Mastic
78	White Siuk Insulation
79	Green Terazzo
80	Blue Carpet Mastic
81	Blue Carpet Mastic
83	1' x 1' Fissure Ceiling Tile
87	12" x 12" Dark Brown Floor Tile

88	12" x 12" Dark Brown Floor Tile Mastic
89	12" x 12" Rose Gold Replacement Floor Tile
90	12" x 12" Rose Gold Replacement Floor Tile Mastic
91	12" x 12" Light Brown w/ Dark Brown/White Specks Replacement Floor Tile
93	12" x 12" Light Blue Floor Tile
94	12" x 12" Light Blue Floor Tile Mastic
C	Tank Insulation
E	Cardboard Pipe Insulation
F	Aircell Pipe Insulation
G	Fiberglass Pipe Insulation

B. The following new homogenous areas have been identified for Building 4210:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

02	2' x 4' Ceiling Panels
03A	12" x 12" Rust Floor Tile
03B	12" x 12" Green Floor Tile
03C	12" x 12" Beige Floor Tile
03E	12" x 12" Tan Floor Tile w/ Brown Streaks
03F	12" x 12" Brown Floor Tile
03G	12" x 12" Light Brown Floor Tile
03H	12" x 12" Beige Floor Tile
03I	12" x 12" Off-White Floor Tile
03J	12" x 12" Tan Floor Tile
04	9" x 9" Floor Tile
08	12" x 12" Green Floor Tile Mastic
09	12" x 12" Beige Floor Tile Mastic
10	12" x 12" Light Brown Floor Tile Mastic
11	12" x 12" Tan Floor Tile Mastic
14	12" x 12" Beige Floor Tile Mastic
25	Ceramic Tile Grout
27	Vibration Collar
28	Beige Ceramic Tile Grout
33	Wall Panels
34	Floor Leveler
48	Blue Carpet Mastic
49	Carpet Mastic
50	Carpet Mastic
51	Carpet Mastic
52	Carpet Mastic
53	Fire Doors
54	Boiler Gaskets
57	Carpet Mastic
58	12" x 12" White w/ Gray Floor Tile
59	12" x 12" White w/ Gray Floor Tile Mastic
60	Plastic Wall Laminate Mastic
61	Chalk Board/Poster Board Adhesive
62	Transom and Interior Window Glazing
63	Skylight Caulk/Glazing
64	Plastic Wall Laminate Adhesive
65	Chalk Board/Poster Board Adhesive
66	12" x 12" Tan w/ Specks Floor Tile
66M	12" x 12" Tan w/ Specks Floor Tile Mastic
67	White w/ Blue Streaks 12" x 12" Vinyl Floor Tile
68	White w/ Blue Streaks 12" x 12" Vinyl Floor Tile Mastic

69	Red 12" x 12" Vinyl Floor Tile
70	Red 12" x 12" Vinyl Floor Tile Mastic
71	Green 12" x 12" Vinyl Floor Tile
72	Green 12" x 12" Vinyl Floor Tile Mastic
73	Yellow 12" x 12" Vinyl Floor Tile
74	Yellow 12" x 12" Vinyl Floor Tile Mastic
75	Blue 12" x 12" Vinyl Floor Tile
76	Blue 12" x 12" Vinyl Floor Tile Mastic
77	2' x 2' Ceiling Tiles
78	White Siuk Insulation
79	Green Terazzo
80	Blue Carpet Mastic
81	Blue Carpet Mastic
82	Acoustical Plaster - Walls and Ceiling
83	1' x 1' Fissure Ceiling Tile
84	Tongue and Groove Wooden Floor
85	12" x 12" Mint Green Replacement Floor Tile
86	12" x 12" Mint Green Replacement Floor Tile Mastic
87	12" x 12" Dark Brown Floor Tile
88	12" x 12" Dark Brown Floor Tile Mastic
89	12" x 12" Rose Gold Replacement Floor Tile
90	12" x 12" Rose Gold Replacement Floor Tile Mastic
91	12" x 12" Light Brown w/ Dark Brown/White Specks Replacement Floor Tile
92	12" x 12" Light Brown w/ Dark Brown/White Specks Replacement Floor Tile Mastic
93	12" x 12" Light Blue Floor Tile
94	12" x 12" Light Blue Floor Tile Mastic
B	Boiler Packing
C	Tank Insulation
J	Mag Block Pipe Insulation Joints

The following areas were deemed to be inaccessible:

02	2' x 4' Ceiling Panels
08	12" x 12" Green Floor Tile Mastic
09	12" x 12" Beige Floor Tile Mastic
10	12" x 12" Light Brown Floor Tile Mastic
11	12" x 12" Tan Floor Tile Mastic
13	12" x 12" Light Brown Floor Tile Mastic
34	Floor Leveler
53	Fire Doors
59	12" x 12" White w/ Gray Floor Tile Mastic
60	Plastic Wall Laminate Mastic
61	Chalk Board/Poster Board Adhesive

66M	12" x 12" Tan w/ Specks Floor Tile Mastic
68	White w/ Blue Streaks 12" x 12" Vinyl Floor Tile Mastic
69	Red 12" x 12" Vinyl Floor Tile
70	Red 12" x 12" Vinyl Floor Tile Mastic
72	Green 12" x 12" Vinyl Floor Tile Mastic
74	Yellow 12" x 12" Vinyl Floor Tile Mastic
76	Blue 12" x 12" Vinyl Floor Tile Mastic
86	12" x 12" Mint Green Replacement Floor Tile Mastic
92	12" x 12" Light Brown w/ Dark Brown/White Specks Replacement Floor Tile Mastic
J	Mag Block Pipe Insulation Joints

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Dionne Carey Walker, IDPH License # 100-09969. The Management Plan was updated by Jackson Montgomery, IDPH License # 100-20634. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Pilson Academy Building 4210 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Pilsen Academy **Unit** 31141 **Building ID** 4210
Address 1420 W. 17th St. **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	Plaster			Throughout Main Building	NO_ACBM	SURFACE					Yes			
02	2' x 4' Ceiling Panels	7,000	SF	Throughout Main Building	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
03A	12" x 12" Rust Floor Tile	5,000	SF	Rooms 101, 108, 201, 202, 208, 209, Lunchroom #3, Womens Ground Floor Bathroom, 1st Floor Teachers' Lounge	ASSUMED	MISC	N	LOC	91	SF	No	ACBM with potential for significant damage	3	LOW
03B	12" x 12" Green Floor Tile	5,000	SF	Rooms 203, 205-207, 208, 202	ASSUMED	MISC	N	LOC	65	SF	No	ACBM with potential for significant damage	3	LOW
03C	12" x 12" Beige Floor Tile	4,150	SF	Lunchroom #1, Stage, Rooms 307, 308, 201, 120, 206, Office, Conference Room, 103, 108	ASSUMED	MISC	N	LOC	23	SF	No	ACBM with potential for significant damage	3	LOW
03D	12" x 12" Light Brown Floor Tile	2,500	SF	Lunchrooms # 1&2, Kitchen, Room 120, All Purpose Room	CHR	MISC	N	LOC	10	SF	No	ACBM with potential for significant damage	5	LOW
03E	12" x 12" Tan Floor Tile w/ Brown Streaks	2,000	SF	Lunchroom 1	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
03F	12" x 12" Brown Floor Tile			Rooms 203, 204, Hallways and Storage	ASSUMED	MISC					Yes			
03G	12" x 12" Light Brown Floor Tile	500	SF	Hallways, 2nd Floor Mens Bathrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
03H	12" x 12" Beige Floor Tile	600	SF	Stage	ASSUMED	MISC	N	LOC	10	SF	Yes	ACBM with potential for significant damage	5	MODERATE
03I	12" x 12" Off-White Floor Tile	600	SF	All Purpose Room	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		MODERATE
03J	12" x 12" Tan Floor Tile	300	SF	All Purpose room	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		MODERATE
04	9" x 9" Floor Tile			None Found	ASSUMED	MISC					Yes			
05	1' x 1' Ceiling Tile			Room 11, 110, 111, Office, Nurse's Room and Hallways	NO_ACBM	MISC					Yes			
06	Wrap Around Cardboard Pipe Insulation			Boiler Room, Boiler Room Storage Area	CHR	TSI					No			
07	12" x 12" Rust Floor Tile Mastic	5,000	SF	Rooms 101, 108, 201, 202, 208, 209, Lunchroom #3, Womens Ground	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Pilsen Academy **Unit** 31141 **Building ID** 4210
Address 1420 W. 17th St. **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Floor Bathroom, 1st Floor Teachers' Lounge										
08	12" x 12" Green Floor Tile Mastic	5,000	SF	Rooms 203, 205-207, 208, 202	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
09	12" x 12" Beige Floor Tile Mastic	3,000	SF	Lunchroom #1, Stage, Rooms 307, 308, 201, 120, Office, Conference, 103, 108	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
10	12" x 12" Light Brown Floor Tile Mastic	3,000	SF	Lunchrooms #1&2, Room 120, Kitchen	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
11	12" x 12" Tan Floor Tile Mastic	2,000	SF	Lunchroom #1	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
12	12" x 12" Brown Floor Tile Mastic			Rooms 203, 214, Hallways and Storage	CHR	MISC					Yes			
13	12" x 12" Light Brown Floor Tile Mastic	200	SF	Hallways, 2nd Floor Mens Bathrooms	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
14	12" x 12" Beige Floor Tile Mastic			Modular Building - DEMOLISHED	ASSUMED	MISC					Yes			
15	12" x 12" Off-White Floor Tile Mastic			Modular Building - DEMOLISHED	CHR	MISC					Yes			
16	12" x 12" Tan Floor Tile Mastic			Modular Building - DEMOLISHED	CHR	MISC					Yes			
17	Interior Brick			Throughout Main Building	NO_ACBM	MISC					Yes			
18	Interior Brick Mortar			Throughout Main Building	NO_ACBM	MISC					No			
19	Cinder Block Mortar			Throughout Ground Floor of Main Building	NO_ACBM	MISC					No			
20	Insulation on Walls			Boiler Storage Room (Previously Weight Room)	NO_ACBM	TSI					No			
21	Chalk Boards			Throughout Main Building	NO_ACBM	MISC					No			
22	Slate Beneath Chalk Boards			Throughout Main Building	NO_ACBM	MISC					No			
23	Terrazzo Flooring			Stairwells At Entrances	NO_ACBM	MISC					No			
24	Multi-Blue Ceramic Tile Grout			Boys Bathroom	NO_ACBM	MISC					No			
25	Ceramic Tile Grout	168	SF	Mens Ground Floor Bathroom, 1st Floor	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Pilsen Academy **Unit** 31141 **Building ID** 4210
Address 1420 W. 17th St. **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Teachers' Bathroom 3rd Floor Boys Bathroom										
26	Yellow and Gray Ceramic Tile Grout			Girls Bathrooms	NO_ACBM	MISC					Yes			
26A	Brown Ceramic Tile Grout			Girls Bathroom	NO_ACBM	MISC					No			
27	Vibration Collar	2	SF	Lunchroom # 1	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
28	Beige Ceramic Tile Grout			Modular Building - DEMOLISHED	ASSUMED	MISC					Yes			
29	4" Black Baseboards			Throughout Main Building	NO_ACBM	MISC					Yes			
30	4" Black Baseboard Mastic			Throughout Main Building	NO_ACBM	MISC					No			
31	Non-Skid Strips			Boiler Room Ramp, Hall by 119 Stair Landings	NO_ACBM	MISC					No			
32	Drywall			Throughout Main Building Ground Floor	NO_ACBM	MISC					No			
33	Wall Panels	1,000	SF	Throughout Main Building - Electrical Room	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
34	Floor Leveler	2,000	SF	Lunchroom #1	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
35	6" Baseboard			Lunchroom #1, Assistant Principle Office, Library, Girls Bathroom	NO_ACBM	MISC					Yes			
36	6" Baseboard Mastic			Lunchroom #1, Assistant Principle Office, Library, Girls Bathroom	NO_ACBM	MISC					No			
37	Red Caulk Around Pipes			Assistant Principles Office	NO_ACBM	MISC					No			
38	4" Black Baseboard			Modular Building - DEMOLISHED	NO_ACBM	MISC					No			
39	4" Black Baseboard Mastic			Modular Building - DEMOLISHED	NO_ACBM	MISC					No			
40	Drywall Joint Compound			Modular Building - DEMOLISHED	NO_ACBM	MISC					No			
41	Brown Carpet Mastic			Modular Building - DEMOLISHED	NO_ACBM	MISC					No			
42	Drywall			Modular Building - DEMOLISHED	NO_ACBM	MISC					No			

Chicago Public Schools

School Pilsen Academy **Unit** 31141 **Building ID** 4210
Address 1420 W. 17th St. **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
43	Blue Carpet Mastic			Rooms 028, 029	NO_ACBM	MISC					No			
44	Blue/Gray Carpet Mastic			Rooms 013, 110, 111	NO_ACBM	MISC					No			
45	Red Flooring			Modular Building - DEMOLISHED	NO_ACBM	MISC					No			
46	Red Flooring Mastic			Modular Building - DEMOLISHED	NO_ACBM	MISC					No			
48	Blue Carpet Mastic			Room 115, 205, 209	ASSUMED	MISC					No			
49	Carpet Mastic			Computer Lab, B02	ASSUMED	MISC					Yes			
50	Carpet Mastic			Office	ASSUMED	MISC					Yes			
51	Carpet Mastic			Room 105	ASSUMED	MISC					Yes			
52	Carpet Mastic			Modular Building - DEMOLISHED	ASSUMED	MISC					Yes			
53	Fire Doors	20		Throughout Facility	ASSUMED	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
54	Boiler Gaskets	20	LF	Boiler Room	ASSUMED	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
55	Exterior Block			Main Building	NO_ACBM	MISC					Yes			
56	Exterior Block Mortar			Main Building	NO_ACBM	MISC					No			
57	Carpet Mastic			Modular Building - DEMOLISHED	ASSUMED	MISC					No			
58	12" x 12" White w/ Gray Floor Tile	2,025	SF	Rooms 106 & 206, Lunchroom, 302, Gym Stage, 208, 202, 101	ASSUMED	MISC	N	DIST	35	SF	No	ACBM with potential for significant damage	5	LOW
59	12" x 12" White w/ Gray Floor Tile Mastic	2,025	SF	Rooms 106 & 206, Lunchroom, 302, Gym Stage, 208, 202, 101	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
60	Plastic Wall Laminate Mastic	1,260	SF	Lunchrooms and Kitchen	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
61	Chalk Board/Poster Board Adhesive	1,100	SF	Throughout Classrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
62	Transom and Interior Window Glazing	250	SF	Classroom and Office Entry Doors	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
63	Skylight Caulk/Glazing			1st Floor by Office	ASSUMED	MISC					Yes			
64	Plastic Wall Laminate Adhesive			Modular Building - DEMOLISHED	ASSUMED	MISC					Yes			
65	Chalk Board/Poster Board Adhesive			Modular Building - DEMOLISHED	ASSUMED	MISC					Yes			
66	12" x 12" Tan w/ Specks Floor Tile	975	SF	Rooms 115, 113, 110, 111, 204, 2nd	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		HIGH

Chicago Public Schools

School Pilsen Academy **Unit** 31141 **Building ID** 4210
Address 1420 W. 17th St. **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Floor Corridor Patch, 201, 202										
66M	12" x 12" Tan w/ Specks Floor Tile Mastic	975	SF	R115, 113, 110, 111, 204, 2nd Floor Corridor Patch, 201, 202	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		HIGH
67	White w/ Blue Streaks 12" x 12" Vinyl Floor Tile	5,000	SF	Lunchroom 1 and 2, Basement Corridor	ASSUMED	MISC	N	LOC	20	SF	No	ACBM with potential for significant damage	5	LOW
68	White w/ Blue Streaks 12" x 12" Vinyl Floor Tile Mastic	5,000	SF	Lunchroom 1 and 2, Basement Corridor	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
69	Red 12" x 12" Vinyl Floor Tile	5,000	SF	Lunchroom 1 and 2, Basement Corridor, Room 202	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
70	Red 12" x 12" Vinyl Floor Tile Mastic	5,000	SF	Lunchroom 1 and 2, Basement Corridor, Room 202	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
71	Green 12" x 12" Vinyl Floor Tile	5,000	SF	Lunchroom 1 and 2, Basement Corridor	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
72	Green 12" x 12" Vinyl Floor Tile Mastic	5,000	SF	Lunchroom 1 and 2, Basement Corridor	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
73	Yellow 12" x 12" Vinyl Floor Tile	5,000	SF	Lunchroom 1 and 2, Basement Corridor, Room 202	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
74	Yellow 12" x 12" Vinyl Floor Tile Mastic	5,000	SF	Lunchroom 1 and 2, Basement Corridor, Rooms 202	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
75	Blue 12" x 12" Vinyl Floor Tile	5,000	SF	Lunchroom 1 and 2, Basement Corridor	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
76	Blue 12" x 12" Vinyl Floor Tile Mastic	5,000	SF	Lunchroom 1 and 2, Basement Corridor	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
77	2' x 2' Ceiling Tiles	5,000	SF	Basement Kitchen	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
78	White Siuk Insulation			Room 120	ASSUMED	MISC					Yes			
79	Green Terazzo			Kitchen	ASSUMED	MISC					Yes			
80	Blue Carpet Mastic			Modular Building - DEMOLISHED	ASSUMED	MISC					Yes			
81	Blue Carpet Mastic			Room 302	ASSUMED	MISC					Yes			
82	Acoustical Plaster - Walls and Ceiling	200	SF	Basement - Kitchen Staff Locker Room and Bathroom	ASSUMED	SURFACE	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
83	1' x 1' Fissure Ceiling Tile			Modular Building - DEMOLISHED	ASSUMED	MISC					Yes			
84	Tongue and Groove Wooden Floor	800	SF	Rooms 301, 304,	ASSUMED	MISC	N	NONE			No	ACBM with the		LOW

Chicago Public Schools

School Pilsen Academy **Unit** 31141 **Building ID** 4210
Address 1420 W. 17th St. **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Gym, 306, 204, 102, 104, 105, 119								potential for damage		
85	12" x 12" Mint Green Replacement Floor Tile	5	SF	Room 203	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
86	12" x 12" Mint Green Replacement Floor Tile Mastic	5	SF	Room 203	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
87	12" x 12" Dark Brown Floor Tile			Rooms 208, 209, 108	ASSUMED	MISC					Yes			
88	12" x 12" Dark Brown Floor Tile Mastic			Rooms 208, 209, 108	ASSUMED	MISC					Yes			
89	12" x 12" Rose Gold Replacement Floor Tile			Room 201	ASSUMED	MISC					Yes			
90	12" x 12" Rose Gold Replacement Floor Tile Mastic			Room 201	ASSUMED	MISC					Yes			
91	12" x 12" Light Brown w/ Dark Brown/White Specks Replacement Floor Tile			Room 201	ASSUMED	MISC					Yes			
92	12" x 12" Light Brown w/ Dark Brown/White Specks Replacement Floor Tile Mastic	5	SF	Room 201	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
93	12" x 12" Light Blue Floor Tile			Room 202	ASSUMED	MISC					Yes			
94	12" x 12" Light Blue Floor Tile Mastic			Room 202	ASSUMED	MISC					Yes			
A1	#1 Boiler Insulation	325	SF	Boiler Room	CHR	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
A2	#2 Boiler Insulation	325	SF	Boiler Room	CHR	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
B	Boiler Packing	12	SF	Boilers	ASSUMED	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
C	Tank Insulation			Basement Tank Room	ASSUMED	TSI					Yes			
D	Mag Block Pipe Insulation	20	SF	Boiler Room	CHR	TSI	Y	LOC	10	SF	No	Damaged or significantly damaged friable thermal system insulating ACBM	5	LOW
E	Cardboard Pipe Insulation	500	SF	Tank Room, Boiler Room and Lunchroom #3	CHR	TSI	Y	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
F	Aircell Pipe Insulation	450	LF	Mechanical Areas and Room 120	CHR	TSI	Y	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
G	Fiberglass Pipe Insulation			Throughout Ground	NO_ACBM	TSI					Yes			

Chicago Public Schools

School Pilsen Academy **Unit** 31141 **Building ID** 4210
Address 1420 W. 17th St. **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Floor							No			
H	Number Skipped				UNDEFINE D						No			
I	Joint Insulation on Fiberglass Pipe Insulation	125	LF	Throughout Ground Floor, Room 101 Bathroom	CHR	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
J	Mag Block Pipe Insulation Joints	20	LF	Boiler Room	ASSUMED	TSI	Y	LOC	10	LF	No	Damaged or significantly damaged friable thermal system insulating ACBM	5	LOW
K	Joint Insulation on Cardboard Pipe Insulation	210	LF	Throughout Ground Floor	CHR	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
L	Joint Insulation on Aircell Pipe Insulation	200	LF	Boiler Room, Throughout the Ground Floor	CHR	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Pilsen Academy Unit 31141 Building ID 4210
Address 1420 W. 17th St. Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date <u>4/8/2025</u>
Inspector Name <u>Dionne Carey Walker</u>
<u>100-09969</u> <u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01	
02	
03A	Damage in Lunchroom office
03B	Damage in Room 203
03C	Damage in Lunchroom/kitchen
03D	Damage in Kitchen
03E	
03F	Material not observed - 2025
03G	Not observed in 207
03H	Damage on Stage steps
03I	No modular building
03J	No modular building
04	Material not observed - 2025
05	Material not observed - 2025
06	Material not observed - 2025
07	
08	
09	
10	
11	
12	Material not observed - 2025
13	Not observed in 207 and 208
14	Material not observed - 2025
15	Material not observed - 2025

Chicago Public Schools

School Pilsen Academy **Unit** 31141 **Building ID** 4210
Address 1420 W. 17th St. **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
16	Material not observed - 2025
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
26A	
27	
28	Material not observed - 2025
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	Material not observed - 2025
39	Material not observed - 2025
40	Material not observed - 2025
41	Material not observed - 2025
42	Material not observed - 2025
43	

Chicago Public Schools

School Pilsen Academy **Unit** 31141 **Building ID** 4210
Address 1420 W. 17th St. **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
44	
45	Material not observed - 2025
46	Material not observed - 2025
48	Material not observed - 2025
49	Material not observed - 2025
50	Material not observed - 2025
51	Material not observed - 2025
52	Material not observed - 2025
53	
54	
55	
56	
57	Material not observed - 2025
58	Damage from deterioration throughout lunchrooms and Room 206
59	
60	
61	
62	
63	Material not observed - 2025
64	Material not observed - 2025
65	Material not observed - 2025
66	Not observed in room 101, 208
66M	Not observed in 101 and 208
67	Damage in Lunchroom 2
68	
69	
70	
71	
72	

Chicago Public Schools

School Pilsen Academy **Unit** 31141 **Building ID** 4210
Address 1420 W. 17th St. **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
73	
74	
75	
76	
77	
78	Material not observed - 2025
79	Material not observed - 2025
80	Material not observed - 2025
81	Material not observed - 2025
82	
83	Material not observed - 2025
84	
85	Not observed in 208
86	Not observed in 208
87	Material not observed - 2025
88	Material not observed - 2025
89	Material not observed - 2025
90	Material not observed - 2025
91	Material not observed - 2025
92	
93	Material not observed - 2025
94	Material not observed - 2025
A1	
A2	
B	
C	Material not observed - 2025
D	Damage in: Boiler room
E	
F	

Chicago Public Schools

School Pilsen Academy **Unit** 31141 **Building ID** 4210
Address 1420 W. 17th St. **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
G	
H	
I	
J	Damage in: Boiler room
K	
L	

Table II
Management Planner's Review

Chicago Public Schools

School Pilsen Academy

Unit 31141

Building ID 4210

Address 1420 W. 17th St.

Chicago, IL, 60608

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	Plaster			Throughout Main Building	No ACBM	SURFACE					
02	2' x 4' Ceiling Panels	7,000	SF	Throughout Main Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
03A	12" x 12" Rust Floor Tile	5,000	SF	Rooms 101, 108, 201, 202, 208, 209, Lunchroom #3, Womens Ground Floor Bathroom, 1st Floor Teachers' Lounge	Assumed	MISC	No	91	SF	5 ACBM with potential for significant damage	Repair
03B	12" x 12" Green Floor Tile	5,000	SF	Rooms 203, 205-207, 208, 202	Assumed	MISC	No	65	SF	5 ACBM with potential for significant damage	Repair
03C	12" x 12" Beige Floor Tile	4,150	SF	Lunchroom #1, Stage, Rooms 307, 308, 201, 120, 206, Office, Conference Room, 103, 108	Assumed	MISC	No	23	SF	5 ACBM with potential for significant damage	Follow O&M Plan
03D	12" x 12" Light Brown Floor Tile	2,500	SF	Lunchrooms # 1&2, Kitchen, Room 120, All Purpose Room	Chrysotile	MISC	No	10	SF	5 ACBM with potential for significant damage	Repair
03E	12" x 12" Tan Floor Tile w/ Brown Streaks	2,000	SF	Lunchroom 1	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
03F	12" x 12" Brown Floor Tile			Rooms 203, 204, Hallways and Storage	Assumed	MISC					
03G	12" x 12" Light Brown Floor Tile	500	SF	Hallways, 2nd Floor Mens Bathrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
03H	12" x 12" Beige Floor Tile	600	SF	Stage	Assumed	MISC	No	10	SF	5 ACBM with potential for significant damage	Repair
03I	12" x 12" Off-White Floor Tile	600	SF	All Purpose Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
03J	12" x 12" Tan Floor Tile	300	SF	All Purpose room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
04	9" x 9" Floor Tile			None Found	Assumed	MISC					
05	1' x 1' Ceiling Tile			Room 11, 110, 111, Office, Nurse's Room and Hallways	No ACBM	MISC					
06	Wrap Around Cardboard Pipe Insulation			Boiler Room, Boiler Room Storage Area	Chrysotile	TSI					
07	12" x 12" Rust Floor Tile Mastic	5,000	SF	Rooms 101, 108, 201, 202, 208, 209, Lunchroom #3, Womens Ground Floor Bathroom, 1st Floor Teachers' Lounge	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
08	12" x 12" Green Floor Tile Mastic	5,000	SF	Rooms 203, 205-207, 208, 202	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
09	12" x 12" Beige Floor Tile Mastic	3,000	SF	Lunchroom #1, Stage, Rooms 307, 308, 201, 120, Office, Conference, 103, 108	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
10	12" x 12" Light Brown Floor Tile Mastic	3,000	SF	Lunchrooms #1&2, Room 120, Kitchen	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
11	12" x 12" Tan Floor Tile Mastic	2,000	SF	Lunchroom #1	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
12	12" x 12" Brown Floor Tile Mastic			Rooms 203, 214, Hallways and Storage	Chrysotile	MISC					
13	12" x 12" Light Brown Floor Tile Mastic	200	SF	Hallways, 2nd Floor Mens Bathrooms	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
14	12" x 12" Beige Floor Tile Mastic			Modular Building - DEMOLISHED	Assumed	MISC					

Chicago Public Schools

School Pilsen Academy

Unit 31141

Building ID 4210

Address 1420 W. 17th St.

Chicago, IL, 60608

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
15	12" x 12" Off-White Floor Tile Mastic			Modular Building - DEMOLISHED	Chrysotile	MISC					
16	12" x 12" Tan Floor Tile Mastic			Modular Building - DEMOLISHED	Chrysotile	MISC					
17	Interior Brick			Throughout Main Building	No ACBM	MISC					
18	Interior Brick Mortar			Throughout Main Building	No ACBM	MISC					
19	Cinder Block Mortar			Throughout Ground Floor of Main Building	No ACBM	MISC					
20	Insulation on Walls			Boiler Storage Room (Previously Weight Room)	No ACBM	TSI					
21	Chalk Boards			Throughout Main Building	No ACBM	MISC					
22	Slate Beneath Chalk Boards			Throughout Main Building	No ACBM	MISC					
23	Terrazzo Flooring			Stairwells At Entrances	No ACBM	MISC					
24	Multi-Blue Ceramic Tile Grout			Boys Bathroom	No ACBM	MISC					
25	Ceramic Tile Grout	168	SF	Mens Ground Floor Bathroom, 1st Floor Teachers' Bathroom 3rd Floor Boys Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Yellow and Gray Ceramic Tile Grout			Girls Bathrooms	No ACBM	MISC					
26A	Brown Ceramic Tile Grout			Girls Bathroom	No ACBM	MISC					
27	Vibration Collar	2	SF	Lunchroom # 1	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Beige Ceramic Tile Grout			Modular Building - DEMOLISHED	Assumed	MISC					
29	4" Black Baseboards			Throughout Main Building	No ACBM	MISC					
30	4" Black Baseboard Mastic			Throughout Main Building	No ACBM	MISC					
31	Non-Skid Strips			Boiler Room Ramp, Hall by 119 Stair Landings	No ACBM	MISC					
32	Drywall			Throughout Main Building Ground Floor	No ACBM	MISC					
33	Wall Panels	1,000	SF	Throughout Main Building - Electrical Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
34	Floor Leveler	2,000	SF	Lunchroom #1	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
35	6" Baseboard			Lunchroom #1, Assistant Principle Office, Library, Girls Bathroom	No ACBM	MISC					
36	6" Baseboard Mastic			Lunchroom #1, Assistant Principle Office, Library, Girls Bathroom	No ACBM	MISC					
37	Red Caulk Around Pipes			Assistant Principles Office	No ACBM	MISC					
38	4" Black Baseboard			Modular Building - DEMOLISHED	No ACBM	MISC					
39	4" Black Baseboard Mastic			Modular Building - DEMOLISHED	No ACBM	MISC					
40	Drywall Joint Compound			Modular Building - DEMOLISHED	No ACBM	MISC					

Chicago Public Schools

School Pilsen Academy

Unit 31141

Building ID 4210

Address 1420 W. 17th St.

Chicago, IL, 60608

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
41	Brown Carpet Mastic			Modular Building - DEMOLISHED	No ACBM	MISC					
42	Drywall			Modular Building - DEMOLISHED	No ACBM	MISC					
43	Blue Carpet Mastic			Rooms 028, 029	No ACBM	MISC					
44	Blue/Gray Carpet Mastic			Rooms 013, 110, 111	No ACBM	MISC					
45	Red Flooring			Modular Building - DEMOLISHED	No ACBM	MISC					
46	Red Flooring Mastic			Modular Building - DEMOLISHED	No ACBM	MISC					
48	Blue Carpet Mastic			Room 115, 205, 209	Assumed	MISC					
49	Carpet Mastic			Computer Lab, B02	Assumed	MISC					
50	Carpet Mastic			Office	Assumed	MISC					
51	Carpet Mastic			Room 105	Assumed	MISC					
52	Carpet Mastic			Modular Building - DEMOLISHED	Assumed	MISC					
53	Fire Doors	20		Throughout Facility	Assumed	TSI	Yes			7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
54	Boiler Gaskets	20	LF	Boiler Room	Assumed	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
55	Exterior Block			Main Building	No ACBM	MISC					
56	Exterior Block Mortar			Main Building	No ACBM	MISC					
57	Carpet Mastic			Modular Building - DEMOLISHED	Assumed	MISC					
58	12" x 12" White w/ Gray Floor Tile	2,025	SF	Rooms 106 & 206, Lunchroom, 302, Gym Stage, 208, 202, 101	Assumed	MISC	No	35	SF	5 ACBM with potential for significant damage	Follow O&M Plan
59	12" x 12" White w/ Gray Floor Tile Mastic	2,025	SF	Rooms 106 & 206, Lunchroom, 302, Gym Stage, 208, 202, 101	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
60	Plastic Wall Laminate Mastic	1,260	SF	Lunchrooms and Kitchen	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
61	Chalk Board/Poster Board Adhesive	1,100	SF	Throughout Classrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
62	Transom and Interior Window Glazing	250	SF	Classroom and Office Entry Doors	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
63	Skylight Caulk/Glazing			1st Floor by Office	Assumed	MISC					
64	Plastic Wall Laminate Adhesive			Modular Building - DEMOLISHED	Assumed	MISC					
65	Chalk Board/Poster Board Adhesive			Modular Building - DEMOLISHED	Assumed	MISC					
66	12" x 12" Tan w/ Specks Floor Tile	975	SF	Rooms 115, 113, 110, 111, 204, 2nd Floor Corridor Patch, 201, 202	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
66M	12" x 12" Tan w/ Specks Floor Tile Mastic	975	SF	R115, 113, 110, 111, 204, 2nd Floor Corridor Patch, 201, 202	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
67	White w/ Blue Streaks 12" x 12" Vinyl Floor Tile	5,000	SF	Lunchroom 1 and 2, Basement Corridor	Assumed	MISC	No	20	SF	5 ACBM with potential for significant damage	Follow O&M Plan
68	White w/ Blue Streaks 12" x 12" Vinyl Floor Tile	5,000	SF	Lunchroom 1 and 2, Basement Corridor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Pilsen Academy

Unit 31141

Building ID 4210

Address 1420 W. 17th St.

Chicago, IL, 60608

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	Mastic										
69	Red 12" x 12" Vinyl Floor Tile	5,000	SF	Lunchroom 1 and 2, Basement Corridor, Room 202	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
70	Red 12" x 12" Vinyl Floor Tile Mastic	5,000	SF	Lunchroom 1 and 2, Basement Corridor, Room 202	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
71	Green 12" x 12" Vinyl Floor Tile	5,000	SF	Lunchroom 1 and 2, Basement Corridor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
72	Green 12" x 12" Vinyl Floor Tile Mastic	5,000	SF	Lunchroom 1 and 2, Basement Corridor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
73	Yellow 12" x 12" Vinyl Floor Tile	5,000	SF	Lunchroom 1 and 2, Basement Corridor, Room 202	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
74	Yellow 12" x 12" Vinyl Floor Tile Mastic	5,000	SF	Lunchroom 1 and 2, Basement Corridor, Rooms 202	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
75	Blue 12" x 12" Vinyl Floor Tile	5,000	SF	Lunchroom 1 and 2, Basement Corridor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
76	Blue 12" x 12" Vinyl Floor Tile Mastic	5,000	SF	Lunchroom 1 and 2, Basement Corridor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
77	2' x 2' Ceiling Tiles	5,000	SF	Basement Kitchen	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
78	White Siuk Insulation			Room 120	Assumed	MISC					
79	Green Terazzo			Kitchen	Assumed	MISC					
80	Blue Carpet Mastic			Modular Building - DEMOLISHED	Assumed	MISC					
81	Blue Carpet Mastic			Room 302	Assumed	MISC					
82	Acoustical Plaster - Walls and Ceiling	200	SF	Basement - Kitchen Staff Locker Room and Bathroom	Assumed	SURFACE	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
83	1' x 1' Fissure Ceiling Tile			Modular Building - DEMOLISHED	Assumed	MISC					
84	Tongue and Groove Wooden Floor	800	SF	Rooms 301, 304, Gym, 306, 204, 102, 104, 105, 119	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
85	12" x 12" Mint Green Replacement Floor Tile	5	SF	Room 203	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
86	12" x 12" Mint Green Replacement Floor Tile Mastic	5	SF	Room 203	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
87	12" x 12" Dark Brown Floor Tile			Rooms 208, 209, 108	Assumed	MISC					
88	12" x 12" Dark Brown Floor Tile Mastic			Rooms 208, 209, 108	Assumed	MISC					
89	12" x 12" Rose Gold Replacement Floor Tile			Room 201	Assumed	MISC					
90	12" x 12" Rose Gold Replacement Floor Tile Mastic			Room 201	Assumed	MISC					
91	12" x 12" Light Brown w/ Dark Brown/White Specks Replacement Floor Tile			Room 201	Assumed	MISC					
92	12" x 12" Light Brown w/ Dark Brown/White Specks Replacement Floor Tile Mastic	5	SF	Room 201	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Pilsen Academy

Unit 31141

Building ID 4210

Address 1420 W. 17th St.

Chicago, IL, 60608

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
93	12" x 12" Light Blue Floor Tile			Room 202	Assumed	MISC					
94	12" x 12" Light Blue Floor Tile Mastic			Room 202	Assumed	MISC					
A1	#1 Boiler Insulation	325	SF	Boiler Room	Chrysotile	TSI	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
A2	#2 Boiler Insulation	325	SF	Boiler Room	Chrysotile	TSI	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
B	Boiler Packing	12	SF	Boilers	Assumed	TSI	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
C	Tank Insulation			Basement Tank Room	Assumed	TSI					
D	Mag Block Pipe Insulation	20	SF	Boiler Room	Chrysotile	TSI	Yes	10	SF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove
E	Cardboard Pipe Insulation	500	SF	Tank Room, Boiler Room and Lunchroom #3	Chrysotile	TSI	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	Aircell Pipe Insulation	450	LF	Mechanical Areas and Room 120	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
G	Fiberglass Pipe Insulation			Throughout Ground Floor	No ACBM	TSI					
H	Number Skipped				Undefined						
I	Joint Insulation on Fiberglass Pipe Insulation	125	LF	Throughout Ground Floor, Room 101 Bathroom	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
J	Mag Block Pipe Insulation Joints	20	LF	Boiler Room	Assumed	TSI	Yes	10	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove
K	Joint Insulation on Cardboard Pipe Insulation	210	LF	Throughout Ground Floor	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
L	Joint Insulation on Aircell Pipe Insulation	200	LF	Boiler Room, Throughout the Ground Floor	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Chicago Public Schools

School Pilsen Academy

Unit 31141

Building ID 4210

Address 1420 W. 17th St.

Chicago, IL, 60608

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	4/29/2025
Manager Planner Name	Jackson Montgomery
100-20634	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
03A	Remove or repair to intact.
03B	Remove or repair to intact.
03C	Remove or repair to intact.
03D	Remove or repair to intact.
03E	
03F	
03G	
03H	Remove or repair to intact.
03I	
03J	
04	

Chicago Public Schools

School Pilsen Academy

Unit 31141

Building ID 4210

Address 1420 W. 17th St.

Chicago, IL, 60608

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
05	
06	
07	
08	
09	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
26A	
27	
28	
29	
30	

Chicago Public Schools

School Pilsen Academy

Unit 31141

Building ID 4210

Address 1420 W. 17th St.

Chicago, IL, 60608

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	Remove or repair to intact.

Chicago Public Schools

School Pilsen Academy

Unit 31141

Building ID 4210

Address 1420 W. 17th St.

Chicago, IL, 60608

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
59	
60	
61	
62	
63	
64	
65	
66	
66M	
67	Remove or repair to intact.
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
80	
81	
82	
83	
84	

Chicago Public Schools

School Pilsen Academy

Unit 31141

Building ID 4210

Address 1420 W. 17th St.

Chicago, IL, 60608

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
85	
86	
87	
88	
89	
90	
91	
92	
93	
94	
A1	
A2	
B	
C	
D	Remove or repair damaged TSI to intact.
E	
F	
G	
H	
I	
J	Remove or repair damaged TSI to intact.
K	
L	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 01
MATERIAL DESCRIPTION: Plaster
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Main Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout Main Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	02		
MATERIAL DESCRIPTION:	2' x 4' Ceiling Panels		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Main Building		
MATERIAL QUANTITY:	7000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **02**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Panels**

MATERIAL LOCATION: **Throughout Main Building**

MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03A		
MATERIAL DESCRIPTION:	12" x 12" Rust Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Deterioration		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 5. ACBM with potential for significant damage

DAMAGE REASON:	Deterioration		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 101, 108, 201, 202, 208, 209, Lunchroom #3, Womens Ground Floor Bathroom, 1st Floor Teachers' Lounge		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in Lunchroom office		

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA:	03A				
MATERIAL DESCRIPTION:	12" x 12" Rust Floor Tile				
MATERIAL LOCATION:	Rooms 101, 108, 201, 202, 208, 209, Lunchroom #3, Womens Ground Floor Bathroom, 1st Floor Teachers' Lounge				
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	91	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

Repair

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03B		
MATERIAL DESCRIPTION:	12" x 12" Green Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Deterioration		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	Deterioration		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 203, 205-207, 208, 202		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in Room 203		

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **03B**

MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile**

MATERIAL LOCATION: **Rooms 203, 205-207, 208, 202**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **65** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03C		
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Deterioration		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	Deterioration		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom #1, Stage, Rooms 307, 308, 201, 120, 206, Office, Conference Room, 103, 108		
MATERIAL QUANTITY:	4150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in Lunchroom/kitchen		

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **03C**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**

MATERIAL LOCATION: **Lunchroom #1, Stage, Rooms 307, 308, 201, 120, 206, Office, Conference Room, 103, 108**

MATERIAL QUANTITY: **4150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **23** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03D		
MATERIAL DESCRIPTION:	12" x 12" Light Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 5. ACBM with potential for significant damage

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchrooms # 1&2, Kitchen, Room 120, All Purpose Room		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in Kitchen		

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **03D**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile**

MATERIAL LOCATION: **Lunchrooms # 1&2, Kitchen, Room 120, All Purpose Room**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03E		
MATERIAL DESCRIPTION:	12" x 12" Tan Floor Tile w/ Brown Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom 1		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **03E**

MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile w/ Brown Streaks**

MATERIAL LOCATION: **Lunchroom 1**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03F		
MATERIAL DESCRIPTION:	12" x 12" Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 203, 204, Hallways and Storage**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **03F**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**

MATERIAL LOCATION: **Rooms 203, 204, Hallways and Storage**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03G		
MATERIAL DESCRIPTION:	12" x 12" Light Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallways, 2nd Floor Mens Bathrooms		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not observed in 207		

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **03G**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile**

MATERIAL LOCATION: **Hallways, 2nd Floor Mens Bathrooms**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03H		
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Stage		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:	Damage on Stage steps		

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **03H**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**

MATERIAL LOCATION: **Stage**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03I		
MATERIAL DESCRIPTION:	12" x 12" Off-White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	All Purpose Room		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	No modular building		

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **03I**

MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile**

MATERIAL LOCATION: **All Purpose Room**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03J		
MATERIAL DESCRIPTION:	12" x 12" Tan Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	All Purpose room		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:	No modular building		

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **03J**

MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile**

MATERIAL LOCATION: **All Purpose room**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 04
MATERIAL DESCRIPTION: 9" x 9" Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: None Found

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **9" x 9" Floor Tile**

MATERIAL LOCATION: **None Found**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 11, 110, 111, Office, Nurse's Room and Hallways**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**

MATERIAL LOCATION: **Room 11, 110, 111, Office, Nurse's Room and Hallways**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06		
MATERIAL DESCRIPTION:	Wrap Around Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room, Boiler Room Storage Area

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **Wrap Around Cardboard Pipe Insulation**

MATERIAL LOCATION: **Boiler Room, Boiler Room Storage Area**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07		
MATERIAL DESCRIPTION:	12" x 12" Rust Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 101, 108, 201, 202, 208, 209, Lunchroom #3, Womens Ground Floor Bathroom, 1st Floor Teachers' Lounge**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **07**

MATERIAL DESCRIPTION: **12" x 12" Rust Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 101, 108, 201, 202, 208, 209, Lunchroom #3, Womens Ground Floor Bathroom, 1st Floor Teachers' Lounge**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08		
MATERIAL DESCRIPTION:	12" x 12" Green Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 203, 205-207, 208, 202		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 203, 205-207, 208, 202**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09		
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom #1, Stage, Rooms 307, 308, 201, 120, Office, Conference, 103, 108		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom #1, Stage, Rooms 307, 308, 201, 120, Office, Conference, 103, 108**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	12" x 12" Light Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchrooms #1&2, Room 120, Kitchen		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile Mastic**

MATERIAL LOCATION: **Lunchrooms #1&2, Room 120, Kitchen**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	12" x 12" Tan Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom #1		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom #1**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12	
MATERIAL DESCRIPTION:	12" x 12" Brown Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 203, 214, Hallways and Storage

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 203, 214, Hallways and Storage**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	12" x 12" Light Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallways, 2nd Floor Mens Bathrooms		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not observed in 207 and 208		

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile Mastic**

MATERIAL LOCATION: **Hallways, 2nd Floor Mens Bathrooms**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 14

MATERIAL DESCRIPTION: 12" x 12" Beige Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Modular Building - DEMOLISHED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**

MATERIAL LOCATION: **Modular Building - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15	
MATERIAL DESCRIPTION:	12" x 12" Off-White Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Modular Building - DEMOLISHED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile Mastic**

MATERIAL LOCATION: **Modular Building - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Modular Building - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile Mastic**

MATERIAL LOCATION: **Modular Building - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Interior Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Main Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Interior Brick**

MATERIAL LOCATION: **Throughout Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Interior Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Main Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **Throughout Main Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Ground Floor of Main Building**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

MATERIAL LOCATION: **Throughout Ground Floor of Main Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Insulation on Walls**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Storage Room (Previously Weight Room)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Insulation on Walls**

MATERIAL LOCATION: **Boiler Storage Room (Previously Weight Room)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Chalk Boards**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Main Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Chalk Boards**

MATERIAL LOCATION: **Throughout Main Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 22
MATERIAL DESCRIPTION: Slate Beneath Chalk Boards
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Main Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Slate Beneath Chalk Boards**

MATERIAL LOCATION: **Throughout Main Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 23
MATERIAL DESCRIPTION: Terrazzo Flooring
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Stairwells At Entrances

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Terrazzo Flooring**

MATERIAL LOCATION: **Stairwells At Entrances**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 24
MATERIAL DESCRIPTION: Multi-Blue Ceramic Tile Grout
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boys Bathroom

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Multi-Blue Ceramic Tile Grout**

MATERIAL LOCATION: **Boys Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	Ceramic Tile Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Mens Ground Floor Bathroom, 1st Floor Teachers' Bathroom 3rd Floor Boys Bathroom		
MATERIAL QUANTITY:	168	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Ceramic Tile Grout**

MATERIAL LOCATION: **Mens Ground Floor Bathroom, 1st Floor Teachers' Bathroom 3rd Floor Boys Bathroom**

MATERIAL QUANTITY: **168** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Yellow and Gray Ceramic Tile Grout**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Girls Bathrooms**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Yellow and Gray Ceramic Tile Grout**

MATERIAL LOCATION: **Girls Bathrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26A**

MATERIAL DESCRIPTION: **Brown Ceramic Tile Grout**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Girls Bathroom**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **26A**

MATERIAL DESCRIPTION: **Brown Ceramic Tile Grout**

MATERIAL LOCATION: **Girls Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	Vibration Collar		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom # 1		
MATERIAL QUANTITY:	2	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Vibration Collar**

MATERIAL LOCATION: **Lunchroom # 1**

MATERIAL QUANTITY: **2** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28	
MATERIAL DESCRIPTION:	Beige Ceramic Tile Grout	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Modular Building - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Beige Ceramic Tile Grout**

MATERIAL LOCATION: **Modular Building - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **4" Black Baseboards**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Main Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **4" Black Baseboards**

MATERIAL LOCATION: **Throughout Main Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 30
MATERIAL DESCRIPTION: 4" Black Baseboard Mastic
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Main Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **4" Black Baseboard Mastic**

MATERIAL LOCATION: **Throughout Main Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 31
MATERIAL DESCRIPTION: Non-Skid Strips
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room Ramp, Hall by 119 Stair Landings

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Non-Skid Strips**

MATERIAL LOCATION: **Boiler Room Ramp, Hall by 119 Stair Landings**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Main Building Ground Floor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Throughout Main Building Ground Floor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	Wall Panels		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Main Building - Electrical Room		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Wall Panels**

MATERIAL LOCATION: **Throughout Main Building - Electrical Room**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	Floor Leveler		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom #1		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Floor Leveler**

MATERIAL LOCATION: **Lunchroom #1**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 35
MATERIAL DESCRIPTION: 6" Baseboard
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Lunchroom #1, Assistant Principle Office, Library, Girls Bathroom

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **6" Baseboard**

MATERIAL LOCATION: **Lunchroom #1, Assistant Principle Office, Library, Girls Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **6" Baseboard Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom #1, Assistant Principle Office, Library, Girls Bathroom**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **6" Baseboard Mastic**

MATERIAL LOCATION: **Lunchroom #1, Assistant Principle Office, Library, Girls Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 37
MATERIAL DESCRIPTION: Red Caulk Around Pipes
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Assistant Principles Office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Red Caulk Around Pipes**

MATERIAL LOCATION: **Assistant Principles Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 38
MATERIAL DESCRIPTION: 4" Black Baseboard
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Modular Building - DEMOLISHED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **4" Black Baseboard**

MATERIAL LOCATION: **Modular Building - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 39
MATERIAL DESCRIPTION: 4" Black Baseboard Mastic
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Modular Building - DEMOLISHED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **4" Black Baseboard Mastic**

MATERIAL LOCATION: **Modular Building - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 40
MATERIAL DESCRIPTION: Drywall Joint Compound
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Modular Building - DEMOLISHED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Drywall Joint Compound**

MATERIAL LOCATION: **Modular Building - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 41
MATERIAL DESCRIPTION: Brown Carpet Mastic
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Modular Building - DEMOLISHED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Brown Carpet Mastic**

MATERIAL LOCATION: **Modular Building - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Modular Building - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Modular Building - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 028, 029**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Blue Carpet Mastic**

MATERIAL LOCATION: **Rooms 028, 029**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 44
MATERIAL DESCRIPTION: Blue/Gray Carpet Mastic
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 013, 110, 111

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Blue/Gray Carpet Mastic**

MATERIAL LOCATION: **Rooms 013, 110, 111**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 45
MATERIAL DESCRIPTION: Red Flooring
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Modular Building - DEMOLISHED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Red Flooring**

MATERIAL LOCATION: **Modular Building - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 46
MATERIAL DESCRIPTION: Red Flooring Mastic
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Modular Building - DEMOLISHED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Red Flooring Mastic**

MATERIAL LOCATION: **Modular Building - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 48
MATERIAL DESCRIPTION: Blue Carpet Mastic
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 115, 205, 209

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Blue Carpet Mastic**

MATERIAL LOCATION: **Room 115, 205, 209**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 49

MATERIAL DESCRIPTION: Carpet Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Computer Lab, B02

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Computer Lab, B02**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 50

MATERIAL DESCRIPTION: Carpet Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Carpet Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 105**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Room 105**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **Carpet Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Modular Building - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Modular Building - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	Fire Doors		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **20** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **Fire Doors**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **20**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	Boiler Gaskets		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Boiler Gaskets**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Exterior Block**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Exterior Block**

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Exterior Block Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **Exterior Block Mortar**

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **Carpet Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Modular Building - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Modular Building - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	12" x 12" White w/ Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 106 & 206, Lunchroom, 302, Gym Stage, 208, 202, 101		
MATERIAL QUANTITY:	2025	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage from deterioration throughout lunchrooms and Room 206		

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Floor Tile**

MATERIAL LOCATION: **Rooms 106 & 206, Lunchroom, 302, Gym Stage, 208, 202, 101**

MATERIAL QUANTITY: **2025** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **35** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	59		
MATERIAL DESCRIPTION:	12" x 12" White w/ Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 106 & 206, Lunchroom, 302, Gym Stage, 208, 202, 101		
MATERIAL QUANTITY:	2025	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 106 & 206, Lunchroom, 302, Gym Stage, 208, 202, 101**

MATERIAL QUANTITY: **2025** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	60		
MATERIAL DESCRIPTION:	Plastic Wall Laminate Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchrooms and Kitchen		
MATERIAL QUANTITY:	1260	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **Plastic Wall Laminate Mastic**

MATERIAL LOCATION: **Lunchrooms and Kitchen**

MATERIAL QUANTITY: **1260** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	61		
MATERIAL DESCRIPTION:	Chalk Board/Poster Board Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Classrooms		
MATERIAL QUANTITY:	1100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **Chalk Board/Poster Board Adhesive**

MATERIAL LOCATION: **Throughout Classrooms**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	62		
MATERIAL DESCRIPTION:	Transom and Interior Window Glazing		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classroom and Office Entry Doors		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Transom and Interior Window Glazing**

MATERIAL LOCATION: **Classroom and Office Entry Doors**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	63	
MATERIAL DESCRIPTION:	Skylight Caulk/Glazing	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor by Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **Skylight Caulk/Glazing**

MATERIAL LOCATION: **1st Floor by Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 64
MATERIAL DESCRIPTION: Plastic Wall Laminate Adhesive
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Modular Building - DEMOLISHED

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **Plastic Wall Laminate Adhesive**

MATERIAL LOCATION: **Modular Building - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **Chalk Board/Poster Board Adhesive**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Modular Building - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **Chalk Board/Poster Board Adhesive**

MATERIAL LOCATION: **Modular Building - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	66		
MATERIAL DESCRIPTION:	12" x 12" Tan w/ Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	HIGH		
MATERIAL LOCATION:	Rooms 115, 113, 110, 111, 204, 2nd Floor Corridor Patch, 201, 202		
MATERIAL QUANTITY:	975	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not observed in room 101, 208		

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **12" x 12" Tan w/ Specks Floor Tile**

MATERIAL LOCATION: **Rooms 115, 113, 110, 111, 204, 2nd Floor Corridor Patch, 201, 202**

MATERIAL QUANTITY: **975** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	66M		
MATERIAL DESCRIPTION:	12" x 12" Tan w/ Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	HIGH		
MATERIAL LOCATION:	R115, 113, 110, 111, 204, 2nd Floor Corridor Patch, 201, 202		
MATERIAL QUANTITY:	975	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	DAMAGE UNITS: SF		
COMMENTS:	Not observed in 101 and 208		

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **66M**

MATERIAL DESCRIPTION: **12" x 12" Tan w/ Specks Floor Tile Mastic**

MATERIAL LOCATION: **R115, 113, 110, 111, 204, 2nd Floor Corridor Patch, 201, 202**

MATERIAL QUANTITY: **975** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	67		
MATERIAL DESCRIPTION:	White w/ Blue Streaks 12" x 12" Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom 1 and 2, Basement Corridor		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in Lunchroom 2		

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **White w/ Blue Streaks 12" x 12" Vinyl Floor Tile**

MATERIAL LOCATION: **Lunchroom 1 and 2, Basement Corridor**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	68		
MATERIAL DESCRIPTION:	White w/ Blue Streaks 12" x 12" Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom 1 and 2, Basement Corridor		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **White w/ Blue Streaks 12" x 12" Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom 1 and 2, Basement Corridor**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	69		
MATERIAL DESCRIPTION:	Red 12" x 12" Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom 1 and 2, Basement Corridor, Room 202		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **Red 12" x 12" Vinyl Floor Tile**

MATERIAL LOCATION: **Lunchroom 1 and 2, Basement Corridor, Room 202**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	70		
MATERIAL DESCRIPTION:	Red 12" x 12" Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom 1 and 2, Basement Corridor, Room 202		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **Red 12" x 12" Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom 1 and 2, Basement Corridor, Room 202**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	71		
MATERIAL DESCRIPTION:	Green 12" x 12" Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom 1 and 2, Basement Corridor		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **Green 12" x 12" Vinyl Floor Tile**

MATERIAL LOCATION: **Lunchroom 1 and 2, Basement Corridor**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	72		
MATERIAL DESCRIPTION:	Green 12" x 12" Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom 1 and 2, Basement Corridor		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **Green 12" x 12" Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom 1 and 2, Basement Corridor**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	73		
MATERIAL DESCRIPTION:	Yellow 12" x 12" Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom 1 and 2, Basement Corridor, Room 202		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **Yellow 12" x 12" Vinyl Floor Tile**

MATERIAL LOCATION: **Lunchroom 1 and 2, Basement Corridor, Room 202**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	74		
MATERIAL DESCRIPTION:	Yellow 12" x 12" Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom 1 and 2, Basement Corridor, Rooms 202		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **Yellow 12" x 12" Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom 1 and 2, Basement Corridor, Rooms 202**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	75		
MATERIAL DESCRIPTION:	Blue 12" x 12" Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom 1 and 2, Basement Corridor		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **Blue 12" x 12" Vinyl Floor Tile**

MATERIAL LOCATION: **Lunchroom 1 and 2, Basement Corridor**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	76		
MATERIAL DESCRIPTION:	Blue 12" x 12" Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom 1 and 2, Basement Corridor		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **Blue 12" x 12" Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom 1 and 2, Basement Corridor**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	77		
MATERIAL DESCRIPTION:	2' x 2' Ceiling Tiles		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement Kitchen		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **2' x 2' Ceiling Tiles**

MATERIAL LOCATION: **Basement Kitchen**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	78	
MATERIAL DESCRIPTION:	White Siuk Insulation	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 120**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **White Siuk Insulation**

MATERIAL LOCATION: **Room 120**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	79	
MATERIAL DESCRIPTION:	Green Terazzo	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **Green Terazzo**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 80
MATERIAL DESCRIPTION: Blue Carpet Mastic
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Modular Building - DEMOLISHED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **Blue Carpet Mastic**

MATERIAL LOCATION: **Modular Building - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 81
MATERIAL DESCRIPTION: Blue Carpet Mastic
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 302

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **Blue Carpet Mastic**

MATERIAL LOCATION: **Room 302**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	82		
MATERIAL DESCRIPTION:	Acoustical Plaster - Walls and Ceiling		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement - Kitchen Staff Locker Room and Bathroom		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **Acoustical Plaster - Walls and Ceiling**

MATERIAL LOCATION: **Basement - Kitchen Staff Locker Room and Bathroom**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 83
MATERIAL DESCRIPTION: 1' x 1' Fissure Ceiling Tile
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Modular Building - DEMOLISHED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **1' x 1' Fissure Ceiling Tile**

MATERIAL LOCATION: **Modular Building - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	84		
MATERIAL DESCRIPTION:	Tongue and Groove Wooden Floor		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 301, 304, Gym, 306, 204, 102, 104, 105, 119		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **Tongue and Groove Wooden Floor**

MATERIAL LOCATION: **Rooms 301, 304, Gym, 306, 204, 102, 104, 105, 119**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	85		
MATERIAL DESCRIPTION:	12" x 12" Mint Green Replacement Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 203		
MATERIAL QUANTITY:	5	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not observed in 208		

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **85**

MATERIAL DESCRIPTION: **12" x 12" Mint Green Replacement Floor Tile**

MATERIAL LOCATION: **Room 203**

MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	86		
MATERIAL DESCRIPTION:	12" x 12" Mint Green Replacement Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 203		
MATERIAL QUANTITY:	5	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not observed in 208		

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **86**

MATERIAL DESCRIPTION: **12" x 12" Mint Green Replacement Floor Tile Mastic**

MATERIAL LOCATION: **Room 203**

MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	87	
MATERIAL DESCRIPTION:	12" x 12" Dark Brown Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 208, 209, 108

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **87**

MATERIAL DESCRIPTION: **12" x 12" Dark Brown Floor Tile**

MATERIAL LOCATION: **Rooms 208, 209, 108**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	88	
MATERIAL DESCRIPTION:	12" x 12" Dark Brown Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 208, 209, 108**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **12" x 12" Dark Brown Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 208, 209, 108**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	89	
MATERIAL DESCRIPTION:	12" x 12" Rose Gold Replacement Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 201

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **89**

MATERIAL DESCRIPTION: **12" x 12" Rose Gold Replacement Floor Tile**

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	90	
MATERIAL DESCRIPTION:	12" x 12" Rose Gold Replacement Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **12" x 12" Rose Gold Replacement Floor Tile Mastic**

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	91		
MATERIAL DESCRIPTION:	12" x 12" Light Brown w/ Dark Brown/White Specks Replacement Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 201

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **91**

MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ Dark Brown/White Specks Replacement Floor Tile**

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	92		
MATERIAL DESCRIPTION:	12" x 12" Light Brown w/ Dark Brown/White Specks Replacement Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ Dark Brown/White Specks Replacement Floor Tile Mastic**

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	93	
MATERIAL DESCRIPTION:	12" x 12" Light Blue Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 202**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **93**

MATERIAL DESCRIPTION: **12" x 12" Light Blue Floor Tile**

MATERIAL LOCATION: **Room 202**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	94	
MATERIAL DESCRIPTION:	12" x 12" Light Blue Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with potential for significant damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 202**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **94**

MATERIAL DESCRIPTION: **12" x 12" Light Blue Floor Tile Mastic**

MATERIAL LOCATION: **Room 202**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A1		
MATERIAL DESCRIPTION:	#1 Boiler Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **325** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **A1**

MATERIAL DESCRIPTION: **#1 Boiler Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **325** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A2		
MATERIAL DESCRIPTION:	#2 Boiler Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	325	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **A2**

MATERIAL DESCRIPTION: **#2 Boiler Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **325** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	B		
MATERIAL DESCRIPTION:	Boiler Packing		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boilers		
MATERIAL QUANTITY:	12	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Boiler Packing**

MATERIAL LOCATION: **Boilers**

MATERIAL QUANTITY: **12** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	Tank Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Tank Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Tank Insulation**

MATERIAL LOCATION: **Basement Tank Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	Mag Block Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	1 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Remove		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	DAMAGE UNITS: SF		
COMMENTS:	Damage in: Boiler room		

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Remove or repair damaged TSI to intact.

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:	Physical Damage Vibration		
HISTORICAL RESPONSE ACTION:	Remove		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Tank Room, Boiler Room and Lunchroom #3**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **Tank Room, Boiler Room and Lunchroom #3**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Remove		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Mechanical Areas and Room 120**

MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Mechanical Areas and Room 120**

MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Ground Floor**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Throughout Ground Floor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Number Skipped**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Number Skipped**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	I		
MATERIAL DESCRIPTION:	Joint Insulation on Fiberglass Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Ground Floor, Room 101 Bathroom		
MATERIAL QUANTITY:	125	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Joint Insulation on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Throughout Ground Floor, Room 101 Bathroom**

MATERIAL QUANTITY: **125** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	J		
MATERIAL DESCRIPTION:	Mag Block Pipe Insulation Joints		
HISTORICAL AHERA DAMAGE CATEGORY	1 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:	Physical Damage Vibration		
HISTORICAL RESPONSE ACTION:	Remove		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:	Physical Damage Vibration		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	DAMAGE UNITS: LF		
COMMENTS:	Damage in: Boiler room		

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Mag Block Pipe Insulation Joints**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Remove or repair damaged TSI to intact.

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	K		
MATERIAL DESCRIPTION:	Joint Insulation on Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Ground Floor		
MATERIAL QUANTITY:	210	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Joint Insulation on Cardboard Pipe Insulation**

MATERIAL LOCATION: **Throughout Ground Floor**

MATERIAL QUANTITY: **210** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUILDING ID:	4210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Pilsen Academy	INSPECTION DATE:	4/8/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	L		
MATERIAL DESCRIPTION:	Joint Insulation on Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room, Throughout the Ground Floor		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31141	BUIDLING ID:	4210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Pilsen Academy	REVIEW DATE:	4/29/2025		
ADDRESS:	1420 W. 17th St.	IDPH LICENSE NO:	100-09969		

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Joint Insulation on Aircell Pipe Insulation**

MATERIAL LOCATION: **Boiler Room, Throughout the Ground Floor**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses



OCCUPATIONAL TRAINING & SUPPLY, INC. 2024
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

Asbestos Abatement Supervisor Refresher

Occupational Training & Supply, Inc. certifies that

Dionne L.C. Walker

has successfully completed the Asbestos Abatement Supervisor Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 10/14/2024

Exam Date: 10/14/2024

Expiration Date: 10/14/2025

Certificate Number: ASR2410142781

Course Credit Hours: ASR 8 Hours

Kristina Miczek

Kristina Miczek, Training Manager

Dionne Walker

Asbestos Project Manager, Illinois Licensed Building Inspector, Air Sampling Professional



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 09969

ISSUED
4/28/2025

EXPIRES
05/15/2026

DIONNE L CAREY WALKER
211 SOMERSET DRIVE
STREAMWOOD, IL 60107
Environmental Health



ENDORSEMENTS

INSPECTOR

TC EXPIRES

10/11/2025

PROJECT MANAGER
AIR SAMPLING PROFESSIONAL





10/14/2025

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



Jackson Montgomery

Illinois Licensed Building Inspector, Air Sampling Professional, Management Planner





2200 Vandalia Street, Collinsville, IL 62234 * Phone: 618-855-8764

Environmental and Occupational Safety & Health Training

Does hereby certify

Jackson Montgomery

600 W. Van Buren St., Suite 500, Chicago, IL 60607



*Has successfully completed and passed the course examination with at least
70% for accreditation under AHERA (Title II)*

Asbestos Management Planner Initial

Class Date: 10/28-29/2024

Examination Date: 10/29/2024

STC Certificate Number: STC-20241029-000101AMPI

Certification Expiration: 10/29/2025

A handwritten signature in black ink that reads 'David M. Mendoza'.

David M. Mendoza – President/Training Director

Certified Environmental Specialist

OSHA Authorized Instructor

This training course is accredited by the Illinois Department of Public Health and the Missouri Department of Natural Resources

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed