

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2392  
SCHOOL NAME: Parker Community Academy  
ADDRESS OF SCHOOL: 6800 S. Stewart  
CITY: Chicago, IL, 60621

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 8/26/2022

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II (Please type or print)**

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 5/7/2025 ENROLLMENT 341  
IDPH INSPECTOR LICENSE NUMBER: 100-21040  
IDPH LICENSED INSPECTOR NAME (Please Print): Josh Herman  
IDPH MP LICENSE NUMBER: 100-00349  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): James Tuinenga

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

*Richard J. Schleyer* 5/30/2025

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Parker Community Academy**

6800 S. Stewart  
Chicago, IL, 60621

Unit: 31181  
Building ID: 5270

IDPH ID Number: 14-016-2990-2392

**REPORT DATE:**  
Friday, May 30, 2025

**Prepared for:**  
**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**  
**TEM Environmental, Inc.**

174 N. Brandon Drive  
Glendale Heights, IL, 60139  
Phone 630-790-0880  
Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

05/29/2025

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299      Unit: 31181      Region: 05      IDPH ID: 14-016-2990-2392

School: Parker Community Academy      Building ID: 5270

Address: 6800 S. Stewart

Chicago, IL, 60621

Building Contact: Hernandez, David      Contact Phone: 7735109244

Current Building Owners: Chicago Public Schools

Reinspection Date: 5/7/2025

Review Date: 05/29/2025

Inspector: Josh Herman      Inspector IDPH License: 100-21040  
Management Planner: James Tuinenga      Management Planner IDPH License: 100-00349

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.



James Tuinenga  
100-00349

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: May 30, 2025

RE: Parker Community Academy, Unit 31181  
6800 S. Stewart  
Chicago, IL, 60621

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Parker Community Academy , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Parker Community Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Parker Community Academy  
Address: 6800 S. Stewart  
IDPH ID: 14-016-2990-2392  
Contact: Hernandez, David

Unit: 31181  
Chicago, IL, 60621  
Building ID: 5270  
Phone: 7735109244

Region: 05

### 2. Description of Facility

Original Construction: 1930  
Total Square Footage: 265000  
Current Occupancy: 341

Additional Construction:  
No of Floors: 4

### 3. LEA Designated Person

Contact: Richard J.Schleyer  
Address: 42 West Madison Street  
Chicago, IL 60602

Phone: (773) 251-7074

### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Phone: 630-790-0880

Fax: 630-790-0882

### 5. Inspector

Inspector Name: Josh Herman

Inspector IDPH license # 100-21040  
Reinspection Date: 5/7/2025

  
Signature:  
Date: 5/7/2025

### 6. Management Planner

Management Planner Name: James Tuinenga

Management Planner IDPH license # 100-00349

  
Signature:  
Date: 05/29/2025

### 7. Review Date: 05/29/2025

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

  
Signature:

Date: 5/30/2025

Name: Richard J.Schleyer



## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Parker Community Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5270:

50	12"x12" White w/Multicolor Specks Floor Tile
50M	Mastic associated w/12"x12" White w/Multicolored Specks Floor Tile
51	6"x6" Terracotta Tile Grout
52	1'x1' Pinhole Ceiling Tile
53	Black Chalkboards
54	Black Lab Countertops
55	Green Stage Curtains
NEW	Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 5270:

50	12"x12" White w/Multicolor Specks Floor Tile
50M	Mastic associated w/12"x12" White w/Multicolored Specks Floor Tile
51	6"x6" Terracotta Tile Grout
52	1'x1' Pinhole Ceiling Tile
53	Black Chalkboards
54	Black Lab Countertops
55	Green Stage Curtains

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

08A	12"x12" Cream & Brown Checkered Floor Tile
10	12x12 Orange Vinyl Floor Tile
11	12x12 Off-White w/Black Streaks Vinyl Floor Tile Mastic
11A	12x12 Off-White w/Black Streaks Vinyl Floor Tile Mastic
12	12x12 Beige Vinyl Floor Tlle
12A	12x12 Beige Vinyl Floor Tile Mastic
13A	12x12 Green Vinyl Floor Tile Mastic
14A	12x12 Blue Vinyl Floor Tile Mastic
15	12x12 Red Vinyl Floor Tile
16	12x12 Grey w/Black Streaks Vinyl Floor Tile
16A	12x12 Grey w/Black Streaks Vinyl Floor Tile Mastic
17A	12x12 Maroon Vinyl Floor Tile Mastic
18A	12x12 Black Vinyl Floor Tile Mastic
25	Grey Linoleum
25A	Grey Linoleum Mastic
26	Green Carpet Mastic NOT OBSERVED
27	Turquoise Carpet Mastic
28	Brown Carpet Mastic
29	2"x2" Ceramic Tile Grout
30	1"x1" Ceramic Tile Grout
31	Terrazzo Flooring
32	Brown Floor Covering
33	Brown Floor Covering
34	12x12 Tan w/White Streaks Vinyl Floor Tile
35	12X12 Off-White w/Tan Streaks Vinyl Floor Tile
36	12x12 Orange Vinyl Floor Tile
37	12x12 Red Vinyl Floor Tile
40	Black Baseboard
40A	Black Baseboard Mastic
42	Drywall
43	2x2 Ceramic Tile Grout
44	Firebrick
45A	9x9 Black Vinyl Floor Tile Mastic NOT OBSERVED
47	Fiberglass Joints
49	2'x4' Ceiling Tile
50	12"x12" White w/Multicolor Specks Floor Tile
50M	Mastic associated w/12"x12" White w/Multicolored Specks Floor Tile

51	6"x6" Terracotta Tile Grout
52	1'x1' Pinhole Ceiling Tile
53	Black Chalkboards
54	Black Lab Countertops
55	Green Stage Curtains
FT-1	12x12 White w/Blue Streaks Vinyl Floor Tile
FT-2	12x12 White w/Orange Floor Tile
FT-3	9"x9" Brown Floor Tile
FT-4	Blue Linoleum
FTM-1	12x12 White w/Blue Streaks Mastic
FTM-2	12x12 White w/Orange Floor Tile Mastic
FTM-3	9x9 Brown Floor Tile Mastic
NEW	Newly Installed Suspect ACM

The following areas were deemed to be inaccessible:

09	12x12 Cream Vinyl Floor Tile Mastic
10A	12x12 Orange Vinyl Floor Tile Mastic
11	12x12 Off-White w/Black Streaks Vinyl Floor Tile Mastic
11A	12x12 Off-White w/Black Streaks Vinyl Floor Tile Mastic
12A	12x12 Beige Vinyl Floor Tile Mastic
13A	12x12 Green Vinyl Floor Tile Mastic
14A	12x12 Blue Vinyl Floor Tile Mastic
15A	12x12 Red Vinyl Floor Tile Mastic
16A	12x12 Grey w/Black Streaks Vinyl Floor Tile Mastic
17A	12x12 Maroon Vinyl Floor Tile Mastic
18A	12x12 Black Vinyl Floor Tile Mastic
19	12x12 Tan w/Black Streaks Vinyl Floor Tile Mastic
23A	12x18 Black Edging Mastic NOT OBSERVED
25A	Grey Linoleum Mastic
26	Green Carpet Mastic NOT OBSERVED
27	Turquoise Carpet Mastic
28	Brown Carpet Mastic
29	2"x2" Ceramic Tile Grout
30	1"x1" Ceramic Tile Grout
34A	12x12 Tan w/White Streaks Vinyl Floor Tile Mastic
35A	12X12 Off-White w/Tan Streaks Vinyl Floor Tile Mastic
36A	12x12 Orange Vinyl Floor Tile Mastic
37A	12x12 Red Vinyl Floor Tile Mastic
38A	12x12 Off-White w/Brown Streaks Vinyl Floor Tile Mastic
40A	Black Baseboard Mastic

43	2x2 Ceramic Tile Grout
44	Firebrick
45A	9x9 Black Vinyl Floor Tile Mastic NOT OBSERVED
FTM-1	12x12 White w/Blue Streaks Mastic
FTM-2	12x12 White w/Orange Floor Tile Mastic
FTM-3	9x9 Brown Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Josh Herman, IDPH License # 100-21040. The Management Plan was updated by James Tuinenga, IDPH License # 100-00349. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Parker Community Academy Building 5270 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

**School** Parker Community Academy **Unit** 31181 **Building ID** 5270  
**Address** 6800 S. Stewart **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
08	12x12 Cream Vinyl Floor Tile	24,730	SF	Rooms 108, 110, 204, 205, 207, 209, 210, 218, 226, 230, 302, 304, 331, 328, 326, 324, 320, 314, 310, 306, 300A, 303 & 408	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08A	12"x12" Cream & Brown Checkered Floor Tile	2,620	SF	Rooms 117, 308, 330 & 409	ASSUMED	MISC	N	DIST	20		No	ACBM with the potential for damage	5	LOW
09	12x12 Cream Vinyl Floor Tile Mastic	22,330	SF	Rooms 108, 110, 204, 205, 207, 209, 210, 218, 226, 230, 331, 328, 326, 324, 320, 314, 310, 306, 300A, 303	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1	Plaster No ACBM			Throughout Building	NO_ACBM	SURFACE					No			
10	12x12 Orange Vinyl Floor Tile	15,690	SF	3rd Floor Corridors, Cafeteria & Lunchroom, Teachers' Lunchroom, Manager's Office, Music Room	ASSUMED	MISC	N	DIST	8		No	ACBM with the potential for damage	3	LOW
10A	12x12 Orange Vinyl Floor Tile Mastic	15,690	SF	3rd Floor Corridors, Cafeteria & Lunchroom, Teachers' Lunchroom, Manager's Office, Music Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	12x12 Off-White w/Black Streaks Vinyl Floor Tile Mastic	5,700	SF	Rooms 202, 203, 206, 208, 105, 106, 107, 116	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11A	12x12 Off-White w/Black Streaks Vinyl Floor Tile Mastic	5,700	SF	Rooms 202, 203, 206, 208, 105, 106, 107, 116	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	12x12 Beige Vinyl Floor Tile	3,628	SF	Rooms 409, 416, 303, 309, 300, 308A, 308, 330, 317	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12A	12x12 Beige Vinyl Floor Tile Mastic	3,628	SF	Rooms 409, 416, 303, 309, 300, 308A, 308, 330, 317	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	12x12 Green Vinyl Floor Tile	4,950	SF	N&S Central Corridors, 3rd & 2nd	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Parker Community Academy **Unit** 31181 **Building ID** 5270  
**Address** 6800 S. Stewart **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Floor Corridors										
13A	12x12 Green Vinyl Floor Tile Mastic	4,950	SF	N&S Central Corridors, 3rd & 2nd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	12x12 Blue Vinyl Floor Tile	4,480	SF	4th Floor Corridors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14A	12x12 Blue Vinyl Floor Tile Mastic	4,480	SF	4th Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	12x12 Red Vinyl Floor Tile	4,950	SF	1st Floor Corridor & Room 212	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15A	12x12 Red Vinyl Floor Tile Mastic	4,950	SF	1st Floor Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	12x12 Grey w/Black Streaks Vinyl Floor Tile	868	SF	Rooms 418 & 420	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16A	12x12 Grey w/Black Streaks Vinyl Floor Tile Mastic	868	SF	Rooms 418 & 420	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	12x12 Maroon Vinyl Floor Tile	2,400	SF	Assembly Hall	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17A	12x12 Maroon Vinyl Floor Tile Mastic	2,400	SF	Assembly Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	12x12 Black Vinyl Floor Tile	2,400	SF	Assembly Hall	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18A	12x12 Black Vinyl Floor Tile Mastic	2,400	SF	Assembly Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	12x12 Tan w/Black Streaks Vinyl Floor Tile Mastic	720	SF	Room 201	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19A	12x12 Tan w/Brown Streaks Vinyl Floor Tile	780	SF	Room 201	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	12x12 Brown Vinyl Floor Tile ABATED			Room 323	ABATED	MISC								
20A	12x12 Brown Vinyl Floor Tile Mastic ABATED			Room 323	ABATED	MISC								
21	9x9 cream w/Streaks Vinyl Floor Tile ABATED			Room 300	ABATED	MISC								
21A	9x9 Cream w/Specs Vinyl Floor Tile Mastic ABATED			Room 300	ABATED	MISC								
22	9x9 Tan Vinyl Floor Tile ABATED			Room 300	ABATED	MISC								
23	12x18 Black Edging NOT OBSERVED	1,080	SF	Service line, Teachers' Lunchroom, Lunchroom, Assembly hall	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23A	12x18 Black Edging Mastic NOT OBSERVED	1,080	SF	Service Line, Teachers' Lunchroom,	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Parker Community Academy **Unit** 31181 **Building ID** 5270  
**Address** 6800 S. Stewart **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				lunchroom, Assembly Hall										
24	9x9 Red Vinyl Floor Tile NOT OBSERVED			Serving Line Teachers' Lunchroom, Lunchroom		MISC						ACBM with the potential for damage		
24A	9x9 Red Vinyl Floor Tile Mastic NOT OBSERVED			Serving Line, Teachers' Lunchroom, Lunchroom		MISC								
25	Grey Linoleum	3,550	SF	Rooms 401, 402, 405 & 406	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25A	Grey Linoleum Mastic	3,550	SF	Rooms 401, 402, 405 & 406	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	Green Carpet Mastic NOT OBSERVED	290	SF	Room 286	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	Turquoise Carpet Mastic	4,166	SF	Rooms 114, 200, 214 & 300, Assembly Hall, Principal's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	Brown Carpet Mastic	2,082	SF	Rooms 100, 103, 122, 200, 214A, 229, 304, 307 & Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	2"x2" Ceramic Tile Grout	4,224	SF	Janitor's Storage Closets, All Washrooms on Each Floor except Boys'	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	1"x1" Ceramic Tile Grout	6,250	SF	Boys' Locker Room, Washroom, Girls' Shower Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	Terrazzo Flooring	17,710	SF	Corridor Borders All Floors, Landings, Steps in All Stairwells	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	Brown Floor Covering	3,600	SF	Girls' Locker Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	Brown Floor Covering	2,400	SF	Boys' Locker Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	12x12 Tan w/White Streaks Vinyl Floor Tile	400	SF	Boiler House: Sheet Metal Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34A	12x12 Tan w/White Streaks Vinyl Floor Tile Mastic	400	SF	Boiler House: Sheet Metal Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	12X12 Off-White w/Tan Streaks Vinyl	556	SF	Boiler House: Tool	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

**School** Parker Community Academy **Unit** 31181 **Building ID** 5270  
**Address** 6800 S. Stewart **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Floor Tile			Storage, 2nd Floor Breakfast Room								potential for damage		
35A	12X12 Off-White w/Tan Streaks Vinyl Floor Tile Mastic	556	SF	Boiler House: Tool Storage, 2nd Floor Breakfast Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	12x12 Orange Vinyl Floor Tile	530	SF	Boiler House: 2nd Floor Corridor and Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36A	12x12 Orange Vinyl Floor Tile Mastic	530	SF	Boiler House: 2nd Floor Corridor and Kitchen	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	12x12 Red Vinyl Floor Tile	310	SF	Boiler House: Gauge Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37A	12x12 Red Vinyl Floor Tile Mastic	310	SF	Boiler House: Gauge Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	12x12 Off-White w/Brown Streaks Vinyl Floor Tile	360	SF	Boiler House: Northeast Entrance Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38A	12x12 Off-White w/Brown Streaks Vinyl Floor Tile Mastic	360	SF	Boiler House: Northeast Entrance Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	Black Baseboard	70	LF	Boiler House: Sheet Metal Office Washroom & Compressor Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40A	Black Baseboard Mastic	70	LF	Boiler House: Sheet Metal Office Washroom & Compressor Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	Black Baseboard NOT OBSERVED					MISC								
41A	Black Baseboard Mastic NOT OBSERVED					MISC								
42	Drywall	800	SF	Boiler House: Sheet Metal Storage Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	2x2 Ceramic Tile Grout	320	SF	Boiler House: Front. Washroom, Janitors' Washroom, Engineer's Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	Firebrick	300	SF	Boiler House: Incinerator, South Coal Storage Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	9x9 Black Vinyl Floor Tile NOT OBSERVED	3,893	SF	Cafeteria, Lunchroom, Teachers'	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Parker Community Academy **Unit** 31181 **Building ID** 5270  
**Address** 6800 S. Stewart **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Lunchroom, Serving Room, Managers										
45A	9x9 Black Vinyl Floor Tile Mastic NOT OBSERVED	3,893	SF	Cafeteria, Lunchroom, Teachers' Lunchroom, Serving Room, Managers	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	Aircell Sheeting NOT OBSERVED			Swimming Pool Area: Behind Radiator Shell		TSI								
47	Fiberglass Joints	6	LF	Boiler Room, Boiler Room Washroom, 2nd Floor	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
48	Fiberglass Joints	210	LF	Pipe Chases Throughout Building	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
49	2'x4' Ceiling Tile	11,000	SF	North Wing Throughout, Southeast Wing Second Floor, Rooms 301-306	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
50	12"x12" White w/Multicolor Specks Floor Tile	720	SF	Room 118	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
50M	Mastic associated w/12"x12" White w/Multicolored Specks Floor Tile	720	SF	Room 118	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
51	6"x6" Terracotta Tile Grout	2,000	SF	Kitchen	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
52	1'x1' Pinhole Ceiling Tile	5,000	SF	Auditorium	ASSUMED	MISC	Y	NONE	0		Yes	ACBM with the potential for damage		LOW
53	Black Chalkboards	1,100	SF	Throughout All Classrooms	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
54	Black Lab Countertops	1,200	SF	Rooms 326, 420, 422	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
55	Green Stage Curtains	750	SF	Auditorium	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
FT-1	12x12 White w/Blue Streaks Vinyl Floor Tile	3,980	SF	Rooms 412, 414, 416, 418, 410A, 410B, 408, 406, 404, 402, 401, 314, 316	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-2	12x12 White w/Orange Floor Tile	3,100	SF	Rooms 300, 301, 302, 304 & 312	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-3	9"x9" Brown Floor Tile	15	SF	Rooms 320 Closet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-4	Blue Linoleum	2,430	SF	Rooms 422, 420,	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

**School** Parker Community Academy **Unit** 31181 **Building ID** 5270  
**Address** 6800 S. Stewart **Region** 05

## **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

## Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

***Inspector's Comments are Summarized at the End of the Report***

# Chicago Public Schools

**School** Parker Community Academy **Unit** 31181 **Building ID** 5270  
**Address** 6800 S. Stewart **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date	<u>5/7/2025</u>
Inspector Name	<u>Josh Herman</u>
<b>100-21040</b>	<b>5/15/2026</b>
Inspector's IDPH License Number / Expiration Date	

#### Inspector's Comments

HA Number:	Inspector Comments:
08	50 SF of Replacement in Room 209 (12"x12" Brown FT)
08A	Damaged Tile in Room 308 (and 310)
09	
1	
10	
10A	
11	2025- Not Observed in Room 116
11A	2025- Not Observed in Room 116
12	
12A	
13	
13A	
14	
14A	
15	
15A	
16	2025- Tile is under Floor Covering in Room 420
16A	2025- Tile and Mastic is under Floor Covering in Room 420
17	
17A	
18	
18A	
19	
19A	

# Chicago Public Schools

**School** Parker Community Academy **Unit** 31181 **Building ID** 5270  
**Address** 6800 S. Stewart **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
20	
20A	
21	
21A	
22	
23	Not Observed 2025
23A	Not Observed 2025
24	Not Observed 2022, 2025
24A	Not Observed 2022, 2025
25	2025- Not Observed in Room 406
25A	2025- Not Observed in Room 406
26	Not Observed 2025
27	2025- No Carpet in 300
28	2025- No Carpet in 307
29	
30	
31	
32	
33	
34	
34A	
35	
35A	
36	
36A	
37	
37A	
38	
38A	

# Chicago Public Schools

**School** Parker Community Academy **Unit** 31181 **Building ID** 5270  
**Address** 6800 S. Stewart **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
40	
40A	
41	Not Observed 2022, 2025
41A	Not Observed 2022, 2025
42	
43	
44	
45	Not Observed 2025
45A	Not Observed 2025
46	Not Observed Multiple Years, including 2025
47	
48	
49	
50	
50M	
51	
52	
53	
54	
55	
FT-1	
FT-2	
FT-3	
FT-4	
FTM-1	
FTM-2	
FTM-3	
G	
H	

# Chicago Public Schools

**School** Parker Community Academy **Unit** 31181 **Building ID** 5270  
**Address** 6800 S. Stewart **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
K	
L	Not Observed 2022, 2025
M	Not Observed 2022, 2025
N	Not Observed 2022, 2025
NEW	
O	Not Observed 2022, 2025

**Table II**  
**Management Planner's Review**

---

# Chicago Public Schools

**School** Parker Community Academy

**Unit** 31181

**Building ID** 5270

**Address** 6800 S. Stewart

Chicago, IL, 60621

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
08	12x12 Cream Vinyl Floor Tile	24,730	SF	Rooms 108, 110, 204, 205, 207, 209, 210, 218, 226, 230, 302, 304, 331, 328, 326, 324, 320, 314, 310, 306, 300A, 303 & 408	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08A	12"x12" Cream & Brown Checkered Floor Tile	2,620	SF	Rooms 117, 308, 330 & 409	Assumed	MISC	No	20	SF	6 ACBM with the potential for damage	Remove
09	12x12 Cream Vinyl Floor Tile Mastic	22,330	SF	Rooms 108, 110, 204, 205, 207, 209, 210, 218, 226, 230, 331, 328, 326, 324, 320, 314, 310, 306, 300A, 303	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1	Plaster No ACBM			Throughout Building	No ACBM	SURFACE					
10	12x12 Orange Vinyl Floor Tile	15,690	SF	3rd Floor Corridors, Cafeteria & Lunchroom, Teachers' Lunchroom, Manager's Office, Music Room	Assumed	MISC	No	8	SF	6 ACBM with the potential for damage	Follow O&M Plan
10A	12x12 Orange Vinyl Floor Tile Mastic	15,690	SF	3rd Floor Corridors, Cafeteria & Lunchroom, Teachers' Lunchroom, Manager's Office, Music Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	12x12 Off-White w/Black Streaks Vinyl Floor Tile Mastic	5,700	SF	Rooms 202, 203, 206, 208, 105, 106, 107, 116	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11A	12x12 Off-White w/Black Streaks Vinyl Floor Tile Mastic	5,700	SF	Rooms 202, 203, 206, 208, 105, 106, 107, 116	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	12x12 Beige Vinyl Floor Tile	3,628	SF	Rooms 409, 416, 303, 309, 300, 308A, 308, 330, 317	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12A	12x12 Beige Vinyl Floor Tile Mastic	3,628	SF	Rooms 409, 416, 303, 309, 300, 308A, 308, 330, 317	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	12x12 Green Vinyl Floor Tile	4,950	SF	N&S Central Corridors, 3rd & 2nd Floor Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13A	12x12 Green Vinyl Floor Tile Mastic	4,950	SF	N&S Central Corridors, 3rd & 2nd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	12x12 Blue Vinyl Floor Tile	4,480	SF	4th Floor Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14A	12x12 Blue Vinyl Floor Tile Mastic	4,480	SF	4th Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	12x12 Red Vinyl Floor Tile	4,950	SF	1st Floor Corridor & Room 212	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15A	12x12 Red Vinyl Floor Tile Mastic	4,950	SF	1st Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	12x12 Grey w/Black Streaks Vinyl Floor Tile	868	SF	Rooms 418 & 420	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16A	12x12 Grey w/Black Streaks Vinyl Floor Tile Mastic	868	SF	Rooms 418 & 420	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12x12 Maroon Vinyl Floor Tile	2,400	SF	Assembly Hall	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17A	12x12 Maroon Vinyl Floor Tile Mastic	2,400	SF	Assembly Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Parker Community Academy

**Unit** 31181

**Building ID** 5270

**Address** 6800 S. Stewart

Chicago, IL, 60621

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
18	12x12 Black Vinyl Floor Tile	2,400	SF	Assembly Hall	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18A	12x12 Black Vinyl Floor Tile Mastic	2,400	SF	Assembly Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12x12 Tan w/Black Streaks Vinyl Floor Tile Mastic	720	SF	Room 201	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19A	12x12 Tan w/Brown Streaks Vinyl Floor Tile	780	SF	Room 201	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	12x12 Brown Vinyl Floor Tile ABATED			Room 323	Abated	MISC					
20A	12x12 Brown Vinyl Floor Tile Mastic ABATED			Room 323	Abated	MISC					
21	9x9 cream w/Streaks Vinyl Floor Tile ABATED			Room 300	Abated	MISC					
21A	9x9 Cream w/Specs Vinyl Floor Tile Mastic ABATED			Room 300	Abated	MISC					
22	9x9 Tan Vinyl Floor Tile ABATED			Room 300	Abated	MISC					
23	12x18 Black Edging NOT OBSERVED	1,080	SF	Service line, Teachers' Lunchroom, Lunchroom, Assembly hall	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23A	12x18 Black Edging Mastic NOT OBSERVED	1,080	SF	Service Line, Teachers' Lunchroom, lunchroom, Assembly Hall	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	9x9 Red Vinyl Floor Tile NOT OBSERVED			Serving Line Teachers' Lunchroom, Lunchroom		MISC				6 ACBM with the potential for damage	
24A	9x9 Red Vinyl Floor Tile Mastic NOT OBSERVED			Serving Line, Teachers' Lunchroom, Lunchroom		MISC					
25	Grey Linoleum	3,550	SF	Rooms 401, 402, 405 & 406	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25A	Grey Linoleum Mastic	3,550	SF	Rooms 401, 402, 405 & 406	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Green Carpet Mastic NOT OBSERVED	290	SF	Room 286	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Turquoise Carpet Mastic	4,166	SF	Rooms 114, 200, 214 & 300, Assembly Hall, Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Brown Carpet Mastic	2,082	SF	Rooms 100, 103, 122, 200, 214A, 229, 304, 307 & Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	2"x2" Ceramic Tile Grout	4,224	SF	Janitor's Storage Closets, All Washrooms on Each Floor except Boys'	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	1"x1" Ceramic Tile Grout	6,250	SF	Boys' Locker Room, Washroom, Girls' Shower Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	Terrazzo Flooring	17,710	SF	Corridor Borders All Floors, Landings, Steps in All Stairwells	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	Brown Floor Covering	3,600	SF	Girls' Locker Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Brown Floor Covering	2,400	SF	Boys' Locker Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Parker Community Academy

**Unit** 31181

**Building ID** 5270

**Address** 6800 S. Stewart

Chicago, IL, 60621

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
34	12x12 Tan w/White Streaks Vinyl Floor Tile	400	SF	Boiler House: Sheet Metal Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34A	12x12 Tan w/White Streaks Vinyl Floor Tile Mastic	400	SF	Boiler House: Sheet Metal Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	12X12 Off-White w/Tan Streaks Vinyl Floor Tile	556	SF	Boiler House: Tool Storage, 2nd Floor Breakfast Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35A	12X12 Off-White w/Tan Streaks Vinyl Floor Tile Mastic	556	SF	Boiler House: Tool Storage, 2nd Floor Breakfast Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12x12 Orange Vinyl Floor Tile	530	SF	Boiler House: 2nd Floor Corridor and Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36A	12x12 Orange Vinyl Floor Tile Mastic	530	SF	Boiler House: 2nd Floor Corridor and Kitchen	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12x12 Red Vinyl Floor Tile	310	SF	Boiler House: Gauge Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37A	12x12 Red Vinyl Floor Tile Mastic	310	SF	Boiler House: Gauge Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	12x12 Off-White w/Brown Streaks Vinyl Floor Tile	360	SF	Boiler House: Northeast Entrance Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38A	12x12 Off-White w/Brown Streaks Vinyl Floor Tile Mastic	360	SF	Boiler House: Northeast Entrance Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	Black Baseboard	70	LF	Boiler House: Sheet Metal Office Washroom & Compressor Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
40A	Black Baseboard Mastic	70	LF	Boiler House: Sheet Metal Office Washroom & Compressor Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
41	Black Baseboard NOT OBSERVED					MISC					
41A	Black Baseboard Mastic NOT OBSERVED					MISC					
42	Drywall	800	SF	Boiler House: Sheet Metal Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	2x2 Ceramic Tile Grout	320	SF	Boiler House: Front. Washroom, Janitors' Washroom., Engineer's Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	Firebrick	300	SF	Boiler House: Incinerator, South Coal Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	9x9 Black Vinyl Floor Tile NOT OBSERVED	3,893	SF	Cafeteria, Lunchroom, Teachers' Lunchroom, Serving Room, Managers	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45A	9x9 Black Vinyl Floor Tile Mastic NOT OBSERVED	3,893	SF	Cafeteria, Lunchroom, Teachers' Lunchroom, Serving Room, Managers	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	Aircell Sheeting NOT OBSERVED			Swimming Pool Area: Behind Radiator Shell		TSI					

# Chicago Public Schools

**School** Parker Community Academy

**Unit** 31181

**Building ID** 5270

**Address** 6800 S. Stewart

Chicago, IL, 60621

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
47	Fiberglass Joints	6	LF	Boiler Room, Boiler Room Washroom, 2nd Floor	Assumed	MISC	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
48	Fiberglass Joints	210	LF	Pipe Chases Throughout Building	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
49	2'x4' Ceiling Tile	11,000	SF	North Wing Throughout, Southeast Wing Second Floor, Rooms 301-306	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
50	12"x12" White w/Multicolor Specks Floor Tile	720	SF	Room 118	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50M	Mastic associated w/12"x12" White w/Multicolored Specks Floor Tile	720	SF	Room 118	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	6"x6" Terracotta Tile Grout	2,000	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	1"x1" Pinhole Ceiling Tile	5,000	SF	Auditorium	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	Black Chalkboards	1,100	SF	Throughout All Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	Black Lab Countertops	1,200	SF	Rooms 326, 420, 422	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	Green Stage Curtains	750	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-1	12x12 White w/Blue Streaks Vinyl Floor Tile	3,980	SF	Rooms 412, 414, 416, 418, 410A, 410B, 408, 406, 404, 402, 401, 314, 316	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-2	12x12 White w/Orange Floor Tile	3,100	SF	Rooms 300, 301, 302, 304 & 312	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-3	9"x9" Brown Floor Tile	15	SF	Rooms 320 Closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-4	Blue Linoleum	2,430	SF	Rooms 422, 420, 405, 326	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-1	12x12 White w/Blue Streaks Mastic	3,980	SF	Rooms 412, 414, 416, 418, 410A, 410B, 408, 406, 404, 402, 401, 314, 316	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-2	12x12 White w/Orange Floor Tile Mastic	3,100	SF	Rooms 300, 301, 302, 304, 312	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-3	9x9 Brown Floor Tile Mastic	15	SF	Room 320 Closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G	Aircell Pipe Insulation	600	LF	Basement and Pipe Chases	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
H	Aircell Joints	60	LF	Basement Pipe Chase	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
K	Aircell Duct Insulation ABATED			Unexcavated Areas	Abated	TSI					
L	Air Cell Tank Insulation NOT OBSERVED			Engine Room So. (Boiler House)		TSI					
M	Mav Covering NOT OBSERVED			Boiler House: Engine Room So.		TSI					
N	Preformed Pipe Covering NOT OBSERVED			Boiler Room & Storage - Tunnels		TSI					
NEW	Newly Installed Suspect ACM			Installed After Implementation of	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Parker Community  
Academy

**Unit** 31181

**Building ID** 5270

**Address** 6800 S. Stewart

Chicago, IL, 60621

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880      Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Management Plan and After Renovations							
O	Preformed Joints & Elbows NOT OBSERVED			Boiler Room & Storage		TSI					

Review Date	HA Number	Management Comments
5/29/2025		

# Chicago Public Schools

**School** Parker Community  
Academy

**Address** 6800 S. Stewart

**Unit** 31181

Chicago, IL, 60621

**Building ID** 5270

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

Manager Planner Name	James Tuinenga
100-00349	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
08	
08A	Response action selective to damage in Room 308 only
09	
1	
10	
10A	
11	
11A	
12	
12A	
13	
13A	
14	
14A	
15	
15A	
16	
16A	
17	
17A	
18	
18A	
19	
19A	
20	
20A	

# Chicago Public Schools

**School** Parker Community  
Academy

**Address** 6800 S. Stewart

**Unit** 31181

Chicago, IL, 60621

**Building ID** 5270

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

***Management Planner's Comments Summarized at the End of the Report***

HA Number	Management Comments
21	
21A	
22	
23	
23A	
24	
24A	
25	
25A	
26	
27	
28	
29	
30	
31	
32	
33	
34	
34A	
35	
35A	
36	
36A	
37	
37A	
38	

# Chicago Public Schools

**School** Parker Community  
Academy

**Address** 6800 S. Stewart

**Unit** 31181

Chicago, IL, 60621

**Building ID** 5270

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
38A	
40	
40A	
41	
41A	
42	
43	
44	
45	
45A	
46	
47	
48	
49	
50	
50M	
51	
52	
53	
54	
55	
FT-1	
FT-2	
FT-3	
FT-4	
FTM-1	

# Chicago Public Schools

**School** Parker Community  
Academy

**Address** 6800 S. Stewart

**Unit** 31181

Chicago, IL, 60621

**Building ID** 5270

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

*Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
FTM-2	
FTM-3	
G	
H	
K	
L	
M	
N	
NEW	
O	

## APPENDIX A

---

### Assessment Sheets, Drawings and Photos

**Chicago Public Schools**

**TEM Environmental, Inc.**

***2025 AHERA REINSPECTION***

# Chicago Public Schools

TEM Environmental, Inc.

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUILDING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08		
MATERIAL DESCRIPTION:	12x12 Cream Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 108, 110, 204, 205, 207, 209, 210, 218, 226, 230, 302, 304, 331, 328, 326, 324, 320, 314, 310, 306, 300A, 303 & 408		
MATERIAL QUANTITY:	24730	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	50 SF of Replacement in Room 209 (12"x12" Brown FT)		

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **12x12 Cream Vinyl Floor Tile**

MATERIAL LOCATION: **Rooms 108, 110, 204, 205, 207, 209, 210, 218, 226, 230, 302, 304, 331, 328, 326, 324, 320, 314, 310, 306, 300A, 303 & 408**

MATERIAL QUANTITY: **24730** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUILDING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08A		
MATERIAL DESCRIPTION:	12"x12" Cream & Brown Checkered Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage Other		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Physical Damage Other		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 117, 308, 330 & 409		
MATERIAL QUANTITY:	2620	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damaged Tile in Room 308 (and 310)		

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **08A**

MATERIAL DESCRIPTION: **12"x12" Cream & Brown Checkered Floor Tile**

MATERIAL LOCATION: **Rooms 117, 308, 330 & 409**

MATERIAL QUANTITY: **2620** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Response action selective to damage in Room 308 only

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09		
MATERIAL DESCRIPTION:	12x12 Cream Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 108, 110, 204, 205, 207, 209, 210, 218, 226, 230, 331, 328, 326, 324, 320, 314, 310, 306, 300A, 303**

MATERIAL QUANTITY: **22330** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/07/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **12x12 Cream Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 108, 110, 204, 205, 207, 209, 210, 218, 226, 230, 331, 328, 326, 324, 320, 314, 310, 306, 300A, 303**

MATERIAL QUANTITY: **22330** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 1

MATERIAL DESCRIPTION: Plaster No ACBM

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **Plaster No ACBM**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	12x12 Orange Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Deterioration Other		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Deterioration Other		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Corridors, Cafeteria & Lunchroom, Teachers' Lunchroom, Manager's Office, Music Room		
MATERIAL QUANTITY:	15690	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **12x12 Orange Vinyl Floor Tile**

MATERIAL LOCATION: **3rd Floor Corridors, Cafeteria & Lunchroom, Teachers' Lunchroom, Manager's Office, Music Room**

MATERIAL QUANTITY: **15690** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **8** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUILDING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10A		
MATERIAL DESCRIPTION:	12x12 Orange Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Corridors, Cafeteria & Lunchroom, Teachers' Lunchroom, Manager's Office, Music Room**

MATERIAL QUANTITY: **15690** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/07/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **10A**

MATERIAL DESCRIPTION: **12x12 Orange Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **3rd Floor Corridors, Cafeteria & Lunchroom, Teachers' Lunchroom, Manager's Office, Music Room**

MATERIAL QUANTITY: **15690** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	12x12 Off-White w/Black Streaks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 202, 203, 206, 208, 105, 106, 107, 116		
MATERIAL QUANTITY:	5700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	2025- Not Observed in Room 116		

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **12x12 Off-White w/Black Streaks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 202, 203, 206, 208, 105, 106, 107, 116**

MATERIAL QUANTITY: **5700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11A		
MATERIAL DESCRIPTION:	12x12 Off-White w/Black Streaks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 202, 203, 206, 208, 105, 106, 107, 116		
MATERIAL QUANTITY:	5700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	2025- Not Observed in Eoom 116		

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **11A**

MATERIAL DESCRIPTION: **12x12 Off-White w/Black Streaks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 202, 203, 206, 208, 105, 106, 107, 116**

MATERIAL QUANTITY: **5700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12		
MATERIAL DESCRIPTION:	12x12 Beige Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 409, 416, 303, 309, 300, 308A, 308, 330, 317		
MATERIAL QUANTITY:	3628	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **12x12 Beige Vinyl Floor Tile**

MATERIAL LOCATION: **Rooms 409, 416, 303, 309, 300, 308A, 308, 330, 317**

MATERIAL QUANTITY: **3628** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12A		
MATERIAL DESCRIPTION:	12x12 Beige Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 409, 416, 303, 309, 300, 308A, 308, 330, 317		
MATERIAL QUANTITY:	3628	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **12A**

MATERIAL DESCRIPTION: **12x12 Beige Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 409, 416, 303, 309, 300, 308A, 308, 330, 317**

MATERIAL QUANTITY: **3628** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	12x12 Green Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	N&S Central Corridors, 3rd & 2nd Floor Corridors		
MATERIAL QUANTITY:	4950	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **12x12 Green Vinyl Floor Tile**

MATERIAL LOCATION: **N&S Central Corridors, 3rd & 2nd Floor Corridors**

MATERIAL QUANTITY: **4950** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13A		
MATERIAL DESCRIPTION:	12x12 Green Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	N&S Central Corridors, 3rd & 2nd Floor Corridors		
MATERIAL QUANTITY:	4950	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **13A**

MATERIAL DESCRIPTION: **12x12 Green Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **N&S Central Corridors, 3rd & 2nd Floor Corridors**

MATERIAL QUANTITY: **4950** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	12x12 Blue Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	4th Floor Corridors		
MATERIAL QUANTITY:	4480	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12x12 Blue Vinyl Floor Tile**

MATERIAL LOCATION: **4th Floor Corridors**

MATERIAL QUANTITY: **4480** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14A		
MATERIAL DESCRIPTION:	12x12 Blue Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	4th Floor Corridors		
MATERIAL QUANTITY:	4480	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **14A**

MATERIAL DESCRIPTION: **12x12 Blue Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **4th Floor Corridors**

MATERIAL QUANTITY: **4480** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	12x12 Red Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Corridor & Room 212		
MATERIAL QUANTITY:	4950	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **12x12 Red Vinyl Floor Tile**

MATERIAL LOCATION: **1st Floor Corridor & Room 212**

MATERIAL QUANTITY: **4950** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUILDING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15A		
MATERIAL DESCRIPTION:	12x12 Red Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Corridor		
MATERIAL QUANTITY:	4950	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **15A**

MATERIAL DESCRIPTION: **12x12 Red Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY: **4950** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	12x12 Grey w/Black Streaks Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 418 & 420		
MATERIAL QUANTITY:	868	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	2025- Tile is under Floor Covering in Room 420		

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **12x12 Grey w/Black Streaks Vinyl Floor Tile**

MATERIAL LOCATION: **Rooms 418 & 420**

MATERIAL QUANTITY: **868** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16A		
MATERIAL DESCRIPTION:	12x12 Grey w/Black Streaks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 418 & 420		
MATERIAL QUANTITY:	868	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	2025- Tile and Mastic is under Floor Covering in Room 420		

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **16A**

MATERIAL DESCRIPTION: **12x12 Grey w/Black Streaks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 418 & 420**

MATERIAL QUANTITY: **868** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUILDING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	12x12 Maroon Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Assembly Hall		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **12x12 Maroon Vinyl Floor Tile**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUILDING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17A		
MATERIAL DESCRIPTION:	12x12 Maroon Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Assembly Hall		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **17A**

MATERIAL DESCRIPTION: **12x12 Maroon Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18		
MATERIAL DESCRIPTION:	12x12 Black Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Assembly Hall		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12x12 Black Vinyl Floor Tile**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUILDING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18A		
MATERIAL DESCRIPTION:	12x12 Black Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Assembly Hall		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **18A**

MATERIAL DESCRIPTION: **12x12 Black Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	12x12 Tan w/Black Streaks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 201		
MATERIAL QUANTITY:	720	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **12x12 Tan w/Black Streaks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19A		
MATERIAL DESCRIPTION:	12x12 Tan w/Brown Streaks Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 201		
MATERIAL QUANTITY:	780	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **19A**

MATERIAL DESCRIPTION: **12x12 Tan w/Brown Streaks Vinyl Floor Tile**

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY: **780** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **12x12 Brown Vinyl Floor Tile ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 323**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/07/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **12x12 Brown Vinyl Floor Tile ABATED**

MATERIAL LOCATION: **Room 323**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20A**

MATERIAL DESCRIPTION: **12x12 Brown Vinyl Floor Tile Mastic ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 323**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/07/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **20A**

MATERIAL DESCRIPTION: **12x12 Brown Vinyl Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Room 323**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 21

MATERIAL DESCRIPTION: 9x9 cream w/Streaks Vinyl Floor Tile ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 300

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **9x9 cream w/Streaks Vinyl Floor Tile ABATED**

MATERIAL LOCATION: **Room 300**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 21A

MATERIAL DESCRIPTION: 9x9 Cream w/Specs Vinyl Floor Tile Mastic ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 300

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **21A**

MATERIAL DESCRIPTION: **9x9 Cream w/Speccks Vinyl Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Room 300**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 22  
MATERIAL DESCRIPTION: 9x9 Tan Vinyl Floor Tile ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 300

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **9x9 Tan Vinyl Floor Tile ABATED**

MATERIAL LOCATION: **Room 300**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUILDING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	12x18 Black Edging NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Service line, Teachers' Lunchroom, Lunchroom, Assembly hall		
MATERIAL QUANTITY:	1080	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **12x18 Black Edging NOT OBSERVED**

MATERIAL LOCATION: **Service line, Teachers' Lunchroom, Lunchroom, Assembly hall**

MATERIAL QUANTITY: **1080** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23A		
MATERIAL DESCRIPTION:	12x18 Black Edging Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Service Line, Teachers' Lunchroom, lunchroom, Assembly Hall		
MATERIAL QUANTITY:	1080	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **23A**

MATERIAL DESCRIPTION: **12x18 Black Edging Mastic NOT OBSERVED**

MATERIAL LOCATION: **Service Line, Teachers' Lunchroom, lunchroom, Assembly Hall**

MATERIAL QUANTITY: **1080** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Josh Herman</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	INSPECTION DATE:	<b>5/7/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>24</b>
MATERIAL DESCRIPTION:	<b>9x9 Red Vinyl Floor Tile NOT OBSERVED</b>
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>
HISTORICAL DAMAGE REASON:	
HISTORICAL RESPONSE ACTION:	
ASBESTOS TYPE:	<b>FRIABLE</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Serving Line Teachers' Lunchroom, Lunchroom**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Not Observed 2022, 2025**

Inspector's Signature:



Date: **05/07/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **9x9 Red Vinyl Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **Serving Line Teachers' Lunchroom, Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 24A

MATERIAL DESCRIPTION: 9x9 Red Vinyl Floor Tile Mastic NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Serving Line, Teachers' Lunchroom, Lunchroom

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed 2022, 2025

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **24A**

MATERIAL DESCRIPTION: **9x9 Red Vinyl Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **Serving Line, Teachers' Lunchroom, Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	Grey Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 401, 402, 405 & 406		
MATERIAL QUANTITY:	3550	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	2025- Not Observed in Room 406		

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Grey Linoleum**

MATERIAL LOCATION: **Rooms 401, 402, 405 & 406**

MATERIAL QUANTITY: **3550** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25A		
MATERIAL DESCRIPTION:	Grey Linoleum Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 401, 402, 405 & 406		
MATERIAL QUANTITY:	3550	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	2025- Not Observed in Room 406		

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **25A**

MATERIAL DESCRIPTION: **Grey Linoleum Mastic**

MATERIAL LOCATION: **Rooms 401, 402, 405 & 406**

MATERIAL QUANTITY: **3550** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	Green Carpet Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 286		
MATERIAL QUANTITY:	290	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Green Carpet Mastic NOT OBSERVED**

MATERIAL LOCATION: **Room 286**

MATERIAL QUANTITY: **290** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Josh Herman</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	INSPECTION DATE:	<b>5/7/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>27</b>		
MATERIAL DESCRIPTION:	<b>Turquoise Carpet Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 114, 200, 214 &amp; 300, Assembly Hall, Principal's Office</b>		
MATERIAL QUANTITY:	<b>4166</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>2025- No Carpet in 300</b>		

Inspector's Signature:



Date: **05/07/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Turquoise Carpet Mastic**

MATERIAL LOCATION: **Rooms 114, 200, 214 & 300, Assembly Hall, Principal's Office**

MATERIAL QUANTITY: **4166** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Josh Herman</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	INSPECTION DATE:	<b>5/7/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>28</b>		
MATERIAL DESCRIPTION:	<b>Brown Carpet Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 100, 103, 122, 200, 214A, 229, 304, 307 &amp; Library</b>		
MATERIAL QUANTITY:	<b>2082</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>2025- No Carpet in 307</b>		

Inspector's Signature:



Date: **05/07/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Brown Carpet Mastic**

MATERIAL LOCATION: **Rooms 100, 103, 122, 200, 214A, 229, 304, 307 & Library**

MATERIAL QUANTITY: **2082** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	2"x2" Ceramic Tile Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Janitor's Storage Closets, All Washrooms on Each Floor except Boys'		
MATERIAL QUANTITY:	4224	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **2"x2" Ceramic Tile Grout**

MATERIAL LOCATION: **Janitor's Storage Closets, All Washrooms on Each Floor except Boys'**

MATERIAL QUANTITY: **4224** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	1"x1" Ceramic Tile Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boys' Locker Room, Washroom, Girls' Shower Room		
MATERIAL QUANTITY:	6250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **1"x1" Ceramic Tile Grout**

MATERIAL LOCATION: **Boys' Locker Room, Washroom, Girls' Shower Room**

MATERIAL QUANTITY: **6250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31		
MATERIAL DESCRIPTION:	Terrazzo Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Corridor Borders All Floors, Landings, Steps in All Stairwells		
MATERIAL QUANTITY:	17710	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Terrazzo Flooring**

MATERIAL LOCATION: **Corridor Borders All Floors, Landings, Steps in All Stairwells**

MATERIAL QUANTITY: **17710** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32		
MATERIAL DESCRIPTION:	Brown Floor Covering		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Girls' Locker Room		
MATERIAL QUANTITY:	3600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Brown Floor Covering**

MATERIAL LOCATION: **Girls' Locker Room**

MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Josh Herman</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	INSPECTION DATE:	<b>5/7/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>33</b>		
MATERIAL DESCRIPTION:	<b>Brown Floor Covering</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Boys' Locker Room</b>		
MATERIAL QUANTITY:	<b>2400</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **05/07/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Brown Floor Covering**

MATERIAL LOCATION: **Boys' Locker Room**

MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	12x12 Tan w/White Streaks Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler House: Sheet Metal Office		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **12x12 Tan w/White Streaks Vinyl Floor Tile**

MATERIAL LOCATION: **Boiler House: Sheet Metal Office**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34A		
MATERIAL DESCRIPTION:	12x12 Tan w/White Streaks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler House: Sheet Metal Office		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **34A**

MATERIAL DESCRIPTION: **12x12 Tan w/White Streaks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Boiler House: Sheet Metal Office**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	12X12 Off-White w/Tan Streaks Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler House: Tool Storage, 2nd Floor Breakfast Room		
MATERIAL QUANTITY:	556	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **12X12 Off-White w/Tan Streaks Vinyl Floor Tile**

MATERIAL LOCATION: **Boiler House: Tool Storage, 2nd Floor Breakfast Room**

MATERIAL QUANTITY: **556** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35A		
MATERIAL DESCRIPTION:	12X12 Off-White w/Tan Streaks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler House: Tool Storage, 2nd Floor Breakfast Room		
MATERIAL QUANTITY:	556	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **35A**

MATERIAL DESCRIPTION: **12X12 Off-White w/Tan Streaks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Boiler House: Tool Storage, 2nd Floor Breakfast Room**

MATERIAL QUANTITY: **556** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	12x12 Orange Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler House: 2nd Floor Corridor and Kitchen		
MATERIAL QUANTITY:	530	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **12x12 Orange Vinyl Floor Tile**

MATERIAL LOCATION: **Boiler House: 2nd Floor Corridor and Kitchen**

MATERIAL QUANTITY: **530** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36A		
MATERIAL DESCRIPTION:	12x12 Orange Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler House: 2nd Floor Corridor and Kitchen		
MATERIAL QUANTITY:	530	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **36A**

MATERIAL DESCRIPTION: **12x12 Orange Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Boiler House: 2nd Floor Corridor and Kitchen**

MATERIAL QUANTITY: **530** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	12x12 Red Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler House: Gauge Room		
MATERIAL QUANTITY:	310	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **12x12 Red Vinyl Floor Tile**

MATERIAL LOCATION: **Boiler House: Gauge Room**

MATERIAL QUANTITY: **310** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37A		
MATERIAL DESCRIPTION:	12x12 Red Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler House: Gauge Room		
MATERIAL QUANTITY:	310	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **37A**

MATERIAL DESCRIPTION: **12x12 Red Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Boiler House: Gauge Room**

MATERIAL QUANTITY: **310** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	12x12 Off-White w/Brown Streaks Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler House: Northeast Entrance Room		
MATERIAL QUANTITY:	360	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **12x12 Off-White w/Brown Streaks Vinyl Floor Tile**

MATERIAL LOCATION: **Boiler House: Northeast Entrance Room**

MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38A		
MATERIAL DESCRIPTION:	12x12 Off-White w/Brown Streaks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler House: Northeast Entrance Room		
MATERIAL QUANTITY:	360	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **38A**

MATERIAL DESCRIPTION: **12x12 Off-White w/Brown Streaks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Boiler House: Northeast Entrance Room**

MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUILDING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	Black Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler House: Sheet Metal Office Washroom & Compressor Room		
MATERIAL QUANTITY:	70	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Black Baseboard**

MATERIAL LOCATION: **Boiler House: Sheet Metal Office Washroom & Compressor Room**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUILDING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40A		
MATERIAL DESCRIPTION:	Black Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler House: Sheet Metal Office Washroom & Compressor Room		
MATERIAL QUANTITY:	70	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **40A**

MATERIAL DESCRIPTION: **Black Baseboard Mastic**

MATERIAL LOCATION: **Boiler House: Sheet Metal Office Washroom & Compressor Room**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Josh Herman</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	INSPECTION DATE:	<b>5/7/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Black Baseboard NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **FRIABLE**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2022, 2025**

Inspector's Signature:



Date: **05/07/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Black Baseboard NOT OBSERVED**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Josh Herman</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	INSPECTION DATE:	<b>5/7/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41A**

MATERIAL DESCRIPTION: **Black Baseboard Mastic NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **FRIABLE**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2022, 2025**

Inspector's Signature:



Date: **05/07/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **41A**

MATERIAL DESCRIPTION: **Black Baseboard Mastic NOT OBSERVED**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42		
MATERIAL DESCRIPTION:	Drywall		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler House: Sheet Metal Storage Room		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Boiler House: Sheet Metal Storage Room**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	2x2 Ceramic Tile Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler House: Front. Washroom, Janitors' Washroom., Engineer's Washroom		
MATERIAL QUANTITY:	320	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **2x2 Ceramic Tile Grout**

MATERIAL LOCATION: **Boiler House: Front. Washroom, Janitors' Washroom., Engineer's Washroom**

MATERIAL QUANTITY: **320** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUILDING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	Firebrick		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler House: Incinerator, South Coal Storage Room		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Firebrick**

MATERIAL LOCATION: **Boiler House: Incinerator, South Coal Storage Room**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUILDING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	9x9 Black Vinyl Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Cafeteria, Lunchroom, Teachers' Lunchroom, Serving Room, Managers		
MATERIAL QUANTITY:	3893	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **9x9 Black Vinyl Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **Cafeteria, Lunchroom, Teachers' Lunchroom, Serving Room, Managers**

MATERIAL QUANTITY: **3893** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUILDING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45A		
MATERIAL DESCRIPTION:	9x9 Black Vinyl Floor Tile Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Cafeteria, Lunchroom, Teachers' Lunchroom, Serving Room, Managers		
MATERIAL QUANTITY:	3893	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **45A**

MATERIAL DESCRIPTION: **9x9 Black Vinyl Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **Cafeteria, Lunchroom, Teachers' Lunchroom, Serving Room, Managers**

MATERIAL QUANTITY: **3893** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 46

MATERIAL DESCRIPTION: Aircell Sheeting NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Swimming Pool Area: Behind Radiator Shell

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed Multiple Years, including 2025

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Aircell Sheeting NOT OBSERVED**

MATERIAL LOCATION: **Swimming Pool Area: Behind Radiator Shell**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47		
MATERIAL DESCRIPTION:	Fiberglass Joints		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room, Boiler Room Washroom, 2nd Floor		
MATERIAL QUANTITY:	6	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Fiberglass Joints**

MATERIAL LOCATION: **Boiler Room, Boiler Room Washroom, 2nd Floor**

MATERIAL QUANTITY: **6** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	Fiberglass Joints		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pipe Chases Throughout Building		
MATERIAL QUANTITY:	210	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Fiberglass Joints**

MATERIAL LOCATION: **Pipe Chases Throughout Building**

MATERIAL QUANTITY: **210** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUILDING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	2'x4' Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	North Wing Throughout, Southeast Wing Second Floor, Rooms 301-306		
MATERIAL QUANTITY:	11000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**

MATERIAL LOCATION: **North Wing Throughout, Southeast Wing Second Floor, Rooms 301-306**

MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-1		
MATERIAL DESCRIPTION:	12x12 White w/Blue Streaks Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 412, 414, 416, 418, 410A, 410B, 408, 406, 404, 402, 401, 314, 316		
MATERIAL QUANTITY:	3980	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FT-1**

MATERIAL DESCRIPTION: **12x12 White w/Blue Streaks Vinyl Floor Tile**

MATERIAL LOCATION: **Rooms 412, 414, 416, 418, 410A, 410B, 408, 406, 404, 402, 401, 314, 316**

MATERIAL QUANTITY: **3980** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-2		
MATERIAL DESCRIPTION:	12x12 White w/Orange Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 300, 301, 302, 304 & 312		
MATERIAL QUANTITY:	3100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FT-2**

MATERIAL DESCRIPTION: **12x12 White w/Orange Floor Tile**

MATERIAL LOCATION: **Rooms 300, 301, 302, 304 & 312**

MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-3		
MATERIAL DESCRIPTION:	9"x9" Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 320 Closet		
MATERIAL QUANTITY:	15	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FT-3**

MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile**

MATERIAL LOCATION: **Rooms 320 Closet**

MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUILDING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-4		
MATERIAL DESCRIPTION:	Blue Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 422, 420, 405, 326		
MATERIAL QUANTITY:	2430	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FT-4**

MATERIAL DESCRIPTION: **Blue Linoleum**

MATERIAL LOCATION: **Rooms 422, 420, 405, 326**

MATERIAL QUANTITY: **2430** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-1		
MATERIAL DESCRIPTION:	12x12 White w/Blue Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 412, 414, 416, 418, 410A, 410B, 408, 406, 404, 402, 401, 314, 316		
MATERIAL QUANTITY:	3980	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FTM-1**

MATERIAL DESCRIPTION: **12x12 White w/Blue Streaks Mastic**

MATERIAL LOCATION: **Rooms 412, 414, 416, 418, 410A, 410B, 408, 406, 404, 402, 401, 314, 316**

MATERIAL QUANTITY: **3980** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-2		
MATERIAL DESCRIPTION:	12x12 White w/Orange Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 300, 301, 302, 304, 312		
MATERIAL QUANTITY:	3100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/07/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FTM-2**

MATERIAL DESCRIPTION: **12x12 White w/Orange Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 300, 301, 302, 304, 312**

MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-3		
MATERIAL DESCRIPTION:	9x9 Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 320 Closet		
MATERIAL QUANTITY:	15	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	DAMAGE UNITS: SF		
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FTM-3**

MATERIAL DESCRIPTION: **9x9 Brown Floor Tile Mastic**

MATERIAL LOCATION: **Room 320 Closet**

MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUILDING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement and Pipe Chases		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Basement and Pipe Chases**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUILDING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	H		
MATERIAL DESCRIPTION:	Aircell Joints		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement Pipe Chase		
MATERIAL QUANTITY:	60	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	DAMAGE UNITS: LF		
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Aircell Joints**

MATERIAL LOCATION: **Basement Pipe Chase**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Aircell Duct Insulation ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Unexcavated Areas**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/07/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Aircell Duct Insulation ABATED**

MATERIAL LOCATION: **Unexcavated Areas**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: L

MATERIAL DESCRIPTION: Air Cell Tank Insulation NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Engine Room So. (Boiler House)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed 2022, 2025

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Air Cell Tank Insulation NOT OBSERVED**

MATERIAL LOCATION: **Engine Room So. (Boiler House)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: M

MATERIAL DESCRIPTION: Mav Covering NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler House: Engine Room So.

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed 2022, 2025

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Mat Covering NOT OBSERVED**

MATERIAL LOCATION: **Boiler House: Engine Room So.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: N

MATERIAL DESCRIPTION: Preformed Pipe Covering NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room & Storage - Tunnels

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed 2022, 2025

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Preformed Pipe Covering NOT OBSERVED**

MATERIAL LOCATION: **Boiler Room & Storage - Tunnels**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	NEW		
MATERIAL DESCRIPTION:	Newly Installed Suspect ACM		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/07/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **NEW**

MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**

MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUILDING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Josh Herman</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	INSPECTION DATE:	<b>5/7/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **O**

MATERIAL DESCRIPTION: **Preformed Joints & Elbows NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **FRIABLE**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room & Storage**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Not Observed 2022, 2025**

Inspector's Signature:



Date: **05/07/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>31181</b>	BUIDLING ID:	<b>5270</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Parker Community Academy</b>	REVIEW DATE:	<b>5/29/2025</b>		
ADDRESS:	<b>6800 S. Stewart</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **O**

MATERIAL DESCRIPTION: **Preformed Joints & Elbows NOT OBSERVED**

MATERIAL LOCATION: **Boiler Room & Storage**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	12"x12" White w/Multicolor Specks Floor Tile		
MATERIAL LOCATION:	Room 118		
MATERIAL QUANTITY:	720	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31181** BUIDLING ID: **5270**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Parker Community Academy** REVIEW DATE: **5/29/2025**

ADDRESS: **6800 S. Stewart** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **12"x12" White w/Multicolor Specks Floor Tile**

MATERIAL LOCATION: **Room 118**

MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/29/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	6"x6" Terracotta Tile Grout		
MATERIAL LOCATION:	Kitchen		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31181** BUIDLING ID: **5270**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Parker Community Academy** REVIEW DATE: **5/29/2025**

ADDRESS: **6800 S. Stewart** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **6"x6" Terracotta Tile Grout**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/29/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	Black Lab Countertops		
MATERIAL LOCATION:	Rooms 326, 420, 422		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31181** BUIDLING ID: **5270**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Parker Community Academy** REVIEW DATE: **5/29/2025**

ADDRESS: **6800 S. Stewart** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Black Lab Countertops**

MATERIAL LOCATION: **Rooms 326, 420, 422**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/29/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31181** BUIDLING ID: **5270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Josh Herman**  
SCHOOL NAME: **Parker Community Academy** INSPECTION DATE: **5/7/2025**  
ADDRESS: **6800 S. Stewart** IDPH LICENSE NO: **100-21040**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **Green Stage Curtains**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC** FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW** CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach** DAMAGE REASON:  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **05/07/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31181** BUIDLING ID: **5270**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Parker Community Academy** REVIEW DATE: **5/29/2025**

ADDRESS: **6800 S. Stewart** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Green Stage Curtains**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/29/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	50M				
MATERIAL DESCRIPTION:	Mastic associated w/12"x12" White w/Multicolored Specks Floor Tile				
MATERIAL LOCATION:	Room 118				
MATERIAL QUANTITY:	720	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31181** BUIDLING ID: **5270**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Parker Community Academy** REVIEW DATE: **5/29/2025**

ADDRESS: **6800 S. Stewart** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **50M**

MATERIAL DESCRIPTION: **Mastic associated w/12"x12" White w/Multicolored Specks Floor Tile**

MATERIAL LOCATION: **Room 118**

MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/29/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	1'x1' Pinhole Ceiling Tile		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	Yes
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31181** BUIDLING ID: **5270**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Parker Community Academy** REVIEW DATE: **5/29/2025**

ADDRESS: **6800 S. Stewart** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **1'x1' Pinhole Ceiling Tile**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/29/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31181	BUIDLING ID:	5270
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Parker Community Academy	INSPECTION DATE:	5/7/2025		
ADDRESS:	6800 S. Stewart	IDPH LICENSE NO:	100-21040		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	Black Chalkboards		
MATERIAL LOCATION:	Throughout All Classrooms		
MATERIAL QUANTITY:	1100	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/07/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31181** BUIDLING ID: **5270**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Parker Community Academy** REVIEW DATE: **5/29/2025**

ADDRESS: **6800 S. Stewart** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **Black Chalkboards**

MATERIAL LOCATION: **Throughout All Classrooms**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/29/2025

## APPENDIX B

---

### Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**JOSH R HERMAN**  
5121 N MONITOR AVE  
CHICAGO, IL 60630

5/23/2025

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 21040

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

**Front of License**

**Back of License**



**ASBESTOS  
PROFESSIONAL  
LICENSE**

**ENDORSEMENTS**

**TC EXPIRES**

INSPECTOR

7/19/2025

ID NUMBER  
100 - 21040

ISSUED  
5/23/2025

EXPIRES  
05/15/2026

**JOSH R HERMAN**  
5121 N MONITOR AVE  
CHICAGO, IL 60630  
Environmental Health



**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**

*Nationally Accredited by PHAB*

Reliable  
Environmental  
Solutions, Inc. **R | E | S**

*This is to certify that*

**James Tuinenga**

*has on 2/2/22, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Building Inspector Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher.*

Course Date: February 2, 2022

**COURSE LENGTH: 4 HOURS**

Examination Date: February 2, 2022

Expiration Date: February 2, 2023

Certificate Number: BIR/1013

*William S. Williams*


Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois  217.787.9800  217.787.9801 FAX  [www.ReliableEnv.com](http://www.ReliableEnv.com)



**TEM ENVIRONMENTAL, INC.**

ENVIRONMENTAL SCIENTISTS | INDUSTRIAL HYGIENISTS



ENDORSEMENTS

INSPECTOR	2/2/2023
PROJECT DESIGNER	2/3/2023
MANAGEMENT PLANNER	2/2/2023
PROJECT MANAGER	2/1/2023
AIR SAMPLING PROFESSIONAL	

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

Reliable  
Environmental  
Solutions, Inc. **R E S**

*This is to certify that*

**James Tuinenga**

*has on 2/02/22, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: February 2, 2022

**COURSE LENGTH: 4 HOURS**

Examination Date: February 2, 2022

Expiration Date: February 2, 2023

*William S. Williams*


Certificate Number: MPR/0458

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois  217.787.9800  217.787.9801 FAX  [www.ReliableEnv.com](http://www.ReliableEnv.com)



**TEM ENVIRONMENTAL, INC.**  
ENVIRONMENTAL SCIENTISTS | INDUSTRIAL HYGIENISTS



**ENDORSEMENTS**

INSPECTOR  
PROJECT DESIGNER  
MANAGEMENT PLANNER  
PROJECT MANAGER  
AIR SAMPLING PROFESSIONAL

**TC EXPIRES**

1/31/2025  
2/1/2025  
1/31/2025  
1/30/2025

**Alteration of this license shall result in legal action**

This license issued under authority of the State of Illinois

Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.

**Reliable  
Environmental  
Solutions, Inc. R E S**

*This is to certify that*

**James Tuinenga**

*has on 2/5/25, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Building Inspector Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher.*

Course Date: February 5, 2025

**COURSE LENGTH: 4 HOURS**

Examination Date: February 5, 2025

Expiration Date: February 5, 2026

Certificate Number: BIR/1227




Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois  217.787.9800  [www.ReliableEnv.com](http://www.ReliableEnv.com)



**TEM ENVIRONMENTAL, INC.**  
ENVIRONMENTAL SCIENTISTS | INDUSTRIAL HYGIENISTS



**ENDORSEMENTS**

INSPECTOR  
PROJECT DESIGNER  
MANAGEMENT PLANNER  
PROJECT MANAGER  
AIR SAMPLING PROFESSIONAL

**TC EXPIRES**

2/5/2026  
2/6/2025  
2/5/2026  
2/4/2026

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

**Reliable  
Environmental  
Solutions, Inc.** **R E S**

*This is to certify that*

**James Tuinenga**

*has on 2/5/25, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: February 5, 2025

**COURSE LENGTH: 4 HOURS**

Examination Date: February 5, 2025

Expiration Date: February 5, 2026



Certificate Number: MPR/0546

Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois  217.787.9800  [www.ReliableEnv.com](http://www.ReliableEnv.com)

## APPENDIX C

---

### **Laboratory Accreditations**

## APPENDIX D

---

### Laboratory Results

## APPENDIX E

---

### Chain of Custody Forms

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>	Loc	Localized
	Dist	Distributed