

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-3522
SCHOOL NAME: Sumner Academy
ADDRESS OF SCHOOL: 4320 W. Fifth
CITY: Chicago, IL, 60624

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 11/3/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 4/25/2025 ENROLLMENT 201
IDPH INSPECTOR LICENSE NUMBER: 100-19554
IDPH LICENSED INSPECTOR NAME (Please Print): Carol Ashman
IDPH MP LICENSE NUMBER: 100-20634
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jackson Montgomery

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 5/19/2025

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Sumner Academy

4320 W. Fifth
Chicago, IL, 60624

Unit: 31221
Building ID: 6110

IDPH ID Number: 14-016-2990-3522

REPORT DATE:
Monday, May 19, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

05/19/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 31221 Region: 03 IDPH ID: 14-016-2990-3522

School: Sumner Academy Building ID: 6110

Address: 4320 W. Fifth

Chicago, IL, 60624

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date: 4/25/2025

Review Date: 05/19/2025

Inspector: Carol Ashman

Inspector IDPH License: 100-19554

Management Planner: Jackson Montgomery

Management Planner IDPH License: 100-20634

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Jackson Montgomery
100-20634

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: May 19, 2025

RE: Sumner Academy, Unit 31221
4320 W. Fifth
Chicago, IL, 60624

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Sumner Academy , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Sumner Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Sumner Academy Unit: 31221 Region: 03
Address: 4320 W. Fifth Chicago, IL, 60624
IDPH ID: 14-016-2990-3522 Building ID: 6110
Contact: Phone:

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: No of Floors:
Current Occupancy: 201

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Carol Ashman

Inspector IDPH license # 100-19554 Signature:
Reinspection Date: 4/25/2025 Date: 4/25/2025

6. Management Planner

Management Planner Name: Jackson Montgomery


Management Planner IDPH license # 100-20634


Signature:
Date: 05/19/2025

7. Review Date: 05/19/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.


Signature:

Date: 5/19/2025

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Sumner Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 6110:

023.3	12" x 12" Brown Floor Tile w/ Dark Brown & White Streaks
023.4	12" x 12" Beige w/ White & Brown Floor Tile
024.2	12" x 12" Tan Flecks Floor Tile Mastic
027.1	12" x 12" Vinyl Floor Tile, Tan Flecks w/ Brown and White Specks
028.1	12" x 12" Vinyl Floor Tile, Beige Flecks w/ Brown and White Specks
036.1	12" x 12" Vinyl Floor Tile, Beige w/ Blue, Gray, and Rust Streaks
056.2	Pink Mixed Carpet Mastic
58	12" x 12" Tan w/ Black and White Floor Tile

60	12" x 12" Tan w/ Blue and Red Floor Tile
61	12" x 12" Tan w/ Blue and Red Floor Tile Mastic
62	12" x 12" Light Brown w/ White and Black Floor Tile
68	12" x 12" Blue/Green /Purple Floor Tile
69	12" x 12" Blue/Gree/Purple Floor Tile Mastic
70	12" x 12" Red Floor Tile
71	12" x 12" Red Floor Tile Mastic
73	12" x 12' Beige w/ White Specks Floor Tile
74	12" x 12' Red w/ White Specks Floor Tile
75	12" x 12" Beige w/White Specks & Red w/ White Specks Floor Tile Mastic

B. The following new homogenous areas have been identified for Building 6110:

76	4" x 4" Brown Ceramic Tile
77	4" x 4" Brown Ceramic Tile Grout
78	4" x 4" Ceramic Tile Mortar

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

013.2	2' x 4' Acoustical Ceiling Tile
023.1	12" x 12" Light Gray w/ Brown and White Streaks Floor Tile
023.3	12" x 12" Brown Floor Tile w/ Dark Brown & White Streaks
023.5	12" x 12" Cream Flecks w/ Tan Specks Floor Tile
024.2	12" x 12" Tan Flecks Floor Tile Mastic
026.2	Dark Brown Vinyl Baseboard Adhesive
027.1	12" x 12" Vinyl Floor Tile, Tan Flecks w/ Brown and White Specks
028.1	12" x 12" Vinyl Floor Tile, Beige Flecks w/ Brown and White Specks
030.1	12" x 12" Vinyl Floor Tile, Brown w/ Dark Brown and White Streaks
031.1	12" x 12" Vinyl Floor Tile, Beige w/ Brown and White Streaks
031.1M	12" x 12" Beige w/ Brown & White Vinyl Floor Tile Mastic
032.1	12" x 12" Vinyl Floor Tile, Light Beige w/ Brown and White Streaks
032.1M	12" x 12" Light Beige w/ Brown & White Vinyl Floor Tile Mastic
033.1	12" x 12" Vinyl Floor Tile, Beige Flecks w/ Brown and White Specks
033.2	12" x 12" Vinyl Floor Tile, Beige w/ Brown and White Streaks
034.1	Black Vinyl Molding
036.1	12" x 12" Vinyl Floor Tile, Beige w/ Blue, Gray, and Rust Streaks
037.1	12" x 12" Vinyl Floor Tile, Cream Flecks w/ Tan Specks
044.2	12" x 12" Vinyl Floor Tile, Beige w/ Blue, Pink, Gray, & Brown
044.2M	12" x 12" Vinyl Floor Tile, Beige, Blue, Pink? Mastic
045.2	12" x 12" Vinyl Floor Tile, Tan w/ Blue, Gray, Brown, Orange & Beige
045.2M	12" x 12" Tan, Black, Gray, Brown, and Gray Vinyl Floor Tile Mastic
047.1	Boiler Brick
048.1	Boiler Brick Mortar
049.2	Fire Doors

050.1	Roof - Non-AHERA
050.2	Roof - Non-AHERA
051.1	Roof Flashing - Non-AHERA
051.2	Roof Flashing - Non-AHERA
053.2	Door Caulk - Non-AHERA
054.1	Window Caulk - Non-AHERA
054.2	Window Caulk - Non-AHERA
33.2	12" x 12" Vinyl Floor Tile, Beige w/ Brown and White Streaks
34.1	Black Vinyl Molding
58	12" x 12" Tan w/ Black and White Floor Tile
59	12" x 12" Tan w/ Black and White Floor Tile Mastic
60	12" x 12" Tan w/ Blue and Red Floor Tile
61	12" x 12" Tan w/ Blue and Red Floor Tile Mastic
62	12" x 12" Light Brown w/ White and Black Floor Tile
63	12" x 12" Light Brown w/ White and Black Floor Tile Mastic
64	Black Chalk Board Adhesive
65	Green Chalk Board Adhesive
66	12" x 12" Tan Floor Tile
67	12" x 12" Tan Floor Tile Mastic
68	12" x 12" Blue/Green /Purple Floor Tile
69	12" x 12" Blue/Gree/Purple Floor Tile Mastic
70	12" x 12" Red Floor Tile
71	12" x 12" Red Floor Tile Mastic
72	Green Terrazzo
73	12" x 12' Beige w/ White Specks Floor Tile
74	12" x 12' Red w/ White Specks Floor Tile
75	12" x 12" Beige w/White Specks & Red w/ White Specks Floor Tile Mastic
76	4" x 4" Brown Ceramic Tile
77	4" x 4" Brown Ceramic Tile Grout
78	4" x 4" Ceramic Tile Mortar
K.2	Joint Insulation on Fiberglass Insulated Piping

The following areas were deemed to be inaccessible:

024.3	12" x 12" Brown w/ Dark Brown and white Floor Tile Mastic
024.4	12" x 12" Cream Flecks w/ Tan Specks Vinyl Floor Tile Mastic
024.5	12" x 12" Beige w/ White & Brown Floor Tile Mastic
026.2	Dark Brown Vinyl Baseboard Adhesive
049.2	Fire Doors

59	12" x 12" Tan w/ Black and White Floor Tile Mastic
63	12" x 12" Light Brown w/ White and Black Floor Tile Mastic
64	Black Chalk Board Adhesive
65	Green Chalk Board Adhesive
67	12" x 12" Tan Floor Tile Mastic
78	4" x 4" Ceramic Tile Mortar

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Carol Ashman, IDPH License # 100-19554. The Management Plan was updated by Jackson Montgomery, IDPH License # 100-20634. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Sumner Academy Building 6110 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Sumner Academy **Unit** 31221 **Building ID** 6110
Address 4320 W. Fifth **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
001.1	Wall/Ceiling Plaster			Throughout	NO_ACBM	SURFACE								
001.2	Wall/Ceiling Plaster			Throughout	NO_ACBM	SURFACE								
002.1	1' x 1' Ceiling Tile			Lunch Room	NO_ACBM	MISC								
002A.1	1' x 1' Acoustic Ceiling Tile			Lunch Room	NO_ACBM	MISC								
013.1	2' x 4' Acoustic Ceiling Tiles			Room 334	NO_ACBM	MISC								
013.2	2' x 4' Acoustical Ceiling Tile	750	SF	Room 335	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
016.1	Window Caulk, Green			Teacher's Lounge, Room 131	NO_ACBM	MISC								
016.2	Window Caulk			Throughout Interior	NO_ACBM	MISC								
017.1	Masonry Brick			Tank Room, Boiler Room	NO_ACBM	MISC								
017.2	Masonry Brick Mortar			Engine Room	NO_ACBM	MISC								
018.1	Masonry Mortar			Tank Room, Boiler Room	NO_ACBM	MISC								
018.2	Masonry Brick Wall			Engine Room	NO_ACBM	MISC								
019.1	Wood Wall Board			Basement Stairwell	NO_ACBM	MISC								
019.2	Wood Wall Board			Room 124	NO_ACBM	MISC								
020.1	Cinder Block			Tank Room, Boiler Room	NO_ACBM	MISC								
020.2	Cinder Block			Store Room Across From Assembly Hall	NO_ACBM	MISC								
021.1	Cinder Block Mortar			Tank Room, Boiler Room	NO_ACBM	MISC								
021.2	Cinder Block Mortar			Storeroom Across From Assembly Hall	NO_ACBM	MISC								
022.1	Drywall			Teacher's Lounge, 1st Floor Slop Sink	NO_ACBM	MISC								
022.2	Drywall			Room 120 and 223	NO_ACBM	MISC								
023.1	12" x 12" Light Gray w/ Brown and White Streaks Floor Tile			Lunch Room	ASSUMED	MISC					No			
023.3	12" x 12" Brown Floor Tile w/ Dark Brown & White Streaks	800	SF	Room 137, 221	ASSUMED	MISC	N	LOC	3	SF	Yes	ACBM with the potential for damage	5	LOW
023.4	12" x 12" Beige w/ White & Brown Floor Tile	15,000	SF	1st, 2nd & 3rd Floor Corridors	CHR	MISC	N	LOC	20	SF	Yes	ACBM with the potential for damage	5	LOW
023.5	12" x 12" Cream Flecks w/ Tan Specks Floor Tile	200	SF	Engineer's Office, Patch in Assembly Hall, 2nd Floor Teacher lounge	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
024.1	12" x 12" Light Gray w/ Brown & White Floor Tile Mastic			Lunch Room	NO_ACBM	MISC								
024.2	12" x 12" Tan Flecks Floor Tile Mastic			Room 221	ASSUMED	MISC					Yes			

Chicago Public Schools

School Sumner Academy **Unit** 31221 **Building ID** 6110
Address 4320 W. Fifth **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
024.3	12" x 12" Brown w/ Dark Brown and white Floor Tile Mastic	800	SF	Room 137, 221	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
024.4	12" x 12" Cream Flecks w/ Tan Specks Vinyl Floor Tile Mastic	200	SF	Engineer's Office, Patch in Assembly Hall, 2nd Floor Teacher lounge	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
024.5	12" x 12" Beige w/ White & Brown Floor Tile Mastic	15,000	SF	1st, 2nd & 3rd Floor Corridors, Room 024	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
025.1	Brown Vinyl Baseboard			Lunch Room	NO_ACBM	MISC								
025.2	Light Brown Vinyl Baseboard			Teacher's Lounge	NO_ACBM	MISC								
026.1	Brown Vinyl Baseboard Adhesive			Lunch Room	NO_ACBM	MISC								
026.2	Dark Brown Vinyl Baseboard Adhesive	80	LF	Teacher's Lounge	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
027.1	12" x 12" Vinyl Floor Tile, Tan Flecks w/ Brown and White Specks	1,576	SF	Lunchroom , Kitchen	ASSUMED	MISC	N	LOC	10	SF	Yes	ACBM with the potential for damage	5	LOW
027.1M	12" x 12" Tan Flecks w/ Brown & White Vinyl Floor Tile Mastic			Lunchroom Kitchen	NO_ACBM	MISC								
027.2	12" x 12" Tan Flecks w/ Brown & White Vinyl Floor Tile Mastic			Assembly Hall, Gym	NO_ACBM	MISC								
027.2M	12" x 12" Tan Flecks w/ Brown & White Vinyl Floor Tile Mastic			Assembly Hall, Gym	NO_ACBM	MISC								
028.1	12" x 12" Vinyl Floor Tile, Beige Flecks w/ Brown and White Specks	332	SF	Room 133, patch in assembly hall	ASSUMED	MISC	N	LOC	5	SF	Yes	ACBM with the potential for damage	5	LOW
028.1M	12" x 12" Beige Flecks w/ Brown & White Vinyl Floor Tile Mastic			Room 133	NO_ACBM	MISC								
028.2	12" x 12" Vinyl Floor Tile, Beige Flecks w/ Brown & White Specks			2nd Floor Corridor	NO_ACBM	MISC								
028.2M	12" x 12" Beige Flecks w/ Brown & White Vinyl Floor Tile Mastic			2nd Floor Corridor	NO_ACBM	MISC								
029.1	Vinyl Floor Tile Molding, Brown			Room 133	NO_ACBM	MISC								
029.2	Vinyl Floor Tile Molding, Brown			Assembly Hall	NO_ACBM	MISC								
030.1	12" x 12" Vinyl Floor Tile, Brown w/ Dark Brown and White Streaks			Rooms 137, 234	ASSUMED	MISC					No			
031.1	12" x 12" Vinyl Floor Tile, Beige w/ Brown and White Streaks			1st Floor Corridor	ASSUMED	MISC					No			
031.1M	12" x 12" Beige w/ Brown & White Vinyl Floor Tile Mastic			1st Floor Corridor	ASSUMED	MISC					No			
032.1	12" x 12" Vinyl Floor Tile, Light Beige w/ Brown and White Streaks			Room 233	ASSUMED	MISC					No			
032.1M	12" x 12" Light Beige w/ Brown & White Vinyl Floor Tile Mastic			Room 223	ASSUMED	MISC					No			
033.1	12" x 12" Vinyl Floor Tile, Beige Flecks w/ Brown and White Specks			2nd Floor Corridor	ASSUMED	MISC					No			

Chicago Public Schools

School Sumner Academy **Unit** 31221 **Building ID** 6110
Address 4320 W. Fifth **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Chicago Public Schools

School Sumner Academy **Unit** 31221 **Building ID** 6110
Address 4320 W. Fifth **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
051.2	Roof Flashing - Non-AHERA			Exterior	ASSUMED	MISC								
053.1	Door Caulk - Non-AHERA			Exterior	CHR	MISC								
053.2	Door Caulk - Non-AHERA			Exterior	ASSUMED	MISC								
054.1	Window Caulk - Non-AHERA			Exterior	ASSUMED	MISC								
054.2	Window Caulk - Non-AHERA			Exterior	ASSUMED	MISC								
055.1	Blue Mixed Carpet Mastic			Room 235	NO_ACBM	MISC								
055.2	Blue Mixed Carpet Mastic			Room 024	NO_ACBM	MISC								
056.1	Pink Mixed Carpet Mastic			Room 235 Closet	NO_ACBM	MISC								
056.2	Pink Mixed Carpet Mastic			Rooms 020, 125, Teacher's Lounge	NO_ACBM	MISC					Yes			
057.1	Brown Mixed Carpet Mastic			Main Office	NO_ACBM	MISC								
33.2	12" x 12" Vinyl Floor Tile, Beige w/ Brown and White Streaks			1st, 2nd & 3rd Floor Corridors	ASSUMED	MISC					No			
34.1	Black Vinyl Molding			1st and 2nd Floor Corridors	ASSUMED	MISC					No			
58	12" x 12" Tan w/ Black and White Floor Tile	325	SF	Rooms 122, Teacher's Lounge	ASSUMED	MISC	N	LOC	6	SF	Yes	ACBM with potential for significant damage	5	LOW
59	12" x 12" Tan w/ Black and White Floor Tile Mastic	325	SF	Rooms 122, Teachers Lounge	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
60	12" x 12" Tan w/ Blue and Red Floor Tile			Rooms 124, 221	ASSUMED	MISC					Yes			
61	12" x 12" Tan w/ Blue and Red Floor Tile Mastic			Rooms Room 124, 221, 332	ASSUMED	MISC					Yes			
62	12" x 12" Light Brown w/ White and Black Floor Tile	1,750	SF	Rooms 231, 335	ASSUMED	MISC	N	LOC	25	SF	Yes	ACBM with the potential for damage	10	LOW
63	12" x 12" Light Brown w/ White and Black Floor Tile Mastic	1,750	SF	Rooms 231, 335	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
64	Black Chalk Board Adhesive	4,000	SF	Classrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
65	Green Chalk Board Adhesive	4,000	SF	Classrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
66	12" x 12" Tan Floor Tile	10,000	SF	Lunch Room 101 (Offices), Rooms 102, faculty Bathroom, 103-107, 109-111, 114-116, PC Lab, 1st Floor Hallway	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
67	12" x 12" Tan Floor Tile Mastic	10,000	SF	Lunch Room 101 (Offices), Rooms 102, faculty Bathroom, 103-107, 109-111, 114-116, PC Lab, 1st Floor Hallway	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Sumner Academy **Unit** 31221 **Building ID** 6110
Address 4320 W. Fifth **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
68	12" x 12" Blue/Green /Purple Floor Tile			Room 112	ASSUMED	MISC					Yes			
69	12" x 12" Blue/Gree/Purple Floor Tile Mastic			Room 112	ASSUMED	MISC					Yes			
70	12" x 12" Red Floor Tile			Lunch Room	ASSUMED	MISC					Yes			
71	12" x 12" Red Floor Tile Mastic			Lunch Room	ASSUMED	MISC					Yes			
72	Green Terrazzo	3,000	SF	Entrance and stairwells	ASSUMED	SURFACE	N	NONE			No	ACBM with the potential for damage		LOW
73	12" x 12' Beige w/ White Specks Floor Tile			Lunchroom	ASSUMED	MISC					Yes			
74	12" x 12' Red w/ White Specks Floor Tile			Lunchroom	ASSUMED	MISC					Yes			
75	12" x 12" Beige w/White Specks & Red w/ White Specks Floor Tile Mastic			Lunchroom	ASSUMED	MISC					Yes			
76	4" x 4" Brown Ceramic Tile	20	SF	Damage in Bathroom 020	ASSUMED	MISC	N	LOC	2	SF		ACBM with potential for significant damage	5	MODERATE
77	4" x 4" Brown Ceramic Tile Grout	20	SF	Bathroom For Room 020	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
78	4" x 4" Ceramic Tile Mortar	20	SF	020 Bathroom	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
A.1	Cardboard Pipe Insulation			Main Entrance	NO_ACBM	MISC								
B.1	Joint Insulation on Cardboard Insulated Piping			Main Entrance	NO_ACBM	MISC								
C.1	Mag Block Pipe Insulation			ABATED	ABATED	TSI								
C.2	Mag-Block Pipe Insulation			ABATED	ABATED	TSI								
D.1	Joint Insulation on Mag Block Insulated Piping			ABATED	ABATED	TSI								
I.1	Cardboard Duct Wrap			Filter Room	NO_ACBM	MISC								
J.2	Joint Insulation on Mag Block Insulated Piping			ABATED	ABATED	TSI								
K.1	Joint Insulation on Fiberglass Insulated Piping			2nd and 3rd Floor Janitor Closets	NO_ACBM	MISC								
K.2	Joint Insulation on Fiberglass Insulated Piping			1st and 2nd Floor Girl's Bathrooms and 1st Floor Boy's Bathroom	ASSUMED	MISC					No			

Chicago Public Schools

School Sumner Academy Unit 31221 Building ID 6110
Address 4320 W. Fifth Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date <u>4/25/2025</u>
Inspector Name <u>Carol Ashman</u>
<u>100-19554</u> <u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
001.1	
001.2	
002.1	
002A.1	
013.1	
013.2	
016.1	
016.2	
017.1	
017.2	
018.1	
018.2	
019.1	
019.2	
020.1	
020.2	
021.1	
021.2	
022.1	
022.2	
023.1	Material not observed - 2025
023.3	Damage in Room 221
023.4	Damage in Corridor Outside Room 138
023.5	

Chicago Public Schools

School Sumner Academy Unit 31221 Building ID 6110
Address 4320 W. Fifth Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
024.1	
024.2	Material not observed - 2025
024.3	
024.4	
024.5	
025.1	
025.2	
026.1	
026.2	
027.1	Damage in Lunchroom
027.1M	
027.2	
027.2M	
028.1	Damage to Patch in Assembly Hall
028.1M	
028.2	
028.2M	
029.1	
029.2	
030.1	Material not observed - 2025
031.1	Material not observed - 2025
031.1M	Material not observed - 2025
032.1	Material not observed - 2025
032.1M	Material not observed - 2025
033.1	Material not observed - 2025
033.1M	
033.2	Material not observed - 2025
034.1	Material not observed - 2025
034.2	

Chicago Public Schools

School Sumner Academy Unit 31221 Building ID 6110
Address 4320 W. Fifth Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
035.1	
035.2	
036.1	Material not observed - 2025
036.1M	
037.1	
038.1	
038A.1	
039.1	
039.2	
040.1	
040.2	
042.2	
043.2	
044.2	Material not observed - 2025
044.2M	Material not observed - 2025
045.2	Material not observed - 2025
045.2M	Material not observed - 2025
046.2	
047.1	
048.1	
049.2	
050.1	
050.2	
051.1	
051.2	
053.1	
053.2	
054.1	
054.2	

Chicago Public Schools

School Sumner Academy **Unit** 31221 **Building ID** 6110
Address 4320 W. Fifth **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
055.1	
055.2	
056.1	
056.2	
057.1	
33.2	Material not observed - 2025
34.1	Material not observed - 2025
58	Damage in 2nd Floor Lounge
59	
60	Material not observed - 2025
61	Material not observed - 2025
62	Damage in Room 335
63	
64	
65	
66	
67	
68	Material not observed - 2025
69	Material not observed - 2025
70	Material not observed - 2025
71	Material not observed - 2025
72	
73	Material not observed - 2025
74	Material not observed - 2025
75	Material not observed - 2025
76	Damage in Bathroom 020
77	
78	
A.1	

Chicago Public Schools

School Sumner Academy Unit 31221 Building ID 6110
Address 4320 W. Fifth Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
B.1	
C.1	
C.2	
D.1	
I.1	
J.2	
K.1	
K.2	Material not observed - 2025

Table II
Management Planner's Review

Chicago Public Schools

School Sumner Academy

Unit 31221

Building ID 6110

Address 4320 W. Fifth

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
001.1	Wall/Ceiling Plaster			Throughout	No ACBM	SURFACE					
001.2	Wall/Ceiling Plaster			Throughout	No ACBM	SURFACE					
002.1	1' x 1' Ceiling Tile			Lunch Room	No ACBM	MISC					
002A.1	1' x 1' Acoustic Ceiling Tile			Lunch Room	No ACBM	MISC					
013.1	2' x 4' Acoustic Ceiling Tiles			Room 334	No ACBM	MISC					
013.2	2' x 4' Acoustical Ceiling Tile	750	SF	Room 335	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
016.1	Window Caulk, Green			Teacher's Lounge, Room 131	No ACBM	MISC					
016.2	Window Caulk			Throughout Interior	No ACBM	MISC					
017.1	Masonry Brick			Tank Room, Boiler Room	No ACBM	MISC					
017.2	Masonry Brick Mortar			Engine Room	No ACBM	MISC					
018.1	Masonry Mortar			Tank Room, Boiler Room	No ACBM	MISC					
018.2	Masonry Brick Wall			Engine Room	No ACBM	MISC					
019.1	Wood Wall Board			Basement Stairwell	No ACBM	MISC					
019.2	Wood Wall Board			Room 124	No ACBM	MISC					
020.1	Cinder Block			Tank Room, Boiler Room	No ACBM	MISC					
020.2	Cinder Block			Store Room Across From Assembly Hall	No ACBM	MISC					
021.1	Cinder Block Mortar			Tank Room, Boiler Room	No ACBM	MISC					
021.2	Cinder Block Mortar			Storeroom Across From Assembly Hall	No ACBM	MISC					
022.1	Drywall			Teacher's Lounge, 1st Floor Slop Sink	No ACBM	MISC					
022.2	Drywall			Room 120 and 223	No ACBM	MISC					
023.1	12" x 12" Light Gray w/ Brown and White Streaks Floor Tile			Lunch Room	Assumed	MISC					
023.3	12" x 12" Brown Floor Tile w/ Dark Brown & White Streaks	800	SF	Room 137, 221	Assumed	MISC	No	3	SF	6 ACBM with the potential for damage	Remove
023.4	12" x 12" Beige w/ White & Brown Floor Tile	15,000	SF	1st, 2nd & 3rd Floor Corridors	Chrysotile	MISC	No	20	SF	6 ACBM with the potential for damage	Remove
023.5	12" x 12" Cream Flecks w/ Tan Specks Floor Tile	200	SF	Engineer's Office, Patch in Assembly Hall, 2nd Floor Teacher lounge	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
024.1	12" x 12" Light Gray w/ Brown & White Floor Tile Mastic			Lunch Room	No ACBM	MISC					
024.2	12" x 12" Tan Flecks Floor Tile Mastic			Room 221	Assumed	MISC					
024.3	12" x 12" Brown w/ Dark Brown and white Floor Tile Mastic	800	SF	Room 137, 221	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
024.4	12" x 12" Cream Flecks w/ Tan Specks Vinyl Floor	200	SF	Engineer's Office, Patch in Assembly	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Sumner Academy

Unit 31221

Building ID 6110

Address 4320 W. Fifth

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	Tile Mastic			Hall, 2nd Floor Teacher lounge							
024.5	12" x 12" Beige w/ White & Brown Floor Tile Mastic	15,000	SF	1st, 2nd & 3rd Floor Corridors, Room 024	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
025.1	Brown Vinyl Baseboard			Lunch Room	No ACBM	MISC					
025.2	Light Brown Vinyl Baseboard			Teacher's Lounge	No ACBM	MISC					
026.1	Brown Vinyl Baseboard Adhesive			Lunch Room	No ACBM	MISC					
026.2	Dark Brown Vinyl Baseboard Adhesive	80	LF	Teacher's Lounge	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
027.1	12" x 12" Vinyl Floor Tile, Tan Flecks w/ Brown and White Specks	1,576	SF	Lunchroom, Kitchen	Assumed	MISC	No	10	SF	6 ACBM with the potential for damage	Remove
027.1M	12" x 12" Tan Flecks w/ Brown & White Vinyl Floor Tile Mastic			Lunchroom Kitchen	No ACBM	MISC					
027.2	12" x 12" Tan Flecks w/ Brown & White Vinyl Floor Tile Mastic			Assembly Hall, Gym	No ACBM	MISC					
027.2M	12" x 12" Tan Flecks w/ Brown & White Vinyl Floor Tile Mastic			Assembly Hall, Gym	No ACBM	MISC					
028.1	12" x 12" Vinyl Floor Tile, Beige Flecks w/ Brown and White Specks	332	SF	Room 133, patch in assembly hall	Assumed	MISC	No	5	SF	6 ACBM with the potential for damage	Repair
028.1M	12" x 12" Beige Flecks w/ Brown & White Vinyl Floor Tile Mastic			Room 133	No ACBM	MISC					
028.2	12" x 12" Vinyl Floor Tile, Beige Flecks w/ Brown & White Specks			2nd Floor Corridor	No ACBM	MISC					
028.2M	12" x 12" Beige Flecks w/ Brown & White Vinyl Floor Tile Mastic			2nd Floor Corridor	No ACBM	MISC					
029.1	Vinyl Floor Tile Molding, Brown			Room 133	No ACBM	MISC					
029.2	Vinyl Floor Tile Molding, Brown			Assembly Hall	No ACBM	MISC					
030.1	12" x 12" Vinyl Floor Tile, Brown w/ Dark Brown and White Streaks			Rooms 137, 234	Assumed	MISC					
031.1	12" x 12" Vinyl Floor Tile, Beige w/ Brown and White Streaks			1st Floor Corridor	Assumed	MISC					
031.1M	12" x 12" Beige w/ Brown & White Vinyl Floor Tile Mastic			1st Floor Corridor	Assumed	MISC					
032.1	12" x 12" Vinyl Floor Tile, Light Beige w/ Brown and White Streaks			Room 233	Assumed	MISC					
032.1M	12" x 12" Light Beige w/ Brown & White Vinyl Floor Tile Mastic			Room 223	Assumed	MISC					
033.1	12" x 12" Vinyl Floor Tile, Beige Flecks w/ Brown			2nd Floor Corridor	Assumed	MISC					

Chicago Public Schools

School Sumner Academy

Unit 31221

Building ID 6110

Address 4320 W. Fifth

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	and White Specks										
033.1M	12" x 12" Beige Flks w/ Brown & White Vinyl Floor Tile Mastic			2nd Floor Corridor	No ACBM	MISC					
033.2	12" x 12" Vinyl Floor Tile, Beige w/ Brown and White Streaks			1st, 2nd & 3rd Floor Corridors	Assumed	MISC					
034.1	Black Vinyl Molding			1st and 2nd Floor Corridors	Assumed	MISC					
034.2	Vinyl Floor Tile Molding, Black			Room 220	No ACBM	MISC					
035.1	Light Brown Black Vinyl Molding Mastic			1st and 2nd Floor Corridors	No ACBM	MISC					
035.2	Vinyl Floor Tile Molding Mastic (Light Brown)			Assembly Hall	No ACBM	MISC					
036.1	12" x 12" Vinyl Floor Tile, Beige w/ Blue, Gray, and Rust Streaks			Room 332	Assumed	MISC					
036.1M	12" x 12" Beige ,Blue, Gry & Rust Vinyl Floor Tile Mastic			Room 332	No ACBM	MISC					
037.1	12" x 12" Vinyl Floor Tile, Cream Flecks w/ Tan Specks	200	SF	Engineer's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
038.1	Incinerator Brick			Tank Room	No ACBM	MISC					
038A.1	Incinerator Brick Mortar			Tank Room	No ACBM	MISC					
039.1	Brick			Exterior	No ACBM	MISC					
039.2	Brick			Exterior	No ACBM	MISC					
040.1	Brick Mortar			Exterior	No ACBM	MISC					
040.2	Brick Mortar			Exterior	No ACBM	MISC					
042.2	Glazed Brick			Assembly Hall	No ACBM	MISC					
043.2	Glazed Brick Mortar			Assembly Hall	No ACBM	MISC					
044.2	12" x 12" Vinyl Floor Tile, Beige w/ Blue, Pink, Gray, & Brown			Room 120 121, and 220	Assumed	MISC					
044.2M	12" x 12" Vinyl Floor Tile, Beige, Blue, Pink? Mastic			Room 120 121, and 220	Assumed	MISC					
045.2	12" x 12" Vinyl Floor Tile, Tan w/ Blue, Gray, Brown, Orange & Beige			Room 321	Assumed	MISC					
045.2M	12" x 12" Tan, Black, Gray, Brown, and Gray Vinyl Floor Tile Mastic			Room 321	Assumed	MISC					
046.2	Gray Vinyl Baseboard			Assembly Hall	No ACBM	MISC					
047.1	Boiler Brick	1,200	SF	Boiler Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
048.1	Boiler Brick Mortar	750	SF	Boiler Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
049.2	Fire Doors	300	SF	Throughout Stairwell Areas	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
050.1	Roof - Non-AHERA			Exterior	Assumed	MISC					

Chicago Public Schools

School Sumner Academy

Unit 31221

Building ID 6110

Address 4320 W. Fifth

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
050.2	Roof - Non-AHERA			Exterior	Assumed	MISC					Follow O&M Plan
051.1	Roof Flashing - Non-AHERA			Exterior	Assumed	MISC					
051.2	Roof Flashing - Non-AHERA			Exterior	Assumed	MISC					
053.1	Door Caulk - Non-AHERA			Exterior	Chrysotile	MISC					Follow O&M Plan
053.2	Door Caulk - Non-AHERA			Exterior	Assumed	MISC					Follow O&M Plan
054.1	Window Caulk - Non-AHERA			Exterior	Assumed	MISC					
054.2	Window Caulk - Non-AHERA			Exterior	Assumed	MISC					Follow O&M Plan
055.1	Blue Mixed Carpet Mastic			Room 235	No ACBM	MISC					
055.2	Blue Mixed Carpet Mastic			Room 024	No ACBM	MISC					
056.1	Pink Mixed Carpet Mastic			Room 235 Closet	No ACBM	MISC					
056.2	Pink Mixed Carpet Mastic			Rooms 020, 125, Teacher's Lounge	No ACBM	MISC					
057.1	Brown Mixed Carpet Mastic			Main Office	No ACBM	MISC					
33.2	12" x 12" Vinyl Floor Tile, Beige w/ Brown and White Streaks			1st, 2nd & 3rd Floor Corridors	Assumed	MISC					
34.1	Black Vinyl Molding			1st and 2nd Floor Corridors	Assumed	MISC					
58	12" x 12" Tan w/ Black and White Floor Tile	325	SF	Rooms 122, Teacher's Lounge	Assumed	MISC	No	6	SF	5 ACBM with potential for significant damage	Remove
59	12" x 12" Tan w/ Black and White Floor Tile Mastic	325	SF	Rooms 122, Teachers Lounge	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
60	12" x 12" Tan w/ Blue and Red Floor Tile			Rooms 124, 221	Assumed	MISC					
61	12" x 12" Tan w/ Blue and Red Floor Tile Mastic			Rooms Room 124, 221, 332	Assumed	MISC					
62	12" x 12" Light Brown w/ White and Black Floor Tile	1,750	SF	Rooms 231, 335	Assumed	MISC	No	25	SF	6 ACBM with the potential for damage	Remove
63	12" x 12" Light Brown w/ White and Black Floor Tile Mastic	1,750	SF	Rooms 231, 335	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
64	Black Chalk Board Adhesive	4,000	SF	Classrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
65	Green Chalk Board Adhesive	4,000	SF	Classrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
66	12" x 12" Tan Floor Tile	10,000	SF	Lunch Room 101 (Offices), Rooms 102, faculty Bathroom, 103-107, 109-111, 114-116, PC Lab, 1st Floor Hallway	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
67	12" x 12" Tan Floor Tile Mastic	10,000	SF	Lunch Room 101 (Offices), Rooms 102, faculty Bathroom, 103-107, 109-111, 114-116, PC Lab, 1st Floor Hallway	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
68	12" x 12" Blue/Green /Purple Floor Tile			Room 112	Assumed	MISC					
69	12" x 12" Blue/Gree/Purple Floor Tile Mastic			Room 112	Assumed	MISC					
70	12" x 12" Red Floor Tile			Lunch Room	Assumed	MISC					
71	12" x 12" Red Floor Tile Mastic			Lunch Room	Assumed	MISC					

Chicago Public Schools

School Sumner Academy

Unit 31221

Building ID 6110

Address 4320 W. Fifth

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
72	Green Terrazzo	3,000	SF	Entrance and stairwells	Assumed	SURFACE	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
73	12" x 12' Beige w/ White Specks Floor Tile			Lunchroom	Assumed	MISC					
74	12" x 12' Red w/ White Specks Floor Tile			Lunchroom	Assumed	MISC					
75	12" x 12" Beige w/White Specks & Red w/ White Specks Floor Tile Mastic			Lunchroom	Assumed	MISC					
76	4" x 4" Brown Ceramic Tile	20	SF	Damage in Bathroom 020	Assumed	MISC	No	2	SF	5 ACBM with potential for significant damage	Repair
77	4" x 4" Brown Ceramic Tile Grout	20	SF	Bathroom For Room 020	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
78	4" x 4" Ceramic Tile Mortar	20	SF	020 Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
A.1	Cardboard Pipe Insulation			Main Entrance	No ACBM	MISC					
B.1	Joint Insulation on Cardboard Insulated Piping			Main Entrance	No ACBM	MISC					
C.1	Mag Block Pipe Insulation			ABATED	Abated	TSI					
C.2	Mag-Block Pipe Insulation			ABATED	Abated	TSI					
D.1	Joint Insulation on Mag Block Insulated Piping			ABATED	Abated	TSI					
I.1	Cardboard Duct Wrap			Filter Room	No ACBM	MISC					
J.2	Joint Insulation on Mag Block Insulated Piping			ABATED	Abated	TSI					
K.1	Joint Insulation on Fiberglass Insulated Piping			2nd and 3rd Floor Janitor Closets	No ACBM	MISC					
K.2	Joint Insulation on Fiberglass Insulated Piping			1st and 2nd Floor Girl's Bathrooms and 1st Floor Boy's Bathroom	Assumed	MISC					

Chicago Public Schools

School Sumner Academy

Unit 31221

Building ID 6110

Address 4320 W. Fifth

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	5/19/2025
Manager Planner Name	Jackson Montgomery
100-20634	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
001.1	
001.2	
002.1	
002A.1	
013.1	
013.2	
016.1	
016.2	
017.1	
017.2	
018.1	
018.2	
019.1	
019.2	
020.1	
020.2	
021.1	
021.2	

Chicago Public Schools

School Sumner Academy

Unit 31221

Building ID 6110

Address 4320 W. Fifth

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
022.1	
022.2	
023.1	
023.3	Sample to determine ACM content, remove or repair to intact.
023.4	Remove or repair to intact.
023.5	
024.1	
024.2	
024.3	
024.4	
024.5	
025.1	
025.2	
026.1	
026.2	
027.1	Sample to determine ACM content, remove or repair to intact.
027.1M	
027.2	
027.2M	
028.1	Sample to determine ACM content, remove or repair to intact.
028.1M	
028.2	
028.2M	
029.1	
029.2	
030.1	
031.1	

Chicago Public Schools

School Sumner Academy

Unit 31221

Building ID 6110

Address 4320 W. Fifth

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
031.1M	
032.1	
032.1M	
033.1	
033.1M	
033.2	
034.1	
034.2	
035.1	
035.2	
036.1	
036.1M	
037.1	
038.1	
038A.1	
039.1	
039.2	
040.1	
040.2	
042.2	
043.2	
044.2	
044.2M	
045.2	
045.2M	
046.2	
047.1	

Chicago Public Schools

School Sumner Academy

Unit 31221

Building ID 6110

Address 4320 W. Fifth

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
048.1	
049.2	
050.1	Non-AHERA
050.2	
051.1	Non-AHERA
051.2	Non-AHERA
053.1	
053.2	
054.1	Non-AHERA
054.2	Non-AHERA
055.1	
055.2	
056.1	
056.2	
057.1	
33.2	
34.1	
58	Sample to determine ACM content, remove or repair to intact.
59	
60	
61	
62	Sample to determine ACM content, remove or repair to intact.
63	
64	
65	
66	
67	

Chicago Public Schools

School Sumner Academy

Unit 31221

Building ID 6110

Address 4320 W. Fifth

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
68	
69	
70	
71	
72	
73	
74	
75	
76	Sample to determine ACM content, remove or repair to intact.
77	
78	
A.1	
B.1	
C.1	
C.2	
D.1	
I.1	
J.2	
K.1	
K.2	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **001.1**

MATERIAL DESCRIPTION: **Wall/Ceiling Plaster**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **001.1**

MATERIAL DESCRIPTION: **Wall/Ceiling Plaster**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **001.2**

MATERIAL DESCRIPTION: **Wall/Ceiling Plaster**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **001.2**

MATERIAL DESCRIPTION: **Wall/Ceiling Plaster**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002.1**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **002.1**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**

MATERIAL LOCATION: **Lunch Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002A.1**

MATERIAL DESCRIPTION: **1' x 1' Acoustic Ceiling Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch Room**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **002A.1**

MATERIAL DESCRIPTION: **1' x 1' Acoustic Ceiling Tile**

MATERIAL LOCATION: **Lunch Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **013.1**

MATERIAL DESCRIPTION: **2' x 4' Acoustic Ceiling Tiles**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 334**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **013.1**

MATERIAL DESCRIPTION: **2' x 4' Acoustic Ceiling Tiles**

MATERIAL LOCATION: **Room 334**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	013.2		
MATERIAL DESCRIPTION:	2' x 4' Acoustical Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 335		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **013.2**

MATERIAL DESCRIPTION: **2' x 4' Acoustical Ceiling Tile**

MATERIAL LOCATION: **Room 335**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **016.1**

MATERIAL DESCRIPTION: **Window Caulk, Green**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Teacher's Lounge, Room 131**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **016.1**

MATERIAL DESCRIPTION: **Window Caulk, Green**

MATERIAL LOCATION: **Teacher's Lounge, Room 131**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **016.2**

MATERIAL DESCRIPTION: **Window Caulk**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Interior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **016.2**

MATERIAL DESCRIPTION: **Window Caulk**

MATERIAL LOCATION: **Throughout Interior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **017.1**

MATERIAL DESCRIPTION: **Masonry Brick**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Tank Room, Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **017.1**

MATERIAL DESCRIPTION: **Masonry Brick**

MATERIAL LOCATION: **Tank Room, Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **017.2**

MATERIAL DESCRIPTION: **Masonry Brick Mortar**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engine Room**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **017.2**

MATERIAL DESCRIPTION: **Masonry Brick Mortar**

MATERIAL LOCATION: **Engine Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **018.1**

MATERIAL DESCRIPTION: **Masonry Mortar**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Tank Room, Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **018.1**

MATERIAL DESCRIPTION: **Masonry Mortar**

MATERIAL LOCATION: **Tank Room, Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **018.2**

MATERIAL DESCRIPTION: **Masonry Brick Wall**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engine Room**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **018.2**

MATERIAL DESCRIPTION: **Masonry Brick Wall**

MATERIAL LOCATION: **Engine Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **019.1**

MATERIAL DESCRIPTION: **Wood Wall Board**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Stairwell**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **019.1**

MATERIAL DESCRIPTION: **Wood Wall Board**

MATERIAL LOCATION: **Basement Stairwell**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **019.2**

MATERIAL DESCRIPTION: **Wood Wall Board**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 124**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **019.2**

MATERIAL DESCRIPTION: **Wood Wall Board**

MATERIAL LOCATION: **Room 124**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **020.1**

MATERIAL DESCRIPTION: **Cinder Block**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Tank Room, Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **020.1**

MATERIAL DESCRIPTION: **Cinder Block**

MATERIAL LOCATION: **Tank Room, Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **020.2**

MATERIAL DESCRIPTION: **Cinder Block**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Store Room Across From Assembly Hall**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **020.2**

MATERIAL DESCRIPTION: **Cinder Block**

MATERIAL LOCATION: **Store Room Across From Assembly Hall**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **021.1**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Tank Room, Boiler Room**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **021.1**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

MATERIAL LOCATION: **Tank Room, Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 021.2
MATERIAL DESCRIPTION: Cinder Block Mortar
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Storeroom Across From Assembly Hall

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **021.2**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

MATERIAL LOCATION: **Storeroom Across From Assembly Hall**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **022.1**

MATERIAL DESCRIPTION: **Drywall**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Teacher's Lounge, 1st Floor Slop Sink**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **022.1**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Teacher's Lounge, 1st Floor Slop Sink**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **022.2**

MATERIAL DESCRIPTION: **Drywall**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 120 and 223**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **022.2**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Room 120 and 223**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	023.1		
MATERIAL DESCRIPTION:	12" x 12" Light Gray w/ Brown and White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **023.1**

MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Brown and White Streaks Floor Tile**

MATERIAL LOCATION: **Lunch Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	023.3		
MATERIAL DESCRIPTION:	12" x 12" Brown Floor Tile w/ Dark Brown & White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 137, 221		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:	Damage in Room 221		

Inspector's Signature: _____ Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **023.3**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/ Dark Brown & White Streaks**

MATERIAL LOCATION: **Room 137, 221**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content, remove or repair to intact.

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	023.4		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ White & Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd & 3rd Floor Corridors		
MATERIAL QUANTITY:	15000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in Corridor Outside Room 138		

Inspector's Signature: _____ Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **023.4**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ White & Brown Floor Tile**

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors**

MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	023.5		
MATERIAL DESCRIPTION:	12" x 12" Cream Flecks w/ Tan Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office, Patch in Assembly Hall, 2nd Floor Teacher lounge		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **023.5**

MATERIAL DESCRIPTION: **12" x 12" Cream Flecks w/ Tan Specks Floor Tile**

MATERIAL LOCATION: **Engineer's Office, Patch in Assembly Hall, 2nd Floor Teacher lounge**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **024.1**

MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Brown & White Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **024.1**

MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Brown & White Floor Tile Mastic**

MATERIAL LOCATION: **Lunch Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	024.2		
MATERIAL DESCRIPTION:	12" x 12" Tan Flecks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 221**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **024.2**

MATERIAL DESCRIPTION: **12" x 12" Tan Flecks Floor Tile Mastic**

MATERIAL LOCATION: **Room 221**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	024.3		
MATERIAL DESCRIPTION:	12" x 12" Brown w/ Dark Brown and white Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 137, 221		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **024.3**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ Dark Brown and white Floor Tile Mastic**

MATERIAL LOCATION: **Room 137, 221**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	024.4		
MATERIAL DESCRIPTION:	12" x 12" Cream Flecks w/ Tan Specks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office, Patch in Assembly Hall, 2nd Floor Teacher lounge		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **024.4**

MATERIAL DESCRIPTION: **12" x 12" Cream Flecks w/ Tan Specks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Engineer's Office, Patch in Assembly Hall, 2nd Floor Teacher lounge**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	024.5		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ White & Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd & 3rd Floor Corridors, Room 024		
MATERIAL QUANTITY:	15000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **024.5**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ White & Brown Floor Tile Mastic**

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors, Room 024**

MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **025.1**

MATERIAL DESCRIPTION: **Brown Vinyl Baseboard**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch Room**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **025.1**

MATERIAL DESCRIPTION: **Brown Vinyl Baseboard**

MATERIAL LOCATION: **Lunch Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **025.2**

MATERIAL DESCRIPTION: **Light Brown Vinyl Baseboard**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Teacher's Lounge**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **025.2**

MATERIAL DESCRIPTION: **Light Brown Vinyl Baseboard**

MATERIAL LOCATION: **Teacher's Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	026.1		
MATERIAL DESCRIPTION:	Brown Vinyl Baseboard Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **026.1**

MATERIAL DESCRIPTION: **Brown Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Lunch Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	026.2		
MATERIAL DESCRIPTION:	Dark Brown Vinyl Baseboard Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Teacher's Lounge		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	DAMAGE UNITS: LF		
COMMENTS:			

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **026.2**

MATERIAL DESCRIPTION: **Dark Brown Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Teacher's Lounge**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	027.1		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Tan Flecks w/ Brown and White Specks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom , Kitchen		
MATERIAL QUANTITY:	1576	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in Lunchroom		

Inspector's Signature: _____ Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **027.1**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Tan Flecks w/ Brown and White Specks**

MATERIAL LOCATION: **Lunchroom , Kitchen**

MATERIAL QUANTITY: **1576** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content, remove or repair to intact.

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	027.1M		
MATERIAL DESCRIPTION:	12" x 12" Tan Flecks w/ Brown & White Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom Kitchen**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **027.1M**

MATERIAL DESCRIPTION: **12" x 12" Tan Flecks w/ Brown & White Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom Kitchen**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **027.2**

MATERIAL DESCRIPTION: **12" x 12" Tan Flecks w/ Brown & White Vinyl Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall, Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **027.2**

MATERIAL DESCRIPTION: **12" x 12" Tan Flecks w/ Brown & White Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Assembly Hall, Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	027.2M		
MATERIAL DESCRIPTION:	12" x 12" Tan Flecks w/ Brown & White Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall, Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **027.2M**

MATERIAL DESCRIPTION: **12" x 12" Tan Flecks w/ Brown & White Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Assembly Hall, Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	028.1		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Beige Flecks w/ Brown and White Specks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 133, patch in assembly hall		
MATERIAL QUANTITY:	332	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:	Damage to Patch in Assembly Hall		

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **028.1**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Beige Flecks w/ Brown and White Specks**

MATERIAL LOCATION: **Room 133, patch in assembly hall**

MATERIAL QUANTITY: **332** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content, remove or repair to intact.

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **028.1M**

MATERIAL DESCRIPTION: **12" x 12" Beige Flecks w/ Brown & White Vinyl Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 133**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **028.1M**

MATERIAL DESCRIPTION: **12" x 12"Beige Flecks w/ Brown & White Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 133**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	028.2		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tilematic, Beige Flecks w/ Brown & White Specks		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **028.2**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tilematic, Beige Flecks w/ Brown & White Specks**

MATERIAL LOCATION: **2nd Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **028.2M**

MATERIAL DESCRIPTION: **12" x 12" Beige Flecks w/ Brown & White Vinyl Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **028.2M**

MATERIAL DESCRIPTION: **12" x 12" Beige Flecks w/ Brown & White Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **2nd Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 029.1

MATERIAL DESCRIPTION: Vinyl Floor Tile Molding, Brown

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 133

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **029.1**

MATERIAL DESCRIPTION: **Vinyl Floor Tile Molding, Brown**

MATERIAL LOCATION: **Room 133**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **029.2**

MATERIAL DESCRIPTION: **Vinyl Floor Tile Molding, Brown**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **029.2**

MATERIAL DESCRIPTION: **Vinyl Floor Tile Molding, Brown**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **030.1**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Brown w/ Dark Brown and White Streaks**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 137, 234**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: _____ Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **030.1**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Brown w/ Dark Brown and White Streaks**

MATERIAL LOCATION: **Rooms 137, 234**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 031.1

MATERIAL DESCRIPTION: 12" x 12" Vinyl Floor Tile, Beige w/ Brown and White Streaks

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st Floor Corridor

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **031.1**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Beige w/ Brown and White Streaks**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	031.1M		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Brown & White Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st Floor Corridor

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **031.1M**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Brown & White Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **032.1**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Light Beige w/ Brown and White Streaks**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 233**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: _____

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **032.1**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Light Beige w/ Brown and White Streaks**

MATERIAL LOCATION: **Room 233**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	032.1M		
MATERIAL DESCRIPTION:	12" x 12" Light Beige w/ Brown & White Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 223**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **032.1M**

MATERIAL DESCRIPTION: **12" x 12" Light Beige w/ Brown & White Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 223**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **033.1**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Beige Flecks w/ Brown and White Specks**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: _____

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **033.1**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Beige Flecks w/ Brown and White Specks**

MATERIAL LOCATION: **2nd Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	033.1M		
MATERIAL DESCRIPTION:	12" x 12" Beige Flks w/ Brown & White Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **033.1M**

MATERIAL DESCRIPTION: **12" x 12" Beige Fls w/ Brown & White Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **2nd Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	033.2		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Beige w/ Brown and White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **033.2**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Beige w/ Brown and White Streaks**

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **034.1**

MATERIAL DESCRIPTION: **Black Vinyl Molding**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st and 2nd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **034.1**

MATERIAL DESCRIPTION: **Black Vinyl Molding**

MATERIAL LOCATION: **1st and 2nd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **034.2**

MATERIAL DESCRIPTION: **Vinyl Floor Tile Molding, Black**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 220**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **034.2**

MATERIAL DESCRIPTION: **Vinyl Floor Tile Molding, Black**

MATERIAL LOCATION: **Room 220**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	035.1		
MATERIAL DESCRIPTION:	Light Brown Black Vinyl Molding Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st and 2nd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **035.1**

MATERIAL DESCRIPTION: **Light Brown Black Vinyl Molding Mastic**

MATERIAL LOCATION: **1st and 2nd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **035.2**

MATERIAL DESCRIPTION: **Vinyl Floor Tile Molding Mastic (Light Brown)**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **035.2**

MATERIAL DESCRIPTION: **Vinyl Floor Tile Molding Mastic (Light Brown)**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	036.1		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Beige w/ Blue, Gray, and Rust Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 332**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **036.1**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Beige w/ Blue, Gray, and Rust Streaks**

MATERIAL LOCATION: **Room 332**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 036.1M

MATERIAL DESCRIPTION: 12" x 12" Beige ,Blue, Gry & Rust Vinyl Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 332

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **036.1M**

MATERIAL DESCRIPTION: **12" x 12" Beige ,Blue, Gry & Rust Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 332**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	037.1		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Cream Flecks w/ Tan Specks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **037.1**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Cream Flecks w/ Tan Specks**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **038.1**

MATERIAL DESCRIPTION: **Incinerator Brick**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Tank Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **038.1**

MATERIAL DESCRIPTION: **Incinerator Brick**

MATERIAL LOCATION: **Tank Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **038A.1**

MATERIAL DESCRIPTION: **Incinerator Brick Mortar**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Tank Room**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **038A.1**

MATERIAL DESCRIPTION: **Incinerator Brick Mortar**

MATERIAL LOCATION: **Tank Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **039.1**

MATERIAL DESCRIPTION: **Brick**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **039.1**

MATERIAL DESCRIPTION: **Brick**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **039.2**

MATERIAL DESCRIPTION: **Brick**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **039.2**

MATERIAL DESCRIPTION: **Brick**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **040.1**

MATERIAL DESCRIPTION: **Brick Mortar**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **040.1**

MATERIAL DESCRIPTION: **Brick Mortar**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **040.2**

MATERIAL DESCRIPTION: **Brick Mortar**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **040.2**

MATERIAL DESCRIPTION: **Brick Mortar**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **042.2**

MATERIAL DESCRIPTION: **Glazed Brick**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **042.2**

MATERIAL DESCRIPTION: **Glazed Brick**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **043.2**

MATERIAL DESCRIPTION: **Glazed Brick Mortar**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **043.2**

MATERIAL DESCRIPTION: **Glazed Brick Mortar**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	044.2		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Beige w/ Blue, Pink, Gray, & Brown		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 120 121, and 220**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **044.2**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Beige w/ Blue, Pink, Gray, & Brown**

MATERIAL LOCATION: **Room 120 121, and 220**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **044.2M**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Beige, Blue, Pink? Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 120 121, and 220**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **044.2M**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Beige, Blue, Pink? Mastic**

MATERIAL LOCATION: **Room 120 121, and 220**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **045.2**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Tan w/ Blue, Gray, Brown, Orange & Beige**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 321**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: _____

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **045.2**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Tan w/ Blue, Gray, Brown, Orange & Beige**

MATERIAL LOCATION: **Room 321**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	045.2M		
MATERIAL DESCRIPTION:	12" x 12" Tan, Black, Gray, Brown, and Gray Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 321

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **045.2M**

MATERIAL DESCRIPTION: **12" x 12" Tan, Black, Gray, Brown, and Gray Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 321**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **046.2**

MATERIAL DESCRIPTION: **Gray Vinyl Baseboard**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **046.2**

MATERIAL DESCRIPTION: **Gray Vinyl Baseboard**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	047.1		
MATERIAL DESCRIPTION:	Boiler Brick		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **047.1**

MATERIAL DESCRIPTION: **Boiler Brick**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	048.1		
MATERIAL DESCRIPTION:	Boiler Brick Mortar		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **048.1**

MATERIAL DESCRIPTION: **Boiler Brick Mortar**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	049.2		
MATERIAL DESCRIPTION:	Fire Doors		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Stairwell Areas		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **049.2**

MATERIAL DESCRIPTION: **Fire Doors**

MATERIAL LOCATION: **Throughout Stairwell Areas**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **050.1**

MATERIAL DESCRIPTION: **Roof - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **050.1**

MATERIAL DESCRIPTION: **Roof - Non-AHERA**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Non-AHERA

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **050.2**

MATERIAL DESCRIPTION: **Roof - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **050.2**

MATERIAL DESCRIPTION: **Roof - Non-AHERA**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	051.1		
MATERIAL DESCRIPTION:	Roof Flashing - Non-AHERA		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **051.1**

MATERIAL DESCRIPTION: **Roof Flashing - Non-AHERA**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Non-AHERA

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	051.2		
MATERIAL DESCRIPTION:	Roof Flashing - Non-AHERA		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **051.2**

MATERIAL DESCRIPTION: **Roof Flashing - Non-AHERA**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Non-AHERA

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	053.1		
MATERIAL DESCRIPTION:	Door Caulk - Non-AHERA		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **053.1**

MATERIAL DESCRIPTION: **Door Caulk - Non-AHERA**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	053.2		
MATERIAL DESCRIPTION:	Door Caulk - Non-AHERA		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **053.2**

MATERIAL DESCRIPTION: **Door Caulk - Non-AHERA**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	054.1		
MATERIAL DESCRIPTION:	Window Caulk - Non-AHERA		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **054.1**

MATERIAL DESCRIPTION: **Window Caulk - Non-AHERA**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Non-AHERA

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **054.2**

MATERIAL DESCRIPTION: **Window Caulk - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **054.2**

MATERIAL DESCRIPTION: **Window Caulk - Non-AHERA**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Non-AHERA

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **055.1**

MATERIAL DESCRIPTION: **Blue Mixed Carpet Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 235**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **055.1**

MATERIAL DESCRIPTION: **Blue Mixed Carpet Mastic**

MATERIAL LOCATION: **Room 235**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **055.2**

MATERIAL DESCRIPTION: **Blue Mixed Carpet Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 024**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **055.2**

MATERIAL DESCRIPTION: **Blue Mixed Carpet Mastic**

MATERIAL LOCATION: **Room 024**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **056.1**

MATERIAL DESCRIPTION: **Pink Mixed Carpet Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 235 Closet**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **056.1**

MATERIAL DESCRIPTION: **Pink Mixed Carpet Mastic**

MATERIAL LOCATION: **Room 235 Closet**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **056.2**

MATERIAL DESCRIPTION: **Pink Mixed Carpet Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 020, 125, Teacher's Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **056.2**

MATERIAL DESCRIPTION: **Pink Mixed Carpet Mastic**

MATERIAL LOCATION: **Rooms 020, 125, Teacher's Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **057.1**

MATERIAL DESCRIPTION: **Brown Mixed Carpet Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **057.1**

MATERIAL DESCRIPTION: **Brown Mixed Carpet Mastic**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33.2	
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Beige w/ Brown and White Streaks	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st, 2nd & 3rd Floor Corridors

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **33.2**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Beige w/ Brown and White Streaks**

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34.1**

MATERIAL DESCRIPTION: **Black Vinyl Molding**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st and 2nd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **34.1**

MATERIAL DESCRIPTION: **Black Vinyl Molding**

MATERIAL LOCATION: **1st and 2nd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	12" x 12" Tan w/ Black and White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 122, Teacher's Lounge		
MATERIAL QUANTITY:	325	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in 2nd Floor Lounge		

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **12" x 12" Tan w/ Black and White Floor Tile**

MATERIAL LOCATION: **Rooms 122, Teacher's Lounge**

MATERIAL QUANTITY: **325** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **6** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content, remove or repair to intact.

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	59		
MATERIAL DESCRIPTION:	12" x 12" Tan w/ Black and White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 122, Teachers Lounge		
MATERIAL QUANTITY:	325	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **12" x 12" Tan w/ Black and White Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 122, Teachers Lounge**

MATERIAL QUANTITY: **325** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	60	
MATERIAL DESCRIPTION:	12" x 12" Tan w/ Blue and Red Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:	Physical Damage	
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 124, 221**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **12" x 12" Tan w/ Blue and Red Floor Tile**

MATERIAL LOCATION: **Rooms 124, 221**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	61	
MATERIAL DESCRIPTION:	12" x 12" Tan w/ Blue and Red Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms Room 124, 221, 332**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **12" x 12" Tan w/ Blue and Red Floor Tile Mastic**

MATERIAL LOCATION: **Rooms Room 124, 221, 332**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	62		
MATERIAL DESCRIPTION:	12" x 12" Light Brown w/ White and Black Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Water		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 231, 335		
MATERIAL QUANTITY:	1750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in Room 335		

Inspector's Signature: _____ Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ White and Black Floor Tile**

MATERIAL LOCATION: **Rooms 231, 335**

MATERIAL QUANTITY: **1750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **25** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content, remove or repair to intact.

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	63		
MATERIAL DESCRIPTION:	12" x 12" Light Brown w/ White and Black Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 231, 335		
MATERIAL QUANTITY:	1750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ White and Black Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 231, 335**

MATERIAL QUANTITY: **1750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	64		
MATERIAL DESCRIPTION:	Black Chalk Board Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **Black Chalk Board Adhesive**

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	65		
MATERIAL DESCRIPTION:	Green Chalk Board Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **Green Chalk Board Adhesive**

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	66		
MATERIAL DESCRIPTION:	12" x 12" Tan Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunch Room 101 (Offices), Rooms 102, faculty Bathroom, 103-107, 109-111, 114-116, PC Lab, 1st Floor Hallway**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile**

MATERIAL LOCATION: **Lunch Room 101 (Offices), Rooms 102, faculty Bathroom, 103-107, 109-111, 114-116, PC Lab, 1st Floor Hallway**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	67		
MATERIAL DESCRIPTION:	12" x 12" Tan Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunch Room 101 (Offices), Rooms 102, faculty Bathroom, 103-107, 109-111, 114-116, PC Lab, 1st Floor Hallway**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile Mastic**

MATERIAL LOCATION: **Lunch Room 101 (Offices), Rooms 102, faculty Bathroom, 103-107, 109-111, 114-116, PC Lab, 1st Floor Hallway**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	68	
MATERIAL DESCRIPTION:	12" x 12" Blue/Green /Purple Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 112**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **12" x 12" Blue/Green /Purple Floor Tile**

MATERIAL LOCATION: **Room 112**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	69	
MATERIAL DESCRIPTION:	12" x 12" Blue/Gree/Purple Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 112**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **12" x 12" Blue/Gree/Purple Floor Tile Mastic**

MATERIAL LOCATION: **Room 112**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	70	
MATERIAL DESCRIPTION:	12" x 12" Red Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile**

MATERIAL LOCATION: **Lunch Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	71		
MATERIAL DESCRIPTION:	12" x 12" Red Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile Mastic**

MATERIAL LOCATION: **Lunch Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	72		
MATERIAL DESCRIPTION:	Green Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Entrance and stairwells		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **Green Terrazzo**

MATERIAL LOCATION: **Entrance and stairwells**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	73	
MATERIAL DESCRIPTION:	12" x 12' Beige w/ White Specks Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:	Physical Damage	
HISTORICAL RESPONSE ACTION:	Remove	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **12" x 12' Beige w/ White Specks Floor Tile**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	74	
MATERIAL DESCRIPTION:	12" x 12' Red w/ White Specks Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **12" x 12' Red w/ White Specks Floor Tile**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	75		
MATERIAL DESCRIPTION:	12" x 12" Beige w/White Specks & Red w/ White Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **12" x 12" Beige w/White Specks & Red w/ White Specks Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A.1**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Entrance**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **04/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **A.1**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **Main Entrance**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B.1**

MATERIAL DESCRIPTION: **Joint Insulation on Cardboard Insulated Piping**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Entrance**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **B.1**

MATERIAL DESCRIPTION: **Joint Insulation on Cardboard Insulated Piping**

MATERIAL LOCATION: **Main Entrance**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C.1**

MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **C.1**

MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C.2**

MATERIAL DESCRIPTION: **Mag-Block Pipe Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **C.2**

MATERIAL DESCRIPTION: **Mag-Block Pipe Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: D.1

MATERIAL DESCRIPTION: Joint Insulation on Mag Block Insulated Piping

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **D.1**

MATERIAL DESCRIPTION: **Joint Insulation on Mag Block Insulated Piping**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	I.1	
MATERIAL DESCRIPTION:	Cardboard Duct Wrap	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Filter Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **I.1**

MATERIAL DESCRIPTION: **Cardboard Duct Wrap**

MATERIAL LOCATION: **Filter Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	J.2		
MATERIAL DESCRIPTION:	Joint Insulation on Mag Block Insulated Piping		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **J.2**

MATERIAL DESCRIPTION: **Joint Insulation on Mag Block Insulated Piping**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	K.1		
MATERIAL DESCRIPTION:	Joint Insulation on Fiberglass Insulated Piping		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd and 3rd Floor Janitor Closets**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **K.1**

MATERIAL DESCRIPTION: **Joint Insulation on Fiberglass Insulated Piping**

MATERIAL LOCATION: **2nd and 3rd Floor Janitor Closets**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	K.2		
MATERIAL DESCRIPTION:	Joint Insulation on Fiberglass Insulated Piping		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st and 2nd Floor Girl's Bathrooms and 1st Floor Boy's Bathroom

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUILDING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **K.2**

MATERIAL DESCRIPTION: **Joint Insulation on Fiberglass Insulated Piping**

MATERIAL LOCATION: **1st and 2nd Floor Girl's Bathrooms and 1st Floor Boy's Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	76			
MATERIAL DESCRIPTION:	4" x 4" Brown Ceramic Tile			
MATERIAL LOCATION:	Damage in Bathroom 020			
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	Damaged	
AHERA DAMAGE CATEGORY:	5 ACBM with potential for significant damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:	2	DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:	Damage in Bathroom 020			

Inspector's Signature:

Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **4" x 4" Brown Ceramic Tile**

MATERIAL LOCATION: **Damage in Bathroom 020**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content, remove or repair to intact.

Management Planner's Signature:



Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	77			
MATERIAL DESCRIPTION:	4" x 4" Brown Ceramic Tile Grout			
MATERIAL LOCATION:	Bathroom For Room 020			
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **4" x 4" Brown Ceramic Tile Grout**

MATERIAL LOCATION: **Bathroom For Room 020**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **05/19/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Sumner Academy	INSPECTION DATE:	4/25/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	78		
MATERIAL DESCRIPTION:	4" x 4" Ceramic Tile Mortar		
MATERIAL LOCATION:	020 Bathroom		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31221	BUIDLING ID:	6110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Sumner Academy	REVIEW DATE:	5/19/2025		
ADDRESS:	4320 W. Fifth	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **4" x 4" Ceramic Tile Mortar**

MATERIAL LOCATION: **020 Bathroom**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:





Management Planner's Signature: *Jackson Montgomery* Date: **05/19/2025**

APPENDIX B

Inspector and Management Planner Licenses

Jackson Montgomery

Illinois Licensed Building Inspector, Air Sampling Professional, Management Planner





2200 Vandalia Street, Collinsville, IL 62234 * Phone: 618-855-8764

Environmental and Occupational Safety & Health Training

Does hereby certify

Jackson Montgomery

600 W. Van Buren St., Suite 500, Chicago, IL 60607



*Has successfully completed and passed the course examination with at least
70% for accreditation under AHERA (Title II)*

Asbestos Management Planner Initial

Class Date: 10/28-29/2024

Examination Date: 10/29/2024

STC Certificate Number: STC-20241029-000101AMPI

Certification Expiration: 10/29/2025

A handwritten signature in black ink that reads 'David M. Mendoza'.

David M. Mendoza – President/Training Director

Certified Environmental Specialist

OSHA Authorized Instructor

This training course is accredited by the Illinois Department of Public Health and the Missouri Department of Natural Resources

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed