

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2846  
SCHOOL NAME: Clark Academic Prep HS  
ADDRESS OF SCHOOL: 5101 W. Harrison  
CITY: Chicago, IL, 60644

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 9/21/2022


**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II (Please type or print)**

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 7/2/2025 ENROLLMENT 436  
IDPH INSPECTOR LICENSE NUMBER: 100-20411  
IDPH LICENSED INSPECTOR NAME (Please Print): Benyamen Maradkel  
IDPH MP LICENSE NUMBER: 100-20634  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jackson Montgomery

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

 8/1/2025  
*Richard J. Schleyer*  
Signature of Designated Person Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Clark Academic Prep HS**

5101 W. Harrison  
Chicago, IL, 60644

Unit: 41051  
Building ID: 6620

IDPH ID Number: 14-016-2990-2846

**REPORT DATE:**  
Friday, August 01, 2025

**Prepared for:**  
**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**  
**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

08/01/2025

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299      Unit: 41051      Region: 03      IDPH ID: 14-016-2990-2846

School: Clark Academic Prep HS      Building ID: 6620

Address: 5101 W. Harrison

Chicago, IL, 60644

Building Contact: Curran, Thomas      Contact Phone: 3126137428

Current Building Owners: Chicago Public Schools

Reinspection Date: 7/2/2025

Review Date: 08/01/2025

Inspector: Benyamen Maradkel

Inspector IDPH License: 100-20411

Management Planner: Jackson Montgomery

Management Planner IDPH License: 100-20634

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates



Jackson Montgomery  
100-20634

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: August 01, 2025

RE: Clark Academic Prep HS, Unit 41051  
5101 W. Harrison  
Chicago, IL, 60644

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Clark Academic Prep HS , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Clark Academic Prep HS, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Clark Academic Prep HS      Unit: 41051      Region: 03  
Address: 5101 W. Harrison      Chicago, IL, 60644  
IDPH ID: 14-016-2990-2846      Building ID: 6620  
Contact: Curran, Thomas      Phone: 3126137428

### 2. Description of Facility

Original Construction: 1972      Additional Construction:  
Total Square Footage: 150700      No of Floors: 2  
Current Occupancy: 436

### 3. LEA Designated Person

Contact: Richard J.Schleyer      Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Doug McCormick  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900      Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Benyamen Maradkel

Inspector IDPH license # 100-20411  
Reinspection Date: 7/2/2025



Signature:  
Date: 7/2/2025

### 6. Management Planner

Management Planner Name: Jackson Montgomery

Management Planner IDPH license # 100-20634




Signature:  
Date: 08/01/2025

### 7. Review Date: 08/01/2025

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Richard J. Schleyer

Date: 8/1/2025

Name: Richard J.Schleyer

## **II. EXECUTIVE SUMMARY**

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Clark Academic Prep HS. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

- A. The following HAs have changed assessment categories for Building 6620:

B. The following new homogenous areas have been identified for Building 6620:

106	Black, Gray, White Epoxy Flooring
107	12" x 12" Blue Ceramic Floor Tile and Grout

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

100	12" x 12" Light Gray Mottled Floor Tile
101	12" x 12" Light Gray Mottled Floor Tile Mastic
102	12" x 12" White w/ Tan Streaks Floor Tile
103	12" x 12" White w/ Tan Streaks Floor Tile Mastic
104	Gray and Blue Streaked Carpet Mastic
105	Pool Heater Duct Insulation
106	Black, Gray, White Epoxy Flooring
107	12" x 12" Blue Ceramic Floor Tile and Grout
2	12" x 12" Yellow Floor Tile
5	12" x 12" Brown Speckled Floor Tile
54	Purple/Lavender/Tan Ceramic Tile Grout
55	Wall Tile Caulk
56	Wall Tile Adhesive
57	Blue Carpet Mastic
58	Orange Carpet Mastic
59	Gray Carpet Mastic
60	12" x 12" Light Gray Floor Tile
61	12" x 12" Light Gray Floor Tile Mastic
67	12" x 12" Blue Floor Tile
68	12" x 12" Blue Floor Tile Mastic
69	Purple Carpet Mastic
71	12" x 12" Beige Floor Tile Mastic
76	Blue Linoleum Flooring
77	Blue Linoleum Mastic
78	12" x 12" Dark Brown w/ Light Gray Specks Floor Tile
79	12" x 12" Dark Brown w/ Light Gray Specks Floor Tile Mastic
80	Ceramic Floor Grout
81	12" x 12" Brown w/ Grayish White Specks Floor Tile
82M	12" x 12" Brown w/ Grayish White Specks Floor Tile Mastic
83	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile
84	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile Mastic
85	1' x 1' Smooth Ceiling Tiles
86	1' x 1' Smooth Ceiling Tile Adhesive
87	Beige Speckled Floor Tile
88	Brown Carpet Adhesive
89	12" x 12" White w/ Dark Gray Streaks Floor Tile

90	12" x 12" White w/ Dark Gray Streaks Floor Tile Mastic
91	Vapor Barrier for Wood Tongue and Groove Flooring
92	12" x 12" Yellow w/ Blue Streaks Floor Tile
93	12" x 12" Gray Mottled Floor Tile
94	12" x 12" Dark Gray Mottled Floor Tile
95	12" x 12" Gray Mottled, Dark Gray Mottled, and Yellow w/ Blue Streaks Floor Tile Mastic
96	2' x 2' Rough Texture Ceiling Tile
97	Blue Carpet Adhesive
98	Fire Door
99	Gray Pattern Carpet Mastic
AA	Pink/White Flooring Material
BB	HA A Mastic

The following areas were deemed to be inaccessible:

17B	12" x 12" Brown Speckled Floor Tile Mastic
25	12" x 12" Maroon w/ White Flecks Floor Tile Mastic
37	12" x 12" White w/ Gray Streaks Floor Tile Mastic
55	Wall Tile Caulk
57	Blue Carpet Mastic
59	Gray Carpet Mastic
68	12" x 12" Blue Floor Tile Mastic
69	Purple Carpet Mastic
71	12" x 12" Beige Floor Tile Mastic
77	Blue Linoleum Mastic
79	12" x 12" Dark Brown w/ Light Gray Specks Floor Tile Mastic
82M	12" x 12" Brown w/ Grayish White Specks Floor Tile Mastic
84	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile Mastic
86	1' x 1' Smooth Ceiling Tile Adhesive
97	Blue Carpet Adhesive

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Benyamen Maradkel, IDPH License # 100-20411. The Management Plan was updated by Jackson Montgomery, IDPH License # 100-20634. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Clark Academic Prep HS Building 6620 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

**School** Clark Academic Prep HS **Unit** 41051 **Building ID** 6620  
**Address** 5101 W. Harrison **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	12" x 12" Brown w/ Pink & White Streaks Floor Tile	20,000	SF	Rooms 107, 115, 116, 215, 242, 248, Boys and Girls Locker Rooms, Storages and Basement 249a, 249b, 1st Floor Corridor, 2nd Floor Corridor, 203, 206, 128, Pool	CHR	MISC	N	NONE				ACBM with the potential for damage		LOW
100	12" x 12" Light Gray Mottled Floor Tile	300	SF	Room 147	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
101	12" x 12" Light Gray Mottled Floor Tile Mastic	300	SF	Room 147	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
102	12" x 12" White w/ Tan Streaks Floor Tile	1,200	SF	Room 110, 109b	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
103	12" x 12" White w/ Tan Streaks Floor Tile Mastic	1,200	SF	Room 110, 109b	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
104	Gray and Blue Streaked Carpet Mastic	2,500	SF	Gurley Center	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
105	Pool Heater Duct Insulation	30	LF	Pump Room	ASSUMED	TSI	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		MODERATE
106	Black, Gray, White Epoxy Flooring	500	SF	Room 122	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		MODERATE
107	12" x 12" Blue Ceramic Floor Tile and Grout	50	SF	Engineers office	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		MODERATE
11	Spray on Fire Proofing			Inaccessible, Access to Roof Area by Girls Locker Room	CHR	SURFACE								
12	Cementitious Fitting Insulation on Cold Water Line			Throughout	NO_ACBM	TSI								
13	Cementitious Fitting Insulation on Hot Water Lines			Throughout	NO_ACBM	TSI								
14	Water Tank Insulation	280	SF	Basement	AMO	TSI	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		LOW
15	Tank Breeching on Domestic Hot Water Tank			Pool Mechanical Room	NO_ACBM	MISC								
16	Metal 2' x 4' Lay-in Ceiling Panels (Not a Suspect Material)			Throughout Facility	NOT_TESTED	MISC								
17A	12" x 12" Yellow Floor Tile Mastic			ABATED	ABATED	MISC								
17B	12" x 12" Brown Speckled Floor Tile Mastic	30,000	SF	1st & 2nd Floor Corridors, 227	CHR	MISC	N	NONE				ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Clark Academic Prep HS **Unit** 41051 **Building ID** 6620  
**Address** 5101 W. Harrison **Region** 03

## **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

## Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

***Inspector's Comments are Summarized at the End of the Report***

# Chicago Public Schools

**School** Clark Academic Prep HS **Unit** 41051 **Building ID** 6620  
**Address** 5101 W. Harrison **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				and Boys Locker Rooms										
3	12" x 12" Beige Floor Tile			2nd Floor Corridor	NO_ACBM	MISC								
30	Cinder Block			Throughout Facility	NO_ACBM	MISC								
31	Cinder Block Mortar			Throughout Facility	NO_ACBM	MISC								
32	Wall Tile Adhesive			Boys Pool Locker Room	NO_ACBM	MISC								
33	Wall Tile Caulk			Boys Pool Locker Room	NO_ACBM	MISC								
34	Clay Floor Tile			Kitchen	NO_ACBM	MISC								
35	Clay Floor Tile Mortar			Kitchen	NO_ACBM	MISC								
36	Ceramic Wall Grout			Kitchen	NO_ACBM	MISC								
37	12" x 12" White w/ Gray Streaks Floor Tile Mastic	1,728	SF	Corridor Between Kitchens and Pool, Industrial Arts, Engineer's Office, Rooms 230 and 232, South Stairwell Landings, Kitchen Storage, Basement Storage	CHR	MISC	N	NONE			ACBM with the potential for damage		LOW	
38	Terrazzo			Stairways and Landings	NO_ACBM	SURFACE								
39	Brown Ceramic Tile Grout			Boys Bathrooms, Mens Bathrooms, kitchen	NO_ACBM	MISC								
4	12" x 12" White w/ Gray Streaks Floor Tile	1,728	SF	Corridor Between Kitchens and Pool, Industrial Arts, Engineer's Office, Rooms 230 and 232, South Stairwell Landings, Kitchen Storage, Basement Storage	CHR	MISC	N	NONE			ACBM with the potential for damage		LOW	
40	Yellow Ceramic Tile Grout			Girls Bathrooms, Womens Bathrooms	NO_ACBM	MISC								
41	White Ceramic Wall Tile Grout			Custodial Rooms in Boys Bathrooms	NO_ACBM	MISC								
42	Terrazzo Basins			Custodial Rooms in Boys Bathrooms	NO_ACBM	MISC								
43	4" Black Vinyl Baseboard			Throughout Facility	NO_ACBM	MISC								
44	4" Black Vinyl Baseboard Mastic			Throughout Facility	NO_ACBM	MISC								
45	12" x 12" Brown w/ Pink & White Streaks	20,000	SF	Rooms 107, 115,	CHR	MISC	N	NONE			ACBM with the		MODERATE	

## Chicago Public Schools

**School** Clark Academic Prep HS **Unit** 41051 **Building ID** 6620  
**Address** 5101 W. Harrison **Region** 03

## **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

## Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

## ***Inspector's Comments are Summarized at the End of the Report***

# Chicago Public Schools

**School** Clark Academic Prep HS **Unit** 41051 **Building ID** 6620  
**Address** 5101 W. Harrison **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
62	Exterior Door Caulk - Non-AHERA			Building Exterior	NO_ACBM	MISC								
63	12" x 12" Light Brown Floor Tile w/ Dark Brown Streaks			ABATED	ABATED	MISC								
64	12" x 12" Light Brown Floor Tile w/ Dark Brown Streaks Mastic			ABATED	ABATED	MISC								
65	Exterior Brick - Non-AHERA			Building Exterior	NO_ACBM	MISC								
66	Exterior Brick Mortar - Non-AHERA			Building Exterior	NO_ACBM	MISC								
67	12" x 12" Blue Floor Tile	200	SF	MDF Room in 116	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
68	12" x 12" Blue Floor Tile Mastic	200	SF	MDF Room in 116	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
69	Purple Carpet Mastic	556	SF	Room 107, 151, Activity center	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
7	Plaster Ceilings and Walls			Throughout Facility	NO_ACBM	SURFACE								
70	Purple Carpet Mastic			1st & 2nd Floor Corridors, Faculty Lounge, 123-125, -145, 147, 149, 155, 150-154, Lockers, 216	NO_ACBM	MISC								
71	12" x 12" Beige Floor Tile Mastic	500	SF	2nd Floor Corridor	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
75	Transite Panel in Floor Radiators	4,000	SF	Rooms	CHR	MISC								
76	Blue Linoleum Flooring	3,600	SF	Rooms 223, 223a, 221, 241, 241 and 243, Elevator	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
77	Blue Linoleum Mastic	3,600	SF	Rooms 223, 223a, 221, 241, 241 and 243, Elevator	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
78	12" x 12" Dark Brown w/ Light Gray Specks Floor Tile	400	SF	1st Floor Activity Center Near Stairs, Gymnasium Vestibule	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
79	12" x 12" Dark Brown w/ Light Gray Specks Floor Tile Mastic	400	SF	1st Floor Activity Center Near Stairs, Gymnasium Vestibule	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
8	Lab Table Tops	400	SF	Rooms 243, 241, 221, 221a, 223	CHR	MISC	N	NONE			ACBM with the potential for damage		LOW	
80	Ceramic Floor Grout	4,500	SF	Pool, 1st & 2nd Floor Girls and Boys Bathrooms and Lockers	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
81	12" x 12" Brown w/ Grayish White Specks	3,800	SF	Front Entrance	ASSUMED	MISC	N	NONE			ACBM with the		LOW	

# Chicago Public Schools

**School** Clark Academic Prep HS **Unit** 41051 **Building ID** 6620  
**Address** 5101 W. Harrison **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Floor Tile			Hallway								potential for damage		
82M	12" x 12" Brown w/ Grayish White Specks Floor Tile Mastic	3,800	SF	Front Entrance Hallway	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
83	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile	1,000	SF	Rooms 109 and 205	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
84	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile Mastic	1,000	SF	Rooms 109 and 205	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
85	1' x 1' Smooth Ceiling Tiles	2,000	SF	Kitchen	ASSUMED	MISC	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		LOW
86	1' x 1' Smooth Ceiling Tile Adhesive	2,000	SF	Kitchen	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
87	Beige Speckled Floor Tile	50	SF	Cafeteria	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
88	Brown Carpet Adhesive	900	SF	Room 231, 233, 253, 251, 250, 248, 247, 244, 242, 240, 200, 218, 220, 220a, 225, 226, 209, 214, 210, 213, 211, 220 Storage, 201, 202, 153, 154, Receiving Room 106, 133, 134, 127, 128, 234, 207, 245, 224, 222, 214, 217, 204, 130, 132, 131, nurse office, office 148, 124, Guidance office	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
89	12" x 12" White w/ Dark Gray Streaks Floor Tile	1,500	SF	Room 208, 109 Storage Room	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
9	Mag Block Duct Insulation	300	LF	Kitchen & Storage Area in Basement, boiler room	CHR	TSI	Y	LOC	5	LF		Damaged or significantly damaged friable thermal system insulating ACBM	5	MODERATE
90	12" x 12" White w/ Dark Gray Streaks Floor Tile Mastic	1,500	SF	Room 208, 109 Storage Room	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
91	Vapor Barrier for Wood Tongue and Groove Flooring	3,000	SF	Gym	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
92	12" x 12" Yellow w/ Blue Streaks Floor Tile	500	SF	2nd Floor Locker Rooms, 205, 252 109	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
93	12" x 12" Gray Mottled Floor Tile	300	SF	2nd Floor Locker	ASSUMED	MISC	N	NONE				ACBM with the		LOW

# Chicago Public Schools

**School** Clark Academic Prep HS **Unit** 41051 **Building ID** 6620  
**Address** 5101 W. Harrison **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Rooms, 205, 252, 109								potential for damage		
94	12" x 12" Dark Gray Mottled Floor Tile	300	SF	2nd Floor Locker Rooms, 205, 252, 109	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
95	12" x 12" Gray Mottled, Dark Gray Mottled, and Yellow w/ Blue Streaks Floor Tile Mastic	1,100	SF	2nd Floor Locker Rooms, 205, 252 109	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
96	2' x 2' Rough Texture Ceiling Tile	2,500	SF	Room143 Offices	ASSUMED	MISC	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		LOW
97	Blue Carpet Adhesive	1,000	SF	Room 212	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
98	Fire Door	50	SF	Floor 1 Book Room	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
99	Gray Pattern Carpet Mastic	1,500	SF	Room 143 Offices	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
AA	Pink/White Flooring Material			Rooms 142,	ASSUMED	MISC								
BB	HA A Mastic			Rooms 221, 241, 122, 222, 242	ASSUMED	MISC								
CC	Panels Over Moveable Doors Room Divide	2,850	SF	123/121, 132/134, 152/154, 232/234, 252/254, House Commons 1, 2 and Gym	CHR	MISC	N	NONE				ACBM with the potential for damage		LOW

# Chicago Public Schools

School Clark Academic Prep HS Unit 41051 Building ID 6620  
Address 5101 W. Harrison Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <u>7/2/2025</u>
Inspector Name <u>Benyamen Maradkel</u>
<u>100-20411</u> <u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date

#### Inspector's Comments

HA Number:	Inspector Comments:
1	
100	
101	
102	
103	
104	
105	
106	
107	
11	Material in inaccessible area(s) - 2025
12	
13	
14	
15	
16	Material not observed - 2025
17A	
17B	
18	
19	
2	Material not observed - 2025
20	
21	
22	
23	Material not observed - 2025

# Chicago Public Schools

**School** Clark Academic Prep HS **Unit** 41051 **Building ID** 6620  
**Address** 5101 W. Harrison **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
24	
25	
26	
27	
28	
29	
3	
30	
31	
32	
33	
34	
35	
36	Material not observed - 2025
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
5	

# Chicago Public Schools

**School** Clark Academic Prep HS **Unit** 41051 **Building ID** 6620  
**Address** 5101 W. Harrison **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
50	
51	
52	
53	
54	Material not observed - 2025
55	
56	
57	
58	Material not observed - 2025
59	
6	
60	Material not observed - 2025
61	Material not observed - 2025
62	
63	
64	
65	
66	
67	
68	
69	
7	
70	
71	
75	Material in inaccessible area(s) - 2025
76	
77	
78	
79	

# Chicago Public Schools

**School** Clark Academic Prep HS **Unit** 41051 **Building ID** 6620  
**Address** 5101 W. Harrison **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
8	
80	
81	
82M	
83	
84	
85	
86	
87	
88	
89	
9	Damage in: Boiler Room
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
AA	Material not observed - 2025
BB	Material not observed - 2025
CC	

# Chicago Public Schools

**School** Clark Academic Prep HS **Unit** 41051 **Building ID** 6620  
**Address** 5101 W. Harrison **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500  
Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

**Table II**  
**Management Planner's Review**

---

# Chicago Public Schools

**School** Clark Academic Prep HS

**Unit** 41051

**Building ID** 6620

**Address** 5101 W. Harrison

Chicago, IL, 60644

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	12" x 12" Brown w/ Pink & White Streaks Floor Tile	20,000	SF	Rooms 107, 115, 116, 215, 242, 248, Boys and Girls Locker Rooms, Storages and Basement 249a, 249b, 1st Floor Corridor, 2nd Floor Corridor, 203, 206, 128, Pool	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
100	12" x 12" Light Gray Mottled Floor Tile	300	SF	Room 147	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
101	12" x 12" Light Gray Mottled Floor Tile Mastic	300	SF	Room 147	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
102	12" x 12" White w/ Tan Streaks Floor Tile	1,200	SF	Room 110, 109b	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
103	12" x 12" White w/ Tan Streaks Floor Tile Mastic	1,200	SF	Room 110, 109b	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
104	Gray and Blue Streaked Carpet Mastic	2,500	SF	Gurley Center	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
105	Pool Heater Duct Insulation	30	LF	Pump Room	Assumed	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
106	Black, Gray, White Epoxy Flooring	500	SF	Room 122	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
107	12" x 12" Blue Ceramic Floor Tile and Grout	50	SF	Engineers office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
11	Spray on Fire Proofing			Inaccessible, Access to Roof Area by Girls Locker Room	Chrysotile	SURFACE					
12	Cementitious Fitting Insulation on Cold Water Line			Throughout	No ACBM	TSI					
13	Cementitious Fitting Insulation on Hot Water Lines			Throughout	No ACBM	TSI					
14	Water Tank Insulation	280	SF	Basement	Amosite	TSI	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
15	Tank Breeching on Domestic Hot Water Tank			Pool Mechanical Room	No ACBM	MISC					
16	Metal 2' x 4' Lay-in Ceiling Panels (Not a Suspect Material)			Throughout Facility	Not Tested	MISC					
17A	12" x 12" Yellow Floor Tile Mastic			ABATED	Abated	MISC					
17B	12" x 12" Brown Speckled Floor Tile Mastic	30,000	SF	1st & 2nd Floor Corridors, 227	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
18	Water Heater Breeching			Mechanical Room	No ACBM	TSI					
19	Water Inlet Pipe Insulation			Mechanical Room	No ACBM	TSI					
2	12" x 12" Yellow Floor Tile			MATERIAL REMOVED	Assumed	MISC					
20	Block Inside Water Heater			ABATED	Abated	MISC					
21	Mud Inside Water Heater			ABATED	Abated	MISC					
22	Orange Rubber Flooring			Gym	No ACBM	MISC					
23	Mastic Beneath Orange Rubber Flooring			Gym	Chrysotile	MISC					
24	12" x 12" Maroon w/ White Flecks Floor Tile	1,000	SF	Girls & Boys Locker Rooms, Coaches Offices, Storage Room Off Gym, H3, H4, Storage by 206, Kitchen Office, Floor 1 Book Room, Floor 1 West Book	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Clark Academic Prep HS

**Unit** 41051

**Building ID** 6620

**Address** 5101 W. Harrison

Chicago, IL, 60644

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Room, Auditorium Storage Room, Telecom Room in Main Office, Basement Corridor							
25	12" x 12" Maroon w/ White Flecks Floor Tile Mastic	1,000	SF	Girls & Boys Locker Rooms, Coaches Offices, Storage Room Off Gym, H3, H4, Storage by 206, Kitchen Office, Floor 1 Book Room, Floor 1 West Book Room, Auditorium Storage Room, Telecom Room in Main Office, Basement Corridor	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Brown Baseboard			Gym, Girls & Boys Locker Rooms, Coaches Offices	No ACBM	MISC					
27	Brown Baseboard Mastic			Gym, Girls & Boys Locker Rooms, Coaches Offices	No ACBM	MISC					
28	Ceramic Wall Base Grout			Pool Room, Girls and Boys Locker Rooms	No ACBM	MISC					
29	Ceramic Floor Tile Grout			Pool Room, Girls and Boys Locker Rooms	No ACBM	MISC					
3	12" x 12" Beige Floor Tile			2nd Floor Corridor	No ACBM	MISC					
30	Cinder Block			Throughout Facility	No ACBM	MISC					
31	Cinder Block Mortar			Throughout Facility	No ACBM	MISC					
32	Wall Tile Adhesive			Boys Pool Locker Room	No ACBM	MISC					
33	Wall Tile Caulk			Boys Pool Locker Room	No ACBM	MISC					
34	Clay Floor Tile			Kitchen	No ACBM	MISC					
35	Clay Floor Tile Mortar			Kitchen	No ACBM	MISC					
36	Ceramic Wall Grout			Kitchen	No ACBM	MISC					
37	12" x 12" White w/ Gray Streaks Floor Tile Mastic	1,728	SF	Corridor Between Kitchen and Pool, Industrial Arts, Engineer's Office, Rooms 230 and 232, South Stairwell Landings, Kitchen Storage, Basement Storage	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
38	Terrazzo			Stairways and Landings	No ACBM	SURFACE					
39	Brown Ceramic Tile Grout			Boys Bathrooms, Mens Bathrooms, kitchen	No ACBM	MISC					
4	12" x 12" White w/ Gray Streaks Floor Tile	1,728	SF	Corridor Between Kitchen and Pool, Industrial Arts, Engineer's Office,	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Clark Academic Prep HS

**Unit** 41051

**Building ID** 6620

**Address** 5101 W. Harrison

Chicago, IL, 60644

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Rooms 230 and 232, South Stairwell Landings, Kitchen Storage, Basement Storage							
40	Yellow Ceramic Tile Grout			Girls Bathrooms, Womens Bathrooms	No ACBM	MISC					
41	White Ceramic Wall Tile Grout			Custodial Rooms in Boys Bathrooms	No ACBM	MISC					
42	Terrazzo Basins			Custodial Rooms in Boys Bathrooms	No ACBM	MISC					
43	4" Black Vinyl Baseboard			Throughout Facility	No ACBM	MISC					
44	4" Black Vinyl Baseboard Mastic			Throughout Facility	No ACBM	MISC					
45	12" x 12" Brown w/ Pink & White Streaks Floor Tile Mastic	20,000	SF	Rooms 107, 115, 116, 215, 242, 248, Boys and Girls Locker Rooms, Storages and Basement 249a, 249b, 1st Floor Corridor, 2nd Floor Corridor, 203, 206, 128, Pool	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
46	4" Light Brown Vinyl Baseboard (Cove Base)			Rooms 102 and 148	No ACBM	MISC					
47	4" Light Brown Vinyl Baseboard (Cove Base) Mastic			Rooms 102 and 148	No ACBM	MISC					
48	Drywall			Room 220, Industrial Arts Corridor	No ACBM	MISC					
49	Interior Brick			Throughout Facility	No ACBM	MISC					
5	12" x 12" Brown Speckled Floor Tile	30,000	SF	1st & 2nd Floor Corridors, 227	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
50	Interior Brick Mortar			Throughout Facility	No ACBM	MISC					
51	Interior Door Caulk	10	LF	Corridor by 241	Chrysotile	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
52	Interior Window Caulk			Throughout Facility	No ACBM	MISC					
53	Interior Window Glazing Non-AHERA			Throughout Facility	No ACBM	MISC					
54	Purple/Lavender/Tan Ceramic Tile Grout			Office Bathroom	Assumed	MISC					
55	Wall Tile Caulk	100	SF	Office Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
56	Wall Tile Adhesive	100	SF	Office Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
57	Blue Carpet Mastic	6,500	SF	Rooms 101-103, and and LRC Offices, 124, 152, Media Center, 144, 141	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
58	Orange Carpet Mastic			Activity Circle	Assumed	MISC					
59	Gray Carpet Mastic	6,200	SF	Activity Circle, Rooms 142, 150	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
6	1' x 1' Wormy Ceiling Tile			Basement, Activity Circle, 1st Floor Mens & Womens Bathrooms	No ACBM	MISC					
60	12" x 12" Light Gray Floor Tile			At Doors of Commons 1+2	Assumed	MISC					
61	12" x 12" Light Gray Floor Tile Mastic			At Doors of Commons 1+2	Assumed	MISC					
62	Exterior Door Caulk - Non-AHERA			Building Exterior	No ACBM	MISC					

# Chicago Public Schools

**School** Clark Academic Prep HS

**Unit** 41051

**Building ID** 6620

**Address** 5101 W. Harrison

Chicago, IL, 60644

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
63	12" x 12" Light Brown Floor Tile w/ Dark Brown Streaks			ABATED	Abated	MISC					
64	12" x 12" Light Brown Floor Tile w/ Dark Brown Streaks Mastic			ABATED	Abated	MISC					
65	Exterior Brick - Non-AHERA			Building Exterior	No ACBM	MISC					
66	Exterior Brick Mortar - Non-AHERA			Building Exterior	No ACBM	MISC					
67	12" x 12" Blue Floor Tile	200	SF	MDF Room in 116	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
68	12" x 12" Blue Floor Tile Mastic	200	SF	MDF Room in 116	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
69	Purple Carpet Mastic	556	SF	Room 107, 151, Activity center	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
7	Plaster Ceilings and Walls			Throughout Facility	No ACBM	SURFACE					
70	Purple Carpet Mastic			1st & 2nd Floor Corridors, Faculty Lounge, 123-125, , -145, 147, 149 , 155, 150-154, Lockers, 216	No ACBM	MISC					
71	12" x 12" Beige Floor Tile Mastic	500	SF	2nd Floor Corridor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
75	Transite Panel in Floor Radiators	4,000	SF	Rooms	Chrysotile	MISC			SF		
76	Blue Linoleum Flooring	3,600	SF	Rooms 223, 223a, 221, 241, 241 and 243, Elevator	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
77	Blue Linoleum Mastic	3,600	SF	Rooms 223, 223a, 221, 241, 241 and 243, Elevator	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
78	12" x 12" Dark Brown w/ Light Gray Specks Floor Tile	400	SF	1st Floor Activity Center Near Stairs, Gymnasium Vestibule	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
79	12" x 12" Dark Brown w/ Light Gray Specks Floor Tile Mastic	400	SF	1st Floor Activity Center Near Stairs, Gymnasium Vestibule	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
8	Lab Table Tops	400	SF	Rooms 243, 241, 221, 221a, 223	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
80	Ceramic Floor Grout	4,500	SF	Pool, 1st & 2nd Floor Girls and Boys Bathrooms and Lockers	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
81	12" x 12" Brown w/ Grayish White Specks Floor Tile	3,800	SF	Front Entrance Hallway	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
82M	12" x 12" Brown w/ Grayish White Specks Floor Tile Mastic	3,800	SF	Front Entrance Hallway	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
83	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile	1,000	SF	Rooms 109 and 205	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
84	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile Mastic	1,000	SF	Rooms 109 and 205	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
85	1' x 1' Smooth Ceiling Tiles	2,000	SF	Kitchen	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

# Chicago Public Schools

**School** Clark Academic Prep HS

**Unit** 41051

**Building ID** 6620

**Address** 5101 W. Harrison

Chicago, IL, 60644

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
86	1' x 1' Smooth Ceiling Tile Adhesive	2,000	SF	Kitchen	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
87	Beige Speckled Floor Tile	50	SF	Cafeteria	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
88	Brown Carpet Adhesive	900	SF	Room 231, 233, 253, 251, 250, 248, 247, 244, 242, 240, 200, 218, 220, 220a, 225, 226, 209, 214, 210, 213, 211, 220 Storage, 201, 202, 153, 154, Receiving Room 106, 133, 134, 127, 128, 234, 207, 245, 224, 222, 214, 217, 204, 130, 132, 131, nurse office, office 148, 124, Guidance office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
89	12" x 12" White w/ Dark Gray Streaks Floor Tile	1,500	SF	Room 208, 109 Storage Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
9	Mag Block Duct Insulation	300	LF	Kitchen & Storage Area in Basement, boiler room	Chrysotile	TSI	Yes	5	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove
90	12" x 12" White w/ Dark Gray Streaks Floor Tile Mastic	1,500	SF	Room 208, 109 Storage Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
91	Vapor Barrier for Wood Tongue and Groove Flooring	3,000	SF	Gym	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
92	12" x 12" Yellow w/ Blue Streaks Floor Tile	500	SF	2nd Floor Locker Rooms, 205, 252 109	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
93	12" x 12" Gray Mottled Floor Tile	300	SF	2nd Floor Locker Rooms, 205, 252, 109	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
94	12" x 12" Dark Gray Mottled Floor Tile	300	SF	2nd Floor Locker Rooms, 205, 252, 109	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
95	12" x 12" Gray Mottled, Dark Gray Mottled, and Yellow w/ Blue Streaks Floor Tile Mastic	1,100	SF	2nd Floor Locker Rooms, 205, 252 109	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
96	2' x 2' Rough Texture Ceiling Tile	2,500	SF	Room143 Offices	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
97	Blue Carpet Adhesive	1,000	SF	Room 212	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
98	Fire Door	50	SF	Floor 1 Book Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
99	Gray Pattern Carpet Mastic	1,500	SF	Room 143 Offices	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
AA	Pink/White Flooring Material			Rooms 142,	Assumed	MISC					
BB	HA A Mastic			Rooms 221, 241, 122, 222, 242	Assumed	MISC					
CC	Panels Over Moveable Doors Room Divide	2,850	SF	123/121, 132/134, 152/154, 232/234, 252/254, House Commons 1, 2 and Gym	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Clark Academic Prep HS

**Unit** 41051

**Building ID** 6620

**Address** 5101 W. Harrison

Chicago, IL, 60644

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

*Management Planner's Comments Summarized at the End of the Report*

Review Date	8/1/2025
Manager Planner Name	Jackson Montgomery
100-20634	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
100	
101	
102	
103	
104	
105	
106	
107	

# Chicago Public Schools

**School** Clark Academic Prep HS

**Unit** 41051

**Building ID** 6620

**Address** 5101 W. Harrison

Chicago, IL, 60644

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
11	If identified, continue O&M.
12	
13	
14	
15	
16	
17A	
17B	
18	
19	
2	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
3	
30	
31	
32	
33	
34	

# Chicago Public Schools

**School** Clark Academic Prep HS

**Unit** 41051

**Building ID** 6620

**Address** 5101 W. Harrison

Chicago, IL, 60644

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
5	
50	
51	
52	
53	Non-AHERA
54	
55	
56	
57	
58	
59	

# Chicago Public Schools

**School** Clark Academic Prep HS

**Unit** 41051

**Building ID** 6620

**Address** 5101 W. Harrison

Chicago, IL, 60644

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
6	
60	
61	
62	Non-AHERA
63	
64	
65	Non-AHERA
66	Non-AHERA
67	
68	
69	
7	
70	
71	
75	If identified, continue O&M.
76	
77	
78	
79	
8	
80	
81	
82M	
83	
84	
85	
86	

# Chicago Public Schools

**School** Clark Academic Prep HS

**Unit** 41051

**Building ID** 6620

**Address** 5101 W. Harrison

Chicago, IL, 60644

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
87	
88	
89	
9	Remove or repair damaged TSI to intact.
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
AA	
BB	
CC	

## APPENDIX A

---

### Assessment Sheets, Drawings and Photos

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2025 AHERA REINSPECTION***

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA RE/INSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1		
MATERIAL DESCRIPTION:	12" x 12" Brown w/ Pink & White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Vibration		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 107, 115, 116, 215, 242, 248, Boys and Girls Locker Rooms, Storages and Basement 249a, 249b, 1st Floor Corridor, 2nd Floor Corridor, 203, 206, 128, Pool**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ Pink & White Streaks Floor Tile**

MATERIAL LOCATION: **Rooms 107, 115, 116, 215, 242, 248, Boys and Girls Locker Rooms, Storages and Basement 249a, 249b, 1st Floor Corridor, 2nd Floor Corridor, 203, 206, 128, Pool**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	INSPECTION DATE:	<b>7/2/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>100</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Light Gray Mottled Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 147</b>		
MATERIAL QUANTITY:	<b>300</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **100**

MATERIAL DESCRIPTION: **12" x 12" Light Gray Mottled Floor Tile**

MATERIAL LOCATION: **Room 147**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	INSPECTION DATE:	<b>7/2/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>101</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Light Gray Mottled Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 147</b>		
MATERIAL QUANTITY:	<b>300</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **101**

MATERIAL DESCRIPTION: **12" x 12" Light Gray Mottled Floor Tile Mastic**

MATERIAL LOCATION: **Room 147**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	INSPECTION DATE:	<b>7/2/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>102</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" White w/ Tan Streaks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 110, 109b</b>		
MATERIAL QUANTITY:	<b>1200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **102**

MATERIAL DESCRIPTION: **12" x 12" White w/ Tan Streaks Floor Tile**

MATERIAL LOCATION: **Room 110, 109b**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	103		
MATERIAL DESCRIPTION:	12" x 12" White w/ Tan Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 110, 109b		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **103**

MATERIAL DESCRIPTION: **12" x 12" White w/ Tan Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Room 110, 109b**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	INSPECTION DATE:	<b>7/2/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>104</b>		
MATERIAL DESCRIPTION:	<b>Gray and Blue Streaked Carpet Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Gurley Center</b>		
MATERIAL QUANTITY:	<b>2500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **104**

MATERIAL DESCRIPTION: **Gray and Blue Streaked Carpet Mastic**

MATERIAL LOCATION: **Gurley Center**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	105		
MATERIAL DESCRIPTION:	Pool Heater Duct Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Pump Room**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **30** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **105**

MATERIAL DESCRIPTION: **Pool Heater Duct Insulation**

MATERIAL LOCATION: **Pump Room**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 11  
MATERIAL DESCRIPTION: Spray on Fire Proofing  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Inaccessible, Access to Roof Area by Girls Locker Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material in inaccessible area(s) - 2025

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Spray on Fire Proofing**

MATERIAL LOCATION: **Inaccessible, Access to Roof Area by Girls Locker Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M.

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 12

MATERIAL DESCRIPTION: Cementitious Fitting Insulation on Cold Water Line

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Cementitious Fitting Insulation on Cold Water Line**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13	
MATERIAL DESCRIPTION:	Cementitious Fitting Insulation on Hot Water Lines	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Cementitious Fitting Insulation on Hot Water Lines**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	Water Tank Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Amosite	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement		
MATERIAL QUANTITY:	280	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Water Tank Insulation**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY: **280** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15	
MATERIAL DESCRIPTION:	Tank Breeching on Domestic Hot Water Tank	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Pool Mechanical Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Tank Breeching on Domestic Hot Water Tank**

MATERIAL LOCATION: **Pool Mechanical Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16	
MATERIAL DESCRIPTION:	Metal 2' x 4' Lay-in Ceiling Panels (Not a Suspect Material)	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Not Tested	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Metal 2' x 4' Lay-in Ceiling Panels (Not a Suspect Material)**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	INSPECTION DATE:	<b>7/2/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>17A</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Yellow Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Abated</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **17A**

MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	INSPECTION DATE:	<b>7/2/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>17B</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Brown Speckled Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1st &amp; 2nd Floor Corridors, 227</b>		
MATERIAL QUANTITY:	<b>30000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **17B**

MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile Mastic**

MATERIAL LOCATION: **1st & 2nd Floor Corridors, 227**

MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Water Heater Breeching**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Mechanical Room**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Water Heater Breeching**

MATERIAL LOCATION: **Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Water Inlet Pipe Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Mechanical Room**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Water Inlet Pipe Insulation**

MATERIAL LOCATION: **Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 2

MATERIAL DESCRIPTION: 12" x 12" Yellow Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: MATERIAL REMOVED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile**

MATERIAL LOCATION: **MATERIAL REMOVED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 20

MATERIAL DESCRIPTION: Block Inside Water Heater

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Block Inside Water Heater**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 21  
MATERIAL DESCRIPTION: Mud Inside Water Heater  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Mud Inside Water Heater**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 22  
MATERIAL DESCRIPTION: Orange Rubber Flooring  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Gym

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Orange Rubber Flooring**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	Mastic Beneath Orange Rubber Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Gym

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Mastic Beneath Orange Rubber Flooring**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	12" x 12" Maroon w/ White Flecks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Girls & Boys Locker Rooms, Coaches Offices, Storage Room Off Gym, H3, H4, Storage by 206, Kitchen Office, Floor 1 Book Room, Floor 1 West Book Room, Auditorium Storage Room, Telecom Room in Main Office, Basement Corridor**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA RE/NSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **12" x 12" Maroon w/ White Flecks Floor Tile**

MATERIAL LOCATION: **Girls & Boys Locker Rooms, Coaches Offices, Storage Room Off Gym, H3, H4, Storage by 206, Kitchen Office, Floor 1 Book Room, Floor 1 West Book Room, Auditorium Storage Room, Telecom Room in Main Office, Basement Corridor**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: *Jackson Montgomery* Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	12" x 12" Maroon w/ White Flecks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Girls & Boys Locker Rooms, Coaches Offices, Storage Room Off Gym, H3, H4, Storage by 206, Kitchen Office, Floor 1 Book Room, Floor 1 West Book Room, Auditorium Storage Room, Telecom Room in Main Office, Basement Corridor**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA RE/NSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **12" x 12" Maroon w/ White Flecks Floor Tile Mastic**

MATERIAL LOCATION: **Girls & Boys Locker Rooms, Coaches Offices, Storage Room Off Gym, H3, H4, Storage by 206, Kitchen Office, Floor 1 Book Room, Floor 1 West Book Room, Auditorium Storage Room, Telecom Room in Main Office, Basement Corridor**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: *Jackson Montgomery* Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **Brown Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym, Girls & Boys Locker Rooms, Coaches Offices**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Brown Baseboard**

MATERIAL LOCATION: **Gym, Girls & Boys Locker Rooms, Coaches Offices**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 27  
MATERIAL DESCRIPTION: Brown Baseboard Mastic  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Gym, Girls & Boys Locker Rooms, Coaches Offices

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Brown Baseboard Mastic**

MATERIAL LOCATION: **Gym, Girls & Boys Locker Rooms, Coaches Offices**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28  
MATERIAL DESCRIPTION: Ceramic Wall Base Grout  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Pool Room, Girls and Boys Locker Rooms

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Ceramic Wall Base Grout**

MATERIAL LOCATION: **Pool Room, Girls and Boys Locker Rooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 29  
MATERIAL DESCRIPTION: Ceramic Floor Tile Grout  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Pool Room, Girls and Boys Locker Rooms

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Ceramic Floor Tile Grout**

MATERIAL LOCATION: **Pool Room, Girls and Boys Locker Rooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 3  
MATERIAL DESCRIPTION: 12" x 12" Beige Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 2nd Floor Corridor

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**

MATERIAL LOCATION: **2nd Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 30  
MATERIAL DESCRIPTION: Cinder Block  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Facility

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Cinder Block**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 31  
MATERIAL DESCRIPTION: Cinder Block Mortar  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Facility

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32  
MATERIAL DESCRIPTION: Wall Tile Adhesive  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boys Pool Locker Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Wall Tile Adhesive**

MATERIAL LOCATION: **Boys Pool Locker Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 33  
MATERIAL DESCRIPTION: Wall Tile Caulk  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boys Pool Locker Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Wall Tile Caulk**

MATERIAL LOCATION: **Boys Pool Locker Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 34  
MATERIAL DESCRIPTION: Clay Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Kitchen

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Clay Floor Tile**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 35  
MATERIAL DESCRIPTION: Clay Floor Tile Mortar  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Kitchen

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Clay Floor Tile Mortar**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 36  
MATERIAL DESCRIPTION: Ceramic Wall Grout  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Kitchen

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Ceramic Wall Grout**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	12" x 12" White w/ Gray Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Corridor Between Kitchen and Pool, Industrial Arts, Engineer's Office, Rooms 230 and 232, South Stairwell Landings, Kitchen Storage, Basement Storage**

MATERIAL QUANTITY: **1728** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **8/1/2025**

ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Corridor Between Kitchen and Pool, Industrial Arts, Engineer's Office, Rooms 230 and 232, South Stairwell Landings, Kitchen Storage, Basement Storage**

MATERIAL QUANTITY: **1728** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 38  
MATERIAL DESCRIPTION: Terrazzo  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Stairways and Landings

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **Stairways and Landings**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 39  
MATERIAL DESCRIPTION: Brown Ceramic Tile Grout  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boys Bathrooms, Mens Bathrooms, kitchen

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Brown Ceramic Tile Grout**

MATERIAL LOCATION: **Boys Bathrooms, Mens Bathrooms, kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	4		
MATERIAL DESCRIPTION:	12" x 12" White w/ Gray Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Corridor Between Kitchen and Pool, Industrial Arts, Engineer's Office, Rooms 230 and 232, South Stairwell Landings, Kitchen Storage, Basement Storage**

MATERIAL QUANTITY: **1728** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Streaks Floor Tile**

MATERIAL LOCATION: **Corridor Between Kitchen and Pool, Industrial Arts, Engineer's Office, Rooms 230 and 232, South Stairwell Landings, Kitchen Storage, Basement Storage**

MATERIAL QUANTITY: **1728** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 40  
MATERIAL DESCRIPTION: Yellow Ceramic Tile Grout  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Girls Bathrooms, Womens Bathrooms

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Yellow Ceramic Tile Grout**

MATERIAL LOCATION: **Girls Bathrooms, Womens Bathrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 41  
MATERIAL DESCRIPTION: White Ceramic Wall Tile Grout  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Custodial Rooms in Boys Bathrooms

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **White Ceramic Wall Tile Grout**

MATERIAL LOCATION: **Custodial Rooms in Boys Bathrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 42  
MATERIAL DESCRIPTION: Terrazzo Basins  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Custodial Rooms in Boys Bathrooms

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Terrazzo Basins**

MATERIAL LOCATION: **Custodial Rooms in Boys Bathrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 43  
MATERIAL DESCRIPTION: 4" Black Vinyl Baseboard  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Facility

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 44  
MATERIAL DESCRIPTION: 4" Black Vinyl Baseboard Mastic  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Facility

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	12" x 12" Brown w/ Pink & White Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Rooms 107, 115, 116, 215, 242, 248, Boys and Girls Locker Rooms, Storages and Basement 249a, 249b, 1st Floor Corridor, 2nd Floor Corridor, 203, 206, 128, Pool		
MATERIAL QUANTITY:	20000	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA RE/INSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ Pink & White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 107, 115, 116, 215, 242, 248, Boys and Girls Locker Rooms, Storages and Basement 249a, 249b, 1st Floor Corridor, 2nd Floor Corridor, 203, 206, 128, Pool**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 46  
MATERIAL DESCRIPTION: 4" Light Brown Vinyl Baseboard (Cove Base)  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 102 and 148

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **4" Light Brown Vinyl Baseboard (Cove Base)**

MATERIAL LOCATION: **Rooms 102 and 148**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 47

MATERIAL DESCRIPTION: 4" Light Brown Vinyl Baseboard (Cove Base) Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 102 and 148

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **4" Light Brown Vinyl Baseboard (Cove Base) Mastic**

MATERIAL LOCATION: **Rooms 102 and 148**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 48  
MATERIAL DESCRIPTION: Drywall  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 220, Industrial Arts Corridor

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Room 220, Industrial Arts Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 49  
MATERIAL DESCRIPTION: Interior Brick  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Facility

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Interior Brick**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	INSPECTION DATE:	<b>7/2/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>5</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Brown Speckled Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1st &amp; 2nd Floor Corridors, 227</b>		
MATERIAL QUANTITY:	<b>30000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile**

MATERIAL LOCATION: **1st & 2nd Floor Corridors, 227**

MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 50  
MATERIAL DESCRIPTION: Interior Brick Mortar  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Facility

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	Interior Door Caulk		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Corridor by 241		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Interior Door Caulk**

MATERIAL LOCATION: **Corridor by 241**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 52  
MATERIAL DESCRIPTION: Interior Window Caulk  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Facility

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **Interior Window Caulk**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53	
MATERIAL DESCRIPTION:	Interior Window Glazing Non-AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **Interior Window Glazing Non-AHERA**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54	
MATERIAL DESCRIPTION:	Purple/Lavender/Tan Ceramic Tile Grout	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Office Bathroom

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Purple/Lavender/Tan Ceramic Tile Grout**

MATERIAL LOCATION: **Office Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	INSPECTION DATE:	<b>7/2/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>55</b>		
MATERIAL DESCRIPTION:	<b>Wall Tile Caulk</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Office Bathroom</b>		
MATERIAL QUANTITY:	<b>100</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BULDING ID: **6620**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **8/1/2025**

ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Wall Tile Caulk**

MATERIAL LOCATION: **Office Bathroom**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	INSPECTION DATE:	<b>7/2/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>56</b>		
MATERIAL DESCRIPTION:	<b>Wall Tile Adhesive</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Office Bathroom</b>		
MATERIAL QUANTITY:	<b>100</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **Wall Tile Adhesive**

MATERIAL LOCATION: **Office Bathroom**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	57		
MATERIAL DESCRIPTION:	Blue Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 101-103, and and LRC Offices, 124, 152, Media Center, 144, 141		
MATERIAL QUANTITY:	6500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **Blue Carpet Mastic**

MATERIAL LOCATION: **Rooms 101-103, and and LRC Offices, 124, 152, Media Center, 144, 141**

MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58	
MATERIAL DESCRIPTION:	Orange Carpet Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Activity Circle

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **Orange Carpet Mastic**

MATERIAL LOCATION: **Activity Circle**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	59		
MATERIAL DESCRIPTION:	Gray Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Activity Circle, Rooms 142, 150		
MATERIAL QUANTITY:	6200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **Gray Carpet Mastic**

MATERIAL LOCATION: **Activity Circle, Rooms 142, 150**

MATERIAL QUANTITY: **6200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 6  
MATERIAL DESCRIPTION: 1' x 1' Wormy Ceiling Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Basement, Activity Circle, 1st Floor Mens & Womens Bathrooms

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **1' x 1' Wormy Ceiling Tile**

MATERIAL LOCATION: **Basement, Activity Circle, 1st Floor Mens & Womens Bathrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	60	
MATERIAL DESCRIPTION:	12" x 12" Light Gray Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: At Doors of Commons 1+2

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **12" x 12" Light Gray Floor Tile**

MATERIAL LOCATION: **At Doors of Commons 1+2**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	61	
MATERIAL DESCRIPTION:	12" x 12" Light Gray Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: At Doors of Commons 1+2

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **12" x 12" Light Gray Floor Tile Mastic**

MATERIAL LOCATION: **At Doors of Commons 1+2**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Exterior Door Caulk - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Exterior Door Caulk - Non-AHERA**

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/ Dark Brown Streaks**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/ Dark Brown Streaks**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	INSPECTION DATE:	<b>7/2/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/ Dark Brown Streaks Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/ Dark Brown Streaks Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **Exterior Brick - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **Exterior Brick - Non-AHERA**

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Clark Academic Prep HS	REVIEW DATE:	8/1/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Non-AHERA**

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	INSPECTION DATE:	<b>7/2/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>67</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Blue Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>MDF Room in 116</b>		
MATERIAL QUANTITY:	<b>200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**

MATERIAL LOCATION: **MDF Room in 116**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	INSPECTION DATE:	<b>7/2/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>68</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Blue Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>MDF Room in 116</b>		
MATERIAL QUANTITY:	<b>200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**

MATERIAL LOCATION: **MDF Room in 116**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	INSPECTION DATE:	<b>7/2/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>69</b>		
MATERIAL DESCRIPTION:	<b>Purple Carpet Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 107, 151, Activity center</b>		
MATERIAL QUANTITY:	<b>556</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **Purple Carpet Mastic**

MATERIAL LOCATION: **Room 107, 151, Activity center**

MATERIAL QUANTITY: **556** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 7

MATERIAL DESCRIPTION: Plaster Ceilings and Walls

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Facility

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **Plaster Ceilings and Walls**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 70  
MATERIAL DESCRIPTION: Purple Carpet Mastic  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st & 2nd Floor Corridors, Faculty Lounge, 123-125, , -145, 147, 149 , 155, 150-154, Lockers, 216

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **Purple Carpet Mastic**

MATERIAL LOCATION: **1st & 2nd Floor Corridors, Faculty Lounge, 123-125, , -145, 147, 149 , 155, 150-154, Lockers, 216**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	INSPECTION DATE:	<b>7/2/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>71</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Beige Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>2nd Floor Corridor</b>		
MATERIAL QUANTITY:	<b>500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**

MATERIAL LOCATION: **2nd Floor Corridor**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	75	
MATERIAL DESCRIPTION:	Transite Panel in Floor Radiators	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:	Rooms	MATERIAL UNITS:	SF
MATERIAL QUANTITY:	4000	DAMAGE UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:	Material in inaccessible area(s) - 2025		

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **Transite Panel in Floor Radiators**

MATERIAL LOCATION: **Rooms**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M.

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	76		
MATERIAL DESCRIPTION:	Blue Linoleum Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 223, 223a, 221, 241, 241 and 243, Elevator		
MATERIAL QUANTITY:	3600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **Blue Linoleum Flooring**

MATERIAL LOCATION: **Rooms 223, 223a, 221, 241, 241 and 243, Elevator**

MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	77		
MATERIAL DESCRIPTION:	Blue Linoleum Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 223, 223a, 221, 241, 241 and 243, Elevator		
MATERIAL QUANTITY:	3600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **Blue Linoleum Mastic**

MATERIAL LOCATION: **Rooms 223, 223a, 221, 241, 241 and 243, Elevator**

MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	INSPECTION DATE:	<b>7/2/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>78</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Dark Brown w/ Light Gray Specks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:	<b>Deterioration</b>		
HISTORICAL RESPONSE ACTION:	<b>Repair</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1st Floor Activity Center Near Stairs, Gymnasium Vestibule</b>		
MATERIAL QUANTITY:	<b>400</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	DAMAGE UNITS: <b>SF</b>		
COMMENTS:			

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **12" x 12" Dark Brown w/ Light Gray Specks Floor Tile**

MATERIAL LOCATION: **1st Floor Activity Center Near Stairs, Gymnasium Vestibule**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	79		
MATERIAL DESCRIPTION:	12" x 12" Dark Brown w/ Light Gray Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Activity Center Near Stairs, Gymnasium Vestibule		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **12" x 12" Dark Brown w/ Light Gray Specks Floor Tile Mastic**

MATERIAL LOCATION: **1st Floor Activity Center Near Stairs, Gymnasium Vestibule**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	INSPECTION DATE:	<b>7/2/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>8</b>		
MATERIAL DESCRIPTION:	<b>Lab Table Tops</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 243, 241, 221, 221a, 223</b>		
MATERIAL QUANTITY:	<b>400</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **Lab Table Tops**

MATERIAL LOCATION: **Rooms 243, 241, 221, 221a, 223**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	INSPECTION DATE:	<b>7/2/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>80</b>		
MATERIAL DESCRIPTION:	<b>Ceramic Floor Grout</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Pool, 1st &amp; 2nd Floor Girls and Boys Bathrooms and Lockers</b>		
MATERIAL QUANTITY:	<b>4500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **Ceramic Floor Grout**

MATERIAL LOCATION: **Pool, 1st & 2nd Floor Girls and Boys Bathrooms and Lockers**

MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	81		
MATERIAL DESCRIPTION:	12" x 12" Brown w/ Grayish White Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Front Entrance Hallway		
MATERIAL QUANTITY:	3800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ Grayish White Specks Floor Tile**

MATERIAL LOCATION: **Front Entrance Hallway**

MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	82M		
MATERIAL DESCRIPTION:	12" x 12" Brown w/ Grayish White Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Front Entrance Hallway		
MATERIAL QUANTITY:	3800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **82M**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ Grayish White Specks Floor Tile Mastic**

MATERIAL LOCATION: **Front Entrance Hallway**

MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	83		
MATERIAL DESCRIPTION:	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 109 and 205		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BULDING ID: **6620**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **8/1/2025**

ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile**

MATERIAL LOCATION: **Rooms 109 and 205**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	84		
MATERIAL DESCRIPTION:	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 109 and 205		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 109 and 205**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	85		
MATERIAL DESCRIPTION:	1' x 1' Smooth Ceiling Tiles		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **85**

MATERIAL DESCRIPTION: **1' x 1' Smooth Ceiling Tiles**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	INSPECTION DATE:	<b>7/2/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>86</b>		
MATERIAL DESCRIPTION:	<b>1' x 1' Smooth Ceiling Tile Adhesive</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Kitchen</b>		
MATERIAL QUANTITY:	<b>2000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **86**

MATERIAL DESCRIPTION: **1' x 1' Smooth Ceiling Tile Adhesive**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	INSPECTION DATE:	<b>7/2/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>87</b>		
MATERIAL DESCRIPTION:	<b>Beige Speckled Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Cafeteria</b>		
MATERIAL QUANTITY:	<b>50</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **87**

MATERIAL DESCRIPTION: **Beige Speckled Floor Tile**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	88		
MATERIAL DESCRIPTION:	Brown Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: Room 231, 233, 253, 251, 250, 248, 247, 244, 242, 240, 200, 218, 220, 220a, 225, 226, 209, 214, 210, 213, 211, 220 Storage, 201, 202, 153, 154, Receiving Room 106, 133, 134, 127, 128, 234, 207, 245, 224, 222, 214, 217, 204, 130, 132, 131, nurse office, office 148, 124, Guidance office

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **Brown Carpet Adhesive**

MATERIAL LOCATION: **Room 231, 233, 253, 251, 250, 248, 247, 244, 242, 240, 200, 218, 220, 220a, 225, 226, 209, 214, 210, 213, 211, 220 Storage, 201, 202, 153, 154, Receiving Room 106, 133, 134, 127, 128, 234, 207, 245, 224, 222, 214, 217, 204, 130, 132, 131, nurse office, office 148, 124, Guidance office**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: *Jackson Montgomery* Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	89		
MATERIAL DESCRIPTION:	12" x 12" White w/ Dark Gray Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 208, 109 Storage Room		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **89**

MATERIAL DESCRIPTION: **12" x 12" White w/ Dark Gray Streaks Floor Tile**

MATERIAL LOCATION: **Room 208, 109 Storage Room**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	9		
MATERIAL DESCRIPTION:	Mag Block Duct Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	1		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Kitchen & Storage Area in Basement, boiler room		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:	Damage in: Boiler Room		

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **Mag Block Duct Insulation**

MATERIAL LOCATION: **Kitchen & Storage Area in Basement, boiler room**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **5** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Remove or repair damaged TSI to intact.

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	90		
MATERIAL DESCRIPTION:	12" x 12" White w/ Dark Gray Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 208, 109 Storage Room		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **12" x 12" White w/ Dark Gray Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Room 208, 109 Storage Room**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	INSPECTION DATE:	<b>7/2/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>91</b>		
MATERIAL DESCRIPTION:	<b>Vapor Barrier for Wood Tongue and Groove Flooring</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Gym</b>		
MATERIAL QUANTITY:	<b>3000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **91**

MATERIAL DESCRIPTION: **Vapor Barrier for Wood Tongue and Groove Flooring**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	92		
MATERIAL DESCRIPTION:	12" x 12" Yellow w/ Blue Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Locker Rooms, 205, 252 109		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **12" x 12" Yellow w/ Blue Streaks Floor Tile**

MATERIAL LOCATION: **2nd Floor Locker Rooms, 205, 252 109**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	93		
MATERIAL DESCRIPTION:	12" x 12" Gray Mottled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Locker Rooms, 205, 252, 109		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **93**

MATERIAL DESCRIPTION: **12" x 12" Gray Mottled Floor Tile**

MATERIAL LOCATION: **2nd Floor Locker Rooms, 205, 252, 109**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	94		
MATERIAL DESCRIPTION:	12" x 12" Dark Gray Mottled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Locker Rooms, 205, 252, 109		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **94**

MATERIAL DESCRIPTION: **12" x 12" Dark Gray Mottled Floor Tile**

MATERIAL LOCATION: **2nd Floor Locker Rooms, 205, 252, 109**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	95		
MATERIAL DESCRIPTION:	12" x 12" Gray Mottled, Dark Gray Mottled, and Yellow w/ Blue Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd Floor Locker Rooms, 205, 252 109**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BULDING ID: **6620**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **8/1/2025**

ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **95**

MATERIAL DESCRIPTION: **12" x 12" Gray Mottled, Dark Gray Mottled, and Yellow w/ Blue Streaks Floor Tile Mastic**

MATERIAL LOCATION: **2nd Floor Locker Rooms, 205, 252 109**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	96		
MATERIAL DESCRIPTION:	2' x 2' Rough Texture Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room143 Offices		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **8/1/2025**

ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **96**

MATERIAL DESCRIPTION: **2' x 2' Rough Texture Ceiling Tile**

MATERIAL LOCATION: **Room143 Offices**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	INSPECTION DATE:	<b>7/2/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>97</b>		
MATERIAL DESCRIPTION:	<b>Blue Carpet Adhesive</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 212</b>		
MATERIAL QUANTITY:	<b>1000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BULDING ID: **6620**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **8/1/2025**

ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **97**

MATERIAL DESCRIPTION: **Blue Carpet Adhesive**

MATERIAL LOCATION: **Room 212**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	INSPECTION DATE:	<b>7/2/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>98</b>		
MATERIAL DESCRIPTION:	<b>Fire Door</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:	<b>Physical Damage</b>		
HISTORICAL RESPONSE ACTION:	<b>Repair</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Floor 1 Book Room</b>		
MATERIAL QUANTITY:	<b>50</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **98**

MATERIAL DESCRIPTION: **Fire Door**

MATERIAL LOCATION: **Floor 1 Book Room**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	INSPECTION DATE:	<b>7/2/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>99</b>		
MATERIAL DESCRIPTION:	<b>Gray Pattern Carpet Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 143 Offices</b>		
MATERIAL QUANTITY:	<b>1500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **99**

MATERIAL DESCRIPTION: **Gray Pattern Carpet Mastic**

MATERIAL LOCATION: **Room 143 Offices**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUILDING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: AA

MATERIAL DESCRIPTION: Pink/White Flooring Material

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 142,

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **AA**

MATERIAL DESCRIPTION: **Pink/White Flooring Material**

MATERIAL LOCATION: **Rooms 142,**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: BB

MATERIAL DESCRIPTION: HA A Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 221, 241, 122, 222, 242

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUILDING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **BB**

MATERIAL DESCRIPTION: **HA A Mastic**

MATERIAL LOCATION: **Rooms 221, 241, 122, 222, 242**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	CC		
MATERIAL DESCRIPTION:	Panels Over Moveable Doors Room Divide		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	123/121, 132/134, 152/154, 232/234, 252/254, House Commons 1, 2 and Gym		
MATERIAL QUANTITY:	2850	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **CC**

MATERIAL DESCRIPTION: **Panels Over Moveable Doors Room Divide**

MATERIAL LOCATION: **123/121, 132/134, 152/154, 232/234, 252/254, House Commons 1, 2 and Gym**

MATERIAL QUANTITY: **2850** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **7/2/2025**  
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **Black, Gray, White Epoxy Flooring**  
MATERIAL LOCATION: **Room 122**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC** FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **MODERATE** CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach** DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE UNITS: **SF**  
DAMAGE QUANTITY:  
COMMENTS:

Inspector's Signature:



Date: **07/02/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

HOMOGENEOUS AREA: **106**

MATERIAL DESCRIPTION: **Black, Gray, White Epoxy Flooring**

MATERIAL LOCATION: **Room 122**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **08/01/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	41051	BUIDLING ID:	6620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Clark Academic Prep HS	INSPECTION DATE:	7/2/2025		
ADDRESS:	5101 W. Harrison	IDPH LICENSE NO:	100-20411		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	107			
MATERIAL DESCRIPTION:	12" x 12" Blue Ceramic Floor Tile and Grout			
MATERIAL LOCATION:	Engineers office			
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:



Date: 07/02/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>41051</b>	BUIDLING ID:	<b>6620</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Clark Academic Prep HS</b>	REVIEW DATE:	<b>8/1/2025</b>		
ADDRESS:	<b>5101 W. Harrison</b>	IDPH LICENSE NO:	<b>100-20411</b>		

HOMOGENEOUS AREA: **107**

MATERIAL DESCRIPTION: **12" x 12" Blue Ceramic Floor Tile and Grout**

MATERIAL LOCATION: **Engineers office**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **08/01/2025**

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2025 AHERA REINSPECTION***

## APPENDIX B

---

### Inspector and Management Planner Licenses



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2025

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Benyamen Maradkel**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 3/7/2025

Exam Date: 3/7/2025

Expiration Date: 3/7/2026

Certificate Number: BIR2503070918


Course Credit Hours: BIR 4 Hrs.

Kristina Miczek, Training Manager

# Benyamen Maradkel

---

## Illinois Licensed Building Inspector



### ENDORSEMENTS

INSPECTOR

### TC EXPIRES





3/7/2026

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.



# Jackson Montgomery

Illinois Licensed Building Inspector, Air Sampling Professional, Management Planner





2200 Vandalia Street, Collinsville, IL 62234 \* Phone: 618-855-8764

## Environmental and Occupational Safety & Health Training

*Does hereby certify*

**Jackson Montgomery**

600 W. Van Buren St., Suite 500, Chicago, IL 60607



*Has successfully completed and passed the course examination with at least  
70% for accreditation under AHERA (Title II)*

## **Asbestos Management Planner Initial**

*Class Date:* 10/28-29/2024

*Examination Date:* 10/29/2024

*STC Certificate Number:* STC-20241029-000101AMPI

*Certification Expiration:* 10/29/2025

A handwritten signature in black ink that reads 'David M. Mendoza'.

David M. Mendoza – President/Training Director

Certified Environmental Specialist

OSHA Authorized Instructor

*This training course is accredited by the Illinois Department of Public Health and the Missouri Department of Natural Resources*

## APPENDIX C

---

### **Laboratory Accreditations**

## APPENDIX D

---

### Laboratory Results

## APPENDIX E

---

### Chain of Custody Forms

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>	Loc	Localized
	Dist	Distributed