

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2050
SCHOOL NAME: Air Force High School (formerly Abbott School)
ADDRESS OF SCHOOL: 3630 S. Wells
CITY: Chicago, IL, 60609

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 9/30/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 4/8/2025 ENROLLMENT 153
IDPH INSPECTOR LICENSE NUMBER: 100-03175
IDPH LICENSED INSPECTOR NAME (Please Print): Marcos Iwankiw
IDPH MP LICENSE NUMBER: 100-18488
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Mike Serio

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 5/5/2025

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____
School has been closed. Date closed: _____
School building has been demolished. Date: _____
School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Air Force High School (formerly Abbott School)

3630 S. Wells
Chicago, IL, 60609

Unit: 45231
Building ID: 2010

IDPH ID Number: 14-016-2990-2050

REPORT DATE:
Monday, May 05, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
Carnow, Conibear and Associates

600 West Van Buren St., Ste 500
Chicago, IL, 60607
Phone (312) 762-2900
Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

05/05/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 45231 Region: 04 IDPH ID: 14-016-2990-2050

School: Air Force High School (formerly Abbott School) Building ID: 2010

Address: 3630 S. Wells

Chicago, IL, 60609

Building Contact: McNamara, Sean Contact Phone: 7737096980

Current Building Owners: Chicago Public Schools

Reinspection Date: 4/8/2025

Review Date: 05/05/2025

Inspector: Marcos Iwankiw

Inspector IDPH License: 100-03175

Management Planner: Mike Serio

Management Planner IDPH License: 100-18488

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Mike Serio
100-18488

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: May 05, 2025

RE: Air Force High School (formerly Abbott School), Unit 45231
3630 S. Wells
Chicago, IL, 60609

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Air Force High School (formerly Abbott School) , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Air Force High School (formerly Abbott School), there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Air Force High School Unit: 45231 Region: 04
(formerly Abbott School)
Address: 3630 S. Wells Chicago, IL, 60609
IDPH ID: 14-016-2990-2050 Building ID: 2010
Contact: McNamara, Sean Phone: 7737096980

2. Description of Facility

Original Construction: 1954 Additional Construction: 1949,1961
Total Square Footage: 11792 No of Floors: 2
Current Occupancy: 153

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145


5. Inspector

Inspector Name: Marcos Iwankiw


Signature:
Date: 4/8/2025

6. Management Planner

Management Planner Name: Mike Serio


Signature:
Date: 05/05/2025

7. Review Date: 05/05/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.


Signature: Date: 5/5/2025

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Air Force High School (formerly Abbott School). This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2010:

006	12" x 12" Beige Floor Tile w/ Brown & White Streaks
008	9" x 9" Dark Brown Floor Tile Mastic
009	Mastic on 12" x 12" Dark Brown w/ Brown & White Streaks Floor Tile
010	Mastic on 12" x 12" Light Brown w/ Brown & White Streaks Floor Tile
011	Partition Floor Joiner Compound
013	Mastic on 12" x 12" Light Brown w/ Brown & White Streaks Floor Tile (Duplicate Of HA 10)
014	Carpet Adhesive
015	Black Vinyl Baseboard

018	Plaster
021	12" x 12" Green Floor Tile
022	Mastic on 12" x 12" Green Floor Tile
023	Tar Paper and Mastic in Vault Closet Areas
024	Vibration Isolator
027	Mastic on 12" x 12" Beige w/ Brown & White Streaks Floor Tile
028	Partition Wall Joiner Compound
029	12" x 12" Dark Gray w/ White & Brown Streaks Floor Tile
032	12" x 12" Light Beige Mix Floor Tile
034	12" x 12" Dark Pink Floor Tile
040	Gray and Yellow Mix Linoleum
044	Mastic 12" x 12" Dark Gray w/ White & Brown Streaks Floor Tile
045	Interior Brick
047	Plaster
050	Mastic on 9" x 9" Brown Floor Tile
051	Desk Top Linoleum
056	12" x 12" Blue Floor Tile
062	Cork Insulation
072	Mastic on 12" x 12" Gray Floor Tile
073	Partition Wall Compound
074	9" x 9" Light Brown Floor Tile
075	9" x 9" Light Brown Floor Tile Mastic

076	Dark Gray Vinyl Baseboard
083	12" x 12" Sandy Beige Floor Tile Mastic
087	12" x 12" Off-White Floor Tile Mastic
088	12" x 12" Light Gray Mix Floor Tile
089	12" x 12" Light Gray Mix Floor Tile Mastic
090	Radiator Grill Lining Material
091	Incinerator Gasket Material By Fire Hole
092	Incinerator Interior Brick
108	Roofing Materials - Non-AHERA
109	Roofing Materials - Non-AHERA
110	Interior Window Caulk
111	12" x 12" Light Beige w/ Brown & White Streaks Floor Tile
112	12" x 12" White w/ Off-White & Beige Streaks Floor Tile
113	HA 111 & HA 112 Checkerboard Floor Tile Pattern Mastic
114	12" x 12" Red Floor Tile
115	12" x 12" Red Floor Tile Mastic
116	12" x 12" Blue Floor Tile
117	12" x 12" Blue Floor Tile Mastic
118	Green Carpet Adhesive
119	Acoustical Ceiling
120	12" x 12" Beige Mix Floor Tile
121	12" x 12" Beige Mix Floor Tile Mastic

122	Red Carpet Adhesive
123	Black Board/ Marker Board Adhesive
124	Gray and Black Mix Terrazzo Flooring
125	12" x 12" Tand w/ Brown and White Streaks Floor Tile
126	12" x 12" Tand w/ Brown and White Streaks Floor Tile Mastic
127	Cork Board Adhesive
128	Green Carpet Adhesive
129	12" x 12" White Mottled Floor Tile
140	Wood Pattern Sheet Flooring
143	Blue Sheet Flooring Mastic
144	Transite Electrical Panel
145	Electrical Wiring Associated w/ Wall Mounted Clocks
146	12" x 12" Light Beige w/ White Streaks Floor Tile
147	12" x 12" Light Beige w/ White Streaks Floor Tile Mastic
148	Black Science Lab Counter Tables
149	Black Science Lab Counter
150	12" x 12" Gray w/ Black Spots Floor Tile
151	12" x 12" Gray w/ Black Spots Floor Tile Mastic
152	2" x 2" Blue, Gray, and Light Gray Vinyl Floor Tile
153	Blue Carpet Mastic
154	Tan CMU
91	9" x 9" Light Brown Mottled Floor Tile Mastic

C	Aircel Pipe Insulation
D	Joint Compound Off Fiberglass Pipe Insulation
E	Joint Compound Off Fiberglass Pipe Insulation
F	Distributed Pipe Insulation in Dirt on Floor
G	Distributed Pipe Insulation in Dirt on Floor
H	Aircell Pipe Insulation
I	Aircell Pipe Insulation
J	Paperwrap Pipe Insulation
L	Hard Joint Compound Off Aircell Pipe Insulation
L-1	Hard Joint Compound Off Aircell Pipe Insulation
M	Hard Joint Compound Off Aircell Pipe Insulation
N	Hard Joint Compound Off Aircell Pipe Insulation
O	Duct Interior Insulation
Q	Magblock Pipe Insulation Joint Compound
R	Water Tank Insulation
S	Aircell Duct Insulation
T	Magblock Insulation
U	Duct Insulation - Black Tar Like Adhesive

B. The following new homogenous areas have been identified for Building 2010:

- 154 Tan CMU
- 155 1" x 1" Gray Ceramic Floor Tile & Grout
- 156 5" x 5" Gray Ceramic Wall Tile & Grout
- 157 5" x 5" Blue Ceramic Wall Tile & Grout
- 158 5" x 5" Quarry Ceramic Floor Tile Grout
- 159 2" x 2" Dark Gray Floor Tile
- 160 2" x 2" Dark Gray Floor Tile Mastic
- 161 2" x 2" Blue Floor Tile
- 162 2" x 2" Blue Floor Tile Mastic
- 163 2" x 2" Off White Floor Tile
- 164 2" x 2" Off White Floor Tile Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

018	Plaster
082	12" x 12" Sandy Beige Floor Tile
086	12" x 12" Off-White Floor Tile
096	Vault Door Insulation
107	Roofing Materials - Non-AHERA
108	Roofing Materials - Non-AHERA
109	Roofing Materials - Non-AHERA
110	Interior Window Caulk
111	12" x 12" Light Beige w/ Brown & White Streaks Floor Tile
112	12" x 12" White w/ Off-White & Beige Streaks Floor Tile
113	HA 111 & HA 112 Checkerboard Floor Tile Pattern Mastic
114	12" x 12" Red Floor Tile
115	12" x 12" Red Floor Tile Mastic
116	12" x 12" Blue Floor Tile
117	12" x 12" Blue Floor Tile Mastic
118	Green Carpet Adhesive
119	Acoustical Ceiling
120	12" x 12" Beige Mix Floor Tile
121	12" x 12" Beige Mix Floor Tile Mastic
122	Red Carpet Adhesive
123	Black Board/ Marker Board Adhesive
124	Gray and Black Mix Terrazzo Flooring
125	12" x 12" Tand w/ Brown and White Streaks Floor Tile
126	12" x 12" Tand w/ Brown and White Streaks Floor Tile Mastic
127	Cork Board Adhesive
128	Green Carpet Adhesive
139	Transite Laboratory Countertop
142	Blue Sheet Flooring
143	Blue Sheet Flooring Mastic
144	Transite Electrical Panel
146	12" x 12" Light Beige w/ White Streaks Floor Tile
147	12" x 12" Light Beige w/ White Streaks Floor Tile Mastic
148	Black Science Lab Counter Tables
149	Black Science Lab Counter
150	12" x 12" Gray w/ Black Spots Floor Tile
151	12" x 12" Gray w/ Black Spots Floor Tile Mastic

152	2" x 2" Blue, Gray, and Light Gray Vinyl Floor Tile
153	Blue Carpet Mastic
154	Tan CMU
155	1" x 1" Gray Ceramic Floor Tile & Grout
156	5" x 5" Gray Ceramic Wall Tile & Grout
157	5" x 5" Blue Ceramic Wall Tile & Grout
158	5" x 5" Quarry Ceramic Floor Tile Grout
159	2" x 2" Dark Gray Floor Tile
160	2" x 2" Dark Gray Floor Tile Mastic
161	2" x 2" Blue Floor Tile
162	2" x 2" Blue Floor Tile Mastic
163	2" x 2" Off White Floor Tile
164	2" x 2" Off White Floor Tile Mastic
88	9" x 9" Cream Floor Tile w/ White Streaks
89	9" x 9" Cream Floor Tile w/ White Streaks Mastic
90	9" x 9" Light Brown Mottled Floor Tile
91	9" x 9" Light Brown Mottled Floor Tile Mastic

The following areas were deemed to be inaccessible:

075	9" x 9" Light Brown Floor Tile Mastic
083	12" x 12" Sandy Beige Floor Tile Mastic
085	9" x 9" Orange Floor Tile Mastic
087	12" x 12" Off-White Floor Tile Mastic
145	Electrical Wiring Associated w/ Wall Mounted Clocks
160	2" x 2" Dark Gray Floor Tile Mastic
162	2" x 2" Blue Floor Tile Mastic
164	2" x 2" Off White Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Marcos Iwankiw, IDPH License # 100-03175. The Management Plan was updated by Mike Serio, IDPH License # 100-18488. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Air Force High School (formerly Abbott School) Building 2010 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010
Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
006	12" x 12" Beige Floor Tile w/ Brown & White Streaks			Material Not Present	NO_ACBM	MISC					Yes			
007	12" x 12" Light Brown Floor Tile w/ Brown & White Streaks			ABATED	ABATED	MISC					No			
008	9" x 9" Dark Brown Floor Tile Mastic			ABATED	ABATED	MISC					Yes			
009	Mastic on 12" x 12" Dark Brown w/ Brown & White Streaks Floor Tile			ABATED	ABATED	MISC					Yes			
010	Mastic on 12" x 12" Light Brown w/ Brown & White Streaks Floor Tile			ABATED	ABATED	MISC					Yes			
011	Partition Floor Joiner Compound			1946/53 Connection by Room 104	NO_ACBM	MISC					Yes			
012	12" x 12" Light Brown w/ Brown & White Streaks Floor Tile			ABATED	ABATED	MISC					No			
013	Mastic on 12" x 12" Light Brown w/ Brown & White Streaks Floor Tile (Duplicate Of HA 10)			ABATED	ABATED	MISC					Yes			
014	Carpet Adhesive			ABATED	ABATED	MISC					Yes			
015	Black Vinyl Baseboard			Material Not Present	NO_ACBM	MISC					Yes			
016	Black Vinyl Baseboard Adhesive			Material Not Present	NO_ACBM	MISC					No			
017	Sink Bottom Caulking			ABATED	ABATED	MISC					No			
018	Plaster	50,000	SF	1946 Building, 1960 Building	ASSUMED	SURFACE	N	LOC	10	SF	Yes	ACBM with potential for significant damage	5	LOW
019	Interior Brick Walls			1946 Building	NO_ACBM	MISC					No			
020	Interior Brick Walls Mortar			1946 Building	NO_ACBM	MISC					No			
021	12" x 12" Green Floor Tile			ABATED	ABATED	MISC					Yes			
022	Mastic on 12" x 12" Green Floor Tile			ABATED	ABATED	MISC					Yes			
023	Tar Paper and Mastic in Vault Closet Areas			ABATED	ABATED	MISC					Yes			
024	Vibration Isolator			1946 Building, Attic Above 200 and 201	NO_ACBM	MISC					Yes			
025	Fan Unit Door Lining			1946 Building, Attic Above 200 and 201	NO_ACBM	TSI					No			
026	Dirt on Floor			ABATED	ABATED	TSI					No			
027	Mastic on 12" x 12" Beige w/ Brown & White Streaks Floor Tile			ABATED	ABATED	MISC					Yes			
028	Partition Wall Joiner Compound			ABATED	ABATED	MISC					Yes			
029	12" x 12" Dark Gray w/ White & Brown Streaks Floor Tile			Material Not Present	NO_ACBM	MISC					Yes			
030	12" x 12" Dark Gray Floor Tile w/ Beige Mix			Material Not Present	NO_ACBM	MISC					No			
031	Mastic on 12" x 12" Dark Gray w/ Beige Mix Floor Tile			ABATED	ABATED	MISC					No			
032	12" x 12" Light Beige Mix Floor Tile			Material Not Present	NO_ACBM	MISC					Yes			
033	Mastic on 12" x 12" Light Beige Mix Floor			ABATED	ABATED	MISC					No			

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010
Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Tile													
034	12" x 12" Dark Pink Floor Tile			Material Not Present	NO_ACBM	MISC					Yes			
035	Adhesive For 12" x 12" Dark Pink Floor Tile			Material Not Present	NO_ACBM	MISC					No			
036	12" x 12" Dark Beige w/ Brown & White Streaks Floor Tile			Material Not Present	NO_ACBM	MISC					No			
037	Mastic on 12" x 12" Dark Beige w/ Brown & White Streaks Floor Tile			Material Not Present	NO_ACBM	MISC					No			
038	12" x 12" Light Gray Mix Floor Tile			Material Not Present	NO_ACBM	MISC					No			
039	Mastic on 12" x 12" Light Gray Mix Floor Tile			ABATED	ABATED	MISC					No			
040	Gray and Yellow Mix Linoleum			Material Not Present	NO_ACBM	MISC					Yes			
041	Burlap w/ Adhesive Under Gray & Yellow Linoleum			Material Not Present	NO_ACBM	MISC					No			
042	12" x 12" Blue Floor Tile			Hallways	NO_ACBM	MISC					No			
043	12" x 12" Blue Floor Tile Mastic	10,000	SF	Hallways	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
044	Mastic 12" x 12" Dark Gray w/ White & Brown Streaks Floor Tile			ABATED	ABATED	MISC					Yes			
045	Interior Brick			1953 Building	NO_ACBM	MISC					Yes			
046	Interior Brick Mortar			1953 Building	NO_ACBM	MISC					No			
047	Plaster			1953 Building	NO_ACBM	SURFACE					Yes			
048	Light Gray Vinyl Baseboard			Material Not Present	NO_ACBM	MISC					No			
049	9" x 9" Brown Floor Tile			ABATED	ABATED	MISC					No			
050	Mastic on 9" x 9" Brown Floor Tile			ABATED	ABATED	MISC					Yes			
051	Desk Top Linoleum			Material Not Present	NO_ACBM	MISC					Yes			
052	Desk Top Linoleum Adhesive			Material Not Present	NO_ACBM	MISC					No			
053	Black Vinyl Baseboard			Material Not Present	NO_ACBM	MISC					No			
054	Black Vinyl Baseboard Adhesive			Material Not Present	NO_ACBM	MISC					No			
055	12" x 12" Dark Beige w/ Brown & White Streaks Floor Tile			ABATED	ABATED	MISC					No			
056	12" x 12" Blue Floor Tile			Hallways	NO_ACBM	MISC					Yes			
057	12" x 12" Blue Floor Tile Adhesive			Hallways	NO_ACBM	MISC					No			
058	Dark Gray Vinyl Baseboard			Material Not Present	NO_ACBM	MISC					No			
059	Dark Gray Vinyl Baseboard Adhesive			Material Not Present	NO_ACBM	MISC					No			
060	12" x 12" Gray Mix Floor Tile			Material Not Present	NO_ACBM	MISC					No			
061	Mastic on 12" x 12" Gray Mix Floor Tile			ABATED	ABATED	MISC					No			
062	Cork Insulation			Fan Room by 214	NO_ACBM	TSI					Yes			
063	Vibration Isolator			Fan Room by 214	NO_ACBM	MISC					No			
064	12" x 12" Beige Floor Tile w/ Brown & White Streaks			Material Not Present	NO_ACBM	MISC					No			
065	Mastic on 12" x 12" Beige Floor Tile w/			Material Not Present	NO_ACBM	MISC					No			

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010
Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Brown & White Streaks													
066	12" x 12" Light Brown Floor Tile			Material Not Present	NO_ACBM	MISC					No			
067	12" x 12" Light Brown Floor Tile Adhesive			Material Not Present	NO_ACBM	MISC					No			
068	12" x 12" Dark Pink Floor Tile			Material Not Present	NO_ACBM	MISC					No			
069	12" x 12" Dark Pink Floor Tile Adhesive			Material Not Present	NO_ACBM	MISC					No			
070	Fan Unit Door Lining Insulation			1946 Building, Basement	NO_ACBM	TSI					No			
071	9" x 9" Gray Floor Tile			ABATED	ABATED	MISC					No			
072	Mastic on 12" x 12" Gray Floor Tile			ABATED	ABATED	MISC					Yes			
073	Partition Wall Compound			Between 1953/60 Buildings, 1st and 2nd Floor Corridors	NO_ACBM	MISC					Yes			
074	9" x 9" Light Brown Floor Tile	200	SF	1960 Building, Store Room by Engineer's Office	CHR	MISC	N	LOC	10	SF	Yes	ACBM with potential for significant damage	5	MODERATE
075	9" x 9" Light Brown Floor Tile Mastic	200	SF	1960 Building, Store Room by Engineer's Office	CHR	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
076	Dark Gray Vinyl Baseboard			Material Not Present	NO_ACBM	MISC					Yes			
077	Dark Gray Vinyl Baseboard Adhesive			Material Not Present	NO_ACBM	MISC					No			
078	Pump Floor/Unit Caulk			1960 Building, Boiler Room	NO_ACBM	MISC					No			
079	Boiler Gasket Material	100	LF	Boiler room	CHR	TSI	N	NONE			No	ACBM with the potential for damage		LOW
080	Interior Brick			1960 Building	NO_ACBM	MISC					No			
081	Interior Brick Mortar			1960 Building	NO_ACBM	MISC					No			
082	12" x 12" Sandy Beige Floor Tile	250	SF	1960 Building, Engineer's Office	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
083	12" x 12" Sandy Beige Floor Tile Mastic	250	SF	1960 Building, Engineer's Office	CHR	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
084	9" x 9" Orange Floor Tile	108	SF	1960 Building, Engineer's Office Corridor	CHR	MISC	N	LOC	10	SF	No	ACBM with potential for significant damage	5	LOW
085	9" x 9" Orange Floor Tile Mastic	108	SF	1960 Building, Engineer's Office Corridor	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
086	12" x 12" Off-White Floor Tile	30	SF	1960 Building, Store Room Bathroom Across From Engineer's Office	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
087	12" x 12" Off-White Floor Tile Mastic	30	SF	1960 Building, Store Room Bathroom Across From	CHR	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010
Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Engineer's Office										
088	12" x 12" Light Gray Mix Floor Tile			Material Not Present	NO_ACBM	MISC					Yes			
089	12" x 12" Light Gray Mix Floor Tile Mastic			Material Not Present	NO_ACBM	MISC					Yes			
090	Radiator Grill Lining Material			1960 Building	NO_ACBM	TSI					Yes			
091	Incinerator Gasket Material By Fire Hole			ABATED	ABATED	TSI					Yes			
092	Incinerator Interior Brick			Material Not Present	NO_ACBM	MISC					Yes			
093	Incinerator Ash Chamber Brick			Material Not Present	NO_ACBM	MISC					No			
094	Vibration Isolator			1946 Building, Fan Unit	NO_ACBM	MISC					No			
095	White Chalky Material and Soil Mix			1953 Building, Unfinished Pipe Space	NO_ACBM	MISC					No			
096	Vault Door Insulation			Material Not Present	ASSUMED	MISC					No			
097	Light Gray Vinyl Baseboard			Material Not Present	NO_ACBM	MISC					No			
098	Light Gray Vinyl Baseboard Adhesive			Material Not Present	NO_ACBM	MISC					No			
099	Beaver Board			Material Not Present	NO_ACBM	MISC					No			
100	Exterior Brick			1946 Building	NO_ACBM	MISC					No			
101	Exterior Brick Mortar			1946 Building	NO_ACBM	MISC					No			
102	Exterior Brick			1953 Building	NO_ACBM	MISC					No			
103	Exterior Brick Mortar			1953 Building	NO_ACBM	MISC					No			
104	Exterior Brick			1960 Building	NO_ACBM	MISC					No			
105	Exterior Brick Mortar			1960 Building	NO_ACBM	MISC					No			
106	Exterior Door Caulk - Non-AHERA			1960 Building	NO_ACBM	MISC					No			
107	Roofing Materials - Non-AHERA			1946 Building	ASSUMED	MISC					No			
108	Roofing Materials - Non-AHERA			1953 Building	ASSUMED	MISC					Yes			
109	Roofing Materials - Non-AHERA			1960 Building	ASSUMED	MISC					Yes			
110	Interior Window Caulk			Material Not Present	ASSUMED	MISC					Yes			
111	12" x 12" Light Beige w/ Brown & White Streaks Floor Tile			Material Not Present	ASSUMED	MISC					Yes			
112	12" x 12" White w/ Off-White & Beige Streaks Floor Tile			Material Not Present	ASSUMED	MISC					Yes			
113	HA 111 & HA 112 Checkerboard Floor Tile Pattern Mastic			Material Not Present	ASSUMED	MISC					Yes			
114	12" x 12" Red Floor Tile			Material Not Present	ASSUMED	MISC					Yes			
115	12" x 12" Red Floor Tile Mastic			Material Not Present	ASSUMED	MISC					Yes			
116	12" x 12" Blue Floor Tile	10,000	SF	Hallways	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
117	12" x 12" Blue Floor Tile Mastic			Material Not Present	ASSUMED	MISC					Yes			
118	Green Carpet Adhesive			Material Not Present	ASSUMED	MISC					Yes			
119	Acoustical Ceiling	10,000	SF	Throughout Hallways of the 1960 Building	ASSUMED	MISC	Y	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010
Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
120	12" x 12" Beige Mix Floor Tile			Material Not Present	ASSUMED	MISC					Yes			
121	12" x 12" Beige Mix Floor Tile Mastic			Material Not Present	ASSUMED	MISC					Yes			
122	Red Carpet Adhesive			Material Not Present	ASSUMED	MISC					Yes			
123	Black Board/ Marker Board Adhesive	5,000	SF	Classrooms	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
124	Gray and Black Mix Terrazzo Flooring	4,000	SF	East Entrances and Stairwells	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
125	12" x 12" Tand w/ Brown and White Streaks Floor Tile			Material Not Present	ASSUMED	MISC					Yes			
126	12" x 12" Tand w/ Brown and White Streaks Floor Tile Mastic			Material Not Present	ASSUMED	MISC					Yes			
127	Cork Board Adhesive			Material Not Present	ASSUMED	MISC					Yes			
128	Green Carpet Adhesive			Material Not Present	ASSUMED	MISC					Yes			
129	12" x 12" White Mottled Floor Tile			Throughout Corridors, Classrooms, and Offices	NO_ACBM	MISC					Yes			
130	12" x 12" White Mottled Floor Tile Mastic			Throughout Corridors, Classrooms, and Offices	NO_ACBM	MISC					No			
131	12" x 12" Blue Mottled Floor Tile			Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules	NO_ACBM	MISC					No			
132	12" x 12" Blue Mottled Floor Tile Mastic			Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules	NO_ACBM	MISC					No			
133	2' x 2' Lay-in Ceiling Tile			First Floor Corridor, Room 216	NO_ACBM	MISC					No			
134	2' x 4' Lay-in Ceiling Tile			Rooms 112a, 126, and 226	NO_ACBM	MISC					No			
135	4" Gray Baseboard			Rooms 115, 117, 133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226, 228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage,	NO_ACBM	MISC					No			

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010
Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Lunchroom, and 2nd Floor Store Room										
136	4" Gray Baseboard Mastic			Rooms 115, 117, 133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226, 228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage, Lunchroom, and 2nd Floor Store Room	NO_ACBM	MISC					No			
137	Gray Sink Undercoating			Rooms 128, 130, and 133	NO_ACBM	MISC					No			
138	Carpet Mastic			Rooms 134 and 212	NO_ACBM	MISC					No			
139	Transite Laboratory Countertop	400	SF	Rooms 109 and 226	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
140	Wood Pattern Sheet Flooring			Gym	NO_ACBM	MISC					Yes			
141	Wood Pattern Sheet Flooring Mastic			Gym	NO_ACBM	MISC					No			
142	Blue Sheet Flooring			Room 126	ASSUMED	MISC					No			
143	Blue Sheet Flooring Mastic			Room 126	ASSUMED	MISC					Yes			
144	Transite Electrical Panel	200	SF	Basement Electrical Vault	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
145	Electrical Wiring Associated w/ Wall Mounted Clocks	150	LF	Throughout Building	CHR	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
146	12" x 12" Light Beige w/ White Streaks Floor Tile	25,000	SF	Rooms 106, 104, 101, Corridor, 103, 109, 110, 112, 113, 115, 116, 117, 128, 127, 132, 233, 232, 231, 230, 229, 228, 227, 225, 226, 217, 215, 211, 209, 210, 206, 205, 204, 203, 202, 201	ASSUMED	SURFACE	N	NONE			Yes	ACBM with potential for significant damage		LOW
147	12" x 12" Light Beige w/ White Streaks Floor Tile Mastic	25,000	SF	Rooms 106, 104, 101, Corridor, 103, 109, 110, 112, 113, 115, 116, 117, 128, 127, 132, 233, 232, 231, 230, 229, 228, 227, 225, 226, 217, 215, 211, 209, 210,	ASSUMED	SURFACE	N	NONE			Yes	ACBM with the potential for damage		LOW

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010
Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				206, 205, 204, 203, 202, 201										
148	Black Science Lab Counter Tables	46		Rooms 109, 226, 216	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
149	Black Science Lab Counter	90	SF	Rooms 109, 226, 216	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
150	12" x 12" Gray w/ Black Spots Floor Tile	800	SF	Rooms 133, 134	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
151	12" x 12" Gray w/ Black Spots Floor Tile Mastic	800	SF	Rooms 133, 134	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
152	2" x 2" Blue, Gray, and Light Gray Vinyl Floor Tile	500	SF	Room 216	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
153	Blue Carpet Mastic	500	SF	Room 212	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
154	Tan CMU	10,000	LF	Girls and Boys Toilet Rooms	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
155	1" x 1" Gray Ceramic Floor Tile & Grout	15,000	SF	Toilet Rooms, Locker Rooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
156	5" x 5" Gray Ceramic Wall Tile & Grout	10,000	LF	Men's and Women's Locker Room	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
157	5" x 5" Blue Ceramic Wall Tile & Grout	1,000	LF	Men's and Women's Locker Rooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
158	5" x 5" Quarry Ceramic Floor Tile Grout	1,000	SF	Kitchen	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
159	2" x 2" Dark Gray Floor Tile	50	SF	Classroom 216	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
160	2" x 2" Dark Gray Floor Tile Mastic	50	SF	Classroom 216	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
161	2" x 2" Blue Floor Tile	50	SF	Classroom 216	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
162	2" x 2" Blue Floor Tile Mastic	50	SF	Classroom 216	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
163	2" x 2" Off White Floor Tile	100	SF	Classroom 216	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
164	2" x 2" Off White Floor Tile Mastic	100	SF	Classroom 216	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
74	9" x 9" Light Brown Floor Tile Mastic	200	SF	1960 Building, Store Room by Engineer's Office	CHR	MISC	N	NONE			No	ACBM with potential for significant damage		LOW
88	9" x 9" Cream Floor Tile w/ White Streaks	10	SF	Engineer's Office	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
89	9" x 9" Cream Floor Tile w/ White Streaks Mastic	10	SF	Engineer's Office	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
90	9" x 9" Light Brown Mottled Floor Tile	5	SF	Engineer's Office	ASSUMED	MISC	N	NONE			No	ACBM with the		LOW

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010
Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
91	9" x 9" Light Brown Mottled Floor Tile Mastic	5	SF	Engineer's Office	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
B	Distributed Pipe Insulation on Floor			ABATED	ABATED	MISC								
C	Aircel Pipe Insulation			ABATED	ABATED	TSI					Yes			
D	Joint Compound Off Fiberglass Pipe Insulation			ABATED	ABATED	TSI					Yes			
E	Joint Compound Off Fiberglass Pipe Insulation			ABATED	ABATED	TSI					Yes			
F	Distributed Pipe Insulation in Dirt on Floor			ABATED	ABATED	TSI					Yes			
G	Distributed Pipe Insulation in Dirt on Floor			ABATED	ABATED	TSI					Yes			
H	Aircell Pipe Insulation			ABATED	ABATED	TSI					Yes			
I	Aircell Pipe Insulation			ABATED	ABATED	TSI					Yes			
J	Paperwrap Pipe Insulation			1946 Building, Pipe Chases	NO_ACBM	TSI					Yes			
K	Hard Joint Compound Off Paperwrap Pipe Insulation	75	LF	1946 Building, Walls and Pipe Chases	CHR	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
L	Hard Joint Compound Off Aircell Pipe Insulation			ABATED	ABATED	TSI					Yes			
L-1	Hard Joint Compound Off Aircell Pipe Insulation			ABATED	ABATED	TSI					Yes			
M	Hard Joint Compound Off Aircell Pipe Insulation			ABATED	ABATED	TSI					Yes			
N	Hard Joint Compound Off Aircell Pipe Insulation			ABATED	ABATED	TSI					Yes			
O	Duct Interior Insulation			1960 Building, Boiler Room	NO_ACBM	TSI					Yes			
P	Magblock Pipe Insulation			ABATED	ABATED	TSI					No			
Q	Magblock Pipe Insulation Joint Compound			ABATED	ABATED	TSI					Yes			
R	Water Tank Insulation			ABATED	ABATED	TSI					Yes			
S	Aircell Duct Insulation			ABATED	ABATED	TSI					Yes			
T	Magblock Insulation	15	LF	1946 Building, Coal/Ash Room Abandoned Mech. Unit	CHR	TSI	Y	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
U	Duct Insulation - Black Tar Like Adhesive			ABATED	ABATED	TSI					Yes			

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010
Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date	<u>4/8/2025</u>
Inspector Name	<u>Marcos Iwankiw</u>
100-03175	5/15/2026
Inspector's IDPH License Number / Expiration Date	

Inspector's Comments

HA Number:	Inspector Comments:
006	
007	
008	
009	
010	
011	
012	
013	
014	
015	
016	
017	
018	Damaged plaster ceiling in basement
019	
020	
021	
022	
023	
024	
025	
026	
027	
028	
029	

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010
Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
030	
031	
032	
033	
034	Material not observed - 2025
035	Material not observed - 2025
036	
037	
038	
039	
040	
041	
042	
043	
044	
045	
046	
047	
048	
049	
050	
051	
052	
053	
054	
055	
056	
057	
058	

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010
Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
059	
060	
061	
062	
063	
064	
065	
066	
067	
068	
069	
070	
071	
072	
073	
074	Damage in Engineer's corridor
075	
076	
077	
078	
079	
080	
081	
082	
083	
084	Damage in Engineer's corridor
085	
086	
087	

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010
Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
088	
089	
090	
091	
092	
093	
094	
095	
096	Material not observed - 2025
097	
098	
099	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
110	Material not observed - 2025
111	Material not observed - 2025
112	Material not observed - 2025
113	Material not observed - 2025
114	Material not observed - 2025
115	Material not observed - 2025
116	

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010
Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
117	Material not observed - 2025
118	Material not observed - 2025
119	
120	Material not observed - 2025
121	Material not observed - 2025
122	Material not observed - 2025
123	
124	
125	Material not observed - 2025
126	Material not observed - 2025
127	Material not observed - 2025
128	Material not observed - 2025
129	
130	
131	
132	
133	
134	
135	
136	
137	
138	
139	
140	
141	
142	Material not observed - 2025
143	Material not observed - 2025
144	
145	

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010
Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
146	
147	
148	
149	
150	
151	
152	
153	
154	
155	
156	
157	
158	
159	
160	
161	
162	
163	
164	
74	
88	
89	
90	
91	
B	
C	
D	
E	
F	

Chicago Public Schools

School Air Force High School (formerly Abbott School) **Unit** 45231 **Building ID** 2010
Address 3630 S. Wells **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
G	
H	
I	
J	
K	
L	
L-1	
M	
N	
O	
P	
Q	
R	
S	
T	
U	

Table II
Management Planner's Review

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
006	12" x 12" Beige Floor Tile w/ Brown & White Streaks			Material Not Present	No ACBM	MISC					
007	12" x 12" Light Brown Floor Tile w/ Brown & White Streaks			ABATED	Abated	MISC					
008	9" x 9" Dark Brown Floor Tile Mastic			ABATED	Abated	MISC					
009	Mastic on 12" x 12" Dark Brown w/ Brown & White Streaks Floor Tile			ABATED	Abated	MISC					
010	Mastic on 12" x 12" Light Brown w/ Brown & White Streaks Floor Tile			ABATED	Abated	MISC					
011	Partition Floor Joiner Compound			1946/53 Connection by Room 104	No ACBM	MISC					
012	12" x 12" Light Brown w/ Brown & White Streaks Floor Tile			ABATED	Abated	MISC					
013	Mastic on 12" x 12" Light Brown w/ Brown & White Streaks Floor Tile (Duplicate Of HA 10)			ABATED	Abated	MISC					
014	Carpet Adhesive			ABATED	Abated	MISC					
015	Black Vinyl Baseboard			Material Not Present	No ACBM	MISC					
016	Black Vinyl Baseboard Adhesive			Material Not Present	No ACBM	MISC					
017	Sink Bottom Caulking			ABATED	Abated	MISC					
018	Plaster	50,000	SF	1946 Building, 1960 Building	Assumed	SURFACE	No	10	SF	5 ACBM with potential for significant damage	Repair
019	Interior Brick Walls			1946 Building	No ACBM	MISC					
020	Interior Brick Walls Mortar			1946 Building	No ACBM	MISC					
021	12" x 12" Green Floor Tile			ABATED	Abated	MISC					
022	Mastic on 12" x 12" Green Floor Tile			ABATED	Abated	MISC					
023	Tar Paper and Mastic in Vault Closet Areas			ABATED	Abated	MISC					
024	Vibration Isolator			1946 Building, Attic Above 200 and 201	No ACBM	MISC					
025	Fan Unit Door Lining			1946 Building, Attic Above 200 and 201	No ACBM	TSI					
026	Dirt on Floor			ABATED	Abated	TSI					
027	Mastic on 12" x 12" Beige w/ Brown & White Streaks Floor Tile			ABATED	Abated	MISC					
028	Partition Wall Joiner Compound			ABATED	Abated	MISC					
029	12" x 12" Dark Gray w/ White & Brown Streaks Floor Tile			Material Not Present	No ACBM	MISC					
030	12" x 12" Dark Gray Floor Tile w/ Beige Mix			Material Not Present	No ACBM	MISC					

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
031	Mastic on 12" x 12" Dark Gray w/ Beige Mix Floor Tile			ABATED	Abated	MISC					
032	12" x 12" Light Beige Mix Floor Tile			Material Not Present	No ACBM	MISC					
033	Mastic on 12" x 12" Light Beige Mix Floor Tile			ABATED	Abated	MISC					
034	12" x 12" Dark Pink Floor Tile			Material Not Present	No ACBM	MISC					
035	Adhesive For 12" x 12" Dark Pink Floor Tile			Material Not Present	No ACBM	MISC					
036	12" x 12" Dark Beige w/ Brown & White Streaks Floor Tile			Material Not Present	No ACBM	MISC					
037	Mastic on 12" x 12" Dark Beige w/ Brown & White Streaks Floor Tile			Material Not Present	No ACBM	MISC					
038	12" x 12" Light Gray Mix Floor Tile			Material Not Present	No ACBM	MISC					
039	Mastic on 12" x 12" Light Gray Mix Floor Tile			ABATED	Abated	MISC					
040	Gray and Yellow Mix Linoleum			Material Not Present	No ACBM	MISC					
041	Burlap w/ Adhesive Under Gray & Yellow Linoleum			Material Not Present	No ACBM	MISC					
042	12" x 12" Blue Floor Tile			Hallways	No ACBM	MISC					
043	12" x 12" Blue Floor Tile Mastic	10,000	SF	Hallways	Chrysotile	MISC	No	SF	6 ACBM with the potential for damage	Follow O&M Plan	
044	Mastic 12" x 12" Dark Gray w/ White & Brown Streaks Floor Tile			ABATED	Abated	MISC					
045	Interior Brick			1953 Building	No ACBM	MISC					
046	Interior Brick Mortar			1953 Building	No ACBM	MISC					
047	Plaster			1953 Building	No ACBM	SURFACE					
048	Light Gray Vinyl Baseboard			Material Not Present	No ACBM	MISC					
049	9" x 9" Brown Floor Tile			ABATED	Abated	MISC					
050	Mastic on 9" x 9" Brown Floor Tile			ABATED	Abated	MISC					
051	Desk Top Linoleum			Material Not Present	No ACBM	MISC					
052	Desk Top Linoleum Adhesive			Material Not Present	No ACBM	MISC					
053	Black Vinyl Baseboard			Material Not Present	No ACBM	MISC					
054	Black Vinyl Baseboard Adhesive			Material Not Present	No ACBM	MISC					
055	12" x 12" Dark Beige w/ Brown & White Streaks Floor Tile			ABATED	Abated	MISC					
056	12" x 12" Blue Floor Tile			Hallways	No ACBM	MISC					
057	12" x 12" Blue Floor Tile Adhesive			Hallways	No ACBM	MISC					
058	Dark Gray Vinyl Baseboard			Material Not Present	No ACBM	MISC					
059	Dark Gray Vinyl Baseboard Adhesive			Material Not Present	No ACBM	MISC					

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
060	12" x 12" Gray Mix Floor Tile			Material Not Present	No ACBM	MISC					
061	Mastic on 12" x 12" Gray Mix Floor Tile			ABATED	Abated	MISC					
062	Cork Insulation			Fan Room by 214	No ACBM	TSI					
063	Vibration Isolator			Fan Room by 214	No ACBM	MISC					
064	12" x 12" Beige Floor Tile w/ Brown & White Streaks			Material Not Present	No ACBM	MISC					
065	Mastic on 12" x 12" Beige Floor Tile w/ Brown & White Streaks			Material Not Present	No ACBM	MISC					
066	12" x 12" Light Brown Floor Tile			Material Not Present	No ACBM	MISC					
067	12" x 12" Light Brown Floor Tile Adhesive			Material Not Present	No ACBM	MISC					
068	12" x 12" Dark Pink Floor Tile			Material Not Present	No ACBM	MISC					
069	12" x 12" Dark Pink Floor Tile Adhesive			Material Not Present	No ACBM	MISC					
070	Fan Unit Door Lining Insulation			1946 Building, Basement	No ACBM	TSI					
071	9" x 9" Gray Floor Tile			ABATED	Abated	MISC					
072	Mastic on 12" x 12" Gray Floor Tile			ABATED	Abated	MISC					
073	Partition Wall Compound			Between 1953/60 Buildings, 1st and 2nd Floor Corridors	No ACBM	MISC					
074	9" x 9" Light Brown Floor Tile	200	SF	1960 Building, Store Room by Engineer's Office	Chrysotile	MISC	No	10	SF	5 ACBM with potential for significant damage	Remove
075	9" x 9" Light Brown Floor Tile Mastic	200	SF	1960 Building, Store Room by Engineer's Office	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
076	Dark Gray Vinyl Baseboard			Material Not Present	No ACBM	MISC					
077	Dark Gray Vinyl Baseboard Adhesive			Material Not Present	No ACBM	MISC					
078	Pump Floor/Unit Caulk			1960 Building, Boiler Room	No ACBM	MISC					
079	Boiler Gasket Material	100	LF	Boiler room	Chrysotile	TSI	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
080	Interior Brick			1960 Building	No ACBM	MISC					
081	Interior Brick Mortar			1960 Building	No ACBM	MISC					
082	12" x 12" Sandy Beige Floor Tile	250	SF	1960 Building, Engineer's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
083	12" x 12" Sandy Beige Floor Tile Mastic	250	SF	1960 Building, Engineer's Office	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
084	9" x 9" Orange Floor Tile	108	SF	1960 Building, Engineer's Office Corridor	Chrysotile	MISC	No	10	SF	5 ACBM with potential for significant damage	Remove
085	9" x 9" Orange Floor Tile Mastic	108	SF	1960 Building, Engineer's Office Corridor	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
086	12" x 12" Off-White Floor Tile	30	SF	1960 Building, Store Room Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
087	12" x 12" Off-White Floor Tile Mastic	30	SF	Across From Engineer's Office 1960 Building, Store Room Bathroom Across Front Engineer's Office	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
088	12" x 12" Light Gray Mix Floor Tile			Material Not Present	No ACBM	MISC					
089	12" x 12" Light Gray Mix Floor Tile Mastic			Material Not Present	No ACBM	MISC					
090	Radiator Grill Lining Material			1960 Building	No ACBM	TSI					
091	Incinerator Gasket Material By Fire Hole			ABATED	Abated	TSI					
092	Incinerator Interior Brick			Material Not Present	No ACBM	MISC					
093	Incinerator Ash Chamber Brick			Material Not Present	No ACBM	MISC					
094	Vibration Isolator			1946 Building, Fan Unit	No ACBM	MISC					
095	White Chalky Material and Soil Mix			1953 Building, Unfinished Pipe Space	No ACBM	MISC					
096	Vault Door Insulation			Material Not Present	Assumed	MISC					Follow O&M Plan
097	Light Gray Vinyl Baseboard			Material Not Present	No ACBM	MISC					
098	Light Gray Vinyl Baseboard Adhesive			Material Not Present	No ACBM	MISC					
099	Beaver Board			Material Not Present	No ACBM	MISC					
100	Exterior Brick			1946 Building	No ACBM	MISC					
101	Exterior Brick Mortar			1946 Building	No ACBM	MISC					
102	Exterior Brick			1953 Building	No ACBM	MISC					
103	Exterior Brick Mortar			1953 Building	No ACBM	MISC					
104	Exterior Brick			1960 Building	No ACBM	MISC					
105	Exterior Brick Mortar			1960 Building	No ACBM	MISC					
106	Exterior Door Caulk - Non-AHERA			1960 Building	No ACBM	MISC					
107	Roofing Materials - Non-AHERA			1946 Building	Assumed	MISC					
108	Roofing Materials - Non-AHERA			1953 Building	Assumed	MISC					
109	Roofing Materials - Non-AHERA			1960 Building	Assumed	MISC					
110	Interior Window Caulk			Material Not Present	Assumed	MISC					Follow O&M Plan
111	12" x 12" Light Beige w/ Brown & White Streaks Floor Tile			Material Not Present	Assumed	MISC					Follow O&M Plan
112	12" x 12" White w/ Off-White & Beige Streaks Floor Tile			Material Not Present	Assumed	MISC					Follow O&M Plan
113	HA 111 & HA 112 Checkerboard Floor Tile Pattern Mastic			Material Not Present	Assumed	MISC					Follow O&M Plan
114	12" x 12" Red Floor Tile			Material Not Present	Assumed	MISC					Follow O&M Plan
115	12" x 12" Red Floor Tile Mastic			Material Not Present	Assumed	MISC					Follow O&M Plan

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
116	12" x 12" Blue Floor Tile	10,000	SF	Hallways	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
117	12" x 12" Blue Floor Tile Mastic			Material Not Present	Assumed	MISC					Follow O&M Plan
118	Green Carpet Adhesive			Material Not Present	Assumed	MISC					Follow O&M Plan
119	Acoustical Ceiling	10,000	SF	Throughout Hallways of the 1960 Building	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
120	12" x 12" Beige Mix Floor Tile			Material Not Present	Assumed	MISC					Follow O&M Plan
121	12" x 12" Beige Mix Floor Tile Mastic			Material Not Present	Assumed	MISC					Follow O&M Plan
122	Red Carpet Adhesive			Material Not Present	Assumed	MISC					Follow O&M Plan
123	Black Board/ Marker Board Adhesive	5,000	SF	Classrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
124	Gray and Black Mix Terrazzo Flooring	4,000	SF	East Entrances and Stairwells	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
125	12" x 12" Tand w/ Brown and White Streaks Floor Tile			Material Not Present	Assumed	MISC					Follow O&M Plan
126	12" x 12" Tand w/ Brown and White Streaks Floor Tile Mastic			Material Not Present	Assumed	MISC					Follow O&M Plan
127	Cork Board Adhesive			Material Not Present	Assumed	MISC					Follow O&M Plan
128	Green Carpet Adhesive			Material Not Present	Assumed	MISC					Follow O&M Plan
129	12" x 12" White Mottled Floor Tile			Throughout Corridors, Classrooms, and Offices	No ACBM	MISC					
130	12" x 12" White Mottled Floor Tile Mastic			Throughout Corridors, Classrooms, and Offices	No ACBM	MISC					
131	12" x 12" Blue Mottled Floor Tile			Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules	No ACBM	MISC					
132	12" x 12" Blue Mottled Floor Tile Mastic			Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules	No ACBM	MISC					
133	2' x 2' Lay-in Ceiling Tile			First Floor Corridor, Room 216	No ACBM	MISC					
134	2' x 4' Lay-in Ceiling Tile			Rooms 112a, 126, and 226	No ACBM	MISC					
135	4" Gray Baseboard			Rooms 115, 117, 133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226, 228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage, Lunchroom, and 2nd Floor Store Room	No ACBM	MISC					
136	4" Gray Baseboard Mastic			Rooms 115, 117, 133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233,	No ACBM	MISC					

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				231, 226, 228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage, Lunchroom, and 2nd Floor Store Room							
137	Gray Sink Undercoating			Rooms 128, 130, and 133	No ACBM	MISC					
138	Carpet Mastic			Rooms 134 and 212	No ACBM	MISC					
139	Transite Laboratory Countertop	400	SF	Rooms 109 and 226	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
140	Wood Pattern Sheet Flooring			Gym	No ACBM	MISC					
141	Wood Pattern Sheet Flooring Mastic			Gym	No ACBM	MISC					
142	Blue Sheet Flooring			Room 126	Assumed	MISC					Follow O&M Plan
143	Blue Sheet Flooring Mastic			Room 126	Assumed	MISC					Follow O&M Plan
144	Transite Electrical Panel	200	SF	Basement Electrical Vault	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
145	Electrical Wiring Associated w/ Wall Mounted Clocks	150	LF	Throughout Building	Chrysotile	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
146	12" x 12" Light Beige w/ White Streaks Floor Tile	25,000	SF	Rooms 106, 104, 101, Corridor, 103, 109, 110, 112, 113, 115, 116, 117, 128, 127, 132, 233, 232, 231, 230, 229, 228, 227, 225, 226, 217, 215, 211, 209, 210, 206, 205, 204, 203, 202, 201	Assumed	SURFACE	No		SF	5 ACBM with potential for significant damage	Follow O&M Plan
147	12" x 12" Light Beige w/ White Streaks Floor Tile Mastic	25,000	SF	Rooms 106, 104, 101, Corridor, 103, 109, 110, 112, 113, 115, 116, 117, 128, 127, 132, 233, 232, 231, 230, 229, 228, 227, 225, 226, 217, 215, 211, 209, 210, 206, 205, 204, 203, 202, 201	Assumed	SURFACE	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
148	Black Science Lab Counter Tables	46		Rooms 109, 226, 216	Assumed	MISC	No			6 ACBM with the potential for damage	Follow O&M Plan
149	Black Science Lab Counter	90	SF	Rooms 109, 226, 216	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
150	12" x 12" Gray w/ Black Spots Floor Tile	800	SF	Rooms 133, 134	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
151	12" x 12" Gray w/ Black Spots Floor Tile Mastic	800	SF	Rooms 133, 134	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
152	2" x 2" Blue, Gray, and Light Gray Vinyl Floor Tile	500	SF	Room 216	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
153	Blue Carpet Mastic	500	SF	Room 212	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
154	Tan CMU	10,000	LF	Girls and Boys Toilet Rooms	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
155	1" x 1" Gray Ceramic Floor Tile & Grout	15,000	SF	Toilet Rooms, Locker Rooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
156	5" x 5" Gray Ceramic Wall Tile & Grout	10,000	LF	Men's and Women's Locker Room	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
157	5" x 5" Blue Ceramic Wall Tile & Grout	1,000	LF	Men's and Women's Locker Rooms	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
158	5" x 5" Quarry Ceramic Floor Tile Grout	1,000	SF	Kitchen	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
159	2" x 2" Dark Gray Floor Tile	50	SF	Classroom 216	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
160	2" x 2" Dark Gray Floor Tile Mastic	50	SF	Classroom 216	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
161	2" x 2" Blue Floor Tile	50	SF	Classroom 216	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
162	2" x 2" Blue Floor Tile Mastic	50	SF	Classroom 216	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
163	2" x 2" Off White Floor Tile	100	SF	Classroom 216	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
164	2" x 2" Off White Floor Tile Mastic	100	SF	Classroom 216	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
74	9" x 9" Light Brown Floor Tile Mastic	200	SF	1960 Building, Store Room by Engineer's Office	Chrysotile	MISC	No		SF	5 ACBM with potential for significant damage	Follow O&M Plan
88	9" x 9" Cream Floor Tile w/ White Streaks	10	SF	Engineer's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
89	9" x 9" Cream Floor Tile w/ White Streaks Mastic	10	SF	Engineer's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
90	9" x 9" Light Brown Mottled Floor Tile	5	SF	Engineer's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
91	9" x 9" Light Brown Mottled Floor Tile Mastic	5	SF	Engineer's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
B	Distributed Pipe Insulation on Floor			ABATED	Abated	MISC					
C	Aircel Pipe Insulation			ABATED	Abated	TSI					
D	Joint Compound Off Fiberglass Pipe Insulation			ABATED	Abated	TSI					
E	Joint Compound Off Fiberglass Pipe Insulation			ABATED	Abated	TSI					
F	Distributed Pipe Insulation in Dirt on Floor			ABATED	Abated	TSI					
G	Distributed Pipe Insulation in Dirt on Floor			ABATED	Abated	TSI					
H	Aircell Pipe Insulation			ABATED	Abated	TSI					
I	Aircell Pipe Insulation			ABATED	Abated	TSI					
J	Paperwrap Pipe Insulation			1946 Building, Pipe Chases	No ACBM	TSI					
K	Hard Joint Compound Off Paperwrap Pipe Insulation	75	LF	1946 Building, Walls and Pipe Chases	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
L	Hard Joint Compound Off Aircell Pipe Insulation			ABATED	Abated	TSI					
L-1	Hard Joint Compound Off Aircell Pipe Insulation			ABATED	Abated	TSI					
M	Hard Joint Compound Off Aircell Pipe Insulation			ABATED	Abated	TSI					
N	Hard Joint Compound Off Aircell Pipe Insulation			ABATED	Abated	TSI					
O	Duct Interior Insulation			1960 Building, Boiler Room	No ACBM	TSI					
P	Magblock Pipe Insulation			ABATED	Abated	TSI					
Q	Magblock Pipe Insulation Joint Compound			ABATED	Abated	TSI					
R	Water Tank Insulation			ABATED	Abated	TSI					
S	Aircell Duct Insulation			ABATED	Abated	TSI					
T	Magblock Insulation	15	LF	1946 Building, Coal/Ash Room Abandoned Mech. Unit	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
U	Duct Insulation - Black Tar Like Adhesive			ABATED	Abated	TSI					

Review Date	5/5/2025
Manager Planner Name	Mike Serio

HA Number	Management Comments
006	
007	

Chicago Public Schools

School Air Force High School
(formerly Abbott School)
Address 3630 S. Wells

Unit 45231
Chicago, IL, 60609

Building ID 2010
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

100-18488	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
008	
009	
010	
011	
012	
013	
014	
015	
016	
017	
018	Sample to determine ACM content, remove or repair to intact.
019	
020	
021	
022	
023	
024	
025	
026	
027	
028	
029	
030	
031	
032	
033	

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
034	If identified, continue O&M
035	If identified, continue O&M
036	
037	
038	
039	
040	
041	
042	
043	
044	
045	
046	
047	
048	
049	
050	
051	
052	
053	
054	
055	
056	
057	
058	
059	

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Address 3630 S. Wells

Unit 45231

Chicago, IL, 60609

Building ID 2010

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
060	
061	
062	
063	
064	
065	
066	
067	
068	
069	
070	
071	
072	
073	
074	Remove and replace damaged material.
075	
076	
077	
078	
079	
080	
081	
082	Sample to determine ACM content prior to disturbance.
083	
084	Remove and replace damaged material.
085	

Chicago Public Schools

School Air Force High School
(formerly Abbott School)
Address 3630 S. Wells

Unit 45231
Chicago, IL, 60609

Building ID 2010
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
086	Sample to determine ACM content prior to disturbance.
087	
088	
089	
090	
091	
092	
093	
094	
095	
096	If identified, continue O&M
097	
098	
099	
100	
101	
102	
103	
104	
105	
106	Non-AHERA
107	Non-AHERA
108	Non-AHERA
109	Non-AHERA
110	If identified, continue O&M
111	If identified, continue O&M

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Address 3630 S. Wells

Unit 45231

Chicago, IL, 60609

Building ID 2010

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
112	If identified, continue O&M
113	If identified, continue O&M
114	If identified, continue O&M
115	If identified, continue O&M
116	Sample to determine ACM content prior to disturbance.
117	If identified, continue O&M
118	If identified, continue O&M
119	Sample to determine ACM content prior to disturbance.
120	If identified, continue O&M
121	If identified, continue O&M
122	If identified, continue O&M
123	Sample to determine ACM content prior to disturbance.
124	Sample to determine ACM content prior to disturbance.
125	If identified, continue O&M
126	If identified, continue O&M
127	If identified, continue O&M
128	If identified, continue O&M
129	
130	
131	
132	
133	
134	
135	
136	
137	

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
138	
139	Sample to determine ACM content prior to disturbance.
140	
141	
142	If identified, continue O&M
143	If identified, continue O&M
144	Sample to determine ACM content prior to disturbance.
145	
146	Sample to determine ACM content prior to disturbance.
147	Sample to determine ACM content prior to disturbance.
148	Sample to determine ACM content prior to disturbance.
149	Sample to determine ACM content prior to disturbance.
150	Sample to determine ACM content prior to disturbance.
151	Sample to determine ACM content prior to disturbance.
152	Sample to determine ACM content prior to disturbance.
153	Sample to determine ACM content prior to disturbance.
154	Sample to determine ACM content prior to disturbance.
155	Sample to determine ACM content prior to disturbance.
156	Sample to determine ACM content prior to disturbance.
157	Sample to determine ACM content prior to disturbance.
158	Sample to determine ACM content prior to disturbance.
159	Sample to determine ACM content prior to disturbance.
160	Sample to determine ACM content prior to disturbance.
161	Sample to determine ACM content prior to disturbance.
162	Sample to determine ACM content prior to disturbance.
163	Sample to determine ACM content prior to disturbance.

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
164	Sample to determine ACM content prior to disturbance.
74	
88	Sample to determine ACM content prior to disturbance.
89	Sample to determine ACM content prior to disturbance.
90	Sample to determine ACM content prior to disturbance.
91	Sample to determine ACM content prior to disturbance.
B	
C	
D	
E	
F	
G	
H	
I	
J	
K	
L	
L-1	
M	
N	
O	
P	
Q	
R	
S	
T	

Chicago Public Schools

School Air Force High School
(formerly Abbott School)

Unit 45231

Building ID 2010

Address 3630 S. Wells

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
U	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA RE/INSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)		INSPECTION DATE:	4/8/2025	
ADDRESS:	3630 S. Wells		IDPH LICENSE NO:	100-03175	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ Brown & White Streaks**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **006**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ Brown & White Streaks**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 007

MATERIAL DESCRIPTION: 12" x 12" Light Brown Floor Tile w/ Brown & White Streaks

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **007**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/ Brown & White Streaks**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 008

MATERIAL DESCRIPTION: 9" x 9" Dark Brown Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **008**

MATERIAL DESCRIPTION: **9" x 9" Dark Brown Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 009

MATERIAL DESCRIPTION: Mastic on 12" x 12" Dark Brown w/ Brown & White Streaks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **009**

MATERIAL DESCRIPTION: **Mastic on 12" x 12" Dark Brown w/ Brown & White Streaks Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 010

MATERIAL DESCRIPTION: Mastic on 12" x 12" Light Brown w/ Brown & White Streaks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **010**

MATERIAL DESCRIPTION: **Mastic on 12" x 12" Light Brown w/ Brown & White Streaks Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 011

MATERIAL DESCRIPTION: Partition Floor Joiner Compound

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1946/53 Connection by Room 104

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **011**

MATERIAL DESCRIPTION: **Partition Floor Joiner Compound**

MATERIAL LOCATION: **1946/53 Connection by Room 104**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 012

MATERIAL DESCRIPTION: 12" x 12" Light Brown w/ Brown & White Streaks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **012**

MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ Brown & White Streaks Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 013

MATERIAL DESCRIPTION: Mastic on 12" x 12" Light Brown w/ Brown & White Streaks Floor Tile (Duplicate Of HA 10)

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **013**

MATERIAL DESCRIPTION: **Mastic on 12" x 12" Light Brown w/ Brown & White Streaks Floor Tile (Duplicate Of HA 10)**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 014

MATERIAL DESCRIPTION: Carpet Adhesive

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **014**

MATERIAL DESCRIPTION: **Carpet Adhesive**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 015
MATERIAL DESCRIPTION: Black Vinyl Baseboard

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **015**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 016

MATERIAL DESCRIPTION: Black Vinyl Baseboard Adhesive

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **016**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 017

MATERIAL DESCRIPTION: Sink Bottom Caulking

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **017**

MATERIAL DESCRIPTION: **Sink Bottom Caulking**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	018		
MATERIAL DESCRIPTION:	Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	5		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 5. ACBM with potential for significant damage

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1946 Building, 1960 Building		
MATERIAL QUANTITY:	50000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damaged plaster ceiling in basement		

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **018**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **1946 Building, 1960 Building**

MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Sample to determine ACM content, remove or repair to intact.

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 019

MATERIAL DESCRIPTION: Interior Brick Walls

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1946 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **019**

MATERIAL DESCRIPTION: **Interior Brick Walls**

MATERIAL LOCATION: **1946 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 020

MATERIAL DESCRIPTION: Interior Brick Walls Mortar

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1946 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **020**

MATERIAL DESCRIPTION: **Interior Brick Walls Mortar**

MATERIAL LOCATION: **1946 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 021

MATERIAL DESCRIPTION: 12" x 12" Green Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **021**

MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 022

MATERIAL DESCRIPTION: Mastic on 12" x 12" Green Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **022**

MATERIAL DESCRIPTION: **Mastic on 12" x 12" Green Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 023

MATERIAL DESCRIPTION: Tar Paper and Mastic in Vault Closet Areas

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **023**

MATERIAL DESCRIPTION: **Tar Paper and Mastic in Vault Closet Areas**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 024

MATERIAL DESCRIPTION: Vibration Isolator

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1946 Building, Attic Above 200 and 201

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **024**

MATERIAL DESCRIPTION: **Vibration Isolator**

MATERIAL LOCATION: **1946 Building, Attic Above 200 and 201**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)		INSPECTION DATE:	4/8/2025	
ADDRESS:	3630 S. Wells		IDPH LICENSE NO:	100-03175	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **025**

MATERIAL DESCRIPTION: **Fan Unit Door Lining**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1946 Building, Attic Above 200 and 201**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **025**

MATERIAL DESCRIPTION: **Fan Unit Door Lining**

MATERIAL LOCATION: **1946 Building, Attic Above 200 and 201**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 026

MATERIAL DESCRIPTION: Dirt on Floor

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **026**

MATERIAL DESCRIPTION: **Dirt on Floor**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 027

MATERIAL DESCRIPTION: Mastic on 12" x 12" Beige w/ Brown & White Streaks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **027**

MATERIAL DESCRIPTION: **Mastic on 12" x 12" Beige w/ Brown & White Streaks Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 028

MATERIAL DESCRIPTION: Partition Wall Joiner Compound

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **028**

MATERIAL DESCRIPTION: **Partition Wall Joiner Compound**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 029

MATERIAL DESCRIPTION: 12" x 12" Dark Gray w/ White & Brown Streaks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **029**

MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/ White & Brown Streaks Floor Tile**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 030

MATERIAL DESCRIPTION: 12" x 12" Dark Gray Floor Tile w/ Beige Mix

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **030**

MATERIAL DESCRIPTION: **12" x 12" Dark Gray Floor Tile w/ Beige Mix**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 031

MATERIAL DESCRIPTION: Mastic on 12" x 12" Dark Gray w/ Beige Mix Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **031**

MATERIAL DESCRIPTION: **Mastic on 12" x 12" Dark Gray w/ Beige Mix Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 032
MATERIAL DESCRIPTION: 12" x 12" Light Beige Mix Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **032**

MATERIAL DESCRIPTION: **12" x 12" Light Beige Mix Floor Tile**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 033

MATERIAL DESCRIPTION: Mastic on 12" x 12" Light Beige Mix Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **033**

MATERIAL DESCRIPTION: **Mastic on 12" x 12" Light Beige Mix Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 034
MATERIAL DESCRIPTION: 12" x 12" Dark Pink Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **034**

MATERIAL DESCRIPTION: **12" x 12" Dark Pink Floor Tile**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 035

MATERIAL DESCRIPTION: Adhesive For 12" x 12" Dark Pink Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **035**

MATERIAL DESCRIPTION: **Adhesive For 12" x 12" Dark Pink Floor Tile**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 036

MATERIAL DESCRIPTION: 12" x 12" Dark Beige w/ Brown & White Streaks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **036**

MATERIAL DESCRIPTION: **12" x 12" Dark Beige w/ Brown & White Streaks Floor Tile**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 037

MATERIAL DESCRIPTION: Mastic on 12" x 12" Dark Beige w/ Brown & White Streaks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **037**

MATERIAL DESCRIPTION: **Mastic on 12" x 12" Dark Beige w/ Brown & White Streaks Floor Tile**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 038
MATERIAL DESCRIPTION: 12" x 12" Light Gray Mix Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **038**

MATERIAL DESCRIPTION: **12" x 12" Light Gray Mix Floor Tile**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 039

MATERIAL DESCRIPTION: Mastic on 12" x 12" Light Gray Mix Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **039**

MATERIAL DESCRIPTION: **Mastic on 12" x 12" Light Gray Mix Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 040
MATERIAL DESCRIPTION: Gray and Yellow Mix Linoleum

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **040**

MATERIAL DESCRIPTION: **Gray and Yellow Mix Linoleum**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:

041

MATERIAL DESCRIPTION:

Burlap w/ Adhesive Under Gray & Yellow Linoleum

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE:

No ACBM

FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

Material Not Present

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **041**

MATERIAL DESCRIPTION: **Burlap w/ Adhesive Under Gray & Yellow Linoleum**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 042
MATERIAL DESCRIPTION: 12" x 12" Blue Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Hallways

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **042**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**

MATERIAL LOCATION: **Hallways**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	043		
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallways		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **043**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**

MATERIAL LOCATION: **Hallways**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 044

MATERIAL DESCRIPTION: Mastic 12" x 12" Dark Gray w/ White & Brown Streaks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **044**

MATERIAL DESCRIPTION: **Mastic 12" x 12" Dark Gray w/ White & Brown Streaks Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 045

MATERIAL DESCRIPTION: Interior Brick

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1953 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **045**

MATERIAL DESCRIPTION: **Interior Brick**

MATERIAL LOCATION: **1953 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 046

MATERIAL DESCRIPTION: Interior Brick Mortar

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1953 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **046**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **1953 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 047

MATERIAL DESCRIPTION: Plaster

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1953 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **047**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **1953 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 048
MATERIAL DESCRIPTION: Light Gray Vinyl Baseboard

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **048**

MATERIAL DESCRIPTION: **Light Gray Vinyl Baseboard**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 049

MATERIAL DESCRIPTION: 9" x 9" Brown Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **049**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 050

MATERIAL DESCRIPTION: Mastic on 9" x 9" Brown Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **050**

MATERIAL DESCRIPTION: **Mastic on 9" x 9" Brown Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 051

MATERIAL DESCRIPTION: Desk Top Linoleum

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **051**

MATERIAL DESCRIPTION: **Desk Top Linoleum**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 052

MATERIAL DESCRIPTION: Desk Top Linoleum Adhesive

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **052**

MATERIAL DESCRIPTION: **Desk Top Linoleum Adhesive**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 053
MATERIAL DESCRIPTION: Black Vinyl Baseboard

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **053**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 054

MATERIAL DESCRIPTION: Black Vinyl Baseboard Adhesive

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **054**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 055

MATERIAL DESCRIPTION: 12" x 12" Dark Beige w/ Brown & White Streaks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **055**

MATERIAL DESCRIPTION: **12" x 12" Dark Beige w/ Brown & White Streaks Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 056
MATERIAL DESCRIPTION: 12" x 12" Blue Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Hallways

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **056**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**

MATERIAL LOCATION: **Hallways**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 057
MATERIAL DESCRIPTION: 12" x 12" Blue Floor Tile Adhesive

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Hallways

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **057**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Adhesive**

MATERIAL LOCATION: **Hallways**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 058

MATERIAL DESCRIPTION: Dark Gray Vinyl Baseboard

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **058**

MATERIAL DESCRIPTION: **Dark Gray Vinyl Baseboard**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 059

MATERIAL DESCRIPTION: Dark Gray Vinyl Baseboard Adhesive

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **059**

MATERIAL DESCRIPTION: **Dark Gray Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 060

MATERIAL DESCRIPTION: 12" x 12" Gray Mix Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **060**

MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 061

MATERIAL DESCRIPTION: Mastic on 12" x 12" Gray Mix Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **061**

MATERIAL DESCRIPTION: **Mastic on 12" x 12" Gray Mix Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **062**

MATERIAL DESCRIPTION: **Cork Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Fan Room by 214**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **062**

MATERIAL DESCRIPTION: **Cork Insulation**

MATERIAL LOCATION: **Fan Room by 214**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 063

MATERIAL DESCRIPTION: Vibration Isolator

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Fan Room by 214

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **063**

MATERIAL DESCRIPTION: **Vibration Isolator**

MATERIAL LOCATION: **Fan Room by 214**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 064

MATERIAL DESCRIPTION: 12" x 12" Beige Floor Tile w/ Brown & White Streaks

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **064**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ Brown & White Streaks**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 065

MATERIAL DESCRIPTION: Mastic on 12" x 12" Beige Floor Tile w/ Brown & White Streaks

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **065**

MATERIAL DESCRIPTION: **Mastic on 12" x 12" Beige Floor Tile w/ Brown & White Streaks**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 066
MATERIAL DESCRIPTION: 12" x 12" Light Brown Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **066**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 067

MATERIAL DESCRIPTION: 12" x 12" Light Brown Floor Tile Adhesive

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **067**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile Adhesive**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **068**
MATERIAL DESCRIPTION: **12" x 12" Dark Pink Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **068**

MATERIAL DESCRIPTION: **12" x 12" Dark Pink Floor Tile**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 069

MATERIAL DESCRIPTION: 12" x 12" Dark Pink Floor Tile Adhesive

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **069**

MATERIAL DESCRIPTION: **12" x 12" Dark Pink Floor Tile Adhesive**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 070

MATERIAL DESCRIPTION: Fan Unit Door Lining Insulation

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1946 Building, Basement

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **5/5/2025**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **070**

MATERIAL DESCRIPTION: **Fan Unit Door Lining Insulation**

MATERIAL LOCATION: **1946 Building, Basement**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 071

MATERIAL DESCRIPTION: 9" x 9" Gray Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **071**

MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 072

MATERIAL DESCRIPTION: Mastic on 12" x 12" Gray Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **072**

MATERIAL DESCRIPTION: **Mastic on 12" x 12" Gray Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 073

MATERIAL DESCRIPTION: Partition Wall Compound

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Between 1953/60 Buildings, 1st and 2nd Floor Corridors

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **073**

MATERIAL DESCRIPTION: **Partition Wall Compound**

MATERIAL LOCATION: **Between 1953/60 Buildings, 1st and 2nd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	074		
MATERIAL DESCRIPTION:	9" x 9" Light Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1960 Building, Store Room by Engineer's Office		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in Engineer's corridor		

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **074**

MATERIAL DESCRIPTION: **9" x 9" Light Brown Floor Tile**

MATERIAL LOCATION: **1960 Building, Store Room by Engineer's Office**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Remove and replace damaged material.

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	075		
MATERIAL DESCRIPTION:	9" x 9" Light Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1960 Building, Store Room by Engineer's Office		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **075**

MATERIAL DESCRIPTION: **9" x 9" Light Brown Floor Tile Mastic**

MATERIAL LOCATION: **1960 Building, Store Room by Engineer's Office**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 076

MATERIAL DESCRIPTION: Dark Gray Vinyl Baseboard

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **076**

MATERIAL DESCRIPTION: **Dark Gray Vinyl Baseboard**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 077

MATERIAL DESCRIPTION: Dark Gray Vinyl Baseboard Adhesive

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **077**

MATERIAL DESCRIPTION: **Dark Gray Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 078

MATERIAL DESCRIPTION: Pump Floor/Unit Caulk

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1960 Building, Boiler Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **078**

MATERIAL DESCRIPTION: **Pump Floor/Unit Caulk**

MATERIAL LOCATION: **1960 Building, Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	079		
MATERIAL DESCRIPTION:	Boiler Gasket Material		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler room		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **079**

MATERIAL DESCRIPTION: **Boiler Gasket Material**

MATERIAL LOCATION: **Boiler room**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**


DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 080

MATERIAL DESCRIPTION: Interior Brick

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1960 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **080**

MATERIAL DESCRIPTION: **Interior Brick**

MATERIAL LOCATION: **1960 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 081

MATERIAL DESCRIPTION: Interior Brick Mortar

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1960 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **081**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **1960 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	082		
MATERIAL DESCRIPTION:	12" x 12" Sandy Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1960 Building, Engineer's Office		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **082**

MATERIAL DESCRIPTION: **12" x 12" Sandy Beige Floor Tile**

MATERIAL LOCATION: **1960 Building, Engineer's Office**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	083		
MATERIAL DESCRIPTION:	12" x 12" Sandy Beige Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1960 Building, Engineer's Office		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **083**

MATERIAL DESCRIPTION: **12" x 12" Sandy Beige Floor Tile Mastic**

MATERIAL LOCATION: **1960 Building, Engineer's Office**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	084		
MATERIAL DESCRIPTION:	9" x 9" Orange Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1960 Building, Engineer's Office Corridor		
MATERIAL QUANTITY:	108	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in Engineer's corridor		

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **084**

MATERIAL DESCRIPTION: **9" x 9" Orange Floor Tile**

MATERIAL LOCATION: **1960 Building, Engineer's Office Corridor**

MATERIAL QUANTITY: **108** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Remove and replace damaged material.

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	085		
MATERIAL DESCRIPTION:	9" x 9" Orange Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1960 Building, Engineer's Office Corridor		
MATERIAL QUANTITY:	108	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **085**

MATERIAL DESCRIPTION: **9" x 9" Orange Floor Tile Mastic**

MATERIAL LOCATION: **1960 Building, Engineer's Office Corridor**

MATERIAL QUANTITY: **108** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	086		
MATERIAL DESCRIPTION:	12" x 12" Off-White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1960 Building, Store Room Bathroom Across From Engineer's Office		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **086**

MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile**

MATERIAL LOCATION: **1960 Building, Store Room Bathroom Across From Engineer's Office**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	087		
MATERIAL DESCRIPTION:	12" x 12" Off-White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1960 Building, Store Room Bathroom Across From Engineer's Office		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **087**

MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile Mastic**

MATERIAL LOCATION: **1960 Building, Store Room Bathroom Across From Engineer's Office**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 088
MATERIAL DESCRIPTION: 12" x 12" Light Gray Mix Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **088**

MATERIAL DESCRIPTION: **12" x 12" Light Gray Mix Floor Tile**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 089

MATERIAL DESCRIPTION: 12" x 12" Light Gray Mix Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **089**

MATERIAL DESCRIPTION: **12" x 12" Light Gray Mix Floor Tile Mastic**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 090

MATERIAL DESCRIPTION: Radiator Grill Lining Material

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1960 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **090**

MATERIAL DESCRIPTION: **Radiator Grill Lining Material**

MATERIAL LOCATION: **1960 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 091

MATERIAL DESCRIPTION: Incinerator Gasket Material By Fire Hole

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **091**

MATERIAL DESCRIPTION: **Incinerator Gasket Material By Fire Hole**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 092

MATERIAL DESCRIPTION: Incinerator Interior Brick

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **092**

MATERIAL DESCRIPTION: **Incinerator Interior Brick**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 093

MATERIAL DESCRIPTION: Incinerator Ash Chamber Brick

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **093**

MATERIAL DESCRIPTION: **Incinerator Ash Chamber Brick**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 094

MATERIAL DESCRIPTION: Vibration Isolator

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1946 Building, Fan Unit

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **094**

MATERIAL DESCRIPTION: **Vibration Isolator**

MATERIAL LOCATION: **1946 Building, Fan Unit**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 095

MATERIAL DESCRIPTION: White Chalky Material and Soil Mix

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1953 Building, Unfinished Pipe Space

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **095**

MATERIAL DESCRIPTION: **White Chalky Material and Soil Mix**

MATERIAL LOCATION: **1953 Building, Unfinished Pipe Space**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 096
MATERIAL DESCRIPTION: Vault Door Insulation
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **096**

MATERIAL DESCRIPTION: **Vault Door Insulation**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 097

MATERIAL DESCRIPTION: Light Gray Vinyl Baseboard

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **097**

MATERIAL DESCRIPTION: **Light Gray Vinyl Baseboard**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 098

MATERIAL DESCRIPTION: Light Gray Vinyl Baseboard Adhesive

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **098**

MATERIAL DESCRIPTION: **Light Gray Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 099

MATERIAL DESCRIPTION: Beaver Board

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **099**

MATERIAL DESCRIPTION: **Beaver Board**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 100

MATERIAL DESCRIPTION: Exterior Brick

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1946 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **100**

MATERIAL DESCRIPTION: **Exterior Brick**

MATERIAL LOCATION: **1946 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 101

MATERIAL DESCRIPTION: Exterior Brick Mortar

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1946 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **101**

MATERIAL DESCRIPTION: **Exterior Brick Mortar**

MATERIAL LOCATION: **1946 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 102

MATERIAL DESCRIPTION: Exterior Brick

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1953 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **102**

MATERIAL DESCRIPTION: **Exterior Brick**

MATERIAL LOCATION: **1953 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 103

MATERIAL DESCRIPTION: Exterior Brick Mortar

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1953 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **5/5/2025**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **103**

MATERIAL DESCRIPTION: **Exterior Brick Mortar**

MATERIAL LOCATION: **1953 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 104

MATERIAL DESCRIPTION: Exterior Brick

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1960 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **104**

MATERIAL DESCRIPTION: **Exterior Brick**

MATERIAL LOCATION: **1960 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 105

MATERIAL DESCRIPTION: Exterior Brick Mortar

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1960 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **105**

MATERIAL DESCRIPTION: **Exterior Brick Mortar**

MATERIAL LOCATION: **1960 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 106

MATERIAL DESCRIPTION: Exterior Door Caulk - Non-AHERA

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1960 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **106**

MATERIAL DESCRIPTION: **Exterior Door Caulk - Non-AHERA**

MATERIAL LOCATION: **1960 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 107

MATERIAL DESCRIPTION: Roofing Materials - Non-AHERA

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1946 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **107**

MATERIAL DESCRIPTION: **Roofing Materials - Non-AHERA**

MATERIAL LOCATION: **1946 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Non-AHERA

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 108

MATERIAL DESCRIPTION: Roofing Materials - Non-AHERA

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1953 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **108**

MATERIAL DESCRIPTION: **Roofing Materials - Non-AHERA**

MATERIAL LOCATION: **1953 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Non-AHERA

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 109

MATERIAL DESCRIPTION: Roofing Materials - Non-AHERA

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1960 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **109**

MATERIAL DESCRIPTION: **Roofing Materials - Non-AHERA**

MATERIAL LOCATION: **1960 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Non-AHERA

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 110

MATERIAL DESCRIPTION: Interior Window Caulk

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **110**

MATERIAL DESCRIPTION: **Interior Window Caulk**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 111

MATERIAL DESCRIPTION: 12" x 12" Light Beige w/ Brown & White Streaks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **111**

MATERIAL DESCRIPTION: **12" x 12" Light Beige w/ Brown & White Streaks Floor Tile**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 112

MATERIAL DESCRIPTION: 12" x 12" White w/ Off-White & Beige Streaks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **112**

MATERIAL DESCRIPTION: **12" x 12" White w/ Off-White & Beige Streaks Floor Tile**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	113	
MATERIAL DESCRIPTION:	HA 111 & HA 112 Checkerboard Floor Tile Pattern Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **113**

MATERIAL DESCRIPTION: **HA 111 & HA 112 Checkerboard Floor Tile Pattern Mastic**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 114

MATERIAL DESCRIPTION: 12" x 12" Red Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **114**

MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 115

MATERIAL DESCRIPTION: 12" x 12" Red Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **115**

MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile Mastic**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	116		
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallways		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **116**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**

MATERIAL LOCATION: **Hallways**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 117

MATERIAL DESCRIPTION: 12" x 12" Blue Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **117**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 118

MATERIAL DESCRIPTION: Green Carpet Adhesive

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **118**

MATERIAL DESCRIPTION: **Green Carpet Adhesive**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	119		
MATERIAL DESCRIPTION:	Acoustical Ceiling		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Hallways of the 1960 Building		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **119**

MATERIAL DESCRIPTION: **Acoustical Ceiling**

MATERIAL LOCATION: **Throughout Hallways of the 1960 Building**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 120
MATERIAL DESCRIPTION: 12" x 12" Beige Mix Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **120**

MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 121

MATERIAL DESCRIPTION: 12" x 12" Beige Mix Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **121**

MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile Mastic**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 122

MATERIAL DESCRIPTION: Red Carpet Adhesive

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **122**

MATERIAL DESCRIPTION: **Red Carpet Adhesive**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	123		
MATERIAL DESCRIPTION:	Black Board/ Marker Board Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **123**

MATERIAL DESCRIPTION: **Black Board/ Marker Board Adhesive**

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	124		
MATERIAL DESCRIPTION:	Gray and Black Mix Terrazzo Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	East Entrances and Stairwells		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **124**

MATERIAL DESCRIPTION: **Gray and Black Mix Terrazzo Flooring**

MATERIAL LOCATION: **East Entrances and Stairwells**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 125

MATERIAL DESCRIPTION: 12" x 12" Tan w/ Brown and White Streaks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **125**

MATERIAL DESCRIPTION: **12" x 12" Tan w/ Brown and White Streaks Floor Tile**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 126

MATERIAL DESCRIPTION: 12" x 12" Tan w/ Brown and White Streaks Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **126**

MATERIAL DESCRIPTION: **12" x 12" Tan w/ Brown and White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 127

MATERIAL DESCRIPTION: Cork Board Adhesive

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **127**

MATERIAL DESCRIPTION: **Cork Board Adhesive**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 128

MATERIAL DESCRIPTION: Green Carpet Adhesive

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **128**

MATERIAL DESCRIPTION: **Green Carpet Adhesive**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 129
MATERIAL DESCRIPTION: 12" x 12" White Mottled Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Corridors, Classrooms, and Offices

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **129**

MATERIAL DESCRIPTION: **12" x 12" White Mottled Floor Tile**

MATERIAL LOCATION: **Throughout Corridors, Classrooms, and Offices**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 130

MATERIAL DESCRIPTION: 12" x 12" White Mottled Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Corridors, Classrooms, and Offices

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **130**

MATERIAL DESCRIPTION: **12" x 12" White Mottled Floor Tile Mastic**

MATERIAL LOCATION: **Throughout Corridors, Classrooms, and Offices**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 131
MATERIAL DESCRIPTION: 12" x 12" Blue Mottled Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **131**

MATERIAL DESCRIPTION: **12" x 12" Blue Mottled Floor Tile**

MATERIAL LOCATION: **Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 132

MATERIAL DESCRIPTION: 12" x 12" Blue Mottled Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **132**

MATERIAL DESCRIPTION: **12" x 12" Blue Mottled Floor Tile Mastic**

MATERIAL LOCATION: **Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 133
MATERIAL DESCRIPTION: 2' x 2' Lay-in Ceiling Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: First Floor Corridor, Room 216

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **133**

MATERIAL DESCRIPTION: **2' x 2' Lay-in Ceiling Tile**

MATERIAL LOCATION: **First Floor Corridor, Room 216**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 134
MATERIAL DESCRIPTION: 2' x 4' Lay-in Ceiling Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 112a, 126, and 226

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **134**

MATERIAL DESCRIPTION: **2' x 4' Lay-in Ceiling Tile**

MATERIAL LOCATION: **Rooms 112a, 126, and 226**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 135

MATERIAL DESCRIPTION: 4" Gray Baseboard

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 115, 117, 133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226, 228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage, Lunchroom, and 2nd Floor Store Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **135**

MATERIAL DESCRIPTION: **4" Gray Baseboard**

MATERIAL LOCATION: **Rooms 115, 117, 133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226, 228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage, Lunchroom, and 2nd Floor Store Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 136
MATERIAL DESCRIPTION: 4" Gray Baseboard Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 115, 117, 133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226, 228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage, Lunchroom, and 2nd Floor Store Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**
SCHOOL NAME: **Air Force High School
(formerly Abbott
School)** REVIEW DATE: **5/5/2025**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **136**

MATERIAL DESCRIPTION: **4" Gray Baseboard Mastic**

MATERIAL LOCATION: **Rooms 115, 117, 133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226, 228, 230, 234,
232, Main Office, Stage Vestibule, Gym Storage, Lunchroom, and 2nd Floor Store Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 137

MATERIAL DESCRIPTION: Gray Sink Undercoating

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 128, 130, and 133

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **137**

MATERIAL DESCRIPTION: **Gray Sink Undercoating**

MATERIAL LOCATION: **Rooms 128, 130, and 133**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 138

MATERIAL DESCRIPTION: Carpet Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 134 and 212

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **138**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Rooms 134 and 212**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	139		
MATERIAL DESCRIPTION:	Transite Laboratory Countertop		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 109 and 226		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **139**

MATERIAL DESCRIPTION: **Transite Laboratory Countertop**

MATERIAL LOCATION: **Rooms 109 and 226**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 140
MATERIAL DESCRIPTION: Wood Pattern Sheet Flooring

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Gym

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **140**

MATERIAL DESCRIPTION: **Wood Pattern Sheet Flooring**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 141

MATERIAL DESCRIPTION: Wood Pattern Sheet Flooring Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Gym

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **141**

MATERIAL DESCRIPTION: **Wood Pattern Sheet Flooring Mastic**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 142

MATERIAL DESCRIPTION: Blue Sheet Flooring

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 126

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **142**

MATERIAL DESCRIPTION: **Blue Sheet Flooring**

MATERIAL LOCATION: **Room 126**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 143

MATERIAL DESCRIPTION: Blue Sheet Flooring Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 126

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **143**

MATERIAL DESCRIPTION: **Blue Sheet Flooring Mastic**

MATERIAL LOCATION: **Room 126**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	144		
MATERIAL DESCRIPTION:	Transite Electrical Panel		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement Electrical Vault		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **144**

MATERIAL DESCRIPTION: **Transite Electrical Panel**

MATERIAL LOCATION: **Basement Electrical Vault**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	145		
MATERIAL DESCRIPTION:	Electrical Wiring Associated w/ Wall Mounted Clocks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Building		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **145**

MATERIAL DESCRIPTION: **Electrical Wiring Associated w/ Wall Mounted Clocks**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	146		
MATERIAL DESCRIPTION:	12" x 12" Light Beige w/ White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 106, 104, 101, Corridor, 103, 109, 110, 112, 113, 115, 116, 117, 128, 127, 132, 233, 232, 231, 230, 229, 228, 227, 225, 226, 217, 215, 211, 209, 210, 206, 205, 204, 203, 202, 201**

MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **146**

MATERIAL DESCRIPTION: **12" x 12" Light Beige w/ White Streaks Floor Tile**

MATERIAL LOCATION: **Rooms 106, 104, 101, Corridor, 103, 109, 110, 112, 113, 115, 116, 117, 128, 127, 132, 233, 232, 231, 230, 229, 228, 227, 225, 226, 217, 215, 211, 209, 210, 206, 205, 204, 203, 202, 201**

MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	147		
MATERIAL DESCRIPTION:	12" x 12" Light Beige w/ White Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 106, 104, 101, Corridor, 103, 109, 110, 112, 113, 115, 116, 117, 128, 127, 132, 233, 232, 231, 230, 229, 228, 227, 225, 226, 217, 215, 211, 209, 210, 206, 205, 204, 203, 202, 201**

MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA:	147				
MATERIAL DESCRIPTION:	12" x 12" Light Beige w/ White Streaks Floor Tile Mastic				
MATERIAL LOCATION:	Rooms 106, 104, 101, Corridor, 103, 109, 110, 112, 113, 115, 116, 117, 128, 127, 132, 233, 232, 231, 230, 229, 228, 227, 225, 226, 217, 215, 211, 209, 210, 206, 205, 204, 203, 202, 201				
MATERIAL QUANTITY:	25000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:		DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	148		
MATERIAL DESCRIPTION:	Black Science Lab Counter Tables		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Rooms 109, 226, 216

MATERIAL QUANTITY: 46 MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **148**

MATERIAL DESCRIPTION: **Black Science Lab Counter Tables**

MATERIAL LOCATION: **Rooms 109, 226, 216**

MATERIAL QUANTITY: **46**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	149		
MATERIAL DESCRIPTION:	Black Science Lab Counter		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 109, 226, 216		
MATERIAL QUANTITY:	90	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **149**

MATERIAL DESCRIPTION: **Black Science Lab Counter**

MATERIAL LOCATION: **Rooms 109, 226, 216**

MATERIAL QUANTITY: **90** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	150		
MATERIAL DESCRIPTION:	12" x 12" Gray w/ Black Spots Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 133, 134		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **150**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Black Spots Floor Tile**

MATERIAL LOCATION: **Rooms 133, 134**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	151		
MATERIAL DESCRIPTION:	12" x 12" Gray w/ Black Spots Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 133, 134		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **151**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Black Spots Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 133, 134**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	152		
MATERIAL DESCRIPTION:	2" x 2" Blue, Gray, and Light Gray Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 216		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **152**

MATERIAL DESCRIPTION: **2" x 2" Blue, Gray, and Light Gray Vinyl Floor Tile**

MATERIAL LOCATION: **Room 216**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	153		
MATERIAL DESCRIPTION:	Blue Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 212		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **153**

MATERIAL DESCRIPTION: **Blue Carpet Mastic**

MATERIAL LOCATION: **Room 212**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	74		
MATERIAL DESCRIPTION:	9" x 9" Light Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Remove		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1960 Building, Store Room by Engineer's Office		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **9" x 9" Light Brown Floor Tile Mastic**

MATERIAL LOCATION: **1960 Building, Store Room by Engineer's Office**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	88		
MATERIAL DESCRIPTION:	9" x 9" Cream Floor Tile w/ White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **9" x 9" Cream Floor Tile w/ White Streaks**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	89		
MATERIAL DESCRIPTION:	9" x 9" Cream Floor Tile w/ White Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **89**

MATERIAL DESCRIPTION: **9" x 9" Cream Floor Tile w/ White Streaks Mastic**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	90		
MATERIAL DESCRIPTION:	9" x 9" Light Brown Mottled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office		
MATERIAL QUANTITY:	5	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **9" x 9" Light Brown Mottled Floor Tile**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	91		
MATERIAL DESCRIPTION:	9" x 9" Light Brown Mottled Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office		
MATERIAL QUANTITY:	5	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **91**

MATERIAL DESCRIPTION: **9" x 9" Light Brown Mottled Floor Tile Mastic**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Distributed Pipe Insulation on Floor**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Distributed Pipe Insulation on Floor**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: C

MATERIAL DESCRIPTION: Aircel Pipe Insulation

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Aircel Pipe Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:

D

MATERIAL DESCRIPTION:

Joint Compound Off Fiberglass Pipe Insulation

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

Follow O&M Plan

ASBESTOS TYPE:

Abated

FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

ABATED

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Joint Compound Off Fiberglass Pipe Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Joint Compound Off Fiberglass Pipe Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Joint Compound Off Fiberglass Pipe Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: F

MATERIAL DESCRIPTION: Distributed Pipe Insulation in Dirt on Floor

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Distributed Pipe Insulation in Dirt on Floor**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Distributed Pipe Insulation in Dirt on Floor**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Distributed Pipe Insulation in Dirt on Floor**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: H

MATERIAL DESCRIPTION: Aircell Pipe Insulation

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: I

MATERIAL DESCRIPTION: Aircell Pipe Insulation

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: J

MATERIAL DESCRIPTION: Paperwrap Pipe Insulation

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1946 Building, Pipe Chases

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**

MATERIAL LOCATION: **1946 Building, Pipe Chases**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	K		
MATERIAL DESCRIPTION:	Hard Joint Compound Off Paperwrap Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1946 Building, Walls and Pipe Chases**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Hard Joint Compound Off Paperwrap Pipe Insulation**

MATERIAL LOCATION: **1946 Building, Walls and Pipe Chases**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: L

MATERIAL DESCRIPTION: Hard Joint Compound Off Aircell Pipe Insulation

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Hard Joint Compound Off Aircell Pipe Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: L-1

MATERIAL DESCRIPTION: Hard Joint Compound Off Aircell Pipe Insulation

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **L-1**

MATERIAL DESCRIPTION: **Hard Joint Compound Off Aircell Pipe Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: M

MATERIAL DESCRIPTION: Hard Joint Compound Off Aircell Pipe Insulation

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Hard Joint Compound Off Aircell Pipe Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: N

MATERIAL DESCRIPTION: Hard Joint Compound Off Aircell Pipe Insulation

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Hard Joint Compound Off Aircell Pipe Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 0

MATERIAL DESCRIPTION: Duct Interior Insulation

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1960 Building, Boiler Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **O**

MATERIAL DESCRIPTION: **Duct Interior Insulation**

MATERIAL LOCATION: **1960 Building, Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: P

MATERIAL DESCRIPTION: Magblock Pipe Insulation

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **Magblock Pipe Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Q

MATERIAL DESCRIPTION: Magblock Pipe Insulation Joint Compound

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **Q**

MATERIAL DESCRIPTION: **Magblock Pipe Insulation Joint Compound**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: R

MATERIAL DESCRIPTION: Water Tank Insulation

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **R**

MATERIAL DESCRIPTION: **Water Tank Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S**

MATERIAL DESCRIPTION: **Aircell Duct Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **S**

MATERIAL DESCRIPTION: **Aircell Duct Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	T		
MATERIAL DESCRIPTION:	Magblock Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1946 Building, Coal/Ash Room Abandoned Mech. Unit		
MATERIAL QUANTITY:	15	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	DAMAGE UNITS: LF		
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **T**

MATERIAL DESCRIPTION: **Magblock Insulation**

MATERIAL LOCATION: **1946 Building, Coal/Ash Room Abandoned Mech. Unit**

MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**


DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **U**

MATERIAL DESCRIPTION: **Duct Insulation - Black Tar Like Adhesive**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUILDING ID:	2010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	REVIEW DATE:	5/5/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **U**

MATERIAL DESCRIPTION: **Duct Insulation - Black Tar Like Adhesive**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/05/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUILDING ID: **2010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Air Force High School
(formerly Abbott School)** INSPECTION DATE: **4/8/2025**
ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-03175**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **158**
MATERIAL DESCRIPTION: **5" x 5" Quarry Ceramic Floor Tile Grout**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: 

Date: **04/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Air Force High School
(formerly Abbott School)** REVIEW DATE: **5/5/2025**

ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **158**

MATERIAL DESCRIPTION: **5" x 5" Quarry Ceramic Floor Tile Grout**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA RE/INSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	164		
MATERIAL DESCRIPTION:	2" x 2" Off White Floor Tile Mastic		
MATERIAL LOCATION:	Classroom 216		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Air Force High School
(formerly Abbott School)** REVIEW DATE: **5/5/2025**

ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **164**

MATERIAL DESCRIPTION: **2" x 2" Off White Floor Tile Mastic**

MATERIAL LOCATION: **Classroom 216**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	154		
MATERIAL DESCRIPTION:	Tan CMU		
MATERIAL LOCATION:	Girls and Boys Toilet Rooms		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Air Force High School
(formerly Abbott School)** REVIEW DATE: **5/5/2025**

ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **154**

MATERIAL DESCRIPTION: **Tan CMU**

MATERIAL LOCATION: **Girls and Boys Toilet Rooms**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	155		
MATERIAL DESCRIPTION:	1" x 1" Gray Ceramic Floor Tile & Grout		
MATERIAL LOCATION:	Toilet Rooms, Locker Rooms		
MATERIAL QUANTITY:	15000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Air Force High School
(formerly Abbott School)** REVIEW DATE: **5/5/2025**

ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **155**

MATERIAL DESCRIPTION: **1" x 1" Gray Ceramic Floor Tile & Grout**

MATERIAL LOCATION: **Toilet Rooms, Locker Rooms**

MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	160		
MATERIAL DESCRIPTION:	2" x 2" Dark Gray Floor Tile Mastic		
MATERIAL LOCATION:	Classroom 216		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Air Force High School
(formerly Abbott School)** REVIEW DATE: **5/5/2025**

ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **160**

MATERIAL DESCRIPTION: **2" x 2" Dark Gray Floor Tile Mastic**

MATERIAL LOCATION: **Classroom 216**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	156		
MATERIAL DESCRIPTION:	5" x 5" Gray Ceramic Wall Tile & Grout		
MATERIAL LOCATION:	Men's and Women's Locker Room		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Air Force High School
(formerly Abbott School)** REVIEW DATE: **5/5/2025**

ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **156**

MATERIAL DESCRIPTION: **5" x 5" Gray Ceramic Wall Tile & Grout**

MATERIAL LOCATION: **Men's and Women's Locker Room**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	161			
MATERIAL DESCRIPTION:	2" x 2" Blue Floor Tile			
MATERIAL LOCATION:	Classroom 216			
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Air Force High School
(formerly Abbott School)** REVIEW DATE: **5/5/2025**

ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **161**

MATERIAL DESCRIPTION: **2" x 2" Blue Floor Tile**

MATERIAL LOCATION: **Classroom 216**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	162		
MATERIAL DESCRIPTION:	2" x 2" Blue Floor Tile Mastic		
MATERIAL LOCATION:	Classroom 216		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Air Force High School
(formerly Abbott School)** REVIEW DATE: **5/5/2025**

ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **162**

MATERIAL DESCRIPTION: **2" x 2" Blue Floor Tile Mastic**

MATERIAL LOCATION: **Classroom 216**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	157		
MATERIAL DESCRIPTION:	5" x 5" Blue Ceramic Wall Tile & Grout		
MATERIAL LOCATION:	Men's and Women's Locker Rooms		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Air Force High School
(formerly Abbott School)** REVIEW DATE: **5/5/2025**

ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **157**

MATERIAL DESCRIPTION: **5" x 5" Blue Ceramic Wall Tile & Grout**

MATERIAL LOCATION: **Men's and Women's Locker Rooms**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	159		
MATERIAL DESCRIPTION:	2" x 2" Dark Gray Floor Tile		
MATERIAL LOCATION:	Classroom 216		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Air Force High School
(formerly Abbott School)** REVIEW DATE: **5/5/2025**

ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **159**

MATERIAL DESCRIPTION: **2" x 2" Dark Gray Floor Tile**

MATERIAL LOCATION: **Classroom 216**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	45231	BUIDLING ID:	2010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Air Force High School (formerly Abbott School)	INSPECTION DATE:	4/8/2025		
ADDRESS:	3630 S. Wells	IDPH LICENSE NO:	100-03175		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	163		
MATERIAL DESCRIPTION:	2" x 2" Off White Floor Tile		
MATERIAL LOCATION:	Classroom 216		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **45231** BUIDLING ID: **2010**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Air Force High School
(formerly Abbott School)** REVIEW DATE: **5/5/2025**

ADDRESS: **3630 S. Wells** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **163**

MATERIAL DESCRIPTION: **2" x 2" Off White Floor Tile**

MATERIAL LOCATION: **Classroom 216**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/05/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses



OCCUPATIONAL TRAINING & SUPPLY, INC.
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2024

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Marcos Iwankiw

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. This course is accredited by the State of Wisconsin, Department of Health Services under ch. DHS 159, Wis. Admin. Code, The Illinois Department of Public Health and The Indiana Department of Environmental Management, under 326 IAC 18. Training was in accordance with requirements listed under EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Location: 12304 75th Street
Kenosha, WI 53142

Certificate Number: BIRWI2410112747
Course Date: 10/11/2024
Exam Date: 10/11/2024
Expiration Date: 10/11/2025




Issue Date: 10/11/2024


Tyler Nicholson, Authorized Signer

Course Credit Hours: BIR WI 4 Hours

Marcos Iwankiw

Illinois Licensed Building Inspector, Air Sampling Professional, Asbestos Project Manager



ENDORSEMENTS **TC EXPIRES**

INSPECTOR 10/11/2025

PROJECT MANAGER 1/2/2026
AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC. **2024**
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Michael Serio

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/18/2024

Exam Date: 11/18/2024

Expiration Date: 11/18/2025

Certificate Number: MPR2411183328

Course Credit Hours: MPR 4 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

Kristina Miczek, Training Manager

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed