

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-0031  
SCHOOL NAME: Morgan Park High School  
ADDRESS OF SCHOOL: 1744 W. Pryor Ave.  
CITY: Chicago, IL, 60643

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 8/18/2022

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II (Please type or print)**

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 4/22/2025 ENROLLMENT 1187  
IDPH INSPECTOR LICENSE NUMBER: 100-21040  
IDPH LICENSED INSPECTOR NAME (Please Print): Josh Herman  
IDPH MP LICENSE NUMBER: 100-00349  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): James Tuinenga

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

*Richard J. Schleyer* 5/16/2025

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Morgan Park High School**

1744 W. Pryor Ave.  
Chicago, IL, 60643

Unit: 46251  
Building ID: 1490

IDPH ID Number: 14-016-2990-0031

**REPORT DATE:**  
Friday, May 16, 2025

**Prepared for:**  
**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**  
**TEM Environmental, Inc.**

174 N. Brandon Drive  
Glendale Heights, IL, 60139  
Phone 630-790-0880  
Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

05/15/2025

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299      Unit: 46251      Region: 06      IDPH ID: 14-016-2990-0031

School: Morgan Park High School      Building ID: 1490

Address: 1744 W. Pryor Ave.

Chicago, IL, 60643

Building Contact: Blake, Gerald      Contact Phone: 7083071890

Current Building Owners: Chicago Public Schools

Reinspection Date: 4/22/2025

Review Date: 05/15/2025

Inspector: Josh Herman

Inspector IDPH License: 100-21040

Management Planner: James Tuinenga

Management Planner IDPH License: 100-00349

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.



James Tuinenga  
100-00349

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: May 16, 2025

RE: Morgan Park High School, Unit 46251  
1744 W. Pryor Ave.  
Chicago, IL, 60643

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Morgan Park High School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Morgan Park High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Morgan Park High School      Unit: 46251      Region: 06  
Address: 1744 W. Pryor Ave.      Chicago, IL, 60643  
IDPH ID: 14-016-2990-0031      Building ID: 1490  
Contact: Blake, Gerald      Phone: 7083071890

### 2. Description of Facility

Original Construction: 1914      Additional Construction: 1964  
Total Square Footage: 167503      No of Floors: 3  
Current Occupancy: 1187

### 3. LEA Designated Person

Contact: Richard J.Schleyer      Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Phone: 630-790-0880      Fax: 630-790-0882

### 5. Inspector

Inspector Name: Josh Herman

Inspector IDPH license # 100-21040  
Reinspection Date: 4/22/2025

  
Signature:  
Date: 4/22/2025

### 6. Management Planner

Management Planner Name: James Tuinenga

Management Planner IDPH license # 100-00349


  
Signature:  
Date: 05/15/2025

### 7. Review Date: 05/15/2025

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 5/16/2025

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Morgan Park High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1490:

119	24"x24" Grey, Light Grey & Green Floor Tile
119A	24"x24" Grey, Light Grey & Green Floor Tile Mastic
120	24"x24" Grey, Light Grey & Orange Floor Tile
120A	24"x24" Grey, Light Grey & Orange Floor Tile Mastic
121	24"x24" Grey, Light Grey & Yellow Floor Tile
121A	24"x24" Grey, Light Grey & Yellow Floor Tile Mastic
28	12"x12" Red Floor Tile
28M	Mastic associated w/12"x12" Red Floor Tile

29	Lab Counter Tops
30	Blue Mosaic Cermaic Tile
31	1"x1" Brown Mosaic Cermaic Tile
32	Drywall
32A	Drywall Joint Compound
33	Mud Fittings
34	Red Terracotta Floor Tile
34M	Adhesive associated w/Red Terracotta Floor Tile
35	Brown Terracotta Floor Tile
D	Lab Tabletops ABATED
NEW	Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 1490:

28	12"x12" Red Floor Tile
28M	Mastic associated w/12"x12" Red Floor Tile
29	Lab Counter Tops
30	Blue Mosaic Cermaic Tile
31	1"x1" Brown Mosaic Cermaic Tile
32	Drywall
32A	Drywall Joint Compound
33	Mud Fittings
34	Red Terracotta Floor Tile
34M	Adhesive associated w/Red Terracotta Floor Tile
35	Brown Terracotta Floor Tile

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

05B	9"x9" Tan Floor Tile
05CC	9"X9" Tan Floor Tile
06B	12"x12" Brown Floor Tile
06C	12"x12" Gray w/Specks Floor Tile NOT OBSERVED
09CC	9x9 Tan Floor Tile Mastic
105	2'x2' Pin Hole Ceiling Tile
106	12"x12" Yellow Speckled Vinyl Floor Tile
107	12"x12" Yellow Speckled Vinyl Floor Tile Mastic
108	12"x12" Gray Speckled Vinyl Floor Tile
109	12"x12" Gray Speckled Vinyl Floor Tile Mastic
10A	12"x12" Tan Floor Tile Mastic
110	Yellow Linoleum NOT OBSERVED
111	12"x12" Gray w/Dark Gray Streaks Vinyl Floor Tile
112	12"x12" Gray w/Dark Gray Streaks Vinyl Floor Tile Mastic
113	14x14 White Speckled Vinyl Floor Tile
114	14x14 White Speckled Vinyl Floor Tile Mastic
115	14x14 Light Blue Speckled Vinyl Floor Tile
116	14x14 Light Blue Speckled Vinyl Floor Tile Mastic
117	14x14 Green Speckled Vinyl Floor Tile
118	14x14 Green Speckled Vinyl Floor Tile Mastic
119	24"x24" Grey, Light Grey & Green Floor Tile
119A	24"x24" Grey, Light Grey & Green Floor Tile Mastic
120	24"x24" Grey, Light Grey & Orange Floor Tile
120A	24"x24" Grey, Light Grey & Orange Floor Tile Mastic
121	24"x24" Grey, Light Grey & Yellow Floor Tile
121A	24"x24" Grey, Light Grey & Yellow Floor Tile Mastic
13A	Brown Baseboard
13B	Black Baseboard
14A	Brown Baseboard Mastic
14B	Black Baseboard Mastic
17C	12"x12" Gray w/Specks Floor Tile NOT OBSERVED
18	12"x12" Tan w/Beige Floor Tile NOT OBSERVED
19	12"x12" Tan w/Beige Floor Tile Mastic NOT OBSERVED
22	Spray-On Insulation
23	Terrazzo

25	Plaster
26	12x12 Tan Marbled Vinyl Floor Tile
26A	12x12 Tan Marbled Vinyl Floor Tile Mastic
27	12x12 Beige Marbled Floor Tile
27A	12x12 Beige Marbled Vinyl Floor Tile Mastic
28	12"x12" Red Floor Tile
28M	Mastic associated w/12"x12" Red Floor Tile
29	Lab Counter Tops
30	Blue Mosaic Cermaic Tile
31	1"x1" Brown Mosaic Cermaic Tile
32	Drywall
32A	Drywall Joint Compound
33	Mud Fittings
34	Red Terracotta Floor Tile
34M	Adhesive associated w/Red Terracotta Floor Tile
35	Brown Terracotta Floor Tile
A	2'x2' Lay-In Ceiling Panels
B	12"x12" Greenish Floor Tile
C	Aircell Pipe Insulation
CM-1	Rust Carpet Mastic
CM-2	Green Carpet Mastic
CM-3	Multicolor Carpet
CM-5	Rust Colored Carpet Mastic
E	Fitting Insulation on Fiberglass Insulated Piping
F	Fitting Insulation on Fiberglass Insulated Piping
G	Vibration Dampener
HA-100	Lining for Room Heating Units
HA-101	Interior Window Caulk
HA-102	Interior Window Glaze
HA-103	1'x1' Grooved Ceiling Tile Glue
HA-104	Black Sink Undercoating
NEW	Newly Installed Suspect ACM

The following areas were deemed to be inaccessible:

09A	9x9 Gray Floor Tile Mastic
09B	9"X9" Tan Floor Tile Mastic
09CC	9x9 Tan Floor Tile Mastic
107	12"x12" Yellow Speckled Vinyl Floor Tile Mastic
109	12"x12" Gray Speckled Vinyl Floor Tile Mastic
10A	12"x12" Tan Floor Tile Mastic
112	12"x12" Gray w/Dark Gray Streaks Vinyl Floor Tile Mastic
114	14x14 White Speckled Vinyl Floor Tile Mastic
116	14x14 Light Blue Speckled Vinyl Floor Tile Mastic
118	14x14 Green Speckled Vinyl Floor Tile Mastic

14A	Brown Baseboard Mastic
14B	Black Baseboard Mastic
17B	12x12 Brown Floor Tile Mastic
22	Spray-On Insulation
CM-1	Rust Carpet Mastic
CM-5	Rust Colored Carpet Mastic
HA-103	1'x1' Grooved Ceiling Tile Glue

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Josh Herman, IDPH License # 100-21040. The Management Plan was updated by James Tuinenga, IDPH License # 100-00349. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 10/31/2022

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Morgan Park High School Building 1490 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

**School** Morgan Park High School **Unit** 46251 **Building ID** 1490  
**Address** 1744 W. Pryor Ave. **Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
05A	9"x9" Gray Floor Tile	800	SF	1964 Building-Rooms 337, 341, 347 & Lunchroom Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
05AA	9"x9" Green Floor Tile (Checkerboard Pattern) ABATED			1925 Building-Room 218 ABATED	ABATED	MISC								
05B	9"x9" Tan Floor Tile	4,700	SF	Library, Library Office, Copy Room, Internet Lab	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05BB	9"x9" Black Floor Tile (Checkerboard Pattern) ABATED			1925 Building-Room 218	ABATED	MISC								
05CC	9"X9" Tan Floor Tile	1,100	SF	Rooms 229 & 263	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06A	12"x12" White w/Specles Floor Tile			1925 Building-Throughout Corridors & Classrooms, Rooms 222 & 310	NO_ACBM	MISC								
06B	12"x12" Brown Floor Tile	11,905	SF	Rooms: 259, 230, 228, 257, 253, 207, 153, 307, and 320	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06C	12"x12" Gray w/Specs Floor Tile NOT OBSERVED			1925 Building-Room 312, (Duplicate of HA 26)	ASSUMED	MISC								
09A	9x9 Gray Floor Tile Mastic	800	SF	1964 Building-Rooms 337, 341, 347 & Lunchroom Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
09AA	9"x9" Green Floor Tile Mastic (Checkerboard Pattern) ABATED			1925 Building-Room 218	ABATED	MISC								
09B	9"X9" Tan Floor Tile Mastic	4,700	SF	Library, Library Office, Copy Room, Internet Lab	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09BB	9"x9" Black Floor Tile Mastic (Checkerboard Pattern) ABATED			1925 Building-Room 218	ABATED	MISC								
09CC	9x9 Tan Floor Tile Mastic	1,100	SF	Rooms 229 & 263	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
105	2x2' Pin Hole Ceiling Tile	3,900	SF	1925 Building- 3rd Floor Corridor, Pool, 109- (1025)	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
106	12"x12" Yellow Speckled Vinyl Floor Tile	13,000	SF	1964 Building-Rooms 215, 217,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Morgan Park High School **Unit** 46251 **Building ID** 1490  
**Address** 1744 W. Pryor Ave. **Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				221, 223, 225, 227, 233, 234, 235, 237, 241, 243, 245, 247, 331, 315, 317, 319, 321, 323, 325, 327, 331, 337, 339, 347										
107	12"x12" Yellow Speckled Vinyl Floor Tile Mastic	13,000	SF	1964 Building- Rooms 215, 217, 221, 223, 225, 227, 233, 234, 235, 237, 241, 243, 245, 247, 331, 315, 317, 319, 321, 323, 325, 327, 331, 337, 339, 347	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
108	12"x12" Gray Speckled Vinyl Floor Tile	7,000	SF	1964 Building- Rooms 215, 217, 221, 223, 225, 227, 233, 234, 235, 237, 241, 243, 245, 247, 331, 315, 317, 319, 321, 323, 325, 327, 331, 337, 339, 347	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
109	12"x12" Gray Speckled Vinyl Floor Tile Mastic	7,800	SF	1964 Building- Rooms 215, 217, 221, 223, 225, 227, 233, 234, 235, 237, 241, 243, 245, 247, 331, 315, 317, 319, 321, 323, 325, 327, 331, 337, 339, 347	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10A	12"x12" Tan Floor Tile Mastic	1,055	SF	1964 Building- Main Entrance, Room 141 & Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
110	Yellow Linoleum NOT OBSERVED	1,500	SF	1964 Building- Room 331	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
111	12"x12" Gray w/Dark Gray Streaks Vinyl Floor Tile	1,000	SF	1964 Building- 3rd & 2nd Floor Corridors next to Elevator	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
112	12"x12" Gray w/Dark Gray Streaks Vinyl Floor Tile Mastic	1,000	SF	1964 Building- 3rd and 2nd Floor Corridors next to Elevator	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
113	14x14 White Speckled Vinyl Floor Tile	1,500	SF	1964 Building- Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Morgan Park High School **Unit** 46251 **Building ID** 1490  
**Address** 1744 W. Pryor Ave. **Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
114	14x14 White Speckled Vinyl Floor Tile Mastic	1,500	SF	1964 Building- Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
115	14x14 Light Blue Speckled Vinyl Floor Tile	1,500	SF	1964 Building- Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
116	14x14 Light Blue Speckled Vinyl Floor Tile Mastic	1,500	SF	1964 Building- Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
117	14x14 Green Speckled Vinyl Floor Tile	1,500	SF	1964 Building- Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
118	14x14 Green Speckled Vinyl Floor Tile Mastic	1,500	SF	1964 Building- Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
119	24"x24" Grey, Light Grey & Green Floor Tile	7,500	SF	1st Floor Corridors	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
119A	24"x24" Grey, Light Grey & Green Floor Tile Mastic	7,500	SF	1st Floor Corridors	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
120	24"x24" Grey, Light Grey & Orange Floor Tile	8,500	SF	2nd Floor Corridors & Locker Room	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
120A	24"x24" Grey, Light Grey & Orange Floor Tile Mastic	8,500	SF	2nd Floor Corridors & Locker Rooms	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
121	24"x24" Grey, Light Grey & Yellow Floor Tile	10,000	SF	3rd Floor Corridors & Science Labs	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
121A	24"x24" Grey, Light Grey & Yellow Floor Tile Mastic	10,000	SF	3rd Floor Corridors & Science Labs	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
12A	12"x12" Tan Floor Tile ABATED			1964 Building- Main Entrance, 141 & Office	ABATED	MISC								
13A	Brown Baseboard	150	LF	1925 Building- Rooms 230, 228, 256 & 255	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13B	Black Baseboard	290	LF	1925 Building- Across from 114, 357 & 355	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14A	Brown Baseboard Mastic	150	LF	1925 Building- Rooms 228, 230, 255 & 256	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14B	Black Baseboard Mastic	290	LF	1925 Building- Across from 114, 355 & 357	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17A	12"x12" White w/ Speckles Floor Tile Mastic			1925 Building- Throughout Corridors & Classrooms, Room 310	NO_ACBM	MISC								
17B	12x12 Brown Floor Tile Mastic	11,905	SF	Rooms 259, 230, 228, 257, 253, 210,	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Morgan Park High School **Unit** 46251 **Building ID** 1490  
**Address** 1744 W. Pryor Ave. **Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				207, 208, 153, 212, 307, 351, and 320										
17C	12"x12" Gray w/Specs Floor Tile NOT OBSERVED			1925 Building- Room 312 (Duplicate of HA 26)	ASSUMED	MISC								
18	12"x12" Tan w/Beige Floor Tile NOT OBSERVED			Room 298, 398 (Duplicate of HA 27)	ASSUMED	MISC								
19	12"x12" Tan w/Beige Floor Tile Mastic NOT OBSERVED			Rooms 298 & 398 (Duplicate of HA 27A)	ASSUMED	MISC								
20	2"x4" Lay-In Ceiling Tile			Throughout 1925 Building	NO_ACBM	MISC								
21	1"x1" Ceiling Tile			1st & 2nd Floor Hall Between Old & New Buildings	NO_ACBM	MISC								
22	Spray-On Insulation	10,000	SF	Throughout 1964 Building	ASSUMED	SURFACE	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
23	Terrazzo	10,000	SF	1925 Building- 1st, 2nd & 3rd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	Plaster			1925 Building- Walls & Ceilings Throughout	NO_ACBM	SURFACE								
25	Plaster	100,000	SF	1964 Building- Walls Throughout	ASSUMED	SURFACE	N	NONE	20		No	ACBM with the potential for damage		MODERATE
26	12x12 Tan Marbled Vinyl Floor Tile	4,800	SF	351, 350, 310, 208, 210, 212, 250	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26A	12x12 Tan Marbled Vinyl Floor Tile Mastic	4,800	SF	351, 350, 310, 208, 210, 212, 250	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12x12 Beige Marbled Floor Tile	500	SF	Room 226A & 3rd Floor Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27A	12x12 Beige Marbled Vinyl Floor Tile Mastic	500	SF	Room 226A & 3rd Floor Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	12"x12" Red Floor Tile	150	SF	Room 218 (Storage Room)	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
28M	Mastic associated w/12"x12" Red Floor Tile	150	SF	Room 218 (Storage Room)	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
29	Lab Counter Tops	1,000	LF	Science Rooms 326, 334, 340 & 348	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
30	Blue Mosaic Cermaic Tile	1,000	SF	Boys' & Girls Locker Rooms (121)	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Morgan Park High School **Unit** 46251 **Building ID** 1490  
**Address** 1744 W. Pryor Ave. **Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
31	1"x1" Brown Mosaic Ceramic Tile	500	SF	& 125F) and Boys' & Girls' Toilet Rooms (123F, 123G)	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
32	Drywall	850	SF	Mechanical Rooms under Gym	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
32A	Drywall Joint Compound	850	SF	Mechanical Rooms under Gym	ASSUMED	SURFACE	N	NONE	0		Yes	ACBM with the potential for damage		LOW
33	Mud Fittings	20	LF	Boiler Room (Room 001)	ASSUMED	TSI	Y	NONE	0		Yes	ACBM with the potential for damage		LOW
34	Red Terracotta Floor Tile	400	SF	Main Entrance Lobby/Vestibule	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
34M	Adhesive associated w/Red Terracotta Floor Tile	400	SF	Main Entrance Lobby/Vestibule	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
35	Brown Terracotta Floor Tile	2,000	SF	Kitchen (139B) & Serving Area (139)	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
A	2'x2' Lay-In Ceiling Panels	3,480	SF	1964 Building- 2nd & 3rd Floor Hallways	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
B	12"x12" Greenish Floor Tile	535	SF	Hallway near New Elevator Wing	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
C	Aircell Pipe Insulation	205	LF	South Tunnel	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
CM-1	Rust Carpet Mastic	700	SF	1925 Building- Attendance Office & Assistant Principal's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
CM-2	Green Carpet Mastic	515	SF	1925 Building- Band Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
CM-3	Multicolor Carpet	1,260	SF	1925 Building- Room 151	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
CM-5	Rust Colored Carpet Mastic	1,020	SF	1964 Building- Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
D	Lab Tabletops ABATED			Science Classrooms	ABATED	MISC					Yes			
E	Fitting Insulation on Fiberglass Insulated Piping	1,000	LF	1964 Building- Throughout School	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
F	Fitting Insulation on Fiberglass Insulated Piping	1,000	SF	1925 Building- Throughout School	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
G	Vibration Dampener	200	SF	1964 Building- Mechanical Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-100	Lining for Room Heating Units	200	SF	Room Heating Units	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable		LOW

# Chicago Public Schools

**School** Morgan Park High School **Unit** 46251 **Building ID** 1490  
**Address** 1744 W. Pryor Ave. **Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												ACBM or friable suspect ACBM		
HA-101	Interior Window Caulk	5,000	LF	Windows Throughout Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-102	Interior Window Glaze	5,000	LF	Windows Throughout Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-103	1'x1' Grooved Ceiling Tile Glue	750	SF	1964 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-104	Black Sink Undercoating	5	SF	Room 242	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	ASSUMED	MISC		UNKNO WN			Yes	ACBM with the potential for damage		

# Chicago Public Schools

School Morgan Park High School Unit 46251 Building ID 1490  
Address 1744 W. Pryor Ave. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <u>4/22/2025</u>
Inspector Name <u>Josh Herman</u>
<b>100-21040</b> <u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date

#### Inspector's Comments

HA Number:	Inspector Comments:
05A	
05AA	
05B	
05BB	
05CC	
06A	
06B	
06C	
09A	
09AA	
09B	
09BB	
09CC	
105	
106	
107	
108	Abated from Room 331 & 347
109	Abated from Room 331 & 347
10A	
110	Not Observed 2025
111	
112	
113	
114	

# Chicago Public Schools

**School** Morgan Park High School **Unit** 46251 **Building ID** 1490  
**Address** 1744 W. Pryor Ave. **Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
115	
116	
117	
118	
119	
119A	
120	
120A	
121	
121A	
12A	
13A	
13B	
14A	
14B	
17A	
17B	
17C	
18	
19	
20	
21	
22	
23	
24	
25	Damaged Plaster in Gym Storage Area and Girls' Washroom
26	
26A	
27	

# Chicago Public Schools

**School** Morgan Park High School **Unit** 46251 **Building ID** 1490  
**Address** 1744 W. Pryor Ave. **Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
27A	
28	
28M	
29	
30	
31	
32	
32A	
33	
34	
34M	
35	
A	
B	
C	
CM-1	
CM-2	
CM-3	
CM-5	
D	
E	Damaged Insulation in Boiler Room
F	
G	
HA-100	
HA-101	
HA-102	
HA-103	
HA-104	
NEW	

# Chicago Public Schools

**School** Morgan Park High School **Unit** 46251 **Building ID** 1490  
**Address** 1744 W. Pryor Ave. **Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive  
Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

**Table II**  
**Management Planner's Review**

---

# Chicago Public Schools

**School** Morgan Park High School

**Unit** 46251

**Building ID** 1490

**Address** 1744 W. Pryor Ave.

Chicago, IL, 60643

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
05A	9"x9" Gray Floor Tile	800	SF	1964 Building- Rooms 337, 341, 347 & Lunchroom Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05AA	9"x9" Green Floor Tile (Checkerboard Pattern) ABATED			1925 Building- Room 218 ABATED	Abated	MISC					
05B	9"x9" Tan Floor Tile	4,700	SF	Library, Library Office, Copy Room, Internet Lab	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05BB	9"x9" Black Floor Tile (Checkerboard Pattern) ABATED			1925 Building- Room 218	Abated	MISC					
05CC	9"x9" Tan Floor Tile	1,100	SF	Rooms 229 & 263	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06A	12"x12" White w/ Speckles Floor Tile			1925 Building- Throughout Corridors & Classrooms, Rooms 222 & 310	No ACBM	MISC					
06B	12"x12" Brown Floor Tile	11,905	SF	Rooms: 259, 230, 228, 257, 253, 207, 153, 307, and 320	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06C	12"x12" Gray w/ Specks Floor Tile NOT OBSERVED			1925 Building- Room 312, (Duplicate of HA 26)	Assumed	MISC					
09A	9x9 Gray Floor Tile Mastic	800	SF	1964 Building- Rooms 337, 341, 347 & Lunchroom Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09AA	9"x9" Green Floor Tile Mastic (Checkerboard Pattern) ABATED			1925 Building- Room 218	Abated	MISC					
09B	9"x9" Tan Floor Tile Mastic	4,700	SF	Library, Library Office, Copy Room, Internet Lab	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09BB	9"x9" Black Floor Tile Mastic (Checkerboard Pattern) ABATED			1925 Building- Room 218	Abated	MISC					
09CC	9x9 Tan Floor Tile Mastic	1,100	SF	Rooms 229 & 263	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105	2"x2" Pin Hole Ceiling Tile	3,900	SF	1925 Building- 3rd Floor Corridor, Pool, 109- (1025)	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
106	12"x12" Yellow Speckled Vinyl Floor Tile	13,000	SF	1964 Building- Rooms 215, 217, 221, 223, 225, 227, 233, 234, 235, 237, 241, 243, 245, 247, 331, 315, 317, 319, 321, 323, 325, 327, 331, 337, 339, 347	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
107	12"x12" Yellow Speckled Vinyl Floor Tile Mastic	13,000	SF	1964 Building- Rooms 215, 217, 221, 223, 225, 227, 233, 234, 235, 237, 241, 243, 245, 247, 331, 315, 317, 319, 321, 323, 325, 327, 331, 337, 339, 347	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
108	12"x12" Gray Speckled Vinyl Floor Tile	7,000	SF	1964 Building- Rooms 215, 217, 221, 223, 225, 227, 233, 234, 235, 237, 241,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Morgan Park High School

**Unit** 46251

**Building ID** 1490

**Address** 1744 W. Pryor Ave.

Chicago, IL, 60643

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				243, 245, 247, 331, 315, 317, 319, 321, 323, 325, 327, 331, 337, 339, 347							
109	12"x12" Gray Speckled Vinyl Floor Tile Mastic	7,800	SF	1964 Building- Rooms 215, 217, 221, 223, 225, 227, 233, 234, 235, 237, 241, 243, 245, 247, 331, 315, 317, 319, 321, 323, 325, 327, 331, 337, 339, 347	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10A	12"x12" Tan Floor Tile Mastic	1,055	SF	1964 Building- Main Entrance, Room 141 & Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
110	Yellow Linoleum NOT OBSERVED	1,500	SF	1964 Building- Room 331	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
111	12"x12" Gray w/Dark Gray Streaks Vinyl Floor Tile	1,000	SF	1964 Building- 3rd & 2nd Floor Corridors next to Elevator	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112	12"x12" Gray w/Dark Gray Streaks Vinyl Floor Tile Mastic	1,000	SF	1964 Building- 3rd and 2nd Floor Corridors next to Elevator	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113	14x14 White Speckled Vinyl Floor Tile	1,500	SF	1964 Building- Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114	14x14 White Speckled Vinyl Floor Tile Mastic	1,500	SF	1964 Building- Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
115	14x14 Light Blue Speckled Vinyl Floor Tile	1,500	SF	1964 Building- Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
116	14x14 Light Blue Speckled Vinyl Floor Tile Mastic	1,500	SF	1964 Building- Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
117	14x14 Green Speckled Vinyl Floor Tile	1,500	SF	1964 Building- Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
118	14x14 Green Speckled Vinyl Floor Tile Mastic	1,500	SF	1964 Building- Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
119	24"x24" Grey, Light Grey & Green Floor Tile	7,500	SF	1st Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
119A	24"x24" Grey, Light Grey & Green Floor Tile Mastic	7,500	SF	1st Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
120	24"x24" Grey, Light Grey & Orange Floor Tile	8,500	SF	2nd Floor Corridors & Locker Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
120A	24"x24" Grey, Light Grey & Orange Floor Tile Mastic	8,500	SF	2nd Floor Corridors & Locker Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
121	24"x24" Grey, Light Grey & Yellow Floor Tile	10,000	SF	3rd Floor Corridors & Science Labs	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
121A	24"x24" Grey, Light Grey & Yellow Floor Tile Mastic	10,000	SF	3rd Floor Corridors & Science Labs	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12A	12"x12" Tan Floor Tile ABATED			1964 Building- Main Entrance, 141 & Office	Abated	MISC					
13A	Brown Baseboard	150	LF	1925 Building- Rooms 230, 228, 256 & 255	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
13B	Black Baseboard	290	LF	1925 Building- Across from 114, 357 & 355	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
14A	Brown Baseboard Mastic	150	LF	1925 Building- Rooms 228, 230, 255 & 256	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
14B	Black Baseboard Mastic	290	LF	1925 Building- Across from 114, 355 & 357	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Morgan Park High School

**Unit** 46251

**Building ID** 1490

**Address** 1744 W. Pryor Ave.

Chicago, IL, 60643

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
17A	12"x12" White w/Specles Floor Tile Mastic			1925 Building- Throughout Corridors & Classrooms, Room 310	No ACBM	MISC					
17B	12x12 Brown Floor Tile Mastic	11,905	SF	Rooms 259, 230, 228, 257, 253, 210, 207, 208, 153, 212, 307, 351, and 320	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17C	12"x12" Gray w/Specs Floor Tile NOT OBSERVED			1925 Building- Room 312 (Duplicate of HA 26)	Assumed	MISC					
18	12"x12" Tan w/Beige Floor Tile NOT OBSERVED			Room 298, 398 (Duplicate of HA 27)	Assumed	MISC					
19	12"x12" Tan w/Beige Floor Tile Mastic NOT OBSERVED			Rooms 298 & 398 (Duplicate of HA 27A)	Assumed	MISC					
20	2'x4' Lay-In Ceiling Tile			Throughout 1925 Building	No ACBM	MISC					
21	1'x1' Ceiling Tile			1st & 2nd Floor Hall Between Old & New Buildings	No ACBM	MISC					
22	Spray-On Insulation	10,000	SF	Throughout 1964 Building	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
23	Terrazzo	10,000	SF	1925 Building- 1st, 2nd & 3rd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Plaster			1925 Building- Walls & Ceilings Throughout	No ACBM	SURFACE					
25	Plaster	100,000	SF	1964 Building- Walls Throughout	Assumed	SURFACE	No	20	SF	6 ACBM with the potential for damage	Repair
26	12x12 Tan Marbled Vinyl Floor Tile	4,800	SF	351, 350, 310, 208, 210, 212, 250	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26A	12x12 Tan Marbled Vinyl Floor Tile Mastic	4,800	SF	351, 350, 310, 208, 210, 212, 250	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12x12 Beige Marbled Floor Tile	500	SF	Room 226A & 3rd Floor Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27A	12x12 Beige Marbled Vinyl Floor Tile Mastic	500	SF	Room 226A & 3rd Floor Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12"x12" Red Floor Tile	150	SF	Room 218 (Storage Room)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28M	Mastic associated w/12"x12" Red Floor Tile	150	SF	Room 218 (Storage Room)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Lab Counter Tops	1,000	LF	Science Rooms 326, 334, 340 & 348	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
30	Blue Mosaic Cermaic Tile	1,000	SF	Boys' & Girls Locker Rooms (121 & 125F) and	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	1"x1" Brown Mosaic Cermaic Tile	500	SF	Boys' & Girls' Toilet Rooms (123F, 123G)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	Drywall	850	SF	Mechanical Rooms under Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32A	Drywall Joint Compound	850	SF	Mechanical Rooms under Gym	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Mud Fittings	20	LF	Boiler Room (Room 001)	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
34	Red Terracotta Floor Tile	400	SF	Main Entrance Lobby/Vestibule	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34M	Adhesive associated w/Red Terracotta Floor Tile	400	SF	Main Entrance Lobby/Vestibule	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Morgan Park High School

**Unit** 46251

**Building ID** 1490

**Address** 1744 W. Pryor Ave.

Chicago, IL, 60643

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
35	Brown Terracotta Floor Tile	2,000	SF	Kitchen (139B) & Serving Area (139)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	2'x2' Lay-In Ceiling Panels	3,480	SF	1964 Building- 2nd & 3rd Floor Hallways	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
B	12"x12" Greenish Floor Tile	535	SF	Hallway near New Elevator Wing	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	Aircell Pipe Insulation	205	LF	South Tunnel	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
CM-1	Rust Carpet Mastic	700	SF	1925 Building- Attendance Office & Assistant Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
CM-2	Green Carpet Mastic	515	SF	1925 Building- Band Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
CM-3	Multicolor Carpet	1,260	SF	1925 Building- Room 151	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
CM-5	Rust Colored Carpet Mastic	1,020	SF	1964 Building- Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
D	Lab Tabletops ABATED			Science Classrooms	Abated	MISC					
E	Fitting Insulation on Fiberglass Insulated Piping	1,000	LF	1964 Building- Throughout School	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	Fitting Insulation on Fiberglass Insulated Piping	1,000	SF	1925 Building- Throughout School	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
G	Vibration Dampener	200	SF	1964 Building- Mechanical Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-100	Lining for Room Heating Units	200	SF	Room Heating Units	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
HA-101	Interior Window Caulk	5,000	LF	Windows Throughout Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
HA-102	Interior Window Glaze	5,000	LF	Windows Throughout Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
HA-103	1'x1' Grooved Ceiling Tile Glue	750	SF	1964 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-104	Black Sink Undercoating	5	SF	Room 242	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Morgan Park High School

**Unit** 46251

**Building ID** 1490

**Address** 1744 W. Pryor Ave.

Chicago, IL, 60643

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

*Management Planner's Comments Summarized at the End of the Report*

Review Date	5/15/2025
Manager Planner Name	James Tuinenga
100-00349	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
05A	
05AA	
05B	
05BB	
05CC	
06A	
06B	
06C	
09A	
09AA	
09B	
09BB	
09CC	

# Chicago Public Schools

**School** Morgan Park High School

**Unit** 46251

**Building ID** 1490

**Address** 1744 W. Pryor Ave.

Chicago, IL, 60643

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
105	
106	
107	
108	
109	
10A	
110	
111	
112	
113	
114	
115	
116	
117	
118	
119	
119A	
120	
120A	
121	
121A	
12A	
13A	
13B	
14A	
14B	
17A	

# Chicago Public Schools

**School** Morgan Park High School

**Unit** 46251

**Building ID** 1490

**Address** 1744 W. Pryor Ave.

Chicago, IL, 60643

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
17B	
17C	
18	
19	
20	
21	
22	
23	
24	
25	repair response action selective to area of damage only
26	
26A	
27	
27A	
28	
28M	
29	
30	
31	
32	
32A	
33	
34	
34M	
35	
A	
B	

# Chicago Public Schools

**School** Morgan Park High School

**Unit** 46251

**Building ID** 1490

**Address** 1744 W. Pryor Ave.

Chicago, IL, 60643

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
C	
CM-1	
CM-2	
CM-3	
CM-5	
D	
E	
F	
G	
HA-100	
HA-101	
HA-102	
HA-103	
HA-104	
NEW	

## APPENDIX A

---

### Assessment Sheets, Drawings and Photos

**Chicago Public Schools**

**TEM Environmental, Inc.**

***2025 AHERA REINSPECTION***

# Chicago Public Schools

TEM Environmental, Inc.

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05A		
MATERIAL DESCRIPTION:	9"X9" Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	1964 Building- Rooms 337, 341, 347 & Lunchroom Office		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **05A**

MATERIAL DESCRIPTION: **9"X9" Gray Floor Tile**

MATERIAL LOCATION: **1964 Building- Rooms 337, 341, 347 & Lunchroom Office**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUILDING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05AA		
MATERIAL DESCRIPTION:	9"x9" Green Floor Tile (Checkerboard Pattern) ABATED		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1925 Building- Room 218 ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **05AA**

MATERIAL DESCRIPTION: **9"x9" Green Floor Tile (Checkerboard Pattern) ABATED**

MATERIAL LOCATION: **1925 Building- Room 218 ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUILDING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05B		
MATERIAL DESCRIPTION:	9"x9" Tan Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Library, Library Office, Copy Room, Internet Lab		
MATERIAL QUANTITY:	4700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **05B**

MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile**

MATERIAL LOCATION: **Library, Library Office, Copy Room, Internet Lab**

MATERIAL QUANTITY: **4700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05BB		
MATERIAL DESCRIPTION:	9"x9" Black Floor Tile (Checkerboard Pattern) ABATED		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1925 Building- Room 218

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **05BB**

MATERIAL DESCRIPTION: **9"x9" Black Floor Tile (Checkerboard Pattern) ABATED**

MATERIAL LOCATION: **1925 Building- Room 218**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05CC		
MATERIAL DESCRIPTION:	9"X9" Tan Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 229 & 263		
MATERIAL QUANTITY:	1100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **05CC**

MATERIAL DESCRIPTION: **9"X9" Tan Floor Tile**

MATERIAL LOCATION: **Rooms 229 & 263**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06A**

MATERIAL DESCRIPTION: **12"x12" White w/ Speckles Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building- Throughout Corridors & Classrooms, Rooms 222 & 310**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: **04/22/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **06A**

MATERIAL DESCRIPTION: **12"x12" White w/ Speckles Floor Tile**

MATERIAL LOCATION: **1925 Building- Throughout Corridors & Classrooms, Rooms 222 & 310**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUILDING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06B		
MATERIAL DESCRIPTION:	12"x12" Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms: 259, 230, 228, 257, 253, 207, 153, 307, and 320		
MATERIAL QUANTITY:	11905	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **06B**

MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile**

MATERIAL LOCATION: **Rooms: 259, 230, 228, 257, 253, 207, 153, 307, and 320**

MATERIAL QUANTITY: **11905** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06C**

MATERIAL DESCRIPTION: **12"x12" Gray w/Specs Floor Tile NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building- Room 312, (Duplicate of HA 26)**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/22/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **06C**

MATERIAL DESCRIPTION: **12"x12" Gray w/Speccks Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **1925 Building- Room 312, (Duplicate of HA 26)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09A		
MATERIAL DESCRIPTION:	9x9 Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1964 Building- Rooms 337, 341, 347 & Lunchroom Office		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **09A**

MATERIAL DESCRIPTION: **9x9 Gray Floor Tile Mastic**

MATERIAL LOCATION: **1964 Building- Rooms 337, 341, 347 & Lunchroom Office**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUILDING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09AA		
MATERIAL DESCRIPTION:	9"x9" Green Floor Tile Mastic (Checkerboard Pattern) ABATED		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1925 Building- Room 218

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **09AA**

MATERIAL DESCRIPTION: **9"x9" Green Floor Tile Mastic (Checkerboard Pattern) ABATED**

MATERIAL LOCATION: **1925 Building- Room 218**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09B		
MATERIAL DESCRIPTION:	9"X9" Tan Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Library, Library Office, Copy Room, Internet Lab		
MATERIAL QUANTITY:	4700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **09B**

MATERIAL DESCRIPTION: **9"X9" Tan Floor Tile Mastic**

MATERIAL LOCATION: **Library, Library Office, Copy Room, Internet Lab**

MATERIAL QUANTITY: **4700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUILDING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09BB		
MATERIAL DESCRIPTION:	9"x9" Black Floor Tile Mastic (Checkerboard Pattern) ABATED		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1925 Building- Room 218

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **09BB**

MATERIAL DESCRIPTION: **9"x9" Black Floor Tile Mastic (Checkerboard Pattern) ABATED**

MATERIAL LOCATION: **1925 Building- Room 218**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09CC		
MATERIAL DESCRIPTION:	9x9 Tan Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 229 & 263		
MATERIAL QUANTITY:	1100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **09CC**

MATERIAL DESCRIPTION: **9x9 Tan Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 229 & 263**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUILDING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	105		
MATERIAL DESCRIPTION:	2'x2' Pin Hole Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1925 Building- 3rd Floor Corridor, Pool, 109- (1025)		
MATERIAL QUANTITY:	3900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **105**

MATERIAL DESCRIPTION: **2'x2' Pin Hole Ceiling Tile**

MATERIAL LOCATION: **1925 Building- 3rd Floor Corridor, Pool, 109- (1025)**

MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	106		
MATERIAL DESCRIPTION:	12"x12" Yellow Speckled Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1964 Building- Rooms 215, 217, 221, 223, 225, 227, 233, 234, 235, 237, 241, 243, 245, 247, 331, 315, 317, 319, 321, 323, 325, 327, 331, 337, 339, 347**

MATERIAL QUANTITY: **13000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/22/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA:	<b>106</b>				
MATERIAL DESCRIPTION:	<b>12"x12" Yellow Speckled Vinyl Floor Tile</b>				
MATERIAL LOCATION:	<b>1964 Building- Rooms 215, 217, 221, 223, 225, 227, 233, 234, 235, 237, 241, 243, 245, 247, 331, 315, 317, 319, 321, 323, 325, 327, 331, 337, 339, 347</b>				
MATERIAL QUANTITY:	<b>13000</b>	MATERIAL UNITS:	<b>SF</b>		
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: 05/15/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	107		
MATERIAL DESCRIPTION:	12"x12" Yellow Speckled Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1964 Building- Rooms 215, 217, 221, 223, 225, 227, 233, 234, 235, 237, 241, 243, 245, 247, 331, 315, 317, 319, 321, 323, 325, 327, 331, 337, 339, 347**

MATERIAL QUANTITY: **13000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/22/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA:	<b>107</b>				
MATERIAL DESCRIPTION:	<b>12"x12" Yellow Speckled Vinyl Floor Tile Mastic</b>				
MATERIAL LOCATION:	<b>1964 Building- Rooms 215, 217, 221, 223, 225, 227, 233, 234, 235, 237, 241, 243, 245, 247, 331, 315, 317, 319, 321, 323, 325, 327, 331, 337, 339, 347</b>				
MATERIAL QUANTITY:	<b>13000</b>	MATERIAL UNITS:	<b>SF</b>		
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: 05/15/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	108		
MATERIAL DESCRIPTION:	12"x12" Gray Speckled Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1964 Building- Rooms 215, 217, 221, 223, 225, 227, 233, 234, 235, 237, 241, 243, 245, 247, 331, 315, 317, 319, 321, 323, 325, 327, 331, 337, 339, 347**

MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS: **Abated from Room 331 & 347**

Inspector's Signature:



Date: **04/22/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA:	<b>108</b>				
MATERIAL DESCRIPTION:	<b>12"x12" Gray Speckled Vinyl Floor Tile</b>				
MATERIAL LOCATION:	<b>1964 Building- Rooms 215, 217, 221, 223, 225, 227, 233, 234, 235, 237, 241, 243, 245, 247, 331, 315, 317, 319, 321, 323, 325, 327, 331, 337, 339, 347</b>				
MATERIAL QUANTITY:	<b>7000</b>	MATERIAL UNITS:	<b>SF</b>		
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: 05/15/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	109		
MATERIAL DESCRIPTION:	12"x12" Gray Speckled Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1964 Building- Rooms 215, 217, 221, 223, 225, 227, 233, 234, 235, 237, 241, 243, 245, 247, 331, 315, 317, 319, 321, 323, 325, 327, 331, 337, 339, 347**

MATERIAL QUANTITY: **7800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Abated from Room 331 & 347**

Inspector's Signature:



Date: **04/22/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA:	<b>109</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Gray Speckled Vinyl Floor Tile Mastic</b>		
MATERIAL LOCATION:	<b>1964 Building- Rooms 215, 217, 221, 223, 225, 227, 233, 234, 235, 237, 241, 243, 245, 247, 331, 315, 317, 319, 321, 323, 325, 327, 331, 337, 339, 347</b>		
MATERIAL QUANTITY:	<b>7800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10A		
MATERIAL DESCRIPTION:	12"x12" Tan Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1964 Building- Main Entrance, Room 141 & Office		
MATERIAL QUANTITY:	1055	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **10A**

MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile Mastic**

MATERIAL LOCATION: **1964 Building- Main Entrance, Room 141 & Office**

MATERIAL QUANTITY: **1055** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	110		
MATERIAL DESCRIPTION:	Yellow Linoleum NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1964 Building- Room 331		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **110**

MATERIAL DESCRIPTION: **Yellow Linoleum NOT OBSERVED**

MATERIAL LOCATION: **1964 Building- Room 331**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	111		
MATERIAL DESCRIPTION:	12"x12" Gray w/Dark Gray Streaks Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1964 Building- 3rd & 2nd Floor Corridors next to Elevator		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **111**

MATERIAL DESCRIPTION: **12"x12" Gray w/Dark Gray Streaks Vinyl Floor Tile**

MATERIAL LOCATION: **1964 Building- 3rd & 2nd Floor Corridors next to Elevator**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	112		
MATERIAL DESCRIPTION:	12"x12" Gray w/Dark Gray Streaks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1964 Building- 3rd and 2nd Floor Corridors next to Elevator		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **112**

MATERIAL DESCRIPTION: **12"x12" Gray w/Dark Gray Streaks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **1964 Building- 3rd and 2nd Floor Corridors next to Elevator**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	113		
MATERIAL DESCRIPTION:	14x14 White Speckled Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1964 Building- Lunchroom		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **113**

MATERIAL DESCRIPTION: **14x14 White Speckled Vinyl Floor Tile**

MATERIAL LOCATION: **1964 Building- Lunchroom**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	114		
MATERIAL DESCRIPTION:	14x14 White Speckled Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1964 Building- Lunchroom		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **114**

MATERIAL DESCRIPTION: **14x14 White Speckled Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **1964 Building- Lunchroom**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	115		
MATERIAL DESCRIPTION:	14x14 Light Blue Speckled Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1964 Building- Lunchroom		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **115**

MATERIAL DESCRIPTION: **14x14 Light Blue Speckled Vinyl Floor Tile**

MATERIAL LOCATION: **1964 Building- Lunchroom**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	116		
MATERIAL DESCRIPTION:	14x14 Light Blue Speckled Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1964 Building- Lunchroom		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **116**

MATERIAL DESCRIPTION: **14x14 Light Blue Speckled Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **1964 Building- Lunchroom**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	117		
MATERIAL DESCRIPTION:	14x14 Green Speckled Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1964 Building- Lunchroom		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **117**

MATERIAL DESCRIPTION: **14x14 Green Speckled Vinyl Floor Tile**

MATERIAL LOCATION: **1964 Building- Lunchroom**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	118		
MATERIAL DESCRIPTION:	14x14 Green Speckled Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1964 Building- Lunchroom		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **118**

MATERIAL DESCRIPTION: **14x14 Green Speckled Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **1964 Building- Lunchroom**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	119		
MATERIAL DESCRIPTION:	24"x24" Grey, Light Grey & Green Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Corridors		
MATERIAL QUANTITY:	7500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **119**

MATERIAL DESCRIPTION: **24"x24" Grey, Light Grey & Green Floor Tile**

MATERIAL LOCATION: **1st Floor Corridors**

MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	119A		
MATERIAL DESCRIPTION:	24"x24" Grey, Light Grey & Green Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Corridors		
MATERIAL QUANTITY:	7500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUIDLING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **119A**

MATERIAL DESCRIPTION: **24"x24" Grey, Light Grey & Green Floor Tile Mastic**

MATERIAL LOCATION: **1st Floor Corridors**

MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	120		
MATERIAL DESCRIPTION:	24"x24" Grey, Light Grey & Orange Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Corridors & Locker Room		
MATERIAL QUANTITY:	8500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **120**

MATERIAL DESCRIPTION: **24"x24" Grey, Light Grey & Orange Floor Tile**

MATERIAL LOCATION: **2nd Floor Corridors & Locker Room**

MATERIAL QUANTITY: **8500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	120A		
MATERIAL DESCRIPTION:	24"x24" Grey, Light Grey & Orange Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Corridors & Locker Rooms		
MATERIAL QUANTITY:	8500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUIDLING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **120A**

MATERIAL DESCRIPTION: **24"x24" Grey, Light Grey & Orange Floor Tile Mastic**

MATERIAL LOCATION: **2nd Floor Corridors & Locker Rooms**

MATERIAL QUANTITY: **8500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	121		
MATERIAL DESCRIPTION:	24"x24" Grey, Light Grey & Yellow Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Corridors & Science Labs		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUIDLING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **121**

MATERIAL DESCRIPTION: **24"x24" Grey, Light Grey & Yellow Floor Tile**

MATERIAL LOCATION: **3rd Floor Corridors & Science Labs**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	121A		
MATERIAL DESCRIPTION:	24"x24" Grey, Light Grey & Yellow Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Corridors & Science Labs		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUIDLING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **121A**

MATERIAL DESCRIPTION: **24"x24" Grey, Light Grey & Yellow Floor Tile Mastic**

MATERIAL LOCATION: **3rd Floor Corridors & Science Labs**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 12A

MATERIAL DESCRIPTION: 12"x12" Tan Floor Tile ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1964 Building- Main Entrance, 141 & Office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **12A**

MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile ABATED**

MATERIAL LOCATION: **1964 Building- Main Entrance, 141 & Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13A		
MATERIAL DESCRIPTION:	Brown Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1925 Building- Rooms 230, 228, 256 & 255		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **13A**

MATERIAL DESCRIPTION: **Brown Baseboard**

MATERIAL LOCATION: **1925 Building- Rooms 230, 228, 256 & 255**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13B		
MATERIAL DESCRIPTION:	Black Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1925 Building- Across from 114, 357 & 355		
MATERIAL QUANTITY:	290	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **13B**

MATERIAL DESCRIPTION: **Black Baseboard**

MATERIAL LOCATION: **1925 Building- Across from 114, 357 & 355**

MATERIAL QUANTITY: **290** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14A		
MATERIAL DESCRIPTION:	Brown Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1925 Building- Rooms 228, 230, 255 & 256		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **14A**

MATERIAL DESCRIPTION: **Brown Baseboard Mastic**

MATERIAL LOCATION: **1925 Building- Rooms 228, 230, 255 & 256**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14B		
MATERIAL DESCRIPTION:	Black Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1925 Building- Across from 114, 355 & 357		
MATERIAL QUANTITY:	290	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **14B**

MATERIAL DESCRIPTION: **Black Baseboard Mastic**

MATERIAL LOCATION: **1925 Building- Across from 114, 355 & 357**

MATERIAL QUANTITY: **290** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 17A

MATERIAL DESCRIPTION: 12"x12" White w/ Speckles Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1925 Building- Throughout Corridors & Classrooms, Room 310

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **17A**

MATERIAL DESCRIPTION: **12"x12" White w/ Speckles Floor Tile Mastic**

MATERIAL LOCATION: **1925 Building- Throughout Corridors & Classrooms, Room 310**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17B		
MATERIAL DESCRIPTION:	12x12 Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 259, 230, 228, 257, 253, 210, 207, 208, 153, 212, 307, 351, and 320		
MATERIAL QUANTITY:	11905	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **17B**

MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 259, 230, 228, 257, 253, 210, 207, 208, 153, 212, 307, 351, and 320**

MATERIAL QUANTITY: **11905** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 17C

MATERIAL DESCRIPTION: 12"x12" Gray w/Specs Floor Tile NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1925 Building- Room 312 (Duplicate of HA 26)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **17C**

MATERIAL DESCRIPTION: **12"x12" Gray w/Speccks Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **1925 Building- Room 312 (Duplicate of HA 26)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 18

MATERIAL DESCRIPTION: 12"x12" Tan w/Beige Floor Tile NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 298, 398 (Duplicate of HA 27)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12"x12" Tan w/Beige Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **Room 298, 398 (Duplicate of HA 27)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **12"x12" Tan w/Beige Floor Tile Mastic NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 298 & 398 (Duplicate of HA 27A)**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/22/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **12"x12" Tan w/Beige Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **Rooms 298 & 398 (Duplicate of HA 27A)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 20  
MATERIAL DESCRIPTION: 2'x4' Lay-In Ceiling Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout 1925 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **2'x4' Lay-In Ceiling Tile**

MATERIAL LOCATION: **Throughout 1925 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUILDING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21	
MATERIAL DESCRIPTION:	1'x1' Ceiling Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st & 2nd Floor Hall Between Old & New Buildings

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **1'x1' Ceiling Tile**

MATERIAL LOCATION: **1st & 2nd Floor Hall Between Old & New Buildings**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	Spray-On Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout 1964 Building		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Spray-On Insulation**

MATERIAL LOCATION: **Throughout 1964 Building**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1925 Building- 1st, 2nd & 3rd Floor Corridors		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **1925 Building- 1st, 2nd & 3rd Floor Corridors**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUILDING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 24  
MATERIAL DESCRIPTION: Plaster  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1925 Building- Walls & Ceilings Throughout

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **1925 Building- Walls & Ceilings Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>1964 Building- Walls Throughout</b>		
MATERIAL QUANTITY:	<b>100000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Damaged Plaster in Gym Storage Area and Girls' Washroom</b>		

Inspector's Signature:



Date: **04/22/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **1964 Building- Walls Throughout**

MATERIAL QUANTITY: **100000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

#### Comments:

repair response action selective to area of damage only

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	12x12 Tan Marbled Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	351, 350, 310, 208, 210, 212, 250		
MATERIAL QUANTITY:	4800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **12x12 Tan Marbled Vinyl Floor Tile**

MATERIAL LOCATION: **351, 350, 310, 208, 210, 212, 250**

MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26A		
MATERIAL DESCRIPTION:	12x12 Tan Marbled Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	351, 350, 310, 208, 210, 212, 250		
MATERIAL QUANTITY:	4800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **26A**

MATERIAL DESCRIPTION: **12x12 Tan Marbled Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **351, 350, 310, 208, 210, 212, 250**

MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	12x12 Beige Marbled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 226A & 3rd Floor Office		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUIDLING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **12x12 Beige Marbled Floor Tile**

MATERIAL LOCATION: **Room 226A & 3rd Floor Office**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27A		
MATERIAL DESCRIPTION:	12x12 Beige Marbled Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 226A & 3rd Floor Office		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **27A**

MATERIAL DESCRIPTION: **12x12 Beige Marbled Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 226A & 3rd Floor Office**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A		
MATERIAL DESCRIPTION:	2'x2' Lay-In Ceiling Panels		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1964 Building- 2nd & 3rd Floor Hallways		
MATERIAL QUANTITY:	3480	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **2'x2' Lay-In Ceiling Panels**

MATERIAL LOCATION: **1964 Building- 2nd & 3rd Floor Hallways**

MATERIAL QUANTITY: **3480** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	B		
MATERIAL DESCRIPTION:	12"x12" Greenish Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Hallway near New Elevator Wing		
MATERIAL QUANTITY:	535	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUIDLING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **12"x12" Greenish Floor Tile**

MATERIAL LOCATION: **Hallway near New Elevator Wing**

MATERIAL QUANTITY: **535** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUILDING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	South Tunnel		
MATERIAL QUANTITY:	205	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **South Tunnel**

MATERIAL QUANTITY: **205** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	CM-1		
MATERIAL DESCRIPTION:	Rust Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1925 Building- Attendance Office & Assistant Principal's Office		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **CM-1**

MATERIAL DESCRIPTION: **Rust Carpet Mastic**

MATERIAL LOCATION: **1925 Building- Attendance Office & Assistant Principal's Office**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	CM-2		
MATERIAL DESCRIPTION:	Green Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1925 Building- Band Room		
MATERIAL QUANTITY:	515	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **CM-2**

MATERIAL DESCRIPTION: **Green Carpet Mastic**

MATERIAL LOCATION: **1925 Building- Band Room**

MATERIAL QUANTITY: **515** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	CM-3		
MATERIAL DESCRIPTION:	Multicolor Carpet		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1925 Building- Room 151		
MATERIAL QUANTITY:	1260	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **CM-3**

MATERIAL DESCRIPTION: **Multicolor Carpet**

MATERIAL LOCATION: **1925 Building- Room 151**

MATERIAL QUANTITY: **1260** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	CM-5		
MATERIAL DESCRIPTION:	Rust Colored Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1964 Building- Main Office		
MATERIAL QUANTITY:	1020	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **CM-5**

MATERIAL DESCRIPTION: **Rust Colored Carpet Mastic**

MATERIAL LOCATION: **1964 Building- Main Office**

MATERIAL QUANTITY: **1020** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: D

MATERIAL DESCRIPTION: Lab Tabletops ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Science Classrooms

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Lab Tabletops ABATED**

MATERIAL LOCATION: **Science Classrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	Fitting Insulation on Fiberglass Insulated Piping		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1964 Building- Throughout School		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:	Damaged Insulation in Boiler Room		

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Fitting Insulation on Fiberglass Insulated Piping**

MATERIAL LOCATION: **1964 Building- Throughout School**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F		
MATERIAL DESCRIPTION:	Fitting Insulation on Fiberglass Insulated Piping		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1925 Building- Throughout School		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Fitting Insulation on Fiberglass Insulated Piping**

MATERIAL LOCATION: **1925 Building- Throughout School**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G		
MATERIAL DESCRIPTION:	Vibration Dampener		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1964 Building- Mechanical Room		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Vibration Dampener**

MATERIAL LOCATION: **1964 Building- Mechanical Room**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	HA-100		
MATERIAL DESCRIPTION:	Lining for Room Heating Units		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room Heating Units		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **HA-100**

MATERIAL DESCRIPTION: **Lining for Room Heating Units**

MATERIAL LOCATION: **Room Heating Units**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	HA-101		
MATERIAL DESCRIPTION:	Interior Window Caulk		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Windows Throughout Building		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **HA-101**

MATERIAL DESCRIPTION: **Interior Window Caulk**

MATERIAL LOCATION: **Windows Throughout Building**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	HA-102		
MATERIAL DESCRIPTION:	Interior Window Glaze		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Windows Throughout Building		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **HA-102**

MATERIAL DESCRIPTION: **Interior Window Glaze**

MATERIAL LOCATION: **Windows Throughout Building**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	HA-103		
MATERIAL DESCRIPTION:	1'x1' Grooved Ceiling Tile Glue		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1964 Building		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **HA-103**

MATERIAL DESCRIPTION: **1'x1' Grooved Ceiling Tile Glue**

MATERIAL LOCATION: **1964 Building**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	HA-104		
MATERIAL DESCRIPTION:	Black Sink Undercoating		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 242		
MATERIAL QUANTITY:	5	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUILDING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **HA-104**

MATERIAL DESCRIPTION: **Black Sink Undercoating**

MATERIAL LOCATION: **Room 242**

MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	NEW		
MATERIAL DESCRIPTION:	Newly Installed Suspect ACM		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/22/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46251</b>	BUIDLING ID:	<b>1490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Morgan Park High School</b>	REVIEW DATE:	<b>5/15/2025</b>		
ADDRESS:	<b>1744 W. Pryor Ave.</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **NEW**

MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**

MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	Lab Counter Tops		
MATERIAL LOCATION:	Science Rooms 326, 334, 340 & 348		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **5/15/2025**

ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Lab Counter Tops**

MATERIAL LOCATION: **Science Rooms 326, 334, 340 & 348**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Josh Herman**  
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/22/2025**  
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-21040**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **1"x1" Brown Mosaic Ceramic Tile**  
MATERIAL LOCATION: **Boys' & Girls' Toilet Rooms (123F, 123G)**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC** FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW** CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach** DAMAGE REASON:  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **04/22/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **5/15/2025**

ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **1"x1" Brown Mosaic Ceramic Tile**

MATERIAL LOCATION: **Boys' & Girls' Toilet Rooms (123F, 123G)**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Josh Herman**  
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/22/2025**  
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-21040**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **Mechanical Rooms under Gym**  
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC** FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW** CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach** DAMAGE REASON:  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **04/22/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **5/15/2025**

ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Mechanical Rooms under Gym**

MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/15/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	32A				
MATERIAL DESCRIPTION:	Drywall Joint Compound				
MATERIAL LOCATION:	Mechanical Rooms under Gym				
MATERIAL QUANTITY:	850	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	SURFACE	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **5/15/2025**

ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **32A**

MATERIAL DESCRIPTION: **Drywall Joint Compound**

MATERIAL LOCATION: **Mechanical Rooms under Gym**

MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/15/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Josh Herman**  
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/22/2025**  
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-21040**

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Mud Fittings**  
MATERIAL LOCATION: **Boiler Room (Room 001)**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**  
MATERIAL CATEGORY: **TSI** FRIABLE: **Yes**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW** CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach** DAMAGE REASON:  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature:



Date: **04/22/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **5/15/2025**

ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Mud Fittings**

MATERIAL LOCATION: **Boiler Room (Room 001)**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	12"x12" Red Floor Tile		
MATERIAL LOCATION:	Room 218 (Storage Room)		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **5/15/2025**

ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **12"x12" Red Floor Tile**

MATERIAL LOCATION: **Room 218 (Storage Room)**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/15/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	28M				
MATERIAL DESCRIPTION:	Mastic associated w/12"x12" Red Floor Tile				
MATERIAL LOCATION:	Room 218 (Storage Room)				
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **5/15/2025**

ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **28M**

MATERIAL DESCRIPTION: **Mastic associated w/12"x12" Red Floor Tile**

MATERIAL LOCATION: **Room 218 (Storage Room)**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/15/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	34M				
MATERIAL DESCRIPTION:	Adhesive associated w/Red Terracotta Floor Tile				
MATERIAL LOCATION:	Main Entrance Lobby/Vestibule				
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **5/15/2025**

ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **34M**

MATERIAL DESCRIPTION: **Adhesive associated w/Red Terracotta Floor Tile**

MATERIAL LOCATION: **Main Entrance Lobby/Vestibule**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/15/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Josh Herman**  
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/22/2025**  
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-21040**

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Blue Mosaic Ceramic Tile**  
MATERIAL LOCATION: **Boys' & Girls Locker Rooms (121 & 125F) and**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC** FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW** CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach** DAMAGE REASON:  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **04/22/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **5/15/2025**

ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Blue Mosaic Ceramic Tile**

MATERIAL LOCATION: **Boys' & Girls Locker Rooms (121 & 125F) and**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Josh Herman**  
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/22/2025**  
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-21040**

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Red Terracotta Floor Tile**  
MATERIAL LOCATION: **Main Entrance Lobby/Vestibule**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC** FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW** CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach** DAMAGE REASON:  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **04/22/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **5/15/2025**

ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Red Terracotta Floor Tile**

MATERIAL LOCATION: **Main Entrance Lobby/Vestibule**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/15/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46251	BUIDLING ID:	1490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Morgan Park High School	INSPECTION DATE:	4/22/2025		
ADDRESS:	1744 W. Pryor Ave.	IDPH LICENSE NO:	100-21040		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	Brown Terracotta Floor Tile		
MATERIAL LOCATION:	Kitchen (139B) & Serving Area (139)		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/22/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **5/15/2025**

ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Brown Terracotta Floor Tile**

MATERIAL LOCATION: **Kitchen (139B) & Serving Area (139)**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/15/2025

## APPENDIX B

---

### Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**JOSH R HERMAN**  
5121 N MONITOR AVE  
CHICAGO, IL 60630

5/23/2025

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 21040

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License



**ASBESTOS  
PROFESSIONAL  
LICENSE**

**ENDORSEMENTS**

**TC EXPIRES**

INSPECTOR

7/19/2025

ID NUMBER  
100 - 21040

ISSUED  
5/23/2025

EXPIRES  
05/15/2026

**JOSH R HERMAN**  
5121 N MONITOR AVE  
CHICAGO, IL 60630  
Environmental Health



**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**

*Nationally Accredited by PHAB*

Reliable  
Environmental  
Solutions, Inc. **R | E | S**

*This is to certify that*

**James Tuinenga**

*has on 2/2/22, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Building Inspector Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher.*

Course Date: February 2, 2022

**COURSE LENGTH: 4 HOURS**

Examination Date: February 2, 2022

Expiration Date: February 2, 2023

Certificate Number: BIR/1013

*William S. Williams*

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois  217.787.9800  217.787.9801 FAX  [www.ReliableEnv.com](http://www.ReliableEnv.com)



**TEM ENVIRONMENTAL, INC.**

ENVIRONMENTAL SCIENTISTS | INDUSTRIAL HYGIENISTS



ENDORSEMENTS

INSPECTOR	2/2/2023
PROJECT DESIGNER	2/3/2023
MANAGEMENT PLANNER	2/2/2023
PROJECT MANAGER	2/1/2023
AIR SAMPLING PROFESSIONAL	

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

Reliable  
Environmental  
Solutions, Inc. **R E S**

*This is to certify that*

**James Tuinenga**

*has on 2/02/22, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: February 2, 2022

**COURSE LENGTH: 4 HOURS**

Examination Date: February 2, 2022

Expiration Date: February 2, 2023

*William S. Williams*


Certificate Number: MPR/0458

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois  217.787.9800  217.787.9801 FAX  [www.ReliableEnv.com](http://www.ReliableEnv.com)



**TEM ENVIRONMENTAL, INC.**  
ENVIRONMENTAL SCIENTISTS | INDUSTRIAL HYGIENISTS



**ENDORSEMENTS**

INSPECTOR  
PROJECT DESIGNER  
MANAGEMENT PLANNER  
PROJECT MANAGER  
AIR SAMPLING PROFESSIONAL

**TC EXPIRES**

1/31/2025  
2/1/2025  
1/31/2025  
1/30/2025

**Alteration of this license shall result in legal action**

This license issued under authority of the State of Illinois

Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.

**Reliable  
Environmental  
Solutions, Inc. R E S**

*This is to certify that*

**James Tuinenga**

*has on 2/5/25, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Building Inspector Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher.*

Course Date: February 5, 2025

**COURSE LENGTH: 4 HOURS**

Examination Date: February 5, 2025

Expiration Date: February 5, 2026

Certificate Number: BIR/1227




Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois  217.787.9800  [www.ReliableEnv.com](http://www.ReliableEnv.com)



**TEM ENVIRONMENTAL, INC.**  
ENVIRONMENTAL SCIENTISTS | INDUSTRIAL HYGIENISTS



**ENDORSEMENTS**

INSPECTOR  
PROJECT DESIGNER  
MANAGEMENT PLANNER  
PROJECT MANAGER  
AIR SAMPLING PROFESSIONAL

**TC EXPIRES**

2/5/2026  
2/6/2025  
2/5/2026  
2/4/2026

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

**Reliable  
Environmental  
Solutions, Inc.** **R E S**

*This is to certify that*

**James Tuinenga**

*has on 2/5/25, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: February 5, 2025

**COURSE LENGTH: 4 HOURS**

Examination Date: February 5, 2025

Expiration Date: February 5, 2026

Certificate Number: MPR/0546



Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois  217.787.9800  [www.ReliableEnv.com](http://www.ReliableEnv.com)

## APPENDIX C

---

### **Laboratory Accreditations**

## APPENDIX D

---

### Laboratory Results

## APPENDIX E

---

### Chain of Custody Forms

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>	Loc	Localized
	Dist	Distributed