

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0043
SCHOOL NAME: Taft High School
ADDRESS OF SCHOOL: 6545 W. Hurlburt St.
CITY: Chicago, IL, 60631

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 4/13/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 9/4/2025 ENROLLMENT 4134
IDPH INSPECTOR LICENSE NUMBER: 100-18350
IDPH LICENSED INSPECTOR NAME (Please Print): Joseph Hennigan
IDPH MP LICENSE NUMBER: 100-04019
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Arturo Saenz

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer

Signature of Designated Person

10/1/2025

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Taft High School

6545 W. Hurlburt St.
Chicago, IL, 60631

Unit: 46311
Building ID: 1580

IDPH ID Number: 14-016-2990-0043

REPORT DATE:
Wednesday, October 01, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
Specialty Consulting, Inc.

2942 W. Van Buren Street
Chicago, IL, 60612
Phone (312) 319-7575
Fax (312) 319-7580

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

10/01/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Specialty Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 46311 Region: 01 IDPH ID: 14-016-2990-0043

School: Taft High School Building ID: 1580

Address: 6545 W. Hurlburt St.

Chicago, IL, 60631

Building Contact: Johnson, Leonard Contact Phone: 3124045469

Current Building Owners: Chicago Public Schools

Reinspection Date: 9/4/2025

Review Date: 10/01/2025

Inspector: Joseph Hennigan

Inspector IDPH License: 100-18350

Management Planner: Arturo Saenz

Management Planner IDPH License: 100-04019

If you have any questions or comments, please contact us at (312) 319-7575

Sincerely,
Specialty Consulting, Inc.



Arturo Saenz
100-04019

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: October 01, 2025

RE: Taft High School, Unit 46311
6545 W. Hurlburt St.
Chicago, IL, 60631

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Taft High School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Taft High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Taft High School Unit: 46311 Region: 01
Address: 6545 W. Hurlbert St. Chicago, IL, 60631
IDPH ID: 14-016-2990-0043 Building ID: 1580
Contact: Johnson, Leonard Phone: 3124045469

2. Description of Facility

Original Construction: 1939 Additional Construction: 1959,1974
Total Square Footage: 175896 No of Floors: 3
Current Occupancy: 4134

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Specialty Consulting, Inc.
Contact: Jigar Shah
Address 2942 W. Van Buren Street
Phone: (312) 319-7575 Fax: (312) 319-7580

5. Inspector

Inspector Name: Joseph Hennigan



Signature:
Date: 9/4/2025

Inspector IDPH license # 100-18350
Reinspection Date: 9/4/2025

6. Management Planner

Management Planner Name: Arturo Saenz



Signature:
Date: 10/01/2025


Management Planner IDPH license # 100-04019

7. Review Date: 10/01/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Richard J. Schleyer

Date: 10/1/2025

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Specialty Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Taft High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1580:

02	12"x12" White w/ Gray Streaks VFT
125	12" x 12" White w/ Light Green Streaks VFT
71	MJP E/F/V on Fiberglass Pipe Insulation

B. The following new homogenous areas have been identified for Building 1580:

1005A	Beige linoleum Mastic
1006A	gray with white streaks linoleum Mastic
149	24" x 6" wood grain vinyl plank flooring
149A	24" x 6" wood grain vinyl plank flooring Mastic
150	12 x 12 tan speckled vft
150A	12 x 12 tan speckled vft Mastic
151	2' x 2' white ceiling tile w/ pinholes
152	12 x 12 off white w/ beige & gray specks vft
152A	12 x 12 off white w/ beige & gray specks vft Mastic
153	12 x 12 light blue streaked vft
153A	12 x 12 off white w/ beige & gray specks vft Mastic
154	12 x 12 blue with blue streaks vft
154A	12 x 12 blue with blue streaks vft Mastic
155	drywall system (board, mud, tape)
156	2 x 2 white ceiling tile with pinholes
157	12 x 12 tan with white specks vft
157A	12 x 12 tan with white specks vft Mastic
158	cloth wire insulation
159	12 x 12 Blue with Dark Blue specs replacement vft
160	9 x 9 gray with white and black streaks vft
160A	9 x 9 gray with white black streaks vft Mastic
161	12 x 12 Cream vft
161A	12 x 12 cream vft Mastic

162	12 x 12 white with gold streaks vft
162A	12 x 12 white with gold streaks vft Mastic
163	Replacement Tiles - 12 x 12 white with gray streaks vft
163A	Replacement Tiles - 12 x 12 white with gray streaks vft Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	12"x12" White w/ Beige Speckles VFT
04	12"x12" White w/ Beige Streaks VFT
05	12"x12" White w/ Beige Streaks VFT Mastic
07	12"x12" Dark Gray w/ White Streaks VFT
09	12"x12" Off White w/ Tan Specks VFT
10	12"x12" White w/ Gold Streaks VFT
1005A	Beige linoleum Mastic
1006A	gray with white streaks linoleum Mastic
102	12" x 12" Brown w/ Black Specks VFT
103	12" x 12" Brown w/ Black Specks VFT Mastic
104	12" x 12" White w/ Gray Specks VFT
105	12" x 12" White w/ Gray Specks VFT Mastic
106	12" x 12" Off White w/ Beige Streaks VFT
107	12" x 12" Off White w/ Beige Streaks VFT Mastic
11	12"x12" Light Brown w/ White Streaks VFT
111	12"x12" White w/ Gray Streaks VFT Mastic
112	12"x12" Brown w/ White Streaks VFT Mastic
113	12"x12" Brown w/ Beige Streaks VFT Mastic
114	12"x12" White w/ Beige Streaks VFT Mastic
115	9"x9" Light Brown w/ Beige Streaks VFT
118	12"x12" Off White w/ Tan Specks VFT Mastic
119	12"x12" White w/ Gold Streaks VFT Mastic
120	12"x12" Light Brown w/ White Streaks VFT Mastic
121	12"x12" Yellow w/ White Streaks VFT Mastic
122	12"x12" Green Speckles VFT Mastic
123	12"x12" Yellow Speckled VFT Mastic
13	12"x12" Green Speckles VFT
130	12" x 12" Dark Gray VFT
131	12" x 12" Dark Gray VFT Mastic
133	Carpet Mastic
134	Carpet Mastic
135	Terrazo
136	Terrazo
137	Terrazo
138	Cardboard Pipe Insulation (Paper Wrap on Insulation)
139	MJP E/V/F on Cardboard Pipe Insulation (Paper Wrap on Pipe Insulation)
14	12"x12" Yellow Speckled VFT
140	2'x4' Ceiling tile w/ grooves
141	Carpet MASTIC
142	Carpet MASTIC

143A	12"x12" light gray w/ gray streaks VFT MASTIC
144	Tectum panels
145	12" x 12" Blue w/ Specks VFT
146	12" x 12" Blue w/ Specks VFT Mastic
148	12" x 12" Light Blue VFT Mastic
149	24" x 6" wood grain vinyl plank flooring
149A	24" x 6" wood grain vinyl plank flooring Mastic
150	12 x 12 tan speckled vft
150A	12 x 12 tan speckled vft Mastic
151	2' x 2' white ceiling tile w/ pinholes
152	12 x 12 off white w/ beige & gray specks vft
152A	12 x 12 off white w/ beige & gray specks vft Mastic
153	12 x 12 light blue streaked vft
153A	12 x 12 off white w/ beige & gray specks vft Mastic
154	12 x 12 blue with blue streaks vft
154A	12 x 12 blue with blue streaks vft Mastic
155	drywall system (board, mud, tape)
156	2 x 2 white ceiling tile with pinholes
157	12 x 12 tan with white specks vft
157A	12 x 12 tan with white specks vft Mastic
158	cloth wire insulation
159	12 x 12 Blue with Dark Blue specs replacement vft
16	2'x4' Dot Wave Ceiling Tile
160	9 x 9 gray with white and black streaks vft
160A	9 x 9 gray with white black streaks vft Mastic
161	12 x 12 Cream vft
161A	12 x 12 cream vft Mastic
163	Replacement Tiles - 12 x 12 white with gray streaks vft
163A	Replacement Tiles - 12 x 12 white with gray streaks vft Mastic
17	1'x1' White Smooth Ceiling Tile
27	Black Table Tops
58	MJP E/F/V on Fiberglass Pipe Insulation
71	MJP E/F/V on Fiberglass Pipe Insulation
72	Hard Coat Plaster
73	Exterior Window Glaze
74	Exterior Window Glaze
75	Exterior Window Glaze
76	Exterior Window Caulk
77	Exterior Window Caulk
78	Exterior Window Caulk
79	Interior Window Caulk
80	Interior Window Glaze
81	Interior Window Glaze
82	Interior Window Glaze
90	12"x12" Tan w/ Brown Streaks VFT
98	2'x4' Dot Wave Ceiling Tile

HA-1000	5' x 2.5' ceiling tile with random pinholes
HA-1003	MJP E/V/F on Cardboard Pipe Insulation (Paper Wrap on Insulation)
HA-1005	Beige Linoleum
HA-1006	Grey w/ White Streaks Linoleum
HA-1007	12"x12" White w/Gray Streaks VFT
HA-1008	12"x12" White w/Gray Streaks VFT Mastic

The following areas were deemed to be inaccessible:

100	12"x12" Off White w/ Gray Streaks VFT Mastic
149A	24" x 6" wood grain vinyl plank flooring Mastic
151	2' x 2' white ceiling tile w/ pinholes
152A	12 x 12 off white w/ beige & gray specks vft Mastic
153A	12 x 12 off white w/ beige & gray specks vft Mastic
154A	12 x 12 blue with blue streaks vft Mastic
155	drywall system (board, mud, tape)
156	2 x 2 white ceiling tile with pinholes
157A	12 x 12 tan with white specks vft Mastic
160A	9 x 9 gray with white black streaks vft Mastic
161A	12 x 12 cream vft Mastic
162A	12 x 12 white with gold streaks vft Mastic
163A	Replacement Tiles - 12 x 12 white with gray streaks vft Mastic
61	MJP E/F/V on Fiberglass Pipe Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Joseph Hennigan, IDPH License # 100-18350. The Management Plan was updated by Arturo Saenz, IDPH License # 100-04019. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 8/14/2023

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Taft High School Building 1580 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Taft High School **Unit** 46311 **Building ID** 1580
Address 6545 W. Hurlburt St. **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	12"x12" White w/ Beige Speckles VFT	200	SF	Basement Break Room - 1939 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02	12"x12" White w/ Gray Streaks VFT	34,500	SF	Damage in rooms 111, 112, 112A, 113, 115 offices, 101, 106, 107, 108, 203, 205, 228, 228E, 221, 219, 217, 207, 306B - 1939 Building	CHR	MISC	N	NONE	200		Yes	ACBM with potential for significant damage	5	MODERATE
03	12"x12" Brown w/ White Streaks VFT	1,600	SF	Room 119-121 Wood Shop - 1939 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04	12"x12" White w/ Beige Streaks VFT	700	SF	Engineers Office Room 321 - 1939 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05	12"x12" White w/ Beige Streaks VFT Mastic	700	SF	Engineer's Office Room 321 - 1939 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06	9"x9" Light Brown w/ Beige Streaks VFT	100	SF	Engineer's Office Hallway - 1939 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	12"x12" Dark Gray w/ White Streaks VFT	98	SF	First Floor Corridor by Mens and Womens Toilet - 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	12"x12" Light Gray w/ Gray Speckles VFT	98	SF	Throughout - 1974 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	12"x12" Off White w/ Tan Specks VFT	4,000	SF	Rooms 146, 147, 157A, 155, 159, 160, 161, 173, 175, 176, 247, 255, 247, 2nd Floor Hallway - 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	12"x12" White w/ Gold Streaks VFT	2,000	SF	Throughout - 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
100	12"x12" Off White w/ Gray Streaks VFT Mastic	2,000	SF	Rooms 214, 216, 300, 300A, and 300L; 1st through 3rd Floor South Corridor - 1939 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1005A	Beige linoleum Mastic	2,300	SF	Rooms 311, 313, 213	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Taft High School **Unit** 46311 **Building ID** 1580
Address 6545 W. Hurlburt St. **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1006A	gray with white streaks linoleum Mastic	3,400	SF	rooms 302, 303, 305, 307, 308, 321, 312, 316, 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
101	2'x4' White w/ Deep Grooves Ceiling Tile			Room 173, 174 - 1974 Building	NO_ACBM									
102	12" x 12" Brown w/ Black Specks VFT	3,200	SF	Rooms 155, 159, 160, 161, 173, 175, 176, 247, 255, Kitchen Office - 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
103	12" x 12" Brown w/ Black Specks VFT Mastic	3,200	SF	Rooms 155, 159, 160, 161, 173, 175, 176, 247, 255, Kitchen Office - 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
104	12" x 12" White w/ Gray Specks VFT	500	SF	Room 207, Teachers Lounge - 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
105	12" x 12" White w/ Gray Specks VFT Mastic	500	SF	Room 207, Teachers Lounge - 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
106	12" x 12" Off White w/ Beige Streaks VFT	1,000	SF	Room 149, 150, 152, 154, Main Office - 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
107	12" x 12" Off White w/ Beige Streaks VFT Mastic	1,000	SF	Room 149, 150, 152, 154, Main Office - 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
108	12" x 12" Brown w/ White & Black Specks VFT - NOT OBSERVED			Room 149, 158-160 - 1974 Building NOT OBSERVED										
109	12" x 12" Brown w/ White & Black Specks VFT Mastic - NOT OBSERVED			Room 149, 158-160 - 1974 Building NOT OBSERVED										
11	12"x12" Light Brown w/ White Streaks VFT	3,000	SF	Rooms 151, 152, 156, 153, 171, 184, 256, 263, 264 - 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
110	12" x 12" White w/ Beige Speckles VFT Mastic - Abated			Room 311, Break Room - 1939 Building	ABATED	MISC								
111	12"x12" White w/ Gray Streaks VFT Mastic	3,000	SF	Throughout Building (See Hatching Maps) - 1939 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Taft High School **Unit** 46311 **Building ID** 1580
Address 6545 W. Hurlburt St. **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
112	12"x12" Brown w/ White Streaks VFT Mastic	1,000	SF	Room 119-121 Wood Shop - 1939 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
113	12"x12" Brown w/ Beige Streaks VFT Mastic	650	SF	Room 321 - 1939 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
114	12"x12" White w/ Beige Streaks VFT Mastic	650	SF	Room 321 - 1939 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
115	9"x9" Light Brown w/ Beige Streaks VFT	100	SF	Engineer's Office Hallway - 1939 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
116	12"x12" Dark Gray w/ White Streaks VFT Mastic	200	SF	First Floor Corridor by Mens and Womens Toilet - 1974 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
117	12"x12" Light Gray w/ Gray Speckles VFT Mastic	23,465	SF	Throughout (See Hatching Maps) - 1974 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
118	12"x12" Off White w/ Tan Specks VFT Mastic	4,000	SF	Rooms 146, 147, 157A, 155, 159, 160, 161, 173, 175, 176, 247, 255, 247, 2nd Floor Hallway - 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
119	12"x12" White w/ Gold Streaks VFT Mastic	2,000	SF	Throughout - 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	12"x12" Yellow w/ White Streaks VFT	2,000	SF	Rooms 151 (replaced with 12 x 12 white w/ gold vft & white w/ gray vft), 153, 171, 184, 256, 283 - 1974 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
120	12"x12" Light Brown w/ White Streaks VFT Mastic	3,000	SF	Rooms 151, 152, 156, 153, 171, 184, 256, 263, 264 - 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
121	12"x12" Yellow w/ White Streaks VFT Mastic	2,000	SF	Room 151 (replaced with 12 x 12 white w/ gold vft & white w/ gray vft), 153, 171, 184, 256, 263, 264 - 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
122	12"x12" Green Speckles VFT Mastic	6,000	SF	Lunchroom, Lunchroom W, Storeroom - 1974	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Taft High School **Unit** 46311 **Building ID** 1580
Address 6545 W. Hurlburt St. **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Building										
123	12"x12" Yellow Speckled VFT Mastic	3,800	SF	Lunchroom, Counseling Offices - 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
124	1' x 1' White w/ Deep Grooves Ceiling Tile			Room 187 - 1974 Bldg.	NO_ACBM									
125	12" x 12" White w/ Light Green Streaks VFT	1,500	SF	Room 306 (306A & 306B) - 1939 Building	CHR	MISC	N	LOC	20		Yes	ACBM with potential for significant damage	2	MODERATE
126	12" x 12" White w/ Light Green Streaks VFT Mastic	1,500	SF	Room 306 (306A and 306B) - 1939 Building	CHR	MISC	N	LOC	20		No	ACBM with potential for significant damage	3	MODERATE
127	Beige w/ Purple Streaks Linoleum			Room 213, 213A - 1939 Building	NO_ACBM									
128	Beige w/ Purple Streaks Linoleum Mastic			Room 213, 213A - 1939 Building	NO_ACBM									
129	2' x 4' Dot Ceiling Tile			Room 213, 213A - 1939 Building	NO_ACBM									
13	12"x12" Green Speckles VFT	6,000	SF	Lunchroom, Lunchroom W, Storeroom - 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
130	12" x 12" Dark Gray VFT	700	SF	Room 140, 142 - 1958 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
131	12" x 12" Dark Gray VFT Mastic	700	SF	Room 140, 142 - 1958 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
132	12" x 12" Beige w/Gray & Tan Streaks VFT ABATED			Rooms 300, 302, 308, 310, 311-313, 316 - 1939 Building ABATED	ABATED	MISC								
132 A	12" x 12" Beige w/Gray & Tan Streaks VFT Mastic ABATED			Rooms: 300, 302, 308, 310, 311-313, 316 - 1939 Building ABATED	ABATED	MISC	N				No			LOW
133	Carpet Mastic	12,000	SF	Choir Room, Band Room, Library, Main Office, 163, 164, 162, 190, 172, 174 - 1974 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
134	Carpet Mastic	2,050	SF	Rooms 206, 208 and 210 - 1939 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
135	Terrazo	2,000	SF	Stairwells - 1974 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
136	Terrazo	2,000	SF	Halls - 1939 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Taft High School **Unit** 46311 **Building ID** 1580
Address 6545 W. Hurlburt St. **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
137	Terrazo	1,000	SF	Gym Lobby - 1958 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
138	Cardboard Pipe Insulation (Paper Wrap on Insulation)	60	LF	Chase Behind Room 134, First Floor Women's Toilet 107A (Above Plaster ceiling), Basement Chiller Room	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
139	MJP E/V/F on Cardboard Pipe Insulation (Paper Wrap on Pipe Insulation)	20	FITTING	Chase Behind Room 134	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
14	12"x12" Yellow Speckled VFT	3,400	SF	Lunchroom, Counseling Offices - 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
140	2'x4' Ceiling tile w/ grooves	33,000	SF	Throughout - 1939 Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
141	Carpet MASTIC	1,500	SF	174, 172, corridor both sides of exit #4 - 1974 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
142	Carpet MASTIC	1,600	SF	Auditorium between the isles, 230, 330 - 1958 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
143	12"x12" light gray w/ gray streaks VFT	27,900	SF	damage in rooms 216, 217, 212, 203	CHR	MISC	N	DIST	69		No	ACBM with the potential for damage		LOW
143A	12"x12" light gray w/ gray streaks VFT MASTIC	27,900	SF	damage in rooms 216, 217, 212, 203	ASSUMED	MISC	N	NONE	69		No	ACBM with the potential for damage		LOW
144	Tectum panels	6,000	SF	Rooms 218, 222, 126	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
145	12" x 12" Blue w/ Specks VFT	800	SF	Room 121 - 1939 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
146	12" x 12" Blue w/ Specks VFT Mastic	800	SF	Room 121 - 1939 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
147	12" x 12" Light Blue w/ Specks VFT	1,800	SF	Room 142, 220 - 1958 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
148	12" x 12" Light Blue VFT Mastic	1,800	SF	Room 142, 220 - 1958 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
149	24" x 6" wood grain vinyl plank flooring	500	SF	Room 230, 2nd floor men's bath	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
149A	24" x 6" wood grain vinyl plank flooring Mastic	500	SF	Room 230 and 2nd floor men's bathroom	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		
150	12 x 12 tan speckled vft	1,364	SF	room 206, 210, 205, 208, 210A, 221	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
150A	12 x 12 tan speckled vft Mastic	1,364	SF	room 206, 210, 205,	ASSUMED	MISC	N	NONE	0			ACBM with the		LOW

Chicago Public Schools

School Taft High School **Unit** 46311 **Building ID** 1580
Address 6545 W. Hurlburt St. **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				208, 210A, 221								potential for damage		
151	2' x 2' white ceiling tile w/ pinholes	5,600	SF	room 316, 312, 310, 307, 308	ASSUMED	MISC	Y	NONE	0			ACBM with the potential for damage		LOW
152	12 x 12 off white w/ beige & gray specks vft	720	SF	Room 319	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
152A	12 x 12 off white w/ beige & gray specks vft Mastic	720	SF	room 319	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
153	12 x 12 light blue streaked vft	302	SF	Room 330	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
153A	12 x 12 off white w/ beige & gray specks vft Mastic	302	SF	room 330	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
154	12 x 12 blue with blue streaks vft	45	SF	Women's bathroom @ 330	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
154A	12 x 12 blue with blue streaks vft Mastic	45	SF	Women's bathroom @ 330	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
155	drywall system (board, mud, tape)	300	SF	wall installed between 342 and 342A	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
156	2 x 2 white ceiling tile with pinholes	20,000	SF	Rooms 300, 300A, 303, 305, 305A, 304 a-b-c-d & office, 302, 302A & office/storage room, 203, 208, 204, 210, 205, 206, 210A, 213, 214, 211	ASSUMED	MISC	Y	NONE	0			ACBM with the potential for damage		LOW
157	12 x 12 tan with white specks vft	225	SF	306 B	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		
157A	12 x 12 tan with white specks vft Mastic	225	SF	306 B	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
158	cloth wire insulation	10	SF	Room 347	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
159	12 x 12 Blue with Dark Blue specs replacement vft	350	SF	room 107 (75), 109 (40), old vault conference room (144), 238 (80)	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
16	2'x4' Dot Wave Ceiling Tile	2,000	SF	First Floor Corridor, Room 114, 212, 302 A - 1939 Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
160	9 x 9 gray with white and black streaks vft	80	SF	storage room by 220	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
160A	9 x 9 gray with white black streaks vft Mastic	80	SF	storage room by 220	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
161	12 x 12 Cream vft	50	SF	Room 207, 212, 219	ASSUMED	MISC	N	NONE	0			ACBM with the		LOW

Chicago Public Schools

School Taft High School **Unit** 46311 **Building ID** 1580
Address 6545 W. Hurlburt St. **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				replacements								potential for damage		
161A	12 x 12 cream vft Mastic	50	SF	Room 207, 212, 219	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
162	12 x 12 white with gold streaks vft	100	SF	Room 151	CHR	MISC	N	NONE	0			ACBM with the potential for damage		LOW
162A	12 x 12 white with gold streaks vft Mastic	100	SF	Room 151	CHR	MISC	N	NONE	0			ACBM with the potential for damage		LOW
163	Replacement Tiles - 12 x 12 white with gray streaks vft	35	SF	# 151	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
163A	Replacement Tiles - 12 x 12 white with gray streaks vft Mastic	35	SF	Room 151	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
17	1'x1' White Smooth Ceiling Tile	120	SF	Room 320 - 1939 Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
19	2'x4' White w/ Pin Holes Ceiling Tile			Room 246, 247, 250, 252, 253, 256, 264 - 1974 Building	NO_ACBM	MISC								
20	1'x1' White w/ Deep Grooves Ceiling Tile			Room 173 - 1974 Building	NO_ACBM	MISC								
21	1'x1' White w/ Small Holes Ceiling Tile			Serving Room, Kitchen, 151/183 Hallway - 1974 Building	NO_ACBM	MISC								
27	Black Table Tops		EA	Room 300, 302A, 305-307 - 1939 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	Hardcoat Plaster	2,000	SF	Throughout - 1939 Building - Damage on 218 gym ceiling plaster, 222 gym ceiling, 228 gym walls, 239, 236, 347, 125	CHR	SURFACE	N	DIST	80		No	ACBM with potential for significant damage	10	MODERATE
55	Drywall Joint Compound			Janitors Closets, Boys and Girls Toilets - 1974 Building	NO_ACBM	MISC								
58	MJP E/F/V on Fiberglass Pipe Insulation	300	FITTING	Sprinkler Room, Chiller Room, W. Crawlspace, Carpenters Shop, Plenum Chamber - 1939 Building	ASSUMED	TSI	Y	DIST	20		No	Damaged or significantly damaged friable thermal system insulating ACM	1	LOW
61	MJP E/F/V on Fiberglass Pipe Insulation		EA	Sprinkler Room, Carpenter Shop,	NO_ACBM	TSI	Y	DIST	10			Damaged or significantly damaged	1	LOW

Chicago Public Schools

School Taft High School **Unit** 46311 **Building ID** 1580
Address 6545 W. Hurlburt St. **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Basement Corridor - 1974 Building								friable thermal system insulating ACBM		
65	12" x 12" Brown w/ White Streaks VFT	890	SF	Room 342 - 1958 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
66	12" x 12" Brown w/ White Streaks VFT Mastic	890	SF	Room 342 - 1958 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
67	12" x 12" Light Gray w/ Dark Gray Specks VFT	3,571	SF	Rooms 342, 340, 341, 338, 339, 337, 336, 324 - 1958 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
68	12" x 12" Light Gray w/ Dark Gray Specks VFT Mastic	3,571	SF	Rooms 342, 340, 341, 338, 339, 337, 336, 324 - 1958 Building- 1958 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69	2' x 4' White w/ Deep Grooves Ceiling Tile			Room 134, 239, 326 - 1958 Building	NO_ACBM	MISC								
70	1' x 1' White w/ Deep Grooves Ceiling Tile			Gymnasium Lobby - 1958 Building	NO_ACBM	MISC								
71	MJP E/F/V on Fiberglass Pipe Insulation	20	FITTING	Fan Units, Unfinished Pipe Space, Rifle Range - 1958 Building	ASSUMED	TSI	Y	DIST	20		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	1	LOW
72	Hard Coat Plaster	10,000	SF	Throughout - 1958 Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
73	Exterior Window Glaze		LF	Exterior Windows - 1939 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
74	Exterior Window Glaze		LF	Exterior Windows - 1958 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
75	Exterior Window Glaze		LF	Exterior Windows - 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
76	Exterior Window Caulk		LF	Exterior Windows - 1939 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
77	Exterior Window Caulk		LF	Exterior Windows - 1958 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
78	Exterior Window Caulk		LF	Exterior Windows - 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
79	Interior Window Caulk		LF	Interior Windows - 1939 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
80	Interior Window Glaze		LF	Interior Windows - 1939 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
81	Interior Window Glaze		LF	Interior Windows - 1958 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
82	Interior Window Glaze		LF	Interior Windows -	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Taft High School **Unit** 46311 **Building ID** 1580
Address 6545 W. Hurlburt St. **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				1974 Building								potential for damage		
84	9"x9" Red VFT	10	SF	Stage South Stairwell - 1939 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
85	9"x9" Red VFT Mastic	10	SF	Stage South Stairwell - 1939 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
86	9"x9" Black VFT	10	SF	Stage South Stairwell - 1939 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
87	9"x9" Black VFT Mastic	10	SF	Stage South Stairwell - 1939 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
88	2"x18" Black VFT	36	SF	Stage South Stairwell - 1939 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
89	2"x18" Black VFT Mastic	36	SF	Stage South Stairwell - 1939 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
90	12"x12" Tan w/ Brown Streaks VFT	400	SF	121 Woodshop - 1939 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
91	12"x12" Tan w/ Brown Streaks VFT Mastic	400	SF	121 Woodshop - 1939 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
92	12"x12" Tan w/ Brown & White Streaks VFT ABATED			Room 117 - 1939 Building ABATED	ABATED	MISC								
93	12"x12" Tan w/ Brown & White Streaks VFT Mastic ABATED			Room 117 - 1939 Building ABATED	ABATED	MISC								
94	Brown Linoleum - NOT OBSERVED			2nd Floor Teachers Lounge - 1939 Building - NOT OBSERVED										
95	Brown Linoleum Mastic - NOT OBSERVED			2nd Floor Teachers Lounge - 1939 Building - NOT OBSERVED										
98	2'x4' Dot Wave Ceiling Tile	1,000	SF	Room 106, 112, 216, 300 - 1939 Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
99	12"x12" Off White w/ Gray Streaks VFT	2,000	SF	Rooms 214, 216, 300, 300A, and 300L; 1st through 3rd Floor South Corridor - 1939 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-1000	5' x 2.5' ceiling tile with random pinholes	10,000	SF	throughout - 1974	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Taft High School **Unit** 46311 **Building ID** 1580
Address 6545 W. Hurlburt St. **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Building										
HA-1001	Black table and counter tops ABATED			Rooms 300, 302, 302A, 305, 308, 310, 312, 313, 316 ABATED	ABATED	MISC							potential for damage	
HA-1002	Gray lab table and counter tops ABATED			Room 183 - 1974 Bldg. ABATED	ABATED	MISC								
HA-1003	MJP E/V/F on Cardboard Pipe Insulation (Paper Wrap on Insulation)	155	FITTING	Chase Behind Room 134	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
HA-1004	Gray transite panel - ABATED			Exhaust hood in Room 302A - ABATED	ABATED	MISC								
HA-1005	Beige Linoleum	3,300	SF	Rooms 311, 313, 213, & office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-1006	Grey w/ White Streaks Linoleum	3,400	SF	Rooms 302, 303, 305, 307, 308, 310, 312, 316, 213, 211 - Material replaced in 213, with HA 1005	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-1007	12"x12" White w/Gray Streaks VFT	600	SF	Room 117	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-1008	12"x12" White w/Gray Streaks VFT Mastic	600	SF	Room 117	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Taft High School Unit 46311 Building ID 1580
Address 6545 W. Hurlburt St. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

Reinspection Date	<u>9/4/2025</u>
Inspector Name	<u>Joseph Hennigan</u>
100-18350	5/15/2026
Inspector's IDPH License Number / Expiration Date	

Inspector's Comments

HA Number:	Inspector Comments:
01	
02	damage - cracks chips, in vft
03	
04	
05	
06	
07	
08	
09	
10	
100	
1005A	
1006A	
101	
102	
103	
104	
105	
106	
107	
108	
109	
11	
110	

Chicago Public Schools

School Taft High School **Unit** 46311 **Building ID** 1580
Address 6545 W. Hurlburt St. **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
111	
112	
113	
114	
115	
116	
117	
118	
119	
12	damaged vft replaced with new tiles
120	
121	damagde vft replaced with new tiles
122	
123	
124	
125	classroom 306 split into two rooms 306A and 306B
126	classroom 306 split into two rooms 306A and 306B
127	
128	
129	
13	
130	
131	
132	
132 A	
133	
134	
135	
136	

Chicago Public Schools

School Taft High School **Unit** 46311 **Building ID** 1580
Address 6545 W. Hurlburt St. **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
137	
138	
139	
14	
140	
141	
142	
143	
143A	
144	
145	
146	
147	
148	
149	New installation
149A	New installation
150	
150A	
151	New install
152	new install
152A	New install
153	new install
153A	new install
154	new install
154A	New install
155	new install
156	new install
157	new replacements for HA125
157A	New replacements for new HA125

Chicago Public Schools

School Taft High School **Unit** 46311 **Building ID** 1580
Address 6545 W. Hurlburt St. **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
158	open box - wire exposed
159	
16	
160	new HA created - may have been in original MP under different HA
160A	new HA created - may have been in original MP under different HA
161	vft replacements patched in
161A	vft replacements patched in
162	New replacement tiles for HA 12 & HA 121
162A	New replacement tiles HA 12 & HA 121
163	New replacement tiles for HA 12 & HA 121
163A	New replacement tiles for HA 12 & HA 121
17	
19	
20	
21	
27	
31	
55	
58	open ends on previous repairs to TSI - Damage throughout - see hatching map - boiler room, motor room, tunnels, tank room
61	Material quantity is unknown - material identified as non ACBM in 3 year report. open ends on previous repairs to TSI
65	
66	
67	
68	Added locations & removed throughout building
69	
70	
71	Damage throughout - see cross hatch drawings - fan units, air tunnels, supply ducts -

Chicago Public Schools

School Taft High School Unit 46311 Building ID 1580
Address 6545 W. Hurlburt St. Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
72	open ends on previous repairs to TSI
73	
74	
75	
76	
77	
78	
79	
80	
81	
82	
84	
85	
86	
87	
88	
89	
90	
91	
92	
93	
94	
95	
98	
99	
HA-1000	
HA-1001	
HA-1002	

Chicago Public Schools

School Taft High School **Unit** 46311 **Building ID** 1580
Address 6545 W. Hurlburt St. **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
HA-1003	
HA-1004	
HA-1005	
HA-1006	
HA-1007	
HA-1008	

Table II
Management Planner's Review

Chicago Public Schools

School Taft High School

Unit 46311

Building ID 1580

Address 6545 W. Hurlburt St.

Chicago, IL, 60631

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	12"x12" White w/ Beige Speckles VFT	200	SF	Basement Break Room - 1939 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02	12"x12" White w/ Gray Streaks VFT	34,500	SF	Damage in rooms 111, 112, 112A, 113, 115 offices, 101, 106, 107, 108, 203, 205, 228, 228E, 221, 219, 217, 207, 306B - 1939 Building	Chrysotile	MISC	No	200	SF	5 ACBM with potential for significant damage	Follow O&M Plan
03	12"x12" Brown w/ White Streaks VFT	1,600	SF	Room 119-121 Wood Shop - 1939 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	12"x12" White w/ Beige Streaks VFT	700	SF	Engineers Office Room 321 - 1939 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	12"x12" White w/ Beige Streaks VFT Mastic	700	SF	Engineer's Office Room 321 - 1939 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	9"x9" Light Brown w/ Beige Streaks VFT	100	SF	Engineer's Office Hallway - 1939 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	12"x12" Dark Gray w/ White Streaks VFT	98	SF	First Floor Corridor by Mens and Womens Toilet - 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	12"x12" Light Gray w/ Gray Speckles VFT	98	SF	Throughout - 1974 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	12"x12" Off White w/ Tan Specks VFT	4,000	SF	Rooms 146, 147, 157A, 155, 159, 160, 161, 173, 175, 176, 247, 255, 247, 2nd Floor Hallway - 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	12"x12" White w/ Gold Streaks VFT	2,000	SF	Throughout - 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
100	12"x12" Off White w/ Gray Streaks VFT Mastic	2,000	SF	Rooms 214, 216, 300, 300A, and 300L; 1st through 3rd Floor South Corridor - 1939 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1005A	Beige linoleum Mastic	2,300	SF	Rooms 311, 313, 213	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1006A	gray with white streaks linoleum Mastic	3,400	SF	rooms 302, 303, 305, 307, 308, 321, 312, 316, 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	2'x4' White w/ Deep Grooves Ceiling Tile			Room 173, 174 - 1974 Building	No ACBM						
102	12" x 12" Brown w/ Black Specks VFT	3,200	SF	Rooms 155, 159, 160, 161, 173, 175, 176, 247, 255, Kitchen Office - 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	12" x 12" Brown w/ Black Specks VFT Mastic	3,200	SF	Rooms 155, 159, 160, 161, 173, 175, 176, 247, 255, Kitchen Office - 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104	12" x 12" White w/ Gray Specks VFT	500	SF	Room 207, Teachers Lounge - 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105	12" x 12" White w/ Gray Specks VFT Mastic	500	SF	Room 207, Teachers Lounge - 1974	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Taft High School

Unit 46311

Building ID 1580

Address 6545 W. Hurlburt St.

Chicago, IL, 60631

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Building							
106	12" x 12" Off White w/ Beige Streaks VFT	1,000	SF	Room 149, 150, 152, 154, Main Office - 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
107	12" x 12" Off White w/ Beige Streaks VFT Mastic	1,000	SF	Room 149, 150, 152, 154, Main Office - 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
108	12" x 12" Brown w/ White & Black Specks VFT - NOT OBSERVED			Room 149, 158-160 - 1974 Building NOT OBSERVED							
109	12" x 12" Brown w/ White & Black Specks VFT Mastic- NOT OBSERVED			Room 149, 158-160 - 1974 Building NOT OBSERVED							
11	12"x12" Light Brown w/ White Streaks VFT	3,000	SF	Rooms 151, 152, 156, 153, 171, 184, 256, 263, 264 - 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
110	12" x 12" White w/ Beige Speckles VFT Mastic - Abated			Room 311, Break Room - 1939 Building	Abated	MISC					
111	12"x12" White w/ Gray Streaks VFT Mastic	3,000	SF	Throughout Building (See Hatching Maps) - 1939 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112	12"x12" Brown w/ White Streaks VFT Mastic	1,000	SF	Room 119-121 Wood Shop - 1939 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113	12"x12" Brown w/ Beige Streaks VFT Mastic	650	SF	Room 321 - 1939 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114	12"x12" White w/ Beige Streaks VFT Mastic	650	SF	Room 321 - 1939 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
115	9"x9" Light Brown w/ Beige Streaks VFT	100	SF	Engineer's Office Hallway - 1939 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
116	12"x12" Dark Gray w/ White Streaks VFT Mastic	200	SF	First Floor Corridor by Mens and Womens Toilet - 1974 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
117	12"x12" Light Gray w/ Gray Speckles VFT Mastic	23,465	SF	Throughout (See Hatching Maps) - 1974 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
118	12"x12" Off White w/ Tan Specks VFT Mastic	4,000	SF	Rooms 146, 147, 157A, 155, 159, 160, 161, 173, 175, 176, 247, 255, 247, 2nd Floor Hallway - 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
119	12"x12" White w/ Gold Streaks VFT Mastic	2,000	SF	Throughout - 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	12"x12" Yellow w/ White Streaks VFT	2,000	SF	Rooms 151 (replaced with 12 x 12 white w/ gold vft & white w/ gray vft), 153, 171, 184, 256, 263, 264 - 1974 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
120	12"x12" Light Brown w/ White Streaks VFT Mastic	3,000	SF	Rooms 151, 152, 156, 153, 171, 184, 256, 263, 264 - 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
121	12"x12" Yellow w/ White Streaks VFT Mastic	2,000	SF	Room 151 (replaced with 12 x 12 white w/ gold vft & white w/ gray vft), 153,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Taft High School

Unit 46311

Building ID 1580

Address 6545 W. Hurlburt St.

Chicago, IL, 60631

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				171, 184, 256, 263 - 1974 Building							
122	12"x12" Green Speckles VFT Mastic	6,000	SF	Lunchroom, Lunchroom W. Storeroom - 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
123	12"x12" Yellow Speckled VFT Mastic	3,800	SF	Lunchroom, Counseling Offices - 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
124	1' x 1' White w/ Deep Grooves Ceiling Tile			Room 187 - 1974 Bldg.	No ACBM						
125	12" x 12" White w/ Light Green Streaks VFT	1,500	SF	Room 306 (306A & 306B) - 1939 Building	Chrysotile	MISC	No	20	SF	5 ACBM with potential for significant damage	Follow O&M Plan
126	12" x 12" White w/ Light Green Streaks VFT Mastic	1,500	SF	Room 306 (306A and 306B) - 1939 Building	Chrysotile	MISC	No	20	SF	5 ACBM with potential for significant damage	Follow O&M Plan
127	Beige w/ Purple Streaks Linoleum			Room 213, 213A - 1939 Building	No ACBM						
128	Beige w/ Purple Streaks Linoleum Mastic			Room 213, 213A - 1939 Building	No ACBM						
129	2' x 4' Dot Ceiling Tile			Room 213, 213A - 1939 Building	No ACBM						
13	12"x12" Green Speckles VFT	6,000	SF	Lunchroom, Lunchroom W. Storeroom - 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
130	12" x 12" Dark Gray VFT	700	SF	Room 140, 142 - 1958 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
131	12" x 12" Dark Gray VFT Mastic	700	SF	Room 140, 142 - 1958 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
132	12" x 12" Beige w/Gray & Tan Streaks VFT ABATED			Rooms 300, 302, 308, 310, 311-313, 316 - 1939 Building ABATED	Abated	MISC					
132 A	12" x 12" Beige w/Gray & Tan Streaks VFT Mastic ABATED			Rooms: 300, 302, 308, 310, 311-313, 316 - 1939 Building ABATED	Abated	MISC	No				
133	Carpet Mastic	12,000	SF	Choir Room, Band Room, Library, Main Office, 163, 164, 162, 190, 172, 174 - 1974 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
134	Carpet Mastic	2,050	SF	Rooms 206, 208 and 210 - 1939 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
135	Terrazzo	2,000	SF	Stairwells - 1974 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
136	Terrazzo	2,000	SF	Halls - 1939 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
137	Terrazzo	1,000	SF	Gym Lobby - 1958 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
138	Cardboard Pipe Insulation (Paper Wrap on Insulation)	60	LF	Chase Behind Room 134, First Floor Women's Toilet 107A (Above Plaster ceiling), Basement Chiller Room	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
139	MJP E/V/F on Cardboard Pipe Insulation (Paper Wrap on Pipe Insulation)	20	FITTING	Chase Behind Room 134	Assumed	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
14	12"x12" Yellow Speckled VFT	3,400	SF	Lunchroom, Counseling Offices - 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
140	2'x4' Ceiling tile w/ grooves	33,000	SF	Throughout - 1939 Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Taft High School

Unit 46311

Building ID 1580

Address 6545 W. Hurlburt St.

Chicago, IL, 60631

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
141	Carpet MASTIC	1,500	SF	174, 172, corridor both sides of exit #4 - 1974 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
142	Carpet MASTIC	1,600	SF	Auditorium between the isles, 230, 330 - 1958 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
143	12"x12" light gray w/ gray streaks VFT	27,900	SF	damage in rooms 216, 217, 212, 203	Chrysotile	MISC	No	69	SF	6 ACBM with the potential for damage	Follow O&M Plan
143A	12"x12" light gray w/ gray streaks VFT MASTIC	27,900	SF	damage in rooms 216, 217, 212, 203	Assumed	MISC	No	69	SF	6 ACBM with the potential for damage	Follow O&M Plan
144	Tectum panels	6,000	SF	Rooms 218, 222, 126	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
145	12" x 12" Blue w/ Specks VFT	800	SF	Room 121 - 1939 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
146	12" x 12" Blue w/ Specks VFT Mastic	800	SF	Room 121 - 1939 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
147	12" x 12" Light Blue w/ Specks VFT	1,800	SF	Room 142, 220 - 1958 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
148	12" x 12" Light Blue VFT Mastic	1,800	SF	Room 142, 220 - 1958 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
149	24" x 6" wood grain vinyl plank flooring	500	SF	Room 230, 2nd floor men's bath	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
149A	24" x 6" wood grain vinyl plank flooring Mastic	500	SF	Room 230 and 2nd floor men's bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
150	12 x 12 tan speckled vft	1,364	SF	room 206, 210, 205, 208, 210A, 221	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
150A	12 x 12 tan speckled vft Mastic	1,364	SF	room 206, 210, 205, 208, 210A, 221	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
151	2' x 2' white ceiling tile w/ pinholes	5,600	SF	room 316, 312, 310, 307, 308	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
152	12 x 12 off white w/ beige & gray specks vft	720	SF	Room 319	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
152A	12 x 12 off white w/ beige & gray specks vft Mastic	720	SF	room 319	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
153	12 x 12 light blue streaked vft	302	SF	Room 330	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
153A	12 x 12 off white w/ beige & gray specks vft Mastic	302	SF	room 330	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
154	12 x 12 blue with blue streaks vft	45	SF	Women's bathroom @ 330	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
154A	12 x 12 blue with blue streaks vft Mastic	45	SF	Women's bathroom @ 330	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
155	drywall system (board, mud, tape)	300	SF	wall installed between 342 and 342A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
156	2 x 2 white ceiling tile with pinholes	20,000	SF	Rooms 300, 300A, 303, 305, 305A, 304 a-b-c-d & office, 302, 302A & office/storage room, 203, 208, 204, 210, 205, 206, 210A, 213, 214, 211	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
157	12 x 12 tan with white specks vft	225	SF	306 B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
157A	12 x 12 tan with white specks vft Mastic	225	SF	306 B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
158	cloth wire insulation	10	SF	Room 347	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
159	12 x 12 Blue with Dark Blue specs replacement vft	350	SF	room 107 (75), 109 (40), old vault conference room (144), 238 (80)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	2'x4' Dot Wave Ceiling Tile	2,000	SF	First Floor Corridor, Room 114, 212, 302 A - 1939 Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Taft High School

Unit 46311

Building ID 1580

Address 6545 W. Hurlburt St.

Chicago, IL, 60631

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
160	9 x 9 gray with white and black streaks vft	80	SF	storage room by 220	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
160A	9 x 9 gray with white black streaks vft Mastic	80	SF	storage room by 220	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
161	12 x 12 Cream vft	50	SF	Room 207, 212, 219 replacements	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
161A	12 x 12 cream vft Mastic	50	SF	Room 207, 212, 219 replacements	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
162	12 x 12 white with gold streaks vft	100	SF	Room 151	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
162A	12 x 12 white with gold streaks vft Mastic	100	SF	Room 151	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
163	Replacement Tiles - 12 x 12 white with gray streaks vft	35	SF	# 151	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
163A	Replacement Tiles - 12 x 12 white with gray streaks vft Mastic	35	SF	Room 151	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	1'x1' White Smooth Ceiling Tile	120	SF	Room 320 - 1939 Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	2'x4' White w/ Pin Holes Ceiling Tile			Room 246, 247, 250, 252, 253, 256, 264 - 1974 Building	No ACBM	MISC					
20	1'x1' White w/ Deep Grooves Ceiling Tile			Room 173 - 1974 Building	No ACBM	MISC					
21	1'x1' White w/ Small Holes Ceiling Tile			Serving Room, Kitchen, 151/183 Hallway - 1974 Building	No ACBM	MISC					
27	Black Table Tops		EA	Room 300, 302A, 305-307 - 1939 Building	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
31	Hardcoat Plaster	2,000	SF	Throughout - 1939 Building - Damage on 218 gym ceiling plaster, 222 gym ceiling, 228 gym walls, 239, 236, 347 , 125	Chrysotile	SURFACE	No	80	SF	5 ACBM with potential for significant damage	Follow O&M Plan
55	Drywall Joint Compound			Janitors Closets, Boys and Girls Toilets	No ACBM	MISC					
58	MJP E/F/V on Fiberglass Pipe Insulation	300	FITTING	Sprinkler Room, Chiller Room, W. Crawlspace, Carpenters Shop, Plenum Chamber - 1939 Building	Assumed	TSI	Yes	20	FITTING	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
61	MJP E/F/V on Fiberglass Pipe Insulation		EA	Sprinkler Room, Carpenter Shop, Basement Corridor - 1974 Building	No ACBM	TSI	Yes	10	EA	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
65	12" x 12" Brown w/ White Streaks VFT	890	SF	Room 342 - 1958 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	12" x 12" Brown w/ White Streaks VFT Mastic	890	SF	Room 342 - 1958 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	12" x 12" Light Gray w/ Dark Gray Specks VFT	3,571	SF	Rooms 342, 340, 341, 338, 339, 337, 336, 324 - 1958 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	12" x 12" Light Gray w/ Dark Gray Specks VFT Mastic	3,571	SF	Rooms 342, 340, 341, 338, 339, 337, 336, 324 - 1958 Building- 1958 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	2' x 4' White w/ Deep Grooves Ceiling Tile			Room 134, 239, 326 - 1958 Building	No ACBM	MISC					

Chicago Public Schools

School Taft High School

Unit 46311

Building ID 1580

Address 6545 W. Hurlburt St.

Chicago, IL, 60631

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
70	1' x 1' White w/ Deep Grooves Ceiling Tile			Gymnasium Lobby - 1958 Building	No ACBM	MISC					
71	MJP E/F/V on Fiberglass Pipe Insulation	20	FITTING	Fan Units, Unfinished Pipe Space, Rifle Range - 1958 Building	Assumed	TSI	Yes	20	FITTING	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
72	Hard Coat Plaster	10,000	SF	Throughout - 1958 Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	Exterior Window Glaze		LF	Exterior Windows - 1939 Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
74	Exterior Window Glaze		LF	Exterior Windows - 1958 Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
75	Exterior Window Glaze		LF	Exterior Windows - 1974 Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
76	Exterior Window Caulk		LF	Exterior Windows - 1939 Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
77	Exterior Window Caulk		LF	Exterior Windows - 1958 Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
78	Exterior Window Caulk		LF	Exterior Windows - 1974 Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
79	Interior Window Caulk		LF	Interior Windows - 1939 Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
80	Interior Window Glaze		LF	Interior Windows - 1939 Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
81	Interior Window Glaze		LF	Interior Windows - 1958 Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
82	Interior Window Glaze		LF	Interior Windows - 1974 Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
84	9"x9" Red VFT	10	SF	Stage South Stairwell - 1939 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
85	9"x9" Red VFT Mastic	10	SF	Stage South Stairwell - 1939 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
86	9"x9" Black VFT	10	SF	Stage South Stairwell - 1939 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
87	9"x9" Black VFT Mastic	10	SF	Stage South Stairwell - 1939 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
88	2"x18" Black VFT	36	SF	Stage South Stairwell - 1939 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
89	2"x18" Black VFT Mastic	36	SF	Stage South Stairwell - 1939 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
90	12"x12" Tan w/ Brown Streaks VFT	400	SF	121 Woodshop - 1939 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
91	12"x12" Tan w/ Brown Streaks VFT Mastic	400	SF	121 Woodshop - 1939 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
92	12"x12" Tan w/ Brown & White Streaks VFT ABATED			Room 117 - 1939 Building ABATED	Abated	MISC					
93	12"x12" Tan w/ Brown & White Streaks VFT Mastic ABATED			Room 117 - 1939 Building ABATED	Abated	MISC					
94	Brown Linoleum - NOT OBSERVED			2nd Floor Teachers Lounge - 1939 Building - NOT OBSERVED							
95	Brown Linoleum Mastic - NOT OBSERVED			2nd Floor Teachers Lounge - 1939 Building - NOT OBSERVED							
98	2'x4' Dot Wave Ceiling Tile	1,000	SF	Room 106, 112, 216, 300 - 1939 Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99	12"x12" Off White w/ Gray Streaks VFT	2,000	SF	Rooms 214, 216, 300, 300A, and 300L; 1st through 3rd Floor South Corridor - 1939 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Taft High School

Unit 46311

Building ID 1580

Address 6545 W. Hurlburt St.

Chicago, IL, 60631

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
HA-1000	5' x 2.5' ceiling tile with random pinholes	10,000	SF	throughout - 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1001	Black table and counter tops ABATED			Rooms 300, 302, 302A, 305, 308, 310, 312, 313, 316 ABATED	Abated	MISC					
HA-1002	Gray lab table and counter tops ABATED			Room 183 - 1974 Bldg. ABATED	Abated	MISC					
HA-1003	MJP E/V/F on Cardboard Pipe Insulation (Paper Wrap on Insulation)	155	FITTING	Chase Behind Room 134	Assumed	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
HA-1004	Gray transite panel - ABATED			Exhaust hood in Room 302A - ABATED	Abated	MISC					
HA-1005	Beige Linoleum	3,300	SF	Rooms 311, 313, 213, & office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1006	Grey w/ White Streaks Linoleum	3,400	SF	Rooms 302, 303, 305, 307, 308, 310, 312, 316, 213, 211 - Material replaced in 213, with HA 1005	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1007	12"x12" White w/Gray Streaks VFT	600	SF	Room 117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1008	12"x12" White w/Gray Streaks VFT Mastic	600	SF	Room 117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Taft High School

Unit 46311

Building ID 1580

Address 6545 W. Hurlburt St.

Chicago, IL, 60631

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

Review Date	10/1/2025
Manager Planner Name	Arturo Saenz
100-04019	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
03	
04	
05	
06	
07	
08	
09	
10	
100	
1005A	
1006A	
101	
102	
103	
104	
105	
106	
107	

Chicago Public Schools

School Taft High School

Unit 46311

Building ID 1580

Address 6545 W. Hurlburt St.

Chicago, IL, 60631

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
108	
109	
11	
110	
111	
112	
113	
114	
115	
116	
117	
118	
119	
12	
120	
121	
122	
123	
124	
125	
126	
127	
128	
129	
13	
130	
131	

Chicago Public Schools

School Taft High School

Unit 46311

Building ID 1580

Address 6545 W. Hurlburt St.

Chicago, IL, 60631

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
132	
132 A	
133	
134	
135	
136	
137	
138	
139	
14	
140	
141	
142	
143	
143A	
144	
145	
146	
147	
148	
149	
149A	
150	
150A	
151	
152	
152A	

Chicago Public Schools

School Taft High School

Unit 46311

Building ID 1580

Address 6545 W. Hurlburt St.

Chicago, IL, 60631

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
153	
153A	
154	
154A	
155	
156	
157	
157A	
158	
159	
16	
160	
160A	
161	
161A	
162	
162A	
163	
163A	
17	
19	
20	
21	
27	
31	
55	
58	Repair Damaged ACM, maintain in Good condition

Chicago Public Schools

School Taft High School

Unit 46311

Building ID 1580

Address 6545 W. Hurlburt St.

Chicago, IL, 60631

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
61	Repair Damaged ACM, maintain in Good condition
65	
66	
67	
68	
69	
70	
71	Repair Damaged ACM, maintain in Good condition
72	
73	
74	
75	
76	
77	
78	
79	
80	
81	
82	
84	
85	
86	
87	
88	
89	
90	
91	

Chicago Public Schools

School Taft High School

Unit 46311

Building ID 1580

Address 6545 W. Hurlburt St.

Chicago, IL, 60631

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
92	
93	
94	
95	
98	
99	
HA-1000	
HA-1001	
HA-1002	
HA-1003	
HA-1004	
HA-1005	
HA-1006	
HA-1007	
HA-1008	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Specialty Consulting, Inc.

2025 AHERA REINSPECTION

Chicago Public Schools

Specialty Consulting, Inc.

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	01		
MATERIAL DESCRIPTION:	12"x12" White w/ Beige Speckles VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement Break Room - 1939 Building		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **12"x12" White w/ Beige Speckles VFT**

MATERIAL LOCATION: **Basement Break Room - 1939 Building**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	02		
MATERIAL DESCRIPTION:	12"x12" White w/ Gray Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 5. ACBM with potential for significant damage

DAMAGE REASON:	Physical Damage Deterioration		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Damage in rooms 111, 112, 112A, 113, 115 offices, 101, 106, 107, 108, 203, 205, 228, 228E, 221, 219, 217, 207, 306B - 1939 Building		
MATERIAL QUANTITY:	34500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	damage - cracks chips, in vft		

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **02**

MATERIAL DESCRIPTION: **12"x12" White w/ Gray Streaks VFT**

MATERIAL LOCATION: **Damage in rooms 111, 112, 112A, 113, 115 offices, 101, 106, 107, 108, 203, 205, 228, 228E, 221, 219, 217, 207, 306B - 1939 Building**

MATERIAL QUANTITY: **34500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **200** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03		
MATERIAL DESCRIPTION:	12"x12" Brown w/ White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 119-121 Wood Shop - 1939 Building		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **12"x12" Brown w/ White Streaks VFT**

MATERIAL LOCATION: **Room 119-121 Wood Shop - 1939 Building**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	04		
MATERIAL DESCRIPTION:	12"x12" White w/ Beige Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineers Office Room 321 - 1939 Building		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **12"x12" White w/ Beige Streaks VFT**

MATERIAL LOCATION: **Engineers Office Room 321 - 1939 Building**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05		
MATERIAL DESCRIPTION:	12"x12" White w/ Beige Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office Room 321 - 1939 Building		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **12"x12" White w/ Beige Streaks VFT Mastic**

MATERIAL LOCATION: **Engineer's Office Room 321 - 1939 Building**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06		
MATERIAL DESCRIPTION:	9"x9" Light Brown w/ Beige Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office Hallway - 1939 Building		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **9"x9" Light Brown w/ Beige Streaks VFT**

MATERIAL LOCATION: **Engineer's Office Hallway - 1939 Building**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07		
MATERIAL DESCRIPTION:	12"x12" Dark Gray w/ White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	First Floor Corridor by Mens and Womens Toilet - 1974 Building		
MATERIAL QUANTITY:	98	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **07**

MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ White Streaks VFT**

MATERIAL LOCATION: **First Floor Corridor by Mens and Womens Toilet - 1974 Building**

MATERIAL QUANTITY: **98** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08		
MATERIAL DESCRIPTION:	12"x12" Light Gray w/ Gray Speckles VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout - 1974 Building		
MATERIAL QUANTITY:	98	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **12"x12" Light Gray w/ Gray Speckles VFT**

MATERIAL LOCATION: **Throughout - 1974 Building**

MATERIAL QUANTITY: **98** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09		
MATERIAL DESCRIPTION:	12"x12" Off White w/ Tan Specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 146, 147, 157A, 155, 159, 160, 161, 173, 175, 176, 247, 255, 247, 2nd Floor Hallway - 1974 Building		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **12"x12" Off White w/ Tan Specks VFT**

MATERIAL LOCATION: **Rooms 146, 147, 157A, 155, 159, 160, 161, 173, 175, 176, 247, 255, 247, 2nd Floor Hallway - 1974 Building**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	12"x12" White w/ Gold Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout - 1974 Building		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **12"x12" White w/ Gold Streaks VFT**

MATERIAL LOCATION: **Throughout - 1974 Building**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	100		
MATERIAL DESCRIPTION:	12"x12" Off White w/ Gray Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 214, 216, 300, 300A, and 300L; 1st through 3rd Floor South Corridor - 1939 Building		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **100**

MATERIAL DESCRIPTION: **12"x12" Off White w/ Gray Streaks VFT Mastic**

MATERIAL LOCATION: **Rooms 214, 216, 300, 300A, and 300L; 1st through 3rd Floor South Corridor - 1939 Building**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 101

MATERIAL DESCRIPTION: 2'x4' White w/ Deep Grooves Ceiling Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 173, 174 - 1974 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **101**

MATERIAL DESCRIPTION: **2'x4' White w/ Deep Grooves Ceiling Tile**

MATERIAL LOCATION: **Room 173, 174 - 1974 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	102		
MATERIAL DESCRIPTION:	12" x 12" Brown w/ Black Specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 155, 159, 160, 161, 173, 175, 176, 247, 255, Kitchen Office - 1974 Building		
MATERIAL QUANTITY:	3200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **102**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ Black Specks VFT**

MATERIAL LOCATION: **Rooms 155, 159, 160, 161, 173, 175, 176, 247, 255, Kitchen Office - 1974 Building**

MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	103		
MATERIAL DESCRIPTION:	12" x 12" Brown w/ Black Specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 155, 159, 160, 161, 173, 175, 176, 247, 255, Kitchen Office - 1974 Building		
MATERIAL QUANTITY:	3200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **103**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ Black Specks VFT Mastic**

MATERIAL LOCATION: **Rooms 155, 159, 160, 161, 173, 175, 176, 247, 255, Kitchen Office - 1974 Building**

MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	104		
MATERIAL DESCRIPTION:	12" x 12" White w/ Gray Specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 207, Teachers Lounge - 1974 Building		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **104**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Specks VFT**

MATERIAL LOCATION: **Room 207, Teachers Lounge - 1974 Building**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	105		
MATERIAL DESCRIPTION:	12" x 12" White w/ Gray Specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 207, Teachers Lounge - 1974 Building		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **105**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Specks VFT Mastic**

MATERIAL LOCATION: **Room 207, Teachers Lounge - 1974 Building**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	106		
MATERIAL DESCRIPTION:	12" x 12" Off White w/ Beige Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 149, 150, 152, 154, Main Office - 1974 Building		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **106**

MATERIAL DESCRIPTION: **12" x 12" Off White w/ Beige Streaks VFT**

MATERIAL LOCATION: **Room 149, 150, 152, 154, Main Office - 1974 Building**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	107		
MATERIAL DESCRIPTION:	12" x 12" Off White w/ Beige Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 149, 150, 152, 154, Main Office - 1974 Building		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **107**

MATERIAL DESCRIPTION: **12" x 12" Off White w/ Beige Streaks VFT Mastic**

MATERIAL LOCATION: **Room 149, 150, 152, 154, Main Office - 1974 Building**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ White & Black Specks VFT - NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 149, 158-160 - 1974 Building NOT OBSERVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/04/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **108**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ White & Black Specks VFT - NOT OBSERVED**

MATERIAL LOCATION: **Room 149, 158-160 - 1974 Building NOT OBSERVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ White & Black Specks VFT Mastic- NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 149, 158-160 - 1974 Building NOT OBSERVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/04/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **109**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ White & Black Specks VFT Mastic- NOT OBSERVED**

MATERIAL LOCATION: **Room 149, 158-160 - 1974 Building NOT OBSERVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	12"x12" Light Brown w/ White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 151, 152, 156, 153, 171, 184, 256, 263, 264 - 1974 Building		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **12"x12" Light Brown w/ White Streaks VFT**

MATERIAL LOCATION: **Rooms 151, 152, 156, 153, 171, 184, 256, 263, 264 - 1974 Building**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	110		
MATERIAL DESCRIPTION:	12" x 12" White w/ Beige Speckles VFT Mastic - Abated		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 311, Break Room - 1939 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **110**

MATERIAL DESCRIPTION: **12" x 12" White w/ Beige Speckles VFT Mastic - Abated**

MATERIAL LOCATION: **Room 311, Break Room - 1939 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	111		
MATERIAL DESCRIPTION:	12"x12" White w/ Gray Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Building (See Hatching Maps) - 1939 Building		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **111**

MATERIAL DESCRIPTION: **12"x12" White w/ Gray Streaks VFT Mastic**

MATERIAL LOCATION: **Throughout Building (See Hatching Maps) - 1939 Building**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	112		
MATERIAL DESCRIPTION:	12"x12" Brown w/ White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 119-121 Wood Shop - 1939 Building		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **112**

MATERIAL DESCRIPTION: **12"x12" Brown w/ White Streaks VFT Mastic**

MATERIAL LOCATION: **Room 119-121 Wood Shop - 1939 Building**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	113		
MATERIAL DESCRIPTION:	12"x12" Brown w/ Beige Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 321 - 1939 Building		
MATERIAL QUANTITY:	650	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **113**

MATERIAL DESCRIPTION: **12"x12" Brown w/ Beige Streaks VFT Mastic**

MATERIAL LOCATION: **Room 321 - 1939 Building**

MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	114		
MATERIAL DESCRIPTION:	12"x12" White w/ Beige Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 321 - 1939 Building		
MATERIAL QUANTITY:	650	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **114**

MATERIAL DESCRIPTION: **12"x12" White w/ Beige Streaks VFT Mastic**

MATERIAL LOCATION: **Room 321 - 1939 Building**

MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	115		
MATERIAL DESCRIPTION:	9"x9" Light Brown w/ Beige Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office Hallway - 1939 Building		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **115**

MATERIAL DESCRIPTION: **9"x9" Light Brown w/ Beige Streaks VFT**

MATERIAL LOCATION: **Engineer's Office Hallway - 1939 Building**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	116		
MATERIAL DESCRIPTION:	12"x12" Dark Gray w/ White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	First Floor Corridor by Mens and Womens Toilet - 1974 Building		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **116**

MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ White Streaks VFT Mastic**

MATERIAL LOCATION: **First Floor Corridor by Mens and Womens Toilet - 1974 Building**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	117		
MATERIAL DESCRIPTION:	12"x12" Light Gray w/ Gray Speckles VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout (See Hatching Maps) - 1974 Building		
MATERIAL QUANTITY:	23465	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **117**

MATERIAL DESCRIPTION: **12"x12" Light Gray w/ Gray Speckles VFT Mastic**

MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1974 Building**

MATERIAL QUANTITY: **23465** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	118		
MATERIAL DESCRIPTION:	12"x12" Off White w/ Tan Specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 146, 147, 157A, 155, 159, 160, 161, 173, 175, 176, 247, 255, 247, 2nd Floor Hallway - 1974 Building		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **118**

MATERIAL DESCRIPTION: **12"x12" Off White w/ Tan Specks VFT Mastic**

MATERIAL LOCATION: **Rooms 146, 147, 157A, 155, 159, 160, 161, 173, 175, 176, 247, 255, 247, 2nd Floor Hallway - 1974 Building**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	119		
MATERIAL DESCRIPTION:	12"x12" White w/ Gold Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout - 1974 Building		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **119**

MATERIAL DESCRIPTION: **12"x12" White w/ Gold Streaks VFT Mastic**

MATERIAL LOCATION: **Throughout - 1974 Building**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12		
MATERIAL DESCRIPTION:	12"x12" Yellow w/ White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 151 (replaced with 12 x 12 white w/ gold vft & white w/ gray vft), 153, 171, 184, 256, 283 - 1974 Building		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	damaged vft replaced with new tiles		

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **12"x12" Yellow w/ White Streaks VFT**

MATERIAL LOCATION: **Rooms 151 (replaced with 12 x 12 white w/ gold vft & white w/ gray vft), 153, 171, 184, 256, 283 - 1974 Building**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	120		
MATERIAL DESCRIPTION:	12"x12" Light Brown w/ White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 151, 152, 156, 153, 171, 184, 256, 263, 264 - 1974 Building		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **120**

MATERIAL DESCRIPTION: **12"x12" Light Brown w/ White Streaks VFT Mastic**

MATERIAL LOCATION: **Rooms 151, 152, 156, 153, 171, 184, 256, 263, 264 - 1974 Building**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	121		
MATERIAL DESCRIPTION:	12"x12" Yellow w/ White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 151 (replaced with 12 x 12 white w/ gold vft & white w/ gray vft), 153, 171, 184, 256, 263 - 1974 Building**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS: **damagde vft replaced with new tiles**

Inspector's Signature:



Date: **09/04/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **121**

MATERIAL DESCRIPTION: **12"x12" Yellow w/ White Streaks VFT Mastic**

MATERIAL LOCATION: **Room 151 (replaced with 12 x 12 white w/ gold vft & white w/ gray vft), 153, 171, 184, 256, 263 - 1974 Building**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	122		
MATERIAL DESCRIPTION:	12"x12" Green Speckles VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom, Lunchroom W. Storeroom - 1974 Building		
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **122**

MATERIAL DESCRIPTION: **12"x12" Green Speckles VFT Mastic**

MATERIAL LOCATION: **Lunchroom, Lunchroom W. Storeroom - 1974 Building**

MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	123		
MATERIAL DESCRIPTION:	12"x12" Yellow Speckled VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom, Counseling Offices - 1974 Building		
MATERIAL QUANTITY:	3800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **123**

MATERIAL DESCRIPTION: **12"x12" Yellow Speckled VFT Mastic**

MATERIAL LOCATION: **Lunchroom, Counseling Offices - 1974 Building**

MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 124

MATERIAL DESCRIPTION: 1' x 1' White w/ Deep Grooves Ceiling Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 187 - 1974 Bldg.

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **124**

MATERIAL DESCRIPTION: **1' x 1' White w/ Deep Grooves Ceiling Tile**

MATERIAL LOCATION: **Room 187 - 1974 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	125		
MATERIAL DESCRIPTION:	12" x 12" White w/ Light Green Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Delamination		
HISTORICAL RESPONSE ACTION:	Remove		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 5. ACBM with potential for significant damage

DAMAGE REASON:	Delamination Physical Damage		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 306 (306A & 306B) - 1939 Building		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	classroom 306 split into two rooms 306A and 306B		

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **125**

MATERIAL DESCRIPTION: **12" x 12" White w/ Light Green Streaks VFT**

MATERIAL LOCATION: **Room 306 (306A & 306B) - 1939 Building**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	126		
MATERIAL DESCRIPTION:	12" x 12" White w/ Light Green Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Deterioration		
HISTORICAL RESPONSE ACTION:	Remove		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 5. ACBM with potential for significant damage

DAMAGE REASON:	Deterioration Physical Damage		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 306 (306A and 306B) - 1939 Building		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	classroom 306 split into two rooms 306A and 306B		

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **126**

MATERIAL DESCRIPTION: **12" x 12" White w/ Light Green Streaks VFT Mastic**

MATERIAL LOCATION: **Room 306 (306A and 306B) - 1939 Building**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 127

MATERIAL DESCRIPTION: Beige w/ Purple Streaks Linoleum

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 213, 213A - 1939 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **127**

MATERIAL DESCRIPTION: **Beige w/ Purple Streaks Linoleum**

MATERIAL LOCATION: **Room 213, 213A - 1939 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 128

MATERIAL DESCRIPTION: Beige w/ Purple Streaks Linoleum Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 213, 213A - 1939 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **128**

MATERIAL DESCRIPTION: **Beige w/ Purple Streaks Linoleum Mastic**

MATERIAL LOCATION: **Room 213, 213A - 1939 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 129
MATERIAL DESCRIPTION: 2' x 4' Dot Ceiling Tile
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 213, 213A - 1939 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **129**

MATERIAL DESCRIPTION: **2' x 4' Dot Ceiling Tile**

MATERIAL LOCATION: **Room 213, 213A - 1939 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	12"x12" Green Speckles VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom, Lunchroom W. Storeroom - 1974 Building		
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **12"x12" Green Speckles VFT**

MATERIAL LOCATION: **Lunchroom, Lunchroom W. Storeroom - 1974 Building**

MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	130		
MATERIAL DESCRIPTION:	12" x 12" Dark Gray VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 140, 142 - 1958 Building		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **130**

MATERIAL DESCRIPTION: **12" x 12" Dark Gray VFT**

MATERIAL LOCATION: **Room 140, 142 - 1958 Building**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	131		
MATERIAL DESCRIPTION:	12" x 12" Dark Gray VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 140, 142 - 1958 Building		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **131**

MATERIAL DESCRIPTION: **12" x 12" Dark Gray VFT Mastic**

MATERIAL LOCATION: **Room 140, 142 - 1958 Building**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 132

MATERIAL DESCRIPTION: 12" x 12" Beige w/Gray & Tan Streaks VFT ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 300, 302, 308, 310, 311-313, 316 - 1939 Building ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **132**

MATERIAL DESCRIPTION: **12" x 12" Beige w/Gray & Tan Streaks VFT ABATED**

MATERIAL LOCATION: **Rooms 300, 302, 308, 310, 311-313, 316 - 1939 Building ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 132 A

MATERIAL DESCRIPTION: 12" x 12" Beige w/Gray & Tan Streaks VFT Mastic ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Rooms: 300, 302, 308, 310, 311-313, 316 - 1939 Building ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **132 A**

MATERIAL DESCRIPTION: **12" x 12" Beige w/Gray & Tan Streaks VFT Mastic ABATED**

MATERIAL LOCATION: **Rooms: 300, 302, 308, 310, 311-313, 316 - 1939 Building ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	133		
MATERIAL DESCRIPTION:	Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Choir Room, Band Room, Library, Main Office, 163, 164, 162, 190, 172, 174 - 1974 Bldg.		
MATERIAL QUANTITY:	12000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **133**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Choir Room, Band Room, Library, Main Office, 163, 164, 162, 190, 172, 174 - 1974 Bldg.**

MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	134		
MATERIAL DESCRIPTION:	Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 206, 208 and 210 - 1939 Bldg.		
MATERIAL QUANTITY:	2050	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **134**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Rooms 206, 208 and 210 - 1939 Bldg.**

MATERIAL QUANTITY: **2050** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	135		
MATERIAL DESCRIPTION:	Terrazo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Stairwells - 1974 Bldg.		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **135**

MATERIAL DESCRIPTION: **Terrazo**

MATERIAL LOCATION: **Stairwells - 1974 Bldg.**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	136		
MATERIAL DESCRIPTION:	Terrazo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Halls - 1939 Bldg.		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **136**

MATERIAL DESCRIPTION: **Terrazo**

MATERIAL LOCATION: **Halls - 1939 Bldg.**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	137		
MATERIAL DESCRIPTION:	Terrazo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym Lobby - 1958 Bldg.		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **137**

MATERIAL DESCRIPTION: **Terrazo**

MATERIAL LOCATION: **Gym Lobby - 1958 Bldg.**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	138		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation (Paper Wrap on Insulation)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Chase Behind Room 134, First Floor Women's Toilet 107A (Above Plaster ceiling), Basement Chiller Room**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/04/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **138**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation (Paper Wrap on Insulation)**

MATERIAL LOCATION: **Chase Behind Room 134, First Floor Women's Toilet 107A (Above Plaster ceiling), Basement Chiller Room**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	139		
MATERIAL DESCRIPTION:	MJP E/V/F on Cardboard Pipe Insulation (Paper Wrap on Pipe Insulation)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Chase Behind Room 134**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: MATERIAL UNITS: **FITTING**

COMMENTS:

Inspector's Signature:



Date: **09/04/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BULDING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **139**

MATERIAL DESCRIPTION: **MJP E/V/F on Cardboard Pipe Insulation (Paper Wrap on Pipe Insulation)**

MATERIAL LOCATION: **Chase Behind Room 134**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	12"x12" Yellow Speckled VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom, Counseling Offices - 1974 Building		
MATERIAL QUANTITY:	3400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12"x12" Yellow Speckled VFT**

MATERIAL LOCATION: **Lunchroom, Counseling Offices - 1974 Building**

MATERIAL QUANTITY: **3400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	140		
MATERIAL DESCRIPTION:	2'x4' Ceiling tile w/ grooves		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout - 1939 Building		
MATERIAL QUANTITY:	33000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **140**

MATERIAL DESCRIPTION: **2'x4' Ceiling tile w/ grooves**

MATERIAL LOCATION: **Throughout - 1939 Building**

MATERIAL QUANTITY: **33000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	141		
MATERIAL DESCRIPTION:	Carpet MASTIC		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	174, 172, corridor both sides of exit #4 - 1974 Bldg.		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **141**

MATERIAL DESCRIPTION: **Carpet MASTIC**

MATERIAL LOCATION: **174, 172, corridor both sides of exit #4 - 1974 Bldg.**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	142		
MATERIAL DESCRIPTION:	Carpet MASTIC		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium between the isles, 230, 330 - 1958 Bldg.		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **142**

MATERIAL DESCRIPTION: **Carpet MASTIC**

MATERIAL LOCATION: **Auditorium between the isles, 230, 330 - 1958 Bldg.**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	143		
MATERIAL DESCRIPTION:	12"x12" light gray w/ gray streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	damage in rooms 216, 217, 212, 203		
MATERIAL QUANTITY:	27900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **143**

MATERIAL DESCRIPTION: **12"x12" light gray w/ gray streaks VFT**

MATERIAL LOCATION: **damage in rooms 216, 217, 212, 203**

MATERIAL QUANTITY: **27900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **69** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	143A		
MATERIAL DESCRIPTION:	12"x12" light gray w/ gray streaks VFT MASTIC		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	damage in rooms 216, 217, 212, 203		
MATERIAL QUANTITY:	27900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **143A**

MATERIAL DESCRIPTION: **12"x12" light gray w/ gray streaks VFT MASTIC**

MATERIAL LOCATION: **damage in rooms 216, 217, 212, 203**

MATERIAL QUANTITY: **27900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **69** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	144		
MATERIAL DESCRIPTION:	Tectum panels		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 218, 222, 126		
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **144**

MATERIAL DESCRIPTION: **Tectum panels**

MATERIAL LOCATION: **Rooms 218, 222, 126**

MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	145		
MATERIAL DESCRIPTION:	12" x 12" Blue w/ Specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 121 - 1939 Bldg.		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **145**

MATERIAL DESCRIPTION: **12" x 12" Blue w/ Specks VFT**

MATERIAL LOCATION: **Room 121 - 1939 Bldg.**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	146		
MATERIAL DESCRIPTION:	12" x 12" Blue w/ Specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 121 - 1939 Bldg.		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **146**

MATERIAL DESCRIPTION: **12" x 12" Blue w/ Specks VFT Mastic**

MATERIAL LOCATION: **Room 121 - 1939 Bldg.**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	147		
MATERIAL DESCRIPTION:	12" x 12" Light Blue w/ Specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 142, 220 - 1958 Bldg.		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **147**

MATERIAL DESCRIPTION: **12" x 12" Light Blue w/ Specks VFT**

MATERIAL LOCATION: **Room 142, 220 - 1958 Bldg.**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	148		
MATERIAL DESCRIPTION:	12" x 12" Light Blue VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 142, 220 - 1958 Bldg		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **148**

MATERIAL DESCRIPTION: **12" x 12" Light Blue VFT Mastic**

MATERIAL LOCATION: **Room 142, 220 - 1958 Bldg**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	2'x4' Dot Wave Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	First Floor Corridor, Room 114, 212, 302 A - 1939 Building		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **2'x4' Dot Wave Ceiling Tile**

MATERIAL LOCATION: **First Floor Corridor, Room 114, 212, 302 A - 1939 Building**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	1'x1' White Smooth Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 320 - 1939 Building		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **1'x1' White Smooth Ceiling Tile**

MATERIAL LOCATION: **Room 320 - 1939 Building**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **2'x4' White w/ Pin Holes Ceiling Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 246, 247, 250, 252, 253, 256, 264 - 1974 Building**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **09/04/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **2'x4' White w/ Pin Holes Ceiling Tile**

MATERIAL LOCATION: **Room 246, 247, 250, 252, 253, 256, 264 - 1974 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 20

MATERIAL DESCRIPTION: 1'x1' White w/ Deep Grooves Ceiling Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 173 - 1974 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **1'x1' White w/ Deep Grooves Ceiling Tile**

MATERIAL LOCATION: **Room 173 - 1974 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 21

MATERIAL DESCRIPTION: 1'x1' White w/ Small Holes Ceiling Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Serving Room, Kitchen, 151/183 Hallway - 1974 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **1'x1' White w/ Small Holes Ceiling Tile**

MATERIAL LOCATION: **Serving Room, Kitchen, 151/183 Hallway - 1974 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	Black Table Tops		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW
MATERIAL LOCATION:	Room 300, 302A, 305-307 - 1939 Building
MATERIAL QUANTITY:	MATERIAL UNITS: EA
DAMAGE QUANTITY:	DAMAGE UNITS: EA
COMMENTS:	

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: 27

MATERIAL DESCRIPTION: **Black Table Tops**

MATERIAL LOCATION: Room 300, 302A, 305-307 - 1939 Building

MATERIAL QUANTITY: _____ **MATERIAL UNITS:** _____ **EA** _____

DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31		
MATERIAL DESCRIPTION:	Hardcoat Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 5. ACBM with potential for significant damage

DAMAGE REASON:	Water Physical Damage		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Throughout - 1939 Building - Damage on 218 gym ceiling plaster, 222 gym ceiling, 228 gym walls, 239, 236, 347 , 125		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Hardcoat Plaster**

MATERIAL LOCATION: **Throughout - 1939 Building - Damage on 218 gym ceiling plaster, 222 gym ceiling, 228 gym walls, 239, 236, 347 , 125**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **80** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 55
MATERIAL DESCRIPTION: Drywall Joint Compound
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Janitors Closets, Boys and Girls Toilets - 1974 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Drywall Joint Compound**

MATERIAL LOCATION: **Janitors Closets, Boys and Girls Toilets - 1974 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	MJP E/F/V on Fiberglass Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	1 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:	Air Erosion/Flow		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Sprinkler Room, Chiller Room, W. Crawlspace, Carpenters Shop, Plenum Chamber - 1939 Building		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:		DAMAGE UNITS:	FITTING
COMMENTS:	open ends on previous repairs to TSI - Damage throughout - see hatching map - boiler room, motor room, tunnels, tank room		

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: 58

MATERIAL DESCRIPTION: MJP E/F/V on Fiberglass Pipe Insulation

MATERIAL LOCATION: Sprinkler Room, Chiller Room, W. Crawlspace, Carpenters Shop, Plenum Chamber - 1939 Building

MATERIAL QUANTITY: 300 MATERIAL UNITS: FITTING

DAMAGE QUANTITY: 20 DAMAGE UNITS: FITTING

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Repair Damaged ACM, maintain in Good condition

Management Planner's Signature:



Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	61		
MATERIAL DESCRIPTION:	MJP E/F/V on Fiberglass Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	1		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:	Air Erosion/Flow		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Sprinkler Room, Carpenter Shop, Basement Corridor - 1974 Building		
MATERIAL QUANTITY:	MATERIAL UNITS:	EA	
DAMAGE QUANTITY:	DAMAGE UNITS:	EA	
COMMENTS:	Material quantity is unknown - material identified as non ACBM in 3 year report. open ends on previous repairs to TSI		

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: 61

MATERIAL DESCRIPTION: MJP E/F/V on Fiberglass Pipe Insulation

MATERIAL LOCATION: Sprinkler Room, Carpenter Shop, Basement Corridor - 1974 Building

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____ EA

DAMAGE QUANTITY: **10** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Repair Damaged ACM, maintain in Good condition

Management Planner's Signature:



Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	65		
MATERIAL DESCRIPTION:	12" x 12" Brown w/ White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 342 - 1958 Building		
MATERIAL QUANTITY:	890	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ White Streaks VFT**

MATERIAL LOCATION: **Room 342 - 1958 Building**

MATERIAL QUANTITY: **890** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	66		
MATERIAL DESCRIPTION:	12" x 12" Brown w/ White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 342 - 1958 Building		
MATERIAL QUANTITY:	890	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ White Streaks VFT Mastic**

MATERIAL LOCATION: **Room 342 - 1958 Building**

MATERIAL QUANTITY: **890** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	67		
MATERIAL DESCRIPTION:	12" x 12" Light Gray w/ Dark Gray Specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 342, 340, 341, 338, 339, 337, 336, 324 - 1958 Building		
MATERIAL QUANTITY:	3571	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Dark Gray Specks VFT**

MATERIAL LOCATION: **Rooms 342, 340, 341, 338, 339, 337, 336, 324 - 1958 Building**

MATERIAL QUANTITY: **3571** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	68		
MATERIAL DESCRIPTION:	12" x 12" Light Gray w/ Dark Gray Specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 342, 340, 341, 338, 339, 337, 336, 324 - 1958 Building- 1958 Building		
MATERIAL QUANTITY:	3571	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Added locations & removed throughout building		

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Dark Gray Specks VFT Mastic**

MATERIAL LOCATION: **Rooms 342, 340, 341, 338, 339, 337, 336, 324 - 1958 Building- 1958 Building**

MATERIAL QUANTITY: **3571** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **2' x 4' White w/ Deep Grooves Ceiling Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 134, 239, 326 - 1958 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/04/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **2' x 4' White w/ Deep Grooves Ceiling Tile**

MATERIAL LOCATION: **Room 134, 239, 326 - 1958 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **1' x 1' White w/ Deep Grooves Ceiling Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gymnasium Lobby - 1958 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/04/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **1' x 1' White w/ Deep Grooves Ceiling Tile**

MATERIAL LOCATION: **Gymnasium Lobby - 1958 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	71		
MATERIAL DESCRIPTION:	MJP E/F/V on Fiberglass Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	1 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:	Air Erosion/Flow		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Fan Units, Unfinished Pipe Space, Rifle Range - 1958 Building		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:		DAMAGE UNITS:	FITTING
COMMENTS:	Damage throughout - see cross hatch drawings - fan units, air tunnels, supply ducts - open ends on previous repairs to TSI		

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Fan Units, Unfinished Pipe Space, Rifle Range - 1958 Building**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **20** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Repair Damaged ACM, maintain in Good condition

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	72		
MATERIAL DESCRIPTION:	Hard Coat Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout - 1958 Building		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **Hard Coat Plaster**

MATERIAL LOCATION: **Throughout - 1958 Building**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	73		
MATERIAL DESCRIPTION:	Exterior Window Glaze		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Exterior Windows - 1939 Building**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/04/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: 73

MATERIAL DESCRIPTION: **Exterior Window Glaze**

MATERIAL LOCATION: **Exterior Windows - 1939 Building**

MATERIAL QUANTITY:

MATERIAL UNITS: LF

DAMAGE QUANTITY: 0

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	74		
MATERIAL DESCRIPTION:	Exterior Window Glaze		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Exterior Windows - 1958 Building**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/04/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: 74

MATERIAL DESCRIPTION: **Exterior Window Glaze**

MATERIAL LOCATION: **Exterior Windows - 1958 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY: 0

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	75		
MATERIAL DESCRIPTION:	Exterior Window Glaze		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Exterior Windows - 1974 Building**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/04/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: 75

MATERIAL DESCRIPTION: Exterior Window Glaze

MATERIAL LOCATION: Exterior Windows - 1974 Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY: 0

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	76		
MATERIAL DESCRIPTION:	Exterior Window Caulk		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Exterior Windows - 1939 Building**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/04/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: 76

MATERIAL DESCRIPTION: Exterior Window Caulk

MATERIAL LOCATION: Exterior Windows - 1939 Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY: 0

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	77		
MATERIAL DESCRIPTION:	Exterior Window Caulk		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Exterior Windows - 1958 Building**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/04/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: 77

MATERIAL DESCRIPTION: Exterior Window Caulk

MATERIAL LOCATION: Exterior Windows - 1958 Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY: 0

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	78		
MATERIAL DESCRIPTION:	Exterior Window Caulk		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Exterior Windows - 1974 Building**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/04/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: 78

MATERIAL DESCRIPTION: Exterior Window Caulk

MATERIAL LOCATION: Exterior Windows - 1974 Building

MATERIAL QUANTITY:

MATERIAL UNITS: LF

DAMAGE QUANTITY: 0

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	79		
MATERIAL DESCRIPTION:	Interior Window Caulk		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Interior Windows - 1939 Building**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/04/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: 79

MATERIAL DESCRIPTION: Interior Window Caulk

MATERIAL LOCATION: **Interior Windows - 1939 Building**

MATERIAL QUANTITY:

MATERIAL UNITS: LF

DAMAGE QUANTITY: 0

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	80		
MATERIAL DESCRIPTION:	Interior Window Glaze		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW
MATERIAL LOCATION:	Interior Windows - 1939 Building
MATERIAL QUANTITY:	MATERIAL UNITS: LF
DAMAGE QUANTITY:	DAMAGE UNITS: LF
COMMENTS:	

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: 80

MATERIAL DESCRIPTION: **Interior Window Glaze**

MATERIAL LOCATION: **Interior Windows - 1939 Building**

MATERIAL QUANTITY:

MATERIAL UNITS: LF

DAMAGE QUANTITY: 0

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	81		
MATERIAL DESCRIPTION:	Interior Window Glaze		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Interior Windows - 1958 Building**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/04/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: 81

MATERIAL DESCRIPTION: **Interior Window Glaze**

MATERIAL LOCATION: **Interior Windows - 1958 Building**

MATERIAL QUANTITY:

MATERIAL UNITS: LF

DAMAGE QUANTITY: 0

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	82		
MATERIAL DESCRIPTION:	Interior Window Glaze		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Interior Windows - 1974 Building**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **09/04/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: 82

MATERIAL DESCRIPTION: **Interior Window Glaze**

MATERIAL LOCATION: **Interior Windows - 1974 Building**

MATERIAL QUANTITY:

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: 0

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	84		
MATERIAL DESCRIPTION:	9"x9" Red VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Stage South Stairwell - 1939 Building		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **9"x9" Red VFT**

MATERIAL LOCATION: **Stage South Stairwell - 1939 Building**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	85		
MATERIAL DESCRIPTION:	9"x9" Red VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Stage South Stairwell - 1939 Building		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **85**

MATERIAL DESCRIPTION: **9"x9" Red VFT Mastic**

MATERIAL LOCATION: **Stage South Stairwell - 1939 Building**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	86		
MATERIAL DESCRIPTION:	9"x9" Black VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Stage South Stairwell - 1939 Building		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **86**

MATERIAL DESCRIPTION: **9"x9" Black VFT**

MATERIAL LOCATION: **Stage South Stairwell - 1939 Building**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	87		
MATERIAL DESCRIPTION:	9"x9" Black VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Stage South Stairwell - 1939 Building		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **87**

MATERIAL DESCRIPTION: **9"x9" Black VFT Mastic**

MATERIAL LOCATION: **Stage South Stairwell - 1939 Building**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	88		
MATERIAL DESCRIPTION:	2"x18" Black VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Stage South Stairwell - 1939 Building		
MATERIAL QUANTITY:	36	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **2"x18" Black VFT**

MATERIAL LOCATION: **Stage South Stairwell - 1939 Building**

MATERIAL QUANTITY: **36** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	89		
MATERIAL DESCRIPTION:	2"x18" Black VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Stage South Stairwell - 1939 Building		
MATERIAL QUANTITY:	36	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **89**

MATERIAL DESCRIPTION: **2"x18" Black VFT Mastic**

MATERIAL LOCATION: **Stage South Stairwell - 1939 Building**

MATERIAL QUANTITY: **36** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	90		
MATERIAL DESCRIPTION:	12"x12" Tan w/ Brown Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	121 Woodshop - 1939 Building		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown Streaks VFT**

MATERIAL LOCATION: **121 Woodshop - 1939 Building**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	91		
MATERIAL DESCRIPTION:	12"x12" Tan w/ Brown Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	121 Woodshop - 1939 Building		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **91**

MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown Streaks VFT Mastic**

MATERIAL LOCATION: **121 Woodshop - 1939 Building**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown & White Streaks VFT ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 117 - 1939 Building ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/04/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown & White Streaks VFT ABATED**

MATERIAL LOCATION: **Room 117 - 1939 Building ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **93**

MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown & White Streaks VFT Mastic ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 117 - 1939 Building ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/04/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **93**

MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown & White Streaks VFT Mastic ABATED**

MATERIAL LOCATION: **Room 117 - 1939 Building ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 94
MATERIAL DESCRIPTION: Brown Linoleum - NOT OBSERVED
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 2nd Floor Teachers Lounge - 1939 Building - NOT OBSERVED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **94**

MATERIAL DESCRIPTION: **Brown Linoleum - NOT OBSERVED**

MATERIAL LOCATION: **2nd Floor Teachers Lounge - 1939 Building - NOT OBSERVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **95**

MATERIAL DESCRIPTION: **Brown Linoleum Mastic - NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **FRIABLE**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Teachers Lounge - 1939 Building - NOT OBSERVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/04/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **95**

MATERIAL DESCRIPTION: **Brown Linoleum Mastic - NOT OBSERVED**

MATERIAL LOCATION: **2nd Floor Teachers Lounge - 1939 Building - NOT OBSERVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	98		
MATERIAL DESCRIPTION:	2'x4' Dot Wave Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 106, 112, 216, 300 - 1939 Building		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **98**

MATERIAL DESCRIPTION: **2'x4' Dot Wave Ceiling Tile**

MATERIAL LOCATION: **Room 106, 112, 216, 300 - 1939 Building**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	99		
MATERIAL DESCRIPTION:	12"x12" Off White w/ Gray Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 214, 216, 300, 300A, and 300L; 1st through 3rd Floor South Corridor - 1939 Building		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **99**

MATERIAL DESCRIPTION: **12"x12" Off White w/ Gray Streaks VFT**

MATERIAL LOCATION: **Rooms 214, 216, 300, 300A, and 300L; 1st through 3rd Floor South Corridor - 1939 Building**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	HA-1000		
MATERIAL DESCRIPTION:	5' x 2.5' ceiling tile with random pinholes		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	throughout - 1974 Building		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **HA-1000**

MATERIAL DESCRIPTION: **5' x 2.5' ceiling tile with random pinholes**

MATERIAL LOCATION: **throughout - 1974 Building**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	HA-1001		
MATERIAL DESCRIPTION:	Black table and counter tops ABATED		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 300, 302, 302A, 305, 308, 310, 312, 313, 316 ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **HA-1001**

MATERIAL DESCRIPTION: **Black table and counter tops ABATED**

MATERIAL LOCATION: **Rooms 300, 302, 302A, 305, 308, 310, 312, 313, 316 ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: HA-1002

MATERIAL DESCRIPTION: Gray lab table and counter tops ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 183 - 1974 Bldg. ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **HA-1002**

MATERIAL DESCRIPTION: **Gray lab table and counter tops ABATED**

MATERIAL LOCATION: **Room 183 - 1974 Bldg. ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	HA-1003		
MATERIAL DESCRIPTION:	MJP E/V/F on Cardboard Pipe Insulation (Paper Wrap on Insulation)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Chase Behind Room 134		
MATERIAL QUANTITY:	155	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:		DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **HA-1003**

MATERIAL DESCRIPTION: **MJP E/V/F on Cardboard Pipe Insulation (Paper Wrap on Insulation)**

MATERIAL LOCATION: **Chase Behind Room 134**

MATERIAL QUANTITY: **155** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: HA-1004

MATERIAL DESCRIPTION: Gray transite panel - ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exhaust hood in Room 302A - ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **HA-1004**

MATERIAL DESCRIPTION: **Gray transite panel - ABATED**

MATERIAL LOCATION: **Exhaust hood in Room 302A - ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	HA-1005		
MATERIAL DESCRIPTION:	Beige Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 311, 313, 213, & office		
MATERIAL QUANTITY:	3300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **HA-1005**

MATERIAL DESCRIPTION: **Beige Linoleum**

MATERIAL LOCATION: **Rooms 311, 313, 213, & office**

MATERIAL QUANTITY: **3300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	HA-1006		
MATERIAL DESCRIPTION:	Grey w/ White Streaks Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 302, 303, 305, 307, 308, 310, 312, 316, 213, 211 - Material replaced in 213, with HA 1005**

MATERIAL QUANTITY: **3400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/04/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **HA-1006**

MATERIAL DESCRIPTION: **Grey w/ White Streaks Linoleum**

MATERIAL LOCATION: **Rooms 302, 303, 305, 307, 308, 310, 312, 316, 213, 211 - Material replaced in 213, with HA 1005**

MATERIAL QUANTITY: **3400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	HA-1007		
MATERIAL DESCRIPTION:	12"x12" White w/Gray Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 117		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **HA-1007**

MATERIAL DESCRIPTION: **12"x12" White w/Gray Streaks VFT**

MATERIAL LOCATION: **Room 117**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	HA-1008		
MATERIAL DESCRIPTION:	12"x12" White w/Gray Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 117		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUILDING ID:	1580
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Taft High School	REVIEW DATE:	10/1/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

HOMOGENEOUS AREA: **HA-1008**

MATERIAL DESCRIPTION: **12"x12" White w/Gray Streaks VFT Mastic**

MATERIAL LOCATION: **Room 117**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	149			
MATERIAL DESCRIPTION:	24" x 6" wood grain vinyl plank flooring			
MATERIAL LOCATION:	Room 230, 2nd floor men's bath			
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	MODERATE			CONDITION:
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:	0	DAMAGE REASON:		
DAMAGE QUANTITY:	0	DAMAGE REASON:		
COMMENTS:	New installation			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **149**

MATERIAL DESCRIPTION: **24" x 6" wood grain vinyl plank flooring**

MATERIAL LOCATION: **Room 230, 2nd floor men's bath**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	149A			
MATERIAL DESCRIPTION:	24" x 6" wood grain vinyl plank flooring Mastic			
MATERIAL LOCATION:	Room 230 and 2nd floor men's bathroom			
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:		
DAMAGE QUANTITY:	0	DAMAGE REASON:		
DAMAGE QUANTITY:	0	DAMAGE REASON:		
COMMENTS:	New installation			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **149A**

MATERIAL DESCRIPTION: **24" x 6" wood grain vinyl plank flooring Mastic**

MATERIAL LOCATION: **Room 230 and 2nd floor men's bathroom**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	152A				
MATERIAL DESCRIPTION:	12 x 12 off white w/ beige & gray specks vft Mastic				
MATERIAL LOCATION:	room 319				
MATERIAL QUANTITY:	720	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:	New install				

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **152A**

MATERIAL DESCRIPTION: **12 x 12 off white w/ beige & gray specks vft Mastic**

MATERIAL LOCATION: **room 319**

MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	155				
MATERIAL DESCRIPTION:	drywall system (board, mud, tape)				
MATERIAL LOCATION:	wall installed between 342 and 342A				
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:	new install				

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **155**

MATERIAL DESCRIPTION: **drywall system (board, mud, tape)**

MATERIAL LOCATION: **wall installed between 342 and 342A**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	151				
MATERIAL DESCRIPTION:	2' x 2' white ceiling tile w/ pinholes				
MATERIAL LOCATION:	room 316, 312, 310, 307, 308				
MATERIAL QUANTITY:	5600	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	Yes		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:	New install				

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **151**

MATERIAL DESCRIPTION: **2' x 2' white ceiling tile w/ pinholes**

MATERIAL LOCATION: **room 316, 312, 310, 307, 308**

MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	154				
MATERIAL DESCRIPTION:	12 x 12 blue with blue streaks vft				
MATERIAL LOCATION:	Women's bathroom @ 330				
MATERIAL QUANTITY:	45	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:	new install				

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **154**

MATERIAL DESCRIPTION: **12 x 12 blue with blue streaks vft**

MATERIAL LOCATION: **Women's bathroom @ 330**

MATERIAL QUANTITY: **45** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	154A				
MATERIAL DESCRIPTION:	12 x 12 blue with blue streaks vft Mastic				
MATERIAL LOCATION:	Women's bathroom @ 330				
MATERIAL QUANTITY:	45	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:	New install				

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **154A**

MATERIAL DESCRIPTION: **12 x 12 blue with blue streaks vft Mastic**

MATERIAL LOCATION: **Women's bathroom @ 330**

MATERIAL QUANTITY: **45** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	1006A			
MATERIAL DESCRIPTION:	gray with white streaks linoleum Mastic			
MATERIAL LOCATION:	rooms 302, 303, 305, 307, 308, 321, 312, 316, 211			
MATERIAL QUANTITY:	3400	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:		
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:	0	DAMAGE REASON:		
DAMAGE QUANTITY:	0	DAMAGE REASON:		
COMMENTS:				

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **1006A**

MATERIAL DESCRIPTION: **gray with white streaks linoleum Mastic**

MATERIAL LOCATION: **rooms 302, 303, 305, 307, 308, 321, 312, 316, 211**

MATERIAL QUANTITY: **3400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	152		
MATERIAL DESCRIPTION:	12 x 12 off white w/ beige & gray specks vft		
MATERIAL LOCATION:	Room 319		
MATERIAL QUANTITY:	720	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:	new install		

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **152**

MATERIAL DESCRIPTION: **12 x 12 off white w/ beige & gray specks vft**

MATERIAL LOCATION: **Room 319**

MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	1005A				
MATERIAL DESCRIPTION:	Beige linoleum Mastic				
MATERIAL LOCATION:	Rooms 311, 313, 213				
MATERIAL QUANTITY:	2300	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **1005A**

MATERIAL DESCRIPTION: **Beige linoleum Mastic**

MATERIAL LOCATION: **Rooms 311, 313, 213**

MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	161A				
MATERIAL DESCRIPTION:	12 x 12 cream vft Mastic				
MATERIAL LOCATION:	Room 207, 212, 219 replacements				
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE UNITS:	SF		
COMMENTS:	vft replacements patched in				

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **161A**

MATERIAL DESCRIPTION: **12 x 12 cream vft Mastic**

MATERIAL LOCATION: **Room 207, 212, 219 replacements**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	160A				
MATERIAL DESCRIPTION:	9 x 9 gray with white black streaks vft Mastic				
MATERIAL LOCATION:	storage room by 220				
MATERIAL QUANTITY:	80	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

COMMENTS:
new HA created - may have been in original MP under different HA

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **160A**

MATERIAL DESCRIPTION: **9 x 9 gray with white black streaks vft Mastic**

MATERIAL LOCATION: **storage room by 220**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	163A				
MATERIAL DESCRIPTION:	Replacement Tiles - 12 x 12 white with gray streaks vft Mastic				
MATERIAL LOCATION:	Room 151				
MATERIAL QUANTITY:	35	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:	New replacement tiles for HA 12 & HA 121				

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **163A**

MATERIAL DESCRIPTION: **Replacement Tiles - 12 x 12 white with gray streaks vft Mastic**

MATERIAL LOCATION: **Room 151**

MATERIAL QUANTITY: **35** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	162A				
MATERIAL DESCRIPTION:	12 x 12 white with gold streaks vft Mastic				
MATERIAL LOCATION:	Room 151				
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Chrysotile				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:	New replacement tiles HA 12 & HA 121				

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **162A**

MATERIAL DESCRIPTION: **12 x 12 white with gold streaks vft Mastic**

MATERIAL LOCATION: **Room 151**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	159			
MATERIAL DESCRIPTION:	12 x 12 Blue with Dark Blue specs replacement vft			
MATERIAL LOCATION:	room 107 (75), 109 (40), old vault conference room (144), 238 (80)			
MATERIAL QUANTITY:	350	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:		
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:	0	DAMAGE REASON:		
DAMAGE QUANTITY:	0	DAMAGE REASON:		
COMMENTS:				

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **159**

MATERIAL DESCRIPTION: **12 x 12 Blue with Dark Blue specs replacement vft**

MATERIAL LOCATION: **room 107 (75), 109 (40), old vault conference room (144), 238 (80)**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	153A				
MATERIAL DESCRIPTION:	12 x 12 off white w/ beige & gray specks vft Mastic				
MATERIAL LOCATION:	room 330				
MATERIAL QUANTITY:	302	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:	new install				

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **153A**

MATERIAL DESCRIPTION: **12 x 12 off white w/ beige & gray specks vft Mastic**

MATERIAL LOCATION: **room 330**

MATERIAL QUANTITY: **302** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	157		
MATERIAL DESCRIPTION:	12 x 12 tan with white specks vft		
MATERIAL LOCATION:	306 B		
MATERIAL QUANTITY:	225	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	CONDITION:		
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			
new replacements for HA125			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **157**

MATERIAL DESCRIPTION: **12 x 12 tan with white specks vft**

MATERIAL LOCATION: **306 B**

MATERIAL QUANTITY: **225** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	158				
MATERIAL DESCRIPTION:	cloth wire insulation				
MATERIAL LOCATION:	Room 347				
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE UNITS:	SF		
COMMENTS:	open box - wire exposed				

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **158**

MATERIAL DESCRIPTION: **cloth wire insulation**

MATERIAL LOCATION: **Room 347**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	150A				
MATERIAL DESCRIPTION:	12 x 12 tan speckled vft Mastic				
MATERIAL LOCATION:	room 206, 210, 205, 208, 210A, 221				
MATERIAL QUANTITY:	1364	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **150A**

MATERIAL DESCRIPTION: **12 x 12 tan speckled vft Mastic**

MATERIAL LOCATION: **room 206, 210, 205, 208, 210A, 221**

MATERIAL QUANTITY: **1364** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	160		
MATERIAL DESCRIPTION:	9 x 9 gray with white and black streaks vft		
MATERIAL LOCATION:	storage room by 220		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:
new HA created - may have been in original MP under different HA

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **160**

MATERIAL DESCRIPTION: **9 x 9 gray with white and black streaks vft**

MATERIAL LOCATION: **storage room by 220**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	153				
MATERIAL DESCRIPTION:	12 x 12 light blue streaked vft				
MATERIAL LOCATION:	Room 330				
MATERIAL QUANTITY:	302	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:	new install				

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **153**

MATERIAL DESCRIPTION: **12 x 12 light blue streaked vft**

MATERIAL LOCATION: **Room 330**

MATERIAL QUANTITY: **302** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	156			
MATERIAL DESCRIPTION:	2 x 2 white ceiling tile with pinholes			
MATERIAL LOCATION:	Rooms 300, 300A, 303, 305, 305A, 304 a-b-c-d & office, 302, 302A & office/storage room, 203, 208, 204, 210, 205, 206, 210A, 213, 214, 211			
MATERIAL QUANTITY:	20000	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	Yes	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:		
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:		
DAMAGE QUANTITY:	0	DAMAGE REASON:		
		DAMAGE REASON:		
COMMENTS:	new install			

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **156**

MATERIAL DESCRIPTION: **2 x 2 white ceiling tile with pinholes**

MATERIAL LOCATION: **Rooms 300, 300A, 303, 305, 305A, 304 a-b-c-d & office, 302, 302A & office/storage room, 203, 208, 204, 210, 205, 206, 210A, 213, 214, 211**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	150		
MATERIAL DESCRIPTION:	12 x 12 tan speckled vft		
MATERIAL LOCATION:	room 206, 210, 205, 208, 210A, 221		
MATERIAL QUANTITY:	1364	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **150**

MATERIAL DESCRIPTION: **12 x 12 tan speckled vft**

MATERIAL LOCATION: **room 206, 210, 205, 208, 210A, 221**

MATERIAL QUANTITY: **1364** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	163				
MATERIAL DESCRIPTION:	Replacement Tiles - 12 x 12 white with gray streaks vft				
MATERIAL LOCATION:	# 151				
MATERIAL QUANTITY:	35	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:	New replacement tiles for HA 12 & HA 121				

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **163**

MATERIAL DESCRIPTION: **Replacement Tiles - 12 x 12 white with gray streaks vft**

MATERIAL LOCATION: **# 151**

MATERIAL QUANTITY: **35** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	157A				
MATERIAL DESCRIPTION:	12 x 12 tan with white specks vft Mastic				
MATERIAL LOCATION:	306 B				
MATERIAL QUANTITY:	225	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:	New replacements for new HA125				

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **157A**

MATERIAL DESCRIPTION: **12 x 12 tan with white specks vft Mastic**

MATERIAL LOCATION: **306 B**

MATERIAL QUANTITY: **225** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	162		
MATERIAL DESCRIPTION:	12 x 12 white with gold streaks vft		
MATERIAL LOCATION:	Room 151		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Chrysotile		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:	New replacement tiles for HA 12 & HA 121		

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **162**

MATERIAL DESCRIPTION: **12 x 12 white with gold streaks vft**

MATERIAL LOCATION: **Room 151**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 10/01/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46311	BUIDLING ID:	1580
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Joseph Hennigan		
SCHOOL NAME:	Taft High School	INSPECTION DATE:	9/4/2025		
ADDRESS:	6545 W. Hurlburt St.	IDPH LICENSE NO:	100-18350		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	161				
MATERIAL DESCRIPTION:	12 x 12 Cream vft				
MATERIAL LOCATION:	Room 207, 212, 219 replacements				
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE UNITS:	SF		
COMMENTS:	vft replacements patched in				

Inspector's Signature:



Date: 09/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Taft High School** REVIEW DATE: **10/1/2025**

ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **161**

MATERIAL DESCRIPTION: **12 x 12 Cream vft**

MATERIAL LOCATION: **Room 207, 212, 219 replacements**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **10/01/2025**

Chicago Public Schools

Specialty Consulting, Inc.

2025 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that JOSEPH L. HENNIGAN
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 01/28/2023 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

01/28/2023

Course Dates:

01/28/2024

Expires:

2301BIR23

Certificate Number:

N Penef *APD*
Director of Training

Nicholas J. Penef

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois

JOSEPH L HENNIGAN
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/5/2024

IDPH ASBESTOS
PROFESSIONAL
LICENSE

ID NUMBER
100 - 18350

ISSUED
4/5/2024 EXPIRES
05/15/2025

JOSEPH L HENNIGAN
2942 W VAN BUREN ST
CHICAGO, IL 60612

Environmental Health



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: **18350**

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 18350	ISSUED 4/5/2024	EXPIRES 05/15/2025	INSPECTOR	1/27/2025
JOSEPH L HENNIGAN 2942 W VAN BUREN ST CHICAGO, IL 60612			PROJECT MANAGER AIR SAMPLING PROFESSIONAL	1/13/2025
			Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that HENNIGAN JOSEPH
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 01/04/2025 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

01/04/2025

Course Dates:

01/04/2026

Expires:

2501BIR08

Certificate Number:

Director of Training

Nicholas J. Peneff
Doctor of Public Health


Phone: 312-491-0081

FORM # A-010B

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that JOSEPH L. HENNIGAN
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 01/15/2022 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

01/15/2022

Course Dates:

01/15/2023

Expires:

2201BIR11

Certificate Number:

A handwritten signature in black ink that reads 'Nicholas J. Peneff'.

Phone: 312-491-0081

Director of Training

Nicholas J. Peneff

Doctor of Public Health

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois

JOSEPH L HENNIGAN
2942 W VAN BUREN ST
CHICAGO, IL 60612

2/28/2022



ASBESTOS
PROFESSIONAL
LICENSE

ID NUMBER
100 - 18350

ISSUED
2/28/2022

EXPIRES
05/15/2023

JOSEPH L HENNIGAN
2942 W VAN BUREN ST
CHICAGO, IL 60612

Environmental Health



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: **18350**

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 18350	ISSUED 2/28/2022	EXPIRES 05/15/2023	INSPECTOR	1/15/2023
JOSEPH L HENNIGAN 2942 W VAN BUREN ST CHICAGO, IL 60612			PROJECT MANAGER	1/22/2023
			AIR SAMPLING PROFESSIONAL	
<p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>				

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES


Nationally Accredited by PHAB



525-535 West Jefferson Street • Springfield, IL

JOSEPH L HENNIGAN
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/30/20




ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 18350

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that
Arturo Saenz

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012562

Kathy DeSalvo
Kathy DeSalvo, Director



Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that
Arturo Saenz

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012583

Kathy DeSalvo
Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

ARTURO SAENZ
2942 W VAN BUREN ST
CHICAGO, IL 60612

7/8/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 04019	ISSUED 7/8/2024	EXPIRES 05/15/2025	INSPECTOR	5/6/2025
ARTURO SAENZ 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			MANAGEMENT PLANNER	5/6/2025
			AIR SAMPLING PROFESSIONAL Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



OCCUPATIONAL TRAINING & SUPPLY, INC.
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2024

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Arturo Saenz

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 5/6/2024

Exam Date: 5/6/2024

Expiration Date: 5/6/2025

Certificate Number: MPR2405061823


Course Credit Hours: MPR 8 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

Kristina Miczek, Training Manager



525-535 West Jefferson Street • Springfield, Illinois



ARTURO SAENZ
2942 W VAN BUREN ST
CHICAGO, IL 60612


2/28/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	11/1/2022
MANAGEMENT PLANNER	11/1/2022
AIR SAMPLING PROFESSIONAL	
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB



525-535 West Jefferson Street • Springfield, Ill

ARTURO SAENZ
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/30/2026

ASBESTOS
PROFESSIONAL
LICENSE

ID NUMBER
100 - 04019

ISSUED
4/30/2025

EXPIRES
05/15/2026

ARTURO SAENZ
2942 W VAN BUREN ST
CHICAGO, IL 60612

Environmental Health




ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	5/6/2025
MANAGEMENT PLANNER	4/2/2026
AIR SAMPLING PROFESSIONAL	
<p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB

**Reliable
Environmental
Solutions, Inc. R E S**

This is to certify that **Arturo Saenz**

*has on 4/2/25, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Refresher Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: April 2, 2025

COURSE LENGTH: 4 HOURS

Examination Date: April 2, 2025

Expiration Date: April 2, 2026

Certificate Number: MPR/0560



Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois 217.787.9800 www.ReliableEnv.com

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed