

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0047
SCHOOL NAME: Lincoln Park High School
ADDRESS OF SCHOOL: 2001 N. Orchard
CITY: Chicago, IL, 60614

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 6/22/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 3/26/2025 ENROLLMENT 2117
IDPH INSPECTOR LICENSE NUMBER: 100-18790
IDPH LICENSED INSPECTOR NAME (Please Print): Allizon Brooks
IDPH MP LICENSE NUMBER: 100-07342
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 4/16/2025
Signature of Designated Person Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____
School has been closed. Date closed: _____
School building has been demolished. Date: _____
School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Lincoln Park High School

2001 N. Orchard
Chicago, IL, 60614

Unit: 46321
Building ID: 1620

IDPH ID Number: 14-016-2990-0047

REPORT DATE:

Wednesday, April 16, 2025

Prepared for:

**Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602**

Prepared by:

Specialty Consulting, Inc.

2942 W. Van Buren Street

Chicago, IL, 60612

Phone (312) 319-7575

Fax (312) 319-7580

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

04/16/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Specialty Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 46321 Region: 02 IDPH ID: 14-016-2990-0047

School: Lincoln Park High School Building ID: 1620

Address: 2001 N. Orchard
Chicago, IL, 60614

Building Contact: Cantore, Anthony Contact Phone: 3122133948

Current Building Owners: Chicago Public Schools

Reinspection Date: 3/26/2025

Review Date: 04/16/2025

Inspector: Allizon Brooks Inspector IDPH License: 100-18790
Management Planner: Jigar Shah Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at (312) 319-7575

Sincerely,
Specialty Consulting, Inc.



Jigar Shah
100-07342

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: April 16, 2025

RE: Lincoln Park High School, Unit 46321
2001 N. Orchard
Chicago, IL, 60614

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Lincoln Park High School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Lincoln Park High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Lincoln Park High School Unit: 46321 Region: 02
Address: 2001 N. Orchard Chicago, IL, 60614
IDPH ID: 14-016-2990-0047 Building ID: 1620
Contact: Cantore, Anthony Phone: 3122133948

2. Description of Facility

Original Construction: 1962 Additional Construction: 1899,1938
Total Square Footage: 35451 No of Floors: 3
Current Occupancy: 2117

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Specialty Consulting, Inc.
Contact: Jigar Shah
Address 2942 W. Van Buren Street
Phone: (312) 319-7575 Fax: (312) 319-7580

5. Inspector

Inspector Name: Allizon Brooks

Inspector IDPH license # 100-18790
Reinspection Date: 3/26/2025

Signature:
Date: 3/26/2025

6. Management Planner

Management Planner Name: Jigar Shah

Management Planner IDPH license # 100-07342


Signature:
Date: 04/16/2025

7. Review Date: 04/16/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 4/16/2025

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Specialty Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Lincoln Park High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1620:

B. The following new homogenous areas have been identified for Building 1620:

99-64

Brown Laminate Wood Flooring

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

37-03	12"x12" Gray w/ Gray Streaks VFT
37-08	12"x12" Off White w/ Tan Streaks VFT Mastic
37-09	12"x12" Black w/ White Streaks VFT (Not Observed)
37-10	12"x12" Black w/ White Streaks VFT Mastic (Not Observed)
37-21	2'x2' Off White Ceiling Tile
37-24	MJP E/F/V on Fiberglass Pipe Insulation
37-30	Hard Coat Plaster
37-38	Terrazzo
37-39	Carpet Mastic
37-42	Beige Linoleum
37-43	Beige Linoleum Mastic
37-44	14"x14" Gray w/ Black Spots VFT
37-45	14"x14" Gray w/ Black Spots VFT Mastic
37-46	2'x2' Ceiling Tile
37-47	14"x14" Blue Speckled VFT
37-48	14"x14" Blue Speckled VFT Mastic
37-51	20"x20" Yellow w/ Streaks VFT
37-52	20"x20" Yellow w/ Streaks VFT Mastic
37-53	20"x20" Brown w/ Streaks VFT
37-54	20"x20" Brown w/ Streaks VFT Mastic
37-55	20"x20" Beige w/ Streaks VFT
37-56	20"x20" Beige w/ Streaks VFT Mastic
37-57	20"x20" Off White w/ Streaks VFT
37-58	20"x20" Off White w/ Streaks VFT Mastic
37-59	20"x20" Gray w/ Streaks VFT
37-60	20"x20" Gray w/ Streaks VFT Mastic
37-61	20"x20" Blue w/ Streaks VFT
37-62	20"x20" Blue w/ Streaks VFT Mastic
37-63	20"x20" Green w/ Streaks VFT
37-64	20"x20" Green w/ Streaks VFT Mastic
38	12"x12" Off White with Tan Streaks VFT
39	12"x12" Off White with Tan Streaks VFT Mastic
40	Linoleum
41	Linoleum Adhesive
42	Tan Linoleum
43	Tan Linoleum Adhesive
44	2' x 4' Lay In Ceiling Panels
45	Insulation in Walls and Vault Door
46	2' x 4' Lay In Ceiling Panels
47	Linoleum

48	Linoleum Adhesive
54	12"x12" Ceiling Tile
55	12"x12" Light Blue with White and Brown Streaks Floor Tile
56	12"x12" Light Blue with White and Brown Streaks VFT Mastic
61-18	2'x2' White Speckled w/ Inch Wormy Ceiling Tile
61-19	1'x1' White Ceiling Tile
61-20	1'x1' Off White w/ Speckles Ceiling Tile
61-21	1'x1' Off White w/ Large Wormy Ceiling Tile
61-30	Carpet Mastic
61-31	2'x2' Dot Wave Ceiling Tile (NOT OBSERVED)
61-32	Lab Counter Tops
61-33	9"x9" Gray w/ White Streaks VFT
61-34	9"x9" Gray w/ White Streaks VFT Mastic
61-35	12"x12" Gray Speckled VFT
61-36	12"x12" Gray Speckled VFT Mastic
61-37	12"x12" Mixed Beige Speckled VFT
61-38	12"x12" Mixed Beige Mastic
61-39	12"x12" Brown Speckled VFT
61-40	12"x12" Brown Speckled VFT Mastic
61-41	12"x12" Blue w/ Black and White Specs VFT
61-42	12"x12" Blue w/ Black and White Specs VFT Mastic
61-43	20"x20" Yellow w/ Streaks VFT
61-44	20"x20" Yellow w/ Streaks VFT Mastic
61-45	20"x20" Brown w/ Streaks VFT
61-46	20"x20" Brown w/ Streaks VFT Mastic
61-47	20"x20" Beige w/ Streaks VFT
61-48	20"x20" Beige w/ Streaks VFT Mastic
61-49	20"x20" Off White w/ Streaks VFT
61-50	20"x20" Off White w/ Streaks VFT Mastic
61-51	20"x20" Gray w/ Streaks VFT
61-52	20"x20" Gray w/ Streaks VFT Mastic
61-53	20"x20" Green w/ Streaks VFT
61-54	20"x20" Green w/ Streaks VFT Mastic
61-55	20"x20" Dark Green w/ Streaks VFT
61-56	20"x20" Dark Green w/ Streaks VFT Mastic
61-57	20"x20" Royal Blue w/ Streaks VFT
61-58	20"x20" Royal Blue w/ Streaks VFT Mastic
99-09	12"x12" Brown w/ White Streaks VFT
99-10	12"x12" Brown w/ White Streaks VFT Mastic
99-21	2'x2' White w/ Wormy Grooves Ceiling Tile
99-23	2'x4' White w/ Wormy Grooves Ceiling Tile
99-24	2'x4' White w/ Pin Holes Ceiling Tile
99-30	MJP E/F/V on Fiberglass Pipe Insulation
99-33	Water Tank Insulation
99-34	Hardcoat Plaster

99-36	Beige Linoleum
99-37	Beige Linoleum Mastic
99-38	Gray Linoleum - NOT OBSERVED
99-38A	Gray Linoleum Mastic- NOT OBSERVED
99-39	Terrazzo
99-41	Black Lab Counter Tops
99-42	Fume Hood
99-43	12"x12" Yellow Speckled VFT
99-44	12"x12" Yellow Speckled VFT Mastic
99-49	Drywall System
99-50	20"x20" Yellow w/ Streaks VFT
99-51	20"x20" Yellow w/ Streaks VFT Mastic
99-52	20"x20" Brown w/ Streaks VFT
99-53	20"x20" Brown w/ Streaks VFT Mastic
99-54	20"x20" Beige w/ Streaks VFT
99-55	20"x20" Beige w/ Streaks VFT Mastic
99-56	20"x20" Off White w/ Streaks VFT
99-57	20"x20" Off White w/ Streaks VFT Mastic
99-58	20"x20" Gray w/ Streaks VFT
99-59	20"x20" Gray w/ Streaks VFT Mastic
99-60	20"x20" Blue w/ Streaks VFT
99-61	20"x20" Blue w/ Streaks VFT Mastic
99-62	20"x20" Green w/ Streaks VFT
99-63	20"x20" Green w/ Streaks VFT Mastic
99-64	Brown Laminate Wood Flooring
FA-05	12"x12" Cream w/ Tan & White Streaks VFT (NOT OBSERVED)
FA-23	1'x1' Small Hole Ceiling Tile
FA-24	1'x1' Medium Hole Ceiling Tile
FA-25	2'x2' Ceiling Tile
FA-32	20"x20" Brown w/ Streaks VFT
FA-33	20"x20" Brown w/ Streaks VFT Mastic
FA-34	20"x20" Beige w/ Streaks VFT
FA-35	20"x20" Beige w/ Streaks VFT Mastic
FA-36	20"x20" Off White w/ Streaks VFT
FA-37	20"x20" Off White w/ Streaks VFT Mastic
FA-38	20"x20" Gray w/ Streaks VFT
FA-39	20"x20" Gray w/ Streaks VFT Mastic
FA-40	20"x20" Blue w/ Streaks VFT
FA-41	20"x20" Blue w/ Streaks VFT Mastic
FA-42	20"x20" Green w/ Streaks VFT
FA-43	20"x20" Green w/ Streaks VFT Mastic
FA-44	20"x20" Peach w/ Streaks VFT
FA-45	20"x20" Peach w/ Streaks VFT Mastic
FA-46	2'x2' Ceiling Tile
FA-47	12"x12" Blue VFT
FA-47A	12"x12" Blue VFT mastic
FA-48	12"x12" Yellow VFT

FA-48A	12"x12" Yellow VFT mastic
FT-001	9"x9" Beige Floor Tile
FTM-001	9"x9" Beige Floor Tile Mastic

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Allizon Brooks, IDPH License # 100-18790. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:	2/6/2022
	4/15/2022
	4/6/2023
	4/6/2023
	7/24/2023
	1/2/2025
	3/28/2025

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Lincoln Park High School Building 1620 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Lincoln Park High School Unit 46321 Building ID 1620

Address 2001 N. Orchard Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
37-16	9"x9" Brown w/ Gray Streaks VFT Mastic (Abated)			Room 103 Rear Office - 1937 Bldg. (Abated)	ABATED	MISC								
37-17	9"x9" Green w/ White Streaks VFT	80	SF	Room 102 Vault - 1937 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
37-18	9"x9" Green w/ White Streaks VFT Mastic	80	SF	Room 102 Vault - 1937 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37-19	9"x9" Gray w/ White Streaks VFT (Abated)			Room 102, 100A, 100 - 1937 Bldg. (Abated)	ABATED	MISC								
37-20	9"x9" Gray w/ White Streaks VFT Mastic (Abated)			Room 102, 100A, 100 - 1937 Bldg. (Abated)	ABATED	MISC								
37-21	2'x2' Off White Ceiling Tile	4,500	SF	Rooms 308, 301, 111, 312, 106 Throughout - 1937 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
37-22	Paperwrap Pipe Insulation	1,678	LF	Boy's & Girl's Toilets Pipe Chases, Swimming Pool, Tunnels, & N, W, & E 232 Office Principals Office; Crawlspace - 1937 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
37-23	MJP E/F/V on Paperwrap Pipe Insulation	390	FITTING	Boy's & Girl's Toilets Pipe Chases, Swimming Pool, Tunnels, & N, W, & E Crawlspace - 1937 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
37-24	MJP E/F/V on Fiberglass Pipe Insulation	300	FITTING	106, Pool, Tunnels, Crawlspace, Rifle Storage, Engine Room, Plenum C - 1937 Bldg.	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
37-25	Mag Block Pipe Insulation	2,845	LF	Swimming Pool, NS Air Tunnel, NE Crawlspace, Rifle Range & Storage, GMV, Engine Room, & Plenum - 1937 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
37-26	MJP E/F/V on Mag Block Pipe Insulation	164	FITTING	Swimming Pool, NS Air Tunnel, NE	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Lincoln Park High School Unit 46321 Building ID 1620

Address 2001 N. Orchard Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Crawlspace, Rifle Range & Storage, GMV, Engine Room, & Plenum - 1937 Bldg.										
37-27	Air Cell Duct Insulation	6,450	SF	West & NW Crawl Spaces, Rifle Range & Storage - 1937 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
37-28	Aircell Pipe Insulation	3,025	LF	Basement Corridor, Throughout - 1937 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
37-29	MJP E/F/V on Aircell Pipe Insulation	465	FITTING	Throughout - 1937 Bldg. (See Hatching Maps)	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
37-30	Hard Coat Plaster	120,000	SF	Throughout - 1937 Bldg.	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		MODERATE
37-31	Exterior Window Caulk	30,000	SF	Throughout - 1937 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37-37	Exterior Window Caulk	30,000	SF	Throughout - 1937 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37-38	Terrazzo	2,000	SF	Stairwells - 1937 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
37-39	Carpet Mastic	3,200	SF	Library and Main Office, 207A - 1937 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37-40	12"x12" Mixed Gray Speckled VFT (Abated)			Rooms 114K, 134B, 134C - 1937 Bldg.	ABATED	MISC								
37-41	12"x12" Mixed Gray Speckled VFT Mastic (Abated)			Rooms 114K, 134B, 134C - 1937 Bldg.	ABATED	MISC								
37-42	Beige Linoleum	700	SF	Room 304 - 1937 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
37-43	Beige Linoleum Mastic	700	SF	Room 304 - 1937 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37-44	14"x14" Gray w/ Black Spots VFT	500	SF	Auditorium Lobby - 1937 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
37-45	14"x14" Gray w/ Black Spots VFT Mastic	500	SF	Auditorium Lobby - 1937 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37-46	2'x2' Ceiling Tile	1,000	SF	Rooms 308, 301 - 1937 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
37-47	14"x14" Blue Speckled VFT	700	SF	Auditorium - 1937 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
37-48	14"x14" Blue Specked VFT Mastic	700	SF	Auditorium - 1937 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Lincoln Park High School Unit 46321 Building ID 1620

Address 2001 N. Orchard Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
37-49	12"x12" Mixed Beige Speckled VFT (Abated)			Rooms 308, 206, 110, 108 - 1937 Bldg. (Abated)	ABATED	MISC								
37-50	12"x12" Mixed Beige Speckled VFT Mastic (Abated)			Rooms 208, 206, 110, 108 - 1937 Bldg. (Abated)	ABATED	MISC								
37-51	20"x20" Yellow w/ Streaks VFT	1,700	SF	Rooms 204, 206, 208, 210, 100, 101, 102, 105C - 1937 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
37-52	20"x20" Yellow w/ Streaks VFT Mastic	1,700	SF	Rooms 204, 206, 209, 210, 100, 101, 102, 105C - 1937 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37-53	20"x20" Brown w/ Streaks VFT	5,000	SF	1st, 2nd and 3rd Floor Corridors - 1937 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
37-54	20"x20" Brown w/ Streaks VFT Mastic	5,000	SF	1st, 2nd and 3rd Floor Corridors - 1937 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37-55	20"x20" Beige w/ Streaks VFT	5,000	SF	1st, 2nd and 3rd Floor Corridors, Room 103B - 1937 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
37-56	20"x20" Beige w/ Streaks VFT Mastic	5,000	SF	1st, 2nd and 3rd Floor Corridors, Room 103B - 1937 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37-57	20"x20" Off White w/ Streaks VFT	3,200	SF	1st, 2nd and 3rd Floor Corridors - 1937 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
37-58	20"x20" Off White w/ Streaks VFT Mastic	3,200	SF	1st, 2nd and 3rd Floor Corridors - 1937 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37-59	20"x20" Gray w/ Streaks VFT	2,600	SF	Rooms 100, 101, 102, 204, 206, 208 and 210 - 1937 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
37-60	20"x20" Gray w/ Streaks VFT Mastic	2,600	SF	Rooms 100, 101, 102, 204, 206, 208 and 210 - 1937 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37-61	20"x20" Blue w/ Streaks VFT	1,400	SF	Rooms 204, 206, 208, 210 - 1937 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Lincoln Park High School Unit 46321 Building ID 1620

Address 2001 N. Orchard Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Stairwell - 1961 Addition (Not Observed)										
61-12	9"x9" Brown w/ White Streaks VFT- Abated			Auditorium Balcony - 1961 Addition (Abated)	ABATED	MISC								
61-13	9"x9" Brown w/ White Streaks VFT Mastic (Abated)			Auditorium Balcony - 1961 Addition (Abated)	ABATED	MISC								
61-14	9"x9" Gray w/ White Streaks VFT	800	SF	Teacher's Lunchroom - 1937 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
61-15	9"x9" Gray w/ White Streaks VFT Mastic	800	SF	Teacher's Lunchroom - 1937 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61-16	Black w/ White Streaks Linoleum (Abated)			East and West Stairwells, Auditorium Stairwell - 1961 Addition (Abated)	ABATED	MISC								
61-17	Black w/ White Streaks Linoleum Mastic (Abated)			East and West Stairwells, Auditorium Stairwell - 1961 Addition (Abated)	ABATED	MISC								
61-18	2'x2' White Speckled w/ Inch Wormy Ceiling Tile	10,000	SF	2nd Floor West Corridor - 1961 FA	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
61-19	1'x1' White Ceiling Tile	7,000	SF	NW & SW Stairwells, Auditorium, Rooms 108, 109 & 110 - 1961 Addition	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
61-20	1'x1' Off White w/ Speckles Ceiling Tile	6,700	SF	Lunchroom - 1961 Addition	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
61-21	1'x1' Off White w/ Large Wormy Ceiling Tile	800	SF	Teachers Lunchroom by Kitchen - 1961 Addition	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
61-22	Air Cell Pipe Insulation	935	LF	NW & NE Crawlspace & Paint Storage - 1961 Addition	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
61-23	MJP E/F/V on Air Cell Pipe Insulation	48	FITTING	NW & NE Crawlspace & Paint Storage - 1961	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Lincoln Park High School Unit 46321 Building ID 1620

Address 2001 N. Orchard Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Addition										
61-24	Mag Block Pipe Insulation	2,500	LF	NE Crawlspace - 1961 Addition	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
61-25	MJP E/F/V on Mag Block Pipe Insulation	100	FITTING	NE Crawlspace - 1961 Addition	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
61-26	Paperwrap Pipe Insulation	350	LF	NE Crawlspace - 1961 Addition	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
61-27	MJP E/F/V on Paperwrap Pipe Insulation	37	FITTING	NE Crawlspace - 1961 Addition	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
61-28	Aircell Duct Insulation	100	SF	Paint Storage Room - 1961 Addition	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
61-29	9"x9" Black w/ White Streaks VFT Mastic (Abated)			West Stairwell & Auditorium Stairwell - 1961 Addition (Abated)	ABATED	MISC								
61-30	Carpet Mastic	1,000	SF	Engineer's Office and CPS Area Office, 182 - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61-31	2'x2' Dot Wave Ceiling Tile (NOT OBSERVED)	500	SF	Room 153 - FA Building (Not Observed)	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
61-32	Lab Counter Tops	200	SF	Rooms 252, 251 - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61-33	9"x9" Gray w/ White Streaks VFT	40	SF	Room 258A - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
61-34	9"x9" Gray w/ White Streaks VFT Mastic	40	SF	Room 258A - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61-35	12"x12" Gray Speckled VFT	500	SF	Room 163C - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
61-36	12"x12" Gray Speckled VFT Mastic	500	SF	Room 163C - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61-37	12"x12" Mixed Beige Speckled VFT	1,000	SF	Room 180 and 180A - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
61-38	12"x12" Mixed Beige Mastic	1,000	SF	Room 180 and 180A - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61-39	12"x12" Brown Speckled VFT	500	SF	Rooms 170 and 172 - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
61-40	12"x12" Brown Speckled VFT Mastic	500	SF	Rooms 170 and 172 - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61-41	12"x12" Blue w/ Black and White Specs VFT	600	SF	Room 154 - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
61-42	12"x12" Blue w/ Black and White Specs VFT Mastic	600	SF	Room 154 - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Lincoln Park High School Unit 46321 Building ID 1620

Address 2001 N. Orchard Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
61-43	20"x20" Yellow w/ Streaks VFT	1,000	SF	Room 109 and 110 - 1961 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
61-44	20"x20" Yellow w/ Streaks VFT Mastic	1,000	SF	Rooms 109 and 110 - 1961 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61-45	20"x20" Brown w/ Streaks VFT	1,200	SF	1st Floor Corridor - 1961 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
61-46	20"x20" Brown w/ Streaks VFT Mastic	1,200	SF	1st Floor Corridor - 1961 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61-47	20"x20" Beige w/ Streaks VFT	1,200	SF	1st Floor Corridor - 1961 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
61-48	20"x20" Beige w/ Streaks VFT Mastic	1,200	SF	1st Floor Corridor - 1961 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61-49	20"x20" Off White w/ Streaks VFT	1,200	SF	1st Floor Corridor - 1961 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
61-50	20"x20" Off White w/ Streaks VFT Mastic	1,200	SF	1st Floor Corridor - 1961 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61-51	20"x20" Gray w/ Streaks VFT	800	SF	Rooms 109 and 110 - 1961 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
61-52	20"x20" Gray w/ Streaks VFT Mastic	800	SF	Rooms 109 and 110 - 1961 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61-53	20"x20" Green w/ Streaks VFT	2,400	SF	Rooms 109, 110 and Cafeteria - 1961 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
61-54	20"x20" Green w/ Streaks VFT Mastic	2,400	SF	Rooms 109, 110 and Cafeteria - 1961 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61-55	20"x20" Dark Green w/ Streaks VFT	1,200	SF	Cafeteria - 1961 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
61-56	20"x20" Dark Green w/ Streaks VFT Mastic	1,200	SF	Cafeteria - 1961 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61-57	20"x20" Royal Blue w/ Streaks VFT	1,200	SF	Cafeteria - 1961 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
61-58	20"x20" Royal Blue w/ Streaks VFT Mastic	1,200	SF	Cafeteria - 1961 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
99-01	12"x12" Gray w/ White Specks VFT	1,200	SF	1st, 2nd, & 3rd Floor Corridors (Abated), Room 229 (Not Observed), 2nd Floor women's toilet, & 113A - 1899 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
99-02	12"x12" Gray w/ White Specks VFT Mastic	1,200	SF	1st, 2nd, & 3rd Floor Corridors (Abated), Room 229 (Not	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Lincoln Park High School Unit 46321 Building ID 1620

Address 2001 N. Orchard Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Observed), 2nd Floor Women's Toilet & 113A - 1899 Bldg.										
99-03	12"x12" White w/ Gray Specks VFT (Abated)			Room 215 - 1899 Bldg. (Abated)	ABATED	MISC								
99-04	12"x12" White w/ Gray Specks VFT Mastic (Abated)			Room 215 - 1899 Bldg. (Abated)	ABATED	MISC								
99-05	12"x12" Beige w/ Brown Specks VFT- (Abated)			Rooms 223, 217, 219, 217A, 224, & storage 217B & C - 1899 Bldg. (Abated)	ABATED	MISC								
99-06	12"x12" Beige w/ Brown Specks VFT Mastic (Abated)			Rooms 223, 217, 219, 217A, 224, & 224 Storage 217B & C - 1899 Bldg. (Abated)	ABATED	MISC								
99-07	12"x12" Light Brown w/ Brown & White Specks VFT (Abated)			Room 113A - 1899 Bldg. (Abated)	ABATED	MISC								
99-08	12"x12" Light Brown w/ Brown & White Specks VFT Mastic (Abated)			Room 113A - 1899 Bldg. (Abated)	ABATED	MISC								
99-09	12"x12" Brown w/ White Streaks VFT	400	SF	Room 112 - 1899 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
99-10	12"x12" Brown w/ White Streaks VFT Mastic	400	SF	Room 112 - 1899 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
99-11	12"x12" Off White w/ Light Brown Streaks VFT (Abated)			Room 14 Foyer, 29, 23 - 1899 Bldg. (Abated)	ABATED	MISC								
99-12	12"x12" Off White w/ Light Brown Streaks VFT Mastic (Abated)			Room 14 Foyer, 29, 23 - 1899 Bldg. (Abated)	ABATED	MISC								
99-13	9"x9" Tan w/ Brown & White Streaks VFT (Abated)			Throughout - 1899 (See Hatching Maps) 119, 114 A & B & C, D,E, F, G, 022, 032, 036, Counselors Corridor (Abated)	ABATED	MISC								
99-14	9"x9" Tan w/ Brown & White Streaks VFT Mastic (Abated)			Throughout - 1899 Bldg. (Abated)	ABATED	MISC								
99-15	9"x9" Green w/ White Streaks VFT (NOT OBSERVED)	305	SF	Science Copy Room - 1899 Bldg. (Not Observed)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
99-16	9"x9" Green w/ White Streaks VFT Mastic	305	SF	Science Copy Room	CHR	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Lincoln Park High School Unit 46321 Building ID 1620

Address 2001 N. Orchard Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	(NOT OBSERVED)			- 1899 Bldg. (Not Observed)								potential for damage		
99-17	9"x9" Tan VFT (Abated)			Room 14 (Under HA 99-10), Room 127A & 129A 1899 Bldg. (Abated)	ABATED	MISC								
99-18	9"x9" Tan VFT Mastic (Abated)			Room 14 (Under HA 99-10) 1899 Bldg. (Abated)	ABATED	MISC								
99-19	9"x9" Rust VFT (Abated)			Room 14 (Under HA 99-10 and 99-17) - 1899 Bldg. (Abated)	ABATED	MISC								
99-20	9"x9" Rust VFT Mastic (Abated)			Room 14 (Under HA 99-10 and 99-17) - 1899 Bldg. (Abated)	ABATED	MISC								
99-21	2'x2' White w/ Wormy Grooves Ceiling Tile	1,200	SF	Library, Work Room A & B, 221 (NOT OBSERVED) - 1899 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
99-22	1'x1' White w/ Wormy Grooves Ceiling Tile (Removed)			Room 217, 217 A & B, 221- 1899 Bldg. (Removed)	ABATED	MISC								
99-23	2'x4' White w/ Wormy Grooves Ceiling Tile	1,200	SF	Room 227 - 1899 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
99-24	2'x4' White w/ Pin Holes Ceiling Tile	400	SF	Engineers Office - 1899 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
99-25	Transite Table Tops (ABATED)			Rooms 23, 29, 124, 127, 129, 224, 229 - 1899 Bldg. ABATED	ABATED	MISC								
99-26	Paperwrap Pipe Insulation	648	LF	Throughout (See Hatching Maps) - 1899 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
99-27	MJP E/F/V on Paperwrap Pipe Insulation	77	FITTING	Throughout (See Hatching Maps) - 1899 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
99-28	Aircell Pipe Insulation	2,840	LF	Rooms 127, 23, 27, 24, & Engineer's Office, Boiler Pump & Sprinkler Rooms, Store Room by 14, basement corridor -	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Lincoln Park High School Unit 46321 Building ID 1620

Address 2001 N. Orchard Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
99-29	MJP E/F/V on Aircell Pipe Insulation	587	FITTING	1899 Bldg. Rooms 127, 23, 27, 24, & Engineer's Office, Boiler Pump & Sprinkler Rooms, Store Room by 14 - 1899 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
99-30	MJP E/F/V on Fiberglass Pipe Insulation	680	FITTING	Boiler & Tank Rooms, Basement Corridor, 127, 129, 124, 122, 29, 24 Closet, Engineers Office - 1899 Bldg.	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
99-31	Mag Block Pipe Insulation	100	LF	Basement Corridor - 1899 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
99-32	MJP E/F/V on Mag Block Pipe Insulation	10	FITTING	Basement Corridor By Plenum Sliding Door - 1899 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
99-33	Water Tank Insulation	300	SF	Boiler Room - 1899 Bldg.	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
99-34	Hardcoat Plaster	100,000	SF	Throughout - 1899 Bldg.	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		MODERATE
99-35	Exterior Window Caulk		LF	Throughout - 1899 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
99-36	Beige Linoleum	5,600	SF	Room 121 (Science Room), 229A, 127, 129, 124, 023, 027 - 1899 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
99-37	Beige Linoleum Mastic	5,600	SF	Room 121 (Science Room), 229A, 127, 129, 124, 023, 027 - 1899 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
99-38	Gray Linoleum - NOT OBSERVED	700	SF	Room 121 - 1899 Bldg. (Not Observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
99-38A	Gray Linoleum Mastic- NOT OBSERVED	700	SF	Room 121 - 1899 Bldg. (Not Observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
99-39	Terrazzo	3,000	SF	Stairwells - 1899 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
99-40	Carpet Mastic (Abated)			Room 112 - Library (Abated)	ABATED	MISC								
99-41	Black Lab Counter Tops	2,200	SF	Room 229, 224 Room 121, 121C,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Lincoln Park High School Unit 46321 Building ID 1620

Address 2001 N. Orchard Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				023, 027 - 1899 Bldg.										
99-42	Fume Hood	160	SF	Rooms 224, 023, 027 - 1899 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
99-43	12"x12" Yellow Speckled VFT	1,400	SF	Rooms 213A, 221, 113A - 1899 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
99-44	12"x12" Yellow Speckled VFT Mastic	1,400	SF	Rooms 213A, 221, 113A - 1899 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
99-45	12"x12" Mixed Beige VFT (Abated)			Room 125, 125 Foyer, Room 122 - 1899 Bldg. (Abated)	ABATED	MISC								
99-46	12"x12" Mixed Beige Speckled VFT Mastic (Abated)			Room 125, 125 Foyer, Room 122 - 1899 Bldg. (Abated)	ABATED	MISC								
99-47	12"x12" Mixed Gray Speckled VFT- (Abated)			1st Floor Counselor's Corridor, 3rd Floor Elevator Lobby, Basement Elevator Lobby - 1899 Bldg. (Abated)	ABATED	MISC								
99-48	12"x12" Mixed Gray Speckled VFT Mastic (Abated)			1st Floor Counselor's Corridor, 3rd Floor Elevator Lobby, Basement Elevator Lobby - 1937 Bldg. (Abated)	ABATED	MISC								
99-49	Drywall System	400	SF	Room 213A - 1899 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
99-50	20"x20" Yellow w/ Streaks VFT	2,500	SF	Rooms 014, 022, 027, 030, 029, 114B, C,D,E,F,G,O,P, 112, 125, 122, 229, 217, 219, 221, 223 and 3rd Floor Corridor - 1899 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
99-51	20"x20" Yellow w/ Streaks VFT Mastic	2,500	SF	Rooms 014, 022, 027, 030, 029, 114B, C,D,E,F,G,O,P, 112, 125, 122, 229, 217, 219, 221, 223 and 3rd Floor Corridor - 1899 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
99-52	20"x20" Brown w/ Streaks VFT	3,000	SF	All Stairwells, 2nd	ASSUMED	MISC	N	NONE	0		No	ACBM with the		MODERATE

Chicago Public Schools

School Lincoln Park High School Unit 46321 Building ID 1620

Address 2001 N. Orchard Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Library, 152 - FA Building (ABATED)										
FA-17	9"x9" Green w/ Black & White Streaks VFT	104	SF	Closet by Boiler Room - FA Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FA-18	9"x9" Green w/ Black & White Streaks VFT Mastic	104	SF	Closet by Boiler Room - FA Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FA-19	9"x9" Black VFT (Abated)			2nd Floor Slop Sink - FA Building (Abated)	ABATED	MISC								
FA-20	9"x9" Black VFT Mastic (Abated)			2nd Floor Slop Sink - FA Building (Abated)	ABATED	MISC								
FA-23	1'x1' Small Hole Ceiling Tile	0	SF	Throughout - FA Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
FA-24	1'x1' Medium Hole Ceiling Tile	0	SF	Throughout - FA Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
FA-25	2'x2' Ceiling Tile	1,600	SF	Lunch Room - FA Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
FA-26	Mag Block Pipe Insulation	5,165	LF	Boiler Room, All Crawlspace and Tunnels - FA Building	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
FA-27	MJP E/F/V on Mag Block Pipe Insulation	285	FITTING	Boiler Room, All Crawlspace and Tunnels - FA Building	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
FA-28	MJP E/F/V on Fiberglass Pipe Insulation	145	FITTING	Northwest Tunnel, Fan Room and Boiler Room - FA Building	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
FA-29	Paperwrap Pipe Insulation	1,680	LF	Tunnels, Boiler Room, & Fan Room - FA Building	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
FA-30	MJP E/F/V on Paperwrap Pipe Insulation	150	FITTING	Tunnels, Boiler Room, & Fan Room - FA Building	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
FA-31	Exterior Window Caulk	300	LF	Throughout - FA Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FA-32	20"x20" Brown w/ Streaks VFT	4,000	SF	1st and 2nd Floor Corridors - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
FA-33	20"x20" Brown w/ Streaks VFT Mastic	4,000	SF	1st and 2nd Floor Corridors - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Lincoln Park High School Unit 46321 Building ID 1620
 Address 2001 N. Orchard Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Building										
FA-34	20"x20" Beige w/ Streaks VFT	4,000	SF	1st and 2nd Floor Corridors - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
FA-35	20"x20" Beige w/ Streaks VFT Mastic	4,000	SF	1st and 2nd Floor Corridors - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FA-36	20"x20" Off White w/ Streaks VFT	4,000	SF	1st and 2nd Floor Corridors - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FA-37	20"x20" Off White w/ Streaks VFT Mastic	4,000	SF	1st and 2nd Floor Corridors - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FA-38	20"x20" Gray w/ Streaks VFT	8,000	SF	Rooms 155, 156, 157, 158, 159, 160, 161, 164, 165, 176, 179, 180, 254, 256, 257, 259, 260, 261, 263, 264 and 267 - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
FA-39	20"x20" Gray w/ Streaks VFT Mastic	8,000	SF	Rooms 155, 156, 157, 158, 159, 160, 161, 164, 165, 176, 179, 180, 254, 256, 257, 269, 260, 261, 263, 264 and 267 - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FA-40	20"x20" Blue w/ Streaks VFT	2,000	SF	Rooms 254, 256, 257, 259, 260, 261, 263, 264 and 267 - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
FA-41	20"x20" Blue w/ Streaks VFT Mastic	2,000	SF	Rooms 254, 256, 257, 259, 260, 261, 263, 264 and 267 - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FA-42	20"x20" Green w/ Streaks VFT	3,500	SF	Rooms 155, 156, 157, 158, 159, 160, 161, 164, 165, 176, 179 and 180 - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
FA-43	20"x20" Green w/ Streaks VFT Mastic	3,500	SF	Rooms 155, 156, 157, 158, 159, 160, 161, 164, 165, 176, 179 and 180 - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Lincoln Park High School Unit 46321 Building ID 1620

Address 2001 N. Orchard Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
FA-44	20"x20" Peach w/ Streaks VFT	8,000	SF	Rooms 155, 156, 157, 158, 159, 160, 161, 164, 165, 176, 179, 180, 254, 256, 257, 259, 260, 261, 263, 264 and 267 - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
FA-45	20"x20" Peach w/ Streaks VFT Mastic	8,000	SF	Rooms 155, 156, 157, 158, 159, 160, 161, 164, 165, 176, 179, 180, 254, 256, 257, 259, 260, 261, 263, 264 and 267 - FA Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FA-46	2'x2' Ceiling Tile	8,000	SF	1st and 2nd Floor Corridors, Room 180C - FA Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
FA-47	12"x12" Blue VFT	400	SF	Room 182 and offices	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
FA-47A	12"x12" Blue VFT mastic	400	SF	Room 182 and offices	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FA-48	12"x12" Yellow VFT	400	SF	Room 182 and offices	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
FA-48A	12"x12" Yellow VFT mastic	400	SF	Room 182 and offices	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-001	9"x9" Beige Floor Tile	800	SF	Engineer's Office (Abated) and Maintenance Room, Basement Corridor Storage Room (Abated) - 1899 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
FTM-001	9"x9" Beige Floor Tile Mastic	800	SF	Engineer's Office and Maintenance Room - 1899 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Lincoln Park High School Unit 46321 Building ID 1620

Address 2001 N. Orchard Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 3/26/2025
Inspector Name Allizon Brooks
100-18790 5/15/2026
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
37-01	
37-02	
37-03	
37-04	
37-05	
37-06	
37-07	
37-08	
37-09	
37-10	
37-11	
37-12	
37-15	
37-16	
37-17	
37-18	
37-19	
37-20	
37-21	
37-22	
37-23	
37-24	
37-25	
37-26	

Chicago Public Schools

School Lincoln Park High School Unit 46321 Building ID 1620

Address 2001 N. Orchard Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
37-27	
37-28	
37-29	
37-30	
37-31	
37-37	
37-38	
37-39	
37-40	
37-41	
37-42	
37-43	
37-44	
37-45	
37-46	
37-47	
37-48	
37-49	
37-50	
37-51	
37-52	
37-53	
37-54	
37-55	
37-56	
37-57	
37-58	
37-59	
37-60	

Chicago Public Schools

School Lincoln Park High School Unit 46321 Building ID 1620

Address 2001 N. Orchard Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
37-61	
37-62	
37-63	
37-64	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
53A	
54	
55	
56	
61-01	
61-02	
61-03	
61-04	
61-05	

Chicago Public Schools

School Lincoln Park High School Unit 46321 Building ID 1620

Address 2001 N. Orchard Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
61-06	
61-07	
61-08	
61-09	
61-10	
61-11	
61-12	
61-13	
61-14	
61-15	
61-16	
61-17	
61-18	
61-19	
61-20	
61-21	
61-22	
61-23	
61-24	
61-25	
61-26	
61-27	
61-28	
61-29	
61-30	
61-31	
61-32	
61-33	
61-34	

Chicago Public Schools

School Lincoln Park High School Unit 46321 Building ID 1620

Address 2001 N. Orchard Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
61-35	
61-36	
61-37	
61-38	
61-39	
61-40	
61-41	
61-42	
61-43	
61-44	
61-45	
61-46	
61-47	
61-48	
61-49	
61-50	
61-51	
61-52	
61-53	
61-54	
61-55	
61-56	
61-57	
61-58	
99-01	
99-02	
99-03	
99-04	
99-05	

Chicago Public Schools

School Lincoln Park High School Unit 46321 Building ID 1620

Address 2001 N. Orchard Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
99-06	
99-07	
99-08	
99-09	
99-10	
99-11	
99-12	
99-13	
99-14	
99-15	
99-16	
99-17	
99-18	
99-19	
99-20	
99-21	
99-22	
99-23	
99-24	
99-25	
99-26	
99-27	
99-28	
99-29	
99-30	
99-31	
99-32	
99-33	
99-34	

Chicago Public Schools

School Lincoln Park High School Unit 46321 Building ID 1620

Address 2001 N. Orchard Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
99-35	
99-36	
99-37	
99-38	
99-38A	
99-39	
99-40	
99-41	
99-42	
99-43	
99-44	
99-45	
99-46	
99-47	
99-48	
99-49	
99-50	
99-51	
99-52	
99-53	
99-54	
99-55	
99-56	
99-57	
99-58	
99-59	
99-60	
99-61	
99-62	

Chicago Public Schools

School Lincoln Park High School Unit 46321 Building ID 1620

Address 2001 N. Orchard Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
99-63	
99-64	good condition
FA-01	
FA-02	
FA-03	
FA-04	
FA-05	
FA-06	
FA-07	
FA-08	
FA-09	
FA-10	
FA-11	
FA-12	
FA-13	
FA-14	
FA-15	
FA-16	
FA-17	
FA-18	
FA-19	
FA-20	
FA-23	
FA-24	
FA-25	
FA-26	
FA-27	
FA-28	
FA-29	

Chicago Public Schools

School Lincoln Park High School Unit 46321 Building ID 1620

Address 2001 N. Orchard Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
FA-30	
FA-31	
FA-32	
FA-33	
FA-34	
FA-35	
FA-36	
FA-37	
FA-38	
FA-39	
FA-40	
FA-41	
FA-42	
FA-43	
FA-44	
FA-45	
FA-46	
FA-47	
FA-47A	
FA-48	
FA-48A	
FT-001	
FTM-001	

Chicago Public Schools

School Lincoln Park High School **Unit** 46321 **Building ID** 1620

Address 2001 N. Orchard **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Lincoln Park High School

Unit 46321

Building ID 1620

Address 2001 N. Orchard

Chicago, IL, 60614

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
37-01	12"x12" Tan w/ Brown & White Specks VFT (Abated)			1st, 2nd & 3rd Floor Corridors, Room 102 - 1937 Bldg. (Abated) 1937	Abated	MISC					
37-02	12"x12" Tan w/ Brown & White Specks VFT Mastic (Abated)			1st, 2nd & 3rd Floor Corridors, Room 102 - 1937 Bldg. (Abated)	Abated	MISC					
37-03	12"x12" Gray w/ Gray Streaks VFT	3,600	SF	2nd Floor Teachers Lounge, Office By Room 207, 207A & Boy's Locker Room - 1937 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-04	12"x12" Gray w/ Gray Streaks VFT Mastic	3,600	SF	2nd Floor Teachers Lounge, Office By Room 207, & Boy's Locker Room - 1937 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-05	12"x12" Beige w/ Brown & White Speckles VFT	6,200	SF	Rooms 111, 103A, Girl's Locker Room - 1937 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-06	12"x12" Beige w/ Brown & White Speckles VFT Mastic	7,200	SF	Rooms 111, 103A, Girl's Locker Room - 1937 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-07	12"x12" Off White w/ Tan Streaks VFT	800	SF	Main Office - 1937 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-08	12"x12" Off White w/ Tan Streaks VFT Mastic	800	SF	Main Office - 1937 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-09	12"x12" Black w/ White Streaks VFT (Not Observed)	800	SF	Main Office - 1937 (Not Observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-10	12"x12" Black w/ White Streaks VFT Mastic (Not Observed)	800	SF	Main Office - 1937 (Not Observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-11	12"x12" Tan w/ Gray Streaks VFT (Abated)			Hallway By Principal's Stairs, Main Office - 1937 Bldg. (Abated)	Abated	MISC					
37-12	12"x12" Tan w/ Gray Streaks VFT Mastic (Abated)			Hallway By Principal's Stairs; Main Office - 1937 Bldg. (Abated)	Abated	MISC					
37-15	9"x9" Brown w/ Gray Streaks VFT (Abated)			Room 103 Rear Office - 1937 Bldg. (Abated)	Abated	MISC					
37-16	9"x9" Brown w/ Gray Streaks VFT Mastic (Abated)			Room 103 Rear Office - 1937 Bldg. (Abated)	Abated	MISC					
37-17	9"x9" Green w/ White Streaks VFT	80	SF	Room 102 Vault - 1937 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-18	9"x9" Green w/ White Streaks VFT Mastic	80	SF	Room 102 Vault - 1937 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-19	9"x9" Gray w/ White Streaks VFT (Abated)			Room 102, 100A, 100 - 1937 Bldg. (Abated)	Abated	MISC					
37-20	9"x9" Gray w/ White Streaks VFT Mastic (Abated)			Room 102, 100A, 100 - 1937 Bldg. (Abated)	Abated	MISC					

Chicago Public Schools

School Lincoln Park High School

Unit 46321

Building ID 1620

Address 2001 N. Orchard

Chicago, IL, 60614

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
37-21	2'x2' Off White Ceiling Tile	4,500	SF	Rooms 308, 301, 111, 312, 106 Throughout - 1937 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-22	Paperwrap Pipe Insulation	1,678	LF	Boy's & Girl's Toilets Pipe Chases, Swimming Pool, Tunnels, & N, W, & E 232 Office Principals Office; Crawlspace - 1937 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
37-23	MJP E/F/V on Paperwrap Pipe Insulation	390	FITTING	Boy's & Girl's Toilets Pipe Chases, Swimming Pool, Tunnels, & N, W, & E Crawlspace - 1937 Bldg.	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
37-24	MJP E/F/V on Fiberglass Pipe Insulation	300	FITTING	106, Pool, Tunnels, Crawlspace, Rifle Storage, Engine Room, Plenum C - 1937 Bldg.	Assumed	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
37-25	Mag Block Pipe Insulation	2,845	LF	Swimming Pool, NS Air Tunnel, NE Crawlspace, Rifle Range & Storage, GMV, Engine Room, & Plenum - 1937 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
37-26	MJP E/F/V on Mag Block Pipe Insulation	164	FITTING	Swimming Pool, NS Air Tunnel, NE Crawlspace, Rifle Range & Storage, GMV, Engine Room, & Plenum - 1937 Bldg.	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
37-27	Air Cell Duct Insulation	6,450	SF	West & NW Crawl Spaces, Rifle Range & Storage - 1937 Bldg.	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-28	Aircell Pipe Insulation	3,025	LF	Basement Corridor, Throughout - 1937 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
37-29	MJP E/F/V on Aircell Pipe Insulation	465	FITTING	Throughout - 1937 Bldg. (See Hatching Maps)	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
37-30	Hard Coat Plaster	120,000	SF	Throughout - 1937 Bldg.	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-31	Exterior Window Caulk	30,000	SF	Throughout - 1937 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-37	Exterior Window Caulk	30,000	SF	Throughout - 1937 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-38	Terrazzo	2,000	SF	Stairwells - 1937 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-39	Carpet Mastic	3,200	SF	Library and Main Office, 207A - 1937 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-40	12"x12" Mixed Gray Speckled VFT (Abated)			Rooms 114K, 134B, 134C - 1937 Bldg.	Abated	MISC					
37-41	12"x12" Mixed Gray Speckled VFT Mastic (Abated)			Rooms 114K, 134B, 134C - 1937 Bldg.	Abated	MISC					
37-42	Beige Linoleum	700	SF	Room 304 - 1937 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-43	Beige Linoleum Mastic	700	SF	Room 304 - 1937 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lincoln Park High School

Unit 46321

Building ID 1620

Address 2001 N. Orchard

Chicago, IL, 60614

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
37-44	14"x14" Gray w/ Black Spots VFT	500	SF	Auditorium Lobby - 1937 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-45	14"x14" Gray w/ Black Spots VFT Mastic	500	SF	Auditorium Lobby - 1937 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-46	2'x2' Ceiling Tile	1,000	SF	Rooms 308, 301 - 1937 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-47	14"x14" Blue Speckled VFT	700	SF	Auditorium - 1937 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-48	14"x14" Blue Speckled VFT Mastic	700	SF	Auditorium - 1937 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-49	12"x12" Mixed Beige Speckled VFT (Abated)			Rooms 308, 206, 110, 108 - 1937 Bldg. (Abated)	Abated	MISC					
37-50	12"x12" Mixed Beige Speckled VFT Mastic (Abated)			Rooms 208, 206, 110, 108 - 1937 Bldg. (Abated)	Abated	MISC					
37-51	20"x20" Yellow w/ Streaks VFT	1,700	SF	Rooms 204, 206, 208, 210, 100, 101, 102, 105C - 1937 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-52	20"x20" Yellow w/ Streaks VFT Mastic	1,700	SF	Rooms 204, 206, 209, 210, 100, 101, 102, 105C - 1937 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-53	20"x20" Brown w/ Streaks VFT	5,000	SF	1st, 2nd and 3rd Floor Corridors - 1937 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-54	20"x20" Brown w/ Streaks VFT Mastic	5,000	SF	1st, 2nd and 3rd Floor Corridors - 1937 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-55	20"x20" Beige w/ Streaks VFT	5,000	SF	1st, 2nd and 3rd Floor Corridors, Room 103B - 1937 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-56	20"x20" Beige w/ Streaks VFT Mastic	5,000	SF	1st, 2nd and 3rd Floor Corridors, Room 103B - 1937 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-57	20"x20" Off White w/ Streaks VFT	3,200	SF	1st, 2nd and 3rd Floor Corridors - 1937 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-58	20"x20" Off White w/ Streaks VFT Mastic	3,200	SF	1st, 2nd and 3rd Floor Corridors - 1937 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-59	20"x20" Gray w/ Streaks VFT	2,600	SF	Rooms 100, 101, 102, 204, 206, 208 and 210 - 1937 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-60	20"x20" Gray w/ Streaks VFT Mastic	2,600	SF	Rooms 100, 101, 102, 204, 206, 208 and 210 - 1937 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-61	20"x20" Blue w/ Streaks VFT	1,400	SF	Rooms 204, 206, 208, 210 - 1937 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-62	20"x20" Blue w/ Streaks VFT Mastic	1,400	SF	Rooms 204, 206, 208, 210 - 1937 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-63	20"x20" Green w/ Streaks VFT	800	SF	Room 101 - 1937 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37-64	20"x20" Green w/ Streaks VFT Mastic	800	SF	Room 101 - 1937 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	12"x12" Off White with Tan Streaks VFT	1,000	SF	162A and B, Councillor's Office - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	12"x12" Off White with Tan Streaks VFT Mastic	1,000	SF	162A and B, Councillor's Office - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lincoln Park High School

Unit 46321

Building ID 1620

Address 2001 N. Orchard

Chicago, IL, 60614

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Building							
40	Linoleum	6,300	SF	Rooms 172 (PKA 152), 252, 257, 250, 251, 253, and Library - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Linoleum Adhesive	6,300	SF	Rooms 172 (PKA 152), 252, 257, 250, 251, 253 and Library - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	Tan Linoleum	700	SF	Rooms 121, 262 & 265	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	Tan Linoleum Adhesive	700	SF	Rooms 121, 262 & 265	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	2' x 4' Lay In Ceiling Panels	700	SF	Rooms 121; 110, 109, 108	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	Insulation in Walls and Vault Door	91	SF	Room 102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	2' x 4' Lay In Ceiling Panels	500	SF	Room 153 - FA Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	Linoleum	305	SF	Science Copy Room - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	Linoleum Adhesive	305	SF	Science Copy Room - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	12"x12" Green with White Floor Tile (Abated)			Room 102 (Abated)	Abated	MISC					
50	12"x12" Green with White Floor Tile Adhesive (Abated)			Room 102 (Abated)	Abated	MISC					
51	12"x12" Gray with White Floor Tile (Abated)			Room 102 (Abated)	Abated	MISC					
52	12"x12" Gray with White Floor Tile Mastic (Abated)			Room 102 (Abated)	Abated	MISC					
53	12"x12" Gray with Gray Floor Tile (Abated)			Room 102 (Abated)	Abated	MISC					
53A	12"x12" Gray with Gray Floor Tile Mastic (Abated)			Room 102 (Abated)	Abated	MISC					
54	12"x12" Ceiling Tile	750	SF	Room 111	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	12"x12" Light Blue with White and Brown Streaks Floor Tile	750	SF	Room 111	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	12"x12" Light Blue with White and Brown Streaks VFT Mastic	750	SF	Room 111	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-01	12"x12" White w/ Grey Speckles VFT			1st Floor West Corridor By Lobby - 1961 Addition	No ACBM	MISC					
61-02	12"x12" White w/ Gray Speckles VFT Mastic			1st Floor West Corridor By Lobby - 1961 Addition	No ACBM	MISC					
61-03	12"x12" Black w/ White Speckles VFT (Abated)			1st Floor West Corridor By Lobby - 1961 Addition (Abated)	Abated	MISC					
61-04	12"x12" Black w/ White Speckles VFT Mastic (Abated)			1st Floor West Corridor By Lobby - 1961 Addition (Abated)	Abated	MISC					
61-05	12"x12" Black w/ White Streaks VFT (Abated)			Auditorium - 1961 Addition (Not observed)	Abated	MISC					
61-06	12"x12" Black w/ White Streaks VFT Mastic (Abated)			Auditorium - 1961 Addition (Not Observed)	Abated	MISC					

Chicago Public Schools

School Lincoln Park High School

Unit 46321

Building ID 1620

Address 2001 N. Orchard

Chicago, IL, 60614

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
61-07	12"x12" Coffee w/ White & Brown Streaks VFT (Abated)			Room 108, Room 257 & North Corridor - 1961 Addition (Abated)	Abated	MISC					
61-08	12"x12" Coffee w/ White & Brown Streaks VFT Mastic (Abated)			Room 108, Room 257 & North Corridor - 1961 Addition (Abated)	Abated	MISC					
61-09	12"x12" Red VFT (Abated)			Lunchroom - 1961 Addition (Abated)	Abated	MISC					
61-10	12"x12" Red VFT Mastic (Abated)			Lunchroom - 1961 Addition (Abated)	Abated	MISC					
61-11	9"x9" Black w/ White Streaks VFT- Abated			West Stairwell & Auditorium Stairwell - 1961 Addition (Not Observed)	Abated	MISC					
61-12	9"x9" Brown w/ White Streaks VFT-Abated			Auditorium Balcony - 1961 Addition (Abated)	Abated	MISC					
61-13	9"x9" Brown w/ White Streaks VFT Mastic (Abated)			Auditorium Balcony - 1961 Addition (Abated)	Abated	MISC					
61-14	9"x9" Gray w/ White Streaks VFT	800	SF	Teacher's Lunchroom - 1937 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-15	9"x9" Gray w/ White Streaks VFT Mastic	800	SF	Teacher's Lunchroom - 1937 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-16	Black w/ White Streaks Linoleum (Abated)			East and West Stairwells, Auditorium Stairwell - 1961 Addition (Abated)	Abated	MISC					
61-17	Black w/ White Streaks Linoleum Mastic (Abated)			East and West Stairwells, Auditorium Stairwell - 1961 Addition (Abated)	Abated	MISC					
61-18	2'x2' White Speckled w/ Inch Wormy Ceiling Tile	10,000	SF	2nd Floor West Corridor - 1961 FA	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-19	1'x1' White Ceiling Tile	7,000	SF	NW & SW Stairwells, Auditorium, Rooms 108, 109 & 110 - 1961 Addition	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-20	1'x1' Off White w/ Speckles Ceiling Tile	6,700	SF	Lunchroom - 1961 Addition	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-21	1'x1' Off White w/ Large Wormy Ceiling Tile	800	SF	Teachers Lunchroom by Kitchen - 1961 Addition	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-22	Air Cell Pipe Insulation	935	LF	NW & NE Crawlspace & Paint Storage - 1961 Addition	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
61-23	MJP E/F/V on Air Cell Pipe Insulation	48	FITTING	NW & NE Crawlspace & Paint Storage - 1961 Addition	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
61-24	Mag Block Pipe Insulation	2,500	LF	NE Crawlspace - 1961 Addition	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
61-25	MJP E/F/V on Mag Block Pipe Insulation	100	FITTING	NE Crawlspace - 1961 Addition	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
61-26	Paperwrap Pipe Insulation	350	LF	NE Crawlspace - 1961 Addition	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
61-27	MJP E/F/V on Paperwrap Pipe Insulation	37	FITTING	NE Crawlspace - 1961 Addition	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
61-28	Aircell Duct Insulation	100	SF	Paint Storage Room - 1961 Addition	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-29	9"x9" Black w/ White Streaks VFT Mastic (Abated)			West Stairwell & Auditorium Stairwell - 1961 Addition (Abated)	Abated	MISC					
61-30	Carpet Mastic	1,000	SF	Engineer's Office and CPS Area Office,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lincoln Park High School

Unit 46321

Building ID 1620

Address 2001 N. Orchard

Chicago, IL, 60614

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				182 - FA Building							
61-31	2'x2' Dot Wave Ceiling Tile (NOT OBSERVED)	500	SF	Room 153 - FA Building (Not Observed)	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-32	Lab Counter Tops	200	SF	Rooms 252, 251 - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-33	9"x9" Gray w/ White Streaks VFT	40	SF	Room 258A - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-34	9"x9" Gray w/ White Streaks VFT Mastic	40	SF	Room 258A - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-35	12"x12" Gray Speckled VFT	500	SF	Room 163C - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-36	12"x12" Gray Speckled VFT Mastic	500	SF	Room 163C - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-37	12"x12" Mixed Beige Speckled VFT	1,000	SF	Room 180 and 180A - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-38	12"x12" Mixed Beige Mastic	1,000	SF	Room 180 and 180A - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-39	12"x12" Brown Speckled VFT	500	SF	Rooms 170 and 172 - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-40	12"x12" Brown Speckled VFT Mastic	500	SF	Rooms 170 and 172 - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-41	12"x12" Blue w/ Black and White Specs VFT	600	SF	Room 154 - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-42	12"x12" Blue w/ Black and White Specs VFT Mastic	600	SF	Room 154 - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-43	20"x20" Yellow w/ Streaks VFT	1,000	SF	Room 109 and 110 - 1961 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-44	20"x20" Yellow w/ Streaks VFT Mastic	1,000	SF	Rooms 109 and 110 - 1961 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-45	20"x20" Brown w/ Streaks VFT	1,200	SF	1st Floor Corridor - 1961 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-46	20"x20" Brown w/ Streaks VFT Mastic	1,200	SF	1st Floor Corridor - 1961 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-47	20"x20" Beige w/ Streaks VFT	1,200	SF	1st Floor Corridor - 1961 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-48	20"x20" Beige w/ Streaks VFT Mastic	1,200	SF	1st Floor Corridor - 1961 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-49	20"x20" Off White w/ Streaks VFT	1,200	SF	1st Floor Corridor - 1961 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-50	20"x20" Off White w/ Streaks VFT Mastic	1,200	SF	1st Floor Corridor - 1961 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-51	20"x20" Gray w/ Streaks VFT	800	SF	Rooms 109 and 110 - 1961 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-52	20"x20" Gray w/ Streaks VFT Mastic	800	SF	Rooms 109 and 110 - 1961 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-53	20"x20" Green w/ Streaks VFT	2,400	SF	Rooms 109, 110 and Cafeteria - 1961 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-54	20"x20" Green w/ Streaks VFT Mastic	2,400	SF	Rooms 109, 110 and Cafeteria - 1961 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-55	20"x20" Dark Green w/ Streaks VFT	1,200	SF	Cafeteria - 1961 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-56	20"x20" Dark Green w/ Streaks VFT Mastic	1,200	SF	Cafeteria - 1961 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-57	20"x20" Royal Blue w/ Streaks VFT	1,200	SF	Cafeteria - 1961 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61-58	20"x20" Royal Blue w/ Streaks VFT Mastic	1,200	SF	Cafeteria - 1961 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-01	12"x12" Gray w/ White Specks VFT	1,200	SF	1st, 2nd, & 3rd Floor Corridors (Abated), Room 229 (Not Observed), 2nd Floor women's toilet, & 113A -	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lincoln Park High School

Unit 46321

Building ID 1620

Address 2001 N. Orchard

Chicago, IL, 60614

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
99-02	12"x12" Gray w/ White Specks VFT Mastic	1,200	SF	1899 Bldg. 1st, 2nd, & 3rd Floor Corridors (Abated), Room 229 (Not Observed), 2nd Floor Women's Toilet & 113A - 1899 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-03	12"x12" White w/ Gray Specks VFT (Abated)			Room 215 - 1899 Bldg. (Abated)	Abated	MISC					
99-04	12"x12" White w/ Gray Specks VFT Mastic (Abated)			Room 215 - 1899 Bldg. (Abated)	Abated	MISC					
99-05	12"x12" Beige w/ Brown Specks VFT-(Abated)			Rooms 223, 217, 219, 217A, 224, & storage 217B & C - 1899 Bldg. (Abated)	Abated	MISC					
99-06	12"x12" Beige w/ Brown Specks VFT Mastic (Abated)			Rooms 223, 217, 219, 217A, 224, & 224 Storage 217B & C - 1899 Bldg. (Abated)	Abated	MISC					
99-07	12"x12" Light Brown w/ Brown & White Specks VFT (Abated)			Room 113A - 1899 Bldg. (Abated)	Abated	MISC					
99-08	12"x12" Light Brown w/ Brown & White Specks VFT Mastic (Abated)			Room 113A - 1899 Bldg. (Abated)	Abated	MISC					
99-09	12"x12" Brown w/ White Streaks VFT	400	SF	Room 112 - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-10	12"x12" Brown w/ White Streaks VFT Mastic	400	SF	Room 112 - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-11	12"x12" Off White w/ Light Brown Streaks VFT (Abated)			Room 14 Foyer, 29, 23 - 1899 Bldg. (Abated)	Abated	MISC					
99-12	12"x12" Off White w/ Light Brown Streaks VFT Mastic (Abated)			Room 14 Foyer, 29, 23 - 1899 Bldg. (Abated)	Abated	MISC					
99-13	9"x9" Tan w/ Brown & White Streaks VFT (Abated)			Throughout - 1899 (See Hatching Maps) 119, 114 A & B & C, D, E, F, G, 022, 032, 036, Counselors Corridor (Abated)	Abated	MISC					
99-14	9"x9" Tan w/ Brown & White Streaks VFT Mastic (Abated)			Throughout - 1899 Bldg. (Abated)	Abated	MISC					
99-15	9"x9" Green w/ White Streaks VFT (NOT OBSERVED)	305	SF	Science Copy Room - 1899 Bldg. (Not Observed)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-16	9"x9" Green w/ White Streaks VFT Mastic (NOT OBSERVED)	305	SF	Science Copy Room - 1899 Bldg. (Not Observed)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-17	9"x9" Tan VFT (Abated)			Room 14 (Under HA 99-10), Room 127A & 129A 1899 Bldg. (Abated)	Abated	MISC					

Chicago Public Schools

School Lincoln Park High School

Unit 46321

Building ID 1620

Address 2001 N. Orchard

Chicago, IL, 60614

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
99-18	9"x9" Tan VFT Mastic (Abated)			Room 14 (Under HA 99-10) 1899 Bldg. (Abated)	Abated	MISC					
99-19	9"x9" Rust VFT (Abated)			Room 14 (Under HA 99-10 and 99-17) - 1899 Bldg. (Abated)	Abated	MISC					
99-20	9"x9" Rust VFT Mastic (Abated)			Room 14 (Under HA 99-10 and 99-17) - 1899 Bldg. (Abated)	Abated	MISC					
99-21	2'x2' White w/ Wormy Grooves Ceiling Tile	1,200	SF	Library, Work Room A & B, 221 (NOT OBSERVED) - 1899 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-22	1'x1' White w/ Wormy Grooves Ceiling Tile (Removed)			Room 217, 217 A & B, 221- 1899 Bldg. (Removed)	Abated	MISC					
99-23	2'x4' White w/ Wormy Grooves Ceiling Tile	1,200	SF	Room 227 - 1899 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-24	2'x4' White w/ Pin Holes Ceiling Tile	400	SF	Engineers Office - 1899 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-25	Transite Table Tops (ABATED)			Rooms 23, 29, 124, 127, 129, 224, 229 - 1899 Bldg. ABATED	Abated	MISC					
99-26	Paperwrap Pipe Insulation	648	LF	Throughout (See Hatching Maps) - 1899 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
99-27	MJP E/F/V on Paperwrap Pipe Insulation	77	FITTING	Throughout (See Hatching Maps) - 1899 Bldg.	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
99-28	Aircell Pipe Insulation	2,840	LF	Rooms 127, 23, 27, 24, & Engineer's Office, Boiler Pump & Sprinkler Rooms, Store Room by 14, basement corridor - 1899 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
99-29	MJP E/F/V on Aircell Pipe Insulation	587	FITTING	Rooms 127, 23, 27, 24, & Engineer's Office, Boiler Pump & Sprinkler Rooms, Store Room by 14 - 1899 Bldg.	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
99-30	MJP E/F/V on Fiberglass Pipe Insulation	680	FITTING	Boiler & Tank Rooms, Basement Corridor, 127, 129, 124, 122, 29, 24 Closet, Engineers Office - 1899 Bldg.	Assumed	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
99-31	Mag Block Pipe Insulation	100	LF	Basement Corridor - 1899 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
99-32	MJP E/F/V on Mag Block Pipe Insulation	10	FITTING	Basement Corridor By Plenum Sliding Door - 1899 Bldg.	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
99-33	Water Tank Insulation	300	SF	Boiler Room - 1899 Bldg.	Assumed	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-34	Hardcoat Plaster	100,000	SF	Throughout - 1899 Bldg.	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-35	Exterior Window Caulk		LF	Throughout - 1899 Bldg.	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
99-36	Beige Linoleum	5,600	SF	Room 121 (Science Room), 229A, 127, 129, 124, 023, 027 - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lincoln Park High School

Unit 46321

Building ID 1620

Address 2001 N. Orchard

Chicago, IL, 60614

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
99-37	Beige Linoleum Mastic	5,600	SF	Room 121 (Science Room), 229A, 127, 129, 124, 023, 027 - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-38	Gray Linoleum - NOT OBSERVED	700	SF	Room 121 - 1899 Bldg. (Not Observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-38A	Gray Linoleum Mastic- NOT OBSERVED	700	SF	Room 121 - 1899 Bldg. (Not Observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-39	Terrazzo	3,000	SF	Stairwells - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-40	Carpet Mastic (Abated)			Room 112 - Library (Abated)	Abated	MISC					
99-41	Black Lab Counter Tops	2,200	SF	Room 229, 224 Room 121, 121C, 023, 027 - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-42	Fume Hood	160	SF	Rooms 224, 023, 027 - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-43	12"x12" Yellow Speckled VFT	1,400	SF	Rooms 213A, 221, 113A - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-44	12"x12" Yellow Speckled VFT Mastic	1,400	SF	Rooms 213A, 221, 113A - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-45	12"x12" Mixed Beige VFT (Abated)			Room 125, 125 Foyer, Room 122 - 1899 Bldg. (Abated)	Abated	MISC					
99-46	12"x12" Mixed Beige Speckled VFT Mastic (Abated)			Room 125, 125 Foyer, Room 122 - 1899 Bldg. (Abated)	Abated	MISC					
99-47	12"x12" Mixed Gray Speckled VFT-(Abated)			1st Floor Counselor's Corridor, 3rd Floor Elevator Lobby, Basement Elevator Lobby - 1899 Bldg. (Abated)	Abated	MISC					
99-48	12"x12" Mixed Gray Speckled VFT Mastic (Abated)			1st Floor Counselor's Corridor, 3rd Floor Elevator Lobby, Basement Elevator Lobby - 1937 Bldg. (Abated)	Abated	MISC					
99-49	Drywall System	400	SF	Room 213A - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-50	20"x20" Yellow w/ Streaks VFT	2,500	SF	Rooms 014, 022, 027, 030, 029, 114B, C,D,E,F,G,O,P, 112, 125, 122, 229, 217, 219, 221, 223 and 3rd Floor Corridor - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-51	20"x20" Yellow w/ Streaks VFT Mastic	2,500	SF	Rooms 014, 022, 027, 030, 029, 114B, C,D,E,F,G,O,P, 112, 125, 122, 229, 217, 219, 221, 223 and 3rd Floor Corridor - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-52	20"x20" Brown w/ Streaks VFT	3,000	SF	All Stairwells, 2nd and 3rd Floor Corridors - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-53	20"x20" Brown w/ Streaks VFT Mastic	3,000	SF	All Stairwells, 2nd and 3rd Floor Corridors - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-54	20"x20" Beige w/ Streaks VFT	3,000	SF	1st, 2nd and 3rd Floor Corridors - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lincoln Park High School

Unit 46321

Building ID 1620

Address 2001 N. Orchard

Chicago, IL, 60614

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
99-55	20"x20" Beige w/ Streaks VFT Mastic	3,000	SF	1st, 2nd and 3rd Floor Corridors - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-56	20"x20" Off White w/ Streaks VFT	3,000	SF	1st, 2nd and 3rd Floor Corridors - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-57	20"x20" Off White w/ Streaks VFT Mastic	3,000	SF	1st, 2nd and 3rd Floor Corridors - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-58	20"x20" Gray w/ Streaks VFT	3,200	SF	Rooms 014, 022, 027, 029, 030, 114 A, B, C, D, E, F, G, H, O, P, 122, 125, 217, 219, 221, 223 and 229 - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-59	20"x20" Gray w/ Streaks VFT Mastic	3,200	SF	Rooms 014, 022, 027, 029, 030, 114A, B, C, D, E, F, G, H, O, P, 122, 125, 217, 219, 221, 223, 229 - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-60	20"x20" Blue w/ Streaks VFT	1,000	SF	Rooms 112, 217, 219, 221, 223 and 229 - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-61	20"x20" Blue w/ Streaks VFT Mastic	1,000	SF	Rooms 112, 217, 219, 221, 223 and 229 - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-62	20"x20" Green w/ Streaks VFT	600	SF	Rooms 122 and 125 - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-63	20"x20" Green w/ Streaks VFT Mastic	600	SF	Rooms 122 and 125 - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99-64	Brown Laminate Wood Flooring	800	SF	Engineer Office/storage closet	Assumed	MISC		0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-01	12"x12" Black w/ White Streaks VFT (Abated)			1st & 2nd Floor Corridors - FA Building (Abated)	Abated	MISC					
FA-02	12"x12" Black w/ White Streaks VFT Mastic (Abated)			1st & 2nd Floor Corridors - FA Building (Abated)	Abated	MISC					
FA-03	12"x12" White w/ Tan Streaks VFT			Band Room, ROTC, 153, 151, 155, 157, 159, 161, 163A, 253 - FA Building	Abated	MISC					
FA-04	12"x12" White w/ Tan Streaks VFT Mastic			Band Room, ROTC, 153, 151, 155, 157, 159, 161, 163A, 253 - FA Building	Abated	MISC					
FA-05	12"x12" Cream w/ Tan & White Streaks VFT (NOT OBSERVED)	6,300	SF	Gym - FA Building (Not Observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-06	12"x12" Cream w/ Tan & White Streaks VFT Mastic (NOT OBSERVED)	6,300	SF	Gym - FA Building (Not Observed)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-07	12"x12' White w/ Gray Speckles VFT (Abated)			Lunch Room, 164 - FA Building (Abated)	Abated	MISC					
FA-08	12"x12' White w/ Gray Speckles VFT Mastic (Abated)			Lunch Room, 164 - FA Building (Abated)	Abated	MISC					
FA-09	12"x12" Black w/ White Speckles VFT (Abated)			Lunch Room, 164 - FA Building	Abated	MISC					

Chicago Public Schools

School Lincoln Park High School

Unit 46321

Building ID 1620

Address 2001 N. Orchard

Chicago, IL, 60614

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				(Abated)							
FA-10	12"x12" Black w/ White Speckles VFT Mastic (Abated)			Lunch Room, 164 - FA Building (Abated)	Abated	MISC					
FA-11	9"x9" Beige w/ White Spots VFT (Abated)			Throughout - FA Building (Abated)	Abated	MISC					
FA-12	9"x9" Beige w/ White Spots VFT Mastic (Abated)			Throughout - FA Building (Abated)	Abated	MISC					
FA-13	9"x9" Gray w/ Black Streaks VFT	104	SF	Closet by Boiler Room - FA Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-14	9"x9" Gray w/ Black Streaks VFT Mastic	104	SF	Closet by Boiler Room - FA Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-15	9"x9" Beige w/ Orange & White Spots VFT (ABATED)			Rooms 252, Counselors Office, Library, 152 - FA Building (ABATED)	Abated	MISC					
FA-16	9"x9" Beige w/ Orange & White Spots VFT Mastic (Abated)			Rooms 252, Counselors Office, Library, 152 - FA Building (ABATED)	Abated	MISC					
FA-17	9"x9" Green w/ Black & White Streaks VFT	104	SF	Closet by Boiler Room - FA Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-18	9"x9" Green w/ Black & White Streaks VFT Mastic	104	SF	Closet by Boiler Room - FA Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-19	9"x9" Black VFT (Abated)			2nd Floor Slop Sink - FA Building (Abated)	Abated	MISC					
FA-20	9"x9" Black VFT Mastic (Abated)			2nd Floor Slop Sink - FA Building (Abated)	Abated	MISC					
FA-23	1'x1' Small Hole Ceiling Tile	0	SF	Throughout - FA Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-24	1'x1' Medium Hole Ceiling Tile	0	SF	Throughout - FA Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-25	2'x2' Ceiling Tile	1,600	SF	Lunch Room - FA Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-26	Mag Block Pipe Insulation	5,165	LF	Boiler Room, All Crawlspace and Tunnels - FA Building	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
FA-27	MJP E/F/V on Mag Block Pipe Insulation	285	FITTING	Boiler Room, All Crawlspace and Tunnels - FA Building	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
FA-28	MJP E/V/F on Fiberglass Pipe Insulation	145	FITTING	Northwest Tunnel, Fan Room and Boiler Room - FA Building	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
FA-29	Paperwrap Pipe Insulation	1,680	LF	Tunnels, Boiler Room, & Fan Room - FA Building	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
FA-30	MJP E/F/V on Paperwrap Pipe Insulation	150	FITTING	Tunnels, Boiler Room, & Fan Room - FA Building	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
FA-31	Exterior Window Caulk	300	LF	Throughout - FA Building	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
FA-32	20"x20" Brown w/ Streaks VFT	4,000	SF	1st and 2nd Floor Corridors - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-33	20"x20" Brown w/ Streaks VFT Mastic	4,000	SF	1st and 2nd Floor Corridors - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-34	20"x20" Beige w/ Streaks VFT	4,000	SF	1st and 2nd Floor Corridors - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lincoln Park High School

Unit 46321

Building ID 1620

Address 2001 N. Orchard

Chicago, IL, 60614

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Building							
FA-35	20"x20" Beige w/ Streaks VFT Mastic	4,000	SF	1st and 2nd Floor Corridors - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-36	20"x20" Off White w/ Streaks VFT	4,000	SF	1st and 2nd Floor Corridors - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-37	20"x20" Off White w/ Streaks VFT Mastic	4,000	SF	1st and 2nd Floor Corridors - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-38	20"x20" Gray w/ Streaks VFT	8,000	SF	Rooms 155, 156, 157, 158, 159, 160, 161, 164, 165, 176, 179, 180, 254, 256, 257, 259, 260, 261, 263, 264 and 267 - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-39	20"x20" Gray w/ Streaks VFT Mastic	8,000	SF	Rooms 155, 156, 157, 158, 159, 160, 161, 164, 165, 176, 179, 180, 254, 256, 257, 269, 260, 261, 263, 264 and 267 - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-40	20"x20" Blue w/ Streaks VFT	2,000	SF	Rooms 254, 256, 257, 259, 260, 261, 263, 264 and 267 - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-41	20"x20" Blue w/ Streaks VFT Mastic	2,000	SF	Rooms 254, 256, 257, 259, 260, 261, 263, 264 and 267 - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-42	20"x20" Green w/ Streaks VFT	3,500	SF	Rooms 155, 156, 157, 158, 159, 160, 161, 164, 165, 176, 179 and 180 - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-43	20"x20" Green w/ Streaks VFT Mastic	3,500	SF	Rooms 155, 156, 157, 158, 159, 160, 161, 164, 165, 176, 179 and 180 - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-44	20"x20" Peach w/ Streaks VFT	8,000	SF	Rooms 155, 156, 157, 158, 159, 160, 161, 164, 165, 176, 179, 180, 254, 256, 257, 259, 260, 261, 263, 264 and 267 - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-45	20"x20" Peach w/ Streaks VFT Mastic	8,000	SF	Rooms 155, 156, 157, 158, 159, 160, 161, 164, 165, 176, 179, 180, 254, 256, 257, 259, 260, 261, 263, 264 and 267 - FA Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-46	2'x2' Ceiling Tile	8,000	SF	1st and 2nd Floor Corridors, Room 180C - FA Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-47	12"x12" Blue VFT	400	SF	Room 182 and offices	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lincoln Park High School

Unit 46321

Building ID 1620

Address 2001 N. Orchard

Chicago, IL, 60614

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
FA-47A	12"x12" Blue VFT mastic	400	SF	Room 182 and offices	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-48	12"x12" Yellow VFT	400	SF	Room 182 and offices	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FA-48A	12"x12" Yellow VFT mastic	400	SF	Room 182 and offices	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-001	9"x9" Beige Floor Tile	800	SF	Engineer's Office (Abated) and Maintenance Room, Basement Corridor Storage Room (Abated) - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-001	9"x9" Beige Floor Tile Mastic	800	SF	Engineer's Office and Maintenance Room - 1899 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lincoln Park High School
Address 2001 N. Orchard

Unit 46321
 Chicago, IL, 60614

Building ID 1620
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

Review Date	4/16/2025
Manager Planner Name	Jigar Shah
100-07342	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
37-01	
37-02	
37-03	
37-04	
37-05	
37-06	
37-07	
37-08	
37-09	
37-10	
37-11	
37-12	
37-15	
37-16	
37-17	
37-18	
37-19	
37-20	
37-21	
37-22	
37-23	
37-24	
37-25	
37-26	
37-27	
37-28	

Chicago Public Schools

School Lincoln Park High School

Unit 46321

Building ID 1620

Address 2001 N. Orchard

Chicago, IL, 60614

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
37-29	
37-30	
37-31	
37-37	
37-38	
37-39	
37-40	
37-41	
37-42	
37-43	
37-44	
37-45	
37-46	
37-47	
37-48	
37-49	
37-50	
37-51	
37-52	
37-53	
37-54	
37-55	
37-56	
37-57	
37-58	
37-59	
37-60	

Chicago Public Schools

School Lincoln Park High School

Unit 46321

Building ID 1620

Address 2001 N. Orchard

Chicago, IL, 60614

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
37-61	
37-62	
37-63	
37-64	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
53A	
54	
55	
56	
61-01	
61-02	
61-03	

Chicago Public Schools

School Lincoln Park High School

Unit 46321

Building ID 1620

Address 2001 N. Orchard

Chicago, IL, 60614

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
61-04	
61-05	
61-06	
61-07	
61-08	
61-09	
61-10	
61-11	
61-12	
61-13	
61-14	
61-15	
61-16	
61-17	
61-18	
61-19	
61-20	
61-21	
61-22	
61-23	
61-24	
61-25	
61-26	
61-27	
61-28	
61-29	
61-30	

Chicago Public Schools

School Lincoln Park High School

Unit 46321

Building ID 1620

Address 2001 N. Orchard

Chicago, IL, 60614

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
61-31	
61-32	
61-33	
61-34	
61-35	
61-36	
61-37	
61-38	
61-39	
61-40	
61-41	
61-42	
61-43	
61-44	
61-45	
61-46	
61-47	
61-48	
61-49	
61-50	
61-51	
61-52	
61-53	
61-54	
61-55	
61-56	
61-57	

Chicago Public Schools

School Lincoln Park High School

Unit 46321

Building ID 1620

Address 2001 N. Orchard

Chicago, IL, 60614

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
61-58	
99-01	
99-02	
99-03	
99-04	
99-05	
99-06	
99-07	
99-08	
99-09	
99-10	
99-11	
99-12	
99-13	
99-14	
99-15	
99-16	
99-17	
99-18	
99-19	
99-20	
99-21	
99-22	
99-23	
99-24	
99-25	
99-26	

Chicago Public Schools

School Lincoln Park High School

Unit 46321

Building ID 1620

Address 2001 N. Orchard

Chicago, IL, 60614

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
99-27	
99-28	
99-29	
99-30	
99-31	
99-32	
99-33	
99-34	
99-35	
99-36	
99-37	
99-38	
99-38A	
99-39	
99-40	
99-41	
99-42	
99-43	
99-44	
99-45	
99-46	
99-47	
99-48	
99-49	
99-50	
99-51	
99-52	

Chicago Public Schools

School Lincoln Park High School

Unit 46321

Building ID 1620

Address 2001 N. Orchard

Chicago, IL, 60614

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
99-53	
99-54	
99-55	
99-56	
99-57	
99-58	
99-59	
99-60	
99-61	
99-62	
99-63	
99-64	
FA-01	
FA-02	
FA-03	
FA-04	
FA-05	
FA-06	
FA-07	
FA-08	
FA-09	
FA-10	
FA-11	
FA-12	
FA-13	
FA-14	
FA-15	

Chicago Public Schools

School Lincoln Park High School

Unit 46321

Building ID 1620

Address 2001 N. Orchard

Chicago, IL, 60614

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
FA-16	
FA-17	
FA-18	
FA-19	
FA-20	
FA-23	
FA-24	
FA-25	
FA-26	
FA-27	
FA-28	
FA-29	
FA-30	
FA-31	
FA-32	
FA-33	
FA-34	
FA-35	
FA-36	
FA-37	
FA-38	
FA-39	
FA-40	
FA-41	
FA-42	
FA-43	
FA-44	

Chicago Public Schools

School Lincoln Park High School

Unit 46321

Building ID 1620

Address 2001 N. Orchard

Chicago, IL, 60614

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
FA-45	
FA-46	
FA-47	
FA-47A	
FA-48	
FA-48A	
FT-001	
FTM-001	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Chicago Public Schools

Specialty Consulting, Inc.

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-01**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown & White Specks VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors, Room 102 - 1937 Bldg. (Abated)**
1937

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-01**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown & White Specks VFT (Abated)**
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors, Room 102 - 1937 Bldg. (Abated)**
1937

MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-02**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown & White Specks VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors, Room 102 - 1937 Bldg. (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-02**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown & White Specks VFT Mastic (Abated)**
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors, Room 102 - 1937 Bldg. (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-03**
MATERIAL DESCRIPTION: **12"x12" Gray w/ Gray Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **2nd Floor Teachers Lounge, Office By Room 207, 207A & Boy's Locker Room - 1937 Bldg.**

MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-03**
MATERIAL DESCRIPTION: **12"x12" Gray w/ Gray Streaks VFT**
MATERIAL LOCATION: **2nd Floor Teachers Lounge, Office By Room 207, 207A & Boy's Locker Room - 1937 Bldg.**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-04**
MATERIAL DESCRIPTION: **12"x12" Gray w/ Gray Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd Floor Teachers Lounge, Office By Room 207, & Boy's Locker Room - 1937 Bldg.**

MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-04**
MATERIAL DESCRIPTION: **12"x12" Gray w/ Gray Streaks VFT Mastic**
MATERIAL LOCATION: **2nd Floor Teachers Lounge, Office By Room 207, & Boy's Locker Room - 1937 Bldg.**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-05**
MATERIAL DESCRIPTION: **12"x12" Beige w/ Brown & White Speckles VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 111, 103A, Girl's Locker Room - 1937 Bldg.**
MATERIAL QUANTITY: **6200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-05**
MATERIAL DESCRIPTION: **12"x12" Beige w/ Brown & White Speckles VFT**
MATERIAL LOCATION: **Rooms 111, 103A, Girl's Locker Room - 1937 Bldg.**
MATERIAL QUANTITY: **6200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-06**
MATERIAL DESCRIPTION: **12"x12" Beige w/ Brown & White Speckles VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 111, 103A, Girl's Locker Room - 1937 Bldg.**

MATERIAL QUANTITY: **7200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-06**
MATERIAL DESCRIPTION: **12"x12" Beige w/ Brown & White Speckles VFT Mastic**
MATERIAL LOCATION: **Rooms 111, 103A, Girl's Locker Room - 1937 Bldg.**
MATERIAL QUANTITY: **7200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-07**
MATERIAL DESCRIPTION: **12"x12" Off White w/ Tan Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Main Office - 1937 Bldg.**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-07**
MATERIAL DESCRIPTION: **12"x12" Off White w/ Tan Streaks VFT**
MATERIAL LOCATION: **Main Office - 1937 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-08**
MATERIAL DESCRIPTION: **12"x12" Off White w/ Tan Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office - 1937 Bldg.**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-08**
MATERIAL DESCRIPTION: **12"x12" Off White w/ Tan Streaks VFT Mastic**
MATERIAL LOCATION: **Main Office - 1937 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-09**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Streaks VFT (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Main Office - 1937 (Not Observed)**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-09**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Streaks VFT (Not Observed)**
MATERIAL LOCATION: **Main Office - 1937 (Not Observed)**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-10**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Streaks VFT Mastic (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office - 1937 (Not Observed)**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-10**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Streaks VFT Mastic (Not Observed)**
MATERIAL LOCATION: **Main Office - 1937 (Not Observed)**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-11**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Gray Streaks VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Hallway By Principal's Stairs, Main Office - 1937 Bldg. (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-11**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Gray Streaks VFT (Abated)**
MATERIAL LOCATION: **Hallway By Principal's Stairs, Main Office - 1937 Bldg. (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-12**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Gray Streaks VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Hallway By Principal's Stairs; Main Office - 1937 Bldg. (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-12**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Gray Streaks VFT Mastic (Abated)**
MATERIAL LOCATION: **Hallway By Principal's Stairs; Main Office - 1937 Bldg. (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-15**
MATERIAL DESCRIPTION: **9"x9" Brown w/ Gray Streaks VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 103 Rear Office - 1937 Bldg. (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-15**
MATERIAL DESCRIPTION: **9"x9" Brown w/ Gray Streaks VFT (Abated)**
MATERIAL LOCATION: **Room 103 Rear Office - 1937 Bldg. (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-16**
MATERIAL DESCRIPTION: **9"x9" Brown w/ Gray Streaks VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 103 Rear Office - 1937 Bldg. (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-16**
MATERIAL DESCRIPTION: **9"x9" Brown w/ Gray Streaks VFT Mastic (Abated)**
MATERIAL LOCATION: **Room 103 Rear Office - 1937 Bldg. (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-17**
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 102 Vault - 1937 Bldg.**

MATERIAL QUANTITY: **80**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-17**
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT**
MATERIAL LOCATION: **Room 102 Vault - 1937 Bldg.**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-18**
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 102 Vault - 1937 Bldg.**

MATERIAL QUANTITY: **80**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-18**
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT Mastic**
MATERIAL LOCATION: **Room 102 Vault - 1937 Bldg.**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-19**
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 102, 100A, 100 - 1937 Bldg. (Abated)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-19**
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks VFT (Abated)**
MATERIAL LOCATION: **Room 102, 100A, 100 - 1937 Bldg. (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-20**
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 102, 100A, 100 - 1937 Bldg. (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-20**

MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks VFT Mastic (Abated)**

MATERIAL LOCATION: **Room 102, 100A, 100 - 1937 Bldg. (Abated)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-21**
MATERIAL DESCRIPTION: **2'x2' Off White Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 308, 301, 111, 312, 106 Throughout - 1937 Bldg.**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-21**
MATERIAL DESCRIPTION: **2'x2' Off White Ceiling Tile**
MATERIAL LOCATION: **Rooms 308, 301, 111, 312, 106 Throughout - 1937 Bldg.**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-22**
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Boy's & Girl's Toilets Pipe Chases, Swimming Pool, Tunnels, & N, W, & E 232 Office Principals Office; Crawlspace - 1937 Bldg.**

MATERIAL QUANTITY: **1678** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-22**
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**
MATERIAL LOCATION: **Boy's & Girl's Toilets Pipe Chases, Swimming Pool, Tunnels, & N, W, & E 232 Office Principals Office; Crawlspace - 1937 Bldg.**
MATERIAL QUANTITY: **1678** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-23**
MATERIAL DESCRIPTION: **MJP E/F/V on Paperwrap Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Boy's & Girl's Toilets Pipe Chases, Swimming Pool, Tunnels, & N, W, & E Crawlspace - 1937 Bldg.**

MATERIAL QUANTITY: **390** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-23**
MATERIAL DESCRIPTION: **MJP E/F/V on Paperwrap Pipe Insulation**
MATERIAL LOCATION: **Boy's & Girl's Toilets Pipe Chases, Swimming Pool, Tunnels, & N, W, & E Crawlspace - 1937 Bldg.**
MATERIAL QUANTITY: **390** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-24**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **106, Pool, Tunnels, Crawlspace, Rifle Storage, Engine Room, Plenum C - 1937 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-24**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **106, Pool, Tunnels, Crawlspace, Rifle Storage, Engine Room, Plenum C - 1937 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-25**
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Swimming Pool, NS Air Tunnel, NE Crawlspace, Rifle Range & Storage, GMV, Engine Room, & Plenum - 1937 Bldg.**

MATERIAL QUANTITY: **2845** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-25**
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**
MATERIAL LOCATION: **Swimming Pool, NS Air Tunnel, NE Crawlspace, Rifle Range & Storage, GMV, Engine Room, & Plenum - 1937 Bldg.**
MATERIAL QUANTITY: **2845** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-26**
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Swimming Pool, NS Air Tunnel, NE Crawlspace, Rifle Range & Storage, GMV, Engine Room, & Plenum - 1937 Bldg.**

MATERIAL QUANTITY: **164** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-26**
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**
MATERIAL LOCATION: **Swimming Pool, NS Air Tunnel, NE Crawlspace, Rifle Range & Storage, GMV, Engine Room, & Plenum - 1937 Bldg.**
MATERIAL QUANTITY: **164** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-27**
MATERIAL DESCRIPTION: **Air Cell Duct Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **West & NW Crawl Spaces, Rifle Range & Storage - 1937 Bldg.**
MATERIAL QUANTITY: **6450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-27**
MATERIAL DESCRIPTION: **Air Cell Duct Insulation**
MATERIAL LOCATION: **West & NW Crawl Spaces, Rifle Range & Storage - 1937 Bldg.**
MATERIAL QUANTITY: **6450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-28**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Basement Corridor, Throughout - 1937 Bldg.**
MATERIAL QUANTITY: **3025** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-28**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Basement Corridor, Throughout - 1937 Bldg.**
MATERIAL QUANTITY: **3025** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-29**
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Throughout - 1937 Bldg. (See Hatching Maps)**

MATERIAL QUANTITY: **465** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-29**
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**
MATERIAL LOCATION: **Throughout - 1937 Bldg. (See Hatching Maps)**
MATERIAL QUANTITY: **465** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-30**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout - 1937 Bldg.**
MATERIAL QUANTITY: **120000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-30**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
MATERIAL LOCATION: **Throughout - 1937 Bldg.**
MATERIAL QUANTITY: **120000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-31**
MATERIAL DESCRIPTION: **Exterior Window Caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout - 1937 Bldg.**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-31**
MATERIAL DESCRIPTION: **Exterior Window Caulk**
MATERIAL LOCATION: **Throughout - 1937 Bldg.**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-37**
MATERIAL DESCRIPTION: **Exterior Window Caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout - 1937 Bldg.**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-37**
MATERIAL DESCRIPTION: **Exterior Window Caulk**
MATERIAL LOCATION: **Throughout - 1937 Bldg.**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-38**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Stairwells - 1937 Bldg.**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-38**
MATERIAL DESCRIPTION: **Terrazzo**
MATERIAL LOCATION: **Stairwells - 1937 Bldg.**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-39**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Library and Main Office, 207A - 1937 Bldg.**

MATERIAL QUANTITY: **3200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-39**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Library and Main Office, 207A - 1937 Bldg.**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-40**
MATERIAL DESCRIPTION: **12"x12" Mixed Gray Speckled VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 114K, 134B, 134C - 1937 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-40**
MATERIAL DESCRIPTION: **12"x12" Mixed Gray Speckled VFT (Abated)**
MATERIAL LOCATION: **Rooms 114K, 134B, 134C - 1937 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-41**
MATERIAL DESCRIPTION: **12"x12" Mixed Gray Speckled VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 114K, 134B, 134C - 1937 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-41**
MATERIAL DESCRIPTION: **12"x12" Mixed Gray Speckled VFT Mastic (Abated)**
MATERIAL LOCATION: **Rooms 114K, 134B, 134C - 1937 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-42**
MATERIAL DESCRIPTION: **Beige Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 304 - 1937 Bldg.**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-42**
MATERIAL DESCRIPTION: **Beige Linoleum**
MATERIAL LOCATION: **Room 304 - 1937 Bldg.**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-43**
MATERIAL DESCRIPTION: **Beige Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 304 - 1937 Bldg.**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-43**
MATERIAL DESCRIPTION: **Beige Linoleum Mastic**
MATERIAL LOCATION: **Room 304 - 1937 Bldg.**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-44**
MATERIAL DESCRIPTION: **14"x14" Gray w/ Black Spots VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Auditorium Lobby - 1937 Bldg.**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-44**
MATERIAL DESCRIPTION: **14"x14" Gray w/ Black Spots VFT**
MATERIAL LOCATION: **Auditorium Lobby - 1937 Bldg.**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-45**
MATERIAL DESCRIPTION: **14"x14" Gray w/ Black Spots VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Auditorium Lobby - 1937 Bldg.**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-45**
MATERIAL DESCRIPTION: **14"x14" Gray w/ Black Spots VFT Mastic**
MATERIAL LOCATION: **Auditorium Lobby - 1937 Bldg.**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-46**
MATERIAL DESCRIPTION: **2'x2' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 308, 301 - 1937 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-46**
MATERIAL DESCRIPTION: **2'x2' Ceiling Tile**
MATERIAL LOCATION: **Rooms 308, 301 - 1937 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-47**
MATERIAL DESCRIPTION: **14"x14" Blue Speckled VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Auditorium - 1937 Bldg.**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-47**
MATERIAL DESCRIPTION: **14"x14" Blue Speckled VFT**
MATERIAL LOCATION: **Auditorium - 1937 Bldg.**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-48**
MATERIAL DESCRIPTION: **14"x14" Blue Specked VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium - 1937 Bldg.**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-48**
MATERIAL DESCRIPTION: **14"x14" Blue Specked VFT Mastic**
MATERIAL LOCATION: **Auditorium - 1937 Bldg.**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-49**
MATERIAL DESCRIPTION: **12"x12" Mixed Beige Speckled VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 308, 206, 110, 108 - 1937 Bldg. (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-49**
MATERIAL DESCRIPTION: **12"x12" Mixed Beige Speckled VFT (Abated)**
MATERIAL LOCATION: **Rooms 308, 206, 110, 108 - 1937 Bldg. (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-50**
MATERIAL DESCRIPTION: **12"x12" Mixed Beige Speckled VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 208, 206, 110, 108 - 1937 Bldg. (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-50**
MATERIAL DESCRIPTION: **12"x12" Mixed Beige Speckled VFT Mastic (Abated)**
MATERIAL LOCATION: **Rooms 208, 206, 110, 108 - 1937 Bldg. (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-51**
MATERIAL DESCRIPTION: **20"x20" Yellow w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 204, 206, 208, 210, 100, 101, 102, 105C - 1937 Bldg.**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-51**
MATERIAL DESCRIPTION: **20"x20" Yellow w/ Streaks VFT**
MATERIAL LOCATION: **Rooms 204, 206, 208, 210, 100, 101, 102, 105C - 1937 Bldg.**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-52**
MATERIAL DESCRIPTION: **20"x20" Yellow w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 204, 206, 209, 210, 100, 101, 102, 105C - 1937 Bldg.**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-52**
MATERIAL DESCRIPTION: **20"x20" Yellow w/ Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms 204, 206, 209, 210, 100, 101, 102, 105C - 1937 Bldg.**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-53**
MATERIAL DESCRIPTION: **20"x20" Brown w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1937 Bldg**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-53**
MATERIAL DESCRIPTION: **20"x20" Brown w/ Streaks VFT**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1937 Bldg**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-54**
MATERIAL DESCRIPTION: **20"x20" Brown w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1937 Bldg.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-54**
MATERIAL DESCRIPTION: **20"x20" Brown w/ Streaks VFT Mastic**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1937 Bldg.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-55**
MATERIAL DESCRIPTION: **20"x20" Beige w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors, Room 103B - 1937 Bldg.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-55**
MATERIAL DESCRIPTION: **20"x20" Beige w/ Streaks VFT**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors, Room 103B - 1937 Bldg.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-56**
MATERIAL DESCRIPTION: **20"x20" Beige w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors, Room 103B - 1937 Bldg.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-56**
MATERIAL DESCRIPTION: **20"x20" Beige w/ Streaks VFT Mastic**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors, Room 103B - 1937 Bldg.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-57**
MATERIAL DESCRIPTION: **20"x20" Off White w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1937 Bldg.**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-57**
MATERIAL DESCRIPTION: **20"x20" Off White w/ Streaks VFT**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1937 Bldg.**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-58**
MATERIAL DESCRIPTION: **20"x20" Off White w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1937 Bldg.**

MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-58**
MATERIAL DESCRIPTION: **20"x20" Off White w/ Streaks VFT Mastic**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1937 Bldg.**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-59**
MATERIAL DESCRIPTION: **20"x20" Gray w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 100, 101, 102, 204, 206, 208 and 210 - 1937 Bldg.**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-59**
MATERIAL DESCRIPTION: **20"x20" Gray w/ Streaks VFT**
MATERIAL LOCATION: **Rooms 100, 101, 102, 204, 206, 208 and 210 - 1937 Bldg.**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-60**
MATERIAL DESCRIPTION: **20"x20" Gray w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 100, 101, 102, 204, 206, 208 and 210 - 1937 Bldg.**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-60**
MATERIAL DESCRIPTION: **20"x20" Gray w/ Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms 100, 101, 102, 204, 206, 208 and 210 - 1937 Bldg.**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-61**
MATERIAL DESCRIPTION: **20"x20" Blue w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 204, 206, 208, 210 - 1937 Bldg.**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-61**
MATERIAL DESCRIPTION: **20"x20" Blue w/ Streaks VFT**
MATERIAL LOCATION: **Rooms 204, 206, 208, 210 - 1937 Bldg.**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-62**
MATERIAL DESCRIPTION: **20"x20" Blue w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 204, 206, 208, 210 - 1937 Bldg.**

MATERIAL QUANTITY: **1400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-62**
MATERIAL DESCRIPTION: **20"x20" Blue w/ Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms 204, 206, 208, 210 - 1937 Bldg.**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-63**
MATERIAL DESCRIPTION: **20"x20" Green w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 101 - 1937 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-63**
MATERIAL DESCRIPTION: **20"x20" Green w/ Streaks VFT**
MATERIAL LOCATION: **Room 101 - 1937 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37-64**
MATERIAL DESCRIPTION: **20"x20" Green w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 101 - 1937 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **37-64**
MATERIAL DESCRIPTION: **20"x20" Green w/ Streaks VFT Mastic**
MATERIAL LOCATION: **Room 101 - 1937 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **12"x12" Off White with Tan Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **162A and B, Councillor's Office - FA Building**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **12"x12" Off White with Tan Streaks VFT**
MATERIAL LOCATION: **162A and B, Councillor's Office - FA Building**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **12"x12" Off White with Tan Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **162A and B, Councillor's Office - FA Building**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **12"x12" Off White with Tan Streaks VFT Mastic**
MATERIAL LOCATION: **162A and B, Councillor's Office - FA Building**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 172 (PKA 152), 252, 257, 250, 251, 253, and Library - FA Building**
MATERIAL QUANTITY: **6300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Linoleum**
MATERIAL LOCATION: **Rooms 172 (PKA 152), 252, 257, 250, 251, 253, and Library - FA Building**
MATERIAL QUANTITY: **6300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Linoleum Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 172 (PKA 152), 252, 257, 250, 251, 253 and Library - FA Building**
MATERIAL QUANTITY: **6300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Linoleum Adhesive**
MATERIAL LOCATION: **Rooms 172 (PKA 152), 252, 257, 250, 251, 253 and Library - FA Building**
MATERIAL QUANTITY: **6300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Tan Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 121, 262 & 265**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Tan Linoleum**
MATERIAL LOCATION: **Rooms 121, 262 & 265**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **Tan Linoleum Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 121, 262 & 265**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **Tan Linoleum Adhesive**
MATERIAL LOCATION: **Rooms 121, 262 & 265**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **2' x 4' Lay In Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 121; 110, 109, 108**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **2' x 4' Lay In Ceiling Panels**
MATERIAL LOCATION: **Rooms 121; 110, 109, 108**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **Insulation in Walls and Vault Door**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 102**
MATERIAL QUANTITY: **91** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **Insulation in Walls and Vault Door**
MATERIAL LOCATION: **Room 102**
MATERIAL QUANTITY: **91** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **2' x 4' Lay In Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 153 - FA Building**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **2' x 4' Lay In Ceiling Panels**
MATERIAL LOCATION: **Room 153 - FA Building**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Science Copy Room - 1899 Bldg.**
MATERIAL QUANTITY: **305** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **Linoleum**
MATERIAL LOCATION: **Science Copy Room - 1899 Bldg.**
MATERIAL QUANTITY: **305** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Linoleum Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Science Copy Room - 1899 Bldg.**

MATERIAL QUANTITY: **305**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Linoleum Adhesive**
MATERIAL LOCATION: **Science Copy Room - 1899 Bldg.**
MATERIAL QUANTITY: **305** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **12"x12" Green with White Floor Tile (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 102 (Abated)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **12"x12" Green with White Floor Tile (Abated)**
MATERIAL LOCATION: **Room 102 (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **12"x12" Green with White Floor Tile Adhesive (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 102 (Abated)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **12"x12" Green with White Floor Tile Adhesive (Abated)**
MATERIAL LOCATION: **Room 102 (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **12"x12" Gray with White Floor Tile (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 102 (Abated)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **12"x12" Gray with White Floor Tile (Abated)**
MATERIAL LOCATION: **Room 102 (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12"x12" Gray with White Floor Tile Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 102 (Abated)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12"x12" Gray with White Floor Tile Mastic (Abated)**
MATERIAL LOCATION: **Room 102 (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **12"x12" Gray with Gray Floor Tile (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 102 (Abated)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **12"x12" Gray with Gray Floor Tile (Abated)**
MATERIAL LOCATION: **Room 102 (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53A**
MATERIAL DESCRIPTION: **12"x12" Gray with Gray Floor Tile Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 102 (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **53A**
MATERIAL DESCRIPTION: **12"x12" Gray with Gray Floor Tile Mastic (Abated)**
MATERIAL LOCATION: **Room 102 (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **12"x12" Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 111**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **12"x12" Ceiling Tile**
MATERIAL LOCATION: **Room 111**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12"x12" Light Blue with White and Brown Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 111**

MATERIAL QUANTITY: **750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12"x12" Light Blue with White and Brown Streaks Floor Tile**
MATERIAL LOCATION: **Room 111**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **12"x12" Light Blue with White and Brown Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 111**

MATERIAL QUANTITY: **750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **12"x12" Light Blue with White and Brown Streaks VFT Mastic**
MATERIAL LOCATION: **Room 111**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-01**
MATERIAL DESCRIPTION: **12"x12" White w/ Grey Speckles VFT**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor West Corridor By Lobby - 1961 Addition**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-01**
MATERIAL DESCRIPTION: **12"x12" White w/ Grey Speckles VFT**
MATERIAL LOCATION: **1st Floor West Corridor By Lobby - 1961 Addition**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-02**
MATERIAL DESCRIPTION: **12"x12" White w/ Gray Speckles VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor West Corridor By Lobby - 1961 Addition**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-02**

MATERIAL DESCRIPTION: **12"x12" White w/ Gray Speckles VFT Mastic**

MATERIAL LOCATION: **1st Floor West Corridor By Lobby - 1961 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-03**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Speckles VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor West Corridor By Lobby - 1961 Addition (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-03**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Speckles VFT (Abated)**
MATERIAL LOCATION: **1st Floor West Corridor By Lobby - 1961 Addition (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-04**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Speckles VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor West Corridor By Lobby - 1961 Addition (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-04**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Speckles VFT Mastic (Abated)**
MATERIAL LOCATION: **1st Floor West Corridor By Lobby - 1961 Addition (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-05**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Streaks VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium - 1961 Addition (Not observed)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-05**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Streaks VFT (Abated)**
MATERIAL LOCATION: **Auditorium - 1961 Addition (Not observed)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-06**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Streaks VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium - 1961 Addition (Not Observed)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-06**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Streaks VFT Mastic (Abated)**
MATERIAL LOCATION: **Auditorium - 1961 Addition (Not Observed)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-07**
MATERIAL DESCRIPTION: **12"x12" Coffee w/ White & Brown Streaks VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 108, Room 257 & North Corridor - 1961 Addition (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-07**
MATERIAL DESCRIPTION: **12"x12" Coffee w/ White & Brown Streaks VFT (Abated)**
MATERIAL LOCATION: **Room 108, Room 257 & North Corridor - 1961 Addition (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-08**
MATERIAL DESCRIPTION: **12"x12" Coffee w/ White & Brown Streaks VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 108, Room 257 & North Corridor - 1961 Addition (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-08**
MATERIAL DESCRIPTION: **12"x12" Coffee w/ White & Brown Streaks VFT Mastic (Abated)**
MATERIAL LOCATION: **Room 108, Room 257 & North Corridor - 1961 Addition (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-09**
MATERIAL DESCRIPTION: **12"x12" Red VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom - 1961 Addition (Abated)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-09**
MATERIAL DESCRIPTION: **12"x12" Red VFT (Abated)**
MATERIAL LOCATION: **Lunchroom - 1961 Addition (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-10**
MATERIAL DESCRIPTION: **12"x12" Red VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom - 1961 Addition (Abated)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-10**
MATERIAL DESCRIPTION: **12"x12" Red VFT Mastic (Abated)**
MATERIAL LOCATION: **Lunchroom - 1961 Addition (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-11**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT- Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **West Stairwell & Auditorium Stairwell - 1961 Addition (Not Observed)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-11**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT- Abated**
MATERIAL LOCATION: **West Stairwell & Auditorium Stairwell - 1961 Addition (Not Observed)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-12**
MATERIAL DESCRIPTION: **9"x9" Brown w/ White Streaks VFT-Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium Balcony - 1961 Addition (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-12**
MATERIAL DESCRIPTION: **9"x9" Brown w/ White Streaks VFT-Abated**
MATERIAL LOCATION: **Auditorium Balcony - 1961 Addition (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-13**
MATERIAL DESCRIPTION: **9"x9" Brown w/ White Streaks VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium Balcony - 1961 Addition (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-13**
MATERIAL DESCRIPTION: **9"x9" Brown w/ White Streaks VFT Mastic (Abated)**
MATERIAL LOCATION: **Auditorium Balcony - 1961 Addition (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-14**
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Teacher's Lunchroom - 1937 Bldg.**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-14**
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks VFT**
MATERIAL LOCATION: **Teacher's Lunchroom - 1937 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-15**
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Teacher's Lunchroom - 1937 Bldg.**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-15**
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks VFT Mastic**
MATERIAL LOCATION: **Teacher's Lunchroom - 1937 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-16**
MATERIAL DESCRIPTION: **Black w/ White Streaks Linoleum (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **East and West Stairwells, Auditorium Stairwell - 1961 Addition (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-16**
MATERIAL DESCRIPTION: **Black w/ White Streaks Linoleum (Abated)**
MATERIAL LOCATION: **East and West Stairwells, Auditorium Stairwell - 1961 Addition (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-17**
MATERIAL DESCRIPTION: **Black w/ White Streaks Linoleum Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **East and West Stairwells, Auditorium Stairwell - 1961 Addition (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-17**
MATERIAL DESCRIPTION: **Black w/ White Streaks Linoleum Mastic (Abated)**
MATERIAL LOCATION: **East and West Stairwells, Auditorium Stairwell - 1961 Addition (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-18**
MATERIAL DESCRIPTION: **2'x2' White Speckled w/ Inch Wormy Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor West Corridor - 1961 FA**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-18**
MATERIAL DESCRIPTION: **2'x2' White Speckled w/ Inch Wormy Ceiling Tile**
MATERIAL LOCATION: **2nd Floor West Corridor - 1961 FA**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-19**
MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **NW & SW Stairwells, Auditorium, Rooms 108, 109 & 110 - 1961 Addition**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-19**
MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile**
MATERIAL LOCATION: **NW & SW Stairwells, Auditorium, Rooms 108, 109 & 110 - 1961 Addition**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-20**
MATERIAL DESCRIPTION: **1'x1' Off White w/ Speckles Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom - 1961 Addition**
MATERIAL QUANTITY: **6700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-20**
MATERIAL DESCRIPTION: **1'x1' Off White w/ Speckles Ceiling Tile**
MATERIAL LOCATION: **Lunchroom - 1961 Addition**
MATERIAL QUANTITY: **6700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-21**
MATERIAL DESCRIPTION: **1'x1' Off White w/ Large Wormy Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Teachers Lunchroom by Kitchen - 1961 Addition**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-21**
MATERIAL DESCRIPTION: **1'x1' Off White w/ Large Wormy Ceiling Tile**
MATERIAL LOCATION: **Teachers Lunchroom by Kitchen - 1961 Addition**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-22**
MATERIAL DESCRIPTION: **Air Cell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **NW & NE Crawlspace & Paint Storage - 1961 Addition**
MATERIAL QUANTITY: **935** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-22**
MATERIAL DESCRIPTION: **Air Cell Pipe Insulation**
MATERIAL LOCATION: **NW & NE Crawlspace & Paint Storage - 1961 Addition**
MATERIAL QUANTITY: **935** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-23**
MATERIAL DESCRIPTION: **MJP E/F/V on Air Cell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **NW & NE Crawlspace & Paint Storage - 1961 Addition**
MATERIAL QUANTITY: **48** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-23**
MATERIAL DESCRIPTION: **MJP E/F/V on Air Cell Pipe Insulation**
MATERIAL LOCATION: **NW & NE Crawlspace & Paint Storage - 1961 Addition**
MATERIAL QUANTITY: **48** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-24**
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **NE Crawlspace - 1961 Addition**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-24**
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**
MATERIAL LOCATION: **NE Crawlspace - 1961 Addition**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-25**
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **NE Crawlspace - 1961 Addition**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-25**
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**
MATERIAL LOCATION: **NE Crawlspace - 1961 Addition**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-26**
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **NE Crawlspace - 1961 Addition**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-26**
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**
MATERIAL LOCATION: **NE Crawlspace - 1961 Addition**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-27**
MATERIAL DESCRIPTION: **MJP E/F/V on Paperwrap Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **NE Crawlspace - 1961 Addition**
MATERIAL QUANTITY: **37** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-27**
MATERIAL DESCRIPTION: **MJP E/F/V on Paperwrap Pipe Insulation**
MATERIAL LOCATION: **NE Crawlspace - 1961 Addition**
MATERIAL QUANTITY: **37** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-28**
MATERIAL DESCRIPTION: **Aircell Duct Insulation**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Paint Storage Room - 1961 Addition**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-28**
MATERIAL DESCRIPTION: **Aircell Duct Insulation**
MATERIAL LOCATION: **Paint Storage Room - 1961 Addition**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-29**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **West Stairwell & Auditorium Stairwell - 1961 Addition (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-29**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT Mastic (Abated)**
MATERIAL LOCATION: **West Stairwell & Auditorium Stairwell - 1961 Addition (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-30**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office and CPS Area Office, 182 - FA Building**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-30**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Engineer's Office and CPS Area Office, 182 - FA Building**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-31**
MATERIAL DESCRIPTION: **2'x2' Dot Wave Ceiling Tile (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 153 - FA Building (Not Observed)**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-31**
MATERIAL DESCRIPTION: **2'x2' Dot Wave Ceiling Tile (NOT OBSERVED)**
MATERIAL LOCATION: **Room 153 - FA Building (Not Observed)**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-32**
MATERIAL DESCRIPTION: **Lab Counter Tops**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 252, 251 - FA Building**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-32**
MATERIAL DESCRIPTION: **Lab Counter Tops**
MATERIAL LOCATION: **Rooms 252, 251 - FA Building**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-33**
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 258A - FA Building**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-33**
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks VFT**
MATERIAL LOCATION: **Room 258A - FA Building**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-34**
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 258A - FA Building**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-34**
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks VFT Mastic**
MATERIAL LOCATION: **Room 258A - FA Building**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-35**
MATERIAL DESCRIPTION: **12"x12" Gray Speckled VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 163C - FA Building**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-35**
MATERIAL DESCRIPTION: **12"x12" Gray Speckled VFT**
MATERIAL LOCATION: **Room 163C - FA Building**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-36**
MATERIAL DESCRIPTION: **12"x12" Gray Speckled VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 163C - FA Building**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-36**
MATERIAL DESCRIPTION: **12"x12" Gray Speckled VFT Mastic**
MATERIAL LOCATION: **Room 163C - FA Building**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-37**
MATERIAL DESCRIPTION: **12"x12" Mixed Beige Speckled VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 180 and 180A - FA Building**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-37**
MATERIAL DESCRIPTION: **12"x12" Mixed Beige Speckled VFT**
MATERIAL LOCATION: **Room 180 and 180A - FA Building**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-38**
MATERIAL DESCRIPTION: **12"x12" Mixed Beige Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 180 and 180A - FA Building**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-38**
MATERIAL DESCRIPTION: **12"x12" Mixed Beige Mastic**
MATERIAL LOCATION: **Room 180 and 180A - FA Building**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-39**
MATERIAL DESCRIPTION: **12"x12" Brown Speckled VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 170 and 172 - FA Building**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-39**
MATERIAL DESCRIPTION: **12"x12" Brown Speckled VFT**
MATERIAL LOCATION: **Rooms 170 and 172 - FA Building**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-40**
MATERIAL DESCRIPTION: **12"x12" Brown Speckled VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 170 and 172 - FA Building**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-40**
MATERIAL DESCRIPTION: **12"x12" Brown Speckled VFT Mastic**
MATERIAL LOCATION: **Rooms 170 and 172 - FA Building**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-41**
MATERIAL DESCRIPTION: **12"x12" Blue w/ Black and White Specs VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 154 - FA Building**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-41**
MATERIAL DESCRIPTION: **12"x12" Blue w/ Black and White Specs VFT**
MATERIAL LOCATION: **Room 154 - FA Building**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-42**
MATERIAL DESCRIPTION: **12"x12" Blue w/ Black and White Specs VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 154 - FA Building**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-42**
MATERIAL DESCRIPTION: **12"x12" Blue w/ Black and White Specs VFT Mastic**
MATERIAL LOCATION: **Room 154 - FA Building**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-43**
MATERIAL DESCRIPTION: **20"x20" Yellow w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 109 and 110 - 1961 Addition**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-43**
MATERIAL DESCRIPTION: **20"x20" Yellow w/ Streaks VFT**
MATERIAL LOCATION: **Room 109 and 110 - 1961 Addition**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-44**
MATERIAL DESCRIPTION: **20"x20" Yellow w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 109 and 110 - 1961 Addition**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-44**
MATERIAL DESCRIPTION: **20"x20" Yellow w/ Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms 109 and 110 - 1961 Addition**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-45**
MATERIAL DESCRIPTION: **20"x20" Brown w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st Floor Corridor - 1961 Addition**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-45**
MATERIAL DESCRIPTION: **20"x20" Brown w/ Streaks VFT**
MATERIAL LOCATION: **1st Floor Corridor - 1961 Addition**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-46**
MATERIAL DESCRIPTION: **20"x20" Brown w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor - 1961 Addition**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-46**
MATERIAL DESCRIPTION: **20"x20" Brown w/ Streaks VFT Mastic**
MATERIAL LOCATION: **1st Floor Corridor - 1961 Addition**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-47**
MATERIAL DESCRIPTION: **20"x20" Beige w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st Floor Corridor - 1961 Addition**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-47**
MATERIAL DESCRIPTION: **20"x20" Beige w/ Streaks VFT**
MATERIAL LOCATION: **1st Floor Corridor - 1961 Addition**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-48**
MATERIAL DESCRIPTION: **20"x20" Beige w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor - 1961 Addition**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-48**
MATERIAL DESCRIPTION: **20"x20" Beige w/ Streaks VFT Mastic**
MATERIAL LOCATION: **1st Floor Corridor - 1961 Addition**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-49**
MATERIAL DESCRIPTION: **20"x20" Off White w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st Floor Corridor - 1961 Addition**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-49**
MATERIAL DESCRIPTION: **20"x20" Off White w/ Streaks VFT**
MATERIAL LOCATION: **1st Floor Corridor - 1961 Addition**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-50**
MATERIAL DESCRIPTION: **20"x20" Off White w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor - 1961 Addition**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-50**
MATERIAL DESCRIPTION: **20"x20" Off White w/ Streaks VFT Mastic**
MATERIAL LOCATION: **1st Floor Corridor - 1961 Addition**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-51**
MATERIAL DESCRIPTION: **20"x20" Gray w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 109 and 110 - 1961 Addition**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-51**
MATERIAL DESCRIPTION: **20"x20" Gray w/ Streaks VFT**
MATERIAL LOCATION: **Rooms 109 and 110 - 1961 Addition**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-52**
MATERIAL DESCRIPTION: **20"x20" Gray w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 109 and 110 - 1961 Addition**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-52**
MATERIAL DESCRIPTION: **20"x20" Gray w/ Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms 109 and 110 - 1961 Addition**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-53**
MATERIAL DESCRIPTION: **20"x20" Green w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 109, 110 and Cafeteria - 1961 Addition**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-53**
MATERIAL DESCRIPTION: **20"x20" Green w/ Streaks VFT**
MATERIAL LOCATION: **Rooms 109, 110 and Cafeteria - 1961 Addition**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-54**
MATERIAL DESCRIPTION: **20"x20" Green w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 109, 110 and Cafeteria - 1961 Addition**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-54**
MATERIAL DESCRIPTION: **20"x20" Green w/ Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms 109, 110 and Cafeteria - 1961 Addition**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-55**
MATERIAL DESCRIPTION: **20"x20" Dark Green w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Cafeteria - 1961 Addition**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-55**
MATERIAL DESCRIPTION: **20"x20" Dark Green w/ Streaks VFT**
MATERIAL LOCATION: **Cafeteria - 1961 Addition**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-56**
MATERIAL DESCRIPTION: **20"x20" Dark Green w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Cafeteria - 1961 Addition**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-56**
MATERIAL DESCRIPTION: **20"x20" Dark Green w/ Streaks VFT Mastic**
MATERIAL LOCATION: **Cafeteria - 1961 Addition**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-57**
MATERIAL DESCRIPTION: **20"x20" Royal Blue w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Cafeteria - 1961 Addition**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-57**
MATERIAL DESCRIPTION: **20"x20" Royal Blue w/ Streaks VFT**
MATERIAL LOCATION: **Cafeteria - 1961 Addition**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61-58**
MATERIAL DESCRIPTION: **20"x20" Royal Blue w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Cafeteria - 1961 Addition**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **61-58**
MATERIAL DESCRIPTION: **20"x20" Royal Blue w/ Streaks VFT Mastic**
MATERIAL LOCATION: **Cafeteria - 1961 Addition**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-01**
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **1st, 2nd, & 3rd Floor Corridors (Abated), Room 229 (Not Observed), 2nd Floor women's toilet, & 113A - 1899 Bldg.**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-01**
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Specks VFT**
MATERIAL LOCATION: **1st, 2nd, & 3rd Floor Corridors (Abated), Room 229 (Not Observed), 2nd Floor women's toilet, & 113A - 1899 Bldg.**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-02**
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd, & 3rd Floor Corridors (Abated), Room 229 (Not Observed), 2nd Floor Women's Toilet & 113A - 1899 Bldg.**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-02**
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Specks VFT Mastic**
MATERIAL LOCATION: **1st, 2nd, & 3rd Floor Corridors (Abated), Room 229 (Not Observed), 2nd Floor Women's Toilet & 113A - 1899 Bldg.**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-03**
MATERIAL DESCRIPTION: **12"x12" White w/ Gray Specks VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 215 - 1899 Bldg. (Abated)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-03**
MATERIAL DESCRIPTION: **12"x12" White w/ Gray Specks VFT (Abated)**
MATERIAL LOCATION: **Room 215 - 1899 Bldg. (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-04**
MATERIAL DESCRIPTION: **12"x12" White w/ Gray Specks VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 215 - 1899 Bldg. (Abated)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-04**
MATERIAL DESCRIPTION: **12"x12" White w/ Gray Specks VFT Mastic (Abated)**
MATERIAL LOCATION: **Room 215 - 1899 Bldg. (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-05**
MATERIAL DESCRIPTION: **12"x12" Beige w/ Brown Specks VFT-(Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 223, 217, 219, 217A, 224, & storage 217B & C - 1899 Bldg. (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-05**
MATERIAL DESCRIPTION: **12"x12" Beige w/ Brown Specks VFT-(Abated)**
MATERIAL LOCATION: **Rooms 223, 217, 219, 217A, 224, & storage 217B & C - 1899 Bldg. (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-06**
MATERIAL DESCRIPTION: **12"x12" Beige w/ Brown Specks VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 223, 217, 219, 217A, 224, & 224 Storage 217B & C - 1899 Bldg. (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-06**
MATERIAL DESCRIPTION: **12"x12" Beige w/ Brown Specks VFT Mastic (Abated)**
MATERIAL LOCATION: **Rooms 223, 217, 219, 217A, 224, & 224 Storage 217B & C - 1899 Bldg. (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-07**
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ Brown & White Specks VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 113A - 1899 Bldg. (Abated)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-07**
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ Brown & White Specks VFT (Abated)**
MATERIAL LOCATION: **Room 113A - 1899 Bldg. (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-08**
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ Brown & White Specks VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 113A - 1899 Bldg. (Abated)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-08**
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ Brown & White Specks VFT Mastic (Abated)**
MATERIAL LOCATION: **Room 113A - 1899 Bldg. (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-09**
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 112 - 1899 Bldg.**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-09**
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Streaks VFT**
MATERIAL LOCATION: **Room 112 - 1899 Bldg.**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-10**
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 112 - 1899 Bldg.**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-10**
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Streaks VFT Mastic**
MATERIAL LOCATION: **Room 112 - 1899 Bldg.**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-11**
MATERIAL DESCRIPTION: **12"x12" Off White w/ Light Brown Streaks VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 14 Foyer, 29, 23 - 1899 Bldg. (Abated)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-11**
MATERIAL DESCRIPTION: **12"x12" Off White w/ Light Brown Streaks VFT (Abated)**
MATERIAL LOCATION: **Room 14 Foyer, 29, 23 - 1899 Bldg. (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-12**
MATERIAL DESCRIPTION: **12"x12" Off White w/ Light Brown Streaks VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 14 Foyer, 29, 23 - 1899 Bldg. (Abated)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-12**
MATERIAL DESCRIPTION: **12"x12" Off White w/ Light Brown Streaks VFT Mastic (Abated)**
MATERIAL LOCATION: **Room 14 Foyer, 29, 23 - 1899 Bldg. (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-13**
MATERIAL DESCRIPTION: **9"x9" Tan w/ Brown & White Streaks VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1899 (See Hatching Maps) 119, 114 A & B & C, D,E, F, G, 022, 032, 036, Counselors Corridor (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-13**
MATERIAL DESCRIPTION: **9"x9" Tan w/ Brown & White Streaks VFT (Abated)**
MATERIAL LOCATION: **Throughout - 1899 (See Hatching Maps) 119, 114 A & B & C, D,E, F, G, 022, 032, 036, Counselors Corridor (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-14**
MATERIAL DESCRIPTION: **9"x9" Tan w/ Brown & White Streaks VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1899 Bldg. (Abated)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-14**
MATERIAL DESCRIPTION: **9"x9" Tan w/ Brown & White Streaks VFT Mastic (Abated)**
MATERIAL LOCATION: **Throughout - 1899 Bldg. (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-15**
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Science Copy Room - 1899 Bldg. (Not Observed)**

MATERIAL QUANTITY: **305** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-15**
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT (NOT OBSERVED)**
MATERIAL LOCATION: **Science Copy Room - 1899 Bldg. (Not Observed)**
MATERIAL QUANTITY: **305** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-16**
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT Mastic (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Science Copy Room - 1899 Bldg. (Not Observed)**

MATERIAL QUANTITY: **305** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-16**
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT Mastic (NOT OBSERVED)**
MATERIAL LOCATION: **Science Copy Room - 1899 Bldg. (Not Observed)**
MATERIAL QUANTITY: **305** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-17**
MATERIAL DESCRIPTION: **9"x9" Tan VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 14 (Under HA 99-10), Room 127A & 129A 1899 Bldg. (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-17**
MATERIAL DESCRIPTION: **9"x9" Tan VFT (Abated)**
MATERIAL LOCATION: **Room 14 (Under HA 99-10), Room 127A & 129A 1899 Bldg. (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-18**
MATERIAL DESCRIPTION: **9"x9" Tan VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 14 (Under HA 99-10) 1899 Bldg. (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-18**
MATERIAL DESCRIPTION: **9"x9" Tan VFT Mastic (Abated)**
MATERIAL LOCATION: **Room 14 (Under HA 99-10) 1899 Bldg. (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-19**
MATERIAL DESCRIPTION: **9"x9" Rust VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 14 (Under HA 99-10 and 99-17) - 1899 Bldg. (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-19**
MATERIAL DESCRIPTION: **9"x9" Rust VFT (Abated)**
MATERIAL LOCATION: **Room 14 (Under HA 99-10 and 99-17) - 1899 Bldg. (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-20**
MATERIAL DESCRIPTION: **9"x9" Rust VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 14 (Under HA 99-10 and 99-17) - 1899 Bldg. (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-20**
MATERIAL DESCRIPTION: **9"x9" Rust VFT Mastic (Abated)**
MATERIAL LOCATION: **Room 14 (Under HA 99-10 and 99-17) - 1899 Bldg. (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-21**
MATERIAL DESCRIPTION: **2'x2' White w/ Wormy Grooves Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Library, Work Room A & B, 221 (NOT OBSERVED) - 1899 Bldg.**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-21**
MATERIAL DESCRIPTION: **2'x2' White w/ Wormy Grooves Ceiling Tile**
MATERIAL LOCATION: **Library, Work Room A & B, 221 (NOT OBSERVED) - 1899 Bldg.**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-22**
MATERIAL DESCRIPTION: **1'x1' White w/ Wormy Grooves Ceiling Tile (Removed)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 217, 217 A & B, 221- 1899 Bldg. (Removed)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-22**
MATERIAL DESCRIPTION: **1'x1' White w/ Wormy Grooves Ceiling Tile (Removed)**
MATERIAL LOCATION: **Room 217, 217 A & B, 221- 1899 Bldg. (Removed)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-23**
MATERIAL DESCRIPTION: **2'x4' White w/ Wormy Grooves Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 227 - 1899 Bldg.**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-23**
MATERIAL DESCRIPTION: **2'x4' White w/ Wormy Grooves Ceiling Tile**
MATERIAL LOCATION: **Room 227 - 1899 Bldg.**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-24**
MATERIAL DESCRIPTION: **2'x4' White w/ Pin Holes Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineers Office - 1899 Bldg.**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-24**
MATERIAL DESCRIPTION: **2'x4' White w/ Pin Holes Ceiling Tile**
MATERIAL LOCATION: **Engineers Office - 1899 Bldg.**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-25**
MATERIAL DESCRIPTION: **Transite Table Tops (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 23, 29, 124, 127, 129, 224, 229 - 1899 Bldg. ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-25**
MATERIAL DESCRIPTION: **Transite Table Tops (ABATED)**
MATERIAL LOCATION: **Rooms 23, 29, 124, 127, 129, 224, 229 - 1899 Bldg. ABATED**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-26**
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1899 Bldg.**
MATERIAL QUANTITY: **648** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-26**
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**
MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1899 Bldg.**
MATERIAL QUANTITY: **648** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-27**
MATERIAL DESCRIPTION: **MJP E/F/V on Paperwrap Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1899 Bldg.**
MATERIAL QUANTITY: **77** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-27**
MATERIAL DESCRIPTION: **MJP E/F/V on Paperwrap Pipe Insulation**
MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1899 Bldg.**
MATERIAL QUANTITY: **77** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-28**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 127, 23, 27, 24, & Engineer's Office, Boiler Pump & Sprinkler Rooms, Store Room by 14, basement corridor - 1899 Bldg.**

MATERIAL QUANTITY: **2840** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-28**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Rooms 127, 23, 27, 24, & Engineer's Office, Boiler Pump & Sprinkler Rooms, Store Room by 14, basement corridor - 1899 Bldg.**
MATERIAL QUANTITY: **2840** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-29**
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 127, 23, 27, 24, & Engineer's Office, Boiler Pump & Sprinkler Rooms, Store Room by 14 - 1899 Bldg.**

MATERIAL QUANTITY: **587** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-29**
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**
MATERIAL LOCATION: **Rooms 127, 23, 27, 24, & Engineer's Office, Boiler Pump & Sprinkler Rooms, Store Room by 14 - 1899 Bldg.**
MATERIAL QUANTITY: **587** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-30**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Boiler & Tank Rooms, Basement Corridor, 127, 129, 124, 122, 29, 24 Closet, Engineers Office - 1899 Bldg.**

MATERIAL QUANTITY: **680** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-30**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Boiler & Tank Rooms, Basement Corridor, 127, 129, 124, 122, 29, 24 Closet, Engineers Office - 1899 Bldg.**
MATERIAL QUANTITY: **680** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-31**
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Basement Corridor - 1899 Bldg.**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-31**
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**
MATERIAL LOCATION: **Basement Corridor - 1899 Bldg.**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-32**
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Basement Corridor By Plenum Sliding Door - 1899 Bldg.**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-32**
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**
MATERIAL LOCATION: **Basement Corridor By Plenum Sliding Door - 1899 Bldg.**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-33**
MATERIAL DESCRIPTION: **Water Tank Insulation**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room - 1899 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-33**
MATERIAL DESCRIPTION: **Water Tank Insulation**
MATERIAL LOCATION: **Boiler Room - 1899 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-34**
MATERIAL DESCRIPTION: **Hardcoat Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout - 1899 Bldg.**
MATERIAL QUANTITY: **100000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-34**
MATERIAL DESCRIPTION: **Hardcoat Plaster**
MATERIAL LOCATION: **Throughout - 1899 Bldg.**
MATERIAL QUANTITY: **100000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-35**
MATERIAL DESCRIPTION: **Exterior Window Caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout - 1899 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-35**
MATERIAL DESCRIPTION: **Exterior Window Caulk**
MATERIAL LOCATION: **Throughout - 1899 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-36**
MATERIAL DESCRIPTION: **Beige Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 121 (Science Room), 229A, 127, 129, 124, 023, 027 - 1899 Bldg.**
MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-36**
MATERIAL DESCRIPTION: **Beige Linoleum**
MATERIAL LOCATION: **Room 121 (Science Room), 229A, 127, 129, 124, 023, 027 - 1899 Bldg.**
MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-37**
MATERIAL DESCRIPTION: **Beige Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 121 (Science Room), 229A, 127, 129, 124, 023, 027 - 1899 Bldg.**
MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-37**
MATERIAL DESCRIPTION: **Beige Linoleum Mastic**
MATERIAL LOCATION: **Room 121 (Science Room), 229A, 127, 129, 124, 023, 027 - 1899 Bldg.**
MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-38**
MATERIAL DESCRIPTION: **Gray Linoleum - NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 121 - 1899 Bldg. (Not Observed)**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-38**
MATERIAL DESCRIPTION: **Gray Linoleum - NOT OBSERVED**
MATERIAL LOCATION: **Room 121 - 1899 Bldg. (Not Observed)**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-38A**
MATERIAL DESCRIPTION: **Gray Linoleum Mastic- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 121 - 1899 Bldg. (Not Observed)**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-38A**
MATERIAL DESCRIPTION: **Gray Linoleum Mastic- NOT OBSERVED**
MATERIAL LOCATION: **Room 121 - 1899 Bldg. (Not Observed)**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-39**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Stairwells - 1899 Bldg.**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-39**
MATERIAL DESCRIPTION: **Terrazzo**
MATERIAL LOCATION: **Stairwells - 1899 Bldg.**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-40**
MATERIAL DESCRIPTION: **Carpet Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 112 - Library (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-40**
MATERIAL DESCRIPTION: **Carpet Mastic (Abated)**
MATERIAL LOCATION: **Room 112 - Library (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-41**
MATERIAL DESCRIPTION: **Black Lab Counter Tops**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 229, 224 Room 121, 121C, 023, 027 - 1899 Bldg.**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-41**
MATERIAL DESCRIPTION: **Black Lab Counter Tops**
MATERIAL LOCATION: **Room 229, 224 Room 121, 121C, 023, 027 - 1899 Bldg.**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-42**
MATERIAL DESCRIPTION: **Fume Hood**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 224, 023, 027 - 1899 Bldg.**
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-42**
MATERIAL DESCRIPTION: **Fume Hood**
MATERIAL LOCATION: **Rooms 224, 023, 027 - 1899 Bldg.**
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-43**
MATERIAL DESCRIPTION: **12"x12" Yellow Speckled VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 213A, 221, 113A - 1899 Bldg.**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-43**
MATERIAL DESCRIPTION: **12"x12" Yellow Speckled VFT**
MATERIAL LOCATION: **Rooms 213A, 221, 113A - 1899 Bldg.**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-44**
MATERIAL DESCRIPTION: **12"x12" Yellow Speckled VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 213A, 221, 113A - 1899 Bldg.**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-45**
MATERIAL DESCRIPTION: **12"x12" Mixed Beige VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 125, 125 Foyer, Room 122 - 1899 Bldg. (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-45**
MATERIAL DESCRIPTION: **12"x12" Mixed Beige VFT (Abated)**
MATERIAL LOCATION: **Room 125, 125 Foyer, Room 122 - 1899 Bldg. (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-46**
MATERIAL DESCRIPTION: **12"x12" Mixed Beige Speckled VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 125, 125 Foyer, Room 122 - 1899 Bldg. (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-46**
MATERIAL DESCRIPTION: **12"x12" Mixed Beige Speckled VFT Mastic (Abated)**
MATERIAL LOCATION: **Room 125, 125 Foyer, Room 122 - 1899 Bldg. (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-47**
MATERIAL DESCRIPTION: **12"x12" Mixed Gray Speckled VFT-(Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Counselor's Corridor, 3rd Floor Elevator Lobby, Basement Elevator Lobby - 1899 Bldg. (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-47**
MATERIAL DESCRIPTION: **12"x12" Mixed Gray Speckled VFT-(Abated)**
MATERIAL LOCATION: **1st Floor Counselor's Corridor, 3rd Floor Elevator Lobby, Basement Elevator Lobby - 1899 Bldg. (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-48**
MATERIAL DESCRIPTION: **12"x12" Mixed Gray Speckled VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Counselor's Corridor, 3rd Floor Elevator Lobby, Basement Elevator Lobby - 1937 Bldg. (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-48**
MATERIAL DESCRIPTION: **12"x12" Mixed Gray Speckled VFT Mastic (Abated)**
MATERIAL LOCATION: **1st Floor Counselor's Corridor, 3rd Floor Elevator Lobby, Basement Elevator Lobby - 1937 Bldg. (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-49**
MATERIAL DESCRIPTION: **Drywall System**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 213A - 1899 Bldg.**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-49**
MATERIAL DESCRIPTION: **Drywall System**
MATERIAL LOCATION: **Room 213A - 1899 Bldg.**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-50**
MATERIAL DESCRIPTION: **20"x20" Yellow w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 014, 022, 027, 030, 029, 114B,C,D,E,F,G,O,P, 112, 125, 122, 229, 217, 219, 221, 223 and 3rd Floor Corridor - 1899 Bldg.**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-50**
MATERIAL DESCRIPTION: **20"x20" Yellow w/ Streaks VFT**
MATERIAL LOCATION: **Rooms 014, 022, 027, 030, 029, 114B,C,D,E,F,G,O,P, 112, 125, 122, 229, 217, 219, 221, 223 and 3rd Floor Corridor - 1899 Bldg.**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-51**
MATERIAL DESCRIPTION: **20"x20" Yellow w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 014, 022, 027, 030, 029, 114B,C,D,E,F,G,O,P, 112, 125, 122, 229, 217, 219, 221, 223 and 3rd Floor Corridor - 1899 Bldg.**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-51**
MATERIAL DESCRIPTION: **20"x20" Yellow w/ Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms 014, 022, 027, 030, 029, 114B,C,D,E,F,G,O,P, 112, 125, 122, 229, 217, 219, 221, 223 and 3rd Floor Corridor - 1899 Bldg.**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-52**
MATERIAL DESCRIPTION: **20"x20" Brown w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **All Stairwells, 2nd and 3rd Floor Corridors - 1899 Bldg.**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-52**
MATERIAL DESCRIPTION: **20"x20" Brown w/ Streaks VFT**
MATERIAL LOCATION: **All Stairwells, 2nd and 3rd Floor Corridors - 1899 Bldg.**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-53**
MATERIAL DESCRIPTION: **20"x20" Brown w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All Stairwells, 2nd and 3rd Floor Corridors - 1899 Bldg.**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-53**
MATERIAL DESCRIPTION: **20"x20" Brown w/ Streaks VFT Mastic**
MATERIAL LOCATION: **All Stairwells, 2nd and 3rd Floor Corridors - 1899 Bldg.**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-54**
MATERIAL DESCRIPTION: **20"x20" Beige w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1899 Bldg.**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-54**
MATERIAL DESCRIPTION: **20"x20" Beige w/ Streaks VFT**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1899 Bldg.**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-55**
MATERIAL DESCRIPTION: **20"x20" Beige w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1899 Bldg.**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-55**
MATERIAL DESCRIPTION: **20"x20" Beige w/ Streaks VFT Mastic**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1899 Bldg.**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-56**
MATERIAL DESCRIPTION: **20"x20" Off White w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1899 Bldg.**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-56**
MATERIAL DESCRIPTION: **20"x20" Off White w/ Streaks VFT**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1899 Bldg.**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-57**
MATERIAL DESCRIPTION: **20"x20" Off White w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1899 Bldg.**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-57**
MATERIAL DESCRIPTION: **20"x20" Off White w/ Streaks VFT Mastic**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors - 1899 Bldg.**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-58**
MATERIAL DESCRIPTION: **20"x20" Gray w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 014, 022, 027, 029, 030, 114 A,B,C,D,E,F,G,H,O,P, 122, 125, 217, 219, 221, 223 and 229 - 1899 Bldg.**

MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-58**
MATERIAL DESCRIPTION: **20"x20" Gray w/ Streaks VFT**
MATERIAL LOCATION: **Rooms 014, 022, 027, 029, 030, 114 A,B,C,D,E,F,G,H,O,P, 122, 125, 217, 219, 221, 223 and 229 - 1899 Bldg.**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-59**
MATERIAL DESCRIPTION: **20"x20" Gray w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 014, 022, 027, 029, 030, 114A,B,C,D,E,F,G,H,O,P 122, 125, 217, 219, 221, 223, 229 - 1899 Bldg.**

MATERIAL QUANTITY: **3200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-59**
MATERIAL DESCRIPTION: **20"x20" Gray w/ Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms 014, 022, 027, 029, 030, 114A,B,C,D,E,F,G,H,O,P 122, 125, 217, 219, 221, 223, 229 - 1899 Bldg.**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-60**
MATERIAL DESCRIPTION: **20"x20" Blue w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 112, 217, 219, 221, 223 and 229 - 1899 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-60**
MATERIAL DESCRIPTION: **20"x20" Blue w/ Streaks VFT**
MATERIAL LOCATION: **Rooms 112, 217, 219, 221, 223 and 229 - 1899 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-61**
MATERIAL DESCRIPTION: **20"x20" Blue w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 112, 217, 219, 221, 223 and 229 - 1899 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-61**
MATERIAL DESCRIPTION: **20"x20" Blue w/ Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms 112, 217, 219, 221, 223 and 229 - 1899 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-62**
MATERIAL DESCRIPTION: **20"x20" Green w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 122 and 125 - 1899 Bldg.**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-62**
MATERIAL DESCRIPTION: **20"x20" Green w/ Streaks VFT**
MATERIAL LOCATION: **Rooms 122 and 125 - 1899 Bldg.**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99-63**
MATERIAL DESCRIPTION: **20"x20" Green w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 122 and 125 - 1899 Bldg.**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **99-63**
MATERIAL DESCRIPTION: **20"x20" Green w/ Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms 122 and 125 - 1899 Bldg.**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-01**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Streaks VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - FA Building (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-01**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Streaks VFT (Abated)**
MATERIAL LOCATION: **1st & 2nd Floor Corridors - FA Building (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-02**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Streaks VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - FA Building (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-02**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Streaks VFT Mastic (Abated)**
MATERIAL LOCATION: **1st & 2nd Floor Corridors - FA Building (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-03**
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Band Room, ROTC, 153, 151, 155, 157, 159, 161, 163A, 253 - FA Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-03**
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Streaks VFT**
MATERIAL LOCATION: **Band Room, ROTC, 153, 151, 155, 157, 159, 161, 163A, 253 - FA Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-04**
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Band Room, ROTC, 153, 151, 155, 157, 159, 161, 163A, 253 - FA Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-04**
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Streaks VFT Mastic**
MATERIAL LOCATION: **Band Room, ROTC, 153, 151, 155, 157, 159, 161, 163A, 253 - FA Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-05**
MATERIAL DESCRIPTION: **12"x12" Cream w/ Tan & White Streaks VFT (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Gym - FA Building (Not Observed)**
MATERIAL QUANTITY: **6300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-05**
MATERIAL DESCRIPTION: **12"x12" Cream w/ Tan & White Streaks VFT (NOT OBSRVED)**
MATERIAL LOCATION: **Gym - FA Building (Not Observed)**
MATERIAL QUANTITY: **6300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-06**
MATERIAL DESCRIPTION: **12"x12" Cream w/ Tan & White Streaks VFT Mastic (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Gym - FA Building (Not Observed)**

MATERIAL QUANTITY: **6300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-06**
MATERIAL DESCRIPTION: **12"x12" Cream w/ Tan & White Streaks VFT Mastic (NOT OBSERVED)**
MATERIAL LOCATION: **Gym - FA Building (Not Observed)**
MATERIAL QUANTITY: **6300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-07**
MATERIAL DESCRIPTION: **12"x12' White w/ Gray Speckles VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch Room, 164 - FA Building (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-07**
MATERIAL DESCRIPTION: **12"x12' White w/ Gray Speckles VFT (Abated)**
MATERIAL LOCATION: **Lunch Room, 164 - FA Building (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-08**
MATERIAL DESCRIPTION: **12"x12' White w/ Gray Speckles VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch Room, 164 - FA Building (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-08**
MATERIAL DESCRIPTION: **12"x12' White w/ Gray Speckles VFT Mastic (Abated)**
MATERIAL LOCATION: **Lunch Room, 164 - FA Building (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-09**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Speckles VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch Room, 164 - FA Building (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-09**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Speckles VFT (Abated)**
MATERIAL LOCATION: **Lunch Room, 164 - FA Building (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-10**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Speckles VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch Room, 164 - FA Building (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-10**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Speckles VFT Mastic (Abated)**
MATERIAL LOCATION: **Lunch Room, 164 - FA Building (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-11**
MATERIAL DESCRIPTION: **9"x9" Beige w/ White Spots VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - FA Building (Abated)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-11**
MATERIAL DESCRIPTION: **9"x9" Beige w/ White Spots VFT (Abated)**
MATERIAL LOCATION: **Throughout - FA Building (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-12**
MATERIAL DESCRIPTION: **9"x9" Beige w/ White Spots VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - FA Building (Abated)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-12**
MATERIAL DESCRIPTION: **9"x9" Beige w/ White Spots VFT Mastic (Abated)**
MATERIAL LOCATION: **Throughout - FA Building (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-13**
MATERIAL DESCRIPTION: **9"x9" Gray w/ Black Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Closet by Boiler Room - FA Building**

MATERIAL QUANTITY: **104**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-13**
MATERIAL DESCRIPTION: **9"x9" Gray w/ Black Streaks VFT**
MATERIAL LOCATION: **Closet by Boiler Room - FA Building**
MATERIAL QUANTITY: **104** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-14**
MATERIAL DESCRIPTION: **9"x9" Gray w/ Black Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Closet by Boiler Room - FA Building**

MATERIAL QUANTITY: **104**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-14**
MATERIAL DESCRIPTION: **9"x9" Gray w/ Black Streaks VFT Mastic**
MATERIAL LOCATION: **Closet by Boiler Room - FA Building**
MATERIAL QUANTITY: **104** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-15**
MATERIAL DESCRIPTION: **9"x9" Beige w/ Orange & White Spots VFT (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:
DISTURBANCE POTENTIAL:
MATERIAL LOCATION: **Rooms 252, Counselors Office, Library, 152 - FA Building (ABATED)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:
COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-15**
MATERIAL DESCRIPTION: **9"x9" Beige w/ Orange & White Spots VFT (ABATED)**
MATERIAL LOCATION: **Rooms 252, Counselors Office, Library, 152 - FA Building (ABATED)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-16**
MATERIAL DESCRIPTION: **9"x9" Beige w/ Orange & White Spots VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 252, Counselors Office, Library, 152 - FA Building (ABATED)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-16**
MATERIAL DESCRIPTION: **9"x9" Beige w/ Orange & White Spots VFT Mastic (Abated)**
MATERIAL LOCATION: **Rooms 252, Counselors Office, Library, 152 - FA Building (ABATED)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-17**
MATERIAL DESCRIPTION: **9"x9" Green w/ Black & White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Closet by Boiler Room - FA Building**

MATERIAL QUANTITY: **104**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-17**
MATERIAL DESCRIPTION: **9"x9" Green w/ Black & White Streaks VFT**
MATERIAL LOCATION: **Closet by Boiler Room - FA Building**
MATERIAL QUANTITY: **104** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-18**
MATERIAL DESCRIPTION: **9"x9" Green w/ Black & White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Closet by Boiler Room - FA Building**

MATERIAL QUANTITY: **104**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-18**
MATERIAL DESCRIPTION: **9"x9" Green w/ Black & White Streaks VFT Mastic**
MATERIAL LOCATION: **Closet by Boiler Room - FA Building**
MATERIAL QUANTITY: **104** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-19**
MATERIAL DESCRIPTION: **9"x9" Black VFT (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Slop Sink - FA Building (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-19**
MATERIAL DESCRIPTION: **9"x9" Black VFT (Abated)**
MATERIAL LOCATION: **2nd Floor Slop Sink - FA Building (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-20**
MATERIAL DESCRIPTION: **9"x9" Black VFT Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Slop Sink - FA Building (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **03/26/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-20**
MATERIAL DESCRIPTION: **9"x9" Black VFT Mastic (Abated)**
MATERIAL LOCATION: **2nd Floor Slop Sink - FA Building (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-23**
MATERIAL DESCRIPTION: **1'x1' Small Hole Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout - FA Building**

MATERIAL QUANTITY: **0**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-23**
MATERIAL DESCRIPTION: **1'x1' Small Hole Ceiling Tile**
MATERIAL LOCATION: **Throughout - FA Building**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-24**
MATERIAL DESCRIPTION: **1'x1' Medium Hole Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout - FA Building**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-24**
MATERIAL DESCRIPTION: **1'x1' Medium Hole Ceiling Tile**
MATERIAL LOCATION: **Throughout - FA Building**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-25**
MATERIAL DESCRIPTION: **2'x2' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunch Room - FA Building**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-25**
MATERIAL DESCRIPTION: **2'x2' Ceiling Tile**
MATERIAL LOCATION: **Lunch Room - FA Building**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-26**
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Boiler Room, All Crawlspace and Tunnels - FA Building**
MATERIAL QUANTITY: **5165** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-26**
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**
MATERIAL LOCATION: **Boiler Room, All Crawlspace and Tunnels - FA Building**
MATERIAL QUANTITY: **5165** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-27**
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Boiler Room, All Crawlspace and Tunnels - FA Building**
MATERIAL QUANTITY: **285** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-27**
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**
MATERIAL LOCATION: **Boiler Room, All Crawlspace and Tunnels - FA Building**
MATERIAL QUANTITY: **285** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-28**
MATERIAL DESCRIPTION: **MJP E/V/F on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Northwest Tunnel, Fan Room and Boiler Room - FA Building**
MATERIAL QUANTITY: **145** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-28**
MATERIAL DESCRIPTION: **MJP E/V/F on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Northwest Tunnel, Fan Room and Boiler Room - FA Building**
MATERIAL QUANTITY: **145** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-29**
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Tunnels, Boiler Room, & Fan Room - FA Building**
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-29**
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**
MATERIAL LOCATION: **Tunnels, Boiler Room, & Fan Room - FA Building**
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-30**
MATERIAL DESCRIPTION: **MJP E/F/V on Paperwrap Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Tunnels, Boiler Room, & Fan Room - FA Building**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-30**
MATERIAL DESCRIPTION: **MJP E/F/V on Paperwrap Pipe Insulation**
MATERIAL LOCATION: **Tunnels, Boiler Room, & Fan Room - FA Building**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-31**
MATERIAL DESCRIPTION: **Exterior Window Caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout - FA Building**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-31**
MATERIAL DESCRIPTION: **Exterior Window Caulk**
MATERIAL LOCATION: **Throughout - FA Building**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-32**
MATERIAL DESCRIPTION: **20"x20" Brown w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st and 2nd Floor Corridors - FA Building**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-32**
MATERIAL DESCRIPTION: **20"x20" Brown w/ Streaks VFT**
MATERIAL LOCATION: **1st and 2nd Floor Corridors - FA Building**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-33**
MATERIAL DESCRIPTION: **20"x20" Brown w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st and 2nd Floor Corridors - FA Building**

MATERIAL QUANTITY: **4000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-33**
MATERIAL DESCRIPTION: **20"x20" Brown w/ Streaks VFT Mastic**
MATERIAL LOCATION: **1st and 2nd Floor Corridors - FA Building**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-34**
MATERIAL DESCRIPTION: **20"x20" Beige w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st and 2nd Floor Corridors - FA Building**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-34**
MATERIAL DESCRIPTION: **20"x20" Beige w/ Streaks VFT**
MATERIAL LOCATION: **1st and 2nd Floor Corridors - FA Building**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-35**
MATERIAL DESCRIPTION: **20"x20" Beige w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st and 2nd Floor Corridors - FA Building**

MATERIAL QUANTITY: **4000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-35**
MATERIAL DESCRIPTION: **20"x20" Beige w/ Streaks VFT Mastic**
MATERIAL LOCATION: **1st and 2nd Floor Corridors - FA Building**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-36**
MATERIAL DESCRIPTION: **20"x20" Off White w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st and 2nd Floor Corridors - FA Building**

MATERIAL QUANTITY: **4000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-36**
MATERIAL DESCRIPTION: **20"x20" Off White w/ Streaks VFT**
MATERIAL LOCATION: **1st and 2nd Floor Corridors - FA Building**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-37**
MATERIAL DESCRIPTION: **20"x20" Off White w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd Floor Corridors - FA Building**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-37**
MATERIAL DESCRIPTION: **20"x20" Off White w/ Streaks VFT Mastic**
MATERIAL LOCATION: **1st and 2nd Floor Corridors - FA Building**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-38**
MATERIAL DESCRIPTION: **20"x20" Gray w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 155, 156, 157, 158, 159, 160, 161, 164, 165, 176, 179, 180, 254, 256, 257, 259, 260, 261, 263, 264 and 267 - FA Building**

MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-38**
MATERIAL DESCRIPTION: **20"x20" Gray w/ Streaks VFT**
MATERIAL LOCATION: **Rooms 155, 156, 157, 158, 159, 160, 161, 164, 165, 176, 179, 180, 254, 256, 257, 259, 260, 261, 263, 264 and 267 - FA Building**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-39**
MATERIAL DESCRIPTION: **20"x20" Gray w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 155, 156, 157, 158, 159, 160, 161, 164, 165, 176, 179, 180, 254, 256, 257, 269, 260, 261, 263, 264 and 267 - FA Building**

MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-39**
MATERIAL DESCRIPTION: **20"x20" Gray w/ Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms 155, 156, 157, 158, 159, 160, 161, 164, 165, 176, 179, 180, 254, 256, 257, 269, 260, 261, 263, 264 and 267 - FA Building**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-40**
MATERIAL DESCRIPTION: **20"x20" Blue w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 254, 256, 257, 259, 260, 261, 263, 264 and 267 - FA Building**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-40**
MATERIAL DESCRIPTION: **20"x20" Blue w/ Streaks VFT**
MATERIAL LOCATION: **Rooms 254, 256, 257, 259, 260, 261, 263, 264 and 267 - FA Building**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-41**
MATERIAL DESCRIPTION: **20"x20" Blue w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 254, 256, 257, 259, 260, 261, 263, 264 and 267 - FA Building**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-41**
MATERIAL DESCRIPTION: **20"x20" Blue w/ Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms 254, 256, 257, 259, 260, 261, 263, 264 and 267 - FA Building**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-42**
MATERIAL DESCRIPTION: **20"x20" Green w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 155, 156, 157, 158, 159, 160, 161, 164, 165, 176, 179 and 180 - FA Building**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-42**
MATERIAL DESCRIPTION: **20"x20" Green w/ Streaks VFT**
MATERIAL LOCATION: **Rooms 155, 156, 157, 158, 159, 160, 161, 164, 165, 176, 179 and 180 - FA Building**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-43**
MATERIAL DESCRIPTION: **20"x20" Green w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 155, 156, 157, 158, 159, 160, 161, 164, 165, 176, 179 and 180 - FA Building**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-43**
MATERIAL DESCRIPTION: **20"x20" Green w/ Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms 155, 156, 157, 158, 159, 160, 161, 164, 165, 176, 179 and 180 - FA Building**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 04/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-44**
MATERIAL DESCRIPTION: **20"x20" Peach w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 155, 156, 157, 158, 159, 160, 161, 164, 165, 176, 179, 180, 254, 256, 257, 259, 260, 261, 263, 264 and 267 - FA Building**

MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-44**
MATERIAL DESCRIPTION: **20"x20" Peach w/ Streaks VFT**
MATERIAL LOCATION: **Rooms 155, 156, 157, 158, 159, 160, 161, 164, 165, 176, 179, 180, 254, 256, 257, 259, 260, 261, 263, 264 and 267 - FA Building**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-45**
MATERIAL DESCRIPTION: **20"x20" Peach w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 155, 156, 157, 158, 159, 160, 161, 164, 165, 176, 179, 180, 254, 256, 257, 259, 260, 261, 263, 264 and 267 - FA Building**

MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-45**
MATERIAL DESCRIPTION: **20"x20" Peach w/ Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms 155, 156, 157, 158, 159, 160, 161, 164, 165, 176, 179, 180, 254, 256, 257, 259, 260, 261, 263, 264 and 267 - FA Building**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-46**
MATERIAL DESCRIPTION: **2'x2' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd Floor Corridors, Room 180C - FA Building**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-46**
MATERIAL DESCRIPTION: **2'x2' Ceiling Tile**
MATERIAL LOCATION: **1st and 2nd Floor Corridors, Room 180C - FA Building**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-47**
MATERIAL DESCRIPTION: **12"x12" Blue VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 182 and offices**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-47**
MATERIAL DESCRIPTION: **12"x12" Blue VFT**
MATERIAL LOCATION: **Room 182 and offices**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-47A**
MATERIAL DESCRIPTION: **12"x12" Blue VFT mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 182 and offices**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-47A**
MATERIAL DESCRIPTION: **12"x12" Blue VFT mastic**
MATERIAL LOCATION: **Room 182 and offices**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-48**
MATERIAL DESCRIPTION: **12"x12" Yellow VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 182 and offices**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-48**
MATERIAL DESCRIPTION: **12"x12" Yellow VFT**
MATERIAL LOCATION: **Room 182 and offices**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FA-48A**
MATERIAL DESCRIPTION: **12"x12" Yellow VFT mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 182 and offices**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FA-48A**
MATERIAL DESCRIPTION: **12"x12" Yellow VFT mastic**
MATERIAL LOCATION: **Room 182 and offices**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-001**
MATERIAL DESCRIPTION: **9"x9" Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Engineer's Office (Abated) and Maintenance Room, Basement Corridor Storage Room (Abated) - 1899 Bldg.**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FT-001**
MATERIAL DESCRIPTION: **9"x9" Beige Floor Tile**
MATERIAL LOCATION: **Engineer's Office (Abated) and Maintenance Room, Basement Corridor Storage Room (Abated) - 1899 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-001**
MATERIAL DESCRIPTION: **9"x9" Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office and Maintenance Room - 1899 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/26/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUIDLING ID: **1620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lincoln Park High School** REVIEW DATE: **4/16/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

HOMOGENEOUS AREA: **FTM-001**
MATERIAL DESCRIPTION: **9"x9" Beige Floor Tile Mastic**
MATERIAL LOCATION: **Engineer's Office and Maintenance Room - 1899 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/16/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46321** BUILDING ID: **1620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**
SCHOOL NAME: **Lincoln Park High School** INSPECTION DATE: **3/26/2025**
ADDRESS: **2001 N. Orchard** IDPH LICENSE NO: **100-18790**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **99-64**
MATERIAL DESCRIPTION: **Brown Laminate Wood Flooring**
MATERIAL LOCATION: **Engineer Office/storage closet**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
good condition

Inspector's Signature: _____ Date: 03/26/2025

APPENDIX B

Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Illinois



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 18790

ISSUED
4/5/2024

EXPIRES
05/15/2025

ALLIZON L BROOKS
2942 W VAN BUREN ST
CHICAGO, IL 60612

Environmental Health



ALLIZON L BROOKS
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/5/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 18790

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS INSPECTOR PROJECT MANAGER AIR SAMPLING PROFESSIONAL	TC EXPIRES 1/27/2025 6/12/2024
ID NUMBER 100 - 18790	ISSUED 4/5/2024	EXPIRES 05/15/2025	Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	
ALLIZON L BROOKS 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health				

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

IDPH ASBESTOS
PROFESSIONAL
LICENSE

ID NUMBER
100 - 18790

ISSUED
4/30/2025

EXPIRES
05/15/2026



ALLIZON L BROOKS
9016 S MORGAN ST
CHICAGO, IL 60620

Environmental Health

ENDORSEMENTS

TC EXPIRES

INSPECTOR

1/4/2026

PROJECT MANAGER
AIR SAMPLING PROFESSIONAL

6/1/2025

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ALLIZON L. BROOKS
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 01/04/2025 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

01/04/2025

Course Dates:

01/04/2026

Expires:

2501BIR02

Certificate Number:

A handwritten signature in black ink, appearing to read "N Peneff".

Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612

6/9/2025

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
	ID NUMBER 100 - 07342	ISSUED 6/9/2025	INSPECTOR PROJECT DESIGNER MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL	3/7/2026 1/27/2026 3/7/2026 4/7/2026
JIGAR M SHAH 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health		EXPIRES 05/15/2026 	Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.


Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB

7233 S. Adams Street | Willowbrook, IL 60527
(630) 655-3900 | www.otssafety.com

2023



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/23/2023

Exam Date: 2/23/2023

Expiration Date: 2/23/2024

Certificate Number: MPR2302230560

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022

Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: MPR2203090714

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022

Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: BIR2203090705

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 07342

ISSUED
4/1/2022

EXPIRES
05/15/2023

JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612



Environmental Health

JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/1/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 <p>ASBESTOS PROFESSIONAL LICENSE</p>			<p>ENDORSEMENTS</p>		<p>TC EXPIRES</p>
<p>ID NUMBER 100 - 07342</p>	<p>ISSUED 4/1/2022</p>	<p>EXPIRES 05/15/2023</p>	<p>INSPECTOR</p>	<p>3/9/2023</p>	
<p>JIGAR M SHAH 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health</p>			<p>PROJECT DESIGNER</p>	<p>3/24/2023</p>	
			<p>MANAGEMENT PLANNER</p>	<p>3/9/2023</p>	
			<p>PROJECT MANAGER</p>	<p>3/2/2023</p>	
			<p>AIR SAMPLING PROFESSIONAL</p>		
			<p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>		

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB



525-535 West Jefferson Street • Springfield, Illinois



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 07342

ISSUED
4/8/2024

EXPIRES
05/15/2025

JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612

Environmental Health



JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/8/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 <p>ASBESTOS PROFESSIONAL LICENSE</p>			<p>ENDORSEMENTS</p> <p>INSPECTOR PROJECT DESIGNER MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL</p>	<p>TC EXPIRES</p> <p>3/8/2025 3/7/2025 3/8/2025 3/25/2024</p>
<p>ID NUMBER 100 - 07342</p>	<p>ISSUED 4/8/2024</p>	<p>EXPIRES 05/15/2025</p>	<p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>	
<p>JIGAR M SHAH 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health</p>				

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH. IMPROVING LIVES

Nationally Accredited by PHAB



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2024

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 3/8/2024

Exam Date: 3/8/2024

Expiration Date: 3/8/2025

Certificate Number: MPR2403081126

Course Credit Hours: MPR 4 Hours

A handwritten signature in black ink that reads "Kristina Miczek". The signature is written in a cursive style.

Kristina Miczek, Training Manager



OCCUPATIONAL TRAINING & SUPPLY, INC.

2025

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 3/7/2025

Exam Date: 3/7/2025

Expiration Date: 3/7/2026

Certificate Number: MPR2503070948

Course Credit Hours: MPR 4 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

Kristina Miczek, Training Manager

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed