

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0004
SCHOOL NAME: Bowen Campus
ADDRESS OF SCHOOL: 2710 E. 89th St.
CITY: Chicago, IL, 60617

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 7/15/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 5/14/2025 ENROLLMENT 273
IDPH INSPECTOR LICENSE NUMBER: 100-21040
IDPH LICENSED INSPECTOR NAME (Please Print): Josh Herman
IDPH MP LICENSE NUMBER: 100-01784
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Steven Geneser

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 5/28/2025

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

05/26/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 46051 Region: 06 IDPH ID: 14-016-2990-0004

School: Bowen Campus Building ID: 1240

Address: 2710 E. 89th St.

Chicago, IL, 60617

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date: 5/14/2025

Review Date: 05/26/2025

Inspector: Josh Herman


Inspector IDPH License: 100-21040

Management Planner: Steven Geneser

Management Planner IDPH License: 100-01784

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.



Steven Geneser
100-01784

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: May 28, 2025

RE: Bowen Campus, Unit 46491
2710 E. 89th St.
Chicago, IL, 60617

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Bowen Campus , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Bowen Campus, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Bowen Campus. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1240:

110	12"x12" Green/Grey Floor Tile
110A	Mastic associated w/12"x12" Green/Grey Floor Tile
111	12"x12" Pink Floor Tile
111A	Mastic associated with 12"x12" Pink Floor Tile NOT OBSERVED
201	Boiler Breeching ABATED
202	Spray-on Fireproofing
203	4'x4' Smooth Ceiling Tile
204	24"x24" White, Light Grey & Grey Floor Tile
204M	Mastic associated w/24"x24" White, Light Grey & Grey Floor Tile

205	Fire Doors
206	Multicolor Mosaic Ceramic Tile Grout
207	Brown Cermamic Tile Grout
208	Sink Undercoating
209	Stair Tread Adhesive
210	Black Stage Curtains
39	Brown Carpet Mastic ABATED
40	Brown Carpet w/Dots ABATED
E	Condensate Tank Insulation
NEW	Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 1240:

- 202 Spray-on Fireproofing
- 203 4'x4' Smooth Ceiling Tile
- 204 24"x24" White, Light Grey & Grey Floor Tile
- 204M Mastic associated w/24"x24" White, Light Grey & Grey Floor Tile
- 205 Fire Doors
- 206 Multicolor Mosaic Ceramic Tile Grout
- 207 Brown Cermamic Tile Grout
- 208 Sink Undercoating
- 209 Stair Tread Adhesive
- 210 Black Stage Curtains
- E Condensate Tank Insulation

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	12x12 Tan w/Brown Specks Floor Tile
01AFT	12X12 Green w/Green Specks Vinyl Floor Tile
01AM	12x12 Green w/Green Specks Vinyl Floor Tile Mastic
01CM	12x12 Dark Gray w/Specks Vinyl Floor Tile Mastic
02	9x9 Floor Tile
03FT6	12x12 Brown Floor Tile
03FT8	12x12 Beige Speckled Floor Tile
04	Tectum Ceiling
06	Linoleum Floor
06FT11	12"x12" Gray Floor Tile
06FT12	12"x12" Light Blue Floor Tile Mastic (under carpet)
06FT13	12"x12" White w/Tan Specks Floor Tile
06FT14	12"x12" Cream Floor Tile
06FT7	12x12 Light Brown Floor Tile
07FT9	12x12 Red Floor Tile- NOT OBSERVED
09	12x12 Tan w/Brown Specks Floor Tile Mastic
09FT12	12"x12" Light Blue Floor Tile
09FT13	12"x12" White w/Tan Specks Floor Tile Mastic
09FT14	12"x12" Cream Floor Tile Mastic
09FT5	12"x12" Dark Brown and Cream Speckled Floor Tile Mastic
100	2'x4' White w/Pin-Holes Ceiling Tile
101	Terrazzo
102	Plaster
103	Air Cell
104	2'x4' Ceiling Tile
105	12"x12" Light Purple Mixed Speckled Floor Tile
106	12"x12" Light Purple Mixed Speckled Floor Tile Mastic
107	12"x12" Light Vanilla Floor Tile Mastic
108	Spray-On NOT OBSERVED
109	Lab Tables
110	12"x12" Green/Grey Floor Tile
110A	Mastic associated w/12"x12" Green/Grey Floor Tile
111	12"x12" Pink Floor Tile
111A	Mastic associated with 12"x12" Pink Floor Tile NOT OBSERVED
112	12"x12" Grey Floor Tile
112A	Mastic associated with 12"x12" Grey Floor Tile
113	12"x12" Grey/White Floor Tile
113A	Mastic associated with 12"x12" Grey/White Floor

	Tile
16	12x12 Floor Tile Mastic
16FT6	12"x12" Brown Floor Tile Mastic
16FT8	12"x12" Beige Speckled Floor Tile
17	9"x9" Maroon and Tan Floor Tile Mastic
19	Linoleum Mastic
1BFT	12x12 Light Gray w/Gray and White Specks Vinyl Floor Tile
1BM	12x12 Gray w/Gray and White Specks Vinyl Floor Tile Mastic
1CFT	12x12 Dark Gray w/Specs Vinyl Floor Tile
1CM	Carpet Mastic
1DS	Drywall System
20	9x9 Floor Tile Mastic
200	1x1 Pink Ceramic Flooring
202	Spray-on Fireproofing
203	4'x4' Smooth Ceiling Tile
204	24"x24" White, Light Grey & Grey Floor Tile
204M	Mastic associated w/24"x24" White, Light Grey & Grey Floor Tile
205	Fire Doors
206	Multicolor Mosaic Ceramic Tile Grout
207	Brown Cermamic Tile Grout
208	Sink Undercoating
209	Stair Tread Adhesive
210	Black Stage Curtains
22	12x12 Beige w/White Streaks Floor Tile NOT OBSERVED
23	12x12 Beige w/White Streaks Floor Tile Mastic
24	Turquoise Carpet Mastic
25	12x12 Gray Floor Tile
26	12x12 Gray Floor Tile Mastic
28	Gray Carpet Mastic NOT OBSERVED
33	Black Baseboard
34	Black Baseboard Mastic
35	9x9 Brown Floor Tile
36	9x9 Brown, 9x9 Tan, & 9x9 Dark Brown Mastic
37	9x9 Tan Floor Tile
38	9x9 Dark Brown Floor Tile
41	Blue Carpet Mastic
42	Gray Carpet and associated Adhesive
42A	2'X2' Smooth Ceiling Tile
42B	Rubber Floor Mastic
43	Light Brown Baseboard
44	Light Brown Baseboard Mastic
45	12x12 Gray w/Green Spots Floor Tile
46	12x12 Gray w/Green Spots Floor Tile Mastic
47	Gray Baseboard

48	Gray Baseboard Mastic
49	Black Baseboard
50	Black Baseboard Mastic
51	Blue Baseboard
52	Blue Baseboard Mastic
53	Turquoise Baseboard
54	Turquoise Baseboard Mastic
55	Tan Linoleum
56	Tan Linoleum, Mastic
57	Brown Baseboard
58	Brown Baseboard Mastic
59	Blue Linoleum
60	Blue Linoleum Mastic
61	Tan Baseboard
62	Tan Baseboard Mastic
63	2x4 Ceiling Tile
64	Blue Carpet
65	Blue Carpet Mastic
66	Beige Linoleum
67	Vibration Collar
75	12x12 Light Vanilla Vinyl Floor Tile
76	TSI on HVAC Ducts
77	Hard Packed Fittings on Fiberglass Insulated Pipes
78	Linoleum and Associated Adhesive
79	12x12 Beige VFT/12x12 Brown VFT (Checkered) w/Mastic
80	Plaster
81	Plaster
82	12x12 Orange and White Floor Tile
83	12x12 Orange and White Floor Tile Mastic
84	12x12 Orange Floor Tile
85	12x12 Orange Floor Tile Mastic
86	12x12 Light Vanilla Floor Tile Mastic
87	Carpet Mastic
88	Linoleum NOT OBSERVED
89	Lab Counter Tops
90	9x9 Gray w/White Streaks Vinyl Floor Tile
91	9x9 Gray w/White Streaks Vinyl Floor Tile Mastic
92	12"x12" Light Cream Mixed Speckled Floor Tile
93	12"x12" Light Cream Mixed Speckled Floor Tile Mastic
94	12"x12" Vanilla Mixed Speckled Floor Tile
95	12"x12" Vanilla Mixed Speckled Floor Tile Mastic
96	12"x12" White w/Blue Specks Floor Tile
97	12"x12" White w/Blue Specks Floor Tile Mastic
98	12"x12" Light Tan w/Streaks Floor Tile
99	12"x12" Light Tan w/Streaks Mastic
D	Pipe Fitting Insulation

E	Condensate Tank Insulation
HA-1000	1'x1' White Ceiling Tile w/Random and Regular Holes
HA-1001	1'x1' White Ceiling Tile w/Holes Glue
HA-1002	Muddled Pipe Fittings
HA-1003	Muddled Pipe Fittings
NEW	Newly Installed Suspect ACM

The following areas were deemed to be inaccessible:

01AM	12x12 Green w/Green Specks Vinyl Floor Tile Mastic
01CM	12x12 Dark Gray w/Specks Vinyl Floor Tile Mastic
04	Tectum Ceiling
05	9x9 Floor Tile ABATED 1991
09	12x12 Tan w/Brown Specks Floor Tile Mastic
09FT13	12"x12" White w/Tan Specks Floor Tile Mastic
09FT14	12"x12" Cream Floor Tile Mastic
09FT5	12"x12" Dark Brown and Cream Speckled Floor Tile Mastic
09FT7	12"x12" Light Brown Floor Tile Mastic
106	12"x12" Light Purple Mixed Speckled Floor Tile Mastic
107	12"x12" Light Vanilla Floor Tile Mastic
16	12x12 Floor Tile Mastic
16FT-2	12"x12" Cream Floor Tile Mastic
16FT10	12"x12" Orange and White Floor Tile Mastic
16FT3	12"x12" Green Floor Tile Mastic
16FT4	9"x9" White w/Green Specks Floor Tile Mastic
16FT6	12"x12" Brown Floor Tile Mastic
16FT7	12"x12" Light Brown Floor Tile Mastic
17	9"x9" Maroon and Tan Floor Tile Mastic
19	Linoleum Mastic
1BM	12x12 Gray w/Gray and White Specks Vinyl Floor Tile Mastic
1CM	Carpet Mastic
20	9x9 Floor Tile Mastic
202	Spray-on Fireproofing
20FT1	9"x9" Dark Brown Floor Tile Mastic
20FT2	9"x9" Light Grey Floor Tile Mastic
23	12x12 Beige w/White Streaks Floor Tile Mastic
26	12x12 Gray Floor Tile Mastic
28	Gray Carpet Mastic NOT OBSERVED
34	Black Baseboard Mastic
36	9x9 Brown, 9x9 Tan, & 9x9 Dark Brown Mastic
42B	Rubber Floor Mastic

44	Light Brown Baseboard Mastic
46	12x12 Gray w/Green Spots Floor Tile Mastic
48	Gray Baseboard Mastic
50	Black Baseboard Mastic
52	Blue Baseboard Mastic
54	Turquoise Baseboard Mastic
56	Tan Linoleum, Mastic
58	Brown Baseboard Mastic
60	Blue Linoleum Mastic
62	Tan Baseboard Mastic
63	2x4 Ceiling Tile
65	Blue Carpet Mastic
83	12x12 Orange and White Floor Tile Mastic
85	12x12 Orange Floor Tile Mastic
86	12x12 Light Vanilla Floor Tile Mastic
87	Carpet Mastic
91	9x9 Gray w/White Streaks Vinyl Floor Tile Mastic
93	12"x12" Light Cream Mixed Speckled Floor Tile Mastic
95	12"x12" Vanilla Mixed Speckled Floor Tile Mastic
97	12"x12" White w/Blue Specks Floor Tile Mastic
99	12"x12" Light Tan w/Streaks Mastic
9FT11	12"x12" Gray Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Josh Herman, IDPH License # 100-21040. The Management Plan was updated by Steven Geneser, IDPH License # 100-01784. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:	6/27/2022
	4/26/2023
	7/17/2024
	9/25/2024

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Bowen Campus Building 1240 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Bowen Campus **Unit** 46051 **Building ID** 1240
Address 2710 E. 89th St. **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	12x12 Tan w/Brown Specks Floor Tile	6,400	SF	Annex Rooms: 490, 312, 240, 224, 225, 230, 231, 242, 234, 235, 129, Dean's Office, Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
01AFT	12X12 Green w/Green Specks Vinyl Floor Tile	1,400	SF	Rooms 229, 241, 261	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
01AM	12x12 Green w/Green Specks Vinyl Floor Tile Mastic	1,400	SF	Rooms 229, 241, 261	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
01CM	12x12 Dark Gray w/Specs Vinyl Floor Tile Mastic	300	SF	261 Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02	9x9 Floor Tile	450	SF	Room 202	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02FT1	9x9 Dark Brown Floor Tile	1,200	SF	Main Building-Rooms 210, 211, 212	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02FT2	9x9 Light Gray Floor Tile	1,600	SF	Main Building-Rooms 311 & 312	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03FT14	12"x12" Cream Floor Tile	51,455	SF	Teachers' Lounge, 1st, 2nd, 3rd, & 4th Floor Hallways, 1st Floor Women's Bathroom, 3rd Floor Men's Bathroom, Rooms 490, 314, 204, 285A; 2nd Floor Handicap Toilet	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03FT3	12x12 Green Floor Tile	800	SF	Main Building-Principal's Office, Conference Room Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03FT4	9x9 White w/Green Specks Floor Tile	900	SF	Main Building-Room 202	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03FT6	12x12 Brown Floor Tile	800	SF	Main Building-1st Floor Hallway Trim, Room 410	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03FT7	12x12 Light Brown Speckled Floor Tile	15,000	SF	Main Building-Rooms 300, 310, 314, 315, 316, 306, 1st and 3rd Floor Faculty Bathrooms, 208A, 207, Main Office, and 2nd Floor Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Bowen Campus **Unit** 46051 **Building ID** 1240
Address 2710 E. 89th St. **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
03FT8	12x12 Beige Speckled Floor Tile	400	SF	Main Building-Room 308	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
04	Tectum Ceiling	5,000	SF	Main Building-Gymnasium	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
05	9x9 Floor Tile ABATED 1991			Annex 1st and 2nd Floor	ABATED	MISC								
06	Linoleum Floor	950	SF	Main Building-Stairways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06FT11	12"x12" Gray Floor Tile	14,000	SF	Annex- Rooms 222, 223, 226, 227, 232, 233, 236, 237, 124, 125, 137, 138, 139, 136	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06FT12	12"x12" Light Blue Floor Tile Mastic (under carpet)	2,000	SF	Annex- 1st Floor Offices, 2nd Floor Faculty Lounge, 140-A-J	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06FT13	12"x12" White w/Tan Specks Floor Tile	1,800	SF	Annex- Rooms 126 and 127	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06FT14	12"x12" Cream Floor Tile	5,000	SF	Annex- 1st and 2nd Floor Hallways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06FT5	12x12 Dark Brown and Cream Speckled Floor Tile	7,200	SF	Annex Rooms: 241, 240, 229, 242, 129, 229A	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06FT7	12x12 Light Brown Floor Tile	17,100	SF	Annex Rooms: 224, 225, 230, 231, 239, 122, 123, 134, 135, 136, 238	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07FT9	12x12 Red Floor Tile- NOT OBSERVED			Main Building-Lunchroom	ASSUMED	MISC								
09	12x12 Tan w/Brown Specks Floor Tile Mastic	6,400	SF	Annex Rooms: 241, 240, 224, 225, 229, 230, 231, 242, 234, 235, 129, Dean's Office, and Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09FT12	12"x12" Light Blue Floor Tile	2,500	SF	Annex- 1st Floor Offices, 2nd Floor Faculty Lounge, Room 140-AJ	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09FT13	12"x12" White w/Tan Specks Floor Tile Mastic	750	SF	Annex- Rooms 126 & 127	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09FT14	12"x12" Cream Floor Tile Mastic	1,850	SF	Annex- 1st and 2nd Floor Hallways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Bowen Campus **Unit** 46051 **Building ID** 1240
Address 2710 E. 89th St. **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
09FT5	12"x12" Dark Brown and Cream Speckled Floor Tile Mastic	7,200	SF	Annex- Rooms 240, 242, 129, 229A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09FT7	12"x12" Light Brown Floor Tile Mastic	17,100	SF	Annex Rooms: 224, 225, 230, 231, 239, 122, 123, 134, 135, 136, 238	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
100	2'x4' White w/Pin-Holes Ceiling Tile	4,300	SF	Throughout 1939 Building, Elevator Lobbies	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
101	Terrazzo	2,000	SF	1939 Building- Stairwell and Baseboard	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
102	Plaster	17,000	SF	Throughout 1939 Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
103	Air Cell	100	LF	1939 Building- Boys' Bathroom in Locker Room, Basement Vault, Boiler Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
104	2'x4' Ceiling Tile	10,000	SF	Throughout Annex	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
105	12"x12" Light Purple Mixed Speckled Floor Tile	400	SF	Annex- Lobby to Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
106	12"x12" Light Purple Mixed Speckled Floor Tile Mastic	400	SF	Annex- Lobby to Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
107	12"x12" Light Vanilla Floor Tile Mastic	4,000	SF	Main Building- Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
108	Spray-On NOT OBSERVED	1,200	SF	1st and 2nd Floor Entrance and Breezeway	ASSUMED	SURFACE	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
109	Lab Tables	1,100	SF	Annex- 229, 302, 306, 308 & 310	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
110	12"x12" Green/Grey Floor Tile	1,800	SF	Rooms 201, 205 & 210	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
110A	Mastic associated w/12"x12" Green/Grey Floor Tile	1,800	SF	Rooms 201, 205 & 210	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
111	12"x12" Pink Floor Tile	650	SF	Annex- Room 112	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
111A	Mastic associated with 12"x12" Pink Floor Tile NOT OBSERVED	300	SF	Room 238	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
112	12"x12" Grey Floor Tile	5,000	SF	Conference Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
112A	Mastic associated with 12"x12" Grey Floor	5,000	SF	Conference Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Bowen Campus **Unit** 46051 **Building ID** 1240
Address 2710 E. 89th St. **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Tile											potential for damage		
113	12"x12" Grey/White Floor Tile	600	SF	Room 410	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
113A	Mastic associated with 12"x12" Grey/White Floor Tile	600	SF	Room 410	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	Transite Panels ABATED			Swimming Pool and Locker Rooms	ABATED									
16	12x12 Floor Tile Mastic	162,000	SF	Main Building, 2nd, 3rd and 4th Floor Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16FT-2	12"x12" Cream Floor Tile Mastic	60,000	SF	1st, 2nd, 3rd & 4th Floor Hallways, 3rd Floor Men's Bathroom, 1st Floor Women's Bathroom, 2nd Floor Handicap Toilet, Rooms 490, 314, 204, 285A	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16FT10	12"x12" Orange and White Floor Tile Mastic	100	SF	Main Building-Engineer's Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16FT3	12"x12" Green Floor Tile Mastic	600	SF	Main Building-Principal's Office, Conference Room Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16FT4	9"x9" White w/Green Specks Floor Tile Mastic	900	SF	Main Building-Room 202	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16FT6	12"x12" Brown Floor Tile Mastic	800	SF	Main Building- 1st Floor Hallway Trim, Room 410	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16FT7	12"x12" Light Brown Floor Tile Mastic	16,000	SF	Main Building-Rooms: 300, 310, 314, 315, 316, 306, 3rd & 1st Floor Faculty Bathroom, 208A, 207, Main Office, and 2nd Floor Corridor (306 & 310 Removed)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16FT8	12"x12" Beige Speckled Floor Tile	1,000	SF	Main Building-Room 308	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16FT9	12"x12" Red Floor Tile Mastic NOT OBSERVED			Main Building-Lunchroom	CHR	MISC								
17	9"x9" Maroon and Tan Floor Tile Mastic	900	SF	Main Building-Swimming Pool and	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Bowen Campus **Unit** 46051 **Building ID** 1240
Address 2710 E. 89th St. **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Corridors										
19	Linoleum Mastic	950	SF	1908 Stairways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1BFT	12x12 Light Gray w/Gray and White Specks Vinyl Floor Tile	4,300	SF	Rooms 229, 241, 229A, 261	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1BM	12x12 Gray w/Gray and White Specks Vinyl Floor Tile Mastic	4,300	SF	Rooms 229, 241, 229A, 261	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1CFT	12x12 Dark Gray w/Specs Vinyl Floor Tile	300	SF	261 Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1CM	Carpet Mastic	9,000	SF	Rooms 144, 140C, 140H, 140E, 140D, 140, 140A, 140J, 200N, 211, 240	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1DS	Drywall System		SF	Room 231, 2nd Floor Breezeway, 1st Floor Breezeway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	9x9 Floor Tile Mastic	0	SF	Main Building- 2nd and 3rd Floor Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
200	1x1 Pink Ceramic Flooring	600	SF	Girls' Bathrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
201	Boiler Breaching ABATED			Boiler Room	ABATED	TSI			0		Yes			
202	Spray-on Fireproofing	10,000	SF	Throughout Annex	ASSUMED	MISC	Y	NONE	0		Yes	ACBM with the potential for damage		LOW
203	4'x4' Smooth Ceiling Tile	2,600	SF	Room 211	ASSUMED	MISC	Y	NONE	0		Yes	ACBM with the potential for damage		LOW
204	24"x24" White, Light Grey & Grey Floor Tile	1,300	SF	Room 306	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
204M	Mastic associated w/24"x24" White, Light Grey & Grey Floor Tile	1,300	SF	Room 306	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
205	Fire Doors		EA	Throughout Original Building	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
206	Multicolor Mosaic Ceramic Tile Grout	600	SF	Hallway near Main Gym	ASSUMED	SURFACE	N	NONE	0		Yes	ACBM with the potential for damage		LOW
207	Brown Ceramic Tile Grout		SF	All Girls' & Boys' Washrooms	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
208	Sink Undercoating	1	EA	Annex- Room 141C	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
209	Stair Tread Adhesive	360	LF	Original Building- All Staircases Throughout	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
20FT1	9"x9" Dark Brown Floor Tile Mastic	1,800	SF	Main Building- Rooms 200, 211-212	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20FT2	9"x9" Light Grey Floor Tile Mastic	900	SF	Main Building-	CHR	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Bowen Campus **Unit** 46051 **Building ID** 1240
Address 2710 E. 89th St. **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Rooms 311 & 312								potential for damage		
21	9x9 Floor Tile Mastic ABATED			Annex Room and Office	ABATED									
210	Black Stage Curtains	2,300	SF	Auditorium	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
22	12x12 Beige w/White Streaks Floor Tile NOT OBSERVED	200	SF	Main Building - Room 211 and 211A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	12x12 Beige w/White Streaks Floor Tile Mastic	200	SF	Main Building - Room 211 and 211A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	Turquoise Carpet Mastic	400	SF	Main Building - Assembly Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	12x12 Gray Floor Tile	600	SF	Main Building - Gym Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	12x12 Gray Floor Tile Mastic	1,000	SF	Main Building - Gym Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	Gray Carpet Mastic NOT OBSERVED	600	SF	Main Building - Room 400	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	Gray Linoleum ABATED			Main Building - Room 306	ABATED	MISC								
30	Gray Linoleum Mastic ABATED			Main Building - Room 306	ABATED	MISC								
31	Brown Baseboard ABATED			Main Building - Room 306	ABATED	MISC								
32	Brown Baseboard Mastic ABATED			Main Building - Room 306	ABATED	MISC								
33	Black Baseboard	75	LF	Main Building - Boys' Gym, 2nd floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	Black Baseboard Mastic	75	LF	Main Building - Boys' Gym, 2nd floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	9x9 Brown Floor Tile	15	SF	Main Building - Gym Vestibule, 2nd Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	9x9 Brown, 9x9 Tan, & 9x9 Dark Brown Mastic	15	SF	Main Building - Gym Vestibule, 2nd Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	9x9 Tan Floor Tile	15	SF	Main Building - Gym Vestibule, 2nd Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	9x9 Dark Brown Floor Tile	15	SF	Main Building - Gym Vestibule	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	Brown Carpet Mastic ABATED			Annex - Child Care Room	ABATED	MISC					Yes			
40	Brown Carpet w/Dots ABATED			Annex - Child Care Room	ABATED	MISC					Yes			
41	Blue Carpet Mastic	750	SF	Annex - Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Bowen Campus **Unit** 46051 **Building ID** 1240
Address 2710 E. 89th St. **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				(228)								potential for damage		
42	Gray Carpet and associated Adhesive	600	SF	Annex- Room 238, Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42A	2'X2' Smooth Ceiling Tile	5,500	SF	Staff Bathroom, Rooms 319, 241, 261, 229A, 229, 231, 140J, 140A, 140, 140D, 140E, 140H, 140G	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
42B	Rubber Floor Mastic	1,400	SF	231 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	Light Brown Baseboard	675	LF	Annex- Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	Light Brown Baseboard Mastic	675	LF	Annex- Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	12x12 Gray w/Green Spots Floor Tile	1,800	SF	Annex- Rooms 126 and 127	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	12x12 Gray w/Green Spots Floor Tile Mastic	1,800	SF	Annex- Rooms 126 and 127	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	Gray Baseboard	2,000	LF	Annex- Rooms: 222, 223, 226, 227, 232, 233, 235, 234, 236, 237, 124, 125, 137, 138, 139	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	Gray Baseboard Mastic	2,000	LF	Annex- Rooms: 222, 223, 226, 227, 232, 233, 235, 234, 236, 237, 124, 125, 137, 138, 139	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	Black Baseboard	450	LF	Annex- Rooms 240, 241, 229, 238	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	Black Baseboard Mastic	450	LF	Annex- Rooms 240, 241, 229, 238	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	Blue Baseboard	125	LF	Annex- Childcare Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	Blue Baseboard Mastic	125	LF	Annex- Childcare Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	Turquoise Baseboard	450	LF	Annex- Rooms 228, Women's 2nd Floor Faculty Lounge, West Office Corridor and Offices	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	Turquoise Baseboard Mastic	450	LF	Annex- Rooms 228, Womens 2nd Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Bowen Campus **Unit** 46051 **Building ID** 1240
Address 2710 E. 89th St. **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Faculty Lounge, West Office Corridor and Offices										
55	Tan Linoleum	800	SF	Annex- Childcare Room, Room 133	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	Tan Linoleum, Mastic	800	SF	Annex- Childcare Room, Room 133	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	Brown Baseboard	200	LF	Annex- Childcare Room and YMCA Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	Brown Baseboard Mastic	200	LF	Annex- Childcare Room and YMCA Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	Blue Linoleum	300	SF	Annex- Childcare Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60	Blue Linoleum Mastic	300	SF	Annex- Childcare Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	Tan Baseboard	1,200	LF	Annex- Rooms 224, 225, 230, 231, 239, 122, 123, 126, 135, 136, 134, Infant Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
62	Tan Baseboard Mastic	1,200	LF	Annex- Rooms 224, 225, 230, 231, 239, 122, 123, 126, 135, 136, 134, Infant Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	2x4 Ceiling Tile	304,571	SF	Throughout Main & Annex Building	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
64	Blue Carpet	1,500	SF	Main Building- Social Room, Library 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
65	Blue Carpet Mastic	1,500	SF	Main Building- Social Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
66	Beige Linoleum	2,500	SF	Main Building- Rooms 211, 307, 308, 310, 310A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
67	Vibration Collar	25	LF	Annex Mechanical Room	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
75	12x12 Light Vanilla Vinyl Floor Tile	4,000	SF	Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
76	TSI on HVAC Ducts	60	LF	Annex 2nd Floor Fan Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable		MODERATE

Chicago Public Schools

School Bowen Campus **Unit** 46051 **Building ID** 1240
Address 2710 E. 89th St. **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
77	Hard Packed Fittings on Fiberglass Insulated Pipes	50	LF	Auto Shop	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
78	Linoleum and Associated Adhesive	3,600	SF	206, 207, 209, 306, 310, 205A, 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
79	12x12 Beige VFT/12x12 Brown VFT (Checkered) w/Mastic	1,000	SF	238 and 239	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
80	Plaster	304,571	SF	Throughout Main Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
81	Plaster	25,000	SF	Throughout Annex Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
82	12x12 Orange and White Floor Tile	100	SF	Main Building-Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
83	12x12 Orange and White Floor Tile Mastic	100	SF	Main Building-Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
84	12x12 Orange Floor Tile	200	SF	Main Building-Cafeteria Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
85	12x12 Orange Floor Tile Mastic	200	SF	Main Building-Cafeteria Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
86	12x12 Light Vanilla Floor Tile Mastic	4,000	SF	Main Building-Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
87	Carpet Mastic	5,000	SF	Main Building- 211 Conference Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
88	Linoleum NOT OBSERVED	700	SF	Room 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
89	Lab Counter Tops	1,400	SF	Main Building-Rooms 310, 308, 307, 306, 206 & 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
90	9x9 Gray w/White Streaks Vinyl Floor Tile	700	SF	Main Building-Rooms 201, 212, 311	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
91	9x9 Gray w/White Streaks Vinyl Floor Tile Mastic	500	SF	Main Building-Rooms 201, 212, 311	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
92	12"x12" Light Cream Mixed Speckled Floor Tile	950	SF	Main Building-Rooms 205, 105A, B, C, D, E, and F	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
93	12"x12" Light Cream Mixed Speckled Floor Tile Mastic	950	SF	Main Building-Rooms 205, 105A, B, C, D, E, and F	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
94	12"x12" Vanilla Mixed Speckled Floor Tile	1,300	SF	Main Building-Rooms 300 and 207, Elevator Vestibule	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Bowen Campus **Unit** 46051 **Building ID** 1240
Address 2710 E. 89th St. **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
95	12"x12" Vanilla Mixed Speckled Floor Tile Mastic	1,300	SF	Main Building- Rooms 300 and 207, Elevator Vestibule	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
96	12"x12" White w/Blue Specks Floor Tile	550	SF	Main Building- Room 209	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
97	12"x12" White w/Blue Specks Floor Tile Mastic	550	SF	Main Building- Room 209	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
98	12"x12" Light Tan w/Streaks Floor Tile	2,800	SF	1939 Building- 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
99	12"x12" Light Tan w/Streaks Mastic	2,800	SF	1939 Building- 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
9FT11	12"x12" Gray Floor Tile Mastic	13,500	SF	Annex- Rooms 222, 223, 226, 227, 232, 233, 236, 237, 124, 125, 137, 138, 139, 136	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Tank Insulation ABATED			Annex Boiler Room	ABATED									
A(#2)	Aircell Pipe Insulation ABATED			Main Building- Mechanical Area, Classrooms, Lunchroom	ABATED									
B	Boiler Breaching ABATED			Annex Boiler Room	ABATED									
C	Cardboard Insulation ABATED			Main Building- Classrooms and Mechanical Areas	ABATED									
D	Pipe Fitting Insulation	130	LF	Throughout Annex	ASSUMED	TSI	Y	LOC	1		No	Damaged or significantly damaged friable thermal system insulating ACBM		MODERATE
D(#2)	Cementitious Joints on Cardboard ABATED			Main Building- Classrooms, Mechanical Area	ABATED									
E	Condensate Tank Insulation	60	LF	Boiler Room	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		MODERATE
F	Joints and Elbows on Fiberglass Runs ABATED			Main Building- Classrooms, Mechanical Areas, 1st, 2nd, and 3rd Floor	ABATED	TSI								
G	Pre-Form Pipe Insulation ABATED			Main Building	ABATED									
H	Elbows on Pre-Formed Pipe Insulation ABATED			Main Building	ABATED									
HA-1000	1'x1' White Ceiling Tile w/Random and	1,200	SF	Kitchen Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Bowen Campus **Unit** 46051 **Building ID** 1240
Address 2710 E. 89th St. **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Chicago Public Schools

School Bowen Campus Unit 46051 Building ID 1240
Address 2710 E. 89th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date <u>5/14/2025</u>
Inspector Name <u>Josh Herman</u>
<u>100-21040</u> <u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01	
01AFT	
01AM	
01CM	
02	
02FT1	Tile Abated in Room 211
02FT2	
03FT14	2025- 3000 SF of Material Abated from 1st Floor Corridor in 2022; 3/4 of Room 314 (545 SF) 2024Abated
03FT3	
03FT4	
03FT6	
03FT7	Tile Removed from RoomS 306 & 310
03FT8	
04	
05	
06	
06FT11	
06FT12	Under Carpet
06FT13	
06FT14	
06FT5	Material abated from Room 241
06FT7	New Floor in Room 231
07FT9	Not Observed Multiple Years

Chicago Public Schools

School Bowen Campus **Unit** 46051 **Building ID** 1240
Address 2710 E. 89th St. **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
09	Material under carpet in Room 240. Mastic abated from Library, Rooms 240 & 241
09FT12	Tile Not Observed. Might be under Carpet
09FT13	
09FT14	
09FT5	
09FT7	
100	
101	
102	Damaged Plaster in Room 200D Storage
103	
104	
105	
106	
107	
108	Not Observed 2025
109	
110	
110A	
111	Not Observed 2025
111A	Not Observed 2025
112	
112A	
113	
113A	
14	
16	
16FT-2	2025- 3000 SF of Material Abated from 1st Floor Corridor in 2022; 3/4 of Room 314 (545 SF) Abated in 2024
16FT10	

Chicago Public Schools

School Bowen Campus **Unit** 46051 **Building ID** 1240
Address 2710 E. 89th St. **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
16FT3	
16FT4	
16FT6	
16FT7	
16FT8	
16FT9	Not Observed Multiple Years
17	
19	
1BFT	
1BM	
1CFT	
1CM	
1DS	
20	
200	
201	Abated 2024
202	
203	
204	
204M	
205	
206	
207	
208	
209	
20FT1	
20FT2	
21	
210	

Chicago Public Schools

School Bowen Campus **Unit** 46051 **Building ID** 1240
Address 2710 E. 89th St. **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
22	Not Observed 2025
23	
24	
25	
26	
28	Not Observed 2025
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
42A	
42B	
43	
44	
45	
46	
47	
48	
49	

Chicago Public Schools

School Bowen Campus **Unit** 46051 **Building ID** 1240
Address 2710 E. 89th St. **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
75	
76	
77	
78	2025- Not Observed in Room 211
79	
80	
81	
82	
83	
84	
85	

Chicago Public Schools

School Bowen Campus **Unit** 46051 **Building ID** 1240
Address 2710 E. 89th St. **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
86	
87	
88	Not Observed 2025
89	
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
9FT11	
A	
A(#2)	
B	
C	
D	
D(#2)	
E	
F	
G	
H	
HA-1000	
HA-1001	
HA-1002	
HA-1003	

Chicago Public Schools

School Bowen Campus **Unit** 46051 **Building ID** 1240
Address 2710 E. 89th St. **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
N	
NEW	
O	
P	
X	
Y	

Table II
Management Planner's Review

Chicago Public Schools

School Bowen Campus

Unit 46051

Building ID 1240

Address 2710 E. 89th St.

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	12x12 Tan w/Brown Specks Floor Tile	6,400	SF	Annex Rooms: 490, 312, 240, 224, 225, 230, 231, 242, 234, 235, 129, Dean's Office, Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
01AFT	12X12 Green w/Green Specks Vinyl Floor Tile	1,400	SF	Rooms 229, 241, 261	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
01AM	12x12 Green w/Green Specks Vinyl Floor Tile Mastic	1,400	SF	Rooms 229, 241, 261	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
01CM	12x12 Dark Gray w/Specs Vinyl Floor Tile Mastic	300	SF	261 Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02	9x9 Floor Tile	450	SF	Room 202	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02FT1	9x9 Dark Brown Floor Tile	1,200	SF	Main Building- Rooms 210, 211, 212	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02FT2	9x9 Light Gray Floor Tile	1,600	SF	Main Building- Rooms 311 & 312	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03FT14	12"x12" Cream Floor Tile	51,455	SF	Teachers' Lounge, 1st, 2nd, 3rd, & 4th Floor Hallways, 1st Floor Women's Bathroom, 3rd Floor Men's Bathroom, Rooms 490, 314, 204, 285A; 2nd Floor Handicap Toilet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03FT3	12x12 Green Floor Tile	800	SF	Main Building- Principal's Office, Conference Room Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03FT4	9x9 White w/Green Specks Floor Tile	900	SF	Main Building- Room 202	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03FT6	12x12 Brown Floor Tile	800	SF	Main Building- 1st Floor Hallway Trim, Room 410	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03FT7	12x12 Light Brown Speckled Floor Tile	15,000	SF	Main Building- Rooms 300, 310, 314, 315, 316, 306, 1st and 3rd Floor Faculty Bathrooms, 208A, 207, Main Office, and 2nd Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03FT8	12x12 Beige Speckled Floor Tile	400	SF	Main Building- Room 308	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	Tectum Ceiling	5,000	SF	Main Building- Gymnasium	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
05	9x9 Floor Tile ABATED 1991			Annex 1st and 2nd Floor	Abated	MISC					
06	Linoleum Floor	950	SF	Main Building- Stairways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06FT11	12"x12" Gray Floor Tile	14,000	SF	Annex- Rooms 222, 223, 226, 227, 232, 233, 236, 237, 124, 125, 137, 138, 139, 136	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06FT12	12"x12" Light Blue Floor Tile Mastic (under carpet)	2,000	SF	Annex- 1st Floor Offices, 2nd Floor Faculty Lounge, 140-A-J	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06FT13	12"x12" White w/Tan Specks Floor Tile	1,800	SF	Annex- Rooms 126 and 127	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06FT14	12"x12" Cream Floor Tile	5,000	SF	Annex- 1st and 2nd Floor Hallways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Bowen Campus

Unit 46051

Building ID 1240

Address 2710 E. 89th St.

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
06FT5	12x12 Dark Brown and Cream Speckled Floor Tile	7,200	SF	Annex Rooms: 241, 240, 229, 242, 129, 229A	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06FT7	12x12 Light Brown Floor Tile	17,100	SF	Annex Rooms: 224, 225, 230, 231, 239, 122, 123, 134, 135, 136, 238	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07FT9	12x12 Red Floor Tile- NOT OBSERVED			Main Building- Lunchroom	Assumed	MISC					
09	12x12 Tan w/Brown Specks Floor Tile Mastic	6,400	SF	Annex Rooms: 241, 240, 224, 225, 229, 230, 231, 242, 234, 235, 129, Dean's Office, and Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09FT12	12"x12" Light Blue Floor Tile	2,500	SF	Annex- 1st Floor Offices, 2nd Floor Faculty Lounge, Room 140-AJ	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09FT13	12"x12" White w/Tan Specks Floor Tile Mastic	750	SF	Annex- Rooms 126 & 127	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09FT14	12"x12" Cream Floor Tile Mastic	1,850	SF	Annex- 1st and 2nd Floor Hallways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09FT5	12"x12" Dark Brown and Cream Speckled Floor Tile Mastic	7,200	SF	Annex- Rooms 240, 242, 129, 229A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09FT7	12"x12" Light Brown Floor Tile Mastic	17,100	SF	Annex Rooms: 224, 225, 230, 231, 239, 122, 123, 134, 135, 136, 238	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
100	2'x4' White w/Pin-Holes Ceiling Tile	4,300	SF	Throughout 1939 Building, Elevator Lobbies	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
101	Terrazzo	2,000	SF	1939 Building- Stairwell and Baseboard	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102	Plaster	17,000	SF	Throughout 1939 Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	Air Cell	100	LF	1939 Building- Boys' Bathroom in Locker Room, Basement Vault, Boiler Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
104	2'x4' Ceiling Tile	10,000	SF	Throughout Annex	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
105	12"x12" Light Purple Mixed Speckled Floor Tile	400	SF	Annex- Lobby to Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
106	12"x12" Light Purple Mixed Speckled Floor Tile Mastic	400	SF	Annex- Lobby to Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
107	12"x12" Light Vanilla Floor Tile Mastic	4,000	SF	Main Building- Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
108	Spray-On NOT OBSERVED	1,200	SF	1st and 2nd Floor Entrance and Breezeway	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
109	Lab Tables	1,100	SF	Annex- 229, 302, 306, 308 & 310	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
110	12"x12" Green/Grey Floor Tile	1,800	SF	Rooms 201, 205 & 210	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
110A	Mastic associated w/12"x12" Green/Grey Floor Tile	1,800	SF	Rooms 201, 205 & 210	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
111	12"x12" Pink Floor Tile	650	SF	Annex- Room 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
111A	Mastic associated with 12"x12" Pink Floor Tile NOT	300	SF	Room 238	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Bowen Campus

Unit 46051

Building ID 1240

Address 2710 E. 89th St.

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
OBSERVED											
112	12"x12" Grey Floor Tile	5,000	SF	Conference Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112A	Mastic associated with 12"x12" Grey Floor Tile	5,000	SF	Conference Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113	12"x12" Grey/White Floor Tile	600	SF	Room 410	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113A	Mastic associated with 12"x12" Grey/White Floor Tile	600	SF	Room 410	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	Transite Panels ABATED			Swimming Pool and Locker Rooms	Abated						
16	12x12 Floor Tile Mastic	162,000	SF	Main Building, 2nd, 3rd and 4th Floor Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16FT-2	12"x12" Cream Floor Tile Mastic	60,000	SF	1st, 2nd, 3rd & 4th Floor Hallways, 3rd Floor Men's Bathroom, 1st Floor Women's Bathroom, 2nd Floor Handicap Toilet, Rooms 490, 314, 204, 285A	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16FT10	12"x12" Orange and White Floor Tile Mastic	100	SF	Main Building- Engineer's Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16FT3	12"x12" Green Floor Tile Mastic	600	SF	Main Building- Principal's Office, Conference Room Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16FT4	9"x9" White w/Green Specks Floor Tile Mastic	900	SF	Main Building- Room 202	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16FT6	12"x12" Brown Floor Tile Mastic	800	SF	Main Building- 1st Floor Hallway Trim, Room 410	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16FT7	12"x12" Light Brown Floor Tile Mastic	16,000	SF	Main Building- Rooms: 300, 310, 314, 315, 316, 306, 3rd & 1st Floor Faculty Bathroom, 208A, 207, Main Office, and 2nd Floor Corridor (306 & 310 Removed)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16FT8	12"x12" Beige Speckled Floor Tile	1,000	SF	Main Building- Room 308	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16FT9	12"x12" Red Floor Tile Mastic NOT OBSERVED			Main Building- Lunchroom	Chrysotile	MISC					
17	9"x9" Maroon and Tan Floor Tile Mastic	900	SF	Main Building- Swimming Pool and Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Linoleum Mastic	950	SF	1908 Stairways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1BFT	12x12 Light Gray w/Gray and White Specks Vinyl Floor Tile	4,300	SF	Rooms 229, 241, 229A, 261	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1BM	12x12 Gray w/Gray and White Specks Vinyl Floor Tile Mastic	4,300	SF	Rooms 229, 241, 229A, 261	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1CFT	12x12 Dark Gray w/Specs Vinyl Floor Tile	300	SF	261 Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1CM	Carpet Mastic	9,000	SF	Rooms 144, 140C, 140H, 140E, 140D,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Bowen Campus

Unit 46051

Building ID 1240

Address 2710 E. 89th St.

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				140, 140A, 140J, 200N, 211, 240							
1DS	Drywall System		SF	Room 231, 2nd Floor Breezeway, 1st Floor Breezeway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	9x9 Floor Tile Mastic	0	SF	Main Building- 2nd and 3rd Floor Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
200	1x1 Pink Ceramic Flooring	600	SF	Girls' Bathrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
201	Boiler Breeching ABATED			Boiler Room	Abated	TSI		0			
202	Spray-on Fireproofing	10,000	SF	Throughout Annex	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
203	4'x4' Smooth Ceiling Tile	2,600	SF	Room 211	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
204	24"x24" White, Light Grey & Grey Floor Tile	1,300	SF	Room 306	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
204M	Mastic associated w/24"x24" White, Light Grey & Grey Floor Tile	1,300	SF	Room 306	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
205	Fire Doors		EA	Throughout Original Building	Assumed	MISC	No		EA	6 ACBM with the potential for damage	Follow O&M Plan
206	Multicolor Mosaic Ceramic Tile Grout	600	SF	Hallway near Main Gym	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
207	Brown Ceramic Tile Grout		SF	All Girls' & Boys' Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
208	Sink Undercoating	1	EA	Annex- Room 141C	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
209	Stair Tread Adhesive	360	LF	Original Building- All Staircases Throughout	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
20FT1	9"x9" Dark Brown Floor Tile Mastic	1,800	SF	Main Building- Rooms 200, 211-212	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20FT2	9"x9" Light Grey Floor Tile Mastic	900	SF	Main Building- Rooms 311 & 312	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	9x9 Floor Tile Mastic ABATED			Annex Room and Office	Abated						
210	Black Stage Curtains	2,300	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12x12 Beige w/White Streaks Floor Tile NOT OBSERVED	200	SF	Main Building - Room 211 and 211A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12x12 Beige w/White Streaks Floor Tile Mastic	200	SF	Main Building - Room 211 and 211A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Turquoise Carpet Mastic	400	SF	Main Building - Assembly Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12x12 Gray Floor Tile	600	SF	Main Building - Gym Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12x12 Gray Floor Tile Mastic	1,000	SF	Main Building - Gym Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Gray Carpet Mastic NOT OBSERVED	600	SF	Main Building - Room 400	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Gray Linoleum ABATED			Main Building - Room 306	Abated	MISC					
30	Gray Linoleum Mastic ABATED			Main Building- Room 306	Abated	MISC					
31	Brown Baseboard ABATED			Main Building- Room 306	Abated	MISC					
32	Brown Baseboard Mastic ABATED			Main Building- Room 306	Abated	MISC					
33	Black Baseboard	75	LF	Main Building- Boys' Gym, 2nd floor	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
34	Black Baseboard Mastic	75	LF	Main Building- Boys' Gym, 2nd floor	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Bowen Campus

Unit 46051

Building ID 1240

Address 2710 E. 89th St.

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
35	9x9 Brown Floor Tile	15	SF	Main Building- Gym Vestibule, 2nd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	9x9 Brown, 9x9 Tan, & 9x9 Dark Brown Mastic	15	SF	Main Building- Gym Vestibule, 2nd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	9x9 Tan Floor Tile	15	SF	Main Building- Gym Vestibule, 2nd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	9x9 Dark Brown Floor Tile	15	SF	Main Building- Gym Vestibule	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Brown Carpet Mastic ABATED			Annex- Child Care Room	Abated	MISC					
40	Brown Carpet w/Dots ABATED			Annex- Child Care Room	Abated	MISC					
41	Blue Carpet Mastic	750	SF	Annex- Library (228)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	Gray Carpet and associated Adhesive	600	SF	Annex- Room 238, Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42A	2'X2' Smooth Ceiling Tile	5,500	SF	Staff Bathroom, Rooms 319, 241, 261, 229A, 229, 231, 140J, 140A, 140, 140D, 140E, 140H, 140G	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
42B	Rubber Floor Mastic	1,400	SF	231 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	Light Brown Baseboard	675	LF	Annex- Corridor	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
44	Light Brown Baseboard Mastic	675	LF	Annex- Corridor	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
45	12x12 Gray w/Green Spots Floor Tile	1,800	SF	Annex- Rooms 126 and 127	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	12x12 Gray w/Green Spots Floor Tile Mastic	1,800	SF	Annex- Rooms 126 and 127	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	Gray Baseboard	2,000	LF	Annex- Rooms: 222, 223, 226, 227, 232, 233, 235, 234, 236, 237, 124, 125, 137, 138, 139	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
48	Gray Baseboard Mastic	2,000	LF	Annex- Rooms: 222, 223, 226, 227, 232, 233, 235, 234, 236, 237, 124, 125, 137, 138, 139	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
49	Black Baseboard	450	LF	Annex- Rooms 240, 241, 229, 238	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
50	Black Baseboard Mastic	450	LF	Annex- Rooms 240, 241, 229, 238	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
51	Blue Baseboard	125	LF	Annex- Childcare Area	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
52	Blue Baseboard Mastic	125	LF	Annex- Childcare Area	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
53	Turquoise Baseboard	450	LF	Annex- Rooms 228, Women's 2nd Floor Faculty Lounge, West Office Corridor and Offices	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
54	Turquoise Baseboard Mastic	450	LF	Annex- Rooms 228, Womens 2nd Floor Faculty Lounge, West Office Corridor and Offices	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
55	Tan Linoleum	800	SF	Annex- Childcare Room, Room 133	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Bowen Campus

Unit 46051

Building ID 1240

Address 2710 E. 89th St.

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
56	Tan Linoleum, Mastic	800	SF	Annex- Childcare Room, Room 133	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	Brown Baseboard	200	LF	Annex- Childcare Room and YMCA Office	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
58	Brown Baseboard Mastic	200	LF	Annex- Childcare Room and YMCA Office	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
59	Blue Linoleum	300	SF	Annex- Childcare Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	Blue Linoleum Mastic	300	SF	Annex- Childcare Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	Tan Baseboard	1,200	LF	Annex- Rooms 224, 225, 230, 231, 239, 122, 123, 126, 135, 136, 134, Infant Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
62	Tan Baseboard Mastic	1,200	LF	Annex- Rooms 224, 225, 230, 231, 239, 122, 123, 126, 135, 136, 134, Infant Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
63	2x4 Ceiling Tile	304,571	SF	Throughout Main & Annex Building	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
64	Blue Carpet	1,500	SF	Main Building- Social Room, Library 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	Blue Carpet Mastic	1,500	SF	Main Building- Social Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	Beige Linoleum	2,500	SF	Main Building- Rooms 211, 307, 308, 310, 310A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	Vibration Collar	25	LF	Annex Mechanical Room	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
75	12x12 Light Vanilla Vinyl Floor Tile	4,000	SF	Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	TSI on HVAC Ducts	60	LF	Annex 2nd Floor Fan Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
77	Hard Packed Fittings on Fiberglass Insulated Pipes	50	LF	Auto Shop	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
78	Linoleum and Associated Adhesive	3,600	SF	206, 207, 209, 306, 310, 205A, 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	12x12 Beige VFT/12x12 Brown VFT (Checkered) w/Mastic	1,000	SF	238 and 239	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80	Plaster	304,571	SF	Throughout Main Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	Plaster	25,000	SF	Throughout Annex Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
82	12x12 Orange and White Floor Tile	100	SF	Main Building- Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
83	12x12 Orange and White Floor Tile Mastic	100	SF	Main Building- Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
84	12x12 Orange Floor Tile	200	SF	Main Building- Cafeteria Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
85	12x12 Orange Floor Tile Mastic	200	SF	Main Building- Cafeteria Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
86	12x12 Light Vanilla Floor Tile Mastic	4,000	SF	Main Building- Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Bowen Campus

Unit 46051

Building ID 1240

Address 2710 E. 89th St.

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
87	Carpet Mastic	5,000	SF	Main Building- 211 Conference Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
88	Linoleum NOT OBSERVED	700	SF	Room 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
89	Lab Counter Tops	1,400	SF	Main Building- Rooms 310, 308, 307, 306, 206 & 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
90	9x9 Gray w/White Streaks Vinyl Floor Tile	700	SF	Main Building- Rooms 201, 212, 311	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
91	9x9 Gray w/White Streaks Vinyl Floor Tile Mastic	500	SF	Main Building- Rooms 201, 212, 311	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
92	12"x12" Light Cream Mixed Speckled Floor Tile	950	SF	Main Building- Rooms 205, 105A, B, C, D, E, and F	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
93	12"x12" Light Cream Mixed Speckled Floor Tile Mastic	950	SF	Main Building- Rooms 205, 105A, B, C, D, E, and F	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
94	12"x12" Vanilla Mixed Speckled Floor Tile	1,300	SF	Main Building- Rooms 300 and 207, Elevator Vestibule	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
95	12"x12" Vanilla Mixed Speckled Floor Tile Mastic	1,300	SF	Main Building- Rooms 300 and 207, Elevator Vestibule	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
96	12"x12" White w/Blue Specks Floor Tile	550	SF	Main Building- Room 209	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
97	12"x12" White w/Blue Specks Floor Tile Mastic	550	SF	Main Building- Room 209	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
98	12"x12" Light Tan w/Streaks Floor Tile	2,800	SF	1939 Building- 1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99	12"x12" Light Tan w/Streaks Mastic	2,800	SF	1939 Building- 1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9FT11	12"x12" Gray Floor Tile Mastic	13,500	SF	Annex- Rooms 222, 223, 226, 227, 232, 233, 236, 237, 124, 125, 137, 138, 139, 136	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Tank Insulation ABATED			Annex Boiler Room	Abated						
A(#2)	Aircell Pipe Insulation ABATED			Main Building- Mechanical Area, Classrooms, Lunchroom	Abated						
B	Boiler Breaching ABATED			Annex Boiler Room	Abated						
C	Cardboard Insulation ABATED			Main Building- Classrooms and Mechanical Areas	Abated						
D	Pipe Fitting Insulation	130	LF	Throughout Annex	Assumed	TSI	Yes	1	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
D(#2)	Cementitious Joints on Cardboard ABATED			Main Building- Classrooms, Mechanical Area	Abated						
E	Condensate Tank Insulation	60	LF	Boiler Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	Joints and Elbows on Fiberglass Runs ABATED			Main Building- Classrooms, Mechanical Areas, 1st, 2nd, and 3rd Floor	Abated	TSI					
G	Pre-Form Pipe Insulation ABATED			Main Building	Abated						

Chicago Public Schools

School Bowen Campus

Unit 46051

Building ID 1240

Address 2710 E. 89th St.

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
H	Elbows on Pre-Formed Pipe Insulation ABATED			Main Building	Abated						
HA-1000	1'x1' White Ceiling Tile w/Random and Regular Holes	1,200	SF	Kitchen Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1001	1'x1' White Ceiling Tile w/Holes Glue	1,200	SF	Kitchen Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1002	Muddled Pipe Fittings	20	LF	1908 Building- Boiler Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
HA-1003	Muddled Pipe Fittings	30	LF	1953 Building- AHU by GYM, GYM	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
N	Cardboard Pipe Insulation ABATED			Main Building- Mechanical Room	Abated						
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan
O	Cementitious Joints ABATED			Main Building- Mechanical Rooms	Abated	TSI					
P	Cementitious Fittings on Fiberglass ABATED			Main Building- Unexcavated Area and Boiler Room	Abated						
X	Paper Wrap Pipe Insulation ABATED			Main Building- Throughout 1st Floor Corridor, Above Plaster Ceiling	Abated						
Y	Joints on Cardboard Pipe Insulation ABATED			Main Building- Throughout 1st Floor Corridor, Above Plaster Ceiling	Abated						

Chicago Public Schools

School Bowen Campus

Unit 46051

Building ID 1240

Address 2710 E. 89th St.

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	5/26/2025
Manager Planner Name	Steven Geneser
100-01784	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
01AFT	
01AM	
01CM	
02	
02FT1	
02FT2	
03FT14	
03FT3	
03FT4	
03FT6	
03FT7	
03FT8	
04	
05	
06	
06FT11	
06FT12	
06FT13	
06FT14	

Chicago Public Schools

School Bowen Campus

Unit 46051

Building ID 1240

Address 2710 E. 89th St.

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
06FT5	
06FT7	
07FT9	
09	
09FT12	
09FT13	
09FT14	
09FT5	
09FT7	
100	
101	
102	Patch or repair plaster as needed
103	
104	
105	
106	
107	
108	
109	
110	
110A	
111	
111A	
112	
112A	
113	
113A	

Chicago Public Schools

School Bowen Campus

Unit 46051

Building ID 1240

Address 2710 E. 89th St.

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
14	
16	
16FT-2	
16FT10	
16FT3	
16FT4	
16FT6	
16FT7	
16FT8	
16FT9	
17	
19	
1BFT	
1BM	
1CFT	
1CM	
1DS	
20	
200	
201	
202	
203	
204	
204M	
205	
206	
207	

Chicago Public Schools

School Bowen Campus

Unit 46051

Building ID 1240

Address 2710 E. 89th St.

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
208	
209	
20FT1	
20FT2	
21	
210	
22	
23	
24	
25	
26	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
42A	

Chicago Public Schools

School Bowen Campus

Unit 46051

Building ID 1240

Address 2710 E. 89th St.

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
42B	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
75	

Chicago Public Schools

School Bowen Campus

Unit 46051

Building ID 1240

Address 2710 E. 89th St.

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
76	
77	
78	
79	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
9FT11	
A	
A(#2)	

Chicago Public Schools

School Bowen Campus

Unit 46051

Building ID 1240

Address 2710 E. 89th St.

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
B	
C	
D	
D(#2)	
E	
F	
G	
H	
HA-1000	
HA-1001	
HA-1002	
HA-1003	
N	
NEW	
O	
P	
X	
Y	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

TEM Environmental, Inc.

2025 AHERA REINSPECTION

Chicago Public Schools

TEM Environmental, Inc.

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	01		
MATERIAL DESCRIPTION:	12x12 Tan w/Brown Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex Rooms: 490, 312, 240, 224, 225, 230, 231, 242, 234, 235, 129, Dean's Office, Library		
MATERIAL QUANTITY:	6400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **12x12 Tan w/Brown Specks Floor Tile**

MATERIAL LOCATION: **Annex Rooms: 490, 312, 240, 224, 225, 230, 231, 242, 234, 235, 129, Dean's Office, Library**

MATERIAL QUANTITY: **6400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	01AFT		
MATERIAL DESCRIPTION:	12X12 Green w/Green Specks Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 229, 241, 261		
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **01AFT**

MATERIAL DESCRIPTION: **12X12 Green w/Green Specks Vinyl Floor Tile**

MATERIAL LOCATION: **Rooms 229, 241, 261**

MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	01AM		
MATERIAL DESCRIPTION:	12x12 Green w/Green Specks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 229, 241, 261		
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **01AM**

MATERIAL DESCRIPTION: **12x12 Green w/Green Specks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 229, 241, 261**

MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	01CM		
MATERIAL DESCRIPTION:	12x12 Dark Gray w/Specs Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	261 Lunchroom		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **01CM**

MATERIAL DESCRIPTION: **12x12 Dark Gray w/Specs Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **261 Lunchroom**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	02		
MATERIAL DESCRIPTION:	9x9 Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 202		
MATERIAL QUANTITY:	450	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **02**

MATERIAL DESCRIPTION: **9x9 Floor Tile**

MATERIAL LOCATION: **Room 202**

MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	02FT1		
MATERIAL DESCRIPTION:	9x9 Dark Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Rooms 210, 211, 212		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Tile Abated in Room 211		

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **02FT1**

MATERIAL DESCRIPTION: **9x9 Dark Brown Floor Tile**

MATERIAL LOCATION: **Main Building- Rooms 210, 211, 212**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	02FT2		
MATERIAL DESCRIPTION:	9x9 Light Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Rooms 311 & 312		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **02FT2**

MATERIAL DESCRIPTION: **9x9 Light Gray Floor Tile**

MATERIAL LOCATION: **Main Building- Rooms 311 & 312**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03FT14		
MATERIAL DESCRIPTION:	12"x12" Cream Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Teachers' Lounge, 1st, 2nd, 3rd, & 4th Floor Hallways, 1st Floor Women's Bathroom, 3rd Floor Men's Bathroom, Rooms 490, 314, 204, 285A; 2nd Floor Handicap Toilet**

MATERIAL QUANTITY: **51455** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS: **2025- 3000 SF of Material Abated from 1st Floor Corridor in 2022; 3/4 of Room 314 (545 SF) 2024Abated**

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **03FT14**

MATERIAL DESCRIPTION: **12"x12" Cream Floor Tile**

MATERIAL LOCATION: **Teachers' Lounge, 1st, 2nd, 3rd, & 4th Floor Hallways, 1st Floor Women's Bathroom, 3rd Floor Men's Bathroom, Rooms 490, 314, 204, 285A; 2nd Floor Handicap Toilet**

MATERIAL QUANTITY: **51455** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03FT3		
MATERIAL DESCRIPTION:	12x12 Green Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Principal's Office, Conference Room Corridor		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	DAMAGE UNITS: SF		
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **03FT3**

MATERIAL DESCRIPTION: **12x12 Green Floor Tile**

MATERIAL LOCATION: **Main Building- Principal's Office, Conference Room Corridor**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03FT4		
MATERIAL DESCRIPTION:	9x9 White w/Green Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Room 202		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **03FT4**

MATERIAL DESCRIPTION: **9x9 White w/Green Specks Floor Tile**

MATERIAL LOCATION: **Main Building- Room 202**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03FT6		
MATERIAL DESCRIPTION:	12x12 Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- 1st Floor Hallway Trim, Room 410		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **03FT6**

MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**

MATERIAL LOCATION: **Main Building- 1st Floor Hallway Trim, Room 410**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03FT7		
MATERIAL DESCRIPTION:	12x12 Light Brown Speckled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Building- Rooms 300, 310, 314, 315, 316, 306, 1st and 3rd Floor Faculty Bathrooms, 208A, 207, Main Office, and 2nd Floor Corridor**

MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Tile Removed from RoomS 306 & 310**

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **03FT7**

MATERIAL DESCRIPTION: **12x12 Light Brown Speckled Floor Tile**

MATERIAL LOCATION: **Main Building- Rooms 300, 310, 314, 315, 316, 306, 1st and 3rd Floor Faculty Bathrooms, 208A, 207, Main Office, and 2nd Floor Corridor**

MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03FT8		
MATERIAL DESCRIPTION:	12x12 Beige Speckled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Main Building- Room 308		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **03FT8**

MATERIAL DESCRIPTION: **12x12 Beige Speckled Floor Tile**

MATERIAL LOCATION: **Main Building- Room 308**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	04		
MATERIAL DESCRIPTION:	Tectum Ceiling		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Gymnasium		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **Tectum Ceiling**

MATERIAL LOCATION: **Main Building- Gymnasium**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **9x9 Floor Tile ABATED 1991**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex 1st and 2nd Floor**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **9x9 Floor Tile ABATED 1991**

MATERIAL LOCATION: **Annex 1st and 2nd Floor**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06		
MATERIAL DESCRIPTION:	Linoleum Floor		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Stairways		
MATERIAL QUANTITY:	950	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **Linoleum Floor**

MATERIAL LOCATION: **Main Building- Stairways**

MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06FT11		
MATERIAL DESCRIPTION:	12"x12" Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Rooms 222, 223, 226, 227, 232, 233, 236, 237, 124, 125, 137, 138, 139, 136		
MATERIAL QUANTITY:	14000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **06FT11**

MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile**

MATERIAL LOCATION: **Annex- Rooms 222, 223, 226, 227, 232, 233, 236, 237, 124, 125, 137, 138, 139, 136**

MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06FT12		
MATERIAL DESCRIPTION:	12"x12" Light Blue Floor Tile Mastic (under carpet)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- 1st Floor Offices, 2nd Floor Faculty Lounge, 140-A-J		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	DAMAGE UNITS: SF		
COMMENTS:	Under Carpet		

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **06FT12**

MATERIAL DESCRIPTION: **12"x12" Light Blue Floor Tile Mastic (under carpet)**

MATERIAL LOCATION: **Annex- 1st Floor Offices, 2nd Floor Faculty Lounge, 140-A-J**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06FT13		
MATERIAL DESCRIPTION:	12"x12" White w/Tan Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Rooms 126 and 127		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **06FT13**

MATERIAL DESCRIPTION: **12"x12" White w/Tan Specks Floor Tile**

MATERIAL LOCATION: **Annex- Rooms 126 and 127**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06FT14		
MATERIAL DESCRIPTION:	12"x12" Cream Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- 1st and 2nd Floor Hallways		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **06FT14**

MATERIAL DESCRIPTION: **12"x12" Cream Floor Tile**

MATERIAL LOCATION: **Annex- 1st and 2nd Floor Hallways**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06FT5		
MATERIAL DESCRIPTION:	12x12 Dark Brown and Cream Speckled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex Rooms: 241, 240, 229, 242, 129, 229A		
MATERIAL QUANTITY:	7200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Material abated from Room 241		

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **06FT5**

MATERIAL DESCRIPTION: **12x12 Dark Brown and Cream Speckled Floor Tile**

MATERIAL LOCATION: **Annex Rooms: 241, 240, 229, 242, 129, 229A**

MATERIAL QUANTITY: **7200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06FT7		
MATERIAL DESCRIPTION:	12x12 Light Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex Rooms: 224, 225, 230, 231, 239, 122, 123, 134, 135, 136, 238		
MATERIAL QUANTITY:	17100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	New Floor in Room 231		

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **06FT7**

MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile**

MATERIAL LOCATION: **Annex Rooms: 224, 225, 230, 231, 239, 122, 123, 134, 135, 136, 238**

MATERIAL QUANTITY: **17100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07FT9**

MATERIAL DESCRIPTION: **12x12 Red Floor Tile- NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **07FT9**

MATERIAL DESCRIPTION: **12x12 Red Floor Tile- NOT OBSERVED**

MATERIAL LOCATION: **Main Building- Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09		
MATERIAL DESCRIPTION:	12x12 Tan w/Brown Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex Rooms: 241, 240, 224, 225, 229, 230, 231, 242, 234, 235, 129, Dean's Office, and Library**

MATERIAL QUANTITY: **6400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS: **Material under carpet in Room 240. Mastic abated from Library, Rooms 240 & 241**

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **12x12 Tan w/Brown Specks Floor Tile Mastic**

MATERIAL LOCATION: **Annex Rooms: 241, 240, 224, 225, 229, 230, 231, 242, 234, 235, 129, Dean's Office, and Library**

MATERIAL QUANTITY: **6400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09FT12		
MATERIAL DESCRIPTION:	12"x12" Light Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- 1st Floor Offices, 2nd Floor Faculty Lounge, Room 140-AJ		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Tile Not Observed. Might be under Carpet		

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **09FT12**

MATERIAL DESCRIPTION: **12"x12" Light Blue Floor Tile**

MATERIAL LOCATION: **Annex- 1st Floor Offices, 2nd Floor Faculty Lounge, Room 140-AJ**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09FT13		
MATERIAL DESCRIPTION:	12"x12" White w/Tan Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Rooms 126 & 127		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **09FT13**

MATERIAL DESCRIPTION: **12"x12" White w/Tan Specks Floor Tile Mastic**

MATERIAL LOCATION: **Annex- Rooms 126 & 127**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09FT14		
MATERIAL DESCRIPTION:	12"x12" Cream Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- 1st and 2nd Floor Hallways		
MATERIAL QUANTITY:	1850	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **09FT14**

MATERIAL DESCRIPTION: **12"x12" Cream Floor Tile Mastic**

MATERIAL LOCATION: **Annex- 1st and 2nd Floor Hallways**

MATERIAL QUANTITY: **1850** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09FT5		
MATERIAL DESCRIPTION:	12"x12" Dark Brown and Cream Speckled Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Rooms 240, 242, 129, 229A		
MATERIAL QUANTITY:	7200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **09FT5**

MATERIAL DESCRIPTION: **12"x12" Dark Brown and Cream Speckled Floor Tile Mastic**

MATERIAL LOCATION: **Annex- Rooms 240, 242, 129, 229A**

MATERIAL QUANTITY: **7200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09FT7		
MATERIAL DESCRIPTION:	12"x12" Light Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex Rooms: 224, 225, 230, 231, 239, 122, 123, 134, 135, 136, 238		
MATERIAL QUANTITY:	17100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **09FT7**

MATERIAL DESCRIPTION: **12"x12" Light Brown Floor Tile Mastic**

MATERIAL LOCATION: **Annex Rooms: 224, 225, 230, 231, 239, 122, 123, 134, 135, 136, 238**

MATERIAL QUANTITY: **17100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	100		
MATERIAL DESCRIPTION:	2'x4' White w/Pin-Holes Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout 1939 Building, Elevator Lobbies		
MATERIAL QUANTITY:	4300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **100**

MATERIAL DESCRIPTION: **2'x4' White w/ Pin-Holes Ceiling Tile**

MATERIAL LOCATION: **Throughout 1939 Building, Elevator Lobbies**

MATERIAL QUANTITY: **4300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	101		
MATERIAL DESCRIPTION:	Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1939 Building- Stairwell and Baseboard		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **101**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **1939 Building- Stairwell and Baseboard**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	102		
MATERIAL DESCRIPTION:	Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout 1939 Building		
MATERIAL QUANTITY:	17000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damaged Plaster in Room 200D Storage		

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **102**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout 1939 Building**

MATERIAL QUANTITY: **17000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Patch or repair plaster as needed

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	103		
MATERIAL DESCRIPTION:	Air Cell		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1939 Building- Boys' Bathroom in Locker Room, Basement Vault, Boiler Room		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	DAMAGE UNITS: LF		
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **103**

MATERIAL DESCRIPTION: **Air Cell**

MATERIAL LOCATION: **1939 Building- Boys' Bathroom in Locker Room, Basement Vault, Boiler Room**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	104		
MATERIAL DESCRIPTION:	2'x4' Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Annex		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **104**

MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**

MATERIAL LOCATION: **Throughout Annex**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	105		
MATERIAL DESCRIPTION:	12"x12" Light Purple Mixed Speckled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Lobby to Gym		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **105**

MATERIAL DESCRIPTION: **12"x12" Light Purple Mixed Speckled Floor Tile**

MATERIAL LOCATION: **Annex- Lobby to Gym**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	106		
MATERIAL DESCRIPTION:	12"x12" Light Purple Mixed Speckled Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Lobby to Gym		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **106**

MATERIAL DESCRIPTION: **12"x12" Light Purple Mixed Speckled Floor Tile Mastic**

MATERIAL LOCATION: **Annex- Lobby to Gym**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	107		
MATERIAL DESCRIPTION:	12"x12" Light Vanilla Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Lunchroom		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **107**

MATERIAL DESCRIPTION: **12"x12" Light Vanilla Floor Tile Mastic**

MATERIAL LOCATION: **Main Building- Lunchroom**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	108		
MATERIAL DESCRIPTION:	Spray-On NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st and 2nd Floor Entrance and Breezeway		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **108**

MATERIAL DESCRIPTION: **Spray-On NOT OBSERVED**

MATERIAL LOCATION: **1st and 2nd Floor Entrance and Breezeway**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	109		
MATERIAL DESCRIPTION:	Lab Tables		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- 229, 302, 306, 308 & 310		
MATERIAL QUANTITY:	1100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **109**

MATERIAL DESCRIPTION: **Lab Tables**

MATERIAL LOCATION: **Annex- 229, 302, 306, 308 & 310**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	110		
MATERIAL DESCRIPTION:	12"x12" Green/Grey Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 201, 205 & 210		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **110**

MATERIAL DESCRIPTION: **12"x12" Green/Grey Floor Tile**

MATERIAL LOCATION: **Rooms 201, 205 & 210**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	110A		
MATERIAL DESCRIPTION:	Mastic associated w/12"x12" Green/Grey Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 201, 205 & 210		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **110A**

MATERIAL DESCRIPTION: **Mastic associated w/12"x12" Green/Grey Floor Tile**

MATERIAL LOCATION: **Rooms 201, 205 & 210**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	111		
MATERIAL DESCRIPTION:	12"x12" Pink Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Room 112		
MATERIAL QUANTITY:	650	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **111**

MATERIAL DESCRIPTION: **12"x12" Pink Floor Tile**

MATERIAL LOCATION: **Annex- Room 112**

MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	111A		
MATERIAL DESCRIPTION:	Mastic associated with 12"x12" Pink Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 238		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **111A**

MATERIAL DESCRIPTION: **Mastic associated with 12"x12" Pink Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **Room 238**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	112		
MATERIAL DESCRIPTION:	12"x12" Grey Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Conference Room		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **112**

MATERIAL DESCRIPTION: **12"x12" Grey Floor Tile**

MATERIAL LOCATION: **Conference Room**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	112A		
MATERIAL DESCRIPTION:	Mastic associated with 12"x12" Grey Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Conference Room		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **112A**

MATERIAL DESCRIPTION: **Mastic associated with 12"x12" Grey Floor Tile**

MATERIAL LOCATION: **Conference Room**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	113		
MATERIAL DESCRIPTION:	12"x12" Grey/White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 410		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **113**

MATERIAL DESCRIPTION: **12"x12" Grey/White Floor Tile**

MATERIAL LOCATION: **Room 410**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	113A		
MATERIAL DESCRIPTION:	Mastic associated with 12"x12" Grey/White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 410		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **113A**

MATERIAL DESCRIPTION: **Mastic associated with 12"x12" Grey/White Floor Tile**

MATERIAL LOCATION: **Room 410**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 14

MATERIAL DESCRIPTION: Transite Panels ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Swimming Pool and Locker Rooms

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Transite Panels ABATED**

MATERIAL LOCATION: **Swimming Pool and Locker Rooms**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	12x12 Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building, 2nd, 3rd and 4th Floor Classrooms		
MATERIAL QUANTITY:	162000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **12x12 Floor Tile Mastic**

MATERIAL LOCATION: **Main Building, 2nd, 3rd and 4th Floor Classrooms**

MATERIAL QUANTITY: **162000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16FT-2		
MATERIAL DESCRIPTION:	12"x12" Cream Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd, 3rd & 4th Floor Hallways, 3rd Floor Men's Bathroom, 1st Floor Women's Bathroom, 2nd Floor Handicap Toilet, Rooms 490, 314, 204, 285A**

MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS: **2025- 3000 SF of Material Abated from 1st Floor Corridor in 2022; 3/4 of Room 314 (545 SF) Abated in 2024**

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **16FT-2**

MATERIAL DESCRIPTION: **12"x12" Cream Floor Tile Mastic**

MATERIAL LOCATION: **1st, 2nd, 3rd & 4th Floor Hallways, 3rd Floor Men's Bathroom, 1st Floor Women's Bathroom, 2nd Floor Handicap Toilet, Rooms 490, 314, 204, 285A**

MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16FT10		
MATERIAL DESCRIPTION:	12"x12" Orange and White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Engineer's Office		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **16FT10**

MATERIAL DESCRIPTION: **12"x12" Orange and White Floor Tile Mastic**

MATERIAL LOCATION: **Main Building- Engineer's Office**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16FT3		
MATERIAL DESCRIPTION:	12"x12" Green Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Principal's Office, Conference Room Corridor		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	DAMAGE UNITS: SF		
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **16FT3**

MATERIAL DESCRIPTION: **12"x12" Green Floor Tile Mastic**

MATERIAL LOCATION: **Main Building- Principal's Office, Conference Room Corridor**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16FT4		
MATERIAL DESCRIPTION:	9"x9" White w/Green Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Room 202		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **16FT4**

MATERIAL DESCRIPTION: **9"x9" White w/Green Specks Floor Tile Mastic**

MATERIAL LOCATION: **Main Building- Room 202**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16FT6		
MATERIAL DESCRIPTION:	12"x12" Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- 1st Floor Hallway Trim, Room 410		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **16FT6**

MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile Mastic**

MATERIAL LOCATION: **Main Building- 1st Floor Hallway Trim, Room 410**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16FT7		
MATERIAL DESCRIPTION:	12"x12" Light Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Building- Rooms: 300, 310, 314, 315, 316, 306, 3rd & 1st Floor Faculty Bathroom, 208A, 207, Main Office, and 2nd Floor Corridor (306 & 310 Removed)**

MATERIAL QUANTITY: **16000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **16FT7**

MATERIAL DESCRIPTION: **12"x12" Light Brown Floor Tile Mastic**

MATERIAL LOCATION: **Main Building- Rooms: 300, 310, 314, 315, 316, 306, 3rd & 1st Floor Faculty Bathroom, 208A, 207, Main Office, and 2nd Floor Corridor (306 & 310 Removed)**

MATERIAL QUANTITY: **16000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16FT8		
MATERIAL DESCRIPTION:	12"x12" Beige Speckled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Room 308		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **16FT8**

MATERIAL DESCRIPTION: **12"x12" Beige Speckled Floor Tile**

MATERIAL LOCATION: **Main Building- Room 308**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16FT9**

MATERIAL DESCRIPTION: **12"x12" Red Floor Tile Mastic NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Chrysotile** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- Lunchroom**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **16FT9**

MATERIAL DESCRIPTION: **12"x12" Red Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **Main Building- Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	9"x9" Maroon and Tan Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Swimming Pool and Corridors		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **9"x9" Maroon and Tan Floor Tile Mastic**

MATERIAL LOCATION: **Main Building- Swimming Pool and Corridors**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	Linoleum Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1908 Stairways		
MATERIAL QUANTITY:	950	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Linoleum Mastic**

MATERIAL LOCATION: **1908 Stairways**

MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1BFT		
MATERIAL DESCRIPTION:	12x12 Light Gray w/Gray and White Specks Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 229, 241, 229A, 261		
MATERIAL QUANTITY:	4300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **1BFT**

MATERIAL DESCRIPTION: **12x12 Light Gray w/Gray and White Specks Vinyl Floor Tile**

MATERIAL LOCATION: **Rooms 229, 241, 229A, 261**

MATERIAL QUANTITY: **4300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1BM		
MATERIAL DESCRIPTION:	12x12 Gray w/Gray and White Specks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 229, 241, 229A, 261		
MATERIAL QUANTITY:	4300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **1BM**

MATERIAL DESCRIPTION: **12x12 Gray w/Gray and White Specks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 229, 241, 229A, 261**

MATERIAL QUANTITY: **4300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1CFT		
MATERIAL DESCRIPTION:	12x12 Dark Gray w/Specs Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	261 Lunchroom		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **1CFT**

MATERIAL DESCRIPTION: **12x12 Dark Gray w/Specs Vinyl Floor Tile**

MATERIAL LOCATION: **261 Lunchroom**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1CM		
MATERIAL DESCRIPTION:	Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 144, 140C, 140H, 140E, 140D, 140, 140A, 140J, 200N, 211, 240		
MATERIAL QUANTITY:	9000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **1CM**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Rooms 144, 140C, 140H, 140E, 140D, 140, 140A, 140J, 200N, 211, 240**

MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1DS		
MATERIAL DESCRIPTION:	Drywall System		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 231, 2nd Floor Breezeway, 1st Floor Breezeway**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: 1DS

MATERIAL DESCRIPTION: **Drywall System**

MATERIAL LOCATION: Room 231, 2nd Floor Breezeway, 1st Floor Breezeway

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____ SF _____

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:

Steven B. Genes

Date: 05/26/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	9x9 Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- 2nd and 3rd Floor Classrooms		
MATERIAL QUANTITY:	0	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **9x9 Floor Tile Mastic**

MATERIAL LOCATION: **Main Building- 2nd and 3rd Floor Classrooms**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	200		
MATERIAL DESCRIPTION:	1x1 Pink Ceramic Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Girls' Bathrooms		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **200**

MATERIAL DESCRIPTION: **1x1 Pink Ceramic Flooring**

MATERIAL LOCATION: **Girls' Bathrooms**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	201		
MATERIAL DESCRIPTION:	Boiler Breeching ABATED		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Abated 2024**

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: 201

MATERIAL DESCRIPTION: **Boiler Breeching ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY: 0

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:

Steven B. Genes

Date: 05/26/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20FT1		
MATERIAL DESCRIPTION:	9"x9" Dark Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Rooms 200, 211-212		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **20FT1**

MATERIAL DESCRIPTION: **9"x9" Dark Brown Floor Tile Mastic**

MATERIAL LOCATION: **Main Building- Rooms 200, 211-212**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20FT2		
MATERIAL DESCRIPTION:	9"x9" Light Grey Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Rooms 311 & 312		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **20FT2**

MATERIAL DESCRIPTION: **9"x9" Light Grey Floor Tile Mastic**

MATERIAL LOCATION: **Main Building- Rooms 311 & 312**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **9x9 Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex Room and Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **9x9 Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Annex Room and Office**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	12x12 Beige w/White Streaks Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building - Room 211 and 211A		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **12x12 Beige w/White Streaks Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **Main Building - Room 211 and 211A**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	12x12 Beige w/White Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building - Room 211 and 211A		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **12x12 Beige w/White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Main Building - Room 211 and 211A**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	Turquoise Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building - Assembly Hall		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Turquoise Carpet Mastic**

MATERIAL LOCATION: **Main Building - Assembly Hall**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	12x12 Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building - Gym Corridor		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **12x12 Gray Floor Tile**

MATERIAL LOCATION: **Main Building - Gym Corridor**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	12x12 Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building - Gym Corridor		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **12x12 Gray Floor Tile Mastic**

MATERIAL LOCATION: **Main Building - Gym Corridor**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	Gray Carpet Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building - Room 400		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Gray Carpet Mastic NOT OBSERVED**

MATERIAL LOCATION: **Main Building - Room 400**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Gray Linoleum ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building - Room 306**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Gray Linoleum ABATED**

MATERIAL LOCATION: **Main Building - Room 306**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Gray Linoleum Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- Room 306**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Gray Linoleum Mastic ABATED**

MATERIAL LOCATION: **Main Building- Room 306**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Brown Baseboard ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- Room 306**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Brown Baseboard ABATED**

MATERIAL LOCATION: **Main Building- Room 306**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32

MATERIAL DESCRIPTION: Brown Baseboard Mastic ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Building- Room 306

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Brown Baseboard Mastic ABATED**

MATERIAL LOCATION: **Main Building- Room 306**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	Black Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Boys' Gym, 2nd floor		
MATERIAL QUANTITY:	75	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Black Baseboard**

MATERIAL LOCATION: **Main Building- Boys' Gym, 2nd floor**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	Black Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Boys' Gym, 2nd floor		
MATERIAL QUANTITY:	75	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Black Baseboard Mastic**

MATERIAL LOCATION: **Main Building- Boys' Gym, 2nd floor**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	9x9 Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Gym Vestibule, 2nd Floor		
MATERIAL QUANTITY:	15	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **9x9 Brown Floor Tile**

MATERIAL LOCATION: **Main Building- Gym Vestibule, 2nd Floor**

MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	9x9 Brown, 9x9 Tan, & 9x9 Dark Brown Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Gym Vestibule, 2nd Floor		
MATERIAL QUANTITY:	15	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **9x9 Brown, 9x9 Tan, & 9x9 Dark Brown Mastic**

MATERIAL LOCATION: **Main Building- Gym Vestibule, 2nd Floor**

MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	9x9 Tan Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Gym Vestibule, 2nd Floor		
MATERIAL QUANTITY:	15	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **9x9 Tan Floor Tile**

MATERIAL LOCATION: **Main Building- Gym Vestibule, 2nd Floor**

MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	9x9 Dark Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Gym Vestibule		
MATERIAL QUANTITY:	15	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **9x9 Dark Brown Floor Tile**

MATERIAL LOCATION: **Main Building- Gym Vestibule**

MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Brown Carpet Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex- Child Care Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Brown Carpet Mastic ABATED**

MATERIAL LOCATION: **Annex- Child Care Room**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Brown Carpet w/Dots ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex- Child Care Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Brown Carpet w/Dots ABATED**

MATERIAL LOCATION: **Annex- Child Care Room**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41		
MATERIAL DESCRIPTION:	Blue Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Library (228)		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Blue Carpet Mastic**

MATERIAL LOCATION: **Annex- Library (228)**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42		
MATERIAL DESCRIPTION:	Gray Carpet and associated Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Room 238, Main Office		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Gray Carpet and associated Adhesive**

MATERIAL LOCATION: **Annex- Room 238, Main Office**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42A		
MATERIAL DESCRIPTION:	2'X2' Smooth Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Staff Bathroom, Rooms 319, 241, 261, 229A, 229, 231, 140J, 140A, 140, 140D, 140E, 140H, 140G		
MATERIAL QUANTITY:	5500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA:	42A				
MATERIAL DESCRIPTION:	2'X2' Smooth Ceiling Tile				
MATERIAL LOCATION:	Staff Bathroom, Rooms 319, 241, 261, 229A, 229, 231, 140J, 140A, 140, 140D, 140E, 140H, 140G				
MATERIAL QUANTITY:	5500	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42B		
MATERIAL DESCRIPTION:	Rubber Floor Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	231 Annex		
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **42B**

MATERIAL DESCRIPTION: **Rubber Floor Mastic**

MATERIAL LOCATION: **231 Annex**

MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	Light Brown Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Corridor		
MATERIAL QUANTITY:	675	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Light Brown Baseboard**

MATERIAL LOCATION: **Annex- Corridor**

MATERIAL QUANTITY: **675** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	Light Brown Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Corridor		
MATERIAL QUANTITY:	675	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Light Brown Baseboard Mastic**

MATERIAL LOCATION: **Annex- Corridor**

MATERIAL QUANTITY: **675** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	12x12 Gray w/Green Spots Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Rooms 126 and 127		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **12x12 Gray w/Green Spots Floor Tile**

MATERIAL LOCATION: **Annex- Rooms 126 and 127**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	12x12 Gray w/Green Spots Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Rooms 126 and 127		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **12x12 Gray w/Green Spots Floor Tile Mastic**

MATERIAL LOCATION: **Annex- Rooms 126 and 127**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47		
MATERIAL DESCRIPTION:	Gray Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Rooms: 222, 223, 226, 227, 232, 233, 235, 234, 236, 237, 124, 125, 137, 138, 139		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Gray Baseboard**

MATERIAL LOCATION: **Annex- Rooms: 222, 223, 226, 227, 232, 233, 235, 234, 236, 237, 124, 125, 137, 138, 139**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	Gray Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Rooms: 222, 223, 226, 227, 232, 233, 235, 234, 236, 237, 124, 125, 137, 138, 139		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Gray Baseboard Mastic**

MATERIAL LOCATION: **Annex- Rooms: 222, 223, 226, 227, 232, 233, 235, 234, 236, 237, 124, 125, 137, 138, 139**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	Black Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Rooms 240, 241, 229, 238		
MATERIAL QUANTITY:	450	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Black Baseboard**

MATERIAL LOCATION: **Annex- Rooms 240, 241, 229, 238**

MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	Black Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Rooms 240, 241, 229, 238		
MATERIAL QUANTITY:	450	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Black Baseboard Mastic**

MATERIAL LOCATION: **Annex- Rooms 240, 241, 229, 238**

MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	Blue Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Childcare Area		
MATERIAL QUANTITY:	125	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Blue Baseboard**

MATERIAL LOCATION: **Annex- Childcare Area**

MATERIAL QUANTITY: **125** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	Blue Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Childcare Area		
MATERIAL QUANTITY:	125	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **Blue Baseboard Mastic**

MATERIAL LOCATION: **Annex- Childcare Area**

MATERIAL QUANTITY: **125** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	Turquoise Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Rooms 228, Women's 2nd Floor Faculty Lounge, West Office Corridor and Offices		
MATERIAL QUANTITY:	450	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **Turquoise Baseboard**

MATERIAL LOCATION: **Annex- Rooms 228, Women's 2nd Floor Faculty Lounge, West Office Corridor and Offices**

MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	Turquoise Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Rooms 228, Womens 2nd Floor Faculty Lounge, West Office Corridor and Offices		
MATERIAL QUANTITY:	450	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Turquoise Baseboard Mastic**

MATERIAL LOCATION: **Annex- Rooms 228, Womens 2nd Floor Faculty Lounge, West Office Corridor and Offices**

MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55		
MATERIAL DESCRIPTION:	Tan Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Childcare Room, Room 133		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Tan Linoleum**

MATERIAL LOCATION: **Annex- Childcare Room, Room 133**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	56		
MATERIAL DESCRIPTION:	Tan Linoleum, Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Childcare Room, Room 133		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **Tan Linoleum, Mastic**

MATERIAL LOCATION: **Annex- Childcare Room, Room 133**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	57		
MATERIAL DESCRIPTION:	Brown Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Childcare Room and YMCA Office		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **Brown Baseboard**

MATERIAL LOCATION: **Annex- Childcare Room and YMCA Office**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	Brown Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Childcare Room and YMCA Office		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **Brown Baseboard Mastic**

MATERIAL LOCATION: **Annex- Childcare Room and YMCA Office**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	59		
MATERIAL DESCRIPTION:	Blue Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Childcare Room		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **Blue Linoleum**

MATERIAL LOCATION: **Annex- Childcare Room**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	60		
MATERIAL DESCRIPTION:	Blue Linoleum Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Childcare Room		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **Blue Linoleum Mastic**

MATERIAL LOCATION: **Annex- Childcare Room**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	61		
MATERIAL DESCRIPTION:	Tan Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Rooms 224, 225, 230, 231, 239, 122, 123, 126, 135, 136, 134, Infant Room		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **Tan Baseboard**

MATERIAL LOCATION: **Annex- Rooms 224, 225, 230, 231, 239, 122, 123, 126, 135, 136, 134, Infant Room**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	62		
MATERIAL DESCRIPTION:	Tan Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Rooms 224, 225, 230, 231, 239, 122, 123, 126, 135, 136, 134, Infant Room		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Tan Baseboard Mastic**

MATERIAL LOCATION: **Annex- Rooms 224, 225, 230, 231, 239, 122, 123, 126, 135, 136, 134, Infant Room**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	63		
MATERIAL DESCRIPTION:	2x4 Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Main & Annex Building		
MATERIAL QUANTITY:	304571	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **2x4 Ceiling Tile**

MATERIAL LOCATION: **Throughout Main & Annex Building**

MATERIAL QUANTITY: **304571** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	64		
MATERIAL DESCRIPTION:	Blue Carpet		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Social Room, Library 211		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **Blue Carpet**

MATERIAL LOCATION: **Main Building- Social Room, Library 211**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	65		
MATERIAL DESCRIPTION:	Blue Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Social Room		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **Blue Carpet Mastic**

MATERIAL LOCATION: **Main Building- Social Room**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	66		
MATERIAL DESCRIPTION:	Beige Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Rooms 211, 307, 308, 310, 310A		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **Beige Linoleum**

MATERIAL LOCATION: **Main Building- Rooms 211, 307, 308, 310, 310A**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	67		
MATERIAL DESCRIPTION:	Vibration Collar		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex Mechanical Room		
MATERIAL QUANTITY:	25	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **Vibration Collar**

MATERIAL LOCATION: **Annex Mechanical Room**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	75		
MATERIAL DESCRIPTION:	12x12 Light Vanilla Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **12x12 Light Vanilla Vinyl Floor Tile**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	76		
MATERIAL DESCRIPTION:	TSI on HVAC Ducts		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Annex 2nd Floor Fan Room		
MATERIAL QUANTITY:	60	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **TSI on HVAC Ducts**

MATERIAL LOCATION: **Annex 2nd Floor Fan Room**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	77		
MATERIAL DESCRIPTION:	Hard Packed Fittings on Fiberglass Insulated Pipes		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Auto Shop		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **Hard Packed Fittings on Fiberglass Insulated Pipes**

MATERIAL LOCATION: **Auto Shop**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	78		
MATERIAL DESCRIPTION:	Linoleum and Associated Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	206, 207, 209, 306, 310, 205A, 211		
MATERIAL QUANTITY:	3600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	2025- Not Observed in Room 211		

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **Linoleum and Associated Adhesive**

MATERIAL LOCATION: **206, 207, 209, 306, 310, 205A, 211**

MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	79		
MATERIAL DESCRIPTION:	12x12 Beige VFT/12x12 Brown VFT (Checkered) w/Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	238 and 239		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **12x12 Beige VFT/12x12 Brown VFT (Checkered) w/Mastic**

MATERIAL LOCATION: **238 and 239**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	80		
MATERIAL DESCRIPTION:	Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Main Building		
MATERIAL QUANTITY:	304571	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout Main Building**

MATERIAL QUANTITY: **304571** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	81		
MATERIAL DESCRIPTION:	Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Annex Building		
MATERIAL QUANTITY:	25000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout Annex Building**

MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	82		
MATERIAL DESCRIPTION:	12x12 Orange and White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Engineer's Office		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **12x12 Orange and White Floor Tile**

MATERIAL LOCATION: **Main Building- Engineer's Office**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	83		
MATERIAL DESCRIPTION:	12x12 Orange and White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Engineer's Office		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **12x12 Orange and White Floor Tile Mastic**

MATERIAL LOCATION: **Main Building- Engineer's Office**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	84		
MATERIAL DESCRIPTION:	12x12 Orange Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Cafeteria Office		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **12x12 Orange Floor Tile**

MATERIAL LOCATION: **Main Building- Cafeteria Office**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	85		
MATERIAL DESCRIPTION:	12x12 Orange Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Cafeteria Office		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **85**

MATERIAL DESCRIPTION: **12x12 Orange Floor Tile Mastic**

MATERIAL LOCATION: **Main Building- Cafeteria Office**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	86		
MATERIAL DESCRIPTION:	12x12 Light Vanilla Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Lunchroom		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **86**

MATERIAL DESCRIPTION: **12x12 Light Vanilla Floor Tile Mastic**

MATERIAL LOCATION: **Main Building- Lunchroom**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	87		
MATERIAL DESCRIPTION:	Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- 211 Conference Room		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **87**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Main Building- 211 Conference Room**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	88		
MATERIAL DESCRIPTION:	Linoleum NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 211		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **Linoleum NOT OBSERVED**

MATERIAL LOCATION: **Room 211**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	89		
MATERIAL DESCRIPTION:	Lab Counter Tops		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Rooms 310, 308, 307, 306, 206 & 211		
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **89**

MATERIAL DESCRIPTION: **Lab Counter Tops**

MATERIAL LOCATION: **Main Building- Rooms 310, 308, 307, 306, 206 & 211**

MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	90		
MATERIAL DESCRIPTION:	9x9 Gray w/White Streaks Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Rooms 201, 212, 311		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **9x9 Gray w/White Streaks Vinyl Floor Tile**

MATERIAL LOCATION: **Main Building- Rooms 201, 212, 311**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	91		
MATERIAL DESCRIPTION:	9x9 Gray w/White Streaks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Rooms 201, 212, 311		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **91**

MATERIAL DESCRIPTION: **9x9 Gray w/White Streaks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Main Building- Rooms 201, 212, 311**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	92		
MATERIAL DESCRIPTION:	12"x12" Light Cream Mixed Speckled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Rooms 205, 105A, B, C, D, E, and F		
MATERIAL QUANTITY:	950	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **12"x12" Light Cream Mixed Speckled Floor Tile**

MATERIAL LOCATION: **Main Building- Rooms 205, 105A, B, C, D, E, and F**

MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	93		
MATERIAL DESCRIPTION:	12"x12" Light Cream Mixed Speckled Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Rooms 205, 105A, B, C, D, E, and F		
MATERIAL QUANTITY:	950	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **93**

MATERIAL DESCRIPTION: **12"x12" Light Cream Mixed Speckled Floor Tile Mastic**

MATERIAL LOCATION: **Main Building- Rooms 205, 105A, B, C, D, E, and F**

MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	94		
MATERIAL DESCRIPTION:	12"x12" Vanilla Mixed Speckled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Rooms 300 and 207, Elevator Vestibule		
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **94**

MATERIAL DESCRIPTION: **12"x12" Vanilla Mixed Speckled Floor Tile**

MATERIAL LOCATION: **Main Building- Rooms 300 and 207, Elevator Vestibule**

MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	95		
MATERIAL DESCRIPTION:	12"x12" Vanilla Mixed Speckled Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Rooms 300 and 207, Elevator Vestibule		
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **95**

MATERIAL DESCRIPTION: **12"x12" Vanilla Mixed Speckled Floor Tile Mastic**

MATERIAL LOCATION: **Main Building- Rooms 300 and 207, Elevator Vestibule**

MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	96		
MATERIAL DESCRIPTION:	12"x12" White w/Blue Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Room 209		
MATERIAL QUANTITY:	550	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **96**

MATERIAL DESCRIPTION: **12"x12" White w/Blue Specks Floor Tile**

MATERIAL LOCATION: **Main Building- Room 209**

MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	97		
MATERIAL DESCRIPTION:	12"x12" White w/Blue Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Room 209		
MATERIAL QUANTITY:	550	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **97**

MATERIAL DESCRIPTION: **12"x12" White w/Blue Specks Floor Tile Mastic**

MATERIAL LOCATION: **Main Building- Room 209**

MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	98		
MATERIAL DESCRIPTION:	12"x12" Light Tan w/Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1939 Building- 1st Floor Corridor		
MATERIAL QUANTITY:	2800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **98**

MATERIAL DESCRIPTION: **12"x12" Light Tan w/Streaks Floor Tile**

MATERIAL LOCATION: **1939 Building- 1st Floor Corridor**

MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	99		
MATERIAL DESCRIPTION:	12"x12" Light Tan w/Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1939 Building- 1st Floor Corridor		
MATERIAL QUANTITY:	2800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **99**

MATERIAL DESCRIPTION: **12"x12" Light Tan w/Streaks Mastic**

MATERIAL LOCATION: **1939 Building- 1st Floor Corridor**

MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	9FT11		
MATERIAL DESCRIPTION:	12"x12" Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex- Rooms 222, 223, 226, 227, 232, 233, 236, 237, 124, 125, 137, 138, 139, 136		
MATERIAL QUANTITY:	13500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **9FT11**

MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile Mastic**

MATERIAL LOCATION: **Annex- Rooms 222, 223, 226, 227, 232, 233, 236, 237, 124, 125, 137, 138, 139, 136**

MATERIAL QUANTITY: **13500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Tank Insulation ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex Boiler Room**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Tank Insulation ABATED**

MATERIAL LOCATION: **Annex Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: A(#2)

MATERIAL DESCRIPTION: Aircell Pipe Insulation ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Building- Mechanical Area, Classrooms, Lunchroom

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **A(#2)**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation ABATED**

MATERIAL LOCATION: **Main Building- Mechanical Area, Classrooms, Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Boiler Breaching ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Boiler Breaching ABATED**

MATERIAL LOCATION: **Annex Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: C

MATERIAL DESCRIPTION: Cardboard Insulation ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Building- Classrooms and Mechanical Areas

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Cardboard Insulation ABATED**

MATERIAL LOCATION: **Main Building- Classrooms and Mechanical Areas**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	Pipe Fitting Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	1 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Throughout Annex**

MATERIAL QUANTITY: **130** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Pipe Fitting Insulation**

MATERIAL LOCATION: **Throughout Annex**

MATERIAL QUANTITY: **130** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **1** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D(#2)		
MATERIAL DESCRIPTION:	Cementitious Joints on Cardboard ABATED		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Building- Classrooms, Mechanical Area

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **D(#2)**

MATERIAL DESCRIPTION: **Cementitious Joints on Cardboard ABATED**

MATERIAL LOCATION: **Main Building- Classrooms, Mechanical Area**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: F

MATERIAL DESCRIPTION: Joints and Elbows on Fiberglass Runs ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Building- Classrooms, Mechanical Areas, 1st, 2nd, and 3rd Floor

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Joints and Elbows on Fiberglass Runs ABATED**

MATERIAL LOCATION: **Main Building- Classrooms, Mechanical Areas, 1st, 2nd, and 3rd Floor**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Pre-Form Pipe Insulation ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Pre-Form Pipe Insulation ABATED**

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: H

MATERIAL DESCRIPTION: Elbows on Pre-Formed Pipe Insulation ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Elbows on Pre-Formed Pipe Insulation ABATED**

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	HA-1000		
MATERIAL DESCRIPTION:	1'x1' White Ceiling Tile w/Random and Regular Holes		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen Storage		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **HA-1000**

MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile w/Random and Regular Holes**

MATERIAL LOCATION: **Kitchen Storage**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	HA-1001		
MATERIAL DESCRIPTION:	1'x1' White Ceiling Tile w/Holes Glue		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen Storage		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **HA-1001**

MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile w/Holes Glue**

MATERIAL LOCATION: **Kitchen Storage**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	HA-1002		
MATERIAL DESCRIPTION:	Muddled Pipe Fittings		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1908 Building- Boiler Room		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **HA-1002**

MATERIAL DESCRIPTION: **Muddled Pipe Fittings**

MATERIAL LOCATION: **1908 Building- Boiler Room**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	HA-1003		
MATERIAL DESCRIPTION:	Muddled Pipe Fittings		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1953 Building- AHU by GYM, GYM		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **HA-1003**

MATERIAL DESCRIPTION: **Muddled Pipe Fittings**

MATERIAL LOCATION: **1953 Building- AHU by GYM, GYM**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: N

MATERIAL DESCRIPTION: Cardboard Pipe Insulation ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Building- Mechanical Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation ABATED**

MATERIAL LOCATION: **Main Building- Mechanical Room**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	NEW		
MATERIAL DESCRIPTION:	Newly Installed Suspect ACM		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Installed After Implementation of Management Plan**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **NEW**

MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**

MATERIAL LOCATION: **Installed After Implementation of Management Plan**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **O**

MATERIAL DESCRIPTION: **Cementitious Joints ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- Mechanical Rooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/14/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **O**

MATERIAL DESCRIPTION: **Cementitious Joints ABATED**

MATERIAL LOCATION: **Main Building- Mechanical Rooms**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: P

MATERIAL DESCRIPTION: Cementitious Fittings on Fiberglass ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Building- Unexcavated Area and Boiler Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **Cementitious Fittings on Fiberglass ABATED**

MATERIAL LOCATION: **Main Building- Unexcavated Area and Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:

MATERIAL DESCRIPTION: Paper Wrap Pipe Insulation ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Building- Throughout 1st Floor Corridor, Above Plaster Ceiling

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA:

MATERIAL DESCRIPTION: **Paper Wrap Pipe Insulation ABATED**

MATERIAL LOCATION: **Main Building- Throughout 1st Floor Corridor, Above Plaster Ceiling**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Y

MATERIAL DESCRIPTION: Joints on Cardboard Pipe Insulation ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Building- Throughout 1st Floor Corridor, Above Plaster Ceiling

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUILDING ID:	1240
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Bowen Campus	REVIEW DATE:	5/26/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

HOMOGENEOUS AREA: **Y**

MATERIAL DESCRIPTION: **Joints on Cardboard Pipe Insulation ABATED**

MATERIAL LOCATION: **Main Building- Throughout 1st Floor Corridor, Above Plaster Ceiling**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	203		
MATERIAL DESCRIPTION:	4'x4' Smooth Ceiling Tile		
MATERIAL LOCATION:	Room 211		
MATERIAL QUANTITY:	2600	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	Yes
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**

SCHOOL NAME: **Bowen Campus** REVIEW DATE: **5/26/2025**

ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **203**

MATERIAL DESCRIPTION: **4'x4' Smooth Ceiling Tile**

MATERIAL LOCATION: **Room 211**

MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	206				
MATERIAL DESCRIPTION:	Multicolor Mosaic Ceramic Tile Grout				
MATERIAL LOCATION:	Hallway near Main Gym				
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	SURFACE	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**

SCHOOL NAME: **Bowen Campus** REVIEW DATE: **5/26/2025**

ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **206**

MATERIAL DESCRIPTION: **Multicolor Mosaic Ceramic Tile Grout**

MATERIAL LOCATION: **Hallway near Main Gym**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	E			
MATERIAL DESCRIPTION:	Condensate Tank Insulation			
MATERIAL LOCATION:	Boiler Room			
MATERIAL QUANTITY:	60	MATERIAL UNITS:	LF	
MATERIAL CATEGORY:	TSI	FRIABLE:	Yes	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	MODERATE			CONDITION:
AHERA DAMAGE CATEGORY:	7 Any remaining friable ACBM or friable suspect ACBM			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:	0	DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	LF	

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**

SCHOOL NAME: **Bowen Campus** REVIEW DATE: **5/26/2025**

ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Condensate Tank Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**


DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	202		
MATERIAL DESCRIPTION:	Spray-on Fireproofing		
MATERIAL LOCATION:	Throughout Annex		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	Yes
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**

SCHOOL NAME: **Bowen Campus** REVIEW DATE: **5/26/2025**

ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **202**

MATERIAL DESCRIPTION: **Spray-on Fireproofing**

MATERIAL LOCATION: **Throughout Annex**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	204M				
MATERIAL DESCRIPTION:	Mastic associated w/24"x24" White, Light Grey & Grey Floor Tile				
MATERIAL LOCATION:	Room 306				
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**

SCHOOL NAME: **Bowen Campus** REVIEW DATE: **5/26/2025**

ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **204M**

MATERIAL DESCRIPTION: **Mastic associated w/24"x24" White, Light Grey & Grey Floor Tile**

MATERIAL LOCATION: **Room 306**

MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	209		
MATERIAL DESCRIPTION:	Stair Tread Adhesive		
MATERIAL LOCATION:	Original Building- All Staircases Throughout		
MATERIAL QUANTITY:	360	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	LF

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**

SCHOOL NAME: **Bowen Campus** REVIEW DATE: **5/26/2025**

ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **209**

MATERIAL DESCRIPTION: **Stair Tread Adhesive**

MATERIAL LOCATION: **Original Building- All Staircases Throughout**

MATERIAL QUANTITY: **360** MATERIAL UNITS: **LF**


DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	204		
MATERIAL DESCRIPTION:	24"x24" White, Light Grey & Grey Floor Tile		
MATERIAL LOCATION:	Room 306		
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**

SCHOOL NAME: **Bowen Campus** REVIEW DATE: **5/26/2025**

ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **204**

MATERIAL DESCRIPTION: **24"x24" White, Light Grey & Grey Floor Tile**

MATERIAL LOCATION: **Room 306**

MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	205		
MATERIAL DESCRIPTION:	Fire Doors		
MATERIAL LOCATION:	Throughout Original Building		
MATERIAL QUANTITY:		MATERIAL UNITS:	EA
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	EA
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**

SCHOOL NAME: **Bowen Campus** REVIEW DATE: **5/26/2025**

ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **205**

MATERIAL DESCRIPTION: **Fire Doors**

MATERIAL LOCATION: **Throughout Original Building**


MATERIAL QUANTITY: MATERIAL UNITS: **EA**

DAMAGE QUANTITY: DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/26/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	207				
MATERIAL DESCRIPTION:	Brown Cermamic Tile Grout				
MATERIAL LOCATION:	All Girls' & Boys' Washrooms				
MATERIAL QUANTITY:		MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE UNITS:	SF		

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**

SCHOOL NAME: **Bowen Campus** REVIEW DATE: **5/26/2025**

ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **207**

MATERIAL DESCRIPTION: **Brown Cermamic Tile Grout**

MATERIAL LOCATION: **All Girls' & Boys' Washrooms**


MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/26/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	208				
MATERIAL DESCRIPTION:	Sink Undercoating				
MATERIAL LOCATION:	Annex- Room 141C				
MATERIAL QUANTITY:	1	MATERIAL UNITS:	EA		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	EA		

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**

SCHOOL NAME: **Bowen Campus** REVIEW DATE: **5/26/2025**

ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **208**

MATERIAL DESCRIPTION: **Sink Undercoating**

MATERIAL LOCATION: **Annex- Room 141C**

MATERIAL QUANTITY: **1** MATERIAL UNITS: **EA**


DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/26/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46051	BUIDLING ID:	1240
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Bowen Campus	INSPECTION DATE:	5/14/2025		
ADDRESS:	2710 E. 89th St.	IDPH LICENSE NO:	100-21040		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	210		
MATERIAL DESCRIPTION:	Black Stage Curtains		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	2300	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**

SCHOOL NAME: **Bowen Campus** REVIEW DATE: **5/26/2025**

ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **210**

MATERIAL DESCRIPTION: **Black Stage Curtains**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/26/2025**

APPENDIX B

Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

JOSH R HERMAN
5121 N MONITOR AVE
CHICAGO, IL 60630

5/23/2025

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 21040

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



**ASBESTOS
PROFESSIONAL
LICENSE**

ENDORSEMENTS

TC EXPIRES

INSPECTOR

7/19/2025

ID NUMBER
100 - 21040

ISSUED
5/23/2025

EXPIRES
05/15/2026

JOSH R HERMAN
5121 N MONITOR AVE
CHICAGO, IL 60630
Environmental Health



Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.


Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB



TEM ENVIRONMENTAL, INC.
ENVIRONMENTAL SCIENTISTS | INDUSTRIAL HYGIENISTS



ENDORSEMENTS

TC EXPIRES

INSPECTOR 4/5/2024

MANAGEMENT PLANNER 4/5/2024

PROJECT MANAGER 4/4/2024

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois

Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

STEVEN B GENESER
210 BARNSIDE CIRCLE
GENEVA, IL 60134


6/6/2025

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 01784

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	5/7/2026
MANAGEMENT PLANNER	5/7/2026
PROJECT MANAGER	5/6/2026
AIR SAMPLING PROFESSIONAL	
<p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

**Reliable
Environmental
Solutions, Inc. R E S**

This is to certify that

Steve Geneser

*has on 5/7/25, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Refresher Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: May 7, 2025

COURSE LENGTH: 4 HOURS

Examination Date: May 7, 2025

Expiration Date: May 7, 2026

Certificate Number: MPR/0561

William S. Williams

Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois 217.787.9800 www.ReliableEnv.com

**Reliable
Environmental
Solutions, Inc. R E S**

This is to certify that

Steve Geneser

*has on 5/7/25, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Building Inspector Refresher Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher.*

Course Date: May 7, 2025

COURSE LENGTH: 4 HOURS

Examination Date: May 7, 2025

Expiration Date: May 7, 2026

Certificate Number: BIR/1252



Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois 217.787.9800 www.ReliableEnv.com



This is to certify that

Steve Geneser

*has on 5/8/24, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Refresher Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: May 8, 2024

Examination Date: May 8, 2024

Expiration Date: May 8, 2025

Certificate Number: MPR/0531

A handwritten signature in black ink that reads "William S. Williams".

Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois 217.787.9800 www.ReliableEnv.com

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed