

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-0028  
SCHOOL NAME: Lindblom High School  
ADDRESS OF SCHOOL: 6130 Wolcott  
CITY: Chicago, IL, 60636

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 9/15/2022

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 6/13/2025 ENROLLMENT 1263  
IDPH INSPECTOR LICENSE NUMBER: 100-21040  
IDPH LICENSED INSPECTOR NAME (Please Print): Josh Herman  
IDPH MP LICENSE NUMBER: 100-00349  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): James Tuinenga

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

*Richard J. Schleyer* 7/10/2025

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Lindblom High School**

6130 Wolcott  
Chicago, IL, 60636

Unit: 46511  
Building ID: 1450

IDPH ID Number: 14-016-2990-0028

**REPORT DATE:**  
Thursday, July 10, 2025

**Prepared for:**  
**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**  
**TEM Environmental, Inc.**

174 N. Brandon Drive  
Glendale Heights, IL, 60139  
Phone 630-790-0880  
Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

07/08/2025

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299      Unit: 46511      Region: 05      IDPH ID: 14-016-2990-0028

School: Lindblom High School      Building ID: 1450

Address: 6130 Wolcott

Chicago, IL, 60636

Building Contact: Johnson, Andre      Contact Phone: 7737096868

Current Building Owners: Chicago Public Schools

Reinspection Date: 6/13/2025

Review Date: 07/08/2025

Inspector: Josh Herman

Inspector IDPH License: 100-21040

Management Planner: James Tuinenga

Management Planner IDPH License: 100-00349

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.



James Tuinenga  
100-00349

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: July 10, 2025

RE: Lindblom High School, Unit 46511  
6130 Wolcott  
Chicago, IL, 60636

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Lindblom High School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Lindblom High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J. Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074.

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Lindblom High School      Unit: 46511      Region: 05  
Address: 6130 Wolcott      Chicago, IL, 60636  
IDPH ID: 14-016-2990-0028      Building ID: 1450  
Contact: Johnson, Andre      Phone: 7737096868

### 2. Description of Facility

Original Construction: 1919      Additional Construction:  
Total Square Footage: 305788      No of Floors: 3  
Current Occupancy: 1263

### 3. LEA Designated Person

Contact: Richard J.Schleyer      Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Phone: 630-790-0880      Fax: 630-790-0882

### 5. Inspector

Inspector Name: Josh Herman

Inspector IDPH license # 100-21040  
Reinspection Date: 6/13/2025

  
Signature:  
Date: 6/13/2025

### 6. Management Planner

Management Planner Name: James Tuinenga

Management Planner IDPH license # 100-00349


  
Signature:  
Date: 07/08/2025

### 7. Review Date: 07/08/2025

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 7/10/2025

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Lindblom High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1450:

72	2'x2' Beige White & Green Floor Tile
73	2'x2' Beige White & Green Floor Tile Mastic
74	12"x12" Checkered White & Mint Green Floor Tile
74M	Mastic associated w/12"x12" Checkered White & Mint Green Floor Tile
75	12"x12" Light Grey Floor Tile
75M	Mastic associated w/12"x12" Light Grey Floor Tile
76	Dark Grey w/Black Terrazzo
77	6"x6" Red & White Ceramic Tile Grout
78	Grey & Green Ceramic Tile Grout

79	2'x4' Smooth Ceiling Tile
80	2'x4' Tectum Ceiling Tile
81	Stair Tread Adhesive
82	Interior Window Caulk
83	Cementitious Barriers
84	Sink Undercoating
85	Maroon Stage Curtains
NEW	Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 1450:

74	12"x12" Checkered White & Mint Green Floor Tile
74M	Mastic associated w/12"x12" Checkered White & Mint Green Floor Tile
75	12"x12" Light Grey Floor Tile
75M	Mastic associated w/12"x12" Light Grey Floor Tile
76	Dark Grey w/Black Terrazzo
77	6"x6" Red & White Ceramic Tile Grout
78	Grey & Green Ceramic Tile Grout
79	2'x4' Smooth Ceiling Tile
80	2'x4' Tectum Ceiling Tile
81	Stair Tread Adhesive
82	Interior Window Caulk
83	Cementitious Barriers
84	Sink Undercoating
85	Maroon Stage Curtains

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

02A	12x12 Yellow Floor Tile
1	Plaster Walls
10A	12x12 Light Tan w/White & Brown Flecks Floor Tile NOT OBSERVED
2	Plaster Ceilings
22A	Transite Panels
50	2 x 4 White Ceiling Tiles
51	12"x12" White and Gray Checked Floor Tile
52	Beige Linoleum
53	Lab Tables
54	2'x2' White Ceiling Tiles
55	Gray Linoleum
56	12"x12" White w/Multi-Colored Streaks Vinyl Floor Tile
56M	12"x12" White w/Multi-Colored Streaks Vinyl Floor Tile Mastic
57	12"x12" Beige w/Tan Vinyl Floor Tile
57M	12"x12" Beige w/Tan Vinyl Floor Tile Mastic
58	12"x12" Yellow Vinyl Floor Tile
58M	12"x12" Yellow Vinyl Floor Tile Mastic
59	Accoustical Ceiling Tiles
60	12x12 Off-White w/Brown Streaks Vinyl Floor Tile
60M	12x12 Off-White w/Brown Streaks Vinyl Floor Tile Mastic
61	12"x12" Tan w/Dark Brown Streaks Floor Tile
61M	12"x12" Tan w/Dark Brown Streaks Floor Tile Mastic
62	12"x12" Beige w/Tan Streaks Floor Tile
62M	12"x12" Beige w/Tan Streaks Floor Tile Mastic
63	Tan, Red, Grey & Black Terrazzo Flooring
64	Light Brown Carpet Mastic
67	Light Grey Linoleum
68	Light Grey Linoleum Adhesive
69	12x12 White w/Grey Floor Tile
70	12x12 White w/Grey Floor Tile Mastic
71	Purple Carpet Adhesive NOT OBSERVED
72	2'x2' Beige White & Green Floor Tile
73	2'x2' Beige White & Green Floor Tile Mastic
74	12"x12" Checkered White & Mint Green Floor Tile
74M	Mastic associated w/12"x12" Checkered White & Mint Green Floor Tile
75	12"x12" Light Grey Floor Tile

75M	Mastic associated w/12"x12" Light Grey Floor Tile
76	Dark Grey w/Black Terrazzo
77	6"x6" Red & White Ceramic Tile Grout
78	Grey & Green Ceramic Tile Grout
79	2'x4' Smooth Ceiling Tile
80	2'x4' Tectum Ceiling Tile
81	Stair Tread Adhesive
82	Interior Window Caulk
83	Cementitious Barriers
84	Sink Undercoating
85	Maroon Stage Curtains
D	Spray-On Fire Proofing NOT OBSERVED
FT-02	12x12 Tan w/White Flecks Floor Tile NOT OBSERVED
FT-03	12"x12" Checkerboard Cream & Light Brown Floor Tile NOT OBSERVED
FT-04	12"x12" Checkerboard Champagne & Cream Floor Tile
FT-05	12x12 Tan w/Brown & White Streaks Floor Tile
FT-09	12x12 Checkerboard Cream & Light Tan Floor Tile- NOT OBSERVED
I	Boiler Insulation NOT OBSERVED
NEW	Newly Installed Suspect ACM

The following areas were deemed to be inaccessible:

15A	Light Wire Insulation
16A	Vibration Dampener
56M	12"x12" White w/Multi-Colored Streaks Vinyl Floor Tile Mastic
57M	12"x12" Beige w/Tan Vinyl Floor Tile Mastic
58M	12"x12" Yellow Vinyl Floor Tile Mastic
60M	12x12 Off-White w/Brown Streaks Vinyl Floor Tile Mastic
61M	12"x12" Tan w/Dark Brown Streaks Floor Tile Mastic
62M	12"x12" Beige w/Tan Streaks Floor Tile Mastic
64	Light Brown Carpet Mastic
68	Light Grey Linoleum Adhesive
70	12x12 White w/Grey Floor Tile Mastic
FT-01	12"x12" Orange Floor Tile NOT OBSERVED
FT-05	12x12 Tan w/Brown & White Streaks Floor Tile
FTM-01	12"x12" Orange Floor Tile Mastic NOT OBSERVED
FTM-05	12x12 Tan w/Brown & White Streaks Floor Tile Mastic

TSI-1

Cardboard Pipe Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Josh Herman, IDPH License # 100-21040. The Management Plan was updated by James Tuinenga, IDPH License # 100-00349. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:	6/15/2022
	5/18/2023
	8/1/2023
	8/29/2023
	11/1/2023
	12/27/2023
	3/28/2024

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Lindblom High School Building 1450 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

**School** Lindblom High School **Unit** 46511 **Building ID** 1450  
**Address** 6130 Wolcott **Region** 05

## **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

## Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

## ***Inspector's Comments are Summarized at the End of the Report***

# Chicago Public Schools

**School** Lindblom High School **Unit** 46511 **Building ID** 1450  
**Address** 6130 Wolcott **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Room										
50	2 x 4 White Ceiling Tiles	100,000	SF	222, 227, 220, 223B, 223A, 221, 304, 303, 323, 322, 327, 127, 324, 325, 322, 323, 313, 303, 304, 302, lower level hallways and 2nd floor hallway	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
51	12"x12" White and Gray Checked Floor Tile	3,000	SF	Rooms 200, 206, 208 & 208A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	Beige Linoleum	5,300	SF	Rooms 227, 205, 302, 303, 304, 323 & 322	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	Lab Tables	1,000	SF	Rooms 127, 205, 227, 302, 304, 308, 322, 323 & 4th Floor Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	2'x2' White Ceiling Tiles	2,500	SF	205, 302, Counselor's Suite, Health Services	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
55	Gray Linoleum	6,000	SF	Fitness Center, 4th Floor Cafeteria, Staff Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	12"x12" White w/Multi-Colored Streaks Vinyl Floor Tile	1,300	SF	Room 127	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56M	12"x12" White w/Multi-Colored Streaks Vinyl Floor Tile Mastic	1,300	SF	Room 127	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	12"x12" Beige w/Tan Vinyl Floor Tile	1,000	SF	Main Office Entry, Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57M	12"x12" Beige w/Tan Vinyl Floor Tile Mastic	250	SF	Main Office Entry, Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	12"x12" Yellow Vinyl Floor Tile	2,000	SF	Health Services	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58M	12"x12" Yellow Vinyl Floor Tile Mastic	2,000	SF	Health Services	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	Acoustical Ceiling Tiles	1,500	SF	Choral Room (137) and Piano Lab (139)	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
60	12x12 Off-White w/Brown Streaks Vinyl Floor Tile	1,250	SF	Robotics Classroom and Engineering Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60M	12x12 Off-White w/Brown Streaks Vinyl Floor Tile Mastic	1,250	SF	Robotics Classroom and Engineering	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Lindblom High School **Unit** 46511 **Building ID** 1450  
**Address** 6130 Wolcott **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Storage										
61	12"x12" Tan w/Dark Brown Streaks Floor Tile	800	SF	Book Store	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61M	12"x12" Tan w/Dark Brown Streaks Floor Tile Mastic	800	SF	Book Store	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
62	12"x12" Beige w/Tan Streaks Floor Tile	750	SF	Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
62M	12"x12" Beige w/Tan Streaks Floor Tile Mastic	750	SF	Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	Tan, Red, Grey & Black Terrazzo Flooring	22,000	SF	Entrance and Hallways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
64	Light Brown Carpet Mastic	19,275	SF	Engineer's Office, Counselor's Office, Room 111, 124, Office, Library, Auditorium, Rooms 126, 251 & Social Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
67	Light Grey Linoleum	7,500	SF	Rooms 201, 301, 304, 308, 313, 322 & 325	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
68	Light Grey Linoleum Adhesive	7,500	SF	Rooms 201, 301, 304, 308, 313, 322 & 325	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69	12x12 White w/Grey Floor Tile	5,000	SF	Rooms 127 & 127A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
70	12x12 White w/Grey Floor Tile Mastic	5,000	SF	Rooms 127 & 127A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
71	Purple Carpet Adhesive NOT OBSERVED			Rooms 137 & 139	ASSUMED	MISC								
72	2'x2' Beige White & Green Floor Tile	1,600	SF	Rooms 201 & 324	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
73	2'x2' Beige White & Green Floor Tile Mastic	600	SF	Room 324	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
74	12"x12" Checkered White & Mint Green Floor Tile	3,550	SF	Rooms 200, 208, 208A & 225	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
74M	Mastic associated w/12"x12" Checkered White & Mint Green Floor Tile	3,550	SF	Rooms 200, 208, 208A & 225	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
75	12"x12" Light Grey Floor Tile	1,360	SF	MDF Room 202, All Exam Rooms Nurse's Office	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
75M	Mastic associated w/12"x12" Light Grey Floor Tile	1,360	SF	MDF Room 202, All Exam Rooms Nurse's Office	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
76	Dark Grey w/Black Terrazzo	300	SF	2nd Floor Girls'	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the		LOW

# Chicago Public Schools

**School** Lindblom High School **Unit** 46511 **Building ID** 1450  
**Address** 6130 Wolcott **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Locker Room Shower								potential for damage		
77	6"x6" Red & White Ceramic Tile Grout	450	SF	East Wall of 2nd Floor Girls' Locker Room	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
78	Grey & Green Ceramic Tile Grout	250	SF	4th Floor Staff Locker Room	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
79	2'x4' Smooth Ceiling Tile	8,400	SF	4th Floor Cafeteria	ASSUMED	MISC	Y	NONE	0		Yes	ACBM with the potential for damage		LOW
80	2'x4' Tectum Ceiling Tile	2,200	SF	Room 251 Band Room	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
81	Stair Tread Adhesive	800	SF	Throughout All Stairwells & Elevator	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
82	Interior Window Caulk	3,100	LF	Throughout Building- All Windows	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
83	Cementitious Barriers	4,500	SF	Along Walls in all Student Washrooms	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
84	Sink Undercoating	4	EA	Nurse's Office, Rooms 136, 139 & 140	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
85	Maroon Stage Curtains	2,500	SF	Auditorium	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
D	Spray-On Fire Proofing NOT OBSERVED	16,000	SF	Boys' & Girls' Gyms, Room 145A Sound Control Room, 1st Floor Mechanical Rooms & Boiler Room	ASSUMED	SURFACE	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
E	Pipe Insulation	800	LF	1948 Building	CHR	TSI	Y	LOC	15		No	Any remaining friable ACBM or friable suspect ACBM		LOW
F	Pipe Fitting Insulation	100	LF	1948 Building- ROTC Storage	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
FT-01	12"x12" Orange Floor Tile NOT OBSERVED			Auditorium	INACCESSIBLE	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-02	12x12 Tan w/White Flecks Floor Tile NOT OBSERVED			Room 323	ASSUMED	MISC								
FT-03	12"x12" Checkerboard Cream & Light Brown Floor Tile NOT OBSERVED	4,500	SF	Main Office, Room 208, 303A & 327	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-04	12"x12" Checkerboard Champagne & Cream Floor Tile	200	SF	Main Office Hallway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Lindblom High School **Unit** 46511 **Building ID** 1450  
**Address** 6130 Wolcott **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
FT-05	12x12 Tan w/Brown & White Streaks Floor Tile	1,500	SF	Room 126	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-06	9x9 Dark Brown Floor Tile ABATED			Engineer's Office	ABATED	MISC								
FT-07	9x9 Checkerboard Green & Pinkish Floor Tile ABATED			Rooms 127, 127B	ABATED	MISC								
FT-08	9x9 Checkerboard Brown & Tan Floor Tile ABATED			Rooms 103A & 101-Breakroom	ABATED	MISC								
FT-09	12x12 Checkerboard Cream & Light Tan Floor Tile-NOT OBSERVED			Rooms 242, 244, 313	ASSUMED	MISC								
FT-11	12"x12" Checkerboard Red & Dark Tan Floor Tile	250	SF	Girls' Gym Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-12	9x9 Checkerboard Brown & Tan Floor Tile ABATED			Room 310	ABATED	MISC								
FT-13	12x12 Beige Specked Floor Tile ABATED			Room 130	ABATED	MISC								
FTM-01	12"x12" Orange Floor Tile Mastic NOT OBSERVED			Auditorium	INACCESSIBLE	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-02	12x12 Tan w/White Flecks Floor Tile Mastic ABATED			Room 324	ABATED	MISC					No			
FTM-03	12x12 Checkerboard Cream & Light Brown Floor Tile Mastic NOT OBSERVED			Main Office, Rooms 208, 303A and 327	NO_ACBM	MISC								
FTM-04	12x12 Checkerboard Champagne & Cream Floor Tile Mastic			Main Office Hall	NO_ACBM	MISC								
FTM-05	12x12 Tan w/Brown & White Streaks Floor Tile Mastic	1,500	SF	Room 126	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-06	9x9 Dark Brown Floor Tile Mastic			Engineer's Office	NO_ACBM	MISC								
FTM-07	9x9 Checkerboard Green & Pinkish Floor Tile Mastic NOT OBSERVED			Rooms 127, 127B, Outside Room 203	NO_ACBM	MISC								
FTM-08	9x9 Checkerboard Brown & Tan Floor Tile Mastic			Rooms 103A & 101-Breakroom	NO_ACBM	MISC								
FTM-09	12x12 Checkerboard Cream & Light Tan Floor Tile Mastic NOT OBSERVED			Room 242, 244, 313	CHR	MISC								
FTM-11	12x12 Checkerboard Red & Dark Tan Floor Tile Mastic			Girls' Gym Office	NO_ACBM	MISC								
FTM-12	9x9 Checkerboard Brown & Tan Floor Tile Mastic ABATED			Room 310	ABATED	MISC								
FTM-13	12"x12" Beige Specked Floor Tile Mastic ABATED			Room 130	ABATED	MISC								
G	Aircell Pipe Insulation NOT OBSERVED			1916 Building-Room 137, East & West Fan Rooms (1st Floor)	CHR	TSI								
H	Pipe Fitting Insulation NOT OBSERVED			1916 Building	CHR	TSI								
I	Boiler Insulation NOT OBSERVED			Boiler Room	ASSUMED	TSI								
NEW	Newly Installed Suspect ACM			Installed After	ASSUMED	MISC		UNKNO			Yes	ACBM with the		

# Chicago Public Schools

**School** Lindblom High School **Unit** 46511 **Building ID** 1450  
**Address** 6130 Wolcott **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Implementation of Management Plan and After Renovations				WN				potential for damage		
TSI-1	Cardboard Pipe Insulation	560	LF	3rd Floor Throughout- Pipe Chasing, Boiler Storage	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

# Chicago Public Schools

School Lindblom High School Unit 46511 Building ID 1450  
Address 6130 Wolcott Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <u>6/13/2025</u>
Inspector Name <u>Josh Herman</u>
<u>100-21040</u> <u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date

#### Inspector's Comments

HA Number:	Inspector Comments:
01A	
02A	
04A	Not Observed 2025. Room 102 Does Not Exist
06A	
07A	
08A	
1	Damaged Plaster in 3rd Fl. Boys Gym by track, Boys' Locker Room, Janitor's Closet, Room 106 & 132
10A	Not Observed 2025
12A	
13A	Not Observed 2025
14A	Not Observed Multiple Years, including 2025
15A	
16A	
17A	
19A	
2	
20A	Not Observed 2025
21A	
22A	
35B	
36C	
50	
51	2025- Not Observed in Room 208, New HA assigned

# Chicago Public Schools

**School** Lindblom High School **Unit** 46511 **Building ID** 1450  
**Address** 6130 Wolcott **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
52	
53	
54	
55	
56	
56M	
57	
57M	
58	
58M	
59	
60	
60M	
61	2025- Baxter innovation Lab
61M	
62	
62M	
63	
64	2025- Not Observed in Room 111
67	
68	
69	
70	
71	
72	
73	
74	
74M	
75	

# Chicago Public Schools

**School** Lindblom High School **Unit** 46511 **Building ID** 1450  
**Address** 6130 Wolcott **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
75M	
76	
77	
78	
79	
80	
81	
82	
83	
84	
85	
D	2025- Not Observed in Gyms, but found in other locations
E	Material damaged inbn 3rd Floor Mechanical Room
F	
FT-01	Not Observed 2025
FT-02	Not Observed Multiple Years, including 2025
FT-03	Not Observed 2025
FT-04	2025- Only Cream Coloored Tile in Main Office Hillway
FT-05	
FT-06	
FT-07	
FT-08	
FT-09	
FT-11	
FT-12	
FT-13	
FTM-01	Not Observed 2025
FTM-02	
FTM-03	Not Observed 2025

# Chicago Public Schools

**School** Lindblom High School **Unit** 46511 **Building ID** 1450  
**Address** 6130 Wolcott **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
FTM-04	
FTM-05	
FTM-06	
FTM-07	Not Observed 2025
FTM-08	
FTM-09	
FTM-11	
FTM-12	
FTM-13	
G	
H	
I	
NEW	
TSI-1	

**Table II**  
**Management Planner's Review**

---

# Chicago Public Schools

**School** Lindblom High School

**Unit** 46511

**Building ID** 1450

**Address** 6130 Wolcott

Chicago, IL, 60636

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01A	9x9 Tan w/Cream Streaks Floor Tile ABATED			1916 Building - Room 322	Abated	MISC					
02A	12x12 Yellow Floor Tile	5,250	SF	1916 Building- Rooms 101, 103	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04A	Linoleum NOT OBSERVED			1916 Building- Room 102	No ACBM	MISC					
06A	Cork Floor			1916 Building- Gym Track Floor	No ACBM	MISC					
07A	9x9 Tan w/Cream Streaks Floor Tile Mastic ABATED			1916 Building- Room 322	Abated	MISC					
08A	12x12 Yellow Floor Tile Mastic			1916 Building- Rooms 101, 103, 201, 224, 239, 240, 225, 310 & 300	No ACBM	MISC					
1	Plaster Walls	98,000	SF	Throughout	Assumed	SURFACE	No	75	SF	6 ACBM with the potential for damage	Repair
10A	12x12 Light Tan w/White & Brown Flecks Floor Tile NOT OBSERVED	2,200	SF	1948 Building- 2nd Floor Hall, Rooms 242 & 244	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12A	12x12 Light Tan w/White & Brown Flecks Floor Tile Mastic ABATED			1948 Building- 2nd Floor Hall, Rooms 242 & 244	Abated	MISC					
13A	Green Floor Sheeting NOT OBSERVED			1948 Building - Room 142	No ACBM	MISC					
14A	Transite Panels NOT OBSERVED			1916 Building		MISC					
15A	Light Wire Insulation			1916 Building	Inaccessible	MISC	No	0		6 ACBM with the potential for damage	Follow O&M Plan
16A	Vibration Dampener			1916 Building	Inaccessible	MISC	No	0		6 ACBM with the potential for damage	Follow O&M Plan
17A	Baseboard			1916 Building- 3rd Floor	No ACBM	MISC					
19A	Baseboard Mastic			1916 Building 3rd Floor	No ACBM	MISC					
2	Plaster Ceilings	58,000	SF	Throughout	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20A	Linoleum Mastic NOT OBSERVED			Room 102	No ACBM	MISC					
21A	Green Floor Sheeting Mastic ABATED			Room 142- ROTC Area	Abated	MISC					
22A	Transite Panels	60	SF	Lab Hoods in Rooms 201 & 322	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35B	Boiler Gaskets	80	LF	Boiler Room	Chrysotile	MISC	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
36C	Tank Insulation ABATED			Pump Room/Boiler Room	Abated	TSI					
50	2 x 4 White Ceiling Tiles	100,000	SF	222, 227, 220, 223B, 223A, 221, 304, 303, 323, 322, 327, 127, 324, 325, 322, 323, 313, 303, 304, 302, lower level hallways and 2nd floor hallway	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
51	12"x12" White and Gray Checked Floor Tile	3,000	SF	Rooms 200, 206, 208 & 208A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	Beige Linoleum	5,300	SF	Rooms 227, 205, 302, 303, 304, 323 & 322	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	Lab Tables	1,000	SF	Rooms 127, 205, 227, 302, 304, 308,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Lindblom High School

**Unit** 46511

**Building ID** 1450

**Address** 6130 Wolcott

Chicago, IL, 60636

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				322, 323 & 4th Floor Cafe							
54	2'x2' White Ceiling Tiles	2,500	SF	205, 302, Counselor's Suite, Health Services	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
55	Gray Linoleum	6,000	SF	Fitness Center, 4th Floor Cafeteria, Staff Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	12"x12" White w/Multi-Colored Streaks Vinyl Floor Tile	1,300	SF	Room 127	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56M	12"x12" White w/Multi-Colored Streaks Vinyl Floor Tile Mastic	1,300	SF	Room 127	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	12"x12" Beige w/Tan Vinyl Floor Tile	1,000	SF	Main Office Entry, Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57M	12"x12" Beige w/Tan Vinyl Floor Tile Mastic	250	SF	Main Office Entry, Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	12"x12" Yellow Vinyl Floor Tile	2,000	SF	Health Services	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58M	12"x12" Yellow Vinyl Floor Tile Mastic	2,000	SF	Health Services	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	Acoustical Ceiling Tiles	1,500	SF	Choral Room (137) and Piano Lab (139)	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
60	12x12 Off-White w/Brown Streaks Vinyl Floor Tile	1,250	SF	Robotics Classroom and Engineering Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60M	12x12 Off-White w/Brown Streaks Vinyl Floor Tile Mastic	1,250	SF	Robotics Classroom and Engineering Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	12"x12" Tan w/Dark Brown Streaks Floor Tile	800	SF	Book Store	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61M	12"x12" Tan w/Dark Brown Streaks Floor Tile Mastic	800	SF	Book Store	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	12"x12" Beige w/Tan Streaks Floor Tile	750	SF	Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62M	12"x12" Beige w/Tan Streaks Floor Tile Mastic	750	SF	Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	Tan, Red, Grey & Black Terrazzo Flooring	22,000	SF	Entrance and Hallways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	Light Brown Carpet Mastic	19,275	SF	Engineer's Office, Counselor's Office, Room 111, 124, Office, Library, Auditorium, Rooms 126, 251 & Social Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	Light Grey Linoleum	7,500	SF	Rooms 201, 301, 304, 308, 313, 322 & 325	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	Light Grey Linoleum Adhesive	7,500	SF	Rooms 201, 301, 304, 308, 313, 322 & 325	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	12x12 White w/Grey Floor Tile	5,000	SF	Rooms 127 & 127A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	12x12 White w/Grey Floor Tile Mastic	5,000	SF	Rooms 127 & 127A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	Purple Carpet Adhesive NOT OBSERVED			Rooms 137 & 139	Assumed	MISC					

# Chicago Public Schools

**School** Lindblom High School

**Unit** 46511

**Building ID** 1450

**Address** 6130 Wolcott

Chicago, IL, 60636

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
72	2'x2' Beige White & Green Floor Tile	1,600	SF	Rooms 201 & 324	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	2'x2' Beige White & Green Floor Tile Mastic	600	SF	Room 324	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	12"x12" Checkered White & Mint Green Floor Tile	3,550	SF	Rooms 200, 208, 208A & 225	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74M	Mastic associated w/12"x12" Checkered White & Mint Green Floor Tile	3,550	SF	Rooms 200, 208, 208A & 225	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	12"x12" Light Grey Floor Tile	1,360	SF	MDF Room 202, All Exam Rooms Nurse's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75M	Mastic associated w/12"x12" Light Grey Floor Tile	1,360	SF	MDF Room 202, All Exam Rooms Nurse's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	Dark Grey w/Black Terrazzo	300	SF	2nd Floor Girls' Locker Room Shower	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	6"x6" Red & White Ceramic Tile Grout	450	SF	East Wall of 2nd Floor Girls' Locker Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	Grey & Green Ceramic Tile Grout	250	SF	4th Floor Staff Locker Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	2'x4' Smooth Ceiling Tile	8,400	SF	4th Floor Cafeteria	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80	2'x4' Tectum Ceiling Tile	2,200	SF	Room 251 Band Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	Stair Tread Adhesive	800	SF	Throughout All Stairwells & Elevator	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
82	Interior Window Caulk	3,100	LF	Throughout Building- All Windows	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
83	Cementitious Barriers	4,500	SF	Along Walls in all Student Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
84	Sink Undercoating	4	EA	Nurse's Office, Rooms 136, 139 & 140	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
85	Maroon Stage Curtains	2,500	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
D	Spray-On Fire Proofing NOT OBSERVED	16,000	SF	Boys' & Girls' Gyms, Room 145A Sound Control Room, 1st Floor Mechanical Rooms & Boiler Room	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E	Pipe Insulation	800	LF	1948 Building	Chrysotile	TSI	Yes	15	LF	7 Any remaining friable ACBM or friable suspect ACBM	Repair
F	Pipe Fitting Insulation	100	LF	1948 Building- ROTC Storage	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
FT-01	12"x12" Orange Floor Tile NOT OBSERVED			Auditorium	Inaccessible	MISC	No	0		6 ACBM with the potential for damage	Follow O&M Plan
FT-02	12x12 Tan w/White Flecks Floor Tile NOT OBSERVED			Room 323	Assumed	MISC					
FT-03	12"x12" Checkerboard Cream & Light Brown Floor Tile NOT OBSERVED	4,500	SF	Main Office, Room 208, 303A & 327	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-04	12"x12" Checkerboard Champagne & Cream Floor Tile	200	SF	Main Office Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-05	12x12 Tan w/Brown & White Streaks Floor Tile	1,500	SF	Room 126	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Lindblom High School

**Unit** 46511

**Building ID** 1450

**Address** 6130 Wolcott

Chicago, IL, 60636

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
FT-06	9x9 Dark Brown Floor Tile ABATED			Engineer's Office	Abated	MISC					
FT-07	9x9 Checkerboard Green & Pinkish Floor Tile ABATED			Rooms 127, 127B	Abated	MISC					
FT-08	9x9 Checkerboard Brown & Tan Floor Tile ABATED			Rooms 103A & 101- Breakroom	Abated	MISC					
FT-09	12x12 Checkerboard Cream & Light Tan Floor Tile- NOT OBSERVED			Rooms 242, 244, 313	Assumed	MISC					
FT-11	12"x12" Checkerboard Red & Dark Tan Floor Tile	250	SF	Girls' Gym Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-12	9x9 Checkerboard Brown & Tan Floor Tile ABATED			Room 310	Abated	MISC					
FT-13	12x12 Beige Speckled Floor Tile ABATED			Room 130	Abated	MISC					
FTM-01	12"x12" Orange Floor Tile Mastic NOT OBSERVED			Auditorium	Inaccessible	MISC	No	0		6 ACBM with the potential for damage	Follow O&M Plan
FTM-02	12x12 Tan w/White Flecks Floor Tile Mastic ABATED			Room 324	Abated	MISC					
FTM-03	12x12 Checkerboard Cream & Light Brown Floor Tile Mastic NOT OBSERVED			Main Office, Rooms 208, 303A and 327	No ACBM	MISC					
FTM-04	12x12 Checkerboard Champagne & Cream Floor Tile Mastic			Main Office Hall	No ACBM	MISC					
FTM-05	12x12 Tan w/Brown & White Streaks Floor Tile Mastic	1,500	SF	Room 126	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-06	9x9 Dark Brown Floor Tile Mastic			Engineer's Office	No ACBM	MISC					
FTM-07	9x9 Checkerboard Green & Pinkish Floor Tile Mastic NOT OBSERVED			Rooms 127, 127B, Outside Room 203	No ACBM	MISC					
FTM-08	9x9 Checkerboard Brown & Tan Floor Tile Mastic			Rooms 103A & 101 - Breakroom	No ACBM	MISC					
FTM-09	12x12 Checkerboard Cream & Light Tan Floor Tile Mastic NOT OBSERVED			Room 242, 244, 313	Chrysotile	MISC					
FTM-11	12x12 Checkerboard Red & Dark Tan Floor Tile Mastic			Girls' Gym Office	No ACBM	MISC					
FTM-12	9x9 Checkerboard Brown & Tan Floor Tile Mastic ABATED			Room 310	Abated	MISC					
FTM-13	12"x12" Beige Speckled Floor Tile Mastic ABATED			Room 130	Abated	MISC					
G	Aircell Pipe Insulation NOT OBSERVED			1916 Building- Room 137, East & West Fan Rooms (1st Floor)	Chrysotile	TSI					
H	Pipe Fitting Insulation NOT OBSERVED			1916 Building	Chrysotile	TSI					
I	Boiler Insulation NOT OBSERVED			Boiler Room	Assumed	TSI					

# Chicago Public Schools

**School** Lindblom High School

**Unit** 46511

**Building ID** 1450

**Address** 6130 Wolcott

Chicago, IL, 60636

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan
TSI-1	Cardboard Pipe Insulation	560	LF	3rd Floor Throughout- Pipe Chasing, Boiler Storage	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Review Date 7/8/2025

HA Number Management Comments

# Chicago Public Schools

**School** Lindblom High School

**Unit** 46511

**Building ID** 1450

**Address** 6130 Wolcott

Chicago, IL, 60636

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Manager Planner Name	James Tuinenga
100-00349	5/15/2026
Manager IDPH License No/Expiration	

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
01A	
02A	
04A	
06A	
07A	
08A	
1	Repair response action selective to areas of damage only
10A	
12A	
13A	
14A	
15A	
16A	
17A	
19A	
2	
20A	
21A	
22A	
35B	
36C	
50	
51	
52	
53	
54	
55	

# Chicago Public Schools

**School** Lindblom High School

**Unit** 46511

**Building ID** 1450

**Address** 6130 Wolcott

Chicago, IL, 60636

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
56	
56M	
57	
57M	
58	
58M	
59	
60	
60M	
61	
61M	
62	
62M	
63	
64	
67	
68	
69	
70	
71	
72	
73	
74	
74M	
75	
75M	
76	

# Chicago Public Schools

**School** Lindblom High School

**Unit** 46511

**Building ID** 1450

**Address** 6130 Wolcott

Chicago, IL, 60636

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
77	
78	
79	
80	
81	
82	
83	
84	
85	
D	
E	Repair response action selective to areas of damage only
F	
FT-01	
FT-02	
FT-03	
FT-04	
FT-05	
FT-06	
FT-07	
FT-08	
FT-09	
FT-11	
FT-12	
FT-13	
FTM-01	
FTM-02	
FTM-03	

# Chicago Public Schools

**School** Lindblom High School

**Unit** 46511

**Building ID** 1450

**Address** 6130 Wolcott

Chicago, IL, 60636

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
FTM-04	
FTM-05	
FTM-06	
FTM-07	
FTM-08	
FTM-09	
FTM-11	
FTM-12	
FTM-13	
G	
H	
I	
NEW	
TSI-1	

## APPENDIX A

---

### Assessment Sheets, Drawings and Photos

**Chicago Public Schools**

**TEM Environmental, Inc.**

***2025 AHERA REINSPECTION***

# Chicago Public Schools

TEM Environmental, Inc.

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 01A

MATERIAL DESCRIPTION: 9x9 Tan w/Cream Streaks Floor Tile ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1916 Building - Room 322

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **01A**

MATERIAL DESCRIPTION: **9x9 Tan w/Cream Streaks Floor Tile ABATED**

MATERIAL LOCATION: **1916 Building - Room 322**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	02A		
MATERIAL DESCRIPTION:	12x12 Yellow Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1916 Building- Rooms 101, 103		
MATERIAL QUANTITY:	5250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **02A**

MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile**

MATERIAL LOCATION: **1916 Building- Rooms 101, 103**

MATERIAL QUANTITY: **5250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04A**

MATERIAL DESCRIPTION: **Linoleum NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1916 Building- Room 102**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS: **Not Observed 2025. Room 102 Does Not Exist**

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **04A**

MATERIAL DESCRIPTION: **Linoleum NOT OBSERVED**

MATERIAL LOCATION: **1916 Building- Room 102**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06A**  
MATERIAL DESCRIPTION: **Cork Floor**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1916 Building- Gym Track Floor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **06A**

MATERIAL DESCRIPTION: **Cork Floor**

MATERIAL LOCATION: **1916 Building- Gym Track Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 07A

MATERIAL DESCRIPTION: 9x9 Tan w/Cream Streaks Floor Tile Mastic ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1916 Building- Room 322

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **07A**

MATERIAL DESCRIPTION: **9x9 Tan w/Cream Streaks Floor Tile Mastic ABATED**

MATERIAL LOCATION: **1916 Building- Room 322**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08A**

MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1916 Building- Rooms 101, 103, 201, 224, 239, 240, 225, 310 & 300**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **08A**

MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile Mastic**

MATERIAL LOCATION: **1916 Building- Rooms 101, 103, 201, 224, 239, 240, 225, 310 & 300**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUILDING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1		
MATERIAL DESCRIPTION:	Plaster Walls		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	98000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF

COMMENTS: Damaged Plaster in 3rd Fl. Boys Gym by track, Boys' Locker Room, Janitor's Closet, Room 106 & 132

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **Plaster Walls**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **98000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **75** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Repair response action selective to areas of damage only

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10A		
MATERIAL DESCRIPTION:	12x12 Light Tan w/White & Brown Flecks Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1948 Building- 2nd Floor Hall, Rooms 242 & 244		
MATERIAL QUANTITY:	2200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **10A**

MATERIAL DESCRIPTION: **12x12 Light Tan w/White & Brown Flecks Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **1948 Building- 2nd Floor Hall, Rooms 242 & 244**

MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12A		
MATERIAL DESCRIPTION:	12x12 Light Tan w/White & Brown Flecks Floor Tile Mastic ABATED		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1948 Building- 2nd Floor Hall, Rooms 242 & 244

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **12A**

MATERIAL DESCRIPTION: **12x12 Light Tan w/White & Brown Flecks Floor Tile Mastic ABATED**

MATERIAL LOCATION: **1948 Building- 2nd Floor Hall, Rooms 242 & 244**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13A**

MATERIAL DESCRIPTION: **Green Floor Sheeting NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1948 Building - Room 142**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Not Observed 2025**

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **13A**

MATERIAL DESCRIPTION: **Green Floor Sheeting NOT OBSERVED**

MATERIAL LOCATION: **1948 Building - Room 142**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Josh Herman</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	INSPECTION DATE:	<b>6/13/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14A**

MATERIAL DESCRIPTION: **Transite Panels NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **FRIABLE**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1916 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years, including 2025**

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **14A**

MATERIAL DESCRIPTION: **Transite Panels NOT OBSERVED**

MATERIAL LOCATION: **1916 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15A		
MATERIAL DESCRIPTION:	Light Wire Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Inaccessible	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1916 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **15A**

MATERIAL DESCRIPTION: **Light Wire Insulation**

MATERIAL LOCATION: **1916 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY: **0**

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16A		
MATERIAL DESCRIPTION:	Vibration Dampener		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Inaccessible	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1916 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **16A**

MATERIAL DESCRIPTION: **Vibration Dampener**

MATERIAL LOCATION: **1916 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY: **0**

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Josh Herman</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	INSPECTION DATE:	<b>6/13/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17A**  
MATERIAL DESCRIPTION: **Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1916 Building- 3rd Floor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **17A**

MATERIAL DESCRIPTION: **Baseboard**

MATERIAL LOCATION: **1916 Building- 3rd Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Josh Herman</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	INSPECTION DATE:	<b>6/13/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19A**

MATERIAL DESCRIPTION: **Baseboard Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1916 Building 3rd Floor**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **19A**

MATERIAL DESCRIPTION: **Baseboard Mastic**

MATERIAL LOCATION: **1916 Building 3rd Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2		
MATERIAL DESCRIPTION:	Plaster Ceilings		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	58000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **Plaster Ceilings**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **58000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Josh Herman</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	INSPECTION DATE:	<b>6/13/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20A**

MATERIAL DESCRIPTION: **Linoleum Mastic NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 102**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS: **Not Observed 2025**

Inspector's Signature: 

Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **20A**

MATERIAL DESCRIPTION: **Linoleum Mastic NOT OBSERVED**

MATERIAL LOCATION: **Room 102**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 21A

MATERIAL DESCRIPTION: Green Floor Sheeting Mastic ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 142- ROTC Area

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **21A**

MATERIAL DESCRIPTION: **Green Floor Sheeting Mastic ABATED**

MATERIAL LOCATION: **Room 142- ROTC Area**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUILDING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22A		
MATERIAL DESCRIPTION:	Transite Panels		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lab Hoods in Rooms 201 & 322		
MATERIAL QUANTITY:	60	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **22A**

MATERIAL DESCRIPTION: **Transite Panels**

MATERIAL LOCATION: **Lab Hoods in Rooms 201 & 322**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35B		
MATERIAL DESCRIPTION:	Boiler Gaskets		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **35B**

MATERIAL DESCRIPTION: **Boiler Gaskets**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36C**

MATERIAL DESCRIPTION: **Tank Insulation ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pump Room/Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **36C**

MATERIAL DESCRIPTION: **Tank Insulation ABATED**

MATERIAL LOCATION: **Pump Room/Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	2 x 4 White Ceiling Tiles		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **222, 227, 220, 223B, 223A, 221, 304, 303, 323, 322, 327, 127, 324, 325, 322, 323, 313, 303, 304, 302, lower level hallways and 2nd floor hallway**

MATERIAL QUANTITY: **100000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **2 x 4 White Ceiling Tiles**

MATERIAL LOCATION: **222, 227, 220, 223B, 223A, 221, 304, 303, 323, 322, 327, 127, 324, 325, 322, 323, 313, 303, 304, 302, lower level hallways and 2nd floor hallway**

MATERIAL QUANTITY: **100000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	12"x12" White and Gray Checked Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 200, 206, 208 & 208A		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	2025- Not Observed in Room 208, New HA assigned		

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **12"x12" White and Gray Checked Floor Tile**

MATERIAL LOCATION: **Rooms 200, 206, 208 & 208A**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	Beige Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 227, 205, 302, 303, 304, 323 & 322		
MATERIAL QUANTITY:	5300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **Beige Linoleum**

MATERIAL LOCATION: **Rooms 227, 205, 302, 303, 304, 323 & 322**

MATERIAL QUANTITY: **5300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Josh Herman</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	INSPECTION DATE:	<b>6/13/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>53</b>		
MATERIAL DESCRIPTION:	<b>Lab Tables</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 127, 205, 227, 302, 304, 308, 322, 323 &amp; 4th Floor Cafe</b>		
MATERIAL QUANTITY:	<b>1000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **Lab Tables**

MATERIAL LOCATION: **Rooms 127, 205, 227, 302, 304, 308, 322, 323 & 4th Floor Cafe**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	2'x2' White Ceiling Tiles		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	205, 302, Counselor's Suite, Health Services		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **2'x2' White Ceiling Tiles**

MATERIAL LOCATION: **205, 302, Counselor's Suite, Health Services**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55		
MATERIAL DESCRIPTION:	Gray Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Fitness Center, 4th Floor Cafeteria, Staff Lunchroom		
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Gray Linoleum**

MATERIAL LOCATION: **Fitness Center, 4th Floor Cafeteria, Staff Lunchroom**

MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Josh Herman</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	INSPECTION DATE:	<b>6/13/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>56</b>		
MATERIAL DESCRIPTION:	<b>12"x12" White w/Multi-Colored Streaks Vinyl Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 127</b>		
MATERIAL QUANTITY:	<b>1300</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **12"x12" White w/Multi-Colored Streaks Vinyl Floor Tile**

MATERIAL LOCATION: **Room 127**

MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	56M		
MATERIAL DESCRIPTION:	12"x12" White w/Multi-Colored Streaks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 127		
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **56M**

MATERIAL DESCRIPTION: **12"x12" White w/Multi-Colored Streaks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 127**

MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Josh Herman</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	INSPECTION DATE:	<b>6/13/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>57</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Beige w/Tan Vinyl Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Main Office Entry, Engineer's Office</b>		
MATERIAL QUANTITY:	<b>1000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **12"x12" Beige w/Tan Vinyl Floor Tile**

MATERIAL LOCATION: **Main Office Entry, Engineer's Office**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	57M		
MATERIAL DESCRIPTION:	12"x12" Beige w/Tan Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office Entry, Engineer's Office		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **57M**

MATERIAL DESCRIPTION: **12"x12" Beige w/Tan Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Main Office Entry, Engineer's Office**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	12"x12" Yellow Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Health Services		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **12"x12" Yellow Vinyl Floor Tile**

MATERIAL LOCATION: **Health Services**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58M		
MATERIAL DESCRIPTION:	12"x12" Yellow Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Health Services		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **58M**

MATERIAL DESCRIPTION: **12"x12" Yellow Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Health Services**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	59		
MATERIAL DESCRIPTION:	Acoustical Ceiling Tiles		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Choral Room (137) and Piano Lab (139)		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **Acoustical Ceiling Tiles**

MATERIAL LOCATION: **Choral Room (137) and Piano Lab (139)**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	60		
MATERIAL DESCRIPTION:	12x12 Off-White w/Brown Streaks Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Robotics Classroom and Engineering Storage		
MATERIAL QUANTITY:	1250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **12x12 Off-White w/Brown Streaks Vinyl Floor Tile**

MATERIAL LOCATION: **Robotics Classroom and Engineering Storage**

MATERIAL QUANTITY: **1250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	60M		
MATERIAL DESCRIPTION:	12x12 Off-White w/Brown Streaks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Robotics Classroom and Engineering Storage		
MATERIAL QUANTITY:	1250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **60M**

MATERIAL DESCRIPTION: **12x12 Off-White w/Brown Streaks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Robotics Classroom and Engineering Storage**

MATERIAL QUANTITY: **1250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Josh Herman</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	INSPECTION DATE:	<b>6/13/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>61</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Tan w/Dark Brown Streaks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Book Store</b>		
MATERIAL QUANTITY:	<b>800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>2025- Baxter innovation Lab</b>		

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **12"x12" Tan w/Dark Brown Streaks Floor Tile**

MATERIAL LOCATION: **Book Store**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	61M		
MATERIAL DESCRIPTION:	12"x12" Tan w/Dark Brown Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Book Store		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **61M**

MATERIAL DESCRIPTION: **12"x12" Tan w/Dark Brown Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Book Store**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	62		
MATERIAL DESCRIPTION:	12"x12" Beige w/Tan Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **12"x12" Beige w/Tan Streaks Floor Tile**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	62M		
MATERIAL DESCRIPTION:	12"x12" Beige w/Tan Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **62M**

MATERIAL DESCRIPTION: **12"x12" Beige w/Tan Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Josh Herman</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	INSPECTION DATE:	<b>6/13/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>63</b>		
MATERIAL DESCRIPTION:	<b>Tan, Red, Grey &amp; Black Terrazzo Flooring</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Entrance and Hallways</b>		
MATERIAL QUANTITY:	<b>22000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **Tan, Red, Grey & Black Terrazzo Flooring**

MATERIAL LOCATION: **Entrance and Hallways**

MATERIAL QUANTITY: **22000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	64		
MATERIAL DESCRIPTION:	Light Brown Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office, Counselor's Office, Room 111, 124, Office, Library, Auditorium, Rooms 126, 251 & Social Room**

MATERIAL QUANTITY: **19275** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS: **2025- Not Observed in Room 111**

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **Light Brown Carpet Mastic**

MATERIAL LOCATION: **Engineer's Office, Counselor's Office, Room 111, 124, Office, Library, Auditorium, Rooms 126, 251 & Social Room**

MATERIAL QUANTITY: **19275** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	67		
MATERIAL DESCRIPTION:	Light Grey Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 201, 301, 304, 308, 313, 322 & 325		
MATERIAL QUANTITY:	7500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **Light Grey Linoleum**

MATERIAL LOCATION: **Rooms 201, 301, 304, 308, 313, 322 & 325**

MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	68		
MATERIAL DESCRIPTION:	Light Grey Linoleum Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 201, 301, 304, 308, 313, 322 & 325		
MATERIAL QUANTITY:	7500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **Light Grey Linoleum Adhesive**

MATERIAL LOCATION: **Rooms 201, 301, 304, 308, 313, 322 & 325**

MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Josh Herman</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	INSPECTION DATE:	<b>6/13/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>69</b>		
MATERIAL DESCRIPTION:	<b>12x12 White w/Grey Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 127 &amp; 127A</b>		
MATERIAL QUANTITY:	<b>5000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **12x12 White w/Grey Floor Tile**

MATERIAL LOCATION: **Rooms 127 & 127A**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	70		
MATERIAL DESCRIPTION:	12x12 White w/Grey Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 127 & 127A		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **12x12 White w/Grey Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 127 & 127A**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 71

MATERIAL DESCRIPTION: Purple Carpet Adhesive NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 137 & 139

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **Purple Carpet Adhesive NOT OBSERVED**

MATERIAL LOCATION: **Rooms 137 & 139**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	72		
MATERIAL DESCRIPTION:	2'x2' Beige White & Green Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 201 & 324		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **2'x2' Beige White & Green Floor Tile**

MATERIAL LOCATION: **Rooms 201 & 324**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	73		
MATERIAL DESCRIPTION:	2'x2' Beige White & Green Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 324		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **2'x2' Beige White & Green Floor Tile Mastic**

MATERIAL LOCATION: **Room 324**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	Spray-On Fire Proofing NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boys' & Girls' Gyms, Room 145A Sound Control Room, 1st Floor Mechanical Rooms & Boiler Room		
MATERIAL QUANTITY:	16000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	2025- Not Observed in Gyms, but found in other locations		

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Spray-On Fire Proofing NOT OBSERVED**

MATERIAL LOCATION: **Boys' & Girls' Gyms, Room 145A Sound Control Room, 1st Floor Mechanical Rooms & Boiler Room**

MATERIAL QUANTITY: **16000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUILDING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1948 Building		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:	Material damaged inb 3rd Floor Mechanical Room		

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Pipe Insulation**

MATERIAL LOCATION: **1948 Building**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **15** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Repair response action selective to areas of damage only

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F		
MATERIAL DESCRIPTION:	Pipe Fitting Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1948 Building- ROTC Storage		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Pipe Fitting Insulation**

MATERIAL LOCATION: **1948 Building- ROTC Storage**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-01		
MATERIAL DESCRIPTION:	12"x12" Orange Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Inaccessible	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2025**

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

**TEM Environmental, Inc.**  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

HOMOGENEOUS AREA: **FT-01**

MATERIAL DESCRIPTION: 12"x12" Orange Floor Tile NOT OBSERVED

MATERIAL LOCATION: Auditorium

**MATERIAL QUANTITY:**

## MATERIAL UNITS:

DAMAGE QUANTITY: **0**

## DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

## Follow O&M Plan

### Comments:

Management Planner's Signature:

Jan Tenwig

Date: 07/08/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-02		
MATERIAL DESCRIPTION:	12x12 Tan w/White Flecks Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 323

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed Multiple Years, including 2025

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FT-02**

MATERIAL DESCRIPTION: **12x12 Tan w/White Flecks Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **Room 323**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUILDING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-03		
MATERIAL DESCRIPTION:	12"x12" Checkerboard Cream & Light Brown Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office, Room 208, 303A & 327**

MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS: **Not Observed 2025**

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FT-03**

MATERIAL DESCRIPTION: **12"x12" Checkerboard Cream & Light Brown Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **Main Office, Room 208, 303A & 327**

MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-04		
MATERIAL DESCRIPTION:	12"x12" Checkerboard Champagne & Cream Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office Hallway		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	2025- Only Cream Colored Tile in Main Office Hallway		

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FT-04**

MATERIAL DESCRIPTION: **12"x12" Checkerboard Champagne & Cream Floor Tile**

MATERIAL LOCATION: **Main Office Hallway**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-05		
MATERIAL DESCRIPTION:	12x12 Tan w/Brown & White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 126		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FT-05**

MATERIAL DESCRIPTION: **12x12 Tan w/Brown & White Streaks Floor Tile**

MATERIAL LOCATION: **Room 126**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Josh Herman</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	INSPECTION DATE:	<b>6/13/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-06**

MATERIAL DESCRIPTION: **9x9 Dark Brown Floor Tile ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FT-06**

MATERIAL DESCRIPTION: **9x9 Dark Brown Floor Tile ABATED**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: FT-07

MATERIAL DESCRIPTION: 9x9 Checkerboard Green & Pinkish Floor Tile ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 127, 127B

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FT-07**

MATERIAL DESCRIPTION: **9x9 Checkerboard Green & Pinkish Floor Tile ABATED**

MATERIAL LOCATION: **Rooms 127, 127B**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUILDING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-08		
MATERIAL DESCRIPTION:	9x9 Checkerboard Brown & Tan Floor Tile ABATED		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 103A & 101- Breakroom

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FT-08**

MATERIAL DESCRIPTION: **9x9 Checkerboard Brown & Tan Floor Tile ABATED**

MATERIAL LOCATION: **Rooms 103A & 101- Breakroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-09	
MATERIAL DESCRIPTION:	12x12 Checkerboard Cream & Light Tan Floor Tile-NOT OBSERVED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 242, 244, 313

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FT-09**

MATERIAL DESCRIPTION: **12x12 Checkerboard Cream & Light Tan Floor Tile-NOT OBSERVED**

MATERIAL LOCATION: **Rooms 242, 244, 313**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-11		
MATERIAL DESCRIPTION:	12"x12" Checkerboard Red & Dark Tan Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Girls' Gym Office		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FT-11**

MATERIAL DESCRIPTION: **12"x12" Checkerboard Red & Dark Tan Floor Tile**

MATERIAL LOCATION: **Girls' Gym Office**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Josh Herman</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	INSPECTION DATE:	<b>6/13/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>FT-12</b>		
MATERIAL DESCRIPTION:	<b>9x9 Checkerboard Brown &amp; Tan Floor Tile ABATED</b>		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	<b>Abated</b>	FRIABLE:	

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 310**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FT-12**

MATERIAL DESCRIPTION: **9x9 Checkerboard Brown & Tan Floor Tile ABATED**

MATERIAL LOCATION: **Room 310**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Josh Herman</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	INSPECTION DATE:	<b>6/13/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>FT-13</b>		
MATERIAL DESCRIPTION:	<b>12x12 Beige Speckled Floor Tile ABATED</b>		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	<b>Abated</b>	FRIABLE:	

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FT-13**

MATERIAL DESCRIPTION: **12x12 Beige Speckled Floor Tile ABATED**

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-01		
MATERIAL DESCRIPTION:	12"x12" Orange Floor Tile Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Inaccessible	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2025**

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FTM-01**

MATERIAL DESCRIPTION: **12"x12" Orange Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: **0** DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-02**

MATERIAL DESCRIPTION: **12x12 Tan w/White Flecks Floor Tile Mastic ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 324**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FTM-02**

MATERIAL DESCRIPTION: **12x12 Tan w/White Flecks Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Room 324**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUILDING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-03		
MATERIAL DESCRIPTION:	12x12 Checkerboard Cream & Light Brown Floor Tile Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Office, Rooms 208, 303A and 327

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed 2025

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FTM-03**

MATERIAL DESCRIPTION: **12x12 Checkerboard Cream & Light Brown Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **Main Office, Rooms 208, 303A and 327**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUILDING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-04		
MATERIAL DESCRIPTION:	12x12 Checkerboard Champagne & Cream Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Office Hall

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FTM-04**

MATERIAL DESCRIPTION: **12x12 Checkerboard Champagne & Cream Floor Tile Mastic**

MATERIAL LOCATION: **Main Office Hall**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-05		
MATERIAL DESCRIPTION:	12x12 Tan w/Brown & White Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 126		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FTM-05**

MATERIAL DESCRIPTION: **12x12 Tan w/Brown & White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Room 126**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Josh Herman</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	INSPECTION DATE:	<b>6/13/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-06**

MATERIAL DESCRIPTION: **9x9 Dark Brown Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature: 

Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FTM-06**

MATERIAL DESCRIPTION: **9x9 Dark Brown Floor Tile Mastic**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-07		
MATERIAL DESCRIPTION:	9x9 Checkerboard Green & Pinkish Floor Tile Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 127, 127B, Outside Room 203

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed 2025

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FTM-07**

MATERIAL DESCRIPTION: **9x9 Checkerboard Green & Pinkish Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **Rooms 127, 127B, Outside Room 203**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-08**

MATERIAL DESCRIPTION: **9x9 Checkerboard Brown & Tan Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 103A & 101 - Breakroom**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FTM-08**

MATERIAL DESCRIPTION: **9x9 Checkerboard Brown & Tan Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 103A & 101 - Breakroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-09		
MATERIAL DESCRIPTION:	12x12 Checkerboard Cream & Light Tan Floor Tile Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 242, 244, 313

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FTM-09**

MATERIAL DESCRIPTION: **12x12 Checkerboard Cream & Light Tan Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **Room 242, 244, 313**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-11		
MATERIAL DESCRIPTION:	12x12 Checkerboard Red & Dark Tan Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Girls' Gym Office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FTM-11**

MATERIAL DESCRIPTION: **12x12 Checkerboard Red & Dark Tan Floor Tile Mastic**

MATERIAL LOCATION: **Girls' Gym Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Josh Herman</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	INSPECTION DATE:	<b>6/13/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>FTM-12</b>		
MATERIAL DESCRIPTION:	<b>9x9 Checkerboard Brown &amp; Tan Floor Tile Mastic ABATED</b>		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	<b>Abated</b>	FRIABLE:	

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 310**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FTM-12**

MATERIAL DESCRIPTION: **9x9 Checkerboard Brown & Tan Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Room 310**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: FTM-13

MATERIAL DESCRIPTION: 12"x12" Beige Speckled Floor Tile Mastic ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 130

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **FTM-13**

MATERIAL DESCRIPTION: **12"x12" Beige Specked Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUILDING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Chrysotile** FRIABLE: \_\_\_\_\_

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1916 Building- Room 137, East & West Fan Rooms (1st Floor)**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation NOT OBSERVED**

MATERIAL LOCATION: **1916 Building- Room 137, East & West Fan Rooms (1st Floor)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUILDING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: H

MATERIAL DESCRIPTION: Pipe Fitting Insulation NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Chrysotile FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1916 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Pipe Fitting Insulation NOT OBSERVED**

MATERIAL LOCATION: **1916 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Josh Herman</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	INSPECTION DATE:	<b>6/13/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Boiler Insulation NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Assumed** FRIABLE:

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Boiler Insulation NOT OBSERVED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	NEW		
MATERIAL DESCRIPTION:	Newly Installed Suspect ACM		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **NEW**

MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**

MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUILDING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	TSI-1		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Throughout- Pipe Chasing, Boiler Storage		
MATERIAL QUANTITY:	560	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUILDING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	REVIEW DATE:	<b>7/8/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **TSI-1**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **3rd Floor Throughout- Pipe Chasing, Boiler Storage**

MATERIAL QUANTITY: **560** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>46511</b>	BUIDLING ID:	<b>1450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Josh Herman</b>		
SCHOOL NAME:	<b>Lindblom High School</b>	INSPECTION DATE:	<b>6/13/2025</b>		
ADDRESS:	<b>6130 Wolcott</b>	IDPH LICENSE NO:	<b>100-21040</b>		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	<b>82</b>			
MATERIAL DESCRIPTION:	<b>Interior Window Caulk</b>			
MATERIAL LOCATION:	<b>Throughout Building- All Windows</b>			
MATERIAL QUANTITY:	<b>3100</b>	MATERIAL UNITS:	<b>LF</b>	
MATERIAL CATEGORY:	<b>MISC</b>	FRIABLE:	<b>No</b>	
ASBESTOS TYPE:	<b>Assumed</b>			
DISTURBANCE POTENTIAL:	<b>LOW</b>	CONDITION:		
AHERA DAMAGE CATEGORY:	<b>6 ACBM with the potential for damage</b>			
ACCESSIBILITY:	<b>Within Reach</b>	DAMAGE REASON:		
DAMAGE QUANTITY:	<b>0</b>	DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	<b>LF</b>	
COMMENTS:				

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46511** BUIDLING ID: **1450**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Lindblom High School** REVIEW DATE: **7/8/2025**

ADDRESS: **6130 Wolcott** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **Interior Window Caulk**

MATERIAL LOCATION: **Throughout Building- All Windows**

MATERIAL QUANTITY: **3100** MATERIAL UNITS: **LF**


DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 07/08/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	84		
MATERIAL DESCRIPTION:	Sink Undercoating		
MATERIAL LOCATION:	Nurse's Office, Rooms 136, 139 & 140		
MATERIAL QUANTITY:	4	MATERIAL UNITS:	EA
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	EA

COMMENTS:

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46511** BUIDLING ID: **1450**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Lindblom High School** REVIEW DATE: **7/8/2025**

ADDRESS: **6130 Wolcott** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **Sink Undercoating**

MATERIAL LOCATION: **Nurse's Office, Rooms 136, 139 & 140**

MATERIAL QUANTITY: **4** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	80		
MATERIAL DESCRIPTION:	2'x4' Tectum Ceiling Tile		
MATERIAL LOCATION:	Room 251 Band Room		
MATERIAL QUANTITY:	2200	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46511** BUIDLING ID: **1450**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Lindblom High School** REVIEW DATE: **7/8/2025**

ADDRESS: **6130 Wolcott** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **2'x4' Tectum Ceiling Tile**

MATERIAL LOCATION: **Room 251 Band Room**

MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	75M				
MATERIAL DESCRIPTION:	Mastic associated w/12"x12" Light Grey Floor Tile				
MATERIAL LOCATION:	MDF Room 202, All Exam Rooms Nurse's Office				
MATERIAL QUANTITY:	1360	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46511** BUIDLING ID: **1450**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Lindblom High School** REVIEW DATE: **7/8/2025**

ADDRESS: **6130 Wolcott** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **75M**

MATERIAL DESCRIPTION: **Mastic associated w/12"x12" Light Grey Floor Tile**

MATERIAL LOCATION: **MDF Room 202, All Exam Rooms Nurse's Office**

MATERIAL QUANTITY: **1360** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 07/08/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	85		
MATERIAL DESCRIPTION:	Maroon Stage Curtains		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46511** BUIDLING ID: **1450**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Lindblom High School** REVIEW DATE: **7/8/2025**

ADDRESS: **6130 Wolcott** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **85**

MATERIAL DESCRIPTION: **Maroon Stage Curtains**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 07/08/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	81		
MATERIAL DESCRIPTION:	Stair Tread Adhesive		
MATERIAL LOCATION:	Throughout All Stairwells & Elevator		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46511** BUIDLING ID: **1450**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Lindblom High School** REVIEW DATE: **7/8/2025**

ADDRESS: **6130 Wolcott** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **Stair Tread Adhesive**

MATERIAL LOCATION: **Throughout All Stairwells & Elevator**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	74M				
MATERIAL DESCRIPTION:	Mastic associated w/12"x12" Checkered White & Mint Green Floor Tile				
MATERIAL LOCATION:	Rooms 200, 208, 208A & 225				
MATERIAL QUANTITY:	3550	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46511** BUIDLING ID: **1450**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Lindblom High School** REVIEW DATE: **7/8/2025**

ADDRESS: **6130 Wolcott** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **74M**

MATERIAL DESCRIPTION: **Mastic associated w/12"x12" Checkered White & Mint Green Floor Tile**

MATERIAL LOCATION: **Rooms 200, 208, 208A & 225**

MATERIAL QUANTITY: **3550** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	78		
MATERIAL DESCRIPTION:	Grey & Green Ceramic Tile Grout		
MATERIAL LOCATION:	4th Floor Staff Locker Room		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46511** BUIDLING ID: **1450**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Lindblom High School** REVIEW DATE: **7/8/2025**

ADDRESS: **6130 Wolcott** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **Grey & Green Ceramic Tile Grout**

MATERIAL LOCATION: **4th Floor Staff Locker Room**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46511** BUIDLING ID: **1450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Josh Herman**  
SCHOOL NAME: **Lindblom High School** INSPECTION DATE: **6/13/2025**  
ADDRESS: **6130 Wolcott** IDPH LICENSE NO: **100-21040**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **Dark Grey w/Black Terrazzo**  
MATERIAL LOCATION: **2nd Floor Girls' Locker Room Shower**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC** FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW** CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach** DAMAGE REASON:  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **06/13/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46511** BUIDLING ID: **1450**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Lindblom High School** REVIEW DATE: **7/8/2025**

ADDRESS: **6130 Wolcott** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **Dark Grey w/Black Terrazzo**

MATERIAL LOCATION: **2nd Floor Girls' Locker Room Shower**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	77		
MATERIAL DESCRIPTION:	6"x6" Red & White Ceramic Tile Grout		
MATERIAL LOCATION:	East Wall of 2nd Floor Girls' Locker Room		
MATERIAL QUANTITY:	450	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46511** BUIDLING ID: **1450**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Lindblom High School** REVIEW DATE: **7/8/2025**

ADDRESS: **6130 Wolcott** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **6"x6" Red & White Ceramic Tile Grout**

MATERIAL LOCATION: **East Wall of 2nd Floor Girls' Locker Room**

MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	83		
MATERIAL DESCRIPTION:	Cementitious Barriers		
MATERIAL LOCATION:	Along Walls in all Student Washrooms		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46511** BUIDLING ID: **1450**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Lindblom High School** REVIEW DATE: **7/8/2025**

ADDRESS: **6130 Wolcott** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **Cementitious Barriers**

MATERIAL LOCATION: **Along Walls in all Student Washrooms**

MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	74		
MATERIAL DESCRIPTION:	12"x12" Checkered White & Mint Green Floor Tile		
MATERIAL LOCATION:	Rooms 200, 208, 208A & 225		
MATERIAL QUANTITY:	3550	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46511** BUIDLING ID: **1450**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Lindblom High School** REVIEW DATE: **7/8/2025**

ADDRESS: **6130 Wolcott** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **12"x12" Checkered White & Mint Green Floor Tile**

MATERIAL LOCATION: **Rooms 200, 208, 208A & 225**

MATERIAL QUANTITY: **3550** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **07/08/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	75		
MATERIAL DESCRIPTION:	12"x12" Light Grey Floor Tile		
MATERIAL LOCATION:	MDF Room 202, All Exam Rooms Nurse's Office		
MATERIAL QUANTITY:	1360	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
COMMENTS:			

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46511** BUIDLING ID: **1450**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Lindblom High School** REVIEW DATE: **7/8/2025**

ADDRESS: **6130 Wolcott** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **12"x12" Light Grey Floor Tile**

MATERIAL LOCATION: **MDF Room 202, All Exam Rooms Nurse's Office**

MATERIAL QUANTITY: **1360** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 07/08/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	46511	BUIDLING ID:	1450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Lindblom High School	INSPECTION DATE:	6/13/2025		
ADDRESS:	6130 Wolcott	IDPH LICENSE NO:	100-21040		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	79		
MATERIAL DESCRIPTION:	2'x4' Smooth Ceiling Tile		
MATERIAL LOCATION:	4th Floor Cafeteria		
MATERIAL QUANTITY:	8400	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	Yes
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 06/13/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46511** BUIDLING ID: **1450**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**

SCHOOL NAME: **Lindblom High School** REVIEW DATE: **7/8/2025**

ADDRESS: **6130 Wolcott** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **2'x4' Smooth Ceiling Tile**

MATERIAL LOCATION: **4th Floor Cafeteria**

MATERIAL QUANTITY: **8400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **07/08/2025**

**Chicago Public Schools**

**TEM Environmental, Inc.**

***2025 AHERA REINSPECTION***

## APPENDIX B

---

### Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**JOSH R HERMAN**  
5121 N MONITOR AVE  
CHICAGO, IL 60630

5/23/2025

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 21040

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License



**ASBESTOS  
PROFESSIONAL  
LICENSE**

**ENDORSEMENTS**

**TC EXPIRES**

INSPECTOR

7/19/2025

ID NUMBER  
100 - 21040

ISSUED  
5/23/2025

EXPIRES  
05/15/2026

**JOSH R HERMAN**  
5121 N MONITOR AVE  
CHICAGO, IL 60630  
Environmental Health



**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**

*Nationally Accredited by PHAB*

Reliable  
Environmental  
Solutions, Inc. **R | E | S**

*This is to certify that*

**James Tuinenga**

*has on 2/2/22, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Building Inspector Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher.*

Course Date: February 2, 2022

**COURSE LENGTH: 4 HOURS**

Examination Date: February 2, 2022

Expiration Date: February 2, 2023

Certificate Number: BIR/1013

*William S. Williams*


Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois  217.787.9800  217.787.9801 FAX  [www.ReliableEnv.com](http://www.ReliableEnv.com)



**TEM ENVIRONMENTAL, INC.**

ENVIRONMENTAL SCIENTISTS | INDUSTRIAL HYGIENISTS



ENDORSEMENTS

INSPECTOR	2/2/2023
PROJECT DESIGNER	2/3/2023
MANAGEMENT PLANNER	2/2/2023
PROJECT MANAGER	2/1/2023
AIR SAMPLING PROFESSIONAL	

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

**Reliable  
Environmental  
Solutions, Inc.      RES**

*This is to certify that*

**James Tuinenga**

*has on 2/02/22, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: February 2, 2022

**COURSE LENGTH: 4 HOURS**

Examination Date: February 2, 2022

Expiration Date: February 2, 2023

*William S. Williams*


Certificate Number: MPR/0458

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois  217.787.9800  217.787.9801 FAX  [www.ReliableEnv.com](http://www.ReliableEnv.com)



**TEM ENVIRONMENTAL, INC.**  
ENVIRONMENTAL SCIENTISTS | INDUSTRIAL HYGIENISTS



**ENDORSEMENTS**

INSPECTOR  
PROJECT DESIGNER  
MANAGEMENT PLANNER  
PROJECT MANAGER  
AIR SAMPLING PROFESSIONAL

**TC EXPIRES**

1/31/2025  
2/1/2025  
1/31/2025  
1/30/2025

**Alteration of this license shall result in legal action**

This license issued under authority of the State of Illinois

Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.

**Reliable  
Environmental  
Solutions, Inc. R E S**

*This is to certify that*

**James Tuinenga**

*has on 2/5/25, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Building Inspector Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher.*

Course Date: February 5, 2025

**COURSE LENGTH: 4 HOURS**

Examination Date: February 5, 2025

Expiration Date: February 5, 2026

Certificate Number: BIR/1227




Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois  217.787.9800  [www.ReliableEnv.com](http://www.ReliableEnv.com)



**TEM ENVIRONMENTAL, INC.**  
ENVIRONMENTAL SCIENTISTS | INDUSTRIAL HYGIENISTS



**ENDORSEMENTS**

INSPECTOR  
PROJECT DESIGNER  
MANAGEMENT PLANNER  
PROJECT MANAGER  
AIR SAMPLING PROFESSIONAL

**TC EXPIRES**

2/5/2026  
2/6/2025  
2/5/2026  
2/4/2026

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

**Reliable  
Environmental  
Solutions, Inc.** **R E S**

*This is to certify that*

**James Tuinenga**

*has on 2/5/25, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: February 5, 2025

**COURSE LENGTH: 4 HOURS**

Examination Date: February 5, 2025

Expiration Date: February 5, 2026

Certificate Number: MPR/0546



Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois  217.787.9800  [www.ReliableEnv.com](http://www.ReliableEnv.com)

## APPENDIX C

---

### **Laboratory Accreditations**

## APPENDIX D

---

### Laboratory Results

## APPENDIX E

---

### Chain of Custody Forms

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>	Loc	Localized
	Dist	Distributed