

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-0008  
SCHOOL NAME: Crane Tech High School  
ADDRESS OF SCHOOL: 2245 W. Jackson  
CITY: Chicago, IL, 60612

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **10/29/2022**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 5/30/2025 ENROLLMENT 292  
IDPH INSPECTOR LICENSE NUMBER: 100-20994  
IDPH LICENSED INSPECTOR NAME (Please Print): Cody Cummins  
IDPH MP LICENSE NUMBER: 100-20634  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jackson Montgomery  
  
DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

6/16/2025

Richard J. Schleyer

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_  
School has been closed. Date closed: \_\_\_\_\_  
School building has been demolished. Date: \_\_\_\_\_  
School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Crane Tech High School**

2245 W. Jackson  
Chicago, IL, 60612

Unit: 46641  
Building ID: 1270

IDPH ID Number: 14-016-2990-0008

**REPORT DATE:**

Monday, June 16, 2025

**Prepared for:**

**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

06/16/2025

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 46641            Region:            IDPH ID: 14-016-2990-0008

School: Crane Tech High School            Building ID: 1270

Address: 2245 W. Jackson

Chicago, IL, 60612

Building Contact: LeBarre, Anthony

Contact Phone: 3126180680

Current Building Owners: Chicago Public Schools

Reinspection Date: 5/30/2025

Review Date: 06/16/2025

Inspector: Cody Cummins

Inspector IDPH License: 100-20994

Management Planner: Jackson Montgomery

Management Planner IDPH License: 100-20634

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates



Jackson Montgomery  
100-20634

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: June 16, 2025

RE: Crane Tech High School, Unit 46641  
2245 W. Jackson  
Chicago, IL, 60612

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Crane Tech High School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Crane Tech High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Crane Tech High School      Unit: 46641      Region:  
Address: 2245 W. Jackson      Chicago, IL, 60612  
IDPH ID: 14-016-2990-0008      Building ID: 1270  
Contact: LeBarre, Anthony      Phone: 3126180680

### 2. Description of Facility

Original Construction: 1923      Additional Construction: 1978  
Total Square Footage: 371560      No of Floors: 4  
Current Occupancy: 292

### 3. LEA Designated Person

Contact: Richard J.Schleyer      Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Doug McCormick  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900      Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Cody Cummins

Inspector IDPH license # 100-20994  
Reinspection Date: 5/30/2025

  
Signature:  
Date: 5/30/2025

### 6. Management Planner

Management Planner Name: Jackson Montgomery

Management Planner IDPH license # 100-20634


  
Signature:  
Date: 06/16/2025

### 7. Review Date: 06/16/2025

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 6/16/2025

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Crane Tech High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1270:

010	2' x 4' Random Dot Lay-in Ceiling Panels
049	Gray and White Linoleum
050	Gray and White Linoleum Mastic
073M	Mastic on Floor Tile Beneath 12" x 12" Floor Tile
076	Material Under Carpet
107	Floor Tile Beneath 12" x 12" Floor Tile Mastic
109	Floor Tile Beneath 12" x 12" Floor Tile Mastic
164	12" x 12" Light Brown w/ White Specks Floor Tile
165M	12" x 12" Beige w/ Cream Specks Floor Tile Adhesive

166	Plaster
AE	Boiler Breeching
C	Preformed Pipe Insulation (Mag Block)

B. The following new homogenous areas have been identified for Building 1270:

185	12" x 12" Blue Mottled Vinyl Floor Tile
186	12" x 12" Blue Mottled Vinyl Floor Tile Mastic
187	12" x 12" Light Blue Mottled Vinyl Floor Tile
188	12" x 12" Light Blue Mottled Vinyl Floor Tile Mastic
189	12" x 12" Green Mottled Vinyl Floor Tile
190	12" x 12" Green Mottled Vinyl Floor Tile Mastic
191	12" x 12" Orange Mottled Vinyl Floor Tile
192	12" x 12" Orange Mottled Vinyl Floor Tile Mastic
193	12" x 12" Off-White Mottled Vinyl Floor Tile
194	12" x 12" Off-White Mottled Vinyl Floor Tile Mastic
195	12" x 12" Yellow Mottled Vinyl Floor Tile
196	12" x 12" Yellow Mottled Vinyl Floor Tile Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

002C	9" x 9" Reddish Brown Floor Tile
002D	9" x 9" Reddish Brown Floor Tile Mastic
003	Red Carpet Mastic
005	Wood Floor Underlayment
013	1' x 1' Fissured Ceiling Tile
014	1' x 1' Smooth Ceiling Tile
015	1' x 1' Dot Ceiling Tile
017	2' x 2' Ceiling Tile
019	2' x 2' Lay-in Ceiling Panels
051	12" x 12" Light Gray Floor Tile
052	12" x 12" Light Gray Floor Tile Mastic
058	Insulation Inside Of Fire Doors
068	12" x 12" Gray Floor Tile
068M	12" x 12" Gray Floor Tile Mastic
069	12" x 12" Cream Colored Floor Tile
072	12" x 12" Tan w/ White Specks Floor Tile
072M	12" x 12" Tan w/ White Specks Floor Tile Mastic
089	Roofing Material - Non-AHERA
097	Roof Caulking - Non-AHERA
10	2' x 4' Random Dot Lay-In Ceiling Panels
104	12" x 12" Beige w/ Brown Streaks Floor Tile
105	12" x 12" Beige w/ Brown Streaks Floor Tile Mastic
112	12" x 12" Aqua Floor Tile (Blue Linoleum)
113	12" x 12" Aqua Floor Tile Mastic (Blue Linoleum Mastic)
116	Tan Linoleum
117	Tan Linoleum Mastic
118	Brown Ceramic Flooring and Grout
119	Brown Ceramic Flooring Mastic
120	2' x 4' White Ceiling Tile
121	2' x 4' White Smooth Ceiling Tile
124	12" x 12" Off Beige Vinyl Floor Tile
125	12" x 12" Off Beige Vinyl Floor Tile Mastic
126	12" x 12" Old Blotted Beige Vinyl Floor Tile
127	12" x 12" Old Blotted Beige Vinyl Floor Tile Mastic
128	12" x 12" New Blotted Beige Vinyl Floor Tile
129	12" x 12" New Blotted Beige Vinyl Floor Tile Mastic
130	12" x 12" White w/ Gray Speckles Vinyl Floor Tile
131	12" x 12" White w/ Gray Speckles Vinyl Floor Tile Mastic
132	12" x 12" White w/ Brown Vinyl Floor Tile

133	12" x 12" White w/ Brown Vinyl Floor Tile Mastic
134	12" x 12" Off-White w/ Brown Vinyl Floor Tile
135	12" x 12" Off-White w/ Brown Vinyl Floor Tile Mastic
136	Blue Linoleum
137	Blue Linoleum Adhesive
138	12" x 12" Brown Texture Vinyl Floor Tile
139	12" x 12" Brown Texture Vinyl Floor Tile Mastic
140	12" x 12" Red Vinyl Floor Tile
141	12" x 12" Red Vinyl Floor Tile Mastic
142	12" x 12" Mustard Vinyl Floor Tile
143	12" x 12" Mustard Vinyl Floor Tile Mastic
144	White Sink Insulation
145	Trapezoid Lab Counters
146	3' x 5' Lab Counter
147	4' x 8' Lab Counters
148	12" x 12" Red Mottled Vinyl Floor Tile
149	12" x 12" Red Mottled Vinyl Floor Tile Mastic
150	Green Carpet Adhesive
151	12" x 12" Brown w/ Light Spots Floor Tile
152	12" x 12" Brown w/ Light Spots Floor Tile Mastic
153	12" x 12" Light Brown w/ Spots Floor Tile
154	12" x 12" Light Brown w/ Spots Floor Tile Mastic
155	12" x 12" Turquoise Floor Tile
156	12" x 12" Turquoise Floor Tile Mastic
157	12" x 12" Blue w/ Streaks Floor Tile
158	12" x 12" Blue w/ Streaks Floor Tile Mastic
159	2' x 2' Gray Carpet Square Glue
161	12" x 12" Blue w/ Blue Streaks Floor Tile
161M	12" x 12" Blue w/ Blue Streaks Floor Tile Mastic
162	12" x 12" Light Green w/ Streaks Floor Tile
162M	12" x 12" Light Green w/ Streaks Floor Tile Adhesive
163	12" x 12" White w/ Brown Specks Floor Tile
163M	12" x 12" White w/ Brown Specks Floor Tile Adhesive
164	12" x 12" Light Brown w/ White Specks Floor Tile
164M	12" x 12" Light Brown w/ White Specks Floor Tile Adhesive
165	12" x 12" Beige w/ Cream Specks Floor Tile
165M	12" x 12" Beige w/ Cream Specks Floor Tile Adhesive
166	Plaster
167	Plaster on Ceiling
168	12" x 12" Tan w/ Black Dots Vinyl Floor Tile
169	12" x 12" Black Floor Tile
170	12" x 12" Tan w/ Black Dots Vinyl Floor Tile Mastic

171	White w/ Brown Flower Design Acoustical Ceiling Tile
172	12" x 12" White w/ Black & Gray Speckled Vinyl Floor Tile
173	12" x 12" Gray w/ Black Speckled Vinyl Floor Tile
174	12" x 12" Blue w/ Black & Brown Speckled Vinyl Floor Tile
175	12" x 12" Blue w/ Black & Brown Speckled, Gray w/ Black Speckled, & White w/ Black & Gray Speckled Vinyl Floor Tile Mastic
176	12" x 12" White w/ Blue & Pink Streaks Floor Tile
177	12" x 12" White w/ Blue & Pink Streaks Floor Tile Mastic
178	Tongue and Groove Wooden Floor
179	12" x 12" White w/ Blue Streaks Floor Tile
180	12" x 12" White w/ Blue Streaks Floor Tile Mastic
181	12" x 12" Light Brown w/ Dark Brown and White Specks Floor Tile
182	12" x 12" Light Brown w/ Dark Brown and White Specks Floor Tile Mastic
183	Marble Flooring
184	12" x 12" Black Floor Tile Mastic
185	12" x 12" Blue Mottled Vinyl Floor Tile
186	12" x 12" Blue Mottled Vinyl Floor Tile Mastic
187	12" x 12" Light Blue Mottled Vinyl Floor Tile
188	12" x 12" Light Blue Mottled Vinyl Floor Tile Mastic
189	12" x 12" Green Mottled Vinyl Floor Tile
190	12" x 12" Green Mottled Vinyl Floor Tile Mastic
191	12" x 12" Orange Mottled Vinyl Floor Tile
192	12" x 12" Orange Mottled Vinyl Floor Tile Mastic
193	12" x 12" Off-White Mottled Vinyl Floor Tile
194	12" x 12" Off-White Mottled Vinyl Floor Tile Mastic
195	12" x 12" Yellow Mottled Vinyl Floor Tile
196	12" x 12" Yellow Mottled Vinyl Floor Tile Mastic
D	Aircell Pipe Insulation
F	Spray-on Fireproofing
G	Vault Door Liners
L	Hard Fittings on Aircell Pipe Insulation

The following areas were deemed to be inaccessible:

002D	9" x 9" Reddish Brown Floor Tile Mastic
005	Wood Floor Underlayment
011	Plaster Patch

013	1' x 1' Fissured Ceiling Tile
017	2' x 2' Ceiling Tile
052	12" x 12" Light Gray Floor Tile Mastic
058	Insulation Inside Of Fire Doors
068M	12" x 12" Gray Floor Tile Mastic
072M	12" x 12" Tan w/ White Specks Floor Tile Mastic
084	Plaster Soffit
10	2' x 4' Random Dot Lay-In Ceiling Panels
105	12" x 12" Beige w/ Brown Streaks Floor Tile Mastic
113	12" x 12" Aqua Floor Tile Mastic (Blue Linoleum Mastic)
117	Tan Linoleum Mastic
119	Brown Ceramic Flooring Mastic
125	12" x 12" Off Beige Vinyl Floor Tile Mastic
127	12" x 12" Old Blotted Beige Vinyl Floor Tile Mastic
129	12" x 12" New Blotted Beige Vinyl Floor Tile Mastic
131	12" x 12" White w/ Gray Speckles Vinyl Floor Tile Mastic
133	12" x 12" White w/ Brown Vinyl Floor Tile Mastic
135	12" x 12" Off-White w/ Brown Vinyl Floor Tile Mastic
137	Blue Linoleum Adhesive
139	12" x 12" Brown Texture Vinyl Floor Tile Mastic
141	12" x 12" Red Vinyl Floor Tile Mastic
143	12" x 12" Mustard Vinyl Floor Tile Mastic
149	12" x 12" Red Mottled Vinyl Floor Tile Mastic
150	Green Carpet Adhesive
152	12" x 12" Brown w/ Light Spots Floor Tile Mastic
154	12" x 12" Light Brown w/ Spots Floor Tile Mastic
156	12" x 12" Turquoise Floor Tile Mastic
158	12" x 12" Blue w/ Streaks Floor Tile Mastic
159	2' x 2' Gray Carpet Square Glue
161M	12" x 12" Blue w/ Blue Streaks Floor Tile Mastic
163M	12" x 12" White w/ Brown Specks Floor Tile Adhesive
164M	12" x 12" Light Brown w/ White Specks Floor Tile Adhesive
165M	12" x 12" Beige w/ Cream Specks Floor Tile Adhesive
171	White w/ Brown Flower Design Acoustical Ceiling Tile
186	12" x 12" Blue Mottled Vinyl Floor Tile Mastic
188	12" x 12" Light Blue Mottled Vinyl Floor Tile Mastic
190	12" x 12" Green Mottled Vinyl Floor Tile Mastic
192	12" x 12" Orange Mottled Vinyl Floor Tile Mastic
194	12" x 12" Off-White Mottled Vinyl Floor Tile

196	Mastic
C	12" x 12" Yellow Mottled Vinyl Floor Tile Mastic
F	Preformed Pipe Insulation (Mag Block)
	Spray-on Fireproofing

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Cody Cummins, IDPH License # 100-20994. The Management Plan was updated by Jackson Montgomery, IDPH License # 100-20634. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Crane Tech High School Building 1270 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Crane Tech High School Unit 46641 Building ID 1270

Address 2245 W. Jackson Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
001	12" x 12" Beige Floor Tile	7,000	SF	Throughout Facility (Auto Shop Hall, Room Next to the Pool, Engineer Office, Hall Outside 260)	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
001M	12" x 12" Beige Floor Tile Mastic	7,000	SF	Throughout Facility (Auto Shop Hall, Room Next to the Pool, Engineer Office, Hall Outside 260)	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
002A	9" x 9" Reddish Brown Floor Tile			ABATED	ABATED	MISC								
002A-M	9" x 9" Reddish Brown Floor Tile Mastic			ABATED	ABATED	MISC								
002B	9" x 9" Black Floor Tile			ABATED	ABATED	MISC								
002B-M	9" x 9" Black Floor Tile Mastic			ABATED	ABATED	MISC								
002C	9" x 9" Reddish Brown Floor Tile	250	SF	Storage Room Under Entrance 1	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		MODERATE
002D	9" x 9" Reddish Brown Floor Tile Mastic	250	SF	Storage Room Under Entrance 1	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
003	Red Carpet Mastic	3,000	SF	Library 207	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
004	Brown Carpet Mastic			Rooms 321, 206, and 413 Office, Police, and Bathroom	NO_ACBM	MISC								
005	Wood Floor Underlayment	2,000	SF	Gym	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
006	Matting			Running Track	NO_ACBM	MISC								
006M	Adhesive Beneath Matting			Running Track	NO_ACBM	MISC								
007	Painted Concrete - Non-AHERA				NO_ACBM	SURFACE								
008	Black/Gray Carpet Mastic			Clinic	NO_ACBM	MISC								
009	Grayish Brown Ceramic Tile Grout			Bathrooms	NO_ACBM	MISC								
010	2' x 4' Random Dot Lay-in Ceiling Panels			DUPLICATE HA							Yes			
011	Plaster Patch	100	SF	Outside of Cafeteria	CHR	SURFACE	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
012	1' x 1' Ceiling Tile			Pool Area	NO_ACBM	MISC								
013	1' x 1' Fissured Ceiling Tile	8,000	SF	Gym	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
014	1' x 1' Smooth Ceiling Tile	2,000	SF	Canteen & Kitchen	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW



# Chicago Public Schools

School Crane Tech High School Unit 46641 Building ID 1270

Address 2245 W. Jackson Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
031	Terrazzo Basins			1st, 2nd & 3rd Floor Maintenance Rooms	NO_ACBM	MISC								
032	White Terrazzo Flooring			1st, 2nd, and 3rd Floor Corridors	NO_ACBM	MISC								
033	Red Border Terrazzo			Corridors	NO_ACBM	MISC								
034	Multi-Brown Ceramic Tile Grout			4th Floor Womens Bathroom	NO_ACBM	MISC								
035	Orange Carpet Mastic			Rooms 307, 310, 313, and 413	NO_ACBM	MISC								
036	Gray Carpet Mastic			Lecture Rooms, Principal's Office, Main Office, and Security, 105, 103, 101	NO_ACBM	MISC								
037	Cementitious Gaskets			2nd Floor Fan Room	NO_ACBM	TSI								
038	Ceiling Tile Under Metal 1' x 1' Ceiling Tile			Above Pool Bleachers	NO_ACBM	MISC								
039	2' x 4' Random Dot Replacement Ceiling Panels			Fan Room #2	NO_ACBM	MISC								
040	Transite Sink Tops	200	SF	Rooms 315, 316, 317, 201, 210, 215, and 216	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
041	Black Material Coating Sink Bottoms	14	SF	Rooms 315, 316, 317, 201, 210, 215, and 216	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
042	Lab Table Tops			Rooms 300, 301, 315, 316, and 317	NO_ACBM	MISC								
043	Terrazzo Flooring			New Addition	NO_ACBM	MISC								
044	Blue Carpet Mastic			Auditorium	NO_ACBM	MISC								
045	Pink Carpet Mastic			Rooms 213 and 214, and Upper Library	NO_ACBM	MISC								
046	Cinder Block			New Addition - Gym	NO_ACBM	MISC								
047	Cinder Block Mortar			New Addition - Gym	NO_ACBM	MISC								
048	Adhesive Behind Mirrors	100	SF	Bathrooms	CHR	MISC					No			
049	Gray and White Linoleum			Rooms 201, 217, 300, and 301	NO_ACBM	MISC					Yes			
050	Gray and White Linoleum Mastic				CHR	MISC					Yes			
051	12" x 12" Light Gray Floor Tile	1,000	SF	Room 106	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
052	12" x 12" Light Gray Floor Tile Mastic	1,000	SF	Room 106	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
053	Fume Hood Interior Backing	25	SF	Rooms 316 and 317	CHR	MISC	N	NONE			No	ACBM with the		LOW

# Chicago Public Schools

School Crane Tech High School Unit 46641 Building ID 1270

Address 2245 W. Jackson Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
054	Kiln Gasket			Room 103	NO_ACBM	TSI								
055	Non Skid Strips			2nd Floor Ramp	NO_ACBM	MISC								
056	Interior Caulk	20	LF	Pool Room	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
057	Drywall			Cat Walk	NO_ACBM	SURFACE								
058	Insulation Inside Of Fire Doors	320	SF	Throughout Facility	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
059	Block			New Addition	NO_ACBM	SURFACE								
060	Block Mortar			New Addition	NO_ACBM	SURFACE								
062	Black Duct Sealant	150	LF	Tunnel	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
063	Chalkboard Adhesive			Running Track	NO_ACBM	MISC								
064	12" x 12" Brown Speckled Floor Tile			ABATED	ABATED	MISC								
064M	12" x 12" Brown Speckled Floor Tile Mastic			ABATED	ABATED	MISC								
065	12" x 12" Black Floor Tile			ABATED	ABATED	MISC								
065M	12" x 12" Black Floor Tile Mastic			ABATED	ABATED	MISC								
066	12" x 12" Dark Brown Floor Tile			ABATED	ABATED	MISC								
066M	12" x 12" Dark Brown Floor Tile Mastic			ABATED	ABATED	MISC								
067	12" x 12" Pink Floor Tile			ABATED	ABATED	MISC								
067M	12" x 12" Pink Floor Tile Mastic			ABATED	ABATED	MISC								
068	12" x 12" Gray Floor Tile	2,200	SF	Rooms 105, and 317, 206H	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
068M	12" x 12" Gray Floor Tile Mastic	2,200	SF	Rooms 105, and 317, 206H	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
069	12" x 12" Cream Colored Floor Tile	50,000	SF	Rooms 433, 435, 401, 443, 433, 440, 441, 420, 416, 414b, 437, 438, 439, 119, 426, 430, 402, 404, 432, 427, 431, 429, 450, 424, 419, 417, 410, 436, 153, 425, 421, 415, 414a, 400, 119b, 415, 103, 115, 117, 118, 406, 409, 420, 422, and 423, and Stage, 408, 407, 442, 434, 428, 309, 310, 308, Cafeteria, 311, 312, 313, 314,	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW



# Chicago Public Schools

School Crane Tech High School Unit 46641 Building ID 1270

Address 2245 W. Jackson Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
079	Blacktar on Outside Of Duct Insulation - Non-AHERA			Roof	CHR	MISC								
080	9" x 9" Reddish Brown Floor Tile			ABATED	ABATED	MISC								
081	9" x 9" Reddish Brown Floor Tile Mastic			ABATED	ABATED	MISC								
082	Exterior Transom Window Caulk - Non-AHERA			North Main Entrance	CHR	MISC								
083	Interior Transom Window Caulk	300	LF	North Main Entrance	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
084	Plaster Soffit	120	SF	South Entrance of New Addition	CHR	SURFACE	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
085	Roof Flashing - Layer 1 - Non-AHERA			New Addition Roof	CHR	MISC								
086	Roof Flashing - Layer 2 - Non-AHERA			New Addition Roof	CHR	MISC								
087	Roof Flashing - Layer 3 - Non-AHERA			New Addition Roof	CHR	MISC								
088	Roofing Material - Non-AHERA			New Addition Roof	CHR	MISC								
089	Roofing Material - Non-AHERA			Original Building	ASSUMED	MISC								
090	Roof Flashing - Non-AHERA			Original Building	NO_ACBM	SURFACE								
091	Decorative Columns - Non-AHERA			Roof	NO_ACBM	MISC								
092	Decorative Column Mastic/Mortar - Non-AHERA			Roof	NO_ACBM	MISC								
093	Exterior Red Face Brick - Non-AHERA			Roof	NO_ACBM	SURFACE								
094	Exterior Red Face Brick Mortar - Non-AHERA			Roof	NO_ACBM	SURFACE								
095	Interior Brick - Non-AHERA			Roof	NO_ACBM	MISC								
096	Interior Brick Mortar - Non-AHERA			Roof	NO_ACBM	MISC								
097	Roof Caulking - Non-AHERA			New Addition	ASSUMED	MISC								
098	Roofing Material - Non-AHERA			New Addition	NOT_TESTED	MISC								
099	Brick Mortar - Non-AHERA			New Addition	NO_ACBM	MISC								
10	2' x 4' Random Dot Lay-In Ceiling Panels	20,000	SF	4th Floor Hallway, Rooms 409, 430, 414A, 408, 407, 406, 404, 405, 403, 402, 401, 400, 443, 442, 441, 440, 439, 438, 437, 436, 435, 434, 433, 432, 427, 431, 428, 430, 450, 3rd Floor Hallway, Rooms 310, 308, 311, 312, 313, 314, 315, 317, 317A, 316, 350C, 350C.	ASSUMED	MISC	Y	LOC	3	SF	No	Damaged or significantly damaged friable misc. ACBM	5	LOW

# Chicago Public Schools

School Crane Tech High School Unit 46641 Building ID 1270

Address 2245 W. Jackson Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				350B, 300, 301, 302, 302A, 302B, 303, 305, 306, 307, 307C, Metro Director Office, Rooms 416, 417, 419, 418, 421, 420, 422, 423, 425, 213, 214, 215, 216, 217, 218, 219, 200, 201, 202, 203, 204, 205, 206A, 206, Library 207, 260, 260A, 261, 114D, 114, 115, Engineers Office										
100	Exterior Window Caulk - Non-AHERA			Building Exterior	NO_ACBM	MISC								
101	Exterior Door Caulk - Non-AHERA			Building Addition Exterior	NO_ACBM	MISC								
103	Tar Paper Over Roof Ducts Non-AHERA			Exterior Roof	CHR	MISC								
104	12" x 12" Beige w/ Brown Streaks Floor Tile	900	SF	Room 415	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
105	12" x 12" Beige w/ Brown Streaks Floor Tile Mastic	900	SF	Room 415	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
106	Floor Tile Beneath 12" x 12" Floor Tile			ABATED	ABATED	MISC								
107	Floor Tile Beneath 12" x 12" Floor Tile Mastic			ABATED	ABATED	MISC					Yes			
108	Floor Tile Beneath 12" x 12" Floor Tile			ABATED	ABATED	MISC								
109	Floor Tile Beneath 12" x 12" Floor Tile Mastic			ABATED	ABATED	MISC					Yes			
110	Floor Tile Beneath 12" x 12" Floor Tile	4,000	SF	Cafeteria/Lunchroom	CHR	MISC					No			
111	Floor Tile Beneath 12" x 12" Floor Tile Mastic	2,000	SF	Cafeteria/Lunchroom	CHR	MISC					No			
112	12" x 12" Aqua Floor Tile (Blue Linoleum)	400	SF	Room 218	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
113	12" x 12" Aqua Floor Tile Mastic (Blue Linoleum Mastic)	400	SF	Room 218	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
114	Floor Tile Beneath 12" x 12" Floor Tile	1,550	SF	Rooms 210 and 212	CHR	MISC					No			
115	Floor Tile Beneath 12" x 12" Floor Tile Mastic	1,550	SF	Rooms 210 and 212	CHR	MISC					No			
116	Tan Linoleum	4,000	SF	Rooms 315, 316, 302, 301, 201 Storage 215, 302A, 302B,	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Crane Tech High School Unit 46641 Building ID 1270

Address 2245 W. Jackson Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
117	Tan Linoleum Mastic	4,000	SF	Rooms 315, 316, 302, 301, 201 Storage 215, 302A, 302B.	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
118	Brown Ceramic Flooring and Grout	8,000	SF	1, 2, 3, 4, Floors Boys & Girls Bathrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
119	Brown Ceramic Flooring Mastic	8,000	SF	1, 2, 3, 4, Floors Boys & Girls Bathrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
120	2' x 4' White Ceiling Tile	200,000	SF	Throughout School	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
121	2' x 4' White Smooth Ceiling Tile	12,300	SF	Cafeteria, Room 412	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
124	12" x 12" Off Beige Vinyl Floor Tile	900	SF	Room 119	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
125	12" x 12" Off Beige Vinyl Floor Tile Mastic	900	SF	Room 119	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
126	12" x 12" Old Blotted Beige Vinyl Floor Tile	2,000	SF	Room 118, Band Hall	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
127	12" x 12" Old Blotted Beige Vinyl Floor Tile Mastic	2,000	SF	Room 118, Band Hall	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
128	12" x 12" New Blotted Beige Vinyl Floor Tile	800	SF	Room 118	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
129	12" x 12" New Blotted Beige Vinyl Floor Tile Mastic	800	SF	Room 118	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
130	12" x 12" White w/ Gray Speckles Vinyl Floor Tile	2,000	SF	Gym Office, 310 Offices, 307, 307, 307C, Metro Director Office.	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
131	12" x 12" White w/ Gray Speckles Vinyl Floor Tile Mastic	2,000	SF	Gym Office, 310 Offices, 307, 307, 307C, Metro Director Office.	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
132	12" x 12" White w/ Brown Vinyl Floor Tile	500	SF	Choral Room 119	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
133	12" x 12" White w/ Brown Vinyl Floor Tile Mastic	500	SF	Choral Room 119	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
134	12" x 12" Off-White w/ Brown Vinyl Floor Tile	300	SF	Choral Room 119 Office	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
135	12" x 12" Off-White w/ Brown Vinyl Floor Tile Mastic	300	SF	Choral Room 119 Office	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Crane Tech High School Unit 46641 Building ID 1270

Address 2245 W. Jackson Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
136	Blue Linoleum	1,200	SF	Room 109, 110	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
137	Blue Linoleum Adhesive	1,200	SF	Room 109, 110	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
138	12" x 12" Brown Texture Vinyl Floor Tile	500	SF	Ramp Outside the Library	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
139	12" x 12" Brown Texture Vinyl Floor Tile Mastic	500	SF	Ramp Outside the Library	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
140	12" x 12" Red Vinyl Floor Tile	65,000	SF	2nd, 3rd, and 4th Floors Corridors	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
141	12" x 12" Red Vinyl Floor Tile Mastic	65,000	SF	2nd, 3rd, and 4th Floor Corridors	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
142	12" x 12" Mustard Vinyl Floor Tile	1,000	SF	Room 260, 260A	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
143	12" x 12" Mustard Vinyl Floor Tile Mastic	1,000	SF	Room 260, 260A	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
144	White Sink Insulation	2		Room 210	ASSUMED	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
145	Trapezoid Lab Counters	80		Room 215, 216, 315, 316	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
146	3' x 5' Lab Counter	20		Room 318	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
147	4' x 8' Lab Counters	20		Room 103, 102	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
148	12" x 12" Red Mottled Vinyl Floor Tile	2,000	SF	Room 411, 412, 413, 261	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
149	12" x 12" Red Mottled Vinyl Floor Tile Mastic	2,000	SF	Room 411, 412, 413, 261	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
150	Green Carpet Adhesive	1,500	SF	Room 108, 219,	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
151	12" x 12" Brown w/ Light Spots Floor Tile	5,000	SF	West Elevator Lobby, 1st Floor MDF Room, Rooms 403, 405, 205, 205a, 200, West Med Room, 2nd Floor Hallway, Lecture Hallway, 440a, 219, Storage Across Room 400, 3rd Floor Kitchen Staff Bathroom, 2nd Floor Storage by West	ASSUMED	MISC	N	LOC	40	SF	No	ACBM with potential for significant damage	3	LOW

# Chicago Public Schools

School Crane Tech High School Unit 46641 Building ID 1270

Address 2245 W. Jackson Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Elevators, 114D										
152	12" x 12" Brown w/ Light Spots Floor Tile Mastic	5,000	SF	West Elevator Lobby, 1st Floor Mdf Room, Rooms 403, 405, 205, 205a, 200, West Med Room, 2nd Floor Hallway, Lecture Hallway, 440a, 219, Storage Across Room 400, 3rd Floor Kitchen Staff Bathroom, 2nd Floor Storage by West Elevators, 114D.	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
153	12" x 12" Light Brown w/ Spots Floor Tile	8,000	SF	Rooms 312, 313, 300, 303-306, 201, 211, 213, 214, 250, 216, 217, 251, 200, 201-204, 114D	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
154	12" x 12" Light Brown w/ Spots Floor Tile Mastic	8,000	SF	Rooms 312, 313, 300, 303-306, 201, 211, 213, 214, 250, 216, 217, 251, 200, 201-204, 114D	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
155	12" x 12" Turquoise Floor Tile	250	SF	Room 206a	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
156	12" x 12" Turquoise Floor Tile Mastic	250	SF	Room 206a	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
157	12" x 12" Blue w/ Streaks Floor Tile	300	SF	Room 101 Kitchen	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
158	12" x 12" Blue w/ Streaks Floor Tile Mastic	300	SF	Room 101 Kitchen	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
159	2' x 2' Gray Carpet Square Glue	700	SF	Rooms 103 and 105	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
16	Zinc			First Floor Hall	NOT_TEST ED	MISC								
161	12" x 12" Blue w/ Blue Streaks Floor Tile	150	SF	2nd Floor Faculty Lounge	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		MODERATE
161M	12" x 12" Blue w/ Blue Streaks Floor Tile Mastic	150	SF	2nd Floor Faculty Lounge	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
162	12" x 12" Light Green w/ Streaks Floor Tile	70	SF	Foyer Outside Rooms 218, 209	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		MODERATE
162M	12" x 12" Light Green w/ Streaks Floor Tile	70	SF	Foyer Outside Room	ASSUMED	MISC	N	NONE			No	ACBM with the		LOW

# Chicago Public Schools

School Crane Tech High School Unit 46641 Building ID 1270

Address 2245 W. Jackson Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Adhesive			218, 209								potential for damage		
163	12" x 12" White w/ Brown Specks Floor Tile	300	SF	Room 212, Main Office, 214 (Patches)	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		MODERATE
163M	12" x 12" White w/ Brown Specks Floor Tile Adhesive	300	SF	Room 212, Main Office, 214 (Patches)	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
164	12" x 12" Light Brown w/ White Specks Floor Tile	100	SF	201a, Security Office	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		MODERATE
164M	12" x 12" Light Brown w/ White Specks Floor Tile Adhesive	100	SF	201a, Security Office	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
165	12" x 12" Beige w/ Cream Specks Floor Tile	100	SF	Kitchen Storage Room, Security Office	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		MODERATE
165M	12" x 12" Beige w/ Cream Specks Floor Tile Adhesive	100	SF	Kitchen Storage Room, Security Office	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
166	Plaster	1,000	SF	4th Floor Hallway, 412, 411, 410, 409, 414A, 408, 407, 406, 405, 404, 403, 402, 401, 400, 443, 442, 441, 440, 439, 438, 437, 436, 435, 434, 433, 432, 427, 431, 428, 430, 450, 3rd Floor Hallway, 309, 310, 308, Cafeteria, 311, 312, 313, 314, 315, 317, 317A, 316, 350C, 321, 350A, 350B, 300, 301, 302, 302A, 302B, 303, 305, 306, 307, 416, 417, 419, 418, 421, 420, 422, 423, 425, 213, 215, 216, 217, 218, 200, 201, 202, 203, 204, 205, 206A, 206, Library 207, 260, 260A, 261, 114D, 114, 115, Engineers Office	ASSUMED	SURFACE	Y	DIST	45	SF	Yes	Damaged friable surfacing ACBM	3	MODERATE

# Chicago Public Schools

School Crane Tech High School Unit 46641 Building ID 1270

Address 2245 W. Jackson Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
167	Plaster on Ceiling	1,000	SF	Basement	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		MODERATE
168	12" x 12" Tan w/ Black Dots Vinyl Floor Tile	5,000	SF	Room 321	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
169	12" x 12" Black Floor Tile	5,000	SF	Room 321	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
170	12" x 12" Tan w/ Black Dots Vinyl Floor Tile Mastic	10,000	SF	Room 321	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
171	White w/ Brown Flower Design Acoustical Ceiling Tile	5,000	SF	Room 321	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
172	12" x 12" White w/ Black & Gray Speckled Vinyl Floor Tile	1,200	SF	Rooms 301, 215, 202	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
173	12" x 12" Gray w/ Black Speckled Vinyl Floor Tile	1,200	SF	Rooms 301, 215, 202	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
174	12" x 12" Blue w/ Black & Brown Speckled Vinyl Floor Tile	1,200	SF	Rooms 301, 215, 202	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
175	12" x 12" Blue w/ Black & Brown Speckled, Gray w/ Black Speckled, & White w/ Black & Gray Speckled Vinyl Floor Tile Mastic	3,600	SF	Rooms 301, 215, 202	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
176	12" x 12" White w/ Blue & Pink Streaks Floor Tile	1,200	SF	Room 209	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
177	12" x 12" White w/ Blue & Pink Streaks Floor Tile Mastic	1,200	SF	Room 209	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
178	Tongue and Groove Wooden Floor	5,000	SF	Gymnasium, 163 Gym	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
179	12" x 12" White w/ Blue Streaks Floor Tile	2,000	SF	Room 261	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
180	12" x 12" White w/ Blue Streaks Floor Tile Mastic	2,000	SF	Room 261	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
181	12" x 12" Light Brown w/ Dark Brown and White Specks Floor Tile	500	SF	Room 261	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
182	12" x 12" Light Brown w/ Dark Brown and White Specks Floor Tile Mastic	500	SF	Room 261	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
183	Marble Flooring	2,000	SF	1st Floor Corridor Entrance	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
184	12" x 12" Black Floor Tile Mastic	5,000	SF	Room 321	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
185	12" x 12" Blue Mottled Vinyl Floor Tile	800	SF	Rooms 261, 412	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
186	12" x 12" Blue Mottled Vinyl Floor Tile Mastic	800	SF	Rooms 261, 412	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
187	12" x 12" Light Blue Mottled Vinyl Floor Tile	400	SF	Rooms 412, 411	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW







# Chicago Public Schools

School Crane Tech High School Unit 46641 Building ID 1270

Address 2245 W. Jackson Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>5/30/2025</b>
Inspector Name <b>Cody Cummins</b>
<b>100-20994</b> <b>5/15/2026</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
001	
001M	
002A	
002A-M	
002B	
002B-M	
002C	
002D	
003	
004	
005	
006	
006M	
007	
008	
009	
010	
011	
012	
013	Not found in library
014	
015	
016	Material not observed - 2025
017	

# Chicago Public Schools

School Crane Tech High School Unit 46641 Building ID 1270

Address 2245 W. Jackson Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
019	
020	Material not observed - 2025
021	
022	
022M	
023M	
024	
024M	
025	
025M	
026	
026M	
027	
027M	
028	
028M	
029	
029M	
030	
031	
032	
033	
034	
035	
036	
037	
038	
039	
040	

# Chicago Public Schools

School Crane Tech High School Unit 46641 Building ID 1270

Address 2245 W. Jackson Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
041	
042	
043	
044	
045	
046	
047	
048	Material in inaccessible area(s) - 2025
049	
050	Material not observed - 2025
051	
052	
053	
054	
055	
056	
057	
058	
059	
060	
062	
063	
064	
064M	
065	
065M	
066	
066M	
067	

# Chicago Public Schools

School Crane Tech High School Unit 46641 Building ID 1270

Address 2245 W. Jackson Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
067M	
068	Not found in 315, 316
068M	Not found in 315, 316
069	Not found in 116, 101
069M	Not found in 116, 101
070	
070M	
071	
072	
072M	
073	
073M	
074	
074M	
075	
076	Material in inaccessible area(s) - 2025 Beneath Existing Carpet
076M	
077	
077M	
078	
078M	
079	
080	
081	
082	
083	
084	
085	

# Chicago Public Schools

School Crane Tech High School Unit 46641 Building ID 1270

Address 2245 W. Jackson Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
086	
087	
088	
089	
090	
091	
092	
093	
094	
095	
096	
097	
098	
099	
10	Damage in 430
100	
101	
103	
104	
105	
106	
107	
108	
109	
110	Material in inaccessible area(s) - 2025 Beneath Existing Tile
111	Material in inaccessible area(s) - 2025 Beneath Existing Floor Tile
112	

# Chicago Public Schools

School Crane Tech High School Unit 46641 Building ID 1270

Address 2245 W. Jackson Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
113	
114	Material in inaccessible area(s) - 2025 Beneath Existing Tile
115	Material in inaccessible area(s) - 2025 Beneath Existing Tile
116	
117	
118	
119	
120	
121	
124	
125	
126	Not found in 116, 117
127	Not found in 116, 117
128	Not found in 116, 117
129	Not found in 116, 117
130	
131	
132	
133	
134	
135	
136	
137	
138	
139	
140	
141	

# Chicago Public Schools

School Crane Tech High School Unit 46641 Building ID 1270

Address 2245 W. Jackson Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
142	
143	
144	
145	
146	
147	
148	
149	
150	
151	Damage in 405
152	
153	
154	
155	
156	
157	
158	
159	
16	Material not observed - 2025
161	
161M	
162	
162M	
163	
163M	
164	
164M	
165	
165M	

# Chicago Public Schools

School Crane Tech High School Unit 46641 Building ID 1270

Address 2245 W. Jackson Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
166	Damage found in: Room 405, First Floor Southwest Hallway Near Elevator
167	
168	
169	
170	
171	
172	
173	
174	
175	
176	
177	
178	
179	
180	
181	
182	
183	
184	
185	
186	
187	
188	
189	
190	
191	
192	
193	
194	

# Chicago Public Schools

School Crane Tech High School Unit 46641 Building ID 1270

Address 2245 W. Jackson Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
195	
196	
20	Material not observed - 2025
23	
76	Material in inaccessible area(s) - 2025 Beneath Existing Carpet
A	
AA	
AB	
AC	
AD	
AE	
AF	
AG	
AH	
AI	
AJ	
AK	
B	Material not observed - 2025
C	
D	
E	
F	
G	
H	
I	
J	
K	
L	

# Chicago Public Schools

School Crane Tech High School Unit 46641 Building ID 1270

Address 2245 W. Jackson Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
M	Material not observed - 2025
N	
O	
P	
Q	
R	
S	
T	
U	
V	
W	
X	
Y	
Z	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Crane Tech High School

Unit 46641

Building ID 1270

Address 2245 W. Jackson

Chicago, IL, 60612

Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
001	12" x 12" Beige Floor Tile	7,000	SF	Throughout Facility (Auto Shop Hall, Room Next to the Pool, Engineer Office, Hall Outside 260)	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
001M	12" x 12" Beige Floor Tile Mastic	7,000	SF	Throughout Facility (Auto Shop Hall, Room Next to the Pool, Engineer Office, Hall Outside 260)	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
002A	9" x 9" Reddish Brown Floor Tile			ABATED	Abated	MISC					
002A-M	9" x 9" Reddish Brown Floor Tile Mastic			ABATED	Abated	MISC					
002B	9" x 9" Black Floor Tile			ABATED	Abated	MISC					
002B-M	9" x 9" Black Floor Tile Mastic			ABATED	Abated	MISC					
002C	9" x 9" Reddish Brown Floor Tile	250	SF	Storage Room Under Entrance 1	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
002D	9" x 9" Reddish Brown Floor Tile Mastic	250	SF	Storage Room Under Entrance 1	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
003	Red Carpet Mastic	3,000	SF	Library 207	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
004	Brown Carpet Mastic			Rooms 321, 206, and 413 Office, Police, and Bathroom	No ACBM	MISC					
005	Wood Floor Underlayment	2,000	SF	Gym	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
006	Matting			Running Track	No ACBM	MISC					
006M	Adhesive Beneath Matting			Running Track	No ACBM	MISC					
007	Painted Concrete - Non-AHERA				No ACBM	SURFACE					
008	Black/Gray Carpet Mastic			Clinic	No ACBM	MISC					
009	Grayish Brown Ceramic Tile Grout			Bathrooms	No ACBM	MISC					
010	2' x 4' Random Dot Lay-in Ceiling Panels			DUPLICATE HA							
011	Plaster Patch	100	SF	Outside of Cafeteria	Chrysotile	SURFACE	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
012	1' x 1' Ceiling Tile			Pool Area	No ACBM	MISC					
013	1' x 1' Fissured Ceiling Tile	8,000	SF	Gym	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
014	1' x 1' Smooth Ceiling Tile	2,000	SF	Canteen & Kitchen	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
015	1' x 1' Dot Ceiling Tile	1,500	SF	Band & Canteen	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
016	Zinc			First Floor Hall	Not Tested	MISC					
017	2' x 2' Ceiling Tile	20,000	SF	Pool, 2nd Floor South Hallway	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
019	2' x 2' Lay-in Ceiling Panels	500	SF	Clinic (110)	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

# Chicago Public Schools

**School** Crane Tech High School

**Unit** 46641

**Building ID** 1270

**Address** 2245 W. Jackson

Chicago, IL, 60612

**Region**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
020	Paint (Not Textured)			Throughout Facility	Not Tested	MISC					
021	Wall Plaques			ABATED	Abated	MISC					
022	4" Baseboard			Throughout Original Building	No ACBM	MISC					
022M	4" Baseboard Adhesive			Throughout Original Building	No ACBM	MISC					
023M	6" Baseboard Mastic			Throughout Original Building	No ACBM	MISC					
024	90 De. Baseboard			Auditorium	No ACBM	MISC					
024M	90 De. Baseboard Mastic			Auditorium	No ACBM	MISC					
025	4" Brown Baseboard			New Addition Gym and Corridor	No ACBM	MISC					
025M	4" Brown Baseboard Mastic			New Addition Gym and Corridor	No ACBM	MISC					
026	6" Brown Baseboard			Hall and Room 106	No ACBM	MISC					
026M	6" Brown Baseboard Mastic			Hall and Room 106	No ACBM	MISC					
027	Interior Brick			Throughout Original Building	No ACBM	MISC					
027M	Interior Brick Mortar			Throughout Original Building	No ACBM	MISC					
028	Cinder Block			Throughout Original Building	No ACBM	MISC					
028M	Cinder Block Mortar			Throughout Original Building	No ACBM	MISC					
029	Glazed Brick			Original Building - Gym, 2nd Floor Fan Room	No ACBM	MISC					
029M	Glazed Brick Mortar			Original Building - Gym and 2nd Floor Fan Room	No ACBM	MISC					
030	Water Tank			Pool Maintenance Area	No ACBM	MISC					
031	Terrazzo Basins			1st, 2nd & 3rd Floor Maintenance Rooms	No ACBM	MISC					
032	White Terrazzo Flooring			1st, 2nd, and 3rd Floor Corridors	No ACBM	MISC					
033	Red Border Terrazzo			Corridors	No ACBM	MISC					
034	Multi-Brown Ceramic Tile Grout			4th Floor Womens Bathroom	No ACBM	MISC					
035	Orange Carpet Mastic			Rooms 307, 310, 313, and 413	No ACBM	MISC					
036	Gray Carpet Mastic			Lecture Rooms, Principal's Office, Main Office, and Security, 105, 103, 101	No ACBM	MISC					
037	Cementitious Gaskets			2nd Floor Fan Room	No ACBM	TSI					
038	Ceiling Tile Under Metal 1' x 1' Ceiling Tile			Above Pool Bleachers	No ACBM	MISC					
039	2' x 4' Random Dot Replacement Ceiling Panels			Fan Room #2	No ACBM	MISC					
040	Transite Sink Tops	200	SF	Rooms 315, 316, 317, 201, 210, 215, and 216	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
041	Black Material Coating Sink Bottoms	14	SF	Rooms 315, 316, 317, 201, 210, 215, and 216	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Crane Tech High School

Unit 46641

Building ID 1270

Address 2245 W. Jackson

Chicago, IL, 60612

Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
042	Lab Table Tops			Rooms 300, 301, 315, 316, and 317	No ACBM	MISC					
043	Terrazzo Flooring			New Addition	No ACBM	MISC					
044	Blue Carpet Mastic			Auditorium	No ACBM	MISC					
045	Pink Carpet Mastic			Rooms 213 and 214, and Upper Library	No ACBM	MISC					
046	Cinder Block			New Addition - Gym	No ACBM	MISC					
047	Cinder Block Mortar			New Addition - Gym	No ACBM	MISC					
048	Adhesive Behind Mirrors	100	SF	Bathrooms	Chrysotile	MISC			SF		Follow O&M Plan
049	Gray and White Linoleum			Rooms 201, 217, 300, and 301	No ACBM	MISC					
050	Gray and White Linoleum Mastic				Chrysotile	MISC					
051	12" x 12" Light Gray Floor Tile	1,000	SF	Room 106	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
052	12" x 12" Light Gray Floor Tile Mastic	1,000	SF	Room 106	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
053	Fume Hood Interior Backing	25	SF	Rooms 316 and 317	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
054	Kiln Gasket			Room 103	No ACBM	TSI					
055	Non Skid Strips			2nd Floor Ramp	No ACBM	MISC					
056	Interior Caulk	20	LF	Pool Room	Chrysotile	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
057	Drywall			Cat Walk	No ACBM	SURFACE					
058	Insulation Inside Of Fire Doors	320	SF	Throughout Facility	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
059	Block			New Addition	No ACBM	SURFACE					
060	Block Mortar			New Addition	No ACBM	SURFACE					
062	Black Duct Sealant	150	LF	Tunnel	Chrysotile	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
063	Chalkboard Adhesive			Running Track	No ACBM	MISC					
064	12" x 12" Brown Speckled Floor Tile			ABATED	Abated	MISC					
064M	12" x 12" Brown Speckled Floor Tile Mastic			ABATED	Abated	MISC					
065	12" x 12" Black Floor Tile			ABATED	Abated	MISC					
065M	12" x 12" Black Floor Tile Mastic			ABATED	Abated	MISC					
066	12" x 12" Dark Brown Floor Tile			ABATED	Abated	MISC					
066M	12" x 12" Dark Brown Floor Tile Mastic			ABATED	Abated	MISC					
067	12" x 12" Pink Floor Tile			ABATED	Abated	MISC					
067M	12" x 12" Pink Floor Tile Mastic			ABATED	Abated	MISC					
068	12" x 12" Gray Floor Tile	2,200	SF	Rooms 105, and 317, 206H	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
068M	12" x 12" Gray Floor Tile Mastic	2,200	SF	Rooms 105, and 317, 206H	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
069	12" x 12" Cream Colored Floor Tile	50,000	SF	Rooms 433, 435, 401, 443, 433, 440, 441, 420, 416, 414b, 437, 438, 439, 119, 426, 430, 402, 404, 432, 427, 431,	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Crane Tech High School

Unit 46641

Building ID 1270

Address 2245 W. Jackson

Chicago, IL, 60612

Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				429, 450, 424, 419, 417, 410, 436, 153, 425, 421, 415, 414a, 400, 119b, 415, 103, 115, 117, 118, 406, 409, 420, 422, and 423, and Stage, 408, 407, 442, 434, 428, 309, 310, 308, Cafeteria, 311, 312, 313, 314, 300, 303, 305, 306, 418, 423, 213, 203,							
069M	12" x 12" Cream Colored Floor Tile Mastic	50,000	SF	Rooms 433, 435, 401, 443, 433, 440, 441, 420, 416, 414b, 437, 438, 439, 119, 426, 430, 402, 404, 432, 427, 431, 429, 450, 424, 419, 417, 410, 436, 153, 425, 421, 415, 414a, 400, 119b, 415, 103, 115, 117, 118, 406, 409, 420, 422, and 423, and Stage, 408, 407, 442, 434, 428, 309, 310, 308, Cafeteria, 311, 312, 313, 314, 300, 303, 305, 306, 418, 423, 213, 203,	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
070	9" x 9" Tan Floor Tile w/ Brown Streaks			ABATED	Abated	MISC					
070M	9" x 9" Tan Floor Tile w/ Brown Streaks Mastic			ABATED	Abated	MISC					
071	Adhesive Backing on Fiberglass Insulation Panels			Hall, Rooms 51a and 51b	No ACBM	TSI					
072	12" x 12" Tan w/ White Specks Floor Tile	400	SF	Room 104	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
072M	12" x 12" Tan w/ White Specks Floor Tile Mastic	400	SF	Room 104	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
073	Floor Tile Beneath 12" x 12" Floor Tile			ABATED	Abated	MISC					
073M	Mastic on Floor Tile Beneath 12" x 12" Floor Tile			ABATED	Abated	MISC					
074	Linoleum (Beneath Carpet)			Room 321	No ACBM	MISC					
074M	Linoleum Mastic			Room 321	No ACBM	MISC					
075	Terrazzo			Stairway, 1-2, 2-3, 3-4	No ACBM	MISC					
076	Material Under Carpet			Room 413	Chrysotile	MISC					
076M	Adhesive For Material Under Carpet			Room 413	No ACBM	MISC					
077	Interior Brick			New Addition Corridor	No ACBM	MISC					
077M	Interior Brick Mortar			New Addition Corridor	No ACBM	MISC					
078	Glazed Brick			Pool Room Walls	No ACBM	MISC					
078M	Glazed Brick Mortar			Pool Room Walls	No ACBM	MISC					
079	Blacktar on Outside Of Duct Insulation - Non-AHERA			Roof	Chrysotile	MISC					
080	9" x 9" Reddish Brown Floor Tile			ABATED	Abated	MISC					

# Chicago Public Schools

School Crane Tech High School

Unit 46641

Building ID 1270

Address 2245 W. Jackson

Chicago, IL, 60612

Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
081	9" x 9" Reddish Brown Floor Tile Mastic			ABATED	Abated	MISC					
082	Exterior Transom Window Caulk - Non-AHERA			North Main Entrance	Chrysotile	MISC					
083	Interior Transom Window Caulk	300	LF	North Main Entrance	Chrysotile	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
084	Plaster Soffit	120	SF	South Entrance of New Addition	Chrysotile	SURFACE	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
085	Roof Flashing - Layer 1 - Non-AHERA			New Addition Roof	Chrysotile	MISC					
086	Roof Flashing - Layer 2 - Non-AHERA			New Addition Roof	Chrysotile	MISC					
087	Roof Flashing - Layer 3 - Non-AHERA			New Addition Roof	Chrysotile	MISC					
088	Roofing Material - Non-AHERA			New Addition Roof	Chrysotile	MISC					
089	Roofing Material - Non-AHERA			Original Building	Assumed	MISC					
090	Roof Flashing - Non-AHERA			Original Building	No ACBM	SURFACE					
091	Decorative Columns - Non-AHERA			Roof	No ACBM	MISC					
092	Decorative Column Mastic/Mortar - Non-AHERA			Roof	No ACBM	MISC					
093	Exterior Red Face Brick - Non-AHERA			Roof	No ACBM	SURFACE					
094	Exterior Red Face Brick Mortar - Non-AHERA			Roof	No ACBM	SURFACE					
095	Interior Brick - Non-AHERA			Roof	No ACBM	MISC					
096	Interior Brick Mortar - Non-AHERA			Roof	No ACBM	MISC					
097	Roof Caulking - Non-AHERA			New Addition	Assumed	MISC					
098	Roofing Material - Non-AHERA			New Addition	Not Tested	MISC					Follow O&M Plan
099	Brick Mortar - Non-AHERA			New Addition	No ACBM	MISC					
10	2' x 4' Random Dot Lay-In Ceiling Panels	20,000	SF	4th Floor Hallway, Rooms 409, 430, 414A, 408, 407, 406, 404, 405, 403, 402, 401, 400, 443, 442, 441, 440, 439, 438, 437, 436, 435, 434, 433, 432, 427, 431, 428, 430, 450, 3rd Floor Hallway, Rooms 310, 308, 311, 312, 313, 314, 315, 317, 317A, 316, 350C, 350C, 350B, 300, 301, 302, 302A, 302B, 303, 305, 306, 307, 307C, Metro Director Office, Rooms 416, 417, 419, 418, 421, 420, 422, 423, 425, 213, 214, 215, 216, 217, 218, 219, 200, 201, 202, 203, 204, 205, 206A, 206, Library 207, 260, 260A, 261, 114D, 114, 115, Engineers Office	Assumed	MISC	Yes	3	SF	4 Damaged or significantly damaged friable misc. ACBM	Remove
100	Exterior Window Caulk - Non-AHERA			Building Exterior	No ACBM	MISC					

# Chicago Public Schools

School Crane Tech High School

Unit 46641

Building ID 1270

Address 2245 W. Jackson

Chicago, IL, 60612

Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
101	Exterior Door Caulk - Non-AHERA			Building Addition Exterior	No ACBM	MISC					
103	Tar Paper Over Roof Ducts Non-AHERA			Exterior Roof	Chrysotile	MISC					
104	12" x 12" Beige w/ Brown Streaks Floor Tile	900	SF	Room 415	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
105	12" x 12" Beige w/ Brown Streaks Floor Tile Mastic	900	SF	Room 415	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
106	Floor Tile Beneath 12" x 12" Floor Tile			ABATED	Abated	MISC					
107	Floor Tile Beneath 12" x 12" Floor Tile Mastic			ABATED	Abated	MISC					
108	Floor Tile Beneath 12" x 12" Floor Tile			ABATED	Abated	MISC					
109	Floor Tile Beneath 12" x 12" Floor Tile Mastic			ABATED	Abated	MISC					
110	Floor Tile Beneath 12" x 12" Floor Tile	4,000	SF	Cafeteria/Lunchroom	Chrysotile	MISC			SF		Follow O&M Plan
111	Floor Tile Beneath 12" x 12" Floor Tile Mastic	2,000	SF	Cafeteria/Lunchroom	Chrysotile	MISC			SF		Follow O&M Plan
112	12" x 12" Aqua Floor Tile (Blue Linoleum)	400	SF	Room 218	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
113	12" x 12" Aqua Floor Tile Mastic (Blue Linoleum Mastic)	400	SF	Room 218	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
114	Floor Tile Beneath 12" x 12" Floor Tile	1,550	SF	Rooms 210 and 212	Chrysotile	MISC			SF		Follow O&M Plan
115	Floor Tile Beneath 12" x 12" Floor Tile Mastic	1,550	SF	Rooms 210 and 212	Chrysotile	MISC			SF		Follow O&M Plan
116	Tan Linoleum	4,000	SF	Rooms 315, 316, 302, 301, 201 Storage 215, 302A, 302B,	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
117	Tan Linoleum Mastic	4,000	SF	Rooms 315, 316, 302, 301, 201 Storage 215, 302A, 302B,	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
118	Brown Ceramic Flooring and Grout	8,000	SF	1, 2, 3, 4, Floors Boys & Girls Bathrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
119	Brown Ceramic Flooring Mastic	8,000	SF	1, 2, 3, 4, Floors Boys & Girls Bathrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
120	2' x 4' White Ceiling Tile	200,000	SF	Throughout School	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
121	2' x 4' White Smooth Ceiling Tile	12,300	SF	Cafeteria, Room 412	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
124	12" x 12" Off Beige Vinyl Floor Tile	900	SF	Room 119	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
125	12" x 12" Off Beige Vinyl Floor Tile Mastic	900	SF	Room 119	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
126	12" x 12" Old Blotted Beige Vinyl Floor Tile	2,000	SF	Room 118, Band Hall	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
127	12" x 12" Old Blotted Beige Vinyl Floor Tile Mastic	2,000	SF	Room 118, Band Hall	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
128	12" x 12" New Blotted Beige Vinyl Floor Tile	800	SF	Room 118	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
129	12" x 12" New Blotted Beige Vinyl Floor Tile Mastic	800	SF	Room 118	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
130	12" x 12" White w/ Gray Speckles Vinyl Floor Tile	2,000	SF	Gym Office, 310 Offices, 307, 307, 307C, Metro Director Office,	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Crane Tech High School

**Unit** 46641

**Building ID** 1270

**Address** 2245 W. Jackson

Chicago, IL, 60612

**Region**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
131	12" x 12" White w/ Gray Speckles Vinyl Floor Tile Mastic	2,000	SF	Gym Office, 310 Offices, 307, 307, 307C, Metro Director Office,	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
132	12" x 12" White w/ Brown Vinyl Floor Tile	500	SF	Choral Room 119	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
133	12" x 12" White w/ Brown Vinyl Floor Tile Mastic	500	SF	Choral Room 119	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
134	12" x 12" Off-White w/ Brown Vinyl Floor Tile	300	SF	Choral Room 119 Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
135	12" x 12" Off-White w/ Brown Vinyl Floor Tile Mastic	300	SF	Choral Room 119 Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
136	Blue Linoleum	1,200	SF	Room 109, 110	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
137	Blue Linoleum Adhesive	1,200	SF	Room 109, 110	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
138	12" x 12" Brown Texture Vinyl Floor Tile	500	SF	Ramp Outside the Library	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
139	12" x 12" Brown Texture Vinyl Floor Tile Mastic	500	SF	Ramp Outside the Library	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
140	12" x 12" Red Vinyl Floor Tile	65,000	SF	2nd, 3rd, and 4th Floors Corridors	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
141	12" x 12" Red Vinyl Floor Tile Mastic	65,000	SF	2nd, 3rd, and 4th Floor Corridors	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
142	12" x 12" Mustard Vinyl Floor Tile	1,000	SF	Room 260, 260A	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
143	12" x 12" Mustard Vinyl Floor Tile Mastic	1,000	SF	Room 260, 260A	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
144	White Sink Insulation	2		Room 210	Assumed	TSI	Yes			7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
145	Trapezoid Lab Counters	80		Room 215, 216, 315, 316	Assumed	MISC	No			6 ACBM with the potential for damage	Follow O&M Plan
146	3' x 5' Lab Counter	20		Room 318	Assumed	MISC	No			6 ACBM with the potential for damage	Follow O&M Plan
147	4' x 8' Lab Counters	20		Room 103, 102	Assumed	MISC	No			6 ACBM with the potential for damage	Follow O&M Plan
148	12" x 12" Red Mottled Vinyl Floor Tile	2,000	SF	Room 411, 412, 413, 261	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
149	12" x 12" Red Mottled Vinyl Floor Tile Mastic	2,000	SF	Room 411, 412, 413, 261	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
150	Green Carpet Adhesive	1,500	SF	Room 108, 219,	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
151	12" x 12" Brown w/ Light Spots Floor Tile	5,000	SF	West Elevator Lobby, 1st Floor MDF Room, Rooms 403, 405, 205, 205a, 200, West Med Room, 2nd Floor Hallway, Lecture Hallway, 440a, 219, Storage Across Room 400, 3rd Floor Kitchen Staff Bathroom, 2nd Floor Storage by West Elevators, 114D	Assumed	MISC	No	40	SF	5 ACBM with potential for significant damage	Repair
152	12" x 12" Brown w/ Light Spots Floor Tile Mastic	5,000	SF	West Elevator Lobby, 1st Floor Mdf Room, Rooms 403, 405, 205, 205a, 200, West Med Room, 2nd Floor Hallway, Lecture Hallway, 440a, 219, Storage Across Room 400, 3rd Floor Kitchen Staff Bathroom, 2nd Floor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Crane Tech High School

Unit 46641

Building ID 1270

Address 2245 W. Jackson

Chicago, IL, 60612

Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
153	12" x 12" Light Brown w/ Spots Floor Tile	8,000	SF	Storage by West Elevators, 114D, Rooms 312, 313, 300, 303-306, 201, 211, 213, 214, 250, 216, 217, 251, 200, 201-204, 114D	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
154	12" x 12" Light Brown w/ Spots Floor Tile Mastic	8,000	SF	Rooms 312, 313, 300, 303-306, 201, 211, 213, 214, 250, 216, 217, 251, 200, 201-204, 114D	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
155	12" x 12" Turquoise Floor Tile	250	SF	Room 206a	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
156	12" x 12" Turquoise Floor Tile Mastic	250	SF	Room 206a	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
157	12" x 12" Blue w/ Streaks Floor Tile	300	SF	Room 101 Kitchen	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
158	12" x 12" Blue w/ Streaks Floor Tile Mastic	300	SF	Room 101 Kitchen	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
159	2' x 2' Gray Carpet Square Glue	700	SF	Rooms 103 and 105	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
16	Zinc			First Floor Hall	Not Tested	MISC					
161	12" x 12" Blue w/ Blue Streaks Floor Tile	150	SF	2nd Floor Faculty Lounge	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
161M	12" x 12" Blue w/ Blue Streaks Floor Tile Mastic	150	SF	2nd Floor Faculty Lounge	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
162	12" x 12" Light Green w/ Streaks Floor Tile	70	SF	Foyer Outside Rooms 218, 209	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
162M	12" x 12" Light Green w/ Streaks Floor Tile Adhesive	70	SF	Foyer Outside Room 218, 209	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
163	12" x 12" White w/ Brown Specks Floor Tile	300	SF	Room 212, Main Office, 214 (Patches)	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
163M	12" x 12" White w/ Brown Specks Floor Tile Adhesive	300	SF	Room 212, Main Office, 214 (Patches)	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
164	12" x 12" Light Brown w/ White Specks Floor Tile	100	SF	201a, Security Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
164M	12" x 12" Light Brown w/ White Specks Floor Tile Adhesive	100	SF	201a, Security Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
165	12" x 12" Beige w/ Cream Specks Floor Tile	100	SF	Kitchen Storage Room, Security Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
165M	12" x 12" Beige w/ Cream Specks Floor Tile Adhesive	100	SF	Kitchen Storage Room, Security Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
166	Plaster	1,000	SF	4th Floor Hallway, 412, 411, 410, 409, 414A, 408, 407, 406, 405, 404, 403, 402, 401, 400, 443, 442, 441, 440, 439, 438, 437, 436, 435, 434, 433, 432, 427, 431, 428, 430, 450, 3rd Floor Hallway, 309, 310, 308, Cafeteria, 311, 312, 313, 314, 315, 317, 317A, 316, 350C, 321, 350A, 350B, 300, 301, 302, 302A, 302B, 303, 305, 306, 307, 416, 417,	Assumed	SURFACE	Yes	45	SF	2 Damaged friable surfacing ACBM	Repair

# Chicago Public Schools

School Crane Tech High School

Unit 46641

Building ID 1270

Address 2245 W. Jackson

Chicago, IL, 60612

Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				419, 418, 421, 420, 422, 423, 425, 213, 215, 216, 217, 218, 200, 201, 202, 203, 204, 205, 206A, 206, Library 207, 260, 260A, 261, 114D, 114, 115, Engineers Office							
167	Plaster on Ceiling	1,000	SF	Basement	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
168	12" x 12" Tan w/ Black Dots Vinyl Floor Tile	5,000	SF	Room 321	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
169	12" x 12" Black Floor Tile	5,000	SF	Room 321	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
170	12" x 12" Tan w/ Black Dots Vinyl Floor Tile Mastic	10,000	SF	Room 321	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
171	White w/ Brown Flower Design Acoustical Ceiling Tile	5,000	SF	Room 321	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
172	12" x 12" White w/ Black & Gray Speckled Vinyl Floor Tile	1,200	SF	Rooms 301, 215, 202	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
173	12" x 12" Gray w/ Black Speckled Vinyl Floor Tile	1,200	SF	Rooms 301, 215, 202	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
174	12" x 12" Blue w/ Black & Brown Speckled Vinyl Floor Tile	1,200	SF	Rooms 301, 215, 202	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
175	12" x 12" Blue w/ Black & Brown Speckled, Gray w/ Black Speckled, & White w/ Black & Gray Speckled Vinyl Floor Tile Mastic	3,600	SF	Rooms 301, 215, 202	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
176	12" x 12" White w/ Blue & Pink Streaks Floor Tile	1,200	SF	Room 209	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
177	12" x 12" White w/ Blue & Pink Streaks Floor Tile Mastic	1,200	SF	Room 209	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
178	Tongue and Groove Wooden Floor	5,000	SF	Gymnasium, 163 Gym	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
179	12" x 12" White w/ Blue Streaks Floor Tile	2,000	SF	Room 261	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
180	12" x 12" White w/ Blue Streaks Floor Tile Mastic	2,000	SF	Room 261	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
181	12" x 12" Light Brown w/ Dark Brown and White Specks Floor Tile	500	SF	Room 261	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
182	12" x 12" Light Brown w/ Dark Brown and White Specks Floor Tile Mastic	500	SF	Room 261	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
183	Marble Flooring	2,000	SF	1st Floor Corridor Entrance	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
184	12" x 12" Black Floor Tile Mastic	5,000	SF	Room 321	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
185	12" x 12" Blue Mottled Vinyl Floor Tile	800	SF	Rooms 261, 412	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
186	12" x 12" Blue Mottled Vinyl Floor Tile Mastic	800	SF	Rooms 261, 412	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
187	12" x 12" Light Blue Mottled Vinyl Floor Tile	400	SF	Rooms 412, 411	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
188	12" x 12" Light Blue Mottled Vinyl Floor Tile Mastic	400	SF	Rooms 412, 411	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
189	12" x 12" Green Mottled Vinyl Floor Tile	300	SF	Rooms 412, 411	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Crane Tech High School

**Unit** 46641

**Building ID** 1270

**Address** 2245 W. Jackson

Chicago, IL, 60612

**Region**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
190	12" x 12" Green Mottled Vinyl Floor Tile Mastic	300	SF	Rooms 412, 411	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
191	12" x 12" Orange Mottled Vinyl Floor Tile	300	SF	Rooms 412, 411	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
192	12" x 12" Orange Mottled Vinyl Floor Tile Mastic	300	SF	Rooms 412, 411	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
193	12" x 12" Off-White Mottled Vinyl Floor Tile	200	SF	Rooms 412, 411	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
194	12" x 12" Off-White Mottled Vinyl Floor Tile Mastic	200	SF	Rooms 412, 411	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
195	12" x 12" Yellow Mottled Vinyl Floor Tile	100	SF	Rooms 412, 411	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
196	12" x 12" Yellow Mottled Vinyl Floor Tile Mastic	100	SF	Rooms 412, 411	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Paint (Not Textured)			Throughout Facility	Not Tested	MISC					
23	6" Baseboard			Throughout Original Building	No ACBM	MISC					
76	Material Under Carpet			Room 413	Chrysotile	MISC					
A	Fiberglass Duct Cement			ABATED	Abated	MISC					
AA	Hard Joint Compound on Fiberglass Pipe Runs			Boiler Room, Pump Room, Old Glass Shop & Throughout Basement	No ACBM	TSI					
AB	Hard Joint Compound Off 15" Steam Line			Boiler Room	No ACBM	TSI					
AC	Hard Joint Compound Off Steam Supply			Auto Shop	No ACBM	TSI					
AD	Hard Joint Compound on Fiberglass Piping			Kitchen	No ACBM	TSI					
AE	Boiler Breeching	20	SF	Boiler Room	Chrysotile	TSI	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
AF	Paper Wrap on Fiberglass Pipe Insulation			New Addition Locker Room	No ACBM	TSI					
AG	Insulation Wrap			2nd Floor Fan Room	No ACBM	TSI					
AH	Cementitious Joint Insulation			See Ha - Ak	No ACBM	TSI					
AI	Cementitious Joint Insulation			New Addition Locker Room	No ACBM	TSI					
AJ	Internal Duct Liner			Basement	No ACBM	TSI					
AK	Cementitious Joint Insulation			Basement of New Addition and Girls Bathroom Plumbing Wall, 1sr, 2nd, 3rd Floors	No ACBM	TSI					
B	Fiberglass Insulation Cement			Attic	Not Tested	MISC					
C	Preformed Pipe Insulation (Mag Block)	100	LF	Boiler Room & Gym	Chrysotile	TSI	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
D	Aircell Pipe Insulation	7,000	LF	Basement Wall Chase	Assumed	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E	Stored Cardboard Pipe Insulation			ABATED	Abated	TSI					
F	Spray-on Fireproofing	1,000	SF	2nd Floor Fan Room, above 4th Floor Ceilings	Assumed	SURFACE	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
G	Vault Door Liners	160	SF	Throughout Facility Including: Coach's Office, 2nd & 3rd Floor Corridors by Elevator	Assumed	TSI	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

# Chicago Public Schools

School Crane Tech High School

Unit 46641

Building ID 1270

Address 2245 W. Jackson

Chicago, IL, 60612

Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
H	Coated Screens			ABATED	Abated	MISC					
I	Kiln Liner			Art Room	No ACBM	MISC					
J	Boiler Insulation Under Metal Jackets			Boiler Room	No ACBM	TSI					
K	Boiler Rope			Boiler Room	No ACBM	MISC					
L	Hard Fittings on Aircell Pipe Insulation	500	LF	Basement	Assumed	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
M	Stored Insulation			Basement	Not Tested	TSI					
N	Insulation Beneath Shell Of Incinerator			Boiler Room	No ACBM	TSI					
O	Incinerator Fire Brick			Boiler Room	No ACBM	TSI					
P	Insulation Beneath Shell Of Sellers Tank			Boiler Room	No ACBM	TSI					
Q	Vibration Collars			Basement	No ACBM	MISC					
R	Black Backing on Fiberglass Lighters			ABATED	Abated	TSI					
S	Hard Joint Compound Off Absorption Chiller Piping			2nd Floor Fan Room	No ACBM	TSI					
T	Fittings Off Chiller Pumps Piping			2nd Floor Fan Room	No ACBM	MISC					
U	Vibration Collars (Cloth)			2nd Floor Fan Room	No ACBM	MISC					
V	Canvas Cloth Off Fan Units			2nd Floor Fan Room	No ACBM	MISC					
W	Hard Joint Compound on Water Cooler Piping			2nd Floor Fan Room	No ACBM	TSI					
X	(Interior) Boiler Packing			Boiler Room	No ACBM	MISC					
Y	Hard Joint Compound on Valve Pump Piping			Boiler Room	No ACBM	TSI					
Z	Hard Joint Compound on Fiberglass Reheat Piping			Plenum Chamber	No ACBM	TSI					

# Chicago Public Schools

**School** Crane Tech High School

**Unit** 46641

**Building ID** 1270

**Address** 2245 W. Jackson

Chicago, IL, 60612

**Region**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

*Management Planner's Comments Summarized at the End of the Report*

Review Date	6/16/2025
Manager Planner Name	Jackson Montgomery
100-20634	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
001	
001M	
002A	
002A-M	
002B	
002B-M	
002C	
002D	
003	
004	
005	
006	
006M	
007	Non-AHERA
008	
009	
010	
011	

# Chicago Public Schools

**School** Crane Tech High School

**Unit** 46641

**Building ID** 1270

**Address** 2245 W. Jackson

Chicago, IL, 60612

**Region**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
012	
013	
014	
015	
016	
017	
019	
020	
021	
022	
022M	
023M	
024	
024M	
025	
025M	
026	
026M	
027	
027M	
028	
028M	
029	
029M	
030	
031	
032	

# Chicago Public Schools

**School** Crane Tech High School

**Unit** 46641

**Building ID** 1270

**Address** 2245 W. Jackson

Chicago, IL, 60612

**Region**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
033	
034	
035	
036	
037	
038	
039	
040	
041	
042	
043	
044	
045	
046	
047	
048	If identified, continue O&M.
049	
050	
051	
052	
053	
054	
055	
056	
057	
058	
059	

# Chicago Public Schools

**School** Crane Tech High School

**Unit** 46641

**Building ID** 1270

**Address** 2245 W. Jackson

Chicago, IL, 60612

**Region**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
060	
062	
063	
064	
064M	
065	
065M	
066	
066M	
067	
067M	
068	
068M	
069	
069M	
070	
070M	
071	
072	
072M	
073	
073M	
074	
074M	
075	
076	If identified, continue O&M.
076M	

# Chicago Public Schools

**School** Crane Tech High School

**Unit** 46641

**Building ID** 1270

**Address** 2245 W. Jackson

Chicago, IL, 60612

**Region**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
077	
077M	
078	
078M	
079	Non-AHERA
080	
081	
082	Non-AHERA
083	
084	
085	Non-AHERA
086	Non-AHERA
087	Non-AHERA
088	Non-AHERA
089	Non-AHERA
090	Non-AHERA
091	Non-AHERA
092	Non-AHERA
093	Non-AHERA
094	Non-AHERA
095	Non-AHERA
096	Non-AHERA
097	Non-AHERA
098	Non-AHERA
099	Non-AHERA
10	Sample to determine ACM content, remove or repair to intact.
100	Non-AHERA

# Chicago Public Schools

**School** Crane Tech High School

**Unit** 46641

**Building ID** 1270

**Address** 2245 W. Jackson

Chicago, IL, 60612

**Region**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
101	Non-AHERA
103	Non-AHERA
104	
105	
106	
107	
108	
109	
110	If identified, continue O&M.
111	If identified, continue O&M.
112	
113	
114	If identified, continue O&M.
115	If identified, continue O&M.
116	
117	
118	
119	
120	
121	
124	
125	
126	
127	
128	
129	
130	

# Chicago Public Schools

**School** Crane Tech High School

**Unit** 46641

**Building ID** 1270

**Address** 2245 W. Jackson

Chicago, IL, 60612

**Region**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
131	
132	
133	
134	
135	
136	
137	
138	
139	
140	
141	
142	
143	
144	
145	
146	
147	
148	
149	
150	
151	Sample to determine ACM content, remove or repair to intact.
152	
153	
154	
155	
156	
157	

# Chicago Public Schools

**School** Crane Tech High School

**Unit** 46641

**Building ID** 1270

**Address** 2245 W. Jackson

Chicago, IL, 60612

**Region**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
158	
159	
16	
161	
161M	
162	
162M	
163	
163M	
164	
164M	
165	
165M	
166	Sample to determine ACM content, remove or repair damaged surfacing material to intact.
167	
168	
169	
170	
171	
172	
173	
174	
175	
176	
177	
178	
179	

# Chicago Public Schools

**School** Crane Tech High School

**Unit** 46641

**Building ID** 1270

**Address** 2245 W. Jackson

Chicago, IL, 60612

**Region**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
180	
181	
182	
183	
184	
185	
186	
187	
188	
189	
190	
191	
192	
193	
194	
195	
196	
20	
23	
76	If identified, continue O&M.
A	
AA	
AB	
AC	
AD	
AE	
AF	

# Chicago Public Schools

**School** Crane Tech High School  
**Address** 2245 W. Jackson

**Unit** 46641  
 Chicago, IL, 60612

**Building ID** 1270  
**Region**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
AG	
AH	
AI	
AJ	
AK	
B	
C	
D	
E	
F	
G	
H	
I	
J	
K	
L	
M	
N	
O	
P	
Q	
R	
S	
T	
U	
V	
W	

# Chicago Public Schools

**School** Crane Tech High School

**Unit** 46641

**Building ID** 1270

**Address** 2245 W. Jackson

Chicago, IL, 60612

**Region**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
X	
Y	
Z	

# APPENDIX A

## Assessment Sheets, Drawings and Photos

---

# Chicago Public Schools

Carnow, Conibear and Associates

*2025 AHERA REINSPECTION*

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **001**  
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Facility (Auto Shop Hall, Room Next to the Pool, Engineer Office, Hall Outside 260)**

MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **001**  
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**  
MATERIAL LOCATION: **Throughout Facility (Auto Shop Hall, Room Next to the Pool, Engineer Office, Hall Outside 260)**  
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **001M**  
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Facility (Auto Shop Hall, Room Next to the Pool, Engineer Office, Hall Outside 260)**

MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **001M**  
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**  
MATERIAL LOCATION: **Throughout Facility (Auto Shop Hall, Room Next to the Pool, Engineer Office, Hall Outside 260)**  
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002A**  
MATERIAL DESCRIPTION: **9" x 9" Reddish Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **002A**

MATERIAL DESCRIPTION: **9" x 9" Reddish Brown Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002A-M**  
MATERIAL DESCRIPTION: **9" x 9" Reddish Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **002A-M**

MATERIAL DESCRIPTION: **9" x 9" Reddish Brown Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002B**  
MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **002B**

MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002B-M**  
MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **002B-M**

MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002C**  
MATERIAL DESCRIPTION: **9" x 9" Reddish Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Storage Room Under Entrance 1**

MATERIAL QUANTITY: **250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **002C**  
MATERIAL DESCRIPTION: **9" x 9" Reddish Brown Floor Tile**  
MATERIAL LOCATION: **Storage Room Under Entrance 1**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002D**  
MATERIAL DESCRIPTION: **9" x 9" Reddish Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Storage Room Under Entrance 1**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **002D**  
MATERIAL DESCRIPTION: **9" x 9" Reddish Brown Floor Tile Mastic**  
MATERIAL LOCATION: **Storage Room Under Entrance 1**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003**  
MATERIAL DESCRIPTION: **Red Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Library 207**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **003**  
MATERIAL DESCRIPTION: **Red Carpet Mastic**  
MATERIAL LOCATION: **Library 207**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 06/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **004**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 321, 206, and 413 Office, Police, and Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **004**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
MATERIAL LOCATION: **Rooms 321, 206, and 413 Office, Police, and Bathroom**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **005**  
MATERIAL DESCRIPTION: **Wood Floor Underlayment**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gym**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **005**  
MATERIAL DESCRIPTION: **Wood Floor Underlayment**  
MATERIAL LOCATION: **Gym**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006**  
MATERIAL DESCRIPTION: **Matting**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Running Track**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **006**  
MATERIAL DESCRIPTION: **Matting**  
MATERIAL LOCATION: **Running Track**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46641**    BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School**    INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson**    IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006M**  
MATERIAL DESCRIPTION: **Adhesive Beneath Matting**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Running Track**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **006M**  
MATERIAL DESCRIPTION: **Adhesive Beneath Matting**  
MATERIAL LOCATION: **Running Track**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **007**  
MATERIAL DESCRIPTION: **Painted Concrete - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **007**

MATERIAL DESCRIPTION: **Painted Concrete - Non-AHERA**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46641**    BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School**    INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson**    IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **008**  
MATERIAL DESCRIPTION: **Black/Gray Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Clinic**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **008**  
MATERIAL DESCRIPTION: **Black/Gray Carpet Mastic**  
MATERIAL LOCATION: **Clinic**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 06/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **009**  
MATERIAL DESCRIPTION: **Grayish Brown Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Bathrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **009**  
MATERIAL DESCRIPTION: **Grayish Brown Ceramic Tile Grout**  
MATERIAL LOCATION: **Bathrooms**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **010**  
MATERIAL DESCRIPTION: **2' x 4' Random Dot Lay-in Ceiling Panels**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **DUPLICATE HA**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **010**  
MATERIAL DESCRIPTION: **2' x 4' Random Dot Lay-in Ceiling Panels**  
MATERIAL LOCATION: **DUPLICATE HA**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **011**  
MATERIAL DESCRIPTION: **Plaster Patch**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Outside of Cafeteria**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **011**  
MATERIAL DESCRIPTION: **Plaster Patch**  
MATERIAL LOCATION: **Outside of Cafeteria**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **012**  
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pool Area**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **012**  
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**  
MATERIAL LOCATION: **Pool Area**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **013**  
MATERIAL DESCRIPTION: **1' x 1' Fissured Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gym**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not found in library**

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **013**  
MATERIAL DESCRIPTION: **1' x 1' Fissured Ceiling Tile**  
MATERIAL LOCATION: **Gym**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 06/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **014**  
MATERIAL DESCRIPTION: **1' x 1' Smooth Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Canteen & Kitchen**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **014**  
MATERIAL DESCRIPTION: **1' x 1' Smooth Ceiling Tile**  
MATERIAL LOCATION: **Canteen & Kitchen**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **015**  
MATERIAL DESCRIPTION: **1' x 1' Dot Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Band & Canteen**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **015**  
MATERIAL DESCRIPTION: **1' x 1' Dot Ceiling Tile**  
MATERIAL LOCATION: **Band & Canteen**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **016**  
MATERIAL DESCRIPTION: **Zinc**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Not Tested** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **First Floor Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **016**  
MATERIAL DESCRIPTION: **Zinc**  
MATERIAL LOCATION: **First Floor Hall**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **017**  
MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Pool, 2nd Floor South Hallway**  
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **017**  
MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile**  
MATERIAL LOCATION: **Pool, 2nd Floor South Hallway**  
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **019**  
MATERIAL DESCRIPTION: **2' x 2' Lay-in Ceiling Panels**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Clinic (110)**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **019**  
MATERIAL DESCRIPTION: **2' x 2' Lay-in Ceiling Panels**  
MATERIAL LOCATION: **Clinic (110)**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **020**  
MATERIAL DESCRIPTION: **Paint (Not Textured)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Not Tested** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **020**  
MATERIAL DESCRIPTION: **Paint (Not Textured)**  
MATERIAL LOCATION: **Throughout Facility**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **021**  
MATERIAL DESCRIPTION: **Wall Plaques**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **021**  
MATERIAL DESCRIPTION: **Wall Plaques**  
MATERIAL LOCATION: **ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **022**  
MATERIAL DESCRIPTION: **4" Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Original Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **022**  
MATERIAL DESCRIPTION: **4" Baseboard**  
MATERIAL LOCATION: **Throughout Original Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **022M**  
MATERIAL DESCRIPTION: **4" Baseboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Original Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **022M**

MATERIAL DESCRIPTION: **4" Baseboard Adhesive**

MATERIAL LOCATION: **Throughout Original Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **023M**  
MATERIAL DESCRIPTION: **6" Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Original Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **023M**  
MATERIAL DESCRIPTION: **6" Baseboard Mastic**  
MATERIAL LOCATION: **Throughout Original Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **024**  
MATERIAL DESCRIPTION: **90 De. Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **024**  
MATERIAL DESCRIPTION: **90 De. Baseboard**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **024M**  
MATERIAL DESCRIPTION: **90 De. Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **024M**  
MATERIAL DESCRIPTION: **90 De. Baseboard Mastic**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 06/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **025**  
MATERIAL DESCRIPTION: **4" Brown Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **New Addition Gym and Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **025**  
MATERIAL DESCRIPTION: **4" Brown Baseboard**  
MATERIAL LOCATION: **New Addition Gym and Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **025M**  
MATERIAL DESCRIPTION: **4" Brown Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **New Addition Gym and Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **025M**  
MATERIAL DESCRIPTION: **4" Brown Baseboard Mastic**  
MATERIAL LOCATION: **New Addition Gym and Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **026**  
MATERIAL DESCRIPTION: **6" Brown Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Hall and Room 106**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **026**  
MATERIAL DESCRIPTION: **6" Brown Baseboard**  
MATERIAL LOCATION: **Hall and Room 106**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **026M**  
MATERIAL DESCRIPTION: **6" Brown Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Hall and Room 106**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **026M**  
MATERIAL DESCRIPTION: **6" Brown Baseboard Mastic**  
MATERIAL LOCATION: **Hall and Room 106**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 06/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **027**  
MATERIAL DESCRIPTION: **Interior Brick**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Original Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **027**  
MATERIAL DESCRIPTION: **Interior Brick**  
MATERIAL LOCATION: **Throughout Original Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **027M**  
MATERIAL DESCRIPTION: **Interior Brick Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Original Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **027M**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **Throughout Original Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46641**    BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School**    INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson**    IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **028**  
MATERIAL DESCRIPTION: **Cinder Block**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Original Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **028**  
MATERIAL DESCRIPTION: **Cinder Block**  
MATERIAL LOCATION: **Throughout Original Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **028M**  
MATERIAL DESCRIPTION: **Cinder Block Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Original Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **028M**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

MATERIAL LOCATION: **Throughout Original Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **029**  
MATERIAL DESCRIPTION: **Glazed Brick**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building - Gym, 2nd Floor Fan Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **029**  
MATERIAL DESCRIPTION: **Glazed Brick**  
MATERIAL LOCATION: **Original Building - Gym, 2nd Floor Fan Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **029M**  
MATERIAL DESCRIPTION: **Glazed Brick Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building - Gym and 2nd Floor Fan Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **029M**  
MATERIAL DESCRIPTION: **Glazed Brick Mortar**  
MATERIAL LOCATION: **Original Building - Gym and 2nd Floor Fan Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **030**  
MATERIAL DESCRIPTION: **Water Tank**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pool Maintenance Area**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **030**  
MATERIAL DESCRIPTION: **Water Tank**  
MATERIAL LOCATION: **Pool Maintenance Area**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **031**  
MATERIAL DESCRIPTION: **Terrazzo Basins**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Maintenance Rooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **031**  
MATERIAL DESCRIPTION: **Terrazzo Basins**  
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Maintenance Rooms**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **032**  
MATERIAL DESCRIPTION: **White Terrazzo Flooring**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st, 2nd, and 3rd Floor Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **032**  
MATERIAL DESCRIPTION: **White Terrazzo Flooring**  
MATERIAL LOCATION: **1st, 2nd, and 3rd Floor Corridors**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **033**  
MATERIAL DESCRIPTION: **Red Border Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **033**  
MATERIAL DESCRIPTION: **Red Border Terrazzo**  
MATERIAL LOCATION: **Corridors**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **034**  
MATERIAL DESCRIPTION: **Multi-Brown Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **4th Floor Womens Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **034**  
MATERIAL DESCRIPTION: **Multi-Brown Ceramic Tile Grout**  
MATERIAL LOCATION: **4th Floor Womens Bathroom**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **035**  
MATERIAL DESCRIPTION: **Orange Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 307, 310, 313, and 413**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **035**  
MATERIAL DESCRIPTION: **Orange Carpet Mastic**  
MATERIAL LOCATION: **Rooms 307, 310, 313, and 413**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **036**  
MATERIAL DESCRIPTION: **Gray Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lecture Rooms, Principal's Office, Main Office, and Security, 105, 103, 101**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **036**  
MATERIAL DESCRIPTION: **Gray Carpet Mastic**  
MATERIAL LOCATION: **Lecture Rooms, Principal's Office, Main Office, and Security, 105, 103, 101**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **037**  
MATERIAL DESCRIPTION: **Cementitious Gaskets**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **037**  
MATERIAL DESCRIPTION: **Cementitious Gaskets**  
MATERIAL LOCATION: **2nd Floor Fan Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **038**  
MATERIAL DESCRIPTION: **Ceiling Tile Under Metal 1' x 1' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Above Pool Bleachers**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **038**  
MATERIAL DESCRIPTION: **Ceiling Tile Under Metal 1' x 1' Ceiling Tile**  
MATERIAL LOCATION: **Above Pool Bleachers**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **039**  
MATERIAL DESCRIPTION: **2' x 4' Random Dot Replacement Ceiling Panels**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Fan Room #2**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **039**  
MATERIAL DESCRIPTION: **2' x 4' Random Dot Replacement Ceiling Panels**  
MATERIAL LOCATION: **Fan Room #2**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **040**  
MATERIAL DESCRIPTION: **Transite Sink Tops**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 315, 316, 317, 201, 210, 215, and 216**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **040**  
MATERIAL DESCRIPTION: **Transite Sink Tops**  
MATERIAL LOCATION: **Rooms 315, 316, 317, 201, 210, 215, and 216**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **041**  
MATERIAL DESCRIPTION: **Black Material Coating Sink Bottoms**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 315, 316, 317, 201, 210, 215, and 216**  
MATERIAL QUANTITY: **14** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **041**  
MATERIAL DESCRIPTION: **Black Material Coating Sink Bottoms**  
MATERIAL LOCATION: **Rooms 315, 316, 317, 201, 210, 215, and 216**  
MATERIAL QUANTITY: **14** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **042**  
MATERIAL DESCRIPTION: **Lab Table Tops**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 300, 301, 315, 316, and 317**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **042**

MATERIAL DESCRIPTION: **Lab Table Tops**

MATERIAL LOCATION: **Rooms 300, 301, 315, 316, and 317**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **043**  
MATERIAL DESCRIPTION: **Terrazzo Flooring**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **New Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **043**  
MATERIAL DESCRIPTION: **Terrazzo Flooring**  
MATERIAL LOCATION: **New Addition**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46641**    BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School**    INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson**    IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **044**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **044**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **045**  
MATERIAL DESCRIPTION: **Pink Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 213 and 214, and Upper Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **045**  
MATERIAL DESCRIPTION: **Pink Carpet Mastic**  
MATERIAL LOCATION: **Rooms 213 and 214, and Upper Library**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **046**  
MATERIAL DESCRIPTION: **Cinder Block**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **New Addition - Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **046**  
MATERIAL DESCRIPTION: **Cinder Block**  
MATERIAL LOCATION: **New Addition - Gym**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **047**  
MATERIAL DESCRIPTION: **Cinder Block Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **New Addition - Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **047**  
MATERIAL DESCRIPTION: **Cinder Block Mortar**  
MATERIAL LOCATION: **New Addition - Gym**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **048**  
MATERIAL DESCRIPTION: **Adhesive Behind Mirrors**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Bathrooms**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material in inaccessible area(s) - 2025**

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **048**  
MATERIAL DESCRIPTION: **Adhesive Behind Mirrors**  
MATERIAL LOCATION: **Bathrooms**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified, continue O&M.

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **049**  
MATERIAL DESCRIPTION: **Gray and White Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 201, 217, 300, and 301**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **049**  
MATERIAL DESCRIPTION: **Gray and White Linoleum**  
MATERIAL LOCATION: **Rooms 201, 217, 300, and 301**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **050**  
MATERIAL DESCRIPTION: **Gray and White Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **050**

MATERIAL DESCRIPTION: **Gray and White Linoleum Mastic**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46641**    BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School**    INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson**    IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **051**  
MATERIAL DESCRIPTION: **12" x 12" Light Gray Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 106**  
MATERIAL QUANTITY: **1000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **051**  
MATERIAL DESCRIPTION: **12" x 12" Light Gray Floor Tile**  
MATERIAL LOCATION: **Room 106**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **052**  
MATERIAL DESCRIPTION: **12" x 12" Light Gray Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 106**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **052**  
MATERIAL DESCRIPTION: **12" x 12" Light Gray Floor Tile Mastic**  
MATERIAL LOCATION: **Room 106**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **053**  
MATERIAL DESCRIPTION: **Fume Hood Interior Backing**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 316 and 317**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **053**  
MATERIAL DESCRIPTION: **Fume Hood Interior Backing**  
MATERIAL LOCATION: **Rooms 316 and 317**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **054**  
MATERIAL DESCRIPTION: **Kiln Gasket**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **054**  
MATERIAL DESCRIPTION: **Kiln Gasket**  
MATERIAL LOCATION: **Room 103**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **055**  
MATERIAL DESCRIPTION: **Non Skid Strips**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Ramp**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **055**  
MATERIAL DESCRIPTION: **Non Skid Strips**  
MATERIAL LOCATION: **2nd Floor Ramp**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **056**  
MATERIAL DESCRIPTION: **Interior Caulk**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Pool Room**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **056**  
MATERIAL DESCRIPTION: **Interior Caulk**  
MATERIAL LOCATION: **Pool Room**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **057**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Cat Walk**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **057**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **Cat Walk**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **058**  
MATERIAL DESCRIPTION: **Insulation Inside Of Fire Doors**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Facility**  
MATERIAL QUANTITY: **320** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **058**  
MATERIAL DESCRIPTION: **Insulation Inside Of Fire Doors**  
MATERIAL LOCATION: **Throughout Facility**  
MATERIAL QUANTITY: **320** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **059**  
MATERIAL DESCRIPTION: **Block**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **New Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **059**  
MATERIAL DESCRIPTION: **Block**  
MATERIAL LOCATION: **New Addition**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **060**  
MATERIAL DESCRIPTION: **Block Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **New Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **060**  
MATERIAL DESCRIPTION: **Block Mortar**  
MATERIAL LOCATION: **New Addition**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **062**  
MATERIAL DESCRIPTION: **Black Duct Sealant**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Tunnel**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **062**  
MATERIAL DESCRIPTION: **Black Duct Sealant**  
MATERIAL LOCATION: **Tunnel**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46641**    BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School**    INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson**    IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **063**  
MATERIAL DESCRIPTION: **Chalkboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Running Track**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **063**  
MATERIAL DESCRIPTION: **Chalkboard Adhesive**  
MATERIAL LOCATION: **Running Track**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **064**  
MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **064**

MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **064M**  
MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **064M**  
MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **065**  
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **065**  
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile**  
MATERIAL LOCATION: **ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **065M**  
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **065M**

MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **066**  
MATERIAL DESCRIPTION: **12" x 12" Dark Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **066**

MATERIAL DESCRIPTION: **12" x 12" Dark Brown Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **066M**  
MATERIAL DESCRIPTION: **12" x 12" Dark Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **066M**  
MATERIAL DESCRIPTION: **12" x 12" Dark Brown Floor Tile Mastic**  
MATERIAL LOCATION: **ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **067**  
MATERIAL DESCRIPTION: **12" x 12" Pink Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **067**  
MATERIAL DESCRIPTION: **12" x 12" Pink Floor Tile**  
MATERIAL LOCATION: **ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **067M**  
MATERIAL DESCRIPTION: **12" x 12" Pink Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **067M**

MATERIAL DESCRIPTION: **12" x 12" Pink Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **068**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 105, and 317, 206H**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not found in 315, 316**

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **068**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile**  
MATERIAL LOCATION: **Rooms 105, and 317, 206H**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **068M**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 105, and 317, 206H**

MATERIAL QUANTITY: **2200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not found in 315, 316**

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **068M**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 105, and 317, 206H**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **069**  
MATERIAL DESCRIPTION: **12" x 12" Cream Colored Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 433, 435, 401, 443, 433, 440, 441, 420, 416, 414b, 437, 438, 439, 119, 426, 430, 402, 404, 432, 427, 431, 429, 450, 424, 419, 417, 410, 436, 153, 425, 421, 415, 414a, 400, 119b, 415, 103, 115, 117, 118, 406, 409, 420, 422, and 423, and Stage, 408, 407, 442, 434, 428, 309, 310, 308, Cafeteria, 311, 312, 313, 314, 300, 303, 305, 306, 418, 423, 213, 203,**

MATERIAL QUANTITY: **50000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not found in 116, 101**

Inspector's Signature: \_\_\_\_\_



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **069**

MATERIAL DESCRIPTION: **12" x 12" Cream Colored Floor Tile**

MATERIAL LOCATION: **Rooms 433, 435, 401, 443, 433, 440, 441, 420, 416, 414b, 437, 438, 439, 119, 426, 430, 402, 404, 432, 427, 431, 429, 450, 424, 419, 417, 410, 436, 153, 425, 421, 415, 414a, 400, 119b, 415, 103, 115, 117, 118, 406, 409, 420, 422, and 423, and Stage, 408, 407, 442, 434, 428, 309, 310, 308, Cafeteria, 311, 312, 313, 314, 300, 303, 305, 306, 418, 423, 213, 203,**

MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **069M**  
MATERIAL DESCRIPTION: **12" x 12" Cream Colored Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 433, 435, 401, 443, 433, 440, 441, 420, 416, 414b, 437, 438, 439, 119, 426, 430, 402, 404, 432, 427, 431, 429, 450, 424, 419, 417, 410, 436, 153, 425, 421, 415, 414a, 400, 119b, 415, 103, 115, 117, 118, 406, 409, 420, 422, and 423, and Stage, 408, 407, 442, 434, 428, 309, 310, 308, Cafeteria, 311, 312, 313, 314, 300, 303, 305, 306, 418, 423, 213, 203,**

MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not found in 116, 101**

Inspector's Signature: \_\_\_\_\_



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **069M**

MATERIAL DESCRIPTION: **12" x 12" Cream Colored Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 433, 435, 401, 443, 433, 440, 441, 420, 416, 414b, 437, 438, 439, 119, 426, 430, 402, 404, 432, 427, 431, 429, 450, 424, 419, 417, 410, 436, 153, 425, 421, 415, 414a, 400, 119b, 415, 103, 115, 117, 118, 406, 409, 420, 422, and 423, and Stage, 408, 407, 442, 434, 428, 309, 310, 308, Cafeteria, 311, 312, 313, 314, 300, 303, 305, 306, 418, 423, 213, 203,**

MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **070**  
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/ Brown Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **070**  
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/ Brown Streaks**  
MATERIAL LOCATION: **ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **070M**  
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/ Brown Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **070M**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/ Brown Streaks Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **071**  
MATERIAL DESCRIPTION: **Adhesive Backing on Fiberglass Insulation Panels**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Hall, Rooms 51a and 51b**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **071**  
MATERIAL DESCRIPTION: **Adhesive Backing on Fiberglass Insulation Panels**  
MATERIAL LOCATION: **Hall, Rooms 51a and 51b**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **072**  
MATERIAL DESCRIPTION: **12" x 12" Tan w/ White Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 104**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **072**  
MATERIAL DESCRIPTION: **12" x 12" Tan w/ White Specks Floor Tile**  
MATERIAL LOCATION: **Room 104**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **072M**  
MATERIAL DESCRIPTION: **12" x 12" Tan w/ White Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 104**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **072M**  
MATERIAL DESCRIPTION: **12" x 12" Tan w/ White Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 104**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46641    BUILDING ID: 1270  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Cody Cummins  
SCHOOL NAME: Crane Tech High School    INSPECTION DATE: 5/30/2025  
ADDRESS: 2245 W. Jackson    IDPH LICENSE NO: 100-20994

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 073  
MATERIAL DESCRIPTION: Floor Tile Beneath 12" x 12" Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **073**  
MATERIAL DESCRIPTION: **Floor Tile Beneath 12" x 12" Floor Tile**  
MATERIAL LOCATION: **ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **073M**  
MATERIAL DESCRIPTION: **Mastic on Floor Tile Beneath 12" x 12" Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **073M**

MATERIAL DESCRIPTION: **Mastic on Floor Tile Beneath 12" x 12" Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **074**  
MATERIAL DESCRIPTION: **Linoleum (Beneath Carpet)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 321**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **074**  
MATERIAL DESCRIPTION: **Linoleum (Beneath Carpet)**  
MATERIAL LOCATION: **Room 321**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **074M**  
MATERIAL DESCRIPTION: **Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 321**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **074M**

MATERIAL DESCRIPTION: **Linoleum Mastic**

MATERIAL LOCATION: **Room 321**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **075**  
MATERIAL DESCRIPTION: **Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Stairway, 1-2, 2-3, 3-4**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **075**  
MATERIAL DESCRIPTION: **Terrazzo**  
MATERIAL LOCATION: **Stairway, 1-2, 2-3, 3-4**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **076**  
MATERIAL DESCRIPTION: **Material Under Carpet**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 413**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material in inaccessible area(s) - 2025  
Beneath Existing Carpet**

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **076**  
MATERIAL DESCRIPTION: **Material Under Carpet**  
MATERIAL LOCATION: **Room 413**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified, continue O&M.

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **076M**  
MATERIAL DESCRIPTION: **Adhesive For Material Under Carpet**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 413**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **076M**

MATERIAL DESCRIPTION: **Adhesive For Material Under Carpet**

MATERIAL LOCATION: **Room 413**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **077**  
MATERIAL DESCRIPTION: **Interior Brick**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **New Addition Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **077**  
MATERIAL DESCRIPTION: **Interior Brick**  
MATERIAL LOCATION: **New Addition Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **077M**  
MATERIAL DESCRIPTION: **Interior Brick Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **New Addition Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **077M**  
MATERIAL DESCRIPTION: **Interior Brick Mortar**  
MATERIAL LOCATION: **New Addition Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 06/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **078**  
MATERIAL DESCRIPTION: **Glazed Brick**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pool Room Walls**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **078**  
MATERIAL DESCRIPTION: **Glazed Brick**  
MATERIAL LOCATION: **Pool Room Walls**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **078M**  
MATERIAL DESCRIPTION: **Glazed Brick Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pool Room Walls**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **078M**

MATERIAL DESCRIPTION: **Glazed Brick Mortar**

MATERIAL LOCATION: **Pool Room Walls**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **079**  
MATERIAL DESCRIPTION: **Blacktar on Outside Of Duct Insulation - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **079**  
MATERIAL DESCRIPTION: **Blacktar on Outside Of Duct Insulation - Non-AHERA**  
MATERIAL LOCATION: **Roof**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:  
Non-AHERA

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **080**  
MATERIAL DESCRIPTION: **9" x 9" Reddish Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **080**  
MATERIAL DESCRIPTION: **9" x 9" Reddish Brown Floor Tile**  
MATERIAL LOCATION: **ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **081**  
MATERIAL DESCRIPTION: **9" x 9" Reddish Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **081**  
MATERIAL DESCRIPTION: **9" x 9" Reddish Brown Floor Tile Mastic**  
MATERIAL LOCATION: **ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **082**  
MATERIAL DESCRIPTION: **Exterior Transom Window Caulk - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **North Main Entrance**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **082**  
MATERIAL DESCRIPTION: **Exterior Transom Window Caulk - Non-AHERA**  
MATERIAL LOCATION: **North Main Entrance**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:  
Non-AHERA

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **083**  
MATERIAL DESCRIPTION: **Interior Transom Window Caulk**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **North Main Entrance**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **083**  
MATERIAL DESCRIPTION: **Interior Transom Window Caulk**  
MATERIAL LOCATION: **North Main Entrance**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **084**  
MATERIAL DESCRIPTION: **Plaster Soffit**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **South Entrance of New Addition**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **084**  
MATERIAL DESCRIPTION: **Plaster Soffit**  
MATERIAL LOCATION: **South Entrance of New Addition**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 06/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **085**  
MATERIAL DESCRIPTION: **Roof Flashing - Layer 1 - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **New Addition Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **085**  
MATERIAL DESCRIPTION: **Roof Flashing - Layer 1 - Non-AHERA**  
MATERIAL LOCATION: **New Addition Roof**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:  
Non-AHERA

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **086**  
MATERIAL DESCRIPTION: **Roof Flashing - Layer 2 - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **New Addition Roof**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **086**  
MATERIAL DESCRIPTION: **Roof Flashing - Layer 2 - Non-AHERA**  
MATERIAL LOCATION: **New Addition Roof**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:  
Non-AHERA

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **087**  
MATERIAL DESCRIPTION: **Roof Flashing - Layer 3 - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **New Addition Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **087**  
MATERIAL DESCRIPTION: **Roof Flashing - Layer 3 - Non-AHERA**  
MATERIAL LOCATION: **New Addition Roof**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:  
Non-AHERA

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **088**  
MATERIAL DESCRIPTION: **Roofing Material - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **New Addition Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **088**  
MATERIAL DESCRIPTION: **Roofing Material - Non-AHERA**  
MATERIAL LOCATION: **New Addition Roof**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:  
Non-AHERA

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **089**  
MATERIAL DESCRIPTION: **Roofing Material - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **089**  
MATERIAL DESCRIPTION: **Roofing Material - Non-AHERA**  
MATERIAL LOCATION: **Original Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:  
Non-AHERA

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **090**  
MATERIAL DESCRIPTION: **Roof Flashing - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: **Original Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:  
COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **090**  
MATERIAL DESCRIPTION: **Roof Flashing - Non-AHERA**  
MATERIAL LOCATION: **Original Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
Non-AHERA

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46641**    BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School**    INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson**    IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **091**  
MATERIAL DESCRIPTION: **Decorative Columns - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **091**

MATERIAL DESCRIPTION: **Decorative Columns - Non-AHERA**

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **092**  
MATERIAL DESCRIPTION: **Decorative Column Mastic/Mortar - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **092**  
MATERIAL DESCRIPTION: **Decorative Column Mastic/Mortar - Non-AHERA**  
MATERIAL LOCATION: **Roof**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
Non-AHERA

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **093**  
MATERIAL DESCRIPTION: **Exterior Red Face Brick - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **093**  
MATERIAL DESCRIPTION: **Exterior Red Face Brick - Non-AHERA**  
MATERIAL LOCATION: **Roof**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
Non-AHERA

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **094**  
MATERIAL DESCRIPTION: **Exterior Red Face Brick Mortar - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **094**  
MATERIAL DESCRIPTION: **Exterior Red Face Brick Mortar - Non-AHERA**  
MATERIAL LOCATION: **Roof**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
Non-AHERA

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **095**  
MATERIAL DESCRIPTION: **Interior Brick - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **095**  
MATERIAL DESCRIPTION: **Interior Brick - Non-AHERA**  
MATERIAL LOCATION: **Roof**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
Non-AHERA

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **096**  
MATERIAL DESCRIPTION: **Interior Brick Mortar - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **096**  
MATERIAL DESCRIPTION: **Interior Brick Mortar - Non-AHERA**  
MATERIAL LOCATION: **Roof**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
Non-AHERA

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **097**  
MATERIAL DESCRIPTION: **Roof Caulking - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **New Addition**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **097**  
MATERIAL DESCRIPTION: **Roof Caulking - Non-AHERA**  
MATERIAL LOCATION: **New Addition**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:  
Non-AHERA

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **098**  
MATERIAL DESCRIPTION: **Roofing Material - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Not Tested** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **New Addition**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **098**  
MATERIAL DESCRIPTION: **Roofing Material - Non-AHERA**  
MATERIAL LOCATION: **New Addition**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:  
Non-AHERA

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **099**  
MATERIAL DESCRIPTION: **Brick Mortar - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **New Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **099**  
MATERIAL DESCRIPTION: **Brick Mortar - Non-AHERA**  
MATERIAL LOCATION: **New Addition**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
Non-AHERA

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **2' x 4' Random Dot Lay-In Ceiling Panels**  
HISTORICAL AHERA DAMAGE CATEGORY **4 Damaged or significantly damaged friable misc. ACBM**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Remove**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Physical Damage**

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **4th Floor Hallway, Rooms 409, 430, 414A, 408, 407, 406, 404, 405, 403, 402, 401, 400, 443, 442, 441, 440, 439, 438, 437, 436, 435, 434, 433, 432, 427, 431, 428, 430, 450, 3rd Floor Hallway, Rooms 310, 308, 311, 312, 313, 314, 315, 317, 317A, 316, 350C, 350C, 350B, 300, 301, 302, 302A, 302B, 303, 305, 306, 307, 307C, Metro Director Office, Rooms 416, 417, 419, 418, 421, 420, 422, 423, 425, 213, 214, 215, 216, 217, 218, 219, 200, 201, 202, 203, 204, 205, 206A, 206, Library 207, 260, 260A, 261, 114D, 114, 115, Engineers Office**

MATERIAL QUANTITY: **20000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Damage in 430**

Inspector's Signature: \_\_\_\_\_



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **2' x 4' Random Dot Lay-In Ceiling Panels**

MATERIAL LOCATION: **4th Floor Hallway, Rooms 409, 430, 414A, 408, 407, 406, 404, 405, 403, 402, 401, 400, 443, 442, 441, 440, 439, 438, 437, 436, 435, 434, 433, 432, 427, 431, 428, 430, 450, 3rd Floor Hallway, Rooms 310, 308, 311, 312, 313, 314, 315, 317, 317A, 316, 350C, 350C, 350B, 300, 301, 302, 302A, 302B, 303, 305, 306, 307, 307C, Metro Director Office, Rooms 416, 417, 419, 418, 421, 420, 422, 423, 425, 213, 214, 215, 216, 217, 218, 219, 200, 201, 202, 203, 204, 205, 206A, 206, Library 207, 260, 260A, 261, 114D, 114, 115, Engineers Office**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Sample to determine ACM content, remove or repair to intact.

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **Exterior Window Caulk - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **Exterior Window Caulk - Non-AHERA**  
MATERIAL LOCATION: **Building Exterior**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
Non-AHERA

Management Planner's Signature:  Date: 06/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **Exterior Door Caulk - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Addition Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **Exterior Door Caulk - Non-AHERA**  
MATERIAL LOCATION: **Building Addition Exterior**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
Non-AHERA

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **Tar Paper Over Roof Ducts Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **Tar Paper Over Roof Ducts Non-AHERA**  
MATERIAL LOCATION: **Exterior Roof**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:  
Non-AHERA

Management Planner's Signature:  Date: 06/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Brown Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 415**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Brown Streaks Floor Tile**  
MATERIAL LOCATION: **Room 415**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Brown Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 415**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Brown Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 415**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **Floor Tile Beneath 12" x 12" Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **Floor Tile Beneath 12" x 12" Floor Tile**  
MATERIAL LOCATION: **ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **Floor Tile Beneath 12" x 12" Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **Floor Tile Beneath 12" x 12" Floor Tile Mastic**  
MATERIAL LOCATION: **ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**  
MATERIAL DESCRIPTION: **Floor Tile Beneath 12" x 12" Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **108**  
MATERIAL DESCRIPTION: **Floor Tile Beneath 12" x 12" Floor Tile**  
MATERIAL LOCATION: **ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**  
MATERIAL DESCRIPTION: **Floor Tile Beneath 12" x 12" Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **109**  
MATERIAL DESCRIPTION: **Floor Tile Beneath 12" x 12" Floor Tile Mastic**  
MATERIAL LOCATION: **ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**  
MATERIAL DESCRIPTION: **Floor Tile Beneath 12" x 12" Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Cafeteria/Lunchroom**

MATERIAL QUANTITY: **4000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material in inaccessible area(s) - 2025  
Beneath Existing Tile**

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **110**  
MATERIAL DESCRIPTION: **Floor Tile Beneath 12" x 12" Floor Tile**  
MATERIAL LOCATION: **Cafeteria/Lunchroom**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified, continue O&M.

Management Planner's Signature:



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**  
MATERIAL DESCRIPTION: **Floor Tile Beneath 12" x 12" Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Cafeteria/Lunchroom**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material in inaccessible area(s) - 2025  
Beneath Existing Floor Tile**

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **111**  
MATERIAL DESCRIPTION: **Floor Tile Beneath 12" x 12" Floor Tile Mastic**  
MATERIAL LOCATION: **Cafeteria/Lunchroom**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified, continue O&M.

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**  
MATERIAL DESCRIPTION: **12" x 12" Aqua Floor Tile (Blue Linoleum)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 218**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **112**  
MATERIAL DESCRIPTION: **12" x 12" Aqua Floor Tile (Blue Linoleum)**  
MATERIAL LOCATION: **Room 218**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**  
MATERIAL DESCRIPTION: **12" x 12" Aqua Floor Tile Mastic (Blue Linoleum Mastic)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 218**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **113**  
MATERIAL DESCRIPTION: **12" x 12" Aqua Floor Tile Mastic (Blue Linoleum Mastic)**  
MATERIAL LOCATION: **Room 218**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114**  
MATERIAL DESCRIPTION: **Floor Tile Beneath 12" x 12" Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 210 and 212**

MATERIAL QUANTITY: **1550**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material in inaccessible area(s) - 2025  
Beneath Existing Tile**

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **114**  
MATERIAL DESCRIPTION: **Floor Tile Beneath 12" x 12" Floor Tile**  
MATERIAL LOCATION: **Rooms 210 and 212**  
MATERIAL QUANTITY: **1550** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified, continue O&M.

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115**  
MATERIAL DESCRIPTION: **Floor Tile Beneath 12" x 12" Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 210 and 212**

MATERIAL QUANTITY: **1550**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material in inaccessible area(s) - 2025  
Beneath Existing Tile**

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **115**  
MATERIAL DESCRIPTION: **Floor Tile Beneath 12" x 12" Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 210 and 212**  
MATERIAL QUANTITY: **1550** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified, continue O&M.

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116**  
MATERIAL DESCRIPTION: **Tan Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 315, 316, 302, 301, 201 Storage 215, 302A, 302B,**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **116**  
MATERIAL DESCRIPTION: **Tan Linoleum**  
MATERIAL LOCATION: **Rooms 315, 316, 302, 301, 201 Storage 215, 302A, 302B,**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117**  
MATERIAL DESCRIPTION: **Tan Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 315, 316, 302, 301, 201 Storage 215, 302A, 302B,**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **117**  
MATERIAL DESCRIPTION: **Tan Linoleum Mastic**  
MATERIAL LOCATION: **Rooms 315, 316, 302, 301, 201 Storage 215, 302A, 302B,**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118**  
MATERIAL DESCRIPTION: **Brown Ceramic Flooring and Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1, 2, 3, 4, Floors Boys & Girls Bathrooms**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **118**  
MATERIAL DESCRIPTION: **Brown Ceramic Flooring and Grout**  
MATERIAL LOCATION: **1, 2, 3, 4, Floors Boys & Girls Bathrooms**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **119**  
MATERIAL DESCRIPTION: **Brown Ceramic Flooring Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1, 2, 3, 4, Floors Boys & Girls Bathrooms**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **119**  
MATERIAL DESCRIPTION: **Brown Ceramic Flooring Mastic**  
MATERIAL LOCATION: **1, 2, 3, 4, Floors Boys & Girls Bathrooms**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **120**  
MATERIAL DESCRIPTION: **2' x 4' White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout School**  
MATERIAL QUANTITY: **200000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **120**  
MATERIAL DESCRIPTION: **2' x 4' White Ceiling Tile**  
MATERIAL LOCATION: **Throughout School**  
MATERIAL QUANTITY: **200000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 06/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **121**  
MATERIAL DESCRIPTION: **2' x 4' White Smooth Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Cafeteria, Room 412**  
MATERIAL QUANTITY: **12300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **121**  
MATERIAL DESCRIPTION: **2' x 4' White Smooth Ceiling Tile**  
MATERIAL LOCATION: **Cafeteria, Room 412**  
MATERIAL QUANTITY: **12300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **124**  
MATERIAL DESCRIPTION: **12" x 12" Off Beige Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 119**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **124**  
MATERIAL DESCRIPTION: **12" x 12" Off Beige Vinyl Floor Tile**  
MATERIAL LOCATION: **Room 119**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **125**  
MATERIAL DESCRIPTION: **12" x 12" Off Beige Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 119**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **125**  
MATERIAL DESCRIPTION: **12" x 12" Off Beige Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Room 119**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **126**  
MATERIAL DESCRIPTION: **12" x 12" Old Blotted Beige Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 118, Band Hall**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not found in 116, 117**

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **126**  
MATERIAL DESCRIPTION: **12" x 12" Old Blotted Beige Vinyl Floor Tile**  
MATERIAL LOCATION: **Room 118, Band Hall**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **127**  
MATERIAL DESCRIPTION: **12" x 12" Old Blotted Beige Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 118, Band Hall**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not found in 116, 117**

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **127**  
MATERIAL DESCRIPTION: **12" x 12" Old Blotted Beige Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Room 118, Band Hall**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **128**  
MATERIAL DESCRIPTION: **12" x 12" New Blotted Beige Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 118**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not found in 116, 117**

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **128**  
MATERIAL DESCRIPTION: **12" x 12" New Blotted Beige Vinyl Floor Tile**  
MATERIAL LOCATION: **Room 118**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **129**  
MATERIAL DESCRIPTION: **12" x 12" New Blotted Beige Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 118**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not found in 116, 117**

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **129**  
MATERIAL DESCRIPTION: **12" x 12" New Blotted Beige Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Room 118**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **130**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Speckles Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gym Office, 310 Offices, 307, 307, 307C, Metro Director Office,**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **130**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Speckles Vinyl Floor Tile**  
MATERIAL LOCATION: **Gym Office, 310 Offices, 307, 307, 307C, Metro Director Office,**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **131**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Speckles Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Gym Office, 310 Offices, 307, 307, 307C, Metro Director Office,**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **131**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Speckles Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Gym Office, 310 Offices, 307, 307, 307C, Metro Director Office,**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 06/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **132**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Choral Room 119**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **132**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Vinyl Floor Tile**  
MATERIAL LOCATION: **Choral Room 119**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **133**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Choral Room 119**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **133**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Choral Room 119**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **134**  
MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Brown Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Choral Room 119 Office**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **134**  
MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Brown Vinyl Floor Tile**  
MATERIAL LOCATION: **Choral Room 119 Office**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **135**  
MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Brown Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Choral Room 119 Office**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **135**  
MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Brown Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Choral Room 119 Office**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **136**  
MATERIAL DESCRIPTION: **Blue Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 109, 110**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **136**  
MATERIAL DESCRIPTION: **Blue Linoleum**  
MATERIAL LOCATION: **Room 109, 110**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 06/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **137**  
MATERIAL DESCRIPTION: **Blue Linoleum Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 109, 110**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **137**  
MATERIAL DESCRIPTION: **Blue Linoleum Adhesive**  
MATERIAL LOCATION: **Room 109, 110**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **138**  
MATERIAL DESCRIPTION: **12" x 12" Brown Texture Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Ramp Outside the Library**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **138**  
MATERIAL DESCRIPTION: **12" x 12" Brown Texture Vinyl Floor Tile**  
MATERIAL LOCATION: **Ramp Outside the Library**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 06/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **139**  
MATERIAL DESCRIPTION: **12" x 12" Brown Texture Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Ramp Outside the Library**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **139**  
MATERIAL DESCRIPTION: **12" x 12" Brown Texture Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Ramp Outside the Library**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **140**  
MATERIAL DESCRIPTION: **12" x 12" Red Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd, 3rd, and 4th Floors Corridors**  
MATERIAL QUANTITY: **65000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **140**  
MATERIAL DESCRIPTION: **12" x 12" Red Vinyl Floor Tile**  
MATERIAL LOCATION: **2nd, 3rd, and 4th Floors Corridors**  
MATERIAL QUANTITY: **65000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **141**  
MATERIAL DESCRIPTION: **12" x 12" Red Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd, 3rd, and 4th Floor Corridors**  
MATERIAL QUANTITY: **65000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **141**  
MATERIAL DESCRIPTION: **12" x 12" Red Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **2nd, 3rd, and 4th Floor Corridors**  
MATERIAL QUANTITY: **65000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **142**  
MATERIAL DESCRIPTION: **12" x 12" Mustard Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 260, 260A**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **142**  
MATERIAL DESCRIPTION: **12" x 12" Mustard Vinyl Floor Tile**  
MATERIAL LOCATION: **Room 260, 260A**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **143**  
MATERIAL DESCRIPTION: **12" x 12" Mustard Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 260, 260A**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **143**  
MATERIAL DESCRIPTION: **12" x 12" Mustard Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Room 260, 260A**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **144**  
MATERIAL DESCRIPTION: **White Sink Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 210**

MATERIAL QUANTITY: **2**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **144**  
MATERIAL DESCRIPTION: **White Sink Insulation**  
MATERIAL LOCATION: **Room 210**  
MATERIAL QUANTITY: **2** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46641**    BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School**    INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson**    IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **145**  
MATERIAL DESCRIPTION: **Trapezoid Lab Counters**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 215, 216, 315, 316**  
MATERIAL QUANTITY: **80**    MATERIAL UNITS:  
DAMAGE QUANTITY:    DAMAGE UNITS:  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **145**  
MATERIAL DESCRIPTION: **Trapezoid Lab Counters**  
MATERIAL LOCATION: **Room 215, 216, 315, 316**  
MATERIAL QUANTITY: **80** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **146**  
MATERIAL DESCRIPTION: **3' x 5' Lab Counter**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 318**

MATERIAL QUANTITY: **20**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **146**  
MATERIAL DESCRIPTION: **3' x 5' Lab Counter**  
MATERIAL LOCATION: **Room 318**  
MATERIAL QUANTITY: **20** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **147**  
MATERIAL DESCRIPTION: **4' x 8' Lab Counters**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 103, 102**  
MATERIAL QUANTITY: **20** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **147**  
MATERIAL DESCRIPTION: **4' x 8' Lab Counters**  
MATERIAL LOCATION: **Room 103, 102**  
MATERIAL QUANTITY: **20** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 06/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **148**  
MATERIAL DESCRIPTION: **12" x 12" Red Mottled Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 411, 412, 413, 261**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **148**  
MATERIAL DESCRIPTION: **12" x 12" Red Mottled Vinyl Floor Tile**  
MATERIAL LOCATION: **Room 411, 412, 413, 261**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 06/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **149**  
MATERIAL DESCRIPTION: **12" x 12" Red Mottled Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 411, 412, 413, 261**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **149**  
MATERIAL DESCRIPTION: **12" x 12" Red Mottled Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Room 411, 412, 413, 261**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **150**  
MATERIAL DESCRIPTION: **Green Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 108, 219,**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **150**  
MATERIAL DESCRIPTION: **Green Carpet Adhesive**  
MATERIAL LOCATION: **Room 108, 219,**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **151**  
MATERIAL DESCRIPTION: **12" x 12" Brown w/ Light Spots Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **West Elevator Lobby, 1st Floor MDF Room, Rooms 403, 405, 205, 205a, 200, West Med Room, 2nd Floor Hallway, Lecture Hallway, 440a, 219, Storage Across Room 400, 3rd Floor Kitchen Staff Bathroom, 2nd Floor Storage by West Elevators, 114D**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS: **Damage in 405**

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **151**  
MATERIAL DESCRIPTION: **12" x 12" Brown w/ Light Spots Floor Tile**  
MATERIAL LOCATION: **West Elevator Lobby, 1st Floor MDF Room, Rooms 403, 405, 205, 205a, 200, West Med Room, 2nd Floor Hallway, Lecture Hallway, 440a, 219, Storage Across Room 400, 3rd Floor Kitchen Staff Bathroom, 2nd Floor Storage by West Elevators, 114D**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **40** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Sample to determine ACM content, remove or repair to intact.

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **152**  
MATERIAL DESCRIPTION: **12" x 12" Brown w/ Light Spots Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **West Elevator Lobby, 1st Floor Mdf Room, Rooms 403, 405, 205, 205a, 200, West Med Room, 2nd Floor Hallway, Lecture Hallway, 440a, 219, Storage Across Room 400, 3rd Floor Kitchen Staff Bathroom, 2nd Floor Storage by West Elevators, 114D,**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **152**  
MATERIAL DESCRIPTION: **12" x 12" Brown w/ Light Spots Floor Tile Mastic**  
MATERIAL LOCATION: **West Elevator Lobby, 1st Floor Mdf Room, Rooms 403, 405, 205, 205a, 200, West Med Room, 2nd Floor Hallway, Lecture Hallway, 440a, 219, Storage Across Room 400, 3rd Floor Kitchen Staff Bathroom, 2nd Floor Storage by West Elevators, 114D,**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **153**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ Spots Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 312, 313, 300, 303-306, 201, 211, 213, 214, 250, 216, 217, 251, 200, 201-204, 114D**

MATERIAL QUANTITY: **8000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **153**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ Spots Floor Tile**  
MATERIAL LOCATION: **Rooms 312, 313, 300, 303-306, 201, 211, 213, 214, 250, 216, 217, 251, 200, 201-204, 114D**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **154**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ Spots Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 312, 313, 300, 303-306, 201, 211, 213, 214, 250, 216, 217, 251, 200, 201-204, 114D**

MATERIAL QUANTITY: **8000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **154**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ Spots Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 312, 313, 300, 303-306, 201, 211, 213, 214, 250, 216, 217, 251, 200, 201-204, 114D**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **155**  
MATERIAL DESCRIPTION: **12" x 12" Turquoise Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 206a**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **155**  
MATERIAL DESCRIPTION: **12" x 12" Turquoise Floor Tile**  
MATERIAL LOCATION: **Room 206a**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **156**  
MATERIAL DESCRIPTION: **12" x 12" Turquoise Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 206a**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **156**  
MATERIAL DESCRIPTION: **12" x 12" Turquoise Floor Tile Mastic**  
MATERIAL LOCATION: **Room 206a**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **157**  
MATERIAL DESCRIPTION: **12" x 12" Blue w/ Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 101 Kitchen**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **157**  
MATERIAL DESCRIPTION: **12" x 12" Blue w/ Streaks Floor Tile**  
MATERIAL LOCATION: **Room 101 Kitchen**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **158**  
MATERIAL DESCRIPTION: **12" x 12" Blue w/ Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 101 Kitchen**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **158**  
MATERIAL DESCRIPTION: **12" x 12" Blue w/ Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 101 Kitchen**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **159**  
MATERIAL DESCRIPTION: **2' x 2' Gray Carpet Square Glue**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 103 and 105**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **159**  
MATERIAL DESCRIPTION: **2' x 2' Gray Carpet Square Glue**  
MATERIAL LOCATION: **Rooms 103 and 105**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Zinc**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Not Tested** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **First Floor Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Zinc**

MATERIAL LOCATION: **First Floor Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **161**  
MATERIAL DESCRIPTION: **12" x 12" Blue w/ Blue Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **2nd Floor Faculty Lounge**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **161**  
MATERIAL DESCRIPTION: **12" x 12" Blue w/ Blue Streaks Floor Tile**  
MATERIAL LOCATION: **2nd Floor Faculty Lounge**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **161M**  
MATERIAL DESCRIPTION: **12" x 12" Blue w/ Blue Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd Floor Faculty Lounge**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **161M**  
MATERIAL DESCRIPTION: **12" x 12" Blue w/ Blue Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **2nd Floor Faculty Lounge**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **162**  
MATERIAL DESCRIPTION: **12" x 12" Light Green w/ Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Foyer Outside Rooms 218, 209**  
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **162**  
MATERIAL DESCRIPTION: **12" x 12" Light Green w/ Streaks Floor Tile**  
MATERIAL LOCATION: **Foyer Outside Rooms 218, 209**  
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **162M**  
MATERIAL DESCRIPTION: **12" x 12" Light Green w/ Streaks Floor Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Foyer Outside Room 218, 209**

MATERIAL QUANTITY: **70**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **162M**  
MATERIAL DESCRIPTION: **12" x 12" Light Green w/ Streaks Floor Tile Adhesive**  
MATERIAL LOCATION: **Foyer Outside Room 218, 209**  
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **163**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 212, Main Office, 214 (Patches)**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **163**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Specks Floor Tile**  
MATERIAL LOCATION: **Room 212, Main Office, 214 (Patches)**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **163M**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Specks Floor Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 212, Main Office, 214 (Patches)**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **163M**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Specks Floor Tile Adhesive**  
MATERIAL LOCATION: **Room 212, Main Office, 214 (Patches)**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **164**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ White Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **201a, Security Office**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **164**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ White Specks Floor Tile**  
MATERIAL LOCATION: **201a, Security Office**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **164M**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ White Specks Floor Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **201a, Security Office**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **164M**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ White Specks Floor Tile Adhesive**  
MATERIAL LOCATION: **201a, Security Office**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **165**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Cream Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Kitchen Storage Room, Security Office**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **165**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Cream Specks Floor Tile**  
MATERIAL LOCATION: **Kitchen Storage Room, Security Office**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **165M**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Cream Specks Floor Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen Storage Room, Security Office**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **165M**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Cream Specks Floor Tile Adhesive**  
MATERIAL LOCATION: **Kitchen Storage Room, Security Office**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **166**  
MATERIAL DESCRIPTION: **Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **2 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **2. Damaged friable surfacing ACBM**

DAMAGE REASON: **Deterioration  
Physical Damage  
Vibration**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **4th Floor Hallway, 412, 411, 410, 409, 414A, 408, 407, 406, 405, 404, 403, 402, 401, 400, 443, 442, 441, 440, 439, 438, 437, 436, 435, 434, 433, 432, 427, 431, 428, 430, 450, 3rd Floor Hallway, 309, 310, 308, Cafeteria, 311, 312, 313, 314, 315, 317, 317A, 316, 350C, 321, 350A, 350B, 300, 301, 302, 302A, 302B, 303, 305, 306, 307, 416, 417, 419, 418, 421, 420, 422, 423, 425, 213, 215, 216, 217, 218, 200, 201, 202, 203, 204, 205, 206A, 206, Library 207, 260, 260A, 261, 114D, 114, 115, Engineers Office**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Damage found in: Room 405, First Floor Southwest Hallway Near Elevator**

Inspector's Signature: \_\_\_\_\_



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **166**  
MATERIAL DESCRIPTION: **Plaster**  
MATERIAL LOCATION: **4th Floor Hallway, 412, 411, 410, 409, 414A, 408, 407, 406, 405, 404, 403, 402, 401, 400, 443, 442, 441, 440, 439, 438, 437, 436, 435, 434, 433, 432, 427, 431, 428, 430, 450, 3rd Floor Hallway, 309, 310, 308, Cafeteria, 311, 312, 313, 314, 315, 317, 317A, 316, 350C, 321, 350A, 350B, 300, 301, 302, 302A, 302B, 303, 305, 306, 307, 416, 417, 419, 418, 421, 420, 422, 423, 425, 213, 215, 216, 217, 218, 200, 201, 202, 203, 204, 205, 206A, 206, Library 207, 260, 260A, 261, 114D, 114, 115, Engineers Office**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **45** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Sample to determine ACM content, remove or repair damaged surfacing material to intact.

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **167**  
MATERIAL DESCRIPTION: **Plaster on Ceiling**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Basement**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **167**  
MATERIAL DESCRIPTION: **Plaster on Ceiling**  
MATERIAL LOCATION: **Basement**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **168**  
MATERIAL DESCRIPTION: **12" x 12" Tan w/ Black Dots Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 321**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **168**  
MATERIAL DESCRIPTION: **12" x 12" Tan w/ Black Dots Vinyl Floor Tile**  
MATERIAL LOCATION: **Room 321**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **169**  
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 321**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **169**  
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile**  
MATERIAL LOCATION: **Room 321**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 06/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **170**  
MATERIAL DESCRIPTION: **12" x 12" Tan w/ Black Dots Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 321**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **170**  
MATERIAL DESCRIPTION: **12" x 12" Tan w/ Black Dots Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Room 321**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **171**  
MATERIAL DESCRIPTION: **White w/ Brown Flower Design Acoustical Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 321**

MATERIAL QUANTITY: **5000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **171**  
MATERIAL DESCRIPTION: **White w/ Brown Flower Design Acoustical Ceiling Tile**  
MATERIAL LOCATION: **Room 321**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **172**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Black & Gray Speckled Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 301, 215, 202**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **172**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Black & Gray Speckled Vinyl Floor Tile**  
MATERIAL LOCATION: **Rooms 301, 215, 202**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **173**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/ Black Speckled Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 301, 215, 202**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **173**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/ Black Speckled Vinyl Floor Tile**  
MATERIAL LOCATION: **Rooms 301, 215, 202**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **174**  
MATERIAL DESCRIPTION: **12" x 12" Blue w/ Black & Brown Speckled Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 301, 215, 202**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **174**  
MATERIAL DESCRIPTION: **12" x 12" Blue w/ Black & Brown Speckled Vinyl Floor Tile**  
MATERIAL LOCATION: **Rooms 301, 215, 202**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **175**  
MATERIAL DESCRIPTION: **12" x 12" Blue w/ Black & Brown Speckled, Gray w/ Black Speckled, & White w/ Black & Gray Speckled Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 301, 215, 202**

MATERIAL QUANTITY: **3600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **175**  
MATERIAL DESCRIPTION: **12" x 12" Blue w/ Black & Brown Speckled, Gray w/ Black Speckled, & White w/ Black & Gray Speckled Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 301, 215, 202**  
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **176**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Blue & Pink Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 209**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **176**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Blue & Pink Streaks Floor Tile**  
MATERIAL LOCATION: **Room 209**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **177**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Blue & Pink Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 209**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **177**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Blue & Pink Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 209**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **178**  
MATERIAL DESCRIPTION: **Tongue and Groove Wooden Floor**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gymnasium, 163 Gym**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **178**  
MATERIAL DESCRIPTION: **Tongue and Groove Wooden Floor**  
MATERIAL LOCATION: **Gymnasium, 163 Gym**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **179**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Blue Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 261**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **179**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Blue Streaks Floor Tile**  
MATERIAL LOCATION: **Room 261**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **180**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Blue Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 261**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **180**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Blue Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 261**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **181**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ Dark Brown and White Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 261**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **181**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ Dark Brown and White Specks Floor Tile**  
MATERIAL LOCATION: **Room 261**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **182**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ Dark Brown and White Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 261**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **182**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ Dark Brown and White Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 261**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **183**  
MATERIAL DESCRIPTION: **Marble Flooring**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Corridor Entrance**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **183**  
MATERIAL DESCRIPTION: **Marble Flooring**  
MATERIAL LOCATION: **1st Floor Corridor Entrance**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **184**  
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 321**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **184**  
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile Mastic**  
MATERIAL LOCATION: **Room 321**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Paint (Not Textured)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Not Tested** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Paint (Not Textured)**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **6" Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Original Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **6" Baseboard**

MATERIAL LOCATION: **Throughout Original Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **Material Under Carpet**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 413**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material in inaccessible area(s) - 2025  
Beneath Existing Carpet**

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **Material Under Carpet**

MATERIAL LOCATION: **Room 413**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified, continue O&M.

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Fiberglass Duct Cement**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Fiberglass Duct Cement**  
MATERIAL LOCATION: **ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AA**  
MATERIAL DESCRIPTION: **Hard Joint Compound on Fiberglass Pipe Runs**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room, Pump Room, Old Glass Shop & Throughout Basement**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **AA**  
MATERIAL DESCRIPTION: **Hard Joint Compound on Fiberglass Pipe Runs**  
MATERIAL LOCATION: **Boiler Room, Pump Room, Old Glass Shop & Throughout Basement**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AB**  
MATERIAL DESCRIPTION: **Hard Joint Compound Off 15" Steam Line**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **AB**  
MATERIAL DESCRIPTION: **Hard Joint Compound Off 15" Steam Line**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AC**  
MATERIAL DESCRIPTION: **Hard Joint Compound Off Steam Supply**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auto Shop**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **AC**  
MATERIAL DESCRIPTION: **Hard Joint Compound Off Steam Supply**  
MATERIAL LOCATION: **Auto Shop**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AD**  
MATERIAL DESCRIPTION: **Hard Joint Compound on Fiberglass Piping**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **AD**  
MATERIAL DESCRIPTION: **Hard Joint Compound on Fiberglass Piping**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AE**  
MATERIAL DESCRIPTION: **Boiler Breeching**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **AE**  
MATERIAL DESCRIPTION: **Boiler Breeching**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 06/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AF**  
MATERIAL DESCRIPTION: **Paper Wrap on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **New Addition Locker Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **AF**

MATERIAL DESCRIPTION: **Paper Wrap on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **New Addition Locker Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AG**  
MATERIAL DESCRIPTION: **Insulation Wrap**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **AG**  
MATERIAL DESCRIPTION: **Insulation Wrap**  
MATERIAL LOCATION: **2nd Floor Fan Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AH**  
MATERIAL DESCRIPTION: **Cementitious Joint Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **See Ha - Ak**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **AH**  
MATERIAL DESCRIPTION: **Cementitious Joint Insulation**  
MATERIAL LOCATION: **See Ha - Ak**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AI**  
MATERIAL DESCRIPTION: **Cementitious Joint Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **New Addition Locker Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **AI**  
MATERIAL DESCRIPTION: **Cementitious Joint Insulation**  
MATERIAL LOCATION: **New Addition Locker Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 06/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AJ**  
MATERIAL DESCRIPTION: **Internal Duct Liner**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **AJ**

MATERIAL DESCRIPTION: **Internal Duct Liner**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AK**  
MATERIAL DESCRIPTION: **Cementitious Joint Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement of New Addition and Girls Bathroom Plumbing Wall, 1sr, 2nd, 3rd Floors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **AK**  
MATERIAL DESCRIPTION: **Cementitious Joint Insulation**  
MATERIAL LOCATION: **Basement of New Addition and Girls Bathroom Plumbing Wall, 1sr, 2nd, 3rd Floors**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Fiberglass Insulation Cement**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Not Tested** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Attic**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Fiberglass Insulation Cement**

MATERIAL LOCATION: **Attic**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Preformed Pipe Insulation (Mag Block)**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room & Gym**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Preformed Pipe Insulation (Mag Block)**  
MATERIAL LOCATION: **Boiler Room & Gym**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Wall Chase**  
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Basement Wall Chase**  
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46641**    BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School**    INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson**    IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Stored Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: **ABATED**  
MATERIAL QUANTITY:    MATERIAL UNITS:  
DAMAGE QUANTITY:    DAMAGE UNITS:  
COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Stored Cardboard Pipe Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Spray-on Fireproofing**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Damaged friable surfacing ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor Fan Room, above 4th Floor Ceilings**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Spray-on Fireproofing**  
MATERIAL LOCATION: **2nd Floor Fan Room, above 4th Floor Ceilings**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Vault Door Liners**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Facility Including: Coach's Office, 2nd & 3rd Floor Corridors by Elevator**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Vault Door Liners**  
MATERIAL LOCATION: **Throughout Facility Including: Coach's Office, 2nd & 3rd Floor Corridors by Elevator**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Coated Screens**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Coated Screens**  
MATERIAL LOCATION: **ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Kiln Liner**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Art Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Kiln Liner**  
MATERIAL LOCATION: **Art Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Boiler Insulation Under Metal Jackets**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Boiler Insulation Under Metal Jackets**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Boiler Rope**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Boiler Rope**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **Hard Fittings on Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **Hard Fittings on Aircell Pipe Insulation**  
MATERIAL LOCATION: **Basement**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **Stored Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Not Tested** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **Stored Insulation**  
MATERIAL LOCATION: **Basement**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **Insulation Beneath Shell Of Incinerator**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Insulation Beneath Shell Of Incinerator**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **Incinerator Fire Brick**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **O**  
MATERIAL DESCRIPTION: **Incinerator Fire Brick**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **Insulation Beneath Shell Of Sellers Tank**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **Insulation Beneath Shell Of Sellers Tank**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **Vibration Collars**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **Vibration Collars**  
MATERIAL LOCATION: **Basement**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **Black Backing on Fiberglass Lighters**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **Black Backing on Fiberglass Lighters**  
MATERIAL LOCATION: **ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **Hard Joint Compound Off Absorption Chiller Piping**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **Hard Joint Compound Off Absorption Chiller Piping**  
MATERIAL LOCATION: **2nd Floor Fan Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **Fittings Off Chiller Pumps Piping**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **Fittings Off Chiller Pumps Piping**  
MATERIAL LOCATION: **2nd Floor Fan Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **U**  
MATERIAL DESCRIPTION: **Vibration Collars (Cloth)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **U**  
MATERIAL DESCRIPTION: **Vibration Collars (Cloth)**  
MATERIAL LOCATION: **2nd Floor Fan Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **V**  
MATERIAL DESCRIPTION: **Canvas Cloth Off Fan Units**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **V**  
MATERIAL DESCRIPTION: **Canvas Cloth Off Fan Units**  
MATERIAL LOCATION: **2nd Floor Fan Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **W**  
MATERIAL DESCRIPTION: **Hard Joint Compound on Water Cooler Piping**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **W**  
MATERIAL DESCRIPTION: **Hard Joint Compound on Water Cooler Piping**  
MATERIAL LOCATION: **2nd Floor Fan Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jackson Montgomery*

Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **X**  
MATERIAL DESCRIPTION: **(Interior) Boiler Packing**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **X**  
MATERIAL DESCRIPTION: **(Interior) Boiler Packing**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Y**  
MATERIAL DESCRIPTION: **Hard Joint Compound on Valve Pump Piping**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **Y**

MATERIAL DESCRIPTION: **Hard Joint Compound on Valve Pump Piping**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Z**  
MATERIAL DESCRIPTION: **Hard Joint Compound on Fiberglass Reheat Piping**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Plenum Chamber**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/30/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

HOMOGENEOUS AREA: **Z**

MATERIAL DESCRIPTION: **Hard Joint Compound on Fiberglass Reheat Piping**

MATERIAL LOCATION: **Plenum Chamber**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**



# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **188**  
MATERIAL DESCRIPTION: **12" x 12" Light Blue Mottled Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 412, 411**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025



# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **189**  
MATERIAL DESCRIPTION: **12" x 12" Green Mottled Vinyl Floor Tile**  
MATERIAL LOCATION: **Rooms 412, 411**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**



# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46641**      BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School**      REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson**      IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **192**  
MATERIAL DESCRIPTION: **12" x 12" Orange Mottled Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 412, 411**  
MATERIAL QUANTITY: **300**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**



# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **191**

MATERIAL DESCRIPTION: **12" x 12" Orange Mottled Vinyl Floor Tile**

MATERIAL LOCATION: **Rooms 412, 411**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY:  DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**



# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **196**  
MATERIAL DESCRIPTION: **12" x 12" Yellow Mottled Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 412, 411**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**



# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46641**      BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School**      REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson**      IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **187**  
MATERIAL DESCRIPTION: **12" x 12" Light Blue Mottled Vinyl Floor Tile**  
MATERIAL LOCATION: **Rooms 412, 411**  
MATERIAL QUANTITY: **400**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**



# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **185**  
MATERIAL DESCRIPTION: **12" x 12" Blue Mottled Vinyl Floor Tile**  
MATERIAL LOCATION: **Rooms 261, 412**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**



# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46641**      BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School**      REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson**      IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **186**

MATERIAL DESCRIPTION: **12" x 12" Blue Mottled Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 261, 412**

MATERIAL QUANTITY: **800**      MATERIAL UNITS: **SF**

DAMAGE QUANTITY:      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**



# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **195**  
MATERIAL DESCRIPTION: **12" x 12" Yellow Mottled Vinyl Floor Tile**  
MATERIAL LOCATION: **Rooms 412, 411**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUIDLING ID: **1270**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Cody Cummins**  
SCHOOL NAME: **Crane Tech High School** INSPECTION DATE: **5/30/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **194**  
MATERIAL DESCRIPTION: **12" x 12" Off-White Mottled Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 412, 411**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC** FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:  
DAMAGE QUANTITY: DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/30/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **194**  
MATERIAL DESCRIPTION: **12" x 12" Off-White Mottled Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 412, 411**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**



# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46641**      BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School**      REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson**      IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **190**  
MATERIAL DESCRIPTION: **12" x 12" Green Mottled Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 412, 411**  
MATERIAL QUANTITY: **300**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:       Date: **06/16/2025**



# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46641** BUILDING ID: **1270**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**  
SCHOOL NAME: **Crane Tech High School** REVIEW DATE: **6/16/2025**  
ADDRESS: **2245 W. Jackson** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **193**

MATERIAL DESCRIPTION: **12" x 12" Off-White Mottled Vinyl Floor Tile**

MATERIAL LOCATION: **Rooms 412, 411**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **200** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# APPENDIX B

## Inspector and Management Planner Licenses

---



2200 Vandalia Street, Collinsville, IL 62234 \* Phone: 618-855-8764

**Environmental and Occupational Safety & Health Training**

*Does hereby certify*

**Cody Cummins**

600 W. Van Buren St., Suite 500, Chicago, IL 60607



*Has successfully completed and passed the course examination with at least  
70% for accreditation under AHERA (Title II)*

**Asbestos Management Planner Initial**

**Class Date:** 10/28-29/2024  
**Examination Date:** 10/29/2024  
**STC Certificate Number:** STC-20241029-000103AMPI  
**Certification Expiration:** 10/29/2025

David M. Mendoza – President/Training Director  
Certified Environmental Specialist  
OSHA Authorized Instructor

# Cody Cummins

Illinois Licensed Building Inspector, Air Sampling Professional, Management Planner

 **ASBESTOS PROFESSIONAL LICENSE**

ID NUMBER: 100 - 20994  
ISSUED: 10/23/2024  
EXPIRES: 05/15/2025

CODY D CUMMINS  
11761 CAMELOT LANE  
ORLAND PARK, IL 60467  
Environmental Health



**ENDORSEMENTS**

INSPECTOR

**TC EXPIRES**

3/8/2025

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid training course certificate.

 **ASBESTOS PROFESSIONAL LICENSE**

ID NUMBER: 100 - 20994  
ISSUED: 2/19/2025  
EXPIRES: 05/15/2026

CODY D CUMMINS  
11761 CAMELOT LANE  
ORLAND PARK, IL 60467  
Environmental Health



**ENDORSEMENTS**

MANAGEMENT PLANNER

**TC EXPIRES**

10/29/2025

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid training course certificate.



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

**2025**

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

## Cody Cummins

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. This course is accredited by the State of Wisconsin, Department of Health Services under ch. DHS 159, Wis. Admin. Code, The Illinois Department of Public Health and The Indiana Department of Environmental Management, under 326 IAC 18. Training was in accordance with requirements listed under EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Location: 12304 75th Street  
Kenosha, WI 53142

Certificate Number: BIRWI2502280827  
Course Date: 2/28/2025  
Exam Date: 2/28/2025  
Expiration Date: 2/28/2026



Issue Date: 2/28/2025

A handwritten signature in blue ink, appearing to read 'Tyler', written over a horizontal line.

Tyler Nicholson, Authorized Signer

Course Credit Hours: BIR WI 4 Hours

# Jackson Montgomery

Illinois Licensed Building Inspector, Air Sampling Professional, Management Planner

**IDPH** ASBESTOS PROFESSIONAL LICENSE

ID NUMBER	ISSUED	EXPIRES
100 - 20634	5/1/2024	05/15/2025

JACKSON D MONTGOMERY  
150 BERKSHIRE DR  
DEKALB, IL 60115  
Environmental Health



<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
INSPECTOR	2/22/2025

AIR SAMPLING PROFESSIONAL  
**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid training course certificate.

**IDPH** ASBESTOS PROFESSIONAL LICENSE

ID NUMBER	ISSUED	EXPIRES
100 - 20634	2/4/2025	05/15/2026

JACKSON D MONTGOMERY  
150 BERKSHIRE DR  
DEKALB, IL 60115  
Environmental Health



<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
MANAGEMENT PLANNER	10/29/2025

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid training course certificate.



2200 Vandalia Street, Collinsville, IL 62234 \* Phone: 618-855-8764

Environmental and Occupational Safety & Health Training

*Does hereby certify*

**Jackson Montgomery**

600 W. Van Buren St., Suite 500, Chicago, IL 60607



*Has successfully completed and passed the course examination with at least  
70% for accreditation under AHERA (Title II)*

**Asbestos Management Planner Initial**

*Class Date:* 10/28-29/2024  
*Examination Date:* 10/29/2024  
*STC Certificate Number:* STC-20241029-000101AMPI  
*Certification Expiration:* 10/29/2025

David M. Mendoza – President/Training Director  
Certified Environmental Specialist  
OSHA Authorized Instructor

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed