

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0029
SCHOOL NAME: Marshall High School
ADDRESS OF SCHOOL: 3250 W. Adams
CITY: Chicago, IL, 60624

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 7/1/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 6/27/2025 ENROLLMENT 226
IDPH INSPECTOR LICENSE NUMBER: 100-09969
IDPH LICENSED INSPECTOR NAME (Please Print): Dionne Carey Walker
IDPH MP LICENSE NUMBER: 100-20634
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jackson Montgomery

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 7/23/2025

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Marshall High School

3250 W. Adams
Chicago, IL, 60624

Unit: 47041
Building ID: 1470

IDPH ID Number: 14-016-2990-0029

REPORT DATE:
Wednesday, July 23, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

07/23/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 47041 Region: 03 IDPH ID: 14-016-2990-0029

School: Marshall High School Building ID: 1470

Address: 3250 W. Adams

Chicago, IL, 60624

Building Contact: Sell, David Contact Phone: 7734260465

Current Building Owners: Chicago Public Schools

Reinspection Date: 6/27/2025

Review Date: 07/23/2025

Inspector: Dionne Carey Walker

Inspector IDPH License: 100-09969

Management Planner: Jackson Montgomery

Management Planner IDPH License: 100-20634

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Jackson Montgomery
100-20634

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: July 23, 2025

RE: Marshall High School, Unit 47041
3250 W. Adams
Chicago, IL, 60624

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Marshall High School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Marshall High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J. Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074.

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Marshall High School Unit: 47041 Region: 03
Address: 3250 W. Adams Chicago, IL, 60624
IDPH ID: 14-016-2990-0029 Building ID: 1470
Contact: Sell, David Phone: 7734260465

2. Description of Facility

Original Construction: 1916 Additional Construction: 1928
Total Square Footage: 80659 No of Floors: 3
Current Occupancy: 226

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Dionne Carey Walker



Signature: Date: 6/27/2025

Inspector IDPH license # 100-09969
Reinspection Date: 6/27/2025

6. Management Planner

Management Planner Name: Jackson Montgomery



Signature: Date: 07/23/2025

Management Planner IDPH license # 100-20634

7. Review Date: 07/23/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.



Signature:

Date: 7/23/2025

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Marshall High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

- A. The following HAs have changed assessment categories for Building 1470:

B. The following new homogenous areas have been identified for Building 1470:

117 Smooth Gray Linoleum

118 Smooth Gray Linoleum Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

| | |
|------|---|
| 10 M | Dark Brown Linoleum Mastic |
| 100 | Beige Linoleum |
| 101 | Beige Linoleum Adhesive |
| 102 | Gray and Tan Terrazzo |
| 103 | 12" x 12" Red Floor Tile |
| 104 | 12" x 12" Red Floor Tile Mastic |
| 105 | 12" x 12" White w/ Brown Specks Floor Tile |
| 106 | 12" x 12" White w/ Brown Specks Floor Tile Mastic |
| 107 | 12" x 12" Light Brown Floor Tile |
| 108 | 12" x 12" Light Brown Floor Tile Mastic |
| 109 | Light Blue Linoleum |
| 11 | 9" x 9" Green w/ White Specks Floor Tile |
| 110 | Light Blue Linoleum Mastic |
| 111 | Textured Gray Linoleum |
| 112 | Textured Gray Linoleum Mastic |
| 113 | 12" x 12" Charcoal Floor Tile |
| 114 | 12" x 12" Charcoal Floor Tile Mastic |
| 115 | 12" x 12" Brown Mottled Floor Tile |
| 116 | 12" x 12" Brown Mottled Floor Tile Mastic |
| 117 | Smooth Gray Linoleum |
| 118 | Smooth Gray Linoleum Mastic |
| 17 | Insulation Inside Of Vault Door |
| 18 | Carpet Mastic |
| 18 A | Purple & White Mix Carpet Mastic |
| 18 B | Orange Carpet Mastic |
| 18 C | Blue w/ Brown Carpet w/ Mastic |
| 18 D | Blue Carpet Mastic |
| 18 F | Lavender Carpet Mastic |
| 18 G | Black and Green Carpet Mastic |
| 18 H | Blue Patterned Carpet Mastic |
| 18 I | Blue Mix Carpet Mastic |
| 18 J | Gray Carpet Mastic |
| 18 K | Brown Mix Carpet Mastic |
| 21 | Roofing Material - Non-AHERA |
| 24 | Fire Door Lining |
| 26 | 9" x 9" Light Green Floor Tile Mastic |
| 4 | 12" x 12" Black w/ Brown Streaks Floor Tile |
| 53 | 12" x 12" Dark Brown w/ White & Black Specks Floor Tile |
| 54 | 12" x 12" Light Brown w/ Red & White Specks Floor Tile |
| 65 | 12" x 12" Olive w/ Brown & White Specks Floor |

| | |
|-----|--|
| | Tile |
| 66 | 12" x 12" White w/ Brown & Gray Streaks Floor Tile |
| 67 | 12" x 12" Light Brown w/ Red & White Streaks Floor Tile |
| 7 | 12" x 12" Gray w/ Brown & White Streaks Floor Tile |
| 7M | 12" x 12" Gray w/ Brown & White Streaks Floor Tile Mastic |
| 8 | 12" x 12" Light Brown w/ Red & White Streaks Floor Tile Mastic |
| 82 | Vault Door Liner |
| 83 | 12" x 12" Gray w/ Brown Specks Floor Tile |
| 84 | 12" x 12" Gray w/ Brown Specks Floor Tile Mastic |
| 85 | 12" x 12" Beige Mix Floor Tile |
| 86 | 12" x 12" Beige Mix Floor Tile Mastic |
| 87 | 12" x 12" White w/ Gray Streaks Floor Tile |
| 88 | 12" x 12" White w/ Gray Streaks Floor Tile Mastic |
| 89 | 12" x 12" Gray Mix Floor Tile |
| 9 M | Orange Linoleum Mastic |
| 90 | 12" x 12" Gray Mix Floor Tile Mastic |
| 91 | 12" x 12" White w/ Gray Streaks Floor Tile |
| 92 | 12" x 12" White w/ Gray Streaks Floor Tile Mastic |
| 93 | 12" x 12" Pink/Purple Speckled Floor Tile |
| 94 | 12" x 12" Pink/Purple Speckled Floor Tile Mastic |
| 95 | 2' x 4' White Ceiling Tile |
| 96 | 4" Brown Vinyl Baseboard |
| 97 | 4" Brown Vinyl Baseboard Adhesive |
| 98 | Red Stage Curtain |
| 99 | Orange Carpet Adhesive |
| A | Blue Linoleum Flooring |
| A-1 | Blue Linoleum Flooring-Mastic |
| B | 12" x 12" Blue Vinyl Floor Tile |
| B-1 | 12" x 12" Blue Vinyl Floor Tile Mastic |

The following areas were deemed to be inaccessible:

| | |
|-----|---|
| 101 | Beige Linoleum Adhesive |
| 104 | 12" x 12" Red Floor Tile Mastic |
| 106 | 12" x 12" White w/ Brown Specks Floor Tile Mastic |
| 108 | 12" x 12" Light Brown Floor Tile Mastic |
| 110 | Light Blue Linoleum Mastic |
| 112 | Textured Gray Linoleum Mastic |
| 114 | 12" x 12" Charcoal Floor Tile Mastic |
| 116 | 12" x 12" Brown Mottled Floor Tile Mastic |
| 118 | Smooth Gray Linoleum Mastic |

| | |
|------|--|
| 17 | Insulation Inside Of Vault Door |
| 18 | Carpet Mastic |
| 18 A | Purple & White Mix Carpet Mastic |
| 18 C | Blue w/ Brown Carpet w/ Mastic |
| 18 D | Blue Carpet Mastic |
| 18 K | Brown Mix Carpet Mastic |
| 2M | 12" x 12" Dark Brown w/ White & Black Streaks Floor Tile Mastic |
| 54 | 12" x 12" Light Brown w/ Red & White Specks Floor Tile |
| 65 | 12" x 12" Olive w/ Brown & White Specks Floor Tile |
| 79 | 12" x 12" Brown w/ White Streaks Floor Tile Mastic |
| 8 | 12" x 12" Light Brown w/ Red & White Streaks Floor Tile Mastic |
| 82 | Vault Door Liner |
| 84 | 12" x 12" Gray w/ Brown Specks Floor Tile Mastic |
| 86 | 12" x 12" Beige Mix Floor Tile Mastic |
| 88 | 12" x 12" White w/ Gray Streaks Floor Tile Mastic |
| 9 M | Orange Linoleum Mastic |
| 90 | 12" x 12" Gray Mix Floor Tile Mastic |
| 92 | 12" x 12" White w/ Gray Streaks Floor Tile Mastic |
| 97 | 4" Brown Vinyl Baseboard Adhesive |
| A-1 | Blue Linoleum Flooring-Mastic |
| B-1 | 12" x 12" Blue Vinyl Floor Tile Mastic |

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Dionne Carey Walker, IDPH License # 100-09969. The Management Plan was updated by Jackson Montgomery, IDPH License # 100-20634. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Marshall High School Building 1470 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Marshall High School **Unit** 47041 **Building ID** 1470
Address 3250 W. Adams **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|--|-----------------|---------------|-----------------------|
| 10 | Dark Brown Linoleum | | | Room 125-1 | NO ACBM | MISC | | | | | | | | |
| 10 M | Dark Brown Linoleum Mastic | | | Room 125-1 | ASSUMED | MISC | | | | | | | | |
| 100 | Beige Linoleum | 750 | SF | Room 323 | ASSUMED | MISC | N | NONE | | | ACBM with the potential for damage | | LOW | |
| 101 | Beige Linoleum Adhesive | 750 | SF | Room 323 | ASSUMED | MISC | N | NONE | | | ACBM with the potential for damage | | LOW | |
| 102 | Gray and Tan Terrazzo | 41,000 | SF | Hallway Borders, Lunchroom, Stairwells | ASSUMED | MISC | N | NONE | | | ACBM with the potential for damage | | LOW | |
| 103 | 12" x 12" Red Floor Tile | 2,700 | SF | Room 124, Gym Pe Storage, Auditorium | ASSUMED | MISC | N | LOC | 4 | SF | ACBM with potential for significant damage | 5 | LOW | |
| 104 | 12" x 12" Red Floor Tile Mastic | 2,700 | SF | Room 124, Gym Pe Storage, Auditorium | ASSUMED | MISC | N | NONE | | | ACBM with the potential for damage | | LOW | |
| 105 | 12" x 12" White w/ Brown Specks Floor Tile | 6,200 | SF | Rooms 212, 214, 216, 325, 337, 341, 347, 353a | ASSUMED | MISC | N | DIST | 4 | SF | ACBM with potential for significant damage | 3 | LOW | |
| 106 | 12" x 12" White w/ Brown Specks Floor Tile Mastic | 6,200 | SF | Rooms 212, 214, 216, 325, 337, 341, 347, 353a | ASSUMED | MISC | N | NONE | | | ACBM with the potential for damage | | LOW | |
| 107 | 12" x 12" Light Brown Floor Tile | 2,500 | SF | 2nd and 3rd Floor Sw Hallways | ASSUMED | MISC | N | LOC | 20 | SF | ACBM with potential for significant damage | 5 | LOW | |
| 108 | 12" x 12" Light Brown Floor Tile Mastic | 2,500 | SF | 2nd and 3rd Floor Sw Hallways | ASSUMED | MISC | N | NONE | | | ACBM with the potential for damage | | LOW | |
| 109 | Light Blue Linoleum | 2,000 | SF | Rooms 312, 316 | ASSUMED | MISC | N | NONE | | | ACBM with the potential for damage | | LOW | |
| 11 | 9" x 9" Green w/ White Specks Floor Tile | | | Rooms 127 and 125 | ASSUMED | MISC | | | | | | | | |
| 110 | Light Blue Linoleum Mastic | 2,000 | SF | Rooms 312, 316 | ASSUMED | MISC | N | NONE | | | ACBM with the potential for damage | | LOW | |
| 111 | Textured Gray Linoleum | 1,500 | SF | Room 147 | ASSUMED | MISC | N | NONE | | | ACBM with the potential for damage | | LOW | |
| 112 | Textured Gray Linoleum Mastic | 1,500 | SF | Room 147 | ASSUMED | MISC | N | NONE | | | ACBM with the potential for damage | | LOW | |
| 113 | 12" x 12" Charcoal Floor Tile | 150 | SF | Gym Office(Small) | ASSUMED | MISC | N | NONE | | | ACBM with the potential for damage | | LOW | |
| 114 | 12" x 12" Charcoal Floor Tile Mastic | 150 | SF | Gym Office(Small) | ASSUMED | MISC | N | NONE | | | ACBM with the potential for damage | | LOW | |
| 115 | 12" x 12" Brown Mottled Floor Tile | 700 | SF | Auditorium Storage, Rooms 257, 258, 357, 358, 457, 458, 321, Gym Office 235-2 | ASSUMED | MISC | N | LOC | 10 | SF | ACBM with potential for significant damage | 5 | LOW | |
| 116 | 12" x 12" Brown Mottled Floor Tile Mastic | 700 | SF | Auditorium Storage, Rooms 257, 258, 357, 358, 457, 458, | ASSUMED | MISC | N | NONE | | | ACBM with the potential for damage | | LOW | |

Chicago Public Schools

School Marshall High School **Unit** 47041 **Building ID** 1470
Address 3250 W. Adams **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Chicago Public Schools

School Marshall High School **Unit** 47041 **Building ID** 1470
Address 3250 W. Adams **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|--|-----------------|---------------|-----------------------|
| | Mastic | | | Closet and Possibly Under the Carpet in Room 125 & Room 125 Closet | | | | | | | | | | |
| 24 | Fire Door Lining | | | Door #9 | ASSUMED | TSI | | | | | | | | |
| 25 | 9" x 9" Tan w/ Brown & Beige Streaks Floor Tile Mastic | | | Rooms 126, 330 (Teachers' Lounge), 1st Floor Corridor | CHR | MISC | | | | | | | | |
| 26 | 9" x 9" Light Green Floor Tile Mastic | | | Rooms 127, Office Closet & Possibly Under the Carpet in 125 & Room 125 Closet | ASSUMED | MISC | | | | | | | | |
| 27 | Black Table Tops | | | Room 344, 327, and 323 | NO_ACBM | MISC | | | | | | | | |
| 28 | Gray Exhaust Hood Lining | | | Room 327 | NO_ACBM | MISC | | | | | | | | |
| 29 | 2' x 5' Thin Black Transite Table Tops | | | ABATED | ABATED | MISC | | | | | | | | |
| 2M | 12" x 12" Dark Brown w/ White & Black Streaks Floor Tile Mastic | 769 | SF | Rooms 210, 325, 344, 346, 347 | CHR | MISC | N | NONE | | | ACBM with the potential for damage | | LOW | |
| 3 | Black Asphalight Flooring | | | Stairways | NO_ACBM | MISC | | | | | | | | |
| 30 | 1.5' x 1.5' Gray Steam Table Boards | | | Open Basement Area | NO_ACBM | MISC | | | | | | | | |
| 31 | Aircell Pipe Insulation | 24 | LF | Outside Gym, Possibly in Inaccessible Areas of the Building | CHR | TSI | Y | NONE | | | Any remaining friable ACBM or friable suspect ACBM | | LOW | |
| 32 | Hard Joint Compound on Aircell Pipe Insulation | | | Possibly in Inaccessible Areas of the Building | AMO | TSI | | | | | | | | |
| 33 | Paperwrap Pipe Insulation | 210 | LF | Possibly in Inaccessible Areas of the Building | CHR | TSI | Y | NONE | | | Any remaining friable ACBM or friable suspect ACBM | | LOW | |
| 34 | Hard Joint Compound on Paperwrap Pipe Insulation | 150 | LF | Throughout Basement | CHR | TSI | Y | NONE | | | Any remaining friable ACBM or friable suspect ACBM | | LOW | |
| 35 | Mag Block Pipe Insulation | 5,000 | LF | Engine Room, Air Tunnel 3 & 8 | CHR | TSI | Y | NONE | | | Any remaining friable ACBM or friable suspect ACBM | | LOW | |
| 36 | Mag Block Pipe Joint Insulation | 120 | LF | Engine Room, Air Tunnel 3 & 8 | CHR | TSI | Y | NONE | | | Any remaining friable ACBM or friable suspect ACBM | | LOW | |
| 37 | Hard Joint Compound on Fiberglass Pipe Insulation | 180 | FITTING | Engine Room, Air Tunnels 3 & 8 | AMO | TSI | Y | NONE | | | Any remaining friable ACBM or friable suspect ACBM | | LOW | |

Chicago Public Schools

School Marshall High School **Unit** 47041 **Building ID** 1470
Address 3250 W. Adams **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Chicago Public Schools

School Marshall High School **Unit** 47041 **Building ID** 1470
Address 3250 W. Adams **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Chicago Public Schools

School Marshall High School **Unit** 47041 **Building ID** 1470
Address 3250 W. Adams **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
| 72 | 2' x 4' White Pinhole Lay-in Ceiling Panels | | | Room 140 | NO_ACBM | MISC | | | | | | | | |
| 73 | Orange Fabric Stage Curtain | | | Stage | NO_ACBM | MISC | | | | | | | | |
| 74 | 4" Black Vinyl Baseboard | | | Throughout Building | NO_ACBM | MISC | | | | | | | | |
| 75 | 4" Black Vinyl Baseboard Mastic | | | Throughout Building | NO_ACBM | MISC | | | | | | | | |
| 76 | Tar Paper Under Floor Tile | | | Room 330 | NO_ACBM | MISC | | | | | | | | |
| 77 | Tar Paper Mastic Under Floor Tile | | | Room 330 | NO_ACBM | MISC | | | | | | | | |
| 78 | 12" x 12" Brown w/ White Streaks Floor Tile | 400 | SF | Room 341 Storage | CHR | MISC | N | LOC | 20 | SF | | ACBM with potential for significant damage | 5 | LOW |
| 79 | 12" x 12" Brown w/ White Streaks Floor Tile Mastic | 400 | SF | Room 341 Storage | CHR | MISC | N | NONE | | | | ACBM with the potential for damage | | LOW |
| 7M | 12" x 12" Gray w/ Brown & White Streaks Floor Tile Mastic | | | Room 235 | ASSUMED | MISC | | | | | | | | |
| 8 | 12" x 12" Light Brown w/ Red & White Streaks Floor Tile Mastic | 65,000 | SF | Corridors, Rooms 109, 220 and 320 | ASSUMED | MISC | N | NONE | | | | ACBM with the potential for damage | | LOW |
| 80 | 9" x 9" Beige Floor Tile | | | Room 246 | CHR | MISC | | | | | | | | |
| 81 | 9" x 9" Beige Floor Tile Mastic | | | Room 246 | CHR | MISC | | | | | | | | |
| 82 | Vault Door Liner | 24 | SF | Rooms 125 | ASSUMED | TSI | Y | NONE | | | | Any remaining friable ACBM or friable suspect ACBM | | LOW |
| 83 | 12" x 12" Gray w/ Brown Specks Floor Tile | 700 | SF | Room 125 | ASSUMED | MISC | N | NONE | | | | ACBM with the potential for damage | | LOW |
| 84 | 12" x 12" Gray w/ Brown Specks Floor Tile Mastic | 700 | SF | Room 125 | ASSUMED | MISC | N | NONE | | | | ACBM with the potential for damage | | LOW |
| 85 | 12" x 12" Beige Mix Floor Tile | 900 | SF | Room 130, 124 (Office/Closet), 127, 132, 134 gills locker room storage | ASSUMED | MISC | N | DIST | 15 | SF | | ACBM with potential for significant damage | 5 | LOW |
| 86 | 12" x 12" Beige Mix Floor Tile Mastic | 900 | SF | Room 130, 124 (Office/Closet), 127, 132, 134 | ASSUMED | MISC | N | NONE | | | | ACBM with the potential for damage | | LOW |
| 87 | 12" x 12" White w/ Gray Streaks Floor Tile | 1,664 | SF | Room 132 & 134 Womens Faculty Bathroom (254) | ASSUMED | MISC | N | LOC | 2 | SF | | ACBM with potential for significant damage | 5 | LOW |
| 88 | 12" x 12" White w/ Gray Streaks Floor Tile Mastic | 1,664 | SF | Room 132 & 134, Womens Faculty Bathroom (254) | ASSUMED | MISC | N | NONE | | | | ACBM with the potential for damage | | LOW |
| 89 | 12" x 12" Gray Mix Floor Tile | 1,500 | SF | Room 143 | ASSUMED | MISC | N | LOC | 3 | SF | | ACBM with potential for significant damage | 5 | LOW |
| 9 | Orange Linoleum | | | Room 101 | NO_ACBM | MISC | | | | | | | | |
| 9 M | Orange Linoleum Mastic | 500 | SF | Room 101 | ASSUMED | MISC | N | NONE | | | | ACBM with the potential for damage | | LOW |
| 90 | 12" x 12" Gray Mix Floor Tile Mastic | 1,500 | SF | Room 143 | ASSUMED | MISC | N | NONE | | | | ACBM with the | | LOW |

Chicago Public Schools

School Marshall High School **Unit** 47041 **Building ID** 1470
Address 3250 W. Adams **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
| 91 | 12" x 12" White w/ Gray Streaks Floor Tile | 500 | SF | Infant/Toddler Center | ASSUMED | MISC | N | NONE | | | | potential for damage | | |
| 92 | 12" x 12" White w/ Gray Streaks Floor Tile Mastic | 500 | SF | Infant/Toddler Center | ASSUMED | MISC | N | NONE | | | | ACBM with the potential for damage | | LOW |
| 93 | 12" x 12" Pink/Purple Speckled Floor Tile | | | Classrooms 147 & 151 | ASSUMED | MISC | | | | | | | | |
| 94 | 12" x 12" Pink/Purple Speckled Floor Tile Mastic | | | Classrooms 147 & 151 | ASSUMED | MISC | | | | | | | | |
| 95 | 2' x 4' White Ceiling Tile | 1,500 | SF | Classrooms 147 & 151 | ASSUMED | MISC | Y | NONE | | | | Any remaining friable ACBM or friable suspect ACBM | | LOW |
| 96 | 4" Brown Vinyl Baseboard | 150 | SF | Classrooms 147 & 151 | ASSUMED | MISC | N | NONE | | | | ACBM with the potential for damage | | LOW |
| 97 | 4" Brown Vinyl Baseboard Adhesive | 150 | SF | Classrooms 147 & 151 | ASSUMED | MISC | N | NONE | | | | ACBM with the potential for damage | | LOW |
| 98 | Red Stage Curtain | 1,000 | SF | Auditorium | ASSUMED | MISC | N | NONE | | | | ACBM with the potential for damage | | LOW |
| 99 | Orange Carpet Adhesive | | | Auditorium and Room 228 | ASSUMED | MISC | | | | | | | | |
| A | Blue Linoleum Flooring | 2,547 | SF | Rooms 327, 344, 348, 314, 246 (Prep), 244 | ASSUMED | MISC | N | LOC | 10 | SF | | ACBM with potential for significant damage | 5 | LOW |
| A-1 | Blue Linoleum Flooring-Mastic | 2,547 | SF | Rooms 327, 344, 348, 314, 246 (Prep), 244 | ASSUMED | MISC | N | NONE | | | | ACBM with the potential for damage | | LOW |
| B | 12" x 12" Blue Vinyl Floor Tile | 1,200 | SF | Rooms 354, 230 (Teachers' Lounge) & 330(Teachers' Lounge), Mens 3rd Floor Bathroom, Room 246 Prep. Replacement tile in 147 | ASSUMED | MISC | N | DIST | 25 | SF | | ACBM with potential for significant damage | 5 | LOW |
| B-1 | 12" x 12" Blue Vinyl Floor Tile Mastic | 1,200 | SF | Rooms 354, 230 (Teachers' Lounge) & 330(Teachers' Lounge), Mens 3rd Floor Bathroom, Room 246 Prep. | ASSUMED | MISC | N | NONE | | | | ACBM with the potential for damage | | LOW |

Chicago Public Schools

School Marshall High School Unit 47041 Building ID 1470
Address 3250 W. Adams Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| |
|---|
| Reinspection Date <u>6/27/2025</u> |
| Inspector Name <u>Dionne Carey Walker</u> |
| <u>100-09969</u> <u>5/15/2026</u> |
| Inspector's IDPH License Number / Expiration Date |

Inspector's Comments

| HA Number: | Inspector Comments: |
|------------|------------------------------|
| 10 | Material not observed - 2025 |
| 10 M | Material not observed - 2025 |
| 100 | |
| 101 | |
| 102 | |
| 103 | Damage in Room 124 |
| 104 | |
| 105 | Damage in 337, 325 |
| 106 | |
| 107 | Damage in hall outside 250 |
| 108 | |
| 109 | Not observed in 151 |
| 11 | Material not observed - 2025 |
| 110 | Not observed in 151 |
| 111 | |
| 112 | |
| 113 | |
| 114 | |
| 115 | Damage in auditorium storage |
| 116 | |
| 117 | |
| 118 | |
| 12 | |
| 12 M | |

Chicago Public Schools

School Marshall High School **Unit** 47041 **Building ID** 1470
Address 3250 W. Adams **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA Number: | Inspector Comments: |
|------------|---|
| 13 | |
| 14 | |
| 15 | |
| 16 | |
| 17 | |
| 18 | |
| 18 A | Not observed in 130, 227 |
| 18 B | Material not observed - 2025 |
| 18 C | |
| 18 D | |
| 18 E | |
| 18 F | Material not observed - 2025 |
| 18 G | Material in inaccessible area(s) - 2025 |
| 18 H | Material not observed - 2025 |
| 18 I | Material not observed - 2025 |
| 18 J | Material not observed - 2025 |
| 18 K | |
| 19 | |
| 2 | |
| 20 | Material in inaccessible area(s) - 2025 |
| 21 | |
| 23 | Material not observed - 2025 |
| 24 | Material not observed - 2025 |
| 25 | Material not observed - 2025 |
| 26 | Material not observed - 2025 |
| 27 | |
| 28 | |
| 29 | |
| 2M | |

Chicago Public Schools

School Marshall High School **Unit** 47041 **Building ID** 1470
Address 3250 W. Adams **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA Number: | Inspector Comments: |
|------------|--|
| 3 | |
| 30 | |
| 31 | Repaired |
| 32 | Material in inaccessible area(s) - 2025 |
| 33 | |
| 34 | |
| 35 | Repaired |
| 36 | |
| 37 | |
| 38 | |
| 39 | |
| 4 | Material not observed - 2025 |
| 40 | |
| 41 | |
| 42 | Material not observed - 2025 |
| 43 | Material not observed - 2025 |
| 44 | |
| 45 | |
| 46 | |
| 47 | Material in inaccessible area(s) - 2025 |
| 48 | |
| 49 | |
| 4M | Material not observed - 2025 |
| 5 | Material not observed - 2025 |
| 50 | |
| 51 | Material not observed - 2025 |
| 52 | |
| 53 | Material not observed - 2025 |
| 54 | Damage in 1st floor hall by between boiler room and main building, hall by 250 |

Chicago Public Schools

School Marshall High School **Unit** 47041 **Building ID** 1470
Address 3250 W. Adams **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA Number: | Inspector Comments: |
|------------|---|
| 55 | |
| 56 | |
| 57 | |
| 58 | |
| 59 | |
| 6 | |
| 60 | |
| 61 | |
| 62 | Material in inaccessible area(s) - 2025 |
| 63 | Material in inaccessible area(s) - 2025 |
| 64 | |
| 65 | |
| 66 | |
| 67 | Material not observed - 2025 |
| 68 | |
| 69 | |
| 7 | Material not observed - 2025 |
| 70 | |
| 71 | |
| 72 | |
| 73 | |
| 74 | |
| 75 | |
| 76 | |
| 77 | |
| 78 | Damage in 341 storage |
| 79 | |
| 7M | Material not observed - 2025 |
| 8 | |

Chicago Public Schools

School Marshall High School **Unit** 47041 **Building ID** 1470
Address 3250 W. Adams **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA Number: | Inspector Comments: |
|------------|--|
| 80 | Material not observed - 2025 |
| 81 | Material not observed - 2025 |
| 82 | |
| 83 | |
| 84 | |
| 85 | Damage in 132, girls locker room storage |
| 86 | |
| 87 | Damage in woman's restroom 254 |
| 88 | |
| 89 | Damage in room 143 |
| 9 | |
| 9 M | |
| 90 | |
| 91 | |
| 92 | |
| 93 | Material not observed - 2025 |
| 94 | Material not observed - 2025 |
| 95 | |
| 96 | |
| 97 | |
| 98 | |
| 99 | Material not observed - 2025 |
| A | Not observed in 147, damage in 246 |
| A-1 | |
| B | Damage in 354 men's room, 330, and 147 |
| B-1 | |

Chicago Public Schools

School Marshall High School **Unit** 47041 **Building ID** 1470
Address 3250 W. Adams **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Table II
Management Planner's Review

Chicago Public Schools

School Marshall High School

Unit 47041

Building ID 1470

Address 3250 W. Adams

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|---|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--|-----------------|
| 10 | Dark Brown Linoleum | | | Room 125-1 | No ACBM | MISC | | | | | |
| 10 M | Dark Brown Linoleum Mastic | | | Room 125-1 | Assumed | MISC | | | | | |
| 100 | Beige Linoleum | 750 | SF | Room 323 | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 101 | Beige Linoleum Adhesive | 750 | SF | Room 323 | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 102 | Gray and Tan Terrazzo | 41,000 | SF | Hallway Borders, Lunchroom, Stairwells | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 103 | 12" x 12" Red Floor Tile | 2,700 | SF | Room 124, Gym Pe Storage, Auditorium | Assumed | MISC | No | 4 | SF | 5 ACBM with potential for significant damage | Follow O&M Plan |
| 104 | 12" x 12" Red Floor Tile Mastic | 2,700 | SF | Room 124, Gym Pe Storage, Auditorium | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 105 | 12" x 12" White w/ Brown Specks Floor Tile | 6,200 | SF | Rooms 212, 214, 216, 325, 337, 341, 347, 353a | Assumed | MISC | No | 4 | SF | 5 ACBM with potential for significant damage | Follow O&M Plan |
| 106 | 12" x 12" White w/ Brown Specks Floor Tile Mastic | 6,200 | SF | Rooms 212, 214, 216, 325, 337, 341, 347, 353a | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 107 | 12" x 12" Light Brown Floor Tile | 2,500 | SF | 2nd and 3rd Floor Sw Hallways | Assumed | MISC | No | 20 | SF | 5 ACBM with potential for significant damage | Repair |
| 108 | 12" x 12" Light Brown Floor Tile Mastic | 2,500 | SF | 2nd and 3rd Floor Sw Hallways | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 109 | Light Blue Linoleum | 2,000 | SF | Rooms 312, 316 | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 11 | 9" x 9" Green w/ White Specks Floor Tile | | | Rooms 127 and 125 | Assumed | MISC | | | | | |
| 110 | Light Blue Linoleum Mastic | 2,000 | SF | Rooms 312, 316 | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 111 | Textured Gray Linoleum | 1,500 | SF | Room 147 | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 112 | Textured Gray Linoleum Mastic | 1,500 | SF | Room 147 | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 113 | 12" x 12" Charcoal Floor Tile | 150 | SF | Gym Office(Small) | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 114 | 12" x 12" Charcoal Floor Tile Mastic | 150 | SF | Gym Office(Small) | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 115 | 12" x 12" Brown Mottled Floor Tile | 700 | SF | Auditorium Storage, Rooms 257, 258, 357, 358, 457, 458, 321, Gym Office 235-2 | Assumed | MISC | No | 10 | SF | 5 ACBM with potential for significant damage | Follow O&M Plan |
| 116 | 12" x 12" Brown Mottled Floor Tile Mastic | 700 | SF | Auditorium Storage, Rooms 257, 258, 357, 358, 457, 458, Gym Office 235-2 | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 117 | Smooth Gray Linoleum | 700 | SF | Room 151 | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 118 | Smooth Gray Linoleum Mastic | 700 | SF | Room 151 | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 12 | 9" x 9" Red Floor Tile | | | ABATED | Abated | MISC | | | | | |
| 12 M | 9" x 9" Red Floor Tile Mastic | | | ABATED | Abated | MISC | | | | | |
| 13 | 2' x 4' Pitted Lay-in Ceiling Panels | | | Throughout Corridors and Classrooms | No ACBM | MISC | | | | | |
| 14 | 2' x 4' White Wormed Lay-in Ceiling Panels | | | Lunchroom, 124, 2nd Floor Corridor, | No ACBM | MISC | | | | | |

Chicago Public Schools

School Marshall High School

Unit 47041

Building ID 1470

Address 3250 W. Adams

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|--|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--|-----------------|
| | | | | 247, 249, 354 | | | | | | | |
| 15 | Exterior Brick - Non-AHERA | | | Exterior of Building | No ACBM | MISC | | | | | |
| 16 | Exterior Brick Mortar - Non-AHERA | | | Exterior of Building | No ACBM | MISC | | | | | |
| 17 | Insulation Inside Of Vault Door | 24 | SF | Rooms 125 | Assumed | TSI | Yes | | SF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 18 | Carpet Mastic | 5,000 | SF | Throughout Building | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 18 A | Purple & White Mix Carpet Mastic | 2,100 | SF | Room 229, 225 | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 18 B | Orange Carpet Mastic | | | Room 228 | Assumed | MISC | | | | | |
| 18 C | Blue w/ Brown Carpet w/ Mastic | 700 | SF | Room 237 | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 18 D | Blue Carpet Mastic | 1,000 | SF | Room 137 and Assistant Principal's Office | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 18 E | Red Carpet Mastic | | | Rooms 124 and 127 | No ACBM | MISC | | | | | |
| 18 F | Lavender Carpet Mastic | | | Room 125 | Assumed | MISC | | | | | |
| 18 G | Black and Green Carpet Mastic | 700 | SF | Principal's Office | Assumed | MISC | | | SF | | |
| 18 H | Blue Patterned Carpet Mastic | | | Room 126 | Assumed | MISC | | | | | |
| 18 I | Blue Mix Carpet Mastic | | | Conference Room | Assumed | MISC | | | | | |
| 18 J | Gray Carpet Mastic | | | Room 136 | Assumed | MISC | | | | | |
| 18 K | Brown Mix Carpet Mastic | 100 | SF | Infant Toddler Center | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 19 | Black Science Lab Tables | 186 | SF | Rooms 212, 214 | Chrysotile | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 2 | 12" x 12" Dark Brown w/ White & Black Streaks Floor Tile | 769 | SF | Rooms 210, 325, 344, 346, 347 | Chrysotile | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 20 | Gray Boiler Rope Gaskets | 30 | LF | Boiler Interiors | Chrysotile | TSI | | | LF | | |
| 21 | Roofing Material - Non-AHERA | | | Roof | Assumed | MISC | | | | | |
| 23 | 9" x 9" Green w/ White Specks Floor Tile Mastic | | | Room 127 Office Closet and Possibly Under the Carpet in Room 125 & Room 125 Closet | Chrysotile | MISC | | | | | |
| 24 | Fire Door Lining | | | Door #9 | Assumed | TSI | | | | | |
| 25 | 9" x 9" Tan w/ Brown & Beige Streaks Floor Tile Mastic | | | Rooms 126, 330 (Teachers' Lounge), 1st Floor Corridor | Chrysotile | MISC | | | | | |
| 26 | 9" x 9" Light Green Floor Tile Mastic | | | Rooms 127, Office Closet & Possibly Under the Carpet in 125 & Room 125 Closet | Assumed | MISC | | | | | |
| 27 | Black Table Tops | | | Room 344, 327, and 323 | No ACBM | MISC | | | | | |
| 28 | Gray Exhaust Hood Lining | | | Room 327 | No ACBM | MISC | | | | | |
| 29 | 2' x 5' Thin Black Transite Table Tops | | | ABATED | Abated | MISC | | | | | |

Chicago Public Schools

School Marshall High School

Unit 47041

Building ID 1470

Address 3250 W. Adams

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|---|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--|-----------------|
| 2M | 12" x 12" Dark Brown w/ White & Black Streaks Floor Tile Mastic | 769 | SF | Rooms 210, 325, 344, 346, 347 | Chrysotile | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 3 | Black Asphaltite Flooring | | | Stairways | No ACBM | MISC | | | | | |
| 30 | 1.5' x 1.5' Gray Steam Table Boards | | | Open Basement Area | No ACBM | MISC | | | | | |
| 31 | Aircell Pipe Insulation | 24 | LF | Outside Gym, Possibly in Inaccessible Areas of the Building | Chrysotile | TSI | Yes | | LF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 32 | Hard Joint Compound on Aircell Pipe Insulation | | | Possibly in Inaccessible Areas of the Building | Amosite | TSI | | | | | |
| 33 | Paperwrap Pipe Insulation | 210 | LF | Possibly in Inaccessible Areas of the Building | Chrysotile | TSI | Yes | | LF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 34 | Hard Joint Compound on Paperwrap Pipe Insulation | 150 | LF | Throughout Basement | Chrysotile | TSI | Yes | | LF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 35 | Mag Block Pipe Insulation | 5,000 | LF | Engine Room, Air Tunnel 3 & 8 | Chrysotile | TSI | Yes | | LF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 36 | Mag Block Pipe Joint Insulation | 120 | LF | Engine Room, Air Tunnel 3 & 8 | Chrysotile | TSI | Yes | | LF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 37 | Hard Joint Compound on Fiberglass Pipe Insulation | 180 | FITTING | Engine Room, Air Tunnels 3 & 8 | Amosite | TSI | Yes | | FITTING | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 38 | Plaster Walls | | | Throughout 1918 Building | No ACBM | SURFACE | | | | | |
| 39 | Plaster Ceilings | | | Throughout 1918 Building | No ACBM | SURFACE | | | | | |
| 4 | 12" x 12" Black w/ Brown Streaks Floor Tile | | | Rooms 132, 134, 143, 145, 230 (Womens Bathroom), 244, 246, 248, 254, and 310, Men's 3rd Floor Bathroom | Assumed | MISC | | | | | |
| 40 | White Boiler Rope Gasket | | | Boilers | No ACBM | MISC | | | | | |
| 41 | Gray Transite Counter Tops | | | ABATED | Abated | MISC | | | | | |
| 42 | Mag Type Boiler Gasket | | | Boiler Room | Chrysotile | TSI | | | | | |
| 43 | Leather Like Boiler Gaskets | | | Boiler Room | Chrysotile | TSI | | | | | |
| 44 | Mineral Wool Boiler Insulation | | | Boiler Room | No ACBM | TSI | | | | | |
| 45 | Water Tank Insulation | | | ABATED | Abated | MISC | | | | | |
| 46 | Water Tank Insulation | | | ABATED | Abated | MISC | | | | | |
| 47 | Aircell Duct Insulation | 1,200 | SF | Crawlspace 3 | Chrysotile | TSI | | | SF | | |
| 48 | Brown Vinyl Stage Curtain | | | Stage | No ACBM | MISC | | | | | |
| 49 | 2' x 4' Brown Ceiling Panels | | | Corridor 9 | No ACBM | MISC | | | | | |
| 4M | 12" x 12" Black w/ Brown Streaks Floor Tile Mastic | | | Rooms 132, 134, 143, 145, 230 (Womens Bathroom), 244, 246, 248, | Chrysotile | MISC | | | | | |

Chicago Public Schools

School Marshall High School

Unit 47041

Building ID 1470

Address 3250 W. Adams

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|---|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--|-----------------|
| | | | | 254, and 310, Men's 3rd Floor Bathroom | | | | | | | |
| 5 | 9" x 9" Tan w/ Brown & Beige Streaks Floor Tile | | | Rooms 126, 330 (Teachers' Lounge), 1st Floor Corridor | Chrysotile | MISC | | | | | |
| 50 | 2' x 5' Black Transite Table Tops | 5,000 | SF | Rooms 244, 246, 248, 344, 346, 348, 321, 325, and 327 | Chrysotile | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 51 | Gray Transite Table Tops | | | Room 214 | Chrysotile | MISC | | | | | |
| 52 | 2' x 4' White Pitted Ceiling Panels | | | Rooms 109, 110, 118, 310, 312, 314, and 320, 1st & 3rd Floor Corridors | No ACBM | MISC | | | | | |
| 53 | 12" x 12" Dark Brown w/ White & Black Specks Floor Tile | | | Room 314, Engineer's Office | Assumed | MISC | | | | | |
| 54 | 12" x 12" Light Brown w/ Red & White Specks Floor Tile | 65,000 | SF | Corridors, Rooms 109, 220 and 320 | Assumed | MISC | No | 45 | SF | 5 ACBM with potential for significant damage | Remove |
| 55 | Ceiling Plaster | | | Throughout 1898 Building | No ACBM | SURFACE | | | | | |
| 56 | Plaster Walls | | | Throughout 1898 Building | No ACBM | SURFACE | | | | | |
| 57 | Gypsum Rock Lath | | | Girls Gyms and Balconies | No ACBM | MISC | | | | | |
| 58 | Aircell Pipe Insulation | 120 | LF | Gym 12 | Chrysotile | TSI | Yes | | LF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 59 | Hard Joint Compound on Aircell Pipe Insulation | 25 | LF | Gym 12 | Chrysotile | TSI | Yes | | LF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 6 | Reddish Brown Linoleum | | | Rooms 223, 225, and 229 | No ACBM | MISC | | | | | |
| 60 | Paperwrap Pipe Insulation | 70 | LF | Boiler Room | Chrysotile | TSI | Yes | | LF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 61 | Hard Joint Compound on Paperwrap Pipe Insulation | 25 | LF | Boiler Room | Chrysotile | TSI | Yes | | LF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 62 | Mag Block Pipe Insulation | | | Boiler Room, Gym 12, Auditorium | Chrysotile | TSI | | | | | |
| 63 | Mag Block Joint Insulation | | | Boiler Room, Gym 12, Auditorium | Chrysotile | TSI | | | | | |
| 64 | Hard Joint Compound on Fiberglass Pipe Insulation | 15 | LF | Boiler Room and Throughout Basement | Chrysotile | TSI | Yes | | LF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 65 | 12" x 12" Olive w/ Brown & White Specks Floor Tile | 500 | SF | Room 130 | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 66 | 12" x 12" White w/ Brown & Gray Streaks Floor Tile | 200 | SF | Room 130 | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 67 | 12" x 12" Light Brown w/ Red & White Streaks Floor Tile | | | Room 147 | Assumed | MISC | | | | | |
| 68 | 1' x 1' White Wommed & Pitted Ceiling Tile | | | Room 144 and Boys Gym, 227-229 | No ACBM | MISC | | | | | |
| 69 | 1' x 1' Beige Grooved Ceiling Tile | | | Girls Gym, Room 333 | No ACBM | MISC | | | | | |
| 7 | 12" x 12" Gray w/ Brown & White Streaks Floor Tile | | | Room 235 | Assumed | MISC | | | | | |

Chicago Public Schools

School Marshall High School

Unit 47041

Building ID 1470

Address 3250 W. Adams

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|--|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--|-----------------|
| 70 | 2' x 4' White Womred Lay-in Ceiling Panels | | | Room 227 and Library | No ACBM | MISC | | | | | |
| 71 | 1' x 1' White Pitted Ceiling Tile | | | Rooms 132, 134, 225, and 229, 2nd Floor Between Girls & Boys Gym | No ACBM | MISC | | | | | |
| 72 | 2' x 4' White Pinhole Lay-in Ceiling Panels | | | Room 140 | No ACBM | MISC | | | | | |
| 73 | Orange Fabric Stage Curtain | | | Stage | No ACBM | MISC | | | | | |
| 74 | 4" Black Vinyl Baseboard | | | Throughout Building | No ACBM | MISC | | | | | |
| 75 | 4" Black Vinyl Baseboard Mastic | | | Throughout Building | No ACBM | MISC | | | | | |
| 76 | Tar Paper Under Floor Tile | | | Room 330 | No ACBM | MISC | | | | | |
| 77 | Tar Paper Mastic Under Floor Tile | | | Room 330 | No ACBM | MISC | | | | | |
| 78 | 12" x 12" Brown w/ White Streaks Floor Tile | 400 | SF | Room 341 Storage | Chrysotile | MISC | No | 20 | SF | 5 ACBM with potential for significant damage | Repair |
| 79 | 12" x 12" Brown w/ White Streaks Floor Tile Mastic | 400 | SF | Room 341 Storage | Chrysotile | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 7M | 12" x 12" Gray w/ Brown & White Streaks Floor Tile Mastic | | | Room 235 | Assumed | MISC | | | | | |
| 8 | 12" x 12" Light Brown w/ Red & White Streaks Floor Tile Mastic | 65,000 | SF | Corridors, Rooms 109, 220 and 320 | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 80 | 9" x 9" Beige Floor Tile | | | Room 246 | Chrysotile | MISC | | | | | |
| 81 | 9" x 9" Beige Floor Tile Mastic | | | Room 246 | Chrysotile | MISC | | | | | |
| 82 | Vault Door Liner | 24 | SF | Rooms 125 | Assumed | TSI | Yes | | SF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 83 | 12" x 12" Gray w/ Brown Specks Floor Tile | 700 | SF | Room 125 | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 84 | 12" x 12" Gray w/ Brown Specks Floor Tile Mastic | 700 | SF | Room 125 | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 85 | 12" x 12" Beige Mix Floor Tile | 900 | SF | Room 130, 124 (Office/Closet), 127, 132, 134 gills locker room storage | Assumed | MISC | No | 15 | SF | 5 ACBM with potential for significant damage | Follow O&M Plan |
| 86 | 12" x 12" Beige Mix Floor Tile Mastic | 900 | SF | Room 130, 124 (Office/Closet), 127, 132, 134 | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 87 | 12" x 12" White w/ Gray Streaks Floor Tile | 1,664 | SF | Room 132 & 134 Womens Faculty Bathroom (254) | Assumed | MISC | No | 2 | SF | 5 ACBM with potential for significant damage | Follow O&M Plan |
| 88 | 12" x 12" White w/ Gray Streaks Floor Tile Mastic | 1,664 | SF | Room 132 & 134, Womens Faculty Bathroom (254) | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 89 | 12" x 12" Gray Mix Floor Tile | 1,500 | SF | Room 143 | Assumed | MISC | No | 3 | SF | 5 ACBM with potential for significant damage | Follow O&M Plan |
| 9 | Orange Linoleum | | | Room 101 | No ACBM | MISC | | | | | |
| 9 M | Orange Linoleum Mastic | 500 | SF | Room 101 | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 90 | 12" x 12" Gray Mix Floor Tile Mastic | 1,500 | SF | Room 143 | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |

Chicago Public Schools

School Marshall High School

Unit 47041

Building ID 1470

Address 3250 W. Adams

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|---|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--|-----------------|
| 91 | 12" x 12" White w/ Gray Streaks Floor Tile | 500 | SF | Infant/Toddler Center | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 92 | 12" x 12" White w/ Gray Streaks Floor Tile Mastic | 500 | SF | Infant/Toddler Center | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 93 | 12" x 12" Pink/Purple Speckled Floor Tile | | | Classrooms 147 & 151 | Assumed | MISC | | | | | |
| 94 | 12" x 12" Pink/Purple Speckled Floor Tile Mastic | | | Classrooms 147 & 151 | Assumed | MISC | | | | | |
| 95 | 2' x 4' White Ceiling Tile | 1,500 | SF | Classrooms 147 & 151 | Assumed | MISC | Yes | | SF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 96 | 4" Brown Vinyl Baseboard | 150 | SF | Classrooms 147 & 151 | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 97 | 4" Brown Vinyl Baseboard Adhesive | 150 | SF | Classrooms 147 & 151 | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 98 | Red Stage Curtain | 1,000 | SF | Auditorium | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 99 | Orange Carpet Adhesive | | | Auditorium and Room 228 | Assumed | MISC | | | | | |
| A | Blue Linoleum Flooring | 2,547 | SF | Rooms 327, 344, 348, 314, 246 (Prep), 244 | Assumed | MISC | No | 10 | SF | 5 ACBM with potential for significant damage | Follow O&M Plan |
| A-1 | Blue Linoleum Flooring-Mastic | 2,547 | SF | Rooms 327, 344, 348, 314, 246 (Prep), 244 | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| B | 12" x 12" Blue Vinyl Floor Tile | 1,200 | SF | Rooms 354, 230(Teachers' Lounge) & 330(Teachers' Lounge), Mens 3rd Floor Bathroom, Room 246 Prep. Replacement tile in 147 | Assumed | MISC | No | 25 | SF | 5 ACBM with potential for significant damage | Follow O&M Plan |
| B-1 | 12" x 12" Blue Vinyl Floor Tile Mastic | 1,200 | SF | Rooms 354, 230(Teachers' Lounge) & 330(Teachers' Lounge), Mens 3rd Floor Bathroom, Room 246 Prep. | Assumed | MISC | No | | SF | 6 ACBM with the potential for damage | Follow O&M Plan |

Chicago Public Schools

School Marshall High School

Unit 47041

Building ID 1470

Address 3250 W. Adams

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| | |
|------------------------------------|--------------------|
| Review Date | 7/23/2025 |
| Manager Planner Name | Jackson Montgomery |
| 100-20634 | 5/15/2026 |
| Manager IDPH License No/Expiration | |

| HA Number | Management Comments |
|-----------|---|
| 10 | |
| 10 M | |
| 100 | |
| 101 | |
| 102 | |
| 103 | Sample to determine ACM content prior to disturbance. |
| 104 | |
| 105 | Sample to determine ACM content prior to disturbance. |
| 106 | |
| 107 | Sample to determine ACM content prior to disturbance. |
| 108 | |
| 109 | |
| 11 | |
| 110 | |
| 111 | |
| 112 | |
| 113 | |
| 114 | |

Chicago Public Schools

School Marshall High School

Unit 47041

Building ID 1470

Address 3250 W. Adams

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Number | Management Comments |
|-----------|---|
| 115 | Sample to determine ACM content prior to disturbance. |
| 116 | |
| 117 | |
| 118 | |
| 12 | |
| 12 M | |
| 13 | |
| 14 | |
| 15 | Non-AHERA |
| 16 | Non-AHERA |
| 17 | |
| 18 | |
| 18 A | |
| 18 B | |
| 18 C | |
| 18 D | |
| 18 E | |
| 18 F | |
| 18 G | If identified, continue O&M. |
| 18 H | |
| 18 I | |
| 18 J | |
| 18 K | |
| 19 | |
| 2 | |
| 20 | If identified, continue O&M. |
| 21 | Non-AHERA |

Chicago Public Schools

School Marshall High School

Unit 47041

Building ID 1470

Address 3250 W. Adams

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Number | Management Comments |
|-----------|------------------------------|
| 23 | |
| 24 | |
| 25 | |
| 26 | |
| 27 | |
| 28 | |
| 29 | |
| 2M | |
| 3 | |
| 30 | |
| 31 | |
| 32 | If identified, continue O&M. |
| 33 | |
| 34 | |
| 35 | |
| 36 | |
| 37 | |
| 38 | |
| 39 | |
| 4 | |
| 40 | |
| 41 | |
| 42 | |
| 43 | |
| 44 | |
| 45 | |
| 46 | |

Chicago Public Schools

School Marshall High School

Unit 47041

Building ID 1470

Address 3250 W. Adams

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Number | Management Comments |
|-----------|---|
| 47 | If identified, continue O&M. |
| 48 | |
| 49 | |
| 4M | |
| 5 | |
| 50 | |
| 51 | |
| 52 | |
| 53 | |
| 54 | Sample to determine ACM content prior to disturbance. |
| 55 | |
| 56 | |
| 57 | |
| 58 | |
| 59 | |
| 6 | |
| 60 | |
| 61 | |
| 62 | If identified, continue O&M. |
| 63 | If identified, continue O&M. |
| 64 | |
| 65 | |
| 66 | |
| 67 | |
| 68 | |
| 69 | |
| 7 | |

Chicago Public Schools

School Marshall High School

Unit 47041

Building ID 1470

Address 3250 W. Adams

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Number | Management Comments |
|-----------|---|
| 70 | |
| 71 | |
| 72 | |
| 73 | |
| 74 | |
| 75 | |
| 76 | |
| 77 | |
| 78 | Remove or repair to intact. |
| 79 | |
| 7M | |
| 8 | |
| 80 | |
| 81 | |
| 82 | |
| 83 | |
| 84 | |
| 85 | Sample to determine ACM content prior to disturbance. |
| 86 | |
| 87 | Sample to determine ACM content prior to disturbance. |
| 88 | |
| 89 | Sample to determine ACM content prior to disturbance. |
| 9 | |
| 9 M | |
| 90 | |
| 91 | |
| 92 | |

Chicago Public Schools

School Marshall High School

Unit 47041

Building ID 1470

Address 3250 W. Adams

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Number | Management Comments |
|-----------|---|
| 93 | |
| 94 | |
| 95 | |
| 96 | |
| 97 | |
| 98 | |
| 99 | |
| A | Sample to determine ACM content prior to disturbance. |
| A-1 | |
| B | Sample to determine ACM content prior to disturbance. |
| B-1 | |

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Dark Brown Linoleum**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 125-1**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Dark Brown Linoleum**

MATERIAL LOCATION: **Room 125-1**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10 M**

MATERIAL DESCRIPTION: **Dark Brown Linoleum Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 125-1**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **10 M**

MATERIAL DESCRIPTION: **Dark Brown Linoleum Mastic**

MATERIAL LOCATION: **Room 125-1**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 100 | | |
| MATERIAL DESCRIPTION: | Beige Linoleum | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 323 | | |
| MATERIAL QUANTITY: | 750 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **100**

MATERIAL DESCRIPTION: **Beige Linoleum**

MATERIAL LOCATION: **Room 323**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 101 | | |
| MATERIAL DESCRIPTION: | Beige Linoleum Adhesive | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 323 | | |
| MATERIAL QUANTITY: | 750 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **101**

MATERIAL DESCRIPTION: **Beige Linoleum Adhesive**

MATERIAL LOCATION: **Room 323**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 102 | | |
| MATERIAL DESCRIPTION: | Gray and Tan Terrazzo | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Hallway Borders, Lunchroom, Stairwells | | |
| MATERIAL QUANTITY: | 41000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **102**

MATERIAL DESCRIPTION: **Gray and Tan Terrazzo**

MATERIAL LOCATION: **Hallway Borders, Lunchroom, Stairwells**

MATERIAL QUANTITY: **41000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 103 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Red Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 5 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 5. ACBM with potential for significant damage

| | | | |
|------------------------|--------------------------------------|-----------------|----|
| DAMAGE REASON: | Physical Damage | | |
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 124, Gym Pe Storage, Auditorium | | |
| MATERIAL QUANTITY: | 2700 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | Damage in Room 124 | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **103**

MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile**

MATERIAL LOCATION: **Room 124, Gym Pe Storage, Auditorium**

MATERIAL QUANTITY: **2700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **4** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 104 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Red Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 124, Gym Pe Storage, Auditorium | | |
| MATERIAL QUANTITY: | 2700 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **104**

MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile Mastic**

MATERIAL LOCATION: **Room 124, Gym Pe Storage, Auditorium**

MATERIAL QUANTITY: **2700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 105 | | |
| MATERIAL DESCRIPTION: | 12" x 12" White w/ Brown Specks Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 5 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | Deterioration Physical Damage | | |
| HISTORICAL RESPONSE ACTION: | Repair | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

| | | | |
|------------------------|---|-----------------|----|
| DAMAGE REASON: | Deterioration Physical Damage | | |
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Rooms 212, 214, 216, 325, 337, 341, 347, 353a | | |
| MATERIAL QUANTITY: | 6200 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | Damage in 337, 325 | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **105**

MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Specks Floor Tile**

MATERIAL LOCATION: **Rooms 212, 214, 216, 325, 337, 341, 347, 353a**

MATERIAL QUANTITY: **6200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **4** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|----|
| HOMOGENEOUS AREA: | 106 | | |
| MATERIAL DESCRIPTION: | 12" x 12" White w/ Brown Specks Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Rooms 212, 214, 216, 325, 337, 341, 347, 353a | | |
| MATERIAL QUANTITY: | 6200 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **106**

MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Specks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 212, 214, 216, 325, 337, 341, 347, 353a**

MATERIAL QUANTITY: **6200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 107 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Light Brown Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 5 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 5. ACBM with potential for significant damage

| | | | |
|------------------------|-------------------------------|-----------------|----|
| DAMAGE REASON: | Physical Damage | | |
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | 2nd and 3rd Floor Sw Hallways | | |
| MATERIAL QUANTITY: | 2500 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | Damage in hall outside 250 | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **107**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile**

MATERIAL LOCATION: **2nd and 3rd Floor Sw Hallways**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----------|
| HOMOGENEOUS AREA: | 108 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Light Brown Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--------------------------------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | 2nd and 3rd Floor Sw Hallways | | |
| MATERIAL QUANTITY: | 2500 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **108**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile Mastic**

MATERIAL LOCATION: **2nd and 3rd Floor Sw Hallways**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 109 | | |
| MATERIAL DESCRIPTION: | Light Blue Linoleum | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------------------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Rooms 312, 316 | | |
| MATERIAL QUANTITY: | 2000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | Not observed in 151 | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **109**

MATERIAL DESCRIPTION: **Light Blue Linoleum**

MATERIAL LOCATION: **Rooms 312, 316**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 11

MATERIAL DESCRIPTION: 9" x 9" Green w/ White Specks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 127 and 125

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **9" x 9" Green w/ White Specks Floor Tile**

MATERIAL LOCATION: **Rooms 127 and 125**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 110 | | |
| MATERIAL DESCRIPTION: | Light Blue Linoleum Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------------------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Rooms 312, 316 | | |
| MATERIAL QUANTITY: | 2000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | Not observed in 151 | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **110**

MATERIAL DESCRIPTION: **Light Blue Linoleum Mastic**

MATERIAL LOCATION: **Rooms 312, 316**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 111 | | |
| MATERIAL DESCRIPTION: | Textured Gray Linoleum | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 147 | | |
| MATERIAL QUANTITY: | 1500 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **111**

MATERIAL DESCRIPTION: **Textured Gray Linoleum**

MATERIAL LOCATION: **Room 147**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 112 | | |
| MATERIAL DESCRIPTION: | Textured Gray Linoleum Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 147 | | |
| MATERIAL QUANTITY: | 1500 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **112**

MATERIAL DESCRIPTION: **Textured Gray Linoleum Mastic**

MATERIAL LOCATION: **Room 147**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 113 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Charcoal Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--------------------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Gym Office(Small) | | |
| MATERIAL QUANTITY: | 150 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **113**

MATERIAL DESCRIPTION: **12" x 12" Charcoal Floor Tile**

MATERIAL LOCATION: **Gym Office(Small)**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 114 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Charcoal Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--------------------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Gym Office(Small) | | |
| MATERIAL QUANTITY: | 150 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **114**

MATERIAL DESCRIPTION: **12" x 12" Charcoal Floor Tile Mastic**

MATERIAL LOCATION: **Gym Office(Small)**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 115 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Brown Mottled Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 5 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 5. ACBM with potential for significant damage

| | | | |
|------------------------|---|-----------------|----|
| DAMAGE REASON: | Physical Damage | | |
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Auditorium Storage, Rooms 257, 258, 357, 358, 457, 458, 321, Gym Office 235-2 | | |
| MATERIAL QUANTITY: | 700 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | Damage in auditorium storage | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **115**

MATERIAL DESCRIPTION: **12" x 12" Brown Mottled Floor Tile**

MATERIAL LOCATION: **Auditorium Storage, Rooms 257, 258, 357, 358, 457, 458, 321, Gym Office 235-2**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----------|
| HOMOGENEOUS AREA: | 116 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Brown Mottled Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Auditorium Storage, Rooms 257, 258, 357, 358, 457, 458, Gym Office 235-2 | | |
| MATERIAL QUANTITY: | 700 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | | |
| COMMENTS: | | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **116**

MATERIAL DESCRIPTION: **12" x 12" Brown Mottled Floor Tile Mastic**

MATERIAL LOCATION: **Auditorium Storage, Rooms 257, 258, 357, 358, 457, 458, Gym Office 235-2**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 12
MATERIAL DESCRIPTION: 9" x 9" Red Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12 M**

MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **12 M**

MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 13

MATERIAL DESCRIPTION: 2' x 4' Pitted Lay-in Ceiling Panels

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Corridors and Classrooms

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **2' x 4' Pitted Lay-in Ceiling Panels**

MATERIAL LOCATION: **Throughout Corridors and Classrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 14

MATERIAL DESCRIPTION: 2' x 4' White Wommed Lay-in Ceiling Panels

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Lunchroom, 124, 2nd Floor Corridor, 247, 249, 354

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **2' x 4' White Wermel Lay-in Ceiling Panels**

MATERIAL LOCATION: **Lunchroom, 124, 2nd Floor Corridor, 247, 249, 354**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Exterior Brick - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Exterior Brick - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|------------|
| HOMOGENEOUS AREA: | 17 | | |
| MATERIAL DESCRIPTION: | Insulation Inside Of Vault Door | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|------------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Rooms 125 | | |
| MATERIAL QUANTITY: | 24 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Insulation Inside Of Vault Door**

MATERIAL LOCATION: **Rooms 125**

MATERIAL QUANTITY: **24** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 18 | | |
| MATERIAL DESCRIPTION: | Carpet Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

| | | | |
|------------------------|---------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Throughout Building | | |
| MATERIAL QUANTITY: | 5000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 18 A | | |
| MATERIAL DESCRIPTION: | Purple & White Mix Carpet Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---------------------------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 229, 225 | | |
| MATERIAL QUANTITY: | 2100 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | Not observed in 130, 227 | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **18 A**

MATERIAL DESCRIPTION: **Purple & White Mix Carpet Mastic**

MATERIAL LOCATION: **Room 229, 225**

MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18 B**

MATERIAL DESCRIPTION: **Orange Carpet Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 228**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **18 B**

MATERIAL DESCRIPTION: **Orange Carpet Mastic**

MATERIAL LOCATION: **Room 228**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 18 C | | |
| MATERIAL DESCRIPTION: | Blue w/ Brown Carpet w/ Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 237 | | |
| MATERIAL QUANTITY: | 700 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **18 C**

MATERIAL DESCRIPTION: **Blue w/ Brown Carpet w/ Mastic**

MATERIAL LOCATION: **Room 237**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 18 D | | |
| MATERIAL DESCRIPTION: | Blue Carpet Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 137 and Assistant Principal's Office | | |
| MATERIAL QUANTITY: | 1000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | | |
| COMMENTS: | | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **18 D**

MATERIAL DESCRIPTION: **Blue Carpet Mastic**

MATERIAL LOCATION: **Room 137 and Assistant Principal's Office**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 18 E
MATERIAL DESCRIPTION: Red Carpet Mastic
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 124 and 127

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **18 E**

MATERIAL DESCRIPTION: **Red Carpet Mastic**

MATERIAL LOCATION: **Rooms 124 and 127**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|------------------------------------|----------|--|
| HOMOGENEOUS AREA: | 18 F | | |
| MATERIAL DESCRIPTION: | Lavender Carpet Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 125

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **18 F**

MATERIAL DESCRIPTION: **Lavender Carpet Mastic**

MATERIAL LOCATION: **Room 125**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|------------------------------------|----------|--|
| HOMOGENEOUS AREA: | 18 G | | |
| MATERIAL DESCRIPTION: | Black and Green Carpet Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Principal's Office

MATERIAL QUANTITY: 700 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS: Material in inaccessible area(s) - 2025

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **18 G**

MATERIAL DESCRIPTION: **Black and Green Carpet Mastic**

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M.

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18 H**

MATERIAL DESCRIPTION: **Blue Patterned Carpet Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 126**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **18 H**

MATERIAL DESCRIPTION: **Blue Patterned Carpet Mastic**

MATERIAL LOCATION: **Room 126**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18 I**

MATERIAL DESCRIPTION: **Blue Mix Carpet Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Conference Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **18 I**

MATERIAL DESCRIPTION: **Blue Mix Carpet Mastic**

MATERIAL LOCATION: **Conference Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18 J**

MATERIAL DESCRIPTION: **Gray Carpet Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 136**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **18 J**

MATERIAL DESCRIPTION: **Gray Carpet Mastic**

MATERIAL LOCATION: **Room 136**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 18 K | | |
| MATERIAL DESCRIPTION: | Brown Mix Carpet Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|------------------------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Infant Toddler Center | | |
| MATERIAL QUANTITY: | 100 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | | |
| COMMENTS: | | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **18 K**

MATERIAL DESCRIPTION: **Brown Mix Carpet Mastic**

MATERIAL LOCATION: **Infant Toddler Center**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 19 | | |
| MATERIAL DESCRIPTION: | Black Science Lab Tables | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Rooms 212, 214 | | |
| MATERIAL QUANTITY: | 186 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Black Science Lab Tables**

MATERIAL LOCATION: **Rooms 212, 214**

MATERIAL QUANTITY: **186** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 2 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Dark Brown w/ White & Black Streaks Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | Deterioration | | |
| HISTORICAL RESPONSE ACTION: | Repair | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

| | | | |
|------------------------|-------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Rooms 210, 325, 344, 346, 347 | | |
| MATERIAL QUANTITY: | 769 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **12" x 12" Dark Brown w/ White & Black Streaks Floor Tile**

MATERIAL LOCATION: **Rooms 210, 325, 344, 346, 347**

MATERIAL QUANTITY: **769** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 20
MATERIAL DESCRIPTION: Gray Boiler Rope Gaskets
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Chrysotile FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Interiors
MATERIAL QUANTITY: 30 MATERIAL UNITS: LF
DAMAGE QUANTITY: DAMAGE UNITS: LF
COMMENTS: Material in inaccessible area(s) - 2025

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Gray Boiler Rope Gaskets**

MATERIAL LOCATION: **Boiler Interiors**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M.

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 21
MATERIAL DESCRIPTION: Roofing Material - Non-AHERA
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Roof

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Roofing Material - Non-AHERA**

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Non-AHERA

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|---|----------|
| HOMOGENEOUS AREA: | 23 | |
| MATERIAL DESCRIPTION: | 9" x 9" Green w/ White Specks Floor Tile Mastic | |
| HISTORICAL AHERA DAMAGE CATEGORY | ACBM with the potential for damage | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 127 Office Closet and Possibly Under the Carpet in Room 125 & Room 125 Closet

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **9" x 9" Green w/ White Specks Floor Tile Mastic**

MATERIAL LOCATION: **Room 127 Office Closet and Possibly Under the Carpet in Room 125 & Room 125 Closet**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Fire Door Lining**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Door #9**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Fire Door Lining**

MATERIAL LOCATION: **Door #9**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|--|----------|
| HOMOGENEOUS AREA: | 25 | |
| MATERIAL DESCRIPTION: | 9" x 9" Tan w/ Brown & Beige Streaks Floor Tile Mastic | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 126, 330 (Teachers' Lounge), 1st Floor Corridor

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **9" x 9" Tan w/ Brown & Beige Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 126, 330 (Teachers' Lounge), 1st Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **9" x 9" Light Green Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 127, Office Closet & Possibly Under the Carpet in 125 & Room 125 Closet**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **9" x 9" Light Green Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 127, Office Closet & Possibly Under the Carpet in 125 & Room 125 Closet**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 27

MATERIAL DESCRIPTION: Black Table Tops

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 344, 327, and 323

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Black Table Tops**

MATERIAL LOCATION: **Room 344, 327, and 323**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28
MATERIAL DESCRIPTION: Gray Exhaust Hood Lining
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 327

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Gray Exhaust Hood Lining**

MATERIAL LOCATION: **Room 327**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 29
MATERIAL DESCRIPTION: 2' x 5' Thin Black Transite Table Tops
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **2' x 5' Thin Black Transite Table Tops**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----------|
| HOMOGENEOUS AREA: | 2M | | |
| MATERIAL DESCRIPTION: | 12" x 12" Dark Brown w/ White & Black Streaks Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 210, 325, 344, 346, 347**

MATERIAL QUANTITY: **769** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **2M**

MATERIAL DESCRIPTION: **12" x 12" Dark Brown w/ White & Black Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 210, 325, 344, 346, 347**

MATERIAL QUANTITY: **769** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 3
MATERIAL DESCRIPTION: Black Asphalight Flooring
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Stairways

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **Black Asphalight Flooring**

MATERIAL LOCATION: **Stairways**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 30

MATERIAL DESCRIPTION: 1.5' x 1.5' Gray Steam Table Boards

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Open Basement Area

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **1.5' x 1.5' Gray Steam Table Boards**

MATERIAL LOCATION: **Open Basement Area**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----|
| HOMOGENEOUS AREA: | 31 | | |
| MATERIAL DESCRIPTION: | Aircell Pipe Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Damaged or significantly damaged friable thermal system insulating ACBM | | |
| HISTORICAL DAMAGE REASON: | Deterioration | | |
| HISTORICAL RESPONSE ACTION: | Repair | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Outside Gym, Possibly in Inaccessible Areas of the Building**

MATERIAL QUANTITY: **24** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS: **Repaired**

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Outside Gym, Possibly in Inaccessible Areas of the Building**

MATERIAL QUANTITY: **24** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|--|----------|
| HOMOGENEOUS AREA: | 32 | |
| MATERIAL DESCRIPTION: | Hard Joint Compound on Aircell Pipe Insulation | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | |
| ASBESTOS TYPE: | Amosite | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Possibly in Inaccessible Areas of the Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material in inaccessible area(s) - 2025

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Hard Joint Compound on Aircell Pipe Insulation**

MATERIAL LOCATION: **Possibly in Inaccessible Areas of the Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M.

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 33 | | |
| MATERIAL DESCRIPTION: | Paperwrap Pipe Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Possibly in Inaccessible Areas of the Building | | |
| MATERIAL QUANTITY: | 210 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**

MATERIAL LOCATION: **Possibly in Inaccessible Areas of the Building**

MATERIAL QUANTITY: **210** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 34 | | |
| MATERIAL DESCRIPTION: | Hard Joint Compound on Paperwrap Pipe Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|---------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Throughout Basement | | |
| MATERIAL QUANTITY: | 150 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Hard Joint Compound on Paperwrap Pipe Insulation**

MATERIAL LOCATION: **Throughout Basement**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----|
| HOMOGENEOUS AREA: | 35 | | |
| MATERIAL DESCRIPTION: | Mag Block Pipe Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Damaged or significantly damaged friable thermal system insulating ACBM | | |
| HISTORICAL DAMAGE REASON: | Deterioration | | |
| HISTORICAL RESPONSE ACTION: | Encapsulate | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engine Room, Air Tunnel 3 & 8**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS: **Repaired**

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**

MATERIAL LOCATION: **Engine Room, Air Tunnel 3 & 8**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Encapsulate

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 36 | | |
| MATERIAL DESCRIPTION: | Mag Block Pipe Joint Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|-------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Engine Room, Air Tunnel 3 & 8 | | |
| MATERIAL QUANTITY: | 120 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Mag Block Pipe Joint Insulation**

MATERIAL LOCATION: **Engine Room, Air Tunnel 3 & 8**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 37 | | |
| MATERIAL DESCRIPTION: | Hard Joint Compound on Fiberglass Pipe Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Amosite | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|--------------------------------|-----------------|---------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Engine Room, Air Tunnels 3 & 8 | | |
| MATERIAL QUANTITY: | 180 | MATERIAL UNITS: | FITTING |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | FITTING |
| COMMENTS: | | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUILDING ID: **1470**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/23/2025**

ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Hard Joint Compound on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Engine Room, Air Tunnels 3 & 8**

MATERIAL QUANTITY: **180** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: MATERIAL UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 38
MATERIAL DESCRIPTION: Plaster Walls
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout 1918 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Plaster Walls**

MATERIAL LOCATION: **Throughout 1918 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 39
MATERIAL DESCRIPTION: Plaster Ceilings
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout 1918 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Plaster Ceilings**

MATERIAL LOCATION: **Throughout 1918 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|---|----------|
| HOMOGENEOUS AREA: | 4 | |
| MATERIAL DESCRIPTION: | 12" x 12" Black w/ Brown Streaks Floor Tile | |
| HISTORICAL AHERA DAMAGE CATEGORY | ACBM with the potential for damage | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | |
| ASBESTOS TYPE: | Assumed | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 132, 134, 143, 145, 230 (Womens Bathroom), 244, 246, 248, 254, and 310, Men's 3rd Floor Bathroom

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **12" x 12" Black w/ Brown Streaks Floor Tile**

MATERIAL LOCATION: **Rooms 132, 134, 143, 145, 230 (Womens Bathroom), 244, 246, 248, 254, and 310, Men's 3rd Floor Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **White Boiler Rope Gasket**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boilers**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **White Boiler Rope Gasket**

MATERIAL LOCATION: **Boilers**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 41
MATERIAL DESCRIPTION: Gray Transite Counter Tops
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Gray Transite Counter Tops**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 42
MATERIAL DESCRIPTION: Mag Type Boiler Gasket
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Chrysotile FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Mag Type Boiler Gasket**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|-----------------------------|----------|
| HOMOGENEOUS AREA: | 43 | |
| MATERIAL DESCRIPTION: | Leather Like Boiler Gaskets | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Leather Like Boiler Gaskets**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Mineral Wool Boiler Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Mineral Wool Boiler Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 45
MATERIAL DESCRIPTION: Water Tank Insulation
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Water Tank Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 46
MATERIAL DESCRIPTION: Water Tank Insulation
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Water Tank Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 47
MATERIAL DESCRIPTION: Aircell Duct Insulation
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Chrysotile FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Crawlspace 3
MATERIAL QUANTITY: 1200 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF
COMMENTS: Material in inaccessible area(s) - 2025

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Aircell Duct Insulation**

MATERIAL LOCATION: **Crawlspace 3**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M.

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 48
MATERIAL DESCRIPTION: Brown Vinyl Stage Curtain
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Stage

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Brown Vinyl Stage Curtain**

MATERIAL LOCATION: **Stage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 49
MATERIAL DESCRIPTION: 2' x 4' Brown Ceiling Panels
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Corridor 9

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **2' x 4' Brown Ceiling Panels**

MATERIAL LOCATION: **Corridor 9**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 4M

MATERIAL DESCRIPTION: 12" x 12" Black w/ Brown Streaks Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 132, 134, 143, 145, 230 (Womens Bathroom), 244, 246, 248, 254, and 310, Men's 3rd Floor Bathroom

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **4M**

MATERIAL DESCRIPTION: **12" x 12" Black w/ Brown Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 132, 134, 143, 145, 230 (Womens Bathroom), 244, 246, 248, 254, and 310, Men's 3rd Floor Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 5

MATERIAL DESCRIPTION: 9" x 9" Tan w/ Brown & Beige Streaks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 126, 330 (Teachers' Lounge), 1st Floor Corridor

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **9" x 9" Tan w/ Brown & Beige Streaks Floor Tile**

MATERIAL LOCATION: **Rooms 126, 330 (Teachers' Lounge), 1st Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 50 | | |
| MATERIAL DESCRIPTION: | 2' x 5' Black Transite Table Tops | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Rooms 244, 246, 248, 344, 346, 348, 321, 325, and 327 | | |
| MATERIAL QUANTITY: | 5000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **2' x 5' Black Transite Table Tops**

MATERIAL LOCATION: **Rooms 244, 246, 248, 344, 346, 348, 321, 325, and 327**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 51
MATERIAL DESCRIPTION: Gray Transite Table Tops
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Chrysotile FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 214

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Gray Transite Table Tops**

MATERIAL LOCATION: **Room 214**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **2' x 4' White Pitted Ceiling Panels**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 109, 110, 118, 310, 312, 314, and 320, 1st & 3rd Floor Corridors**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **2' x 4' White Pitted Ceiling Panels**

MATERIAL LOCATION: **Rooms 109, 110, 118, 310, 312, 314, and 320, 1st & 3rd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|---|----------|
| HOMOGENEOUS AREA: | 53 | |
| MATERIAL DESCRIPTION: | 12" x 12" Dark Brown w/ White & Black Specks Floor Tile | |
| HISTORICAL AHERA DAMAGE CATEGORY | ACBM with the potential for damage | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | |
| ASBESTOS TYPE: | Assumed | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 314, Engineer's Office

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **12" x 12" Dark Brown w/ White & Black Specks Floor Tile**

MATERIAL LOCATION: **Room 314, Engineer's Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 54 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Light Brown w/ Red & White Specks Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 5 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Corridors, Rooms 109, 220 and 320 | | |
| MATERIAL QUANTITY: | 65000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | Damage in 1st floor hall by between boiler room and main building, hall by 250 | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ Red & White Specks Floor Tile**

MATERIAL LOCATION: **Corridors, Rooms 109, 220 and 320**

MATERIAL QUANTITY: **65000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **45** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 55
MATERIAL DESCRIPTION: Ceiling Plaster
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout 1898 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Ceiling Plaster**

MATERIAL LOCATION: **Throughout 1898 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Plaster Walls**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1898 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **Plaster Walls**

MATERIAL LOCATION: **Throughout 1898 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **Gypsum Rock Lath**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Girls Gyms and Balconies**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **Gypsum Rock Lath**

MATERIAL LOCATION: **Girls Gyms and Balconies**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----|
| HOMOGENEOUS AREA: | 58 | | |
| MATERIAL DESCRIPTION: | Aircell Pipe Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Damaged or significantly damaged friable thermal system insulating ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Gym 12**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Gym 12**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 59 | | |
| MATERIAL DESCRIPTION: | Hard Joint Compound on Aircell Pipe Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|--------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Gym 12 | | |
| MATERIAL QUANTITY: | 25 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **Hard Joint Compound on Aircell Pipe Insulation**

MATERIAL LOCATION: **Gym 12**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 6

MATERIAL DESCRIPTION: Reddish Brown Linoleum

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 223, 225, and 229

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **Reddish Brown Linoleum**

MATERIAL LOCATION: **Rooms 223, 225, and 229**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----|
| HOMOGENEOUS AREA: | 60 | | |
| MATERIAL DESCRIPTION: | Paperwrap Pipe Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Damaged or significantly damaged friable thermal system insulating ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----|
| HOMOGENEOUS AREA: | 61 | | |
| MATERIAL DESCRIPTION: | Hard Joint Compound on Paperwrap Pipe Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Damaged or significantly damaged friable thermal system insulating ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **Hard Joint Compound on Paperwrap Pipe Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room, Gym 12, Auditorium**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material in inaccessible area(s) - 2025**

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**

MATERIAL LOCATION: **Boiler Room, Gym 12, Auditorium**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M.

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **Mag Block Joint Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room, Gym 12, Auditorium**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material in inaccessible area(s) - 2025**

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **Mag Block Joint Insulation**

MATERIAL LOCATION: **Boiler Room, Gym 12, Auditorium**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M.

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----|
| HOMOGENEOUS AREA: | 64 | | |
| MATERIAL DESCRIPTION: | Hard Joint Compound on Fiberglass Pipe Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Damaged or significantly damaged friable thermal system insulating ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|-------------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Boiler Room and Throughout Basement | | |
| MATERIAL QUANTITY: | 15 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **Hard Joint Compound on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Boiler Room and Throughout Basement**

MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 65 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Olive w/ Brown & White Specks Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 130 | | |
| MATERIAL QUANTITY: | 500 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **12" x 12" Olive w/ Brown & White Specks Floor Tile**

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 66 | | |
| MATERIAL DESCRIPTION: | 12" x 12" White w/ Brown & Gray Streaks Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 130 | | |
| MATERIAL QUANTITY: | 200 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **12" x 12" White w/ Brown & Gray Streaks Floor Tile**

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|---|----------|
| HOMOGENEOUS AREA: | 67 | |
| MATERIAL DESCRIPTION: | 12" x 12" Light Brown w/ Red & White Streaks Floor Tile | |
| HISTORICAL AHERA DAMAGE CATEGORY | ACBM with the potential for damage | |
| HISTORICAL DAMAGE REASON: | Physical Damage | |
| HISTORICAL RESPONSE ACTION: | Repair | |
| ASBESTOS TYPE: | Assumed | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 147

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ Red & White Streaks Floor Tile**

MATERIAL LOCATION: **Room 147**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **1' x 1' White Wormed & Pitted Ceiling Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 144 and Boys Gym, 227-229**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **1' x 1' White Wormed & Pitted Ceiling Tile**

MATERIAL LOCATION: **Room 144 and Boys Gym, 227-229**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **1' x 1' Beige Grooved Ceiling Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Girls Gym, Room 333**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **1' x 1' Beige Grooved Ceiling Tile**

MATERIAL LOCATION: **Girls Gym, Room 333**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 7

MATERIAL DESCRIPTION: 12" x 12" Gray w/ Brown & White Streaks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 235

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Brown & White Streaks Floor Tile**

MATERIAL LOCATION: **Room 235**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 70
MATERIAL DESCRIPTION: 2' x 4' White Wommed Lay-in Ceiling Panels
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 227 and Library

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **2' x 4' White Wommed Lay-in Ceiling Panels**

MATERIAL LOCATION: **Room 227 and Library**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **1' x 1' White Pitted Ceiling Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 132, 134, 225, and 229, 2nd Floor Between Girls & Boys Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **1' x 1' White Pitted Ceiling Tile**

MATERIAL LOCATION: **Rooms 132, 134, 225, and 229, 2nd Floor Between Girls & Boys Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 72
MATERIAL DESCRIPTION: 2' x 4' White Pinhole Lay-in Ceiling Panels
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 140

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **2' x 4' White Pinhole Lay-in Ceiling Panels**

MATERIAL LOCATION: **Room 140**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 73
MATERIAL DESCRIPTION: Orange Fabric Stage Curtain
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Stage

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **Orange Fabric Stage Curtain**

MATERIAL LOCATION: **Stage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 74
MATERIAL DESCRIPTION: 4" Black Vinyl Baseboard
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 75
MATERIAL DESCRIPTION: 4" Black Vinyl Baseboard Mastic
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 76
MATERIAL DESCRIPTION: Tar Paper Under Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 330

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **Tar Paper Under Floor Tile**

MATERIAL LOCATION: **Room 330**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 77

MATERIAL DESCRIPTION: Tar Paper Mastic Under Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 330

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **Tar Paper Mastic Under Floor Tile**

MATERIAL LOCATION: **Room 330**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 78 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Brown w/ White Streaks Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 5 ACBM with potential for significant damage | | |
| HISTORICAL DAMAGE REASON: | Physical Damage Deterioration | | |
| HISTORICAL RESPONSE ACTION: | Repair | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

| | | | |
|------------------------|----------------------------------|-----------------|----|
| DAMAGE REASON: | Physical Damage Deterioration | | |
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 341 Storage | | |
| MATERIAL QUANTITY: | 400 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | Damage in 341 storage | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ White Streaks Floor Tile**

MATERIAL LOCATION: **Room 341 Storage**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 79 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Brown w/ White Streaks Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 341 Storage | | |
| MATERIAL QUANTITY: | 400 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Room 341 Storage**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 7M

MATERIAL DESCRIPTION: 12" x 12" Gray w/ Brown & White Streaks Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 235

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **7M**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Brown & White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Room 235**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 8 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Light Brown w/ Red & White Streaks Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | Physical Damage | | |
| HISTORICAL RESPONSE ACTION: | Repair | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Corridors, Rooms 109, 220 and 320 | | |
| MATERIAL QUANTITY: | 65000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ Red & White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Corridors, Rooms 109, 220 and 320**

MATERIAL QUANTITY: **65000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 80
MATERIAL DESCRIPTION: 9" x 9" Beige Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Chrysotile FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 246

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile**

MATERIAL LOCATION: **Room 246**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 81
MATERIAL DESCRIPTION: 9" x 9" Beige Floor Tile Mastic
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Chrysotile FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 246

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile Mastic**

MATERIAL LOCATION: **Room 246**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 82 | | |
| MATERIAL DESCRIPTION: | Vault Door Liner | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|-----------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Rooms 125 | | |
| MATERIAL QUANTITY: | 24 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **Vault Door Liner**

MATERIAL LOCATION: **Rooms 125**

MATERIAL QUANTITY: **24** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----------|
| HOMOGENEOUS AREA: | 83 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Gray w/ Brown Specks Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 125 | | |
| MATERIAL QUANTITY: | 700 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Brown Specks Floor Tile**

MATERIAL LOCATION: **Room 125**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 84 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Gray w/ Brown Specks Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 125 | | |
| MATERIAL QUANTITY: | 700 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Brown Specks Floor Tile Mastic**

MATERIAL LOCATION: **Room 125**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 85 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Beige Mix Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 5 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

| | | | |
|------------------------|---|-----------------|-----------|
| DAMAGE REASON: | Physical Damage | | |
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 130, 124 (Office/Closet), 127, 132, 134 gills locker room storage | | |
| MATERIAL QUANTITY: | 900 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | Damage in 132, girls locker room storage | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **85**

MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile**

MATERIAL LOCATION: **Room 130, 124 (Office/Closet), 127, 132, 134 gills locker room storage**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **15** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 86 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Beige Mix Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 130, 124 (Office/Closet), 127, 132, 134 | | |
| MATERIAL QUANTITY: | 900 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **86**

MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile Mastic**

MATERIAL LOCATION: **Room 130, 124 (Office/Closet), 127, 132, 134**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 87 | | |
| MATERIAL DESCRIPTION: | 12" x 12" White w/ Gray Streaks Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 5 ACBM with potential for significant damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 5. ACBM with potential for significant damage

| | | | |
|------------------------|--|-----------------|----|
| DAMAGE REASON: | Physical Damage | | |
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 132 & 134 Womens Faculty Bathroom (254) | | |
| MATERIAL QUANTITY: | 1664 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | Damage in woman's restroom 254 | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **87**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Streaks Floor Tile**

MATERIAL LOCATION: **Room 132 & 134 Womens Faculty Bathroom (254)**

MATERIAL QUANTITY: **1664** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----------|
| HOMOGENEOUS AREA: | 88 | | |
| MATERIAL DESCRIPTION: | 12" x 12" White w/ Gray Streaks Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with potential for significant damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 132 & 134, Womens Faculty Bathroom (254) | | |
| MATERIAL QUANTITY: | 1664 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Room 132 & 134, Womens Faculty Bathroom (254)**

MATERIAL QUANTITY: **1664** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 89 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Gray Mix Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 5 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | Physical Damage | | |
| HISTORICAL RESPONSE ACTION: | Repair | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 5. ACBM with potential for significant damage

| | | | |
|------------------------|--------------------|-----------------|----|
| DAMAGE REASON: | Physical Damage | | |
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 143 | | |
| MATERIAL QUANTITY: | 1500 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | Damage in room 143 | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **89**

MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile**

MATERIAL LOCATION: **Room 143**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 9

MATERIAL DESCRIPTION: Orange Linoleum

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 101

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **Orange Linoleum**

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 9 M | | |
| MATERIAL DESCRIPTION: | Orange Linoleum Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 101 | | |
| MATERIAL QUANTITY: | 500 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **9 M**

MATERIAL DESCRIPTION: **Orange Linoleum Mastic**

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 90 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Gray Mix Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 143 | | |
| MATERIAL QUANTITY: | 1500 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile Mastic**

MATERIAL LOCATION: **Room 143**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 91 | | |
| MATERIAL DESCRIPTION: | 12" x 12" White w/ Gray Streaks Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|------------------------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Infant/Toddler Center | | |
| MATERIAL QUANTITY: | 500 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | | |
| COMMENTS: | | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **91**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Streaks Floor Tile**

MATERIAL LOCATION: **Infant/Toddler Center**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|----|
| HOMOGENEOUS AREA: | 92 | | |
| MATERIAL DESCRIPTION: | 12" x 12" White w/ Gray Streaks Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Infant/Toddler Center | | |
| MATERIAL QUANTITY: | 500 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Infant/Toddler Center**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 93
MATERIAL DESCRIPTION: 12" x 12" Pink/Purple Speckled Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Classrooms 147 & 151

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **93**

MATERIAL DESCRIPTION: **12" x 12" Pink/Purple Speckled Floor Tile**

MATERIAL LOCATION: **Classrooms 147 & 151**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | |
|----------------------------------|--|----------|
| HOMOGENEOUS AREA: | 94 | |
| MATERIAL DESCRIPTION: | 12" x 12" Pink/Purple Speckled Floor Tile Mastic | |
| HISTORICAL AHERA DAMAGE CATEGORY | | |
| HISTORICAL DAMAGE REASON: | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | |
| ASBESTOS TYPE: | Assumed | FRIABLE: |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Classrooms 147 & 151

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **94**

MATERIAL DESCRIPTION: **12" x 12" Pink/Purple Speckled Floor Tile Mastic**

MATERIAL LOCATION: **Classrooms 147 & 151**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 95 | | |
| MATERIAL DESCRIPTION: | 2' x 4' White Ceiling Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|----------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Classrooms 147 & 151 | | |
| MATERIAL QUANTITY: | 1500 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **95**

MATERIAL DESCRIPTION: **2' x 4' White Ceiling Tile**

MATERIAL LOCATION: **Classrooms 147 & 151**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------|----------|----|
| HOMOGENEOUS AREA: | 96 | | |
| MATERIAL DESCRIPTION: | 4" Brown Vinyl Baseboard | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Classrooms 147 & 151 | | |
| MATERIAL QUANTITY: | 150 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **96**

MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard**

MATERIAL LOCATION: **Classrooms 147 & 151**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|-----------------------------------|----------|----|
| HOMOGENEOUS AREA: | 97 | | |
| MATERIAL DESCRIPTION: | 4" Brown Vinyl Baseboard Adhesive | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Classrooms 147 & 151 | | |
| MATERIAL QUANTITY: | 150 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **97**

MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Classrooms 147 & 151**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 98 | | |
| MATERIAL DESCRIPTION: | Red Stage Curtain | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-------------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Auditorium | | |
| MATERIAL QUANTITY: | 1000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **98**

MATERIAL DESCRIPTION: **Red Stage Curtain**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 99
MATERIAL DESCRIPTION: Orange Carpet Adhesive
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Auditorium and Room 228

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **99**

MATERIAL DESCRIPTION: **Orange Carpet Adhesive**

MATERIAL LOCATION: **Auditorium and Room 228**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | A | | |
| MATERIAL DESCRIPTION: | Blue Linoleum Flooring | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 5 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

| | | | |
|------------------------|--|-----------------|-----------|
| DAMAGE REASON: | Physical Damage | | |
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Rooms 327, 344, 348, 314, 246 (Prep), 244 | | |
| MATERIAL QUANTITY: | 2547 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | SF | | |
| COMMENTS: | Not observed in 147, damage in 246 | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Blue Linoleum Flooring**

MATERIAL LOCATION: **Rooms 327, 344, 348, 314, 246 (Prep), 244**

MATERIAL QUANTITY: **2547** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|----------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | A-1 | | |
| MATERIAL DESCRIPTION: | Blue Linoleum Flooring-Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Rooms 327, 344, 348, 314, 246 (Prep), 244 | | |
| MATERIAL QUANTITY: | 2547 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **A-1**

MATERIAL DESCRIPTION: **Blue Linoleum Flooring-Mastic**

MATERIAL LOCATION: **Rooms 327, 344, 348, 314, 246 (Prep), 244**

MATERIAL QUANTITY: **2547** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | B | | |
| MATERIAL DESCRIPTION: | 12" x 12" Blue Vinyl Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 5 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 5. ACBM with potential for significant damage

| | | | |
|------------------------|---|-----------------|----|
| DAMAGE REASON: | Physical Damage | | |
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Rooms 354, 230(Teachers' Lounge) & 330(Teachers' Lounge), Mens 3rd Floor Bathroom, Room 246 Prep. Replacement tile in 147 | | |
| MATERIAL QUANTITY: | 1200 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | Damage in 354 men's room, 330, and 147 | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **12" x 12" Blue Vinyl Floor Tile**

MATERIAL LOCATION: **Rooms 354, 230(Teachers' Lounge) & 330(Teachers' Lounge), Mens 3rd Floor Bathroom, Room 246 Prep. Replacement tile in 147**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **25** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | B-1 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Blue Vinyl Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Rooms 354, 230(Teachers' Lounge) & 330(Teachers' Lounge), Mens 3rd Floor Bathroom, Room 246 Prep. | | |
| MATERIAL QUANTITY: | 1200 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUILDING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jackson Montgomery | | |
| SCHOOL NAME: | Marshall High School | REVIEW DATE: | 7/23/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

HOMOGENEOUS AREA: **B-1**

MATERIAL DESCRIPTION: **12" x 12" Blue Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 354, 230(Teachers' Lounge) & 330(Teachers' Lounge), Mens 3rd Floor Bathroom, Room 246 Prep.**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**

CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey Walker**

SCHOOL NAME: **Marshall High School** INSPECTION DATE: **6/27/2025**

ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-09969**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **117**

MATERIAL DESCRIPTION: **Smooth Gray Linoleum**

MATERIAL LOCATION: **Room 151**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **MODERATE** CONDITION: **No Damage**

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:

DAMAGE REASON:

DAMAGE REASON:

DAMAGE UNITS:

DAMAGE QUANTITY: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/23/2025**

ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **117**

MATERIAL DESCRIPTION: **Smooth Gray Linoleum**

MATERIAL LOCATION: **Room 151**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *07/23/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 47041 | BUIDLING ID: | 1470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Dionne Carey Walker | | |
| SCHOOL NAME: | Marshall High School | INSPECTION DATE: | 6/27/2025 | | |
| ADDRESS: | 3250 W. Adams | IDPH LICENSE NO: | 100-09969 | | |

INFORMATION FROM CURRENT INSPECTION

| | | | |
|------------------------|--------------------------------------|-----------------|-----------|
| HOMOGENEOUS AREA: | 118 | | |
| MATERIAL DESCRIPTION: | Smooth Gray Linoleum Mastic | | |
| MATERIAL LOCATION: | Room 151 | | |
| MATERIAL QUANTITY: | 700 | MATERIAL UNITS: | SF |
| MATERIAL CATEGORY: | MISC | FRIABLE: | No |
| ASBESTOS TYPE: | Assumed | | |
| DISTURBANCE POTENTIAL: | LOW | CONDITION: | No Damage |
| AHERA DAMAGE CATEGORY: | 6 ACBM with the potential for damage | | |
| ACCESSIBILITY: | Not Reachable | DAMAGE REASON: | |
| DAMAGE QUANTITY: | | DAMAGE REASON: | |
| | | DAMAGE REASON: | |
| | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 06/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47041** BUIDLING ID: **1470**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Marshall High School** REVIEW DATE: **7/23/2025**

ADDRESS: **3250 W. Adams** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **118**

MATERIAL DESCRIPTION: **Smooth Gray Linoleum Mastic**

MATERIAL LOCATION: **Room 151**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *07/23/2025*

APPENDIX B

Inspector and Management Planner Licenses



OCCUPATIONAL TRAINING & SUPPLY, INC. 2024
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

Asbestos Abatement Supervisor Refresher

Occupational Training & Supply, Inc. certifies that

Dionne L.C. Walker

has successfully completed the Asbestos Abatement Supervisor Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 10/14/2024

Exam Date: 10/14/2024

Expiration Date: 10/14/2025

Certificate Number: ASR2410142781

Course Credit Hours: ASR 8 Hours

Kristina Miczek

Kristina Miczek, Training Manager

Dionne Walker

Asbestos Project Manager, Illinois Licensed Building Inspector, Air Sampling Professional



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 09969

ISSUED
4/28/2025

EXPIRES
05/15/2026

DIONNE L CAREY WALKER
211 SOMERSET DRIVE
STREAMWOOD, IL 60107
Environmental Health



ENDORSEMENTS

INSPECTOR

TC EXPIRES

10/11/2025

PROJECT MANAGER
AIR SAMPLING PROFESSIONAL



10/14/2025

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



Jackson Montgomery

Illinois Licensed Building Inspector, Air Sampling Professional, Management Planner



ENDORSEMENTS

INSPECTOR

TC EXPIRES

2/22/2025

ENDORSEMENTS

TC EXPIRES

10/29/2025

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



2200 Vandalia Street, Collinsville, IL 62234 * Phone: 618-855-8764

Environmental and Occupational Safety & Health Training

Does hereby certify

Jackson Montgomery

600 W. Van Buren St., Suite 500, Chicago, IL 60607



*Has successfully completed and passed the course examination with at least
70% for accreditation under AHERA (Title II)*

Asbestos Management Planner Initial

Class Date: 10/28-29/2024

Examination Date: 10/29/2024

STC Certificate Number: STC-20241029-000101AMPI

Certification Expiration: 10/29/2025

A handwritten signature in black ink that reads 'David M. Mendoza'.

David M. Mendoza – President/Training Director

Certified Environmental Specialist

OSHA Authorized Instructor

This training course is accredited by the Illinois Department of Public Health and the Missouri Department of Natural Resources

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

| | CODE | KEY |
|--------------------------|------|--|
| MATERIAL | ACBM | Asbestos Containing Building Materials |
| MATERIAL CATEGORY | MISC | Miscellaneous |
| | SURF | Surfacing |
| | TSI | Thermal System Insulation |
| MATERIAL UNITS | LF | Linear Feet |
| | SF | Square Feet |
| | CF | Cubic Feet |
| DAMAGE TYPE | Loc | Localized |
| | Dist | Distributed |