

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0545
SCHOOL NAME: Clemente Academy
ADDRESS OF SCHOOL: 1147 N. Western Ave
CITY: Chicago, IL, 60622

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 9/20/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 5/9/2025 ENROLLMENT 485
IDPH INSPECTOR LICENSE NUMBER: 100-18790
IDPH LICENSED INSPECTOR NAME (Please Print): Allizon Brooks
IDPH MP LICENSE NUMBER: 100-04019
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Arturo Saenz

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 6/9/2025

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Clemente Academy

1147 N. Western Ave
Chicago, IL, 60622

Unit: 51091
Building ID: 1840

IDPH ID Number: 14-016-2990-0545

REPORT DATE:
Monday, June 09, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
Specialty Consulting, Inc.

2942 W. Van Buren Street
Chicago, IL, 60612
Phone (312) 319-7575
Fax (312) 319-7580

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

06/09/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Specialty Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 51091 Region: 02 IDPH ID: 14-016-2990-0545

School: Clemente Academy Building ID: 1840

Address: 1147 N. Western Ave

Chicago, IL, 60622

Building Contact: Campos, Roberto Contact Phone: 3127239460

Current Building Owners: Chicago Public Schools

Reinspection Date: 5/9/2025

Review Date: 06/09/2025

Inspector: Allizon Brooks

Inspector IDPH License: 100-18790

Management Planner: Arturo Saenz

Management Planner IDPH License: 100-04019

If you have any questions or comments, please contact us at (312) 319-7575

Sincerely,
Specialty Consulting, Inc.



Arturo Saenz
100-04019

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: June 09, 2025

RE: Clemente Academy, Unit 51091
1147 N. Western Ave
Chicago, IL, 60622

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Clemente Academy , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Clemente Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Clemente Academy Unit: 51091 Region: 02
Address: 1147 N. Western Ave Chicago, IL, 60622
IDPH ID: 14-016-2990-0545 Building ID: 1840
Contact: Campos, Roberto Phone: 3127239460

2. Description of Facility

Original Construction: 1974 Additional Construction: 1974,1974
Total Square Footage: 354518 No of Floors: 8
Current Occupancy: 485

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Specialty Consulting, Inc.
Contact: Jigar Shah
Address 2942 W. Van Buren Street
Phone: (312) 319-7575 Fax: (312) 319-7580

5. Inspector

Inspector Name: Allizon Brooks

Inspector IDPH license # 100-18790 Signature:
Reinspection Date: 5/9/2025 Date: 5/9/2025

6. Management Planner

Management Planner Name: Arturo Saenz

Management Planner IDPH license # 100-04019 Signature:
Date: 06/09/2025




7. Review Date: 06/09/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 6/9/2025

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Specialty Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Clemente Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

- A. The following HAs have changed assessment categories for Building 1840:

B. The following new homogenous areas have been identified for Building 1840:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

06	12"x12" Brown w/Specks Floor Tile
06A	12"x12" Brown w/ Specks Floor Tile Mastic
07	12"x12" Black w/speckle VFT
11	Spray-on Insulation
14	MJP E/F/V on Fiberglass Pipe Insulation
15	12"x12" Black Floor Tile Mastic
17	12"x12" Orange VFT
18	12"x12" Orange VFT Mastic
19	12"x12" Beige w/Specks VFT
20	12"x12" Beige w/Specks VFT Mastic
21	Drywall
22	1'x1' White Ceiling Tile
23	1'x1' White Ceiling Tile Mastic
24	2'x4' White Ceiling Tile
25	Carpet
26	Yellow Mastic
27	Carpet on Yellow Mastic
28	12"x12" Brown Speckled VFT
29	12"x12" Brown Speckled VFT Mastic
32	Terrazzo
33	Lab Countertops
34	12"x12" Beige w/black speckles VFT
35	12"x12" Beige w/black speckles VFT Mastic
36	12"x12" Blue w/blue speckles VFT
37	12"x12" Blue w/blue speckles Mastic
38	12"x12" Yellow speckle VFT
39	12"x12" Yellow speckle VFT Mastic
40	12"x12" White w/gray speckle VFT
41	12"x12" White w/gray speckle VFT Mastic
42	12"x12" Purple speckle VFT
43	12"x12" Purple speckle VFT Mastic
44	2'x4' Pin-Hole Ceiling Tile
45	2'x2' White ceiling tile
46	2'x4' White smooth ceiling tile
47	Transite Fume Hood
48	Tank Insulation
49	Red Fire Stop Sealant
50	Dark Brown Linoleum
50A	Dark Brown Linoelum Mastic
51	18"x18" Black Anti-slip Floor Tile
51A	18"x18" Black Anti-slip Floor Tile Mastic
52	12"x12" Off-White w/Beige + White Streaks Floor

	Tile
52A	12"x12" Off-White w/Beige + White Streaks Floor Tile Mastic
53	2' x 4' White Pinhole Ceiling Tile
54	1' x 1' White Pinhole Ceiling tile
55	1' x 4' White Pinhole Ceiling Tile
56	Linoleum White
56A	Linoleum Gray
57	Table and countertops black
58	Fume Hood
59	16" x 16" Gray w/ specks VFT
59A	16" x 16" Gray w/ specks VFT Mastic
60	16" x 16" Blue w/ specks VFT
60A	16" x 16" Blue w/ specks VFT Mastic
61	16" x 16" Yellow w/ specks VFT
61A	16" x 16" Yellow w/ specks VFT Mastic
C	Hard Coat Plaster
D	Drywall Tape
E	Drywall Joint Compound

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Allizon Brooks, IDPH License # 100-18790. The Management Plan was updated by Arturo Saenz, IDPH License # 100-04019. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Clemente Academy Building 1840 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Clemente Academy **Unit** 51091 **Building ID** 1840
Address 1147 N. Western Ave **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	12"x12" Dark Brown w/ Speckles Floor Tile	14,790	SF	Bsmt, Halls, 2/4-7 floor lunchrms, ROTC, 201-208/215/216/218/23 0/231/235, TV Studio, Audio, Dark/Control/Supply Rooms, Stairways, 4th floor vestibule, 5/6/7 floor baths, 499/599/699/799/81 6/818/822	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
02	12"x12" Dark Brown w/ Speckle Floor Tile Mastic	14,790	SF	Bsmt, Halls, 2/4-7 floor lunchrms, ROTC, 201-208/215/216/218/23 0/231/235, TV Studio, Audio, Dark/Control/Supply Rooms, Stairways, 4th floor vestibule, 5/6/7 floor baths, 499/599/699/799/81 6/818/822/ (Rooms 812,813,817,820, 821,826 Abated)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03	Vibration Dampening Cloth	341	LF	Valve and Mechanical Rooms and Mechanical Rooms in Main and Athletic Bldgs.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
04	Ventilation Duct Caulk	1,000	LF	Mechanical Rooms, Penthouse	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05	Water Tank Insulation	260	SF	Athletic Building, Gym-Mechanical Room Tank #2	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
06	12"x12" Brown w/ Specks Floor Tile	800	SF	2nd & 4th Floor Escalator Lobbies, 316 (Nurse), 218 & Hall, 2nd Fl West Waiting Room, Main Office Lobby	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
06A	12"x12" Brown w/ Specks Floor Tile Mastic	800	SF	2nd & 4th Floor Escalator Lobbies, 316 (Nurse), 218 &	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Clemente Academy **Unit** 51091 **Building ID** 1840
Address 1147 N. Western Ave **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Hall, 2nd Fl West Waiting Room, Main Office Lobby										
07	12"x12" Black w/speckle VFT	900	SF	Basement South Corridor and 7th floor MDF Room (706)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
08	Insulation in Fire Doors	48	SF	Storage Room outside assembly hall	CHR	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
11	Spray-on Insulation	50,000	SF	Throughout	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
14	MJP E/F/V on Fiberglass Pipe Insulation	500	FITTING	Mechanical room, Penthouse	ASSUMED	TSI	Y	DIST	60		No	Damaged or significantly damaged friable thermal system insulating ACBM	3	LOW
15	12"x12" Black Floor Tile Mastic	900	SF	Basement South Corridor and 7th floor MDF Room (706)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	12"x12" Orange VFT	800	SF	5th Floor Foyer	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
18	12"x12" Orange VFT Mastic	800	SF	5th Floor Foyer	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	12"x12" Beige w/Specs VFT	160,000	SF	Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	12"x12" Beige w/Specs VFT Mastic	160,000	SF	Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Drywall	10,000	SF	Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
22	1'x1' White Ceiling Tile	64,000	SF	Throughout	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
23	1'x1' White Ceiling Tile Mastic	64,000	SF	Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	2'x4' White Ceiling Tile	200,000	SF	Throughout	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
25	Carpet	10,000	SF	Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
26	Yellow Mastic	10,000	SF	Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	Carpet on Yellow Mastic	10,000	SF	Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	12"x12" Brown Speckled VFT	800	SF	Room 802	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Clemente Academy **Unit** 51091 **Building ID** 1840
Address 1147 N. Western Ave **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
29	12"x12" Brown Speckled VFT Mastic	800	SF	Room 802	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	2' x 4' Tectum Ceiling Tile			Room 810	NO_ACBM	MISC					No			
31	Beige Speckled Linoleum - Abated			Room 810	ABATED	MISC								
31A	Beige Speckled Linoleum Mastic - Abated			Room 810	ABATED	MISC								
32	Terrazzo	7,000	SF	Main Lobby, Auditorium Upper Level, Athletic Building, Stairwells, Gym Lobby	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
33	Lab Countertops	500	SF	Rooms 822, 816, 813, 817	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
34	12"x12" Beige w/black speckles VFT	18,000	SF	200R, 200D, 200F, 200B, 3rd floor Foyer, Office Mail Room, Corridor to Principal's Office, Stairwell (east and west), 2nd floor Corridor North Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
35	12"x12" Beige w/black speckles VFT Mastic	18,000	SF	200R, 200D, 200F, 200B, 3rd floor Foyer, Office Mail Room, Corridor to Principal's Office, Stairwell (east and west), 2nd floor Corridor North Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	12"x12" Blue w/blue speckles VFT	160	SF	Room 219, Clinic	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
37	12"x12" Blue w/blue speckles Mastic	50	SF	Room 219, Clinic	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	12"x12" Yellow speckle VFT	50	SF	Room 219, Clinic	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
39	12"x12" Yellow speckle VFT Mastic	50	SF	Room 219, Clinic	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	12"x12" White w/gray speckle VFT	600	SF	Room 219, Clinic	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
41	12"x12" White w/gray speckle VFT Mastic	600	SF	Room 219, Clinic	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	12"x12" Purple speckle VFT	200	SF	Clinic, Basement and Center Stairwell	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Clemente Academy **Unit** 51091 **Building ID** 1840
Address 1147 N. Western Ave **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
43	12"x12" Purple speckle VFT Mastic	200	SF	Clinic, Basement and Center Stairwell	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	2'x4' Pin-Hole Ceiling Tile	1,800	SF	Clinic, Room 219	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
45	2'x2' White ceiling tile	2,600	SF	Auditorium	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
46	2'x4' White smooth ceiling tile	3,500	SF	Weight Room, Library	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
47	Transite Fume Hood	16	SF	Rooms 813	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	Tank Insulation	450	SF	Penthouse	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
49	Red Fire Stop Sealant	3	SF	Penthouse	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	Dark Brown Linoleum	500	SF	Rooms 820, 820F, 817, 812, 812A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
50A	Dark Brown Linoelum Mastic	500	SF	Rooms 820, 820F, 817, 812, 812A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	18"x18" Black Anti-slip Floor Tile	100	SF	8th FL Stairwell Landing	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
51A	18"x18" Black Anti-slip Floor Tile Mastic	100	SF	8th FL Stairwell Landing	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	12"x12" Off-White w/Beige + White Streaks Floor Tile	600	SF	816A, 818B, 821A, and 822B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
52A	12"x12" Off-White w/Beige + White Streaks Floor Tile Mastic	600	SF	816A, 818B, 821A, and 822B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	2' x 4' White Pinhole Ceiling Tile	50,000	SF	8th floor, 7th floor, 6th floor corridors, 810, 826, 820, 812, 702, 701, 799, 703, 324, 301B, 301, 324A, 320, 319, 318, 316	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
54	1' x 1' White Pinhole Ceiling tile	10,000	SF	8th, 7th, 6th, floor corridors. As well as Rooms 702, 701, 799, 703	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
55	1' x 4' White Pinhole Ceiling Tile	8,000	SF	8th floor, 7th floor, and 6th floor corridor	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
56	Linoleum White	1,200	SF	Rooms 810 & 810A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
56A	Linoleum Gray	1,200	SF	Rooms 810 & 810A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Clemente Academy **Unit** 51091 **Building ID** 1840
Address 1147 N. Western Ave **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
57	Table and countertops black	300	SF	Rooms 810, 810A, 826	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
58	Fume Hood	18	SF	Room 810	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
59	16" x 16" Gray w/ specks VFT	1,200	SF	Rooms 816 & 826	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
59A	16" x 16" Gray w/ specks VFT Mastic	1,200	SF	Rooms 816 & 826	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60	16" x 16" Blue w/ specks VFT	1,200	SF	Rooms 816 & 826	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
60A	16" x 16" Blue w/ specks VFT Mastic	1,200	SF	Rooms 816 & 826	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	16" x 16" Yellow w/ specks VFT	1,200	SF	Rooms 816 & 826	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
61A	16" x 16" Yellow w/ specks VFT Mastic	1,200	SF	Rooms 816 & 826	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Ductwrap	950	SF	Main Building Penthouse	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
B	Duct Insulation	25	SF	Main Building Penthouse	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
C	Hard Coat Plaster	25,000	SF	Throughout	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
D	Drywall Tape	500	LF	Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
E	Drywall Joint Compound	500	SF	Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Clemente Academy Unit 51091 Building ID 1840
Address 1147 N. Western Ave Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

Reinspection Date <u>5/9/2025</u>
Inspector Name <u>Allizon Brooks</u>
<u>100-18790</u> <u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01	Abated in Rooms 812, 813, 817, 820, 821, and 826
02	abated in Rooms 812, 813, 817, 820, 821, and 826
03	
04	
05	
06	
06A	
07	
08	
11	
14	
15	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	

Chicago Public Schools

School Clemente Academy Unit 51091 Building ID 1840
Address 1147 N. Western Ave Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
29	
30	
31	
31A	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
50A	
51	
51A	
52	
52A	
53	

Chicago Public Schools

School Clemente Academy Unit 51091 Building ID 1840
Address 1147 N. Western Ave Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
54	
55	
56	
56A	
57	
58	
59	
59A	
60	
60A	
61	
61A	
A	
B	
C	
D	
E	

Table II
Management Planner's Review

Chicago Public Schools

School Clemente Academy

Unit 51091

Building ID 1840

Address 1147 N. Western Ave

Chicago, IL, 60622

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	12"X12" Dark Brown w/Specckles Floor Tile	14,790	SF	Bsmt, Halls, 2/4-7 floor lunchrms, ROTC, 201-208/215/216/218/230/231/235, TV Studio, Audio, Dark/Control/Supply Rooms, Stairways, 4th floor vestibule, 5/6/7 floor baths, 499/599/699/799/816/818/822	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02	12"x12" Dark Brown w/Specle Floor Tile Mastic	14,790	SF	Bsmt, Halls, 2/4-7 floor lunchrms, ROTC, 201-208/215/216/218/230/231/235, TV Studio, Audio, Dark/Control/Supply Rooms, Stairways, 4th floor vestibule, 5/6/7 floor baths, 499/599/699/799/816/818/822/ (Rooms 812,813,817,820, 821, 826 Abated)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03	Vibration Dampening Cloth	341	LF	Valve and Mechanical Rooms and Mechanical Rooms in Main and Athletic Bldgs.	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
04	Ventilation Duct Caulk	1,000	LF	Mechanical Rooms, Penthouse	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
05	Water Tank Insulation	260	SF	Athletic Building, Gym-Mechanical Room Tank #2	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	12"x12" Brown w/Speccks Floor Tile	800	SF	2nd & 4th Floor Escalator Lobbies, 316 (Nurse), 218 & Hall, 2nd Fl West Waiting Room, Main Office Lobby	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06A	12"x12" Brown w/ Specks Floor Tile Mastic	800	SF	2nd & 4th Floor Escalator Lobbies, 316 (Nurse), 218 & Hall, 2nd Fl West Waiting Room, Main Office Lobby	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	12"x12" Black w/speckle VFT	900	SF	Basement South Corridor and 7th floor MDF Room (706)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	Insulation in Fire Doors	48	SF	Storage Room outside assembly hall	Chrysotile	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	Spray-on Insulation	50,000	SF	Throughout	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	MJP E/F/V on Fiberglass Pipe Insulation	500	FITTING	Mechanical room, Penthouse	Assumed	TSI	Yes	60	FITTING	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
15	12"x12" Black Floor Tile Mastic	900	SF	Basement South Corridor and 7th floor MDF Room (706)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12"x12" Orange VFT	800	SF	5th Floor Foyer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Clemente Academy

Unit 51091

Building ID 1840

Address 1147 N. Western Ave

Chicago, IL, 60622

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
18	12"x12" Orange VFT Mastic	800	SF	5th Floor Foyer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12"x12" Beige w/Specs VFT	160,000	SF	Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	12"x12" Beige w/Specs VFT Mastic	160,000	SF	Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Drywall	10,000	SF	Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	1'x1' White Ceiling Tile	64,000	SF	Throughout	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	1'x1' White Ceiling Tile Mastic	64,000	SF	Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	2'x4' White Ceiling Tile	200,000	SF	Throughout	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Carpet	10,000	SF	Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Yellow Mastic	10,000	SF	Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Carpet on Yellow Mastic	10,000	SF	Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12"x12" Brown Speckled VFT	800	SF	Room 802	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12"x12" Brown Speckled VFT Mastic	800	SF	Room 802	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	2' x 4' Tectum Ceiling Tile			Room 810	No ACBM	MISC					
31	Beige Speckled Linoleum - Abated			Room 810	Abated	MISC					
31A	Beige Speckled Linoleum Mastic - Abated			Room 810	Abated	MISC					
32	Terrazzo	7,000	SF	Main Lobby, Auditorium Upper Level, Athletic Building, Stairwells, Gym Lobby	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Lab Countertops	500	SF	Rooms 822, 816, 813, 817	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	12"x12" Beige w/black speckles VFT	18,000	SF	200R, 200D, 200F, 200B, 3rd floor Foyer, Office Mail Room, Corridor to Principal's Office, Stairwell (east and west), 2nd floor Corridor North Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	12"x12" Beige w/black speckles VFT Mastic	18,000	SF	200R, 200D, 200F, 200B, 3rd floor Foyer, Office Mail Room, Corridor to Principal's Office, Stairwell (east and west), 2nd floor Corridor North Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12"x12" Blue w/blue speckles VFT	160	SF	Room 219, Clinic	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12"x12" Blue w/blue speckles Mastic	50	SF	Room 219, Clinic	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	12"x12" Yellow speckle VFT	50	SF	Room 219, Clinic	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	12"x12" Yellow speckle VFT Mastic	50	SF	Room 219, Clinic	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	12"x12" White w/gray speckle VFT	600	SF	Room 219, Clinic	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	12"x12" White w/gray speckle VFT Mastic	600	SF	Room 219, Clinic	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	12"x12" Purple speckle VFT	200	SF	Clinic, Basement and Center Stairwell	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	12"x12" Purple speckle VFT Mastic	200	SF	Clinic, Basement and Center Stairwell	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	2'x4' Pin-Hole Ceiling Tile	1,800	SF	Clinic, Room 219	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Clemente Academy

Unit 51091

Building ID 1840

Address 1147 N. Western Ave

Chicago, IL, 60622

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
45	2'x2' White ceiling tile	2,600	SF	Auditorium	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	2'x4' White smooth ceiling tile	3,500	SF	Weight Room, Library	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	Transite Fume Hood	16	SF	Rooms 813	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	Tank Insulation	450	SF	Penthouse	Assumed	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	Red Fire Stop Sealant	3	SF	Penthouse	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	Dark Brown Linoleum	500	SF	Rooms 820, 820F, 817, 812, 812A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50A	Dark Brown Linoelum Mastic	500	SF	Rooms 820, 820F, 817, 812, 812A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	18"x18" Black Anti-slip Floor Tile	100	SF	8th FL Stairwell Landing	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51A	18"x18" Black Anti-slip Floor Tile Mastic	100	SF	8th FL Stairwell Landing	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	12"x12" Off-White w/Beige + White Streaks Floor Tile	600	SF	816A, 818B, 821A, and 822B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52A	12"x12" Off-White w/Beige + White Streaks Floor Tile Mastic	600	SF	816A, 818B, 821A, and 822B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	2' x 4' White Pinhole Ceiling Tile	50,000	SF	8th floor, 7th floor, 6th floor corridors, 810, 826, 820, 812, 702, 701, 799, 703, 324, 301B, 301, 324A, 320, 319, 318, 316	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	1' x 1' White Pinhole Ceiling tile	10,000	SF	8th, 7th, 6th, floor corridors. As well as Rooms 702, 701, 799, 703	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	1' x 4' White Pinhole Ceiling Tile	8,000	SF	8th floor, 7th floor, and 6th floor corridor	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	Linoleum White	1,200	SF	Rooms 810 & 810A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56A	Linoleum Gray	1,200	SF	Rooms 810 & 810A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	Table and countertops black	300	SF	Rooms 810, 810A, 826	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	Fume Hood	18	SF	Room 810	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	16" x 16" Gray w/ specks VFT	1,200	SF	Rooms 816 & 826	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59A	16" x 16" Gray w/ specks VFT Mastic	1,200	SF	Rooms 816 & 826	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	16" x 16" Blue w/ specks VFT	1,200	SF	Rooms 816 & 826	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60A	16" x 16" Blue w/ specks VFT Mastic	1,200	SF	Rooms 816 & 826	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	16" x 16" Yellow w/ specks VFT	1,200	SF	Rooms 816 & 826	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61A	16" x 16" Yellow w/ specks VFT Mastic	1,200	SF	Rooms 816 & 826	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Ductwrap	950	SF	Main Building Penthouse	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
B	Duct Insulation	25	SF	Main Building Penthouse	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	Hard Coat Plaster	25,000	SF	Throughout	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
D	Drywall Tape	500	LF	Throughout	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
E	Drywall Joint Compound	500	SF	Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Clemente Academy

Unit 51091

Building ID 1840

Address 1147 N. Western Ave

Chicago, IL, 60622

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

Review Date	6/9/2025
Manager Planner Name	Arturo Saenz
100-04019	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
03	
04	
05	
06	
06A	

Chicago Public Schools

School Clemente Academy

Unit 51091

Building ID 1840

Address 1147 N. Western Ave

Chicago, IL, 60622

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
07	
08	
11	
14	Repair Damaged ACM and maintain in Good condition
15	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
31A	
32	
33	
34	
35	
36	
37	

Chicago Public Schools

School Clemente Academy

Unit 51091

Building ID 1840

Address 1147 N. Western Ave

Chicago, IL, 60622

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
50A	
51	
51A	
52	
52A	
53	
54	
55	
56	
56A	
57	
58	
59	
59A	

Chicago Public Schools

School Clemente Academy

Unit 51091

Building ID 1840

Address 1147 N. Western Ave

Chicago, IL, 60622

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
60	
60A	
61	
61A	
A	
B	
C	
D	
E	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Specialty Consulting, Inc.

2025 AHERA REINSPECTION

Chicago Public Schools

Specialty Consulting, Inc.

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	01		
MATERIAL DESCRIPTION:	12"X12" Dark Brown w/Specckles Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Bsmt, Halls, 2/4-7 floor luchrms, ROTC, 201-208/215/216/218/230/231/235, TV Studio, Audio, Dark/Control/Supply Rooms, Stairways, 4th floor vestibule, 5/6/7 floor baths, 499/599/699/799/816/818/822		
MATERIAL QUANTITY:	14790	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Abated in Rooms 812, 813, 817, 820, 821, and 826		

Inspector's Signature:

Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **12"X12" Dark Brown w/ Speckles Floor Tile**

MATERIAL LOCATION: **Bsmt, Halls, 2/4-7 floor lunchrms, ROTC, 201-208/215/216/218/230/231/235, TV Studio, Audio, Dark/Control/Supply Rooms, Stairways, 4th floor vestibule, 5/6/7 floor baths, 499/599/699/799/816/818/822**

MATERIAL QUANTITY: **14790** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	02		
MATERIAL DESCRIPTION:	12"x12" Dark Brown w/ Speckle Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Bsmt, Halls, 2/4-7 floor lunchrms, ROTC, 201-208/215/216/218/230/231/235, TV Studio, Audio, Dark/Control/Supply Rooms, Stairways, 4th floor vestibule, 5/6/7 floor baths, 499/599/699/799/816/818/822/ (Rooms 812,813,817,820, 821, 826 Abated)**

MATERIAL QUANTITY: **14790** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **abated in Rooms 812, 813, 817, 820, 821, and 826**

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **02**

MATERIAL DESCRIPTION: **12"x12" Dark Brown w/Specle Floor Tile Mastic**

MATERIAL LOCATION: **Bsmt, Halls, 2/4-7 floor lunchrms, ROTC, 201-208/215/216/218/230/231/235, TV Studio, Audio, Dark/Control/Supply Rooms, Stairways, 4th floor vestibule, 5/6/7 floor baths, 499/599/699/799/816/818/822/ (Rooms 812,813,817,820, 821, 826 Abated)**

MATERIAL QUANTITY: **14790** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03		
MATERIAL DESCRIPTION:	Vibration Dampening Cloth		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Valve and Mechanical Rooms and Mechanical Rooms in Main and Athletic Bldgs.		
MATERIAL QUANTITY:	341	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: **05/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **Vibration Dampening Cloth**

MATERIAL LOCATION: **Valve and Mechanical Rooms and Mechanical Rooms in Main and Athletic Bldgs.**

MATERIAL QUANTITY: **341** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	04		
MATERIAL DESCRIPTION:	Ventilation Duct Caulk		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Mechanical Rooms, Penthouse		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **Ventilation Duct Caulk**

MATERIAL LOCATION: **Mechanical Rooms, Penthouse**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05		
MATERIAL DESCRIPTION:	Water Tank Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Athletic Building, Gym-Mechanical Room Tank #2		
MATERIAL QUANTITY:	260	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **Water Tank Insulation**

MATERIAL LOCATION: **Athletic Building, Gym-Mechanical Room Tank #2**

MATERIAL QUANTITY: **260** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06		
MATERIAL DESCRIPTION:	12"x12" Brown w/Speccks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	2nd & 4th Floor Escalator Lobbies, 316 (Nurse), 218 & Hall, 2nd Fl West Waiting Room, Main Office Lobby		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **12"x12" Brown w/Speccks Floor Tile**

MATERIAL LOCATION: **2nd & 4th Floor Escalator Lobbies, 316 (Nurse), 218 & Hall, 2nd Fl West Waiting Room, Main Office Lobby**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06A		
MATERIAL DESCRIPTION:	12"x12" Brown w/ Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd & 4th Floor Escalator Lobbies, 316 (Nurse), 218 & Hall, 2nd Fl West Waiting Room, Main Office Lobby		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA:	06A				
MATERIAL DESCRIPTION:	12"x12" Brown w/ Specks Floor Tile Mastic				
MATERIAL LOCATION:	2nd & 4th Floor Escalator Lobbies, 316 (Nurse), 218 & Hall, 2nd Fl West Waiting Room, Main Office Lobby				
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07		
MATERIAL DESCRIPTION:	12"x12" Black w/speckle VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Basement South Corridor and 7th floor MDF Room (706)		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **07**

MATERIAL DESCRIPTION: **12"x12" Black w/speckle VFT**

MATERIAL LOCATION: **Basement South Corridor and 7th floor MDF Room (706)**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08		
MATERIAL DESCRIPTION:	Insulation in Fire Doors		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Storage Room outside assembly hall		
MATERIAL QUANTITY:	48	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **Insulation in Fire Doors**

MATERIAL LOCATION: **Storage Room outside assembly hall**

MATERIAL QUANTITY: **48** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	Spray-on Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	50000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Spray-on Insulation**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	MJP E/F/V on Fiberglass Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	1 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:	Deterioration Water Vibration		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Mechanical room, Penthouse		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:		DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Mechanical room, Penthouse**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **60** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Repair Damaged ACM and maintain in Good condition

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	12"x12" Black Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement South Corridor and 7th floor MDF Room (706)		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **12"x12" Black Floor Tile Mastic**

MATERIAL LOCATION: **Basement South Corridor and 7th floor MDF Room (706)**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	12"x12" Orange VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	5th Floor Foyer		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: **05/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **12"x12" Orange VFT**

MATERIAL LOCATION: **5th Floor Foyer**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18		
MATERIAL DESCRIPTION:	12"x12" Orange VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	5th Floor Foyer		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12"x12" Orange VFT Mastic**

MATERIAL LOCATION: **5th Floor Foyer**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	12"x12" Beige w/Speccks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	160000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **12"x12" Beige w/Specs VFT**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **160000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	12"x12" Beige w/Speccks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	160000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **12"x12" Beige w/Specs VFT Mastic**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **160000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	Drywall		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	1'x1' White Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	64000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **64000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	1'x1' White Ceiling Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	64000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile Mastic**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **64000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	2'x4' White Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	200000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **2'x4' White Ceiling Tile**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **200000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	Carpet		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Carpet**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	Yellow Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Yellow Mastic**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	Carpet on Yellow Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Carpet on Yellow Mastic**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	12"x12" Brown Speckled VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 802		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **12"x12" Brown Speckled VFT**

MATERIAL LOCATION: **Room 802**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	12"x12" Brown Speckled VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 802		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **12"x12" Brown Speckled VFT Mastic**

MATERIAL LOCATION: **Room 802**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 30
MATERIAL DESCRIPTION: 2' x 4' Tectum Ceiling Tile
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 810

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **2' x 4' Tectum Ceiling Tile**

MATERIAL LOCATION: **Room 810**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 31

MATERIAL DESCRIPTION: Beige Speckled Linoleum - Abated

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 810

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Beige Speckled Linoleum - Abated**

MATERIAL LOCATION: **Room 810**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 31A

MATERIAL DESCRIPTION: Beige Speckled Linoleum Mastic - Abated

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 810

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **31A**

MATERIAL DESCRIPTION: **Beige Speckled Linoleum Mastic - Abated**

MATERIAL LOCATION: **Room 810**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32		
MATERIAL DESCRIPTION:	Terrazo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Main Lobby, Auditorium Upper Level, Athletic Building, Stairwells, Gym Lobby		
MATERIAL QUANTITY:	7000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Terrazo**

MATERIAL LOCATION: **Main Lobby, Auditorium Upper Level, Athletic Building, Stairwells, Gym Lobby**

MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	Lab Countertops		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Rooms 822, 816, 813, 817		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Lab Countertops**

MATERIAL LOCATION: **Rooms 822, 816, 813, 817**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	12"x12" Beige w/black speckles VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	200R, 200D, 200F, 200B, 3rd floor Foyer, Office Mail Room, Corridor to Principal's Office, Stairwell (east and west), 2nd floor Corridor North Building		
MATERIAL QUANTITY:	18000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **12"x12" Beige w/black speckles VFT**

MATERIAL LOCATION: **200R, 200D, 200F, 200B, 3rd floor Foyer, Office Mail Room, Corridor to Principal's Office, Stairwell (east and west), 2nd floor Corridor North Building**

MATERIAL QUANTITY: **18000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	12"x12" Beige w/black speckles VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	200R, 200D, 200F, 200B, 3rd floor Foyer, Office Mail Room, Corridor to Principal's Office, Stairwell (east and west), 2nd floor Corridor North Building		
MATERIAL QUANTITY:	18000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **12"x12" Beige w/black speckles VFT Mastic**

MATERIAL LOCATION: **200R, 200D, 200F, 200B, 3rd floor Foyer, Office Mail Room, Corridor to Principal's Office, Stairwell (east and west), 2nd floor Corridor North Building**

MATERIAL QUANTITY: **18000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	12"x12" Blue w/blue speckles VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 219, Clinic		
MATERIAL QUANTITY:	160	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **12"x12" Blue w/blue speckles VFT**

MATERIAL LOCATION: **Room 219, Clinic**

MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	12"x12" Blue w/blue speckles Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 219, Clinic		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **12"x12" Blue w/blue speckles Mastic**

MATERIAL LOCATION: **Room 219, Clinic**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	12"x12" Yellow speckle VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 219, Clinic		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **12"x12" Yellow speckle VFT**

MATERIAL LOCATION: **Room 219, Clinic**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39		
MATERIAL DESCRIPTION:	12"x12" Yellow speckle VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 219, Clinic		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **12"x12" Yellow speckle VFT Mastic**

MATERIAL LOCATION: **Room 219, Clinic**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	12"x12" White w/gray speckle VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 219, Clinic		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **12"x12" White w/gray speckle VFT**

MATERIAL LOCATION: **Room 219, Clinic**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41		
MATERIAL DESCRIPTION:	12"x12" White w/gray speckle VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 219, Clinic		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **12"x12" White w/gray speckle VFT Mastic**

MATERIAL LOCATION: **Room 219, Clinic**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42		
MATERIAL DESCRIPTION:	12"x12" Purple speckle VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Clinic, Basement and Center Stairwell		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: **05/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **12"x12" Purple speckle VFT**

MATERIAL LOCATION: **Clinic, Basement and Center Stairwell**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	12"x12" Purple speckle VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Clinic, Basement and Center Stairwell		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **12"x12" Purple speckle VFT Mastic**

MATERIAL LOCATION: **Clinic, Basement and Center Stairwell**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	2'x4' Pin-Hole Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Clinic, Room 219		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **2'x4' Pin-Hole Ceiling Tile**

MATERIAL LOCATION: **Clinic, Room 219**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	2'x2' White ceiling tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	2600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **2'x2' White ceiling tile**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	2'x4' White smooth ceiling tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Weight Room, Library		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **2'x4' White smooth ceiling tile**

MATERIAL LOCATION: **Weight Room, Library**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47		
MATERIAL DESCRIPTION:	Transite Fume Hood		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 813		
MATERIAL QUANTITY:	16	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Transite Fume Hood**

MATERIAL LOCATION: **Rooms 813**

MATERIAL QUANTITY: **16** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	Tank Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Penthouse		
MATERIAL QUANTITY:	450	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Tank Insulation**

MATERIAL LOCATION: **Penthouse**

MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	Red Fire Stop Sealant		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Penthouse		
MATERIAL QUANTITY:	3	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Red Fire Stop Sealant**

MATERIAL LOCATION: **Penthouse**

MATERIAL QUANTITY: **3** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	Dark Brown Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Rooms 820, 820F, 817, 812, 812A		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: **05/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Dark Brown Linoleum**

MATERIAL LOCATION: **Rooms 820, 820F, 817, 812, 812A**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50A		
MATERIAL DESCRIPTION:	Dark Brown Linoelum Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 820, 820F, 817, 812, 812A		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **50A**

MATERIAL DESCRIPTION: **Dark Brown Linoleum Mastic**

MATERIAL LOCATION: **Rooms 820, 820F, 817, 812, 812A**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	18"x18" Black Anti-slip Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	8th FL Stairwell Landing		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: **05/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **18"x18" Black Anti-slip Floor Tile**

MATERIAL LOCATION: **8th FL Stairwell Landing**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51A		
MATERIAL DESCRIPTION:	18"x18" Black Anti-slip Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	8th FL Stairwell Landing		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **51A**

MATERIAL DESCRIPTION: **18"x18" Black Anti-slip Floor Tile Mastic**

MATERIAL LOCATION: **8th FL Stairwell Landing**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	12"x12" Off-White w/Beige + White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	816A, 818B, 821A, and 822B		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **12"x12" Off-White w/Beige + White Streaks Floor Tile**

MATERIAL LOCATION: **816A, 818B, 821A, and 822B**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52A		
MATERIAL DESCRIPTION:	12"x12" Off-White w/Beige + White Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	816A, 818B, 821A, and 822B		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **52A**

MATERIAL DESCRIPTION: **12"x12" Off-White w/Beige + White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **816A, 818B, 821A, and 822B**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	2' x 4' White Pinhole Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	8th floor, 7th floor, 6th floor corridors, 810, 826, 820, 812, 702, 701, 799, 703, 324, 301B, 301, 324A, 320, 319, 318, 316		
MATERIAL QUANTITY:	50000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **2' x 4' White Pinhole Ceiling Tile**

MATERIAL LOCATION: **8th floor, 7th floor, 6th floor corridors, 810, 826, 820, 812, 702, 701, 799, 703, 324, 301B, 301, 324A, 320, 319, 318, 316**

MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	1' x 1' White Pinhole Ceiling tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	8th, 7th, 6th, floor corridors. As well as Rooms 702, 701, 799, 703		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **1' x 1' White Pinhole Ceiling tile**

MATERIAL LOCATION: **8th, 7th, 6th, floor corridors. As well as Rooms 702, 701, 799, 703**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55		
MATERIAL DESCRIPTION:	1' x 4' White Pinhole Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	8th floor, 7th floor, and 6th floor corridor		
MATERIAL QUANTITY:	8000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **1' x 4' White Pinhole Ceiling Tile**

MATERIAL LOCATION: **8th floor, 7th floor, and 6th floor corridor**

MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	56		
MATERIAL DESCRIPTION:	Linoleum White		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Rooms 810 & 810A		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **Linoleum White**

MATERIAL LOCATION: **Rooms 810 & 810A**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	56A		
MATERIAL DESCRIPTION:	Linoleum Gray		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 810 & 810A		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **56A**

MATERIAL DESCRIPTION: **Linoleum Gray**

MATERIAL LOCATION: **Rooms 810 & 810A**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	57		
MATERIAL DESCRIPTION:	Table and countertops black		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Rooms 810, 810A, 826		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **Table and countertops black**

MATERIAL LOCATION: **Rooms 810, 810A, 826**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	Fume Hood		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 810		
MATERIAL QUANTITY:	18	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **Fume Hood**

MATERIAL LOCATION: **Room 810**

MATERIAL QUANTITY: **18** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	59		
MATERIAL DESCRIPTION:	16" x 16" Gray w/ specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Rooms 816 & 826		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: **05/09/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **16" x 16" Gray w/ specks VFT**

MATERIAL LOCATION: **Rooms 816 & 826**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	59A		
MATERIAL DESCRIPTION:	16" x 16" Gray w/ specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 816 & 826		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **59A**

MATERIAL DESCRIPTION: **16" x 16" Gray w/ specks VFT Mastic**

MATERIAL LOCATION: **Rooms 816 & 826**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	60		
MATERIAL DESCRIPTION:	16" x 16" Blue w/ specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Rooms 816 & 826		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: **05/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **16" x 16" Blue w/ specks VFT**

MATERIAL LOCATION: **Rooms 816 & 826**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	60A		
MATERIAL DESCRIPTION:	16" x 16" Blue w/ specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 816 & 826		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **60A**

MATERIAL DESCRIPTION: **16" x 16" Blue w/ specks VFT Mastic**

MATERIAL LOCATION: **Rooms 816 & 826**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	61		
MATERIAL DESCRIPTION:	16" x 16" Yellow w/ specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Rooms 816 & 826		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: **05/09/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **16" x 16" Yellow w/ specks VFT**

MATERIAL LOCATION: **Rooms 816 & 826**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	61A		
MATERIAL DESCRIPTION:	16" x 16" Yellow w/ specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 816 & 826		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **61A**

MATERIAL DESCRIPTION: **16" x 16" Yellow w/ specks VFT Mastic**

MATERIAL LOCATION: **Rooms 816 & 826**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A		
MATERIAL DESCRIPTION:	Ductwrap		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building Penthouse		
MATERIAL QUANTITY:	950	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Ductwrap**

MATERIAL LOCATION: **Main Building Penthouse**

MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	B		
MATERIAL DESCRIPTION:	Duct Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building Penthouse		
MATERIAL QUANTITY:	25	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Duct Insulation**

MATERIAL LOCATION: **Main Building Penthouse**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	Hard Coat Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	25000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Hard Coat Plaster**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	Drywall Tape		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Drywall Tape**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUIDLING ID:	1840
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Allizon Brooks		
SCHOOL NAME:	Clemente Academy	INSPECTION DATE:	5/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	Drywall Joint Compound		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/09/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	51091	BUILDING ID:	1840
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Clemente Academy	REVIEW DATE:	6/9/2025		
ADDRESS:	1147 N. Western Ave	IDPH LICENSE NO:	100-18790		

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Drywall Joint Compound**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Specialty Consulting, Inc.

2025 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Illinois



ASBESTOS
PROFESSIONAL
LICENSE

ID NUMBER
100 - 18790

ISSUED
4/5/2024

EXPIRES
05/15/2025

ALLIZON L BROOKS
2942 W VAN BUREN ST
CHICAGO, IL 60612

Environmental Health



ALLIZON L BROOKS
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/5/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 18790

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License


Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 18790	ISSUED 4/5/2024	EXPIRES 05/15/2025	INSPECTOR	1/27/2025
ALLIZON L BROOKS 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			PROJECT MANAGER AIR SAMPLING PROFESSIONAL	6/12/2024
			Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



ENDORSEMENTS	TC EXPIRES
INSPECTOR	1/4/2026
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	6/1/2025
Alteration of this license shall result in legal action	
This license issued under authority of the State of Illinois	
Department of Public Health	
This license is valid only when accompanied by a valid	
training course certificate.	

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ALLIZON L. BROOKS
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 01/04/2025 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

01/04/2025

Course Dates:

01/04/2026

Expires:

2501BIR02

Certificate Number:

N. Penef

Phone: 312-491-0081

Director of Training

Nicholas J. Penef

Doctor of Public Health

FORM # A-010B



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that
Arturo Saenz

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012562

Kathy DeSalvo
Kathy DeSalvo, Director



Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that
Arturo Saenz

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012583

Kathy DeSalvo
Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

ARTURO SAENZ
2942 W VAN BUREN ST
CHICAGO, IL 60612

7/8/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 04019	ISSUED 7/8/2024	EXPIRES 05/15/2025	INSPECTOR	5/6/2025
ARTURO SAENZ 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			MANAGEMENT PLANNER	5/6/2025
			AIR SAMPLING PROFESSIONAL Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



OCCUPATIONAL TRAINING & SUPPLY, INC.
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2024

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Arturo Saenz

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 5/6/2024

Exam Date: 5/6/2024

Expiration Date: 5/6/2025

Certificate Number: MPR2405061823


Course Credit Hours: MPR 8 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

Kristina Miczek, Training Manager



525-535 West Jefferson Street • Springfield, Illinois



ARTURO SAENZ
2942 W VAN BUREN ST
CHICAGO, IL 60612


2/28/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	11/1/2022
MANAGEMENT PLANNER	11/1/2022
AIR SAMPLING PROFESSIONAL	
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



525-535 West Jefferson Street • Springfield, Ill

ARTURO SAENZ
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/30/2026



ASBESTOS
PROFESSIONAL
LICENSE

ID NUMBER
100 - 04019

ISSUED
4/30/2025

EXPIRES
05/15/2026

ARTURO SAENZ
2942 W VAN BUREN ST
CHICAGO, IL 60612

Environmental Health




ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	5/6/2025
MANAGEMENT PLANNER	4/2/2026
AIR SAMPLING PROFESSIONAL	
<p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB

**Reliable
Environmental
Solutions, Inc. R E S**

This is to certify that **Arturo Saenz**

*has on 4/2/25, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Refresher Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: April 2, 2025

COURSE LENGTH: 4 HOURS

Examination Date: April 2, 2025

Expiration Date: April 2, 2026

Certificate Number: MPR/0560



Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois 217.787.9800 www.ReliableEnv.com

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed