

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-0616  
SCHOOL NAME: Manley Academy  
ADDRESS OF SCHOOL: 2935 W. Polk  
CITY: Chicago, IL, 60612

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 7/14/2022

If the address on this form is different than the address of the building, submit a written explanation.

**SECTION II** *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 7/10/2025 ENROLLMENT 131  
IDPH INSPECTOR LICENSE NUMBER: 100-09969  
IDPH LICENSED INSPECTOR NAME (Please Print): Dionne Carey Walker  
IDPH MP LICENSE NUMBER: 100-18488  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Mike Serio

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

*Richard J. Schleyer* 8/8/2025

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Manley Academy**

2935 W. Polk  
Chicago, IL, 60612

Unit: 53111  
Building ID: 1460

IDPH ID Number: 14-016-2990-0616

**REPORT DATE:**  
Friday, August 08, 2025

**Prepared for:**  
**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**  
**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

08/08/2025

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299      Unit: 53111      Region: 03      IDPH ID: 14-016-2990-0616

School: Manley Academy      Building ID: 1460

Address: 2935 W. Polk

Chicago, IL, 60612

Building Contact: Daniels, David      Contact Phone: 6302949828

Current Building Owners: Chicago Public Schools

Reinspection Date: 7/10/2025

Review Date: 08/08/2025

Inspector: Dionne Carey Walker

Inspector IDPH License: 100-09969

Management Planner: Mike Serio

Management Planner IDPH License: 100-18488

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates



Mike Serio  
100-18488

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: August 08, 2025

RE: Manley Academy, Unit 53111  
2935 W. Polk  
Chicago, IL, 60612

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Manley Academy , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Manley Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Manley Academy      Unit: 53111      Region: 03  
Address: 2935 W. Polk      Chicago, IL, 60612  
IDPH ID: 14-016-2990-0616      Building ID: 1460  
Contact: Daniels, David      Phone: 6302949828

### 2. Description of Facility

Original Construction: 1928      Additional Construction:  
Total Square Footage: 213820      No of Floors: 3  
Current Occupancy: 131

### 3. LEA Designated Person

Contact: Richard J.Schleyer      Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Doug McCormick  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900      Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Dionne Carey Walker

  
Signature:  
Date: 7/10/2025

Inspector IDPH license # 100-09969  
Reinspection Date: 7/10/2025

### 6. Management Planner

Management Planner Name: Mike Serio

  
Signature:  
Date: 08/08/2025

Management Planner IDPH license # 100-18488

### 7. Review Date: 08/08/2025

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

  
Signature:      Date: 8/8/2025

Name: Richard J.Schleyer

## **II. EXECUTIVE SUMMARY**

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Manley Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

- A. The following HAs have changed assessment categories for Building 1460:

B. The following new homogenous areas have been identified for Building 1460:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

10	Green Linoleum
100	Red Carpet Adhesive
1002	Gray Carpet Glue
1003	12" x 12" Beige, White, and Brown Spotted Floor Tile
1004	12" x 12" Beige, White, and Brown Spotted Floor Tile Mastic
101	12" x 12" Orange Floor Tile
102	12" x 12" Orange Floor Tile Mastic
103	12" x 12" Gray w/ White Streaks Floor Tile
104	12" x 12" Gray w/ White Streaks Floor Tile Mastic
105	12" x 12" Brown/Beige/White Mix Floor Tile
106	12" x 12" Light Gray/White Mix Floor Tile
107	12" x 12" Dark Gray Mix Floor Tile
108	12" x 12" Dark Gray, Light Gray, and Brown Mix Floor Tile Mastic
109	12" x 12" White w/ Gray Specks Floor Tile
10A	Green Linoleum Mastic
110	12" x 12" White w/ Gray Specks Floor Tile Mastic
111	2' x 2' White Ceiling Tiles w/ Pinholes
112	12" x 12" Light Red Floor Tile
113	12" x 12" Black Floor Tile
114	12" x 12" Light Red and Black Floor Tile Mastic
12	12" x 12" Brownish Green Floor Tile
14A	12" x 12" Wood Grain Floor Tile Mastic
16	Exterior Brick Mortar - Non-AHERA
17	Drywall Tape
18	Drywall Mud
25	2' x 4' Ceiling Tile
26	6"x12"Ceiling Tile and Wall Tile
27	1' x 1' Pinhole Ceiling Tile
27A	1' x 1' Pinhole Ceiling Tile Adhesive
28	1' x 1' White Wormy Texture Ceiling Tile
28A	1' x 1' White Wormy Texture Ceiling Tile Adhesive
30	Desks (Science Rooms)
31	Green Stage Curtain
32	Yellow Stage Curtain
33	Canvas Hair Dryer Hose
34	Boiler Breeching
3A	12" x 12" White w/ Beige Specks Floor Tile Mastic
45	Plaster Ceiling
46	Plaster Walls

50	Acoustical Plaster
51	Carpet Mastic
52	12" x 12" Brown Speckled Floor Tile
52A	12" x 12" Brown Speckled Floor Tile Mastic
53	12" x 12" Off-White Floor Tile w/ Black Specks
53A	12" x 12" Off-White Floor Tile w/ Black Specks Mastic
57	White Heat Pads
59	Black Baseboard
59A	Black Baseboard Adhesive
60	12" x 12" Off-White w/ White Specks Floor Tile
62	Roof Fields - Non-AHERA
63	12" x 12" Blue Floor Tile
64	12" x 12" Blue Floor Tile Mastic
65	Insulation Inside Of Vault Door
66	12" x 12" Gray Floor Tile
67	12" x 12" Gray Floor Tile Mastic
68	12" x 12" Green Floor Tile
69	12" x 12" Green Floor Tile Mastic
7	12" x 12" Gray w/ White Streaks Floor Tile
70	Elevator Brake Shoes
71	Purple Carpet Mastic
72	Blue/Purple/Pink Mix Carpet Mastic
73	Blue Carpet Mastic
74	Brown Carpet Mastic
75	Blue Linoleum
76	Blue Linoleum Mastic
77	4" Blue Vinyl Baseboard
78	4" Blue Vinyl Baseboard Mastic
79	4" Dark Gray Vinyl Baseboard
8	12" x 12" Light Gray Floor Tile
80	4" Dark Gray Vinyl Baseboard Mastic
81	Lab Tables and Sinks
82	Blue/White Mix Carpet Mastic
83	12" x 12" Pink Vinyl Floor Tile
84	12" x 12" Pink Vinyl Floor Tile Mastic
85	Purple Carpet Adhesive
86	Light Brown Carpet Adhesive
87	Blue w/ Red and Orange Carpet Adhesive
88	Chalk Board Adhesive
89	Red/Maroon Terrazzo
8A	12" x 12" Light Gray Floor Tile Mastic
9	Brown Linoleum
90	Blue Carpet Adhesive
91	12" x 12" Light Brown w/ White Floor Tile
92	12" x 12" Light Brown Floor Tile w/ White Mastic
93	Light Blue w/ Blue Specks Linoleum
94	Light Blue w/ Blue Specks Linoleum Mastic

95	Tan Linoleum
96	Tan Linoleum Mastic
97	12" x 12" White w/ Green Specks Floor Tile
98	12" x 12" White w/ Green Specks Floor Tile Mastic
99	Burgandy Carpet w/ Blue and Orange Specks Adhesive
9A	Brown Linoleum Mastic
A	Black Linoleum Flooring
A-1	Black Linoleum Flooring-Mastic
HA-1000	2' x 4' White Plaing Ceiling Tile
HA-1001	2' x 4' White Fissures and Pinholes Ceiling Tile

The following areas were deemed to be inaccessible:

100	Red Carpet Adhesive
1002	Gray Carpet Glue
1004	12" x 12" Beige, White, and Brown Spotted Floor Tile Mastic
103	12" x 12" Gray w/ White Streaks Floor Tile
104	12" x 12" Gray w/ White Streaks Floor Tile Mastic
111	2' x 2' White Ceiling Tiles w/ Pinholes
13A	9" x 9" Brown Floor Tile Mastic
14	12" x 12" Wood Grain Floor Tile
14A	12" x 12" Wood Grain Floor Tile Mastic
17	Drywall Tape
18	Drywall Mud
1A	12" x 12" Brown Floor Tile Mastic
20A	12" x 12" Black Floor Tile Mastic
27	1' x 1' Pinhole Ceiling Tile
27A	1' x 1' Pinhole Ceiling Tile Adhesive
2A	12" x 12" Beige w/ Brown & White Spks Floor Tile Mastic
3A	12" x 12" White w/ Beige Specks Floor Tile Mastic
45	Plaster Ceiling
50	Acoustical Plaster
51	Carpet Mastic
52A	12" x 12" Brown Speckled Floor Tile Mastic
59A	Black Baseboard Adhesive
60A	12" x 12" Off-White w/ White Specksfloor Tile Mastic
65	Insulation Inside Of Vault Door
67	12" x 12" Gray Floor Tile Mastic
71	Purple Carpet Mastic
72	Blue/Purple/Pink Mix Carpet Mastic
73	Blue Carpet Mastic
74	Brown Carpet Mastic

76	Blue Linoleum Mastic
7A	12" x 12" Gray w/ White Streaks Floor Tile Mastic
80	4" Dark Gray Vinyl Baseboard Mastic
82	Blue/White Mix Carpet Mastic
84	12" x 12" Pink Vinyl Floor Tile Mastic
85	Purple Carpet Adhesive
86	Light Brown Carpet Adhesive
87	Blue w/ Red and Orange Carpet Adhesive
88	Chalk Board Adhesive
8A	12" x 12" Light Gray Floor Tile Mastic
94	Light Blue w/ Blue Specks Linoleum Mastic
96	Tan Linoleum Mastic
98	12" x 12" White w/ Green Specks Floor Tile Mastic
99	Burgandy Carpet w/ Blue and Orange Specks Adhesive

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Dionne Carey Walker, IDPH License # 100-09969. The Management Plan was updated by Mike Serio, IDPH License # 100-18488. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Manley Academy Building 1460 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

**School** Manley Academy **Unit** 53111 **Building ID** 1460  
**Address** 2935 W. Polk **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	12" x 12" Brown Floor Tile	950	SF	Rooms 104a	CHR	MISC	N	NONE				ACBM with the potential for damage		LOW
10	Green Linoleum			Room 203	ASSUMED	MISC								
100	Red Carpet Adhesive	320	SF	Room 102	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
1002	Gray Carpet Glue	400	SF	Room 124 in Network 5 Wing	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
1003	12" x 12" Beige, White, and Brown Spotted Floor Tile	200	SF	Kitchen in Network 5 Wing, 100 (Principal's Office)	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
1004	12" x 12" Beige, White, and Brown Spotted Floor Tile Mastic	200	SF	Room 122 Kitchen in Network 5 Wing, 100 (Principal's Office)	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
101	12" x 12" Orange Floor Tile			Girls Locker Room, Laundry Room	ASSUMED	MISC								
102	12" x 12" Orange Floor Tile Mastic			Girls Locker Room, Laundry Room	ASSUMED	MISC								
103	12" x 12" Gray w/ White Streaks Floor Tile	980	SF	Room 110	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
104	12" x 12" Gray w/ White Streaks Floor Tile Mastic	980	SF	Room 110	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
105	12" x 12" Brown/Beige/White Mix Floor Tile	200	SF	Rooms 315, 310	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
106	12" x 12" Light Gray/White Mix Floor Tile	200	SF	Rooms 315, 310	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
107	12" x 12" Dark Gray Mix Floor Tile	200	SF	Rooms 315, 310	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
108	12" x 12" Dark Gray, Light Gray, and Brown Mix Floor Tile Mastic	600	SF	Rooms 315, 310	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
109	12" x 12" White w/ Gray Specks Floor Tile	700	SF	Room 211	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
10A	Green Linoleum Mastic			Room 203	ASSUMED	MISC								
11	12" x 12" White w/ Brown Specks Floor Tile			Rooms 225 and 103	CHR	MISC								
110	12" x 12" White w/ Gray Specks Floor Tile Mastic	700	SF	Room 211	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
111	2' x 2' White Ceiling Tiles w/ Pinholes	600	SF	Rooms 315, 310	ASSUMED	MISC	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		LOW
112	12" x 12" Light Red Floor Tile	400	SF	Room 100 (Principal's Office)	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
113	12" x 12" Black Floor Tile	200	SF	Room 100 (Principal's Office)	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Manley Academy **Unit** 53111 **Building ID** 1460  
**Address** 2935 W. Polk **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
114	12" x 12" Light Red and Black Floor Tile Mastic	600	SF	Room 100 (Principal's Office)	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
11A	12" x 12" White w/ Brown Specks Floor Tile Mastic			Rooms 225 and 103	CHR	MISC								
12	12" x 12" Brownish Green Floor Tile			Room 225	ASSUMED	MISC								
12A	12" x 12" Brownish Green Floor Tile Mastic			ABATED	ABATED	MISC								
13	9" x 9" Brown Floor Tile	200	SF	Room 225	CHR	MISC	N	NONE				ACBM with the potential for damage		LOW
13A	9" x 9" Brown Floor Tile Mastic	200	SF	Room 225	CHR	MISC	N	NONE				ACBM with the potential for damage		LOW
14	12" x 12" Wood Grain Floor Tile	75	SF	3rd Floor Band Storage	CHR	MISC	N	NONE				ACBM with the potential for damage		LOW
14A	12" x 12" Wood Grain Floor Tile Mastic	75	SF	3rd Floor Band Storage	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
15	Yellow Linoleum			ABATED	ABATED	MISC								
16	Exterior Brick Mortar - Non-AHERA			Exterior of Building	ASSUMED	MISC								
17	Drywall Tape	300	LF	Rooms 112 & 124	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
18	Drywall Mud	300	LF	Rooms 112 & 124	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
19	12" x 12" Red Floor Tile			Auditorium	CHR	MISC								
19A	12" x 12" Red Floor Tile Mastic			Auditorium	CHR	MISC								
1A	12" x 12" Brown Floor Tile Mastic	950	SF	Rooms 104a	CHR	MISC	N	NONE				ACBM with the potential for damage		LOW
2	12" x 12" Beige w/ Brown & White Specks Floor Tile	1,350	SF	Rooms 115, Girls Gym Office	CHR	MISC	N	NONE				ACBM with the potential for damage		LOW
20	12" x 12" Black Floor Tile	750	SF	Auditorium	CHR	MISC	N	LOC	100	SF		ACBM with potential for significant damage	3	LOW
20A	12" x 12" Black Floor Tile Mastic	750	SF	Auditorium	CHR	MISC	N	NONE				ACBM with the potential for damage		LOW
22	9" x 9" Green Floor Tile			ABATED	ABATED	MISC								
22A	9" x 9" Green Floor Tile Mastic			ABATED	ABATED	MISC								
23	12" x 12" Beige w/ Carmel Streaks Floor Tile			ABATED	ABATED	MISC								
23A	12" x 12" Beige w/ Carmel Streaks Floor Tile Mastic			ABATED	ABATED	MISC								
24	9" x 9" White Floor Tile w/ Blue Streaks			Room 110	CHR	MISC								
24A	9" x 9" White Floor Tile w/ Blue Streaks Mastic			Room 110	CHR	MISC								
25	2' x 4' Ceiling Tile	25,700	SF	Rooms 214, 206, 203, 210, 2nd Floor Mens Bathroom and	ASSUMED	MISC	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		LOW

# Chicago Public Schools

**School** Manley Academy **Unit** 53111 **Building ID** 1460  
**Address** 2935 W. Polk **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Lunchroom, 122, 124, 116, 118										
26	6"x12"Ceiling Tile and Wall Tile	5,700	SF	Auditorium	ASSUMED	MISC	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		LOW
27	1' x 1' Pinhole Ceiling Tile	2,500	SF	Room 317 & Kitchen	ASSUMED	MISC	Y	LOC	50	SF		Damaged or significantly damaged friable misc. ACBM	3	LOW
27A	1' x 1' Pinhole Ceiling Tile Adhesive	2,500	SF	Room 317 & Kitchen	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
28	1' x 1' White Wormy Texture Ceiling Tile			Rooms 112 114 and 124	ASSUMED	MISC								
28A	1' x 1' White Wormy Texture Ceiling Tile Adhesive			Rooms 112 114, 124	ASSUMED	MISC								
29	Counter Top/Sink			ABATED	ABATED	MISC								
2A	12" x 12" Beige w/ Brown & White Spks Floor Tile Mastic	1,350	SF	Rooms 115, Girls Gym Office	CHR	MISC	N	NONE				ACBM with the potential for damage		LOW
3	12" x 12" White w/ Beige Specks Floor Tile	750	SF	Room 137	CHR	MISC	N	NONE				ACBM with the potential for damage		LOW
30	Desks (Science Rooms)	16	EA	Room 315	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
31	Green Stage Curtain			Auditorium	ASSUMED	MISC								
32	Yellow Stage Curtain			Auditorium	ASSUMED	MISC								
33	Canvas Hair Dryer Hose			Girls Locker Room	ASSUMED	MISC								
34	Boiler Breeching	50	LF	Boiler Room	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		MODERATE
35	Water Tank Insulation			ABATED	ABATED	TSI								
36	Water Tank Insulation			ABATED	ABATED	TSI								
37	Air Cell Pipe Insulation	150	LF	Attic Over Gym & in Gym, Throughout Basement, Boiler Room	CHR	TSI	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		LOW
38	Hard Joint Compound Off Air Cell Pipe Insulation	15	LF	Attic Over Gym, Throughout Basement	CHR	TSI	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		LOW
39	Mag Block Insulation			ABATED	ABATED	TSI								
3A	12" x 12" White w/ Beige Specks Floor Tile Mastic	750	SF	Room 137	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
4	9" x 9" Black Floor Tile	700	SF	Front of the Auditorium & Construction Tech. Hallway, Room 114, Room 225, Engineer Tool Closet	CHR	MISC	N	LOC	80	SF		ACBM with potential for significant damage	5	MODERATE

# Chicago Public Schools

**School** Manley Academy **Unit** 53111 **Building ID** 1460  
**Address** 2935 W. Polk **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

## ***Inspector's Comments are Summarized at the End of the Report***

# Chicago Public Schools

**School** Manley Academy **Unit** 53111 **Building ID** 1460  
**Address** 2935 W. Polk **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
58	9" x 9" Peach Floor Tile			ABATED	ABATED	MISC								
58A	9" x 9" Peach Floor Tile Mastic			ABATED	ABATED	MISC								
59	Black Baseboard	500	SF	Rooms 112, 114, and 124	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
59A	Black Baseboard Adhesive	500	SF	Rooms 112, 114, and 124	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
5A	9" x 9" Maroon Floor Tile Mastic			ABATED	ABATED	MISC								
6	9" x 18" Black Floor Tile			ABATED	ABATED	MISC								
60	12" x 12" Off-White w/ White Specks Floor Tile	1,560	SF	Principal's Office	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
60A	12" x 12" Off-White w/ White Specksfloor Tile Mastic	1,560	SF	Principals Office	CHR	MISC	N	NONE			ACBM with the potential for damage		LOW	
61	Roof Flashing - Non-AHERA				CHR	MISC								
62	Roof Fields - Non-AHERA				ASSUMED	MISC								
63	12" x 12" Blue Floor Tile	600	SF	Rooms 112, 114, 315	ASSUMED	MISC								
64	12" x 12" Blue Floor Tile Mastic	600	SF	Rooms 112, 114, 315	ASSUMED	MISC								
65	Insulation Inside Of Vault Door	32	SF	Main Office	ASSUMED	TSI	Y	NONE			Any remaining friable ACBM or friable suspect ACBM		LOW	
66	12" x 12" Gray Floor Tile	360	SF	Elevator Landings On 1st, 2nd & 3rd Floor s	ASSUMED	MISC	N	LOC	2	SF		ACBM with potential for significant damage	5	LOW
67	12" x 12" Gray Floor Tile Mastic	360	SF	Elevator Landings On 1st, 2nd & 3rd Floor s	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
68	12" x 12" Green Floor Tile			Room 215	ASSUMED	MISC								
69	12" x 12" Green Floor Tile Mastic			Room 215	ASSUMED	MISC								
6A	9" x 18" Black Floor Tile Mastic			ABATED	ABATED	MISC								
7	12" x 12" Gray w/ White Streaks Floor Tile	500	SF	Room 216, and Principle's Office	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
70	Elevator Brake Shoes	10	SF	Basement	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
71	Purple Carpet Mastic	2,600	SF	Room 104	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
72	Blue/Purple/Pink Mix Carpet Mastic	1,000	SF	Room 103	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
73	Blue Carpet Mastic	800	SF	Rooms 122	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
74	Brown Carpet Mastic	2,900	SF	Rooms 107, 101	ASSUMED	MISC	N	NONE			ACBM with the potential for damage		LOW	
75	Blue Linoleum	4,000	SF	Rooms 302, 307,	ASSUMED	MISC	N	NONE			ACBM with the		LOW	

Chicago Public Schools

**School** Manley Academy **Unit** 53111 **Building ID** 1460  
**Address** 2935 W. Polk **Region** 03

## **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

## Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

## *Inspector's Comments are Summarized at the End of the Report*

# Chicago Public Schools

**School** Manley Academy **Unit** 53111 **Building ID** 1460  
**Address** 2935 W. Polk **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Mastic													
93	Light Blue w/ Blue Specks Linoleum	2,150	SF	Rooms 304, 308	ASSUMED	MISC	N	NONE			ACBM with the potential for damage			LOW
94	Light Blue w/ Blue Specks Linoleum Mastic	2,150	SF	Rooms 304, 308	ASSUMED	MISC	N	NONE			ACBM with the potential for damage			LOW
95	Tan Linoleum	650	SF	Room 215	ASSUMED	MISC	N	NONE			ACBM with the potential for damage			LOW
96	Tan Linoleum Mastic	650	SF	Room 215	ASSUMED	MISC	N	NONE			ACBM with the potential for damage			LOW
97	12" x 12" White w/ Green Specks Floor Tile	180	SF	Boys Gym Office	ASSUMED	MISC	N	NONE			ACBM with the potential for damage			LOW
98	12" x 12" White w/ Green Specks Floor Tile Mastic	180	SF	Boys Gym Office	ASSUMED	MISC	N	NONE			ACBM with the potential for damage			LOW
99	Burgandy Carpet w/ Blue and Orange Specks Adhesive	1,600	SF	Room 209b, 201	ASSUMED	MISC	N	NONE			ACBM with the potential for damage			LOW
9A	Brown Linoleum Mastic			2nd Floor Gym Office	ASSUMED	MISC								
A	Black Linoleum Flooring			Girls Locker Room Laundry Area	ASSUMED	MISC								
A-1	Black Linoleum Flooring-Mastic			Girls Locker Room Laundry Area	ASSUMED	MISC								
HA-1000	2' x 4' White Plaing Ceiling Tile	2,000	SF	Culinary Classroom 207, 211	ASSUMED	MISC	Y	NONE			Any remaining friable ACBM or friable suspect ACBM			LOW
HA-1001	2' x 4' White Fissures and Pinholes Ceiling Tile	800	SF	Room 215	ASSUMED	MISC	Y	NONE			Any remaining friable ACBM or friable suspect ACBM			LOW

# Chicago Public Schools

School Manley Academy Unit 53111 Building ID 1460  
Address 2935 W. Polk Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <u>7/10/2025</u>
Inspector Name <u>Dionne Carey Walker</u>
<u>100-09969</u> <u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date

#### Inspector's Comments

HA Number:	Inspector Comments:
1	
10	Material not observed - 2025
100	
1002	
1003	Not observed in 122
1004	
101	Material not observed - 2025
102	Material not observed - 2025
103	
104	
105	
106	
107	
108	
109	
10A	Material not observed - 2025
11	Material not observed - 2025
110	
111	
112	
113	
114	
11A	Material not observed - 2025
12	Material not observed - 2025

# Chicago Public Schools

**School** Manley Academy **Unit** 53111 **Building ID** 1460  
**Address** 2935 W. Polk **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
12A	
13	
13A	
14	
14A	
15	
16	
17	
18	
19	Material not observed - 2025
19A	Material not observed - 2025
1A	
2	
20	Damage in Auditorium
20A	
22	
22A	
23	
23A	
24	Material not observed - 2025
24A	Material not observed - 2025
25	
26	Not observed in 101
27	Damage in Room 317
27A	
28	Material not observed - 2025
28A	Material not observed - 2025
29	
2A	

# Chicago Public Schools

**School** Manley Academy **Unit** 53111 **Building ID** 1460  
**Address** 2935 W. Polk **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
3	
30	
31	Material not observed - 2025
32	Material not observed - 2025
33	Material not observed - 2025
34	
35	
36	
37	Did not observed damage in chemical room
38	Not observed in boiler room or tunnels
39	
3A	
4	Damage in Engineers Tool Storage
40	
41	
42	
43	
44	
45	Damage found in: 3rd floor corridor, Room 300, Room 312, Room 313
46	Damage in Room 302
47	Material not observed - 2025
48	
49	Damage in Boiler Room
4A	
5	
50	
51	
52	Not observed in 316, 317, 307, 302
52A	Not observed in 316, 317, 307, 302

# Chicago Public Schools

**School** Manley Academy **Unit** 53111 **Building ID** 1460  
**Address** 2935 W. Polk **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
53	Material not observed - 2025
53A	Material not observed - 2025
54	
55	
56	
57	Material not observed - 2025
58	
58A	
59	
59A	
5A	
6	
60	
60A	
61	
62	
63	Rooms 112 and 114 inaccessible. Not observed in 300, 302, 306, 307
64	Rooms 112 and 114 inaccessible. Not observed in 300, 302, 306, 307
65	
66	Damage in Elevator
67	
68	Material not observed - 2025
69	Material not observed - 2025
6A	
7	
70	
71	
72	
73	

# Chicago Public Schools

**School** Manley Academy **Unit** 53111 **Building ID** 1460  
**Address** 2935 W. Polk **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
74	
75	
76	
77	Material in inaccessible area(s) - 2025
78	Material in inaccessible area(s) - 2025
79	
7A	
8	
80	
81	
82	Not observed in 207, 209
83	
84	
85	
86	Not observed in 214
87	
88	
89	
8A	
9	Material not observed - 2025
90	Material not observed - 2025
91	Material not observed - 2025
92	Material not observed - 2025
93	
94	
95	
96	
97	
98	

# Chicago Public Schools

**School** Manley Academy **Unit** 53111 **Building ID** 1460  
**Address** 2935 W. Polk **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
99	
9A	Material not observed - 2025
A	Material not observed - 2025
A-1	Material not observed - 2025
HA-1000	
HA-1001	Missing ceiling tile in Room 215

**Table II**  
**Management Planner's Review**

---

# Chicago Public Schools

**School** Manley Academy

**Unit** 53111

**Building ID** 1460

**Address** 2935 W. Polk

Chicago, IL, 60612

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	12" x 12" Brown Floor Tile	950	SF	Rooms 104a	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
10	Green Linoleum			Room 203	Assumed	MISC					
100	Red Carpet Adhesive	320	SF	Room 102	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
1002	Gray Carpet Glue	400	SF	Room 124 in Network 5 Wing	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
1003	12" x 12" Beige, White, and Brown Spotted Floor Tile	200	SF	Kitchen in Network 5 Wing, 100 (Principal's Office)	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
1004	12" x 12" Beige, White, and Brown Spotted Floor Tile Mastic	200	SF	Room 122 Kitchen in Network 5 Wing, 100 (Principal's Office)	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
101	12" x 12" Orange Floor Tile			Girls Locker Room, Laundry Room	Assumed	MISC					
102	12" x 12" Orange Floor Tile Mastic			Girls Locker Room, Laundry Room	Assumed	MISC					
103	12" x 12" Gray w/ White Streaks Floor Tile	980	SF	Room 110	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
104	12" x 12" Gray w/ White Streaks Floor Tile Mastic	980	SF	Room 110	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
105	12" x 12" Brown/Beige/White Mix Floor Tile	200	SF	Rooms 315, 310	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
106	12" x 12" Light Gray/White Mix Floor Tile	200	SF	Rooms 315, 310	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
107	12" x 12" Dark Gray Mix Floor Tile	200	SF	Rooms 315, 310	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
108	12" x 12" Dark Gray, Light Gray, and Brown Mix Floor Tile Mastic	600	SF	Rooms 315, 310	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
109	12" x 12" White w/ Gray Specks Floor Tile	700	SF	Room 211	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
10A	Green Linoleum Mastic			Room 203	Assumed	MISC					
11	12" x 12" White w/ Brown Specks Floor Tile			Rooms 225 and 103	Chrysotile	MISC					
110	12" x 12" White w/ Gray Specks Floor Tile Mastic	700	SF	Room 211	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
111	2' x 2' White Ceiling Tiles w/ Pinholes	600	SF	Rooms 315, 310	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
112	12" x 12" Light Red Floor Tile	400	SF	Room 100 (Principal's Office)	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
113	12" x 12" Black Floor Tile	200	SF	Room 100 (Principal's Office)	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
114	12" x 12" Light Red and Black Floor Tile Mastic	600	SF	Room 100 (Principal's Office)	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
11A	12" x 12" White w/ Brown Specks Floor Tile Mastic			Rooms 225 and 103	Chrysotile	MISC					
12	12" x 12" Brownish Green Floor Tile			Room 225	Assumed	MISC					
12A	12" x 12" Brownish Green Floor Tile Mastic			ABATED	Abated	MISC					
13	9" x 9" Brown Floor Tile	200	SF	Room 225	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
13A	9" x 9" Brown Floor Tile Mastic	200	SF	Room 225	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
14	12" x 12" Wood Grain Floor Tile	75	SF	3rd Floor Band Storage	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
14A	12" x 12" Wood Grain Floor Tile Mastic	75	SF	3rd Floor Band Storage	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
15	Yellow Linoleum			ABATED	Abated	MISC					
16	Exterior Brick Mortar - Non-AHERA			Exterior of Building	Assumed	MISC					

# Chicago Public Schools

**School** Manley Academy

**Unit** 53111

**Building ID** 1460

**Address** 2935 W. Polk

Chicago, IL, 60612

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
17	Drywall Tape	300	LF	Rooms 112 & 124	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
18	Drywall Mud	300	LF	Rooms 112 & 124	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
19	12" x 12" Red Floor Tile			Auditorium	Chrysotile	MISC					
19A	12" x 12" Red Floor Tile Mastic			Auditorium	Chrysotile	MISC					
1A	12" x 12" Brown Floor Tile Mastic	950	SF	Rooms 104a	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
2	12" x 12" Beige w/ Brown & White Specks Floor Tile	1,350	SF	Rooms 115, Girls Gym Office	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
20	12" x 12" Black Floor Tile	750	SF	Auditorium	Chrysotile	MISC	No	100	SF	5 ACBM with potential for significant damage	Remove
20A	12" x 12" Black Floor Tile Mastic	750	SF	Auditorium	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
22	9" x 9" Green Floor Tile			ABATED	Abated	MISC					
22A	9" x 9" Green Floor Tile Mastic			ABATED	Abated	MISC					
23	12" x 12" Beige w/ Carmel Streaks Floor Tile			ABATED	Abated	MISC					
23A	12" x 12" Beige w/ Carmel Streaks Floor Tile Mastic			ABATED	Abated	MISC					
24	9" x 9" White Floor Tile w/ Blue Streaks			Room 110	Chrysotile	MISC					
24A	9" x 9" White Floor Tile w/ Blue Streaks Mastic			Room 110	Chrysotile	MISC					
25	2' x 4' Ceiling Tile	25,700	SF	Rooms 214, 206, 203, 210, 2nd Floor Mens Bathroom and Lunchroom, 122, 124, 116, 118	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
26	6"x12"Ceiling Tile and Wall Tile	5,700	SF	Auditorium	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
27	1' x 1' Pinhole Ceiling Tile	2,500	SF	Room 317 & Kitchen	Assumed	MISC	Yes	50	SF	4 Damaged or significantly damaged friable misc. ACBM	Remove
27A	1' x 1' Pinhole Ceiling Tile Adhesive	2,500	SF	Room 317 & Kitchen	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
28	1' x 1' White Wormy Texture Ceiling Tile			Rooms 112 114 and 124	Assumed	MISC					
28A	1' x 1' White Wormy Texture Ceiling Tile Adhesive			Rooms 112 114, 124	Assumed	MISC					
29	Counter Top/Sink			ABATED	Abated	MISC					
2A	12" x 12" Beige w/ Brown & White Spks Floor Tile Mastic	1,350	SF	Rooms 115, Girls Gym Office	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
3	12" x 12" White w/ Beige Specks Floor Tile	750	SF	Room 137	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
30	Desks (Science Rooms)	16	EA	Room 315	Assumed	MISC	No		EA	6 ACBM with the potential for damage	Follow O&M Plan
31	Green Stage Curtain			Auditorium	Assumed	MISC					
32	Yellow Stage Curtain			Auditorium	Assumed	MISC					
33	Canvas Hair Dryer Hose			Girls Locker Room	Assumed	MISC					
34	Boiler Breeching	50	LF	Boiler Room	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Manley Academy

**Unit** 53111

**Building ID** 1460

**Address** 2935 W. Polk

Chicago, IL, 60612

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
35	Water Tank Insulation			ABATED	Abated	TSI					
36	Water Tank Insulation			ABATED	Abated	TSI					
37	Air Cell Pipe Insulation	150	LF	Attic Over Gym & in Gym, Throughout Basement, Boiler Room	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
38	Hard Joint Compound Off Air Cell Pipe Insulation	15	LF	Attic Over Gym, Throughout Basement	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
39	Mag Block Insulation			ABATED	Abated	TSI					
3A	12" x 12" White w/ Beige Specks Floor Tile Mastic	750	SF	Room 137	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
4	9" x 9" Black Floor Tile	700	SF	Front of the Auditorium & Construction Tech. Hallway, Room 114, Room 225, Engineer Tool Closet	Chrysotile	MISC	No	80	SF	5 ACBM with potential for significant damage	Remove
40	Mag Block Joint Insulation			ABATED	Abated	TSI					
41	Paper Wrap Pipe Insulation			ABATED	Abated	TSI					
42	Hard Joint Compound Paper Wrap Pipe Insulation			ABATED	Abated	TSI					
43	Hard Joint Compound on Fiberglass Pipe Insulation			ABATED	Abated	TSI					
44	Air Cell Heat Shields			ABATED	Abated	TSI					
45	Plaster Ceiling	250,000	SF	Throughout	Assumed	SURFACE	Yes	80	SF	2 Damaged friable surfacing ACBM	Repair
46	Plaster Walls	350,000	SF	Rooms 335, 307, 302, 206, 207, 122, 124, and Boys Gym Throughout Building	Assumed	SURFACE	Yes	542	SF	2 Damaged friable surfacing ACBM	Repair
47	Plaster Patch			Boiler Room	Chrysotile	SURFACE					
48	Fire Doors	280	SF	Auditorium	Chrysotile	TSI	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
49	Boiler Gaskets	30	LF	Boiler Room	Chrysotile	MISC	No	15	LF	5 ACBM with potential for significant damage	Repair
4A	9" x 9" Black Floor Tile Mastic	700	SF	Front of the Auditorium & Construction Tech. Hallway, Engineer Tool Closet	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
5	9" x 9" Maroon Floor Tile			ABATED	Abated	MISC					
50	Acoustical Plaster	80,000	SF	Auditorium	Assumed	SURFACE	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
51	Carpet Mastic	4,000	SF	Library and Rooms 213, 201	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
52	12" x 12" Brown Speckled Floor Tile	3,500	SF	Rooms 115, 1st Floor Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
52A	12" x 12" Brown Speckled Floor Tile Mastic	3,500	SF	Rooms 115, 1st Floor Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
53	12" x 12" Off-White Floor Tile w/ Black Specks			Room 315	Assumed	MISC					
53A	12" x 12" Off-White Floor Tile w/ Black Specks Mastic			Room 315	Assumed	MISC					

# Chicago Public Schools

**School** Manley Academy  
**Address** 2935 W. Polk

**Unit** 53111  
**Chicago, IL, 60612**

**Building ID** 1460  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
54	White Rope Gasket			ABATED	Abated	MISC					
55	Garlock Sheet Goods			ABATED	Abated	MISC					
56	Gaskets			ABATED	Abated	MISC					
57	White Heat Pads			Room 315	Assumed	MISC					
58	9" x 9" Peach Floor Tile			ABATED	Abated	MISC					
58A	9" x 9" Peach Floor Tile Mastic			ABATED	Abated	MISC					
59	Black Baseboard	500	SF	Rooms 112, 114, and 124	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
59A	Black Baseboard Adhesive	500	SF	Rooms 112, 114, and 124	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
5A	9" x 9" Maroon Floor Tile Mastic			ABATED	Abated	MISC					
6	9" x 18" Black Floor Tile			ABATED	Abated	MISC					
60	12" x 12" Off-White w/ White Specks Floor Tile	1,560	SF	Principal's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
60A	12" x 12" Off-White w/ White Specksfloor Tile Mastic	1,560	SF	Principals Office	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
61	Roof Flashing - Non-AHERA				Chrysotile	MISC					
62	Roof Fields - Non-AHERA				Assumed	MISC					
63	12" x 12" Blue Floor Tile	600	SF	Rooms 112, 114, 315	Assumed	MISC			SF		
64	12" x 12" Blue Floor Tile Mastic	600	SF	Rooms 112, 114, 315	Assumed	MISC			SF		
65	Insulation Inside Of Vault Door	32	SF	Main Office	Assumed	TSI	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
66	12" x 12" Gray Floor Tile	360	SF	Elevator Landings On 1st, 2nd & 3rd Floor s	Assumed	MISC	No	2	SF	5 ACBM with potential for significant damage	Remove
67	12" x 12" Gray Floor Tile Mastic	360	SF	Elevator Landings On 1st, 2nd & 3rd Floor s	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
68	12" x 12" Green Floor Tile			Room 215	Assumed	MISC					
69	12" x 12" Green Floor Tile Mastic			Room 215	Assumed	MISC					
6A	9" x 18" Black Floor Tile Mastic			ABATED	Abated	MISC					
7	12" x 12" Gray w/ White Streaks Floor Tile	500	SF	Room 216, and Principle's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
70	Elevator Brake Shoes	10	SF	Basement	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
71	Purple Carpet Mastic	2,600	SF	Room 104	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
72	Blue/Purple/Pink Mix Carpet Mastic	1,000	SF	Room 103	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
73	Blue Carpet Mastic	800	SF	Rooms 122	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
74	Brown Carpet Mastic	2,900	SF	Rooms 107, 101	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
75	Blue Linoleum	4,000	SF	Rooms 302, 307, 310 & 315	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
76	Blue Linoleum Mastic	4,000	SF	Rooms 302, 307, 310, 315	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
77	4" Blue Vinyl Baseboard			Rooms 112, 114 & 124	Assumed	MISC					

# Chicago Public Schools

**School** Manley Academy

**Unit** 53111

**Building ID** 1460

**Address** 2935 W. Polk

Chicago, IL, 60612

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
78	4" Blue Vinyl Baseboard Mastic			Rooms 112, 114 & 124	Assumed	MISC					
79	4" Dark Gray Vinyl Baseboard	350	LF	Rooms 124, 122	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
7A	12" x 12" Gray w/ White Streaks Floor Tile Mastic	500	SF	Room 216 and Principal's Office	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
8	12" x 12" Light Gray Floor Tile	360	SF	Room 216	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
80	4" Dark Gray Vinyl Baseboard Mastic	350	LF	Rooms 124, 122	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
81	Lab Tables and Sinks	500	SF	Rooms 300, 302, 307, 310, 311, & 315	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
82	Blue/White Mix Carpet Mastic	650	SF	Rooms 209a & 209b	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
83	12" x 12" Pink Vinyl Floor Tile	9,000	SF	1st, 2nd and 3rd Floor Corridors	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
84	12" x 12" Pink Vinyl Floor Tile Mastic	9,000	SF	1st, 2nd and 3rd Floor Corridors	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
85	Purple Carpet Adhesive	2,600	SF	Room 104	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
86	Light Brown Carpet Adhesive	800	SF	Room 212	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
87	Blue w/ Red and Orange Carpet Adhesive	1,500	SF	Room 212, 213	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
88	Chalk Board Adhesive	14,200	SF	Throughout All Classrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
89	Red/Maroon Terrazzo	4,000	SF	Hallways Trim Border, Stairwells, Hallway Adjacent WomensKitchen, Lunchroom, Kitchen	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
8A	12" x 12" Light Gray Floor Tile Mastic	360	SF	Room 216	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
9	Brown Linoleum			2nd Floor Gym Office	Assumed	MISC					
90	Blue Carpet Adhesive			Room 122	Assumed	MISC					
91	12" x 12" Light Brown w/ White Floor Tile			Room 215	Assumed	MISC					
92	12" x 12" Light Brown Floor Tile w/ White Mastic			Room 215	Assumed	MISC					
93	Light Blue w/ Blue Specks Linoleum	2,150	SF	Rooms 304, 308	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
94	Light Blue w/ Blue Specks Linoleum Mastic	2,150	SF	Rooms 304, 308	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
95	Tan Linoleum	650	SF	Room 215	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
96	Tan Linoleum Mastic	650	SF	Room 215	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
97	12" x 12" White w/ Green Specks Floor Tile	180	SF	Boys Gym Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
98	12" x 12" White w/ Green Specks Floor Tile Mastic	180	SF	Boys Gym Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
99	Burgandy Carpet w/ Blue and Orange Specks Adhesive	1,600	SF	Room 209b, 201	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
9A	Brown Linoleum Mastic			2nd Floor Gym Office	Assumed	MISC					
A	Black Linoleum Flooring			Girls Locker Room Laundry Area	Assumed	MISC					
A-1	Black Linoleum Flooring-Mastic			Girls Locker Room Laundry Area	Assumed	MISC					
HA-1000	2' x 4' White Plaing Ceiling Tile	2,000	SF	Culinary Classroom 207, 211	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
HA-	2' x 4' White Fissures and Pinholes Ceiling Tile	800	SF	Room 215	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable	Follow O&M Plan

# Chicago Public Schools

**School** Manley Academy

**Unit** 53111

**Building ID** 1460

**Address** 2935 W. Polk

Chicago, IL, 60612

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1001										suspect ACBM	

Review Date	8/8/2025
Manager Planner Name	Mike Serio
100-18488	5/15/2026

HA Number	Management Comments
1	
10	
100	

# Chicago Public Schools

**School** Manley Academy

**Unit** 53111

**Building ID** 1460

**Address** 2935 W. Polk

Chicago, IL, 60612

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

Manager IDPH License No/Expiration

HA Number	Management Comments
1002	
1003	
1004	
101	
102	
103	
104	
105	
106	
107	
108	
109	
10A	
11	
110	
111	
112	
113	
114	
11A	
12	
12A	
13	
13A	
14	
14A	
15	

# Chicago Public Schools

**School** Manley Academy

**Unit** 53111

**Building ID** 1460

**Address** 2935 W. Polk

Chicago, IL, 60612

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
16	Non-AHERA
17	
18	
19	
19A	
1A	
2	
20	Remove or repair to intact.
20A	
22	
22A	
23	
23A	
24	
24A	
25	
26	
27	Sample to determine ACM content, remove or repair to intact.
27A	
28	
28A	
29	
2A	
3	
30	
31	
32	

# Chicago Public Schools

**School** Manley Academy

**Unit** 53111

**Building ID** 1460

**Address** 2935 W. Polk

Chicago, IL, 60612

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
33	
34	
35	
36	
37	
38	
39	
3A	
4	Remove or repair to intact.
40	
41	
42	
43	
44	
45	Sample to determine ACM content, remove or repair damaged surfacing material to intact.
46	Sample to determine ACM content, remove or repair damaged surfacing material to intact.
47	
48	
49	Remove or repair to intact.
4A	
5	
50	
51	
52	
52A	
53	
53A	

# Chicago Public Schools

**School** Manley Academy

**Unit** 53111

**Building ID** 1460

**Address** 2935 W. Polk

Chicago, IL, 60612

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
54	
55	
56	
57	
58	
58A	
59	
59A	
5A	
6	
60	
60A	
61	Non-AHERA
62	Non-AHERA
63	If identified, continue O&M.
64	If identified, continue O&M.
65	
66	Sample to determine ACM content, remove or repair to intact.
67	
68	
69	
6A	
7	
70	
71	
72	
73	

# Chicago Public Schools

**School** Manley Academy

**Unit** 53111

**Building ID** 1460

**Address** 2935 W. Polk

Chicago, IL, 60612

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
74	
75	
76	
77	If identified, continue O&M.
78	If identified, continue O&M.
79	
7A	
8	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
8A	
9	
90	
91	
92	
93	
94	
95	
96	

# Chicago Public Schools

**School** Manley Academy

**Unit** 53111

**Building ID** 1460

**Address** 2935 W. Polk

Chicago, IL, 60612

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
97	
98	
99	
9A	
A	
A-1	
HA-1000	
HA-1001	

## APPENDIX A

---

### Assessment Sheets, Drawings and Photos

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2025 AHERA REINSPECTION***

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>1</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Brown Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 104a</b>		
MATERIAL QUANTITY:	<b>950</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**

MATERIAL LOCATION: **Rooms 104a**

MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **Green Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 203**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Green Linoleum**

MATERIAL LOCATION: **Room 203**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>100</b>		
MATERIAL DESCRIPTION:	<b>Red Carpet Adhesive</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 102</b>		
MATERIAL QUANTITY:	<b>320</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **100**

MATERIAL DESCRIPTION: **Red Carpet Adhesive**

MATERIAL LOCATION: **Room 102**

MATERIAL QUANTITY: **320** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>1002</b>		
MATERIAL DESCRIPTION:	<b>Gray Carpet Glue</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 124 in Network 5 Wing</b>		
MATERIAL QUANTITY:	<b>400</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **1002**

MATERIAL DESCRIPTION: **Gray Carpet Glue**

MATERIAL LOCATION: **Room 124 in Network 5 Wing**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>1003</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Beige, White, and Brown Spotted Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Kitchen in Network 5 Wing, 100 (Principal's Office)</b>		
MATERIAL QUANTITY:	<b>200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:	<b>Not observed in 122</b>		

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **1003**

MATERIAL DESCRIPTION: **12" x 12" Beige, White, and Brown Spotted Floor Tile**

MATERIAL LOCATION: **Kitchen in Network 5 Wing, 100 (Principal's Office)**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>1004</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Beige, White, and Brown Spotted Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 122 Kitchen in Network 5 Wing, 100 (Principal's Office)**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **1004**

MATERIAL DESCRIPTION: **12" x 12" Beige, White, and Brown Spotted Floor Tile Mastic**

MATERIAL LOCATION: **Room 122 Kitchen in Network 5 Wing, 100 (Principal's Office)**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	101	
MATERIAL DESCRIPTION:	12" x 12" Orange Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Girls Locker Room, Laundry Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **101**

MATERIAL DESCRIPTION: **12" x 12" Orange Floor Tile**

MATERIAL LOCATION: **Girls Locker Room, Laundry Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	102	
MATERIAL DESCRIPTION:	12" x 12" Orange Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Girls Locker Room, Laundry Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **102**

MATERIAL DESCRIPTION: **12" x 12" Orange Floor Tile Mastic**

MATERIAL LOCATION: **Girls Locker Room, Laundry Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>103</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Gray w/ White Streaks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 110</b>		
MATERIAL QUANTITY:	<b>980</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **103**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ White Streaks Floor Tile**

MATERIAL LOCATION: **Room 110**

MATERIAL QUANTITY: **980** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>104</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Gray w/ White Streaks Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 110</b>		
MATERIAL QUANTITY:	<b>980</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **104**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Room 110**

MATERIAL QUANTITY: **980** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	105		
MATERIAL DESCRIPTION:	12" x 12" Brown/Beige/White Mix Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 315, 310		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **105**

MATERIAL DESCRIPTION: **12" x 12" Brown/Beige/White Mix Floor Tile**

MATERIAL LOCATION: **Rooms 315, 310**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	106		
MATERIAL DESCRIPTION:	12" x 12" Light Gray/White Mix Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 315, 310		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **106**

MATERIAL DESCRIPTION: **12" x 12" Light Gray/White Mix Floor Tile**

MATERIAL LOCATION: **Rooms 315, 310**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>107</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Dark Gray Mix Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 315, 310</b>		
MATERIAL QUANTITY:	<b>200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **107**

MATERIAL DESCRIPTION: **12" x 12" Dark Gray Mix Floor Tile**

MATERIAL LOCATION: **Rooms 315, 310**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>108</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Dark Gray, Light Gray, and Brown Mix Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 315, 310**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **108**

MATERIAL DESCRIPTION: **12" x 12" Dark Gray, Light Gray, and Brown Mix Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 315, 310**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	109		
MATERIAL DESCRIPTION:	12" x 12" White w/ Gray Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 211		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **109**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Specks Floor Tile**

MATERIAL LOCATION: **Room 211**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10A**

MATERIAL DESCRIPTION: **Green Linoleum Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 203**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **10A**

MATERIAL DESCRIPTION: **Green Linoleum Mastic**

MATERIAL LOCATION: **Room 203**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 11

MATERIAL DESCRIPTION: 12" x 12" White w/ Brown Specks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Chrysotile FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 225 and 103

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Specks Floor Tile**

MATERIAL LOCATION: **Rooms 225 and 103**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>110</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" White w/ Gray Specks Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 211</b>		
MATERIAL QUANTITY:	<b>700</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **110**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Specks Floor Tile Mastic**

MATERIAL LOCATION: **Room 211**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>111</b>		
MATERIAL DESCRIPTION:	<b>2' x 2' White Ceiling Tiles w/ Pinholes</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 315, 310</b>		
MATERIAL QUANTITY:	<b>600</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **111**

MATERIAL DESCRIPTION: **2' x 2' White Ceiling Tiles w/ Pinholes**

MATERIAL LOCATION: **Rooms 315, 310**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>112</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Light Red Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 100 (Principal's Office)</b>		
MATERIAL QUANTITY:	<b>400</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **112**

MATERIAL DESCRIPTION: **12" x 12" Light Red Floor Tile**

MATERIAL LOCATION: **Room 100 (Principal's Office)**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>113</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Black Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 100 (Principal's Office)</b>		
MATERIAL QUANTITY:	<b>200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **113**

MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile**

MATERIAL LOCATION: **Room 100 (Principal's Office)**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>114</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Light Red and Black Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 100 (Principal's Office)</b>		
MATERIAL QUANTITY:	<b>600</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **114**

MATERIAL DESCRIPTION: **12" x 12" Light Red and Black Floor Tile Mastic**

MATERIAL LOCATION: **Room 100 (Principal's Office)**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 11A

MATERIAL DESCRIPTION: 12" x 12" White w/ Brown Specks Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Chrysotile FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 225 and 103

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **11A**

MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Specks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 225 and 103**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 12  
MATERIAL DESCRIPTION: 12" x 12" Brownish Green Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 225

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **12" x 12" Brownish Green Floor Tile**

MATERIAL LOCATION: **Room 225**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 12A

MATERIAL DESCRIPTION: 12" x 12" Brownish Green Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **12A**

MATERIAL DESCRIPTION: **12" x 12" Brownish Green Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>13</b>		
MATERIAL DESCRIPTION:	<b>9" x 9" Brown Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 225</b>		
MATERIAL QUANTITY:	<b>200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile**

MATERIAL LOCATION: **Room 225**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>13A</b>		
MATERIAL DESCRIPTION:	<b>9" x 9" Brown Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 225</b>		
MATERIAL QUANTITY:	<b>200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **13A**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile Mastic**

MATERIAL LOCATION: **Room 225**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	12" x 12" Wood Grain Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Band Storage		
MATERIAL QUANTITY:	75	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12" x 12" Wood Grain Floor Tile**

MATERIAL LOCATION: **3rd Floor Band Storage**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14A		
MATERIAL DESCRIPTION:	12" x 12" Wood Grain Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Band Storage		
MATERIAL QUANTITY:	75	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **14A**

MATERIAL DESCRIPTION: **12" x 12" Wood Grain Floor Tile Mastic**

MATERIAL LOCATION: **3rd Floor Band Storage**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **Yellow Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Yellow Linoleum**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Non-AHERA

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>17</b>		
MATERIAL DESCRIPTION:	<b>Drywall Tape</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 112 &amp; 124</b>		
MATERIAL QUANTITY:	<b>300</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Drywall Tape**

MATERIAL LOCATION: **Rooms 112 & 124**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>18</b>		
MATERIAL DESCRIPTION:	<b>Drywall Mud</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 112 &amp; 124</b>		
MATERIAL QUANTITY:	<b>300</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Drywall Mud**

MATERIAL LOCATION: **Rooms 112 & 124**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19A**

MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **19A**

MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile Mastic**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1A		
MATERIAL DESCRIPTION:	12" x 12" Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 104a		
MATERIAL QUANTITY:	950	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **1A**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 104a**

MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>2</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Beige w/ Brown &amp; White Specks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 115, Girls Gym Office</b>		
MATERIAL QUANTITY:	<b>1350</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Brown & White Specks Floor Tile**

MATERIAL LOCATION: **Rooms 115, Girls Gym Office**

MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>20</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Black Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>5 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:	<b>Deterioration Physical Damage</b>		
HISTORICAL RESPONSE ACTION:	<b>Repair</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	<b>Deterioration Physical Damage</b>		
DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Auditorium</b>		
MATERIAL QUANTITY:	<b>750</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>SF</b>		
COMMENTS:	<b>Damage in Auditorium</b>		

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>20A</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Black Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Auditorium</b>		
MATERIAL QUANTITY:	<b>750</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **20A**

MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile Mastic**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 22  
MATERIAL DESCRIPTION: 9" x 9" Green Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 22A

MATERIAL DESCRIPTION: 9" x 9" Green Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **22A**

MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 23

MATERIAL DESCRIPTION: 12" x 12" Beige w/ Carmel Streaks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Carmel Streaks Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 23A

MATERIAL DESCRIPTION: 12" x 12" Beige w/ Carmel Streaks Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **23A**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Carmel Streaks Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 24  
MATERIAL DESCRIPTION: 9" x 9" White Floor Tile w/ Blue Streaks  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 110

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **9" x 9" White Floor Tile w/ Blue Streaks**

MATERIAL LOCATION: **Room 110**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 24A

MATERIAL DESCRIPTION: 9" x 9" White Floor Tile w/ Blue Streaks Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 110

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **24A**

MATERIAL DESCRIPTION: **9" x 9" White Floor Tile w/ Blue Streaks Mastic**

MATERIAL LOCATION: **Room 110**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	2' x 4' Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 214, 206, 203, 210, 2nd Floor Mens Bathroom and Lunchroom, 122, 124, 116, 118**

MATERIAL QUANTITY: **25700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**

MATERIAL LOCATION: **Rooms 214, 206, 203, 210, 2nd Floor Mens Bathroom and Lunchroom, 122, 124, 116, 118**

MATERIAL QUANTITY: **25700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>26</b>		
MATERIAL DESCRIPTION:	<b>6"x12" Ceiling Tile and Wall Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Auditorium</b>		
MATERIAL QUANTITY:	<b>5700</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Not observed in 101</b>		

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **6"x12" Ceiling Tile and Wall Tile**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **5700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	1' x 1' Pinhole Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	4 Damaged or significantly damaged friable misc. ACBM		
HISTORICAL DAMAGE REASON:	Deterioration Vibration		
HISTORICAL RESPONSE ACTION:	Encapsulate		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON:	Deterioration Vibration		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 317 & Kitchen		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in Room 317		

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **1' x 1' Pinhole Ceiling Tile**

MATERIAL LOCATION: **Room 317 & Kitchen**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Encapsulate**

Comments:

Sample to determine ACM content, remove or repair to intact.

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>27A</b>		
MATERIAL DESCRIPTION:	<b>1' x 1' Pinhole Ceiling Tile Adhesive</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 317 &amp; Kitchen</b>		
MATERIAL QUANTITY:	<b>2500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **27A**

MATERIAL DESCRIPTION: **1' x 1' Pinhole Ceiling Tile Adhesive**

MATERIAL LOCATION: **Room 317 & Kitchen**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>28</b>		
MATERIAL DESCRIPTION:	<b>1' x 1' White Wormy Texture Ceiling Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 112 114 and 124**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **1' x 1' White Wormy Texture Ceiling Tile**

MATERIAL LOCATION: **Rooms 112 114 and 124**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>28A</b>		
MATERIAL DESCRIPTION:	<b>1' x 1' White Wormy Texture Ceiling Tile Adhesive</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 112 114, 124**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **28A**

MATERIAL DESCRIPTION: **1' x 1' White Wormy Texture Ceiling Tile Adhesive**

MATERIAL LOCATION: **Rooms 112 114, 124**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 29  
MATERIAL DESCRIPTION: Counter Top/Sink  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Counter Top/Sink**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2A		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Brown & White Spks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 115, Girls Gym Office		
MATERIAL QUANTITY:	1350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **2A**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Brown & White Spks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 115, Girls Gym Office**

MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>3</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" White w/ Beige Specks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with potential for significant damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 137</b>		
MATERIAL QUANTITY:	<b>750</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **12" x 12" White w/ Beige Specks Floor Tile**

MATERIAL LOCATION: **Room 137**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>30</b>		
MATERIAL DESCRIPTION:	<b>Desks (Science Rooms)</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 315</b>		
MATERIAL QUANTITY:	<b>16</b>	MATERIAL UNITS:	<b>EA</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>EA</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Desks (Science Rooms)**

MATERIAL LOCATION: **Room 315**

MATERIAL QUANTITY: **16** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 31  
MATERIAL DESCRIPTION: Green Stage Curtain  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Auditorium

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Green Stage Curtain**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32  
MATERIAL DESCRIPTION: Yellow Stage Curtain  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Auditorium

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Yellow Stage Curtain**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 33  
MATERIAL DESCRIPTION: Canvas Hair Dryer Hose  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Girls Locker Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Canvas Hair Dryer Hose**

MATERIAL LOCATION: **Girls Locker Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>34</b>		
MATERIAL DESCRIPTION:	<b>Boiler Breeching</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with potential for significant damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Boiler Room</b>		
MATERIAL QUANTITY:	<b>50</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Boiler Breeching**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 35  
MATERIAL DESCRIPTION: Water Tank Insulation  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Water Tank Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 36  
MATERIAL DESCRIPTION: Water Tank Insulation  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Water Tank Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	Air Cell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Remove		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Attic Over Gym & in Gym, Throughout Basement, Boiler Room**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS: **Did not observed damage in chemical room**

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Air Cell Pipe Insulation**

MATERIAL LOCATION: **Attic Over Gym & in Gym, Throughout Basement, Boiler Room**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	Hard Joint Compound Off Air Cell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Attic Over Gym, Throughout Basement		
MATERIAL QUANTITY:	15	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:	Not observed in boiler room or tunnels		

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Hard Joint Compound Off Air Cell Pipe Insulation**

MATERIAL LOCATION: **Attic Over Gym, Throughout Basement**

MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 39  
MATERIAL DESCRIPTION: Mag Block Insulation  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Mag Block Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>3A</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" White w/ Beige Specks Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 137</b>		
MATERIAL QUANTITY:	<b>750</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **3A**

MATERIAL DESCRIPTION: **12" x 12" White w/ Beige Specks Floor Tile Mastic**

MATERIAL LOCATION: **Room 137**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	4		
MATERIAL DESCRIPTION:	9" x 9" Black Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 Damaged or significantly damaged friable misc. ACBM		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 5. ACBM with potential for significant damage

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Front of the Auditorium & Construction Tech. Hallway, Room 114, Room 225, Engineer Tool Closet		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in Engineers Tool Storage		

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile**

MATERIAL LOCATION: **Front of the Auditorium & Construction Tech. Hallway, Room 114, Room 225, Engineer Tool Closet**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **80** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Remove or repair to intact.

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 40  
MATERIAL DESCRIPTION: Mag Block Joint Insulation  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Mag Block Joint Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 41  
MATERIAL DESCRIPTION: Paper Wrap Pipe Insulation  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Paper Wrap Pipe Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42	
MATERIAL DESCRIPTION:	Hard Joint Compound Paper Wrap Pipe Insulation	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Hard Joint Compound Paper Wrap Pipe Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43	
MATERIAL DESCRIPTION:	Hard Joint Compound on Fiberglass Pipe Insulation	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Hard Joint Compound on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 44  
MATERIAL DESCRIPTION: Air Cell Heat Shields  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Air Cell Heat Shields**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	Plaster Ceiling		
HISTORICAL AHERA DAMAGE CATEGORY	2 Significantly damaged friable surfacing ACBM		
HISTORICAL DAMAGE REASON:	Vibration Deterioration Vibration		
HISTORICAL RESPONSE ACTION:	Encapsulate		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **2. Damaged friable surfacing ACBM**

DAMAGE REASON:	Water Deterioration		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	250000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage found in: 3rd floor corridor, Room 300, Room 312, Room 313		

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Plaster Ceiling**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **250000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **80** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Encapsulate**

Comments:

Sample to determine ACM content, remove or repair damaged surfacing material to intact.

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	Plaster Walls		
HISTORICAL AHERA DAMAGE CATEGORY	2 Damaged friable surfacing ACBM		
HISTORICAL DAMAGE REASON:	Deterioration Vibration Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **2. Damaged friable surfacing ACBM**

DAMAGE REASON:	Deterioration Vibration Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 335, 307, 302, 206, 207, 122, 124, and Boys Gym Throughout Building		
MATERIAL QUANTITY:	350000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in Room 302		

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Plaster Walls**

MATERIAL LOCATION: **Rooms 335, 307, 302, 206, 207, 122, 124, and Boys Gym Throughout Building**

MATERIAL QUANTITY: **350000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **542** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Sample to determine ACM content, remove or repair damaged surfacing material to intact.

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 47

MATERIAL DESCRIPTION: Plaster Patch

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Chrysotile FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Plaster Patch**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>48</b>		
MATERIAL DESCRIPTION:	<b>Fire Doors</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Auditorium</b>		
MATERIAL QUANTITY:	<b>280</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Fire Doors**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **280** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>49</b>		
MATERIAL DESCRIPTION:	<b>Boiler Gaskets</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>5 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	<b>Deterioration</b>		
DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Boiler Room</b>		
MATERIAL QUANTITY:	<b>30</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:	<b>Damage in Boiler Room</b>		

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Boiler Gaskets**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **15** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	4A		
MATERIAL DESCRIPTION:	9" x 9" Black Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Front of the Auditorium & Construction Tech. Hallway, Engineer Tool Closet		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **4A**

MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile Mastic**

MATERIAL LOCATION: **Front of the Auditorium & Construction Tech. Hallway, Engineer Tool Closet**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 5  
MATERIAL DESCRIPTION: 9" x 9" Maroon Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **9" x 9" Maroon Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	Acoustical Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	80000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Acoustical Plaster**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **80000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>51</b>		
MATERIAL DESCRIPTION:	<b>Carpet Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Library and Rooms 213, 201</b>		
MATERIAL QUANTITY:	<b>4000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Library and Rooms 213, 201**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>52</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Brown Speckled Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 115, 1st Floor Office</b>		
MATERIAL QUANTITY:	<b>3500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Not observed in 316, 317, 307, 302</b>		

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile**

MATERIAL LOCATION: **Rooms 115, 1st Floor Office**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>52A</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Brown Speckled Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 115, 1st Floor Office</b>		
MATERIAL QUANTITY:	<b>3500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:	<b>Not observed in 316, 317, 307, 302</b>		

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **52A**

MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 115, 1st Floor Office**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 53  
MATERIAL DESCRIPTION: 12" x 12" Off-White Floor Tile w/ Black Specks  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 315

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/ Black Specks**

MATERIAL LOCATION: **Room 315**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53A**

MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/ Black Specks Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 315**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **53A**

MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/ Black Specks Mastic**

MATERIAL LOCATION: **Room 315**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 54  
MATERIAL DESCRIPTION: White Rope Gasket  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **White Rope Gasket**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 55  
MATERIAL DESCRIPTION: Garlock Sheet Goods  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Garlock Sheet Goods**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **Gaskets**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **Gaskets**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 57  
MATERIAL DESCRIPTION: White Heat Pads  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 315

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **White Heat Pads**

MATERIAL LOCATION: **Room 315**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **9" x 9" Peach Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **9" x 9" Peach Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 58A

MATERIAL DESCRIPTION: 9" x 9" Peach Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **58A**

MATERIAL DESCRIPTION: **9" x 9" Peach Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>59</b>		
MATERIAL DESCRIPTION:	<b>Black Baseboard</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 112, 114, and 124</b>		
MATERIAL QUANTITY:	<b>500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **Black Baseboard**

MATERIAL LOCATION: **Rooms 112, 114, and 124**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>59A</b>		
MATERIAL DESCRIPTION:	<b>Black Baseboard Adhesive</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 112, 114, and 124</b>		
MATERIAL QUANTITY:	<b>500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **59A**

MATERIAL DESCRIPTION: **Black Baseboard Adhesive**

MATERIAL LOCATION: **Rooms 112, 114, and 124**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 5A

MATERIAL DESCRIPTION: 9" x 9" Maroon Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **5A**

MATERIAL DESCRIPTION: **9" x 9" Maroon Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 6  
MATERIAL DESCRIPTION: 9" x 18" Black Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **9" x 18" Black Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>60</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Off-White w/ White Specks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Principal's Office</b>		
MATERIAL QUANTITY:	<b>1560</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/ White Specks Floor Tile**

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY: **1560** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	60A		
MATERIAL DESCRIPTION:	12" x 12" Off-White w/ White Specksfloor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Principals Office**

MATERIAL QUANTITY: **1560** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **60A**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/ White Specks floor Tile Mastic**

MATERIAL LOCATION: **Principals Office**

MATERIAL QUANTITY: **1560** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 61  
MATERIAL DESCRIPTION: Roof Flashing - Non-AHERA  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **Roof Flashing - Non-AHERA**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Non-AHERA

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Roof Fields - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Roof Fields - Non-AHERA**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Non-AHERA

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	63	
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 112, 114, 315

MATERIAL QUANTITY: 600 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS: Rooms 112 and 114 inaccessible. Not observed in 300, 302, 306, 307

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**

MATERIAL LOCATION: **Rooms 112, 114, 315**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M.

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	64	
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 112, 114, 315

MATERIAL QUANTITY: 600 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS: Rooms 112 and 114 inaccessible. Not observed in 300, 302, 306, 307

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 112, 114, 315**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M.

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>65</b>		
MATERIAL DESCRIPTION:	<b>Insulation Inside Of Vault Door</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Main Office</b>		
MATERIAL QUANTITY:	<b>32</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **Insulation Inside Of Vault Door**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **32** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	66		
MATERIAL DESCRIPTION:	12" x 12" Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage Deterioration		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	Physical Damage Deterioration		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Elevator Landings On 1st, 2nd & 3rd Floor s		
MATERIAL QUANTITY:	360	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in Elevator		

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile**

MATERIAL LOCATION: **Elevator Landings On 1st, 2nd & 3rd Floor s**

MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Sample to determine ACM content, remove or repair to intact.

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	67		
MATERIAL DESCRIPTION:	12" x 12" Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Elevator Landings On 1st, 2nd & 3rd Floor s		
MATERIAL QUANTITY:	360	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile Mastic**

MATERIAL LOCATION: **Elevator Landings On 1st, 2nd & 3rd Floor s**

MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 215**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile**

MATERIAL LOCATION: **Room 215**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 215**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile Mastic**

MATERIAL LOCATION: **Room 215**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 6A  
MATERIAL DESCRIPTION: 9" x 18" Black Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **6A**

MATERIAL DESCRIPTION: **9" x 18" Black Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>7</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Gray w/ White Streaks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 216, and Principle's Office</b>		
MATERIAL QUANTITY:	<b>500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ White Streaks Floor Tile**

MATERIAL LOCATION: **Room 216, and Principle's Office**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>70</b>		
MATERIAL DESCRIPTION:	<b>Elevator Brake Shoes</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Basement</b>		
MATERIAL QUANTITY:	<b>10</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **Elevator Brake Shoes**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>71</b>		
MATERIAL DESCRIPTION:	<b>Purple Carpet Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 104</b>		
MATERIAL QUANTITY:	<b>2600</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **Purple Carpet Mastic**

MATERIAL LOCATION: **Room 104**

MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>72</b>		
MATERIAL DESCRIPTION:	<b>Blue/Purple/Pink Mix Carpet Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 103</b>		
MATERIAL QUANTITY:	<b>1000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **Blue/Purple/Pink Mix Carpet Mastic**

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>73</b>		
MATERIAL DESCRIPTION:	<b>Blue Carpet Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 122</b>		
MATERIAL QUANTITY:	<b>800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **Blue Carpet Mastic**

MATERIAL LOCATION: **Rooms 122**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>74</b>		
MATERIAL DESCRIPTION:	<b>Brown Carpet Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 107, 101</b>		
MATERIAL QUANTITY:	<b>2900</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **Brown Carpet Mastic**

MATERIAL LOCATION: **Rooms 107, 101**

MATERIAL QUANTITY: **2900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>75</b>		
MATERIAL DESCRIPTION:	<b>Blue Linoleum</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 302, 307, 310 &amp; 315</b>		
MATERIAL QUANTITY:	<b>4000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **Blue Linoleum**

MATERIAL LOCATION: **Rooms 302, 307, 310 & 315**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	76		
MATERIAL DESCRIPTION:	Blue Linoleum Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 302, 307, 310, 315		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **Blue Linoleum Mastic**

MATERIAL LOCATION: **Rooms 302, 307, 310, 315**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **4" Blue Vinyl Baseboard**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 112, 114 & 124**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Material in inaccessible area(s) - 2025**

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **4" Blue Vinyl Baseboard**

MATERIAL LOCATION: **Rooms 112, 114 & 124**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified, continue O&M.

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **4" Blue Vinyl Baseboard Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 112, 114 & 124**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Material in inaccessible area(s) - 2025**

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **4" Blue Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Rooms 112, 114 & 124**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified, continue O&M.

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>79</b>		
MATERIAL DESCRIPTION:	<b>4" Dark Gray Vinyl Baseboard</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 124, 122</b>		
MATERIAL QUANTITY:	<b>350</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **4" Dark Gray Vinyl Baseboard**

MATERIAL LOCATION: **Rooms 124, 122**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>7A</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Gray w/ White Streaks Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 216 and Principal's Office</b>		
MATERIAL QUANTITY:	<b>500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **7A**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Room 216 and Principal's Office**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>8</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Light Gray Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 216</b>		
MATERIAL QUANTITY:	<b>360</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53111** BULDING ID: **1460**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Manley Academy** REVIEW DATE: **8/8/2025**

ADDRESS: **2935 W. Polk** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **12" x 12" Light Gray Floor Tile**

MATERIAL LOCATION: **Room 216**

MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>80</b>		
MATERIAL DESCRIPTION:	<b>4" Dark Gray Vinyl Baseboard Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 124, 122</b>		
MATERIAL QUANTITY:	<b>350</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **4" Dark Gray Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Rooms 124, 122**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>81</b>		
MATERIAL DESCRIPTION:	<b>Lab Tables and Sinks</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 300, 302, 307, 310, 311, &amp; 315</b>		
MATERIAL QUANTITY:	<b>500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **Lab Tables and Sinks**

MATERIAL LOCATION: **Rooms 300, 302, 307, 310, 311, & 315**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>82</b>		
MATERIAL DESCRIPTION:	<b>Blue/White Mix Carpet Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 209a &amp; 209b</b>		
MATERIAL QUANTITY:	<b>650</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Not observed in 207, 209</b>		

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **Blue/White Mix Carpet Mastic**

MATERIAL LOCATION: **Rooms 209a & 209b**

MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	83		
MATERIAL DESCRIPTION:	12" x 12" Pink Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridors		
MATERIAL QUANTITY:	9000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **12" x 12" Pink Vinyl Floor Tile**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors**

MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	84		
MATERIAL DESCRIPTION:	12" x 12" Pink Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridors		
MATERIAL QUANTITY:	9000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **12" x 12" Pink Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors**

MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>85</b>		
MATERIAL DESCRIPTION:	<b>Purple Carpet Adhesive</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 104</b>		
MATERIAL QUANTITY:	<b>2600</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **85**

MATERIAL DESCRIPTION: **Purple Carpet Adhesive**

MATERIAL LOCATION: **Room 104**

MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>86</b>		
MATERIAL DESCRIPTION:	<b>Light Brown Carpet Adhesive</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 212</b>		
MATERIAL QUANTITY:	<b>800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Not observed in 214</b>		

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **86**

MATERIAL DESCRIPTION: **Light Brown Carpet Adhesive**

MATERIAL LOCATION: **Room 212**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>87</b>		
MATERIAL DESCRIPTION:	<b>Blue w/ Red and Orange Carpet Adhesive</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 212, 213</b>		
MATERIAL QUANTITY:	<b>1500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **87**

MATERIAL DESCRIPTION: **Blue w/ Red and Orange Carpet Adhesive**

MATERIAL LOCATION: **Room 212, 213**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>88</b>		
MATERIAL DESCRIPTION:	<b>Chalk Board Adhesive</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Throughout All Classrooms</b>		
MATERIAL QUANTITY:	<b>14200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **Chalk Board Adhesive**

MATERIAL LOCATION: **Throughout All Classrooms**

MATERIAL QUANTITY: **14200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	89		
MATERIAL DESCRIPTION:	Red/Maroon Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallways Trim Border, Stairwells, Hallway Adjacent WomensKitchen, Lunchroom, Kitchen		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **89**

MATERIAL DESCRIPTION: **Red/Maroon Terrazzo**

MATERIAL LOCATION: **Hallways Trim Border, Stairwells, Hallway Adjacent WomensKitchen, Lunchroom, Kitchen**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>8A</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Light Gray Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 216</b>		
MATERIAL QUANTITY:	<b>360</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **8A**

MATERIAL DESCRIPTION: **12" x 12" Light Gray Floor Tile Mastic**

MATERIAL LOCATION: **Room 216**

MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **Brown Linoleum**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Gym Office**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **Brown Linoleum**

MATERIAL LOCATION: **2nd Floor Gym Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **Blue Carpet Adhesive**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 122**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **Blue Carpet Adhesive**

MATERIAL LOCATION: **Room 122**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 91  
MATERIAL DESCRIPTION: 12" x 12" Light Brown w/ White Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 215

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **91**

MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ White Floor Tile**

MATERIAL LOCATION: **Room 215**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/ White Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 215**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile w/ White Mastic**

MATERIAL LOCATION: **Room 215**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>93</b>		
MATERIAL DESCRIPTION:	<b>Light Blue w/ Blue Specks Linoleum</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 304, 308</b>		
MATERIAL QUANTITY:	<b>2150</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **93**

MATERIAL DESCRIPTION: **Light Blue w/ Blue Specks Linoleum**

MATERIAL LOCATION: **Rooms 304, 308**

MATERIAL QUANTITY: **2150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	94		
MATERIAL DESCRIPTION:	Light Blue w/ Blue Specks Linoleum Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 304, 308		
MATERIAL QUANTITY:	2150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **94**

MATERIAL DESCRIPTION: **Light Blue w/ Blue Specks Linoleum Mastic**

MATERIAL LOCATION: **Rooms 304, 308**

MATERIAL QUANTITY: **2150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>95</b>		
MATERIAL DESCRIPTION:	<b>Tan Linoleum</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 215</b>		
MATERIAL QUANTITY:	<b>650</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53111** BULDING ID: **1460**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Manley Academy** REVIEW DATE: **8/8/2025**

ADDRESS: **2935 W. Polk** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **95**

MATERIAL DESCRIPTION: **Tan Linoleum**

MATERIAL LOCATION: **Room 215**

MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>96</b>		
MATERIAL DESCRIPTION:	<b>Tan Linoleum Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 215</b>		
MATERIAL QUANTITY:	<b>650</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53111** BULDING ID: **1460**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Manley Academy** REVIEW DATE: **8/8/2025**

ADDRESS: **2935 W. Polk** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **96**

MATERIAL DESCRIPTION: **Tan Linoleum Mastic**

MATERIAL LOCATION: **Room 215**

MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>97</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" White w/ Green Specks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Boys Gym Office</b>		
MATERIAL QUANTITY:	<b>180</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **97**

MATERIAL DESCRIPTION: **12" x 12" White w/ Green Specks Floor Tile**

MATERIAL LOCATION: **Boys Gym Office**

MATERIAL QUANTITY: **180** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	98		
MATERIAL DESCRIPTION:	12" x 12" White w/ Green Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boys Gym Office		
MATERIAL QUANTITY:	180	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **98**

MATERIAL DESCRIPTION: **12" x 12" White w/ Green Specks Floor Tile Mastic**

MATERIAL LOCATION: **Boys Gym Office**

MATERIAL QUANTITY: **180** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>99</b>		
MATERIAL DESCRIPTION:	<b>Burgandy Carpet w/ Blue and Orange Specks Adhesive</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 209b, 201</b>		
MATERIAL QUANTITY:	<b>1600</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **99**

MATERIAL DESCRIPTION: **Burgandy Carpet w/ Blue and Orange Specks Adhesive**

MATERIAL LOCATION: **Room 209b, 201**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9A**

MATERIAL DESCRIPTION: **Brown Linoleum Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Gym Office**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **9A**

MATERIAL DESCRIPTION: **Brown Linoleum Mastic**

MATERIAL LOCATION: **2nd Floor Gym Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUILDING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: A

MATERIAL DESCRIPTION: Black Linoleum Flooring

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Girls Locker Room Laundry Area

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Black Linoleum Flooring**

MATERIAL LOCATION: **Girls Locker Room Laundry Area**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: A-1

MATERIAL DESCRIPTION: Black Linoleum Flooring-Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Girls Locker Room Laundry Area

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **A-1**

MATERIAL DESCRIPTION: **Black Linoleum Flooring-Mastic**

MATERIAL LOCATION: **Girls Locker Room Laundry Area**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **08/08/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Dionne Carey Walker</b>		
SCHOOL NAME:	<b>Manley Academy</b>	INSPECTION DATE:	<b>7/10/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>HA-1000</b>		
MATERIAL DESCRIPTION:	<b>2' x 4' White Plaing Ceiling Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Culinary Classroom 207, 211</b>		
MATERIAL QUANTITY:	<b>2000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **07/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUIDLING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **HA-1000**

MATERIAL DESCRIPTION: **2' x 4' White Plaing Ceiling Tile**

MATERIAL LOCATION: **Culinary Classroom 207, 211**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53111	BUIDLING ID:	1460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Dionne Carey Walker		
SCHOOL NAME:	Manley Academy	INSPECTION DATE:	7/10/2025		
ADDRESS:	2935 W. Polk	IDPH LICENSE NO:	100-09969		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	HA-1001		
MATERIAL DESCRIPTION:	2' x 4' White Fissures and Pinholes Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Damaged or significantly damaged friable misc. ACBM		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Encapsulate		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 215		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Missing ceiling tile in Room 215		

Inspector's Signature:



Date: 07/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>53111</b>	BUILDING ID:	<b>1460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Manley Academy</b>	REVIEW DATE:	<b>8/8/2025</b>		
ADDRESS:	<b>2935 W. Polk</b>	IDPH LICENSE NO:	<b>100-09969</b>		

---

HOMOGENEOUS AREA: **HA-1001**

MATERIAL DESCRIPTION: **2' x 4' White Fissures and Pinholes Ceiling Tile**

MATERIAL LOCATION: **Room 215**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Encapsulate**

Comments:

Management Planner's Signature:  Date: 08/08/2025

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2025 AHERA REINSPECTION***

## APPENDIX B

---

### Inspector and Management Planner Licenses



**OCCUPATIONAL TRAINING & SUPPLY, INC. 2024**  
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

## Asbestos Abatement Supervisor Refresher

Occupational Training & Supply, Inc. certifies that

**Dionne L.C. Walker**

has successfully completed the Asbestos Abatement Supervisor Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 10/14/2024

Exam Date: 10/14/2024

Expiration Date: 10/14/2025

Certificate Number: ASR2410142781

Course Credit Hours: ASR 8 Hours

*Kristina Miczek*

Kristina Miczek, Training Manager

# Dionne Walker

---

Asbestos Project Manager, Illinois Licensed Building Inspector, Air Sampling Professional



**ASBESTOS  
PROFESSIONAL  
LICENSE**

ID NUMBER  
100 - 09969

ISSUED  
4/28/2025

EXPIRES  
05/15/2026

**DIONNE L CAREY WALKER**  
211 SOMERSET DRIVE  
STREAMWOOD, IL 60107  
Environmental Health



**ENDORSEMENTS**

INSPECTOR

**TC EXPIRES**

10/11/2025

PROJECT MANAGER  
AIR SAMPLING PROFESSIONAL

10/14/2025

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.





OCCUPATIONAL TRAINING & SUPPLY, INC. **2024**  
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

---

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Michael Serio**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/18/2024

Exam Date: 11/18/2024

Expiration Date: 11/18/2025

Certificate Number: MPR2411183328

Course Credit Hours: MPR 4 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

---

Kristina Miczek, Training Manager

## APPENDIX C

---

### **Laboratory Accreditations**

## APPENDIX D

---

### Laboratory Results

## APPENDIX E

---

### Chain of Custody Forms

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>	Loc	Localized
	Dist	Distributed