

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0044
SCHOOL NAME: Tilden Academy
ADDRESS OF SCHOOL: 4747 S. Union
CITY: Chicago, IL, 60609

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 9/14/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 3/21/2025 ENROLLMENT 227
IDPH INSPECTOR LICENSE NUMBER: 100-20411
IDPH LICENSED INSPECTOR NAME (Please Print): Benyamen Maradkel
IDPH MP LICENSE NUMBER: 100-18488
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Mike Serio

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 4/18/2025

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Tilden Academy

4747 S. Union
Chicago, IL, 60609

Unit: 53121
Building ID: 1590

IDPH ID Number: 14-016-2990-0044

REPORT DATE:
Friday, April 18, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

04/18/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 53121 Region: 04 IDPH ID: 14-016-2990-0044

School: Tilden Academy Building ID: 1590

Address: 4747 S. Union

Chicago, IL, 60609

Building Contact: Delaney, Matthew Contact Phone: 7733690412

Current Building Owners: Chicago Public Schools

Reinspection Date: 3/21/2025

Review Date: 04/18/2025

Inspector: Benyamen Maradkel

Inspector IDPH License: 100-20411

Management Planner: Mike Serio

Management Planner IDPH License: 100-18488

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Mike Serio
100-18488

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: April 18, 2025

RE: Tilden Academy, Unit 53121
4747 S. Union
Chicago, IL, 60609

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Tilden Academy , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Tilden Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Tilden Academy Unit: 53121 Region: 04
Address: 4747 S. Union Chicago, IL, 60609
IDPH ID: 14-016-2990-0044 Building ID: 1590
Contact: Delaney, Matthew Phone: 7733690412

2. Description of Facility

Original Construction: 1905 Additional Construction:
Total Square Footage: 328514 No of Floors: 3
Current Occupancy: 227

3. LEA Designated Person

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Benyamen Maradkel

Inspector IDPH license # 100-20411
Reinspection Date: 3/21/2025

John A. [Signature]

Signature: _____
Date: 3/21/2025

6. Management Planner

Management Planner Name: Mike Serio

Management Planner IDPH license # 100-18488

Signature: Michael J. Senn

Date: 04/18/2025

7. Review Date: 04/18/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: Richard J. Schlegel

Signature:

Date: 4/18/2025

Name: Richard J. Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Tilden Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1590:

1	2' x 4' Ceiling Tile
10	12" x 12" Vinyl Floor Tile, Yellowish Green
103	4" Tan Baseboard w/ Adhesive
107	Black Linoleum
10A	12" x 12" Vinyl Floor Tile, Yellowish Green Mastic
14	12" x 12" Vinyl Floor Tile, Black
15	12" x 12" Vinyl Floor Tile, Blue
16	12" x 12" Vinyl Floor Tile, Mottled Brown
18	12" x 12" Vinyl Floor Tile, Beige Mottled

18A	12" x 12" Vinyl Floor Tile, Beige Mottled Mastic
19	12" x 12" Mottled Gray Vinyl Floor Tile
19A	12" x 12" Mottled Gray Vinyl Floor Tile Mastic
21A	9" x 9" Vinyl Floor Tile, Tan w/ Dark Streaks Mastic
23	Bluish Gray Linoleum
28	Wall Board
35	12" x 12" Dark Blue Vinyl Floor Tile
4	12" x 12" Vinyl Floor Tile, Dark Brown
41	12" x 12" Tan w/ Dark Beige Specks Floor Tile
42	12" x 12" Tan w/ Dark Beige Specks Floor Tile Mastic
43	12" x 12" Dark Gray w/ White Specks Vinyl Floor Tile
44	12" x 12" Dark Gray w/ White Specks Vinyl Floor Tile Mastic
45	12" x 12" Battleship Gray w/ White Specks Floor Tile
47	12" x 12" Beige w/ Dark Beige & White Specks Floor Tile
51	12" x 12" Olive Green w/ Dark Green & Whitet Specks Floor Tile
52	12" x 12" Olive Grn w/ Dark Grn & Whitet Specks Floor Tile Mastic
61	Lab Table Tops
65	Black Carpet Mastic
68	Foam Type Insulation
69	12" x 12" White Floor Tile w/ Cream Streak

7	Brown Linoleum
9	12" x 12" Vinyl Floor Tile, Off-White Mottled
E	Boiler Gaskets
F	Aircell Pipe Insulation
M	Tan Carpet
N	Tan Carpet Mastic

B. The following new homogenous areas have been identified for Building 1590:

103	4" Tan Baseboard w/ Adhesive
104	1" x1" Tan & Brown Multicolor Ceramic Floor Tile & Grout
105	4" Gray Baseboard w/ Adhesive
106	4" Black Baseboard w/ Adhesive
107	Black Linoleum
108	12" x 12" Black w/ White Specks Floor Tile
109	12" x 12" Black w/ White Specks Floor Tile Mastic
110	Black & Gray Terrazzo
111	Red & Brown Terrazzo

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

103	4" Tan Baseboard w/ Adhesive
104	1" x1" Tan & Brown Multicolor Ceramic Floor Tile & Grout
105	4" Gray Baseboard w/ Adhesive
106	4" Black Baseboard w/ Adhesive
107	Black Linoleum
108	12" x 12" Black w/ White Specks Floor Tile
109	12" x 12" Black w/ White Specks Floor Tile Mastic
11	12" x 12" Vinyl Floor Tile, Off-White w/ Tan Specks
110	Black & Gray Terrazzo
111	Red & Brown Terrazzo
11A	12" x 12" Vinyl Floor Tile, Off-White w/ Tan Specks Mastic
14	12" x 12" Vinyl Floor Tile, Black
15	12" x 12" Vinyl Floor Tile, Blue
16	12" x 12" Vinyl Floor Tile, Mottled Brown
16A	12" x 12" Vinyl Floor Tile, Mottled Brown Mastic
17	12" x 12" Vinyl Floor Tile, Mottled Tan
17A	12" x 12" Vinyl Floor Tile, Mottled Tan Mastic
18	12" x 12" Vinyl Floor Tile, Beige Mottled
18A	12" x 12" Vinyl Floor Tile, Beige Mottled Mastic
19	12" x 12" Mottled Gray Vinyl Floor Tile
19A	12" x 12" Mottled Gray Vinyl Floor Tile Mastic
21	9" x 9" Vinyl Floor Tile, Tan w/ Dark Streaks
21A	9" x 9" Vinyl Floor Tile, Tan w/ Dark Streaks Mastic
22	9" x 9" Vinyl Floor Tile, Brown
22A	9" x 9" Vinyl Floor Tile, Brown Mastic
26	Brick Mortar, ROTC Building - Non-AHERA
31	12" x 12" Brown w/ White Specks Vinyl Floor Tile
32	12" x 12" Brown w/ White Specks Vinyl Floor Tile Mastic
33	12" x 12" Yellow w/ White Specks Vinyl Floor Tile
34	12" x 12" Yellow w/ White Specks Vinyl Floor Tile Mastic
35	12" x 12" Dark Blue Vinyl Floor Tile
36	12" x 12" Dark Blue Vinyl Floor Tile Mastic
37	12" x 12" Light Blue Vinyl Floor Tile
38	12" x 12" Light Blue Vinyl Floor Tile Mastic
39	12" x 12" Yellow w/ White Streaks Vinyl Floor Tile
40	12" x 12" Yellow w/ White Streaks Vinyl Floor Tile

	Mastic
41	12" x 12" Tan w/ Dark Beige Specks Floor Tile
42	12" x 12" Tan w/ Dark Beige Specks Floor Tile
	Mastic
43	12" x 12" Dark Gray w/ White Specks Vinyl Floor Tile
44	12" x 12" Dark Gray w/ White Specks Vinyl Floor Tile Mastic
45	12" x 12" Battleship Gray w/ White Specks Floor Tile
46	12" x 12" Battleship Gray w/ White Specks Floor Tile Mastic
47	12" x 12" Beige w/ Dark Beige & White Specks Floor Tile
48	12" x 12" Beige w/ Dark Beige & Whitet Specks Floor Tile Mastic
49	12" x 12" Beige w/ Dark Beige & Whitet Specks Floor Tile Mastic
50	12" x 12" Baby Blue w/ Dark Blue Specks Floor Tile Mastic
51	12" x 12" Olive Green w/ Dark Green & Whitet Specks Floor Tile
52	12" x 12" Olive Grn w/ Dark Grn & Whitet Specks Floor Tile Mastic
53	Boiler Breeching
54	Two Tanks
60	Blue Linoleum and Associated Adhesive
62	Gray Rubber Flax Adhesive
63	Green Carpet Adhesive
64	Multicolored Carpet Adhesive
65	Black Carpet Mastic
67	12" x 12" White w/ Dark Gray Specks Floor Tile
68	Foam Type Insulation
69	12" x 12" White Floor Tile w/ Cream Streak
70	Wood Flooring
71	2" x 2" White Ceramic Tile
72	2" x 2" White Ceramic Tile Mastic
73	Blue Carpet Adhesive
74	12" x 12" Blue, Gray, White Vinyl Floor Tile
75	12" x 12" Blue, Gray, White Vinyl Floor Tile Mastic
HA-100	1' x 1' White Plain Ceiling Tile
HA-101	Glue For 1' x 1' White Plain Ceiling Tile
HA-102	Boiler Breeching Insulation
M	Tan Carpet
N	Tan Carpet Mastic

The following areas were deemed to be inaccessible:

103	4" Tan Baseboard w/ Adhesive
105	4" Gray Baseboard w/ Adhesive
106	4" Black Baseboard w/ Adhesive
109	12" x 12" Black w/ White Specks Floor Tile Mastic
10A	12" x 12" Vinyl Floor Tile, Yellowish Green Mastic
11A	12" x 12" Vinyl Floor Tile, Off-White w/ Tan Specks Mastic
12A	12" x 12" Vinyl Floor Tile, Off-White w/ Gray Specks Mastic
15A	12" x 12" Vinyl Floor Tile, Blue Mastic
16A	12" x 12" Vinyl Floor Tile, Mottled Brown Mastic
17A	12" x 12" Vinyl Floor Tile, Mottled Tan Mastic
18A	12" x 12" Vinyl Floor Tile, Beige Mottled Mastic
20A	12" x 12" Vinyl Floor Tile, Beige Mastic
21A	9" x 9" Vinyl Floor Tile, Tan w/ Dark Streaks Mastic
27A	9" x 9" Sand Floor Tile Mastic
34	12" x 12" Yellow w/ White Specks Vinyl Floor Tile Mastic
36	12" x 12" Dark Blue Vinyl Floor Tile Mastic
40	12" x 12" Yellow w/ White Streaks Vinyl Floor Tile Mastic
46	12" x 12" Battleship Gray w/ White Specks Floor Tile Mastic
4A	12" x 12" Vinyl Floor Tile, Dark Brown Mastic
52	12" x 12" Olive Grn w/ Dark Grn & Whitet Specks Floor Tile Mastic
5A	9" x 9" Vinyl Floor Tile, Tan Mastic (Checkered)
62	Gray Rubber Flax Adhesive
63	Green Carpet Adhesive
64	Multicolored Carpet Adhesive
9A	12" x 12" Vinyl Floor Tile, Off-White Mottled Mastic
E	Boiler Gaskets
F	Aircell Pipe Insulation
HA-101	Glue For 1' x 1' White Plain Ceiling Tile
N	Tan Carpet Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Benyamen Maradkel, IDPH License # 100-20411. The Management Plan was updated by Mike Serio, IDPH License # 100-18488. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Tilden Academy Building 1590 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Tilden Academy **Unit** 53121 **Building ID** 1590
Address 4747 S. Union **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	2' x 4' Ceiling Tile			4th Hall, 3rd Hall, 003, 228, 438, 439, 227, 433, 436, 437, 438, 440, 323, 320, 314, 313, 315, 311, Throughout Classrooms, 403, 411	NO_ACBM	MISC					Yes			
10	12" x 12" Vinyl Floor Tile, Yellowish Green	400	SF	1st Floor North Corridor	CHR	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
103	4" Tan Baseboard w/ Adhesive	40	LF	Room 401	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
104	1" x1" Tan & Brown Multicolor Ceramic Floor Tile & Grout	300	SF	Girls Locker Room Shower	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
105	4" Gray Baseboard w/ Adhesive	200	LF	Room 403, 405	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
106	4" Black Baseboard w/ Adhesive	100	LF	Room 407	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
107	Black Linoleum	1,500	SF	4th, 3rd, 2nd Floor Girls Restroom	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
108	12" x 12" Black w/ White Specks Floor Tile	700	SF	Boys Locker Room	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
109	12" x 12" Black w/ White Specks Floor Tile Mastic	700	SF	Boys Locker Room	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
10A	12" x 12" Vinyl Floor Tile, Yellowish Green Mastic	400	SF	1st Floor Corridor	CHR	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
11	12" x 12" Vinyl Floor Tile, Off-White w/ Tan Specks	7,500	SF	Rooms 227, 317, 420, 425, 429, 431, 435, 207, 209, 321, 330, 332, 306, 305, 325, 327, 329, 304, 238, 202, Main Office, 207, 209	ASSUMED	MISC	N	DIST	120	SF	No	ACBM with potential for significant damage	5	HIGH
110	Black & Gray Terrazzo	10,000	SF	Main Entrance Corridors	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
111	Red & Brown Terrazzo	20,000	SF	4th, 3rd and 2nd Floor Corridors and Stairwells	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
11A	12" x 12" Vinyl Floor Tile, Off-White w/ Tan Specks Mastic	7,500	SF	Rooms 227, 317, 420, 425, 429, 431, 433, 207, 209, 321, 330, 332, 306, 305, 325, 327, 329, 304, 238, 202, Main	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Tilden Academy **Unit** 53121 **Building ID** 1590
Address 4747 S. Union **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Office, 207, 209										
12	12" x 12" Vinyl Floor Tile, Off-White w/ Gray Specks	39,000	SF	1st, 2nd, 3rd and 4th Floor Classrooms 436, 438 201, 228, 426, 437 (patches), 211	CHR	MISC	N	DIST	45	SF	No	ACBM with potential for significant damage	5	LOW
12A	12" x 12" Vinyl Floor Tile, Off-White w/ Gray Specks Mastic	39,000	SF	1st, 2nd, 3rd and 4th Floor Classrooms, 436, 438, 426, 437 (patches), 211	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
13	9" x 9" Vinyl Floor Tile, Beige w/ Dark Specks	2,800	SF	2nd and 3rd Floor N/E Hallways	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
13A	9" x 9" Vinyl Floor Tile, Beige w/ Dark Specks Mastic	2,800	SF	2nd and 3rd Floor N/E Hallways	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
14	12" x 12" Vinyl Floor Tile, Black	4,000	SF	Kitchen and Lunchroom, Gym Locker Room, Gym Teacher Washroom	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
14A	12" x 12" Vinyl Floor Tile, Black Mastic	3,400	SF	Kitchen and Lunchroom, Gym Locker Room, Gym Teachers' Washroom	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
15	12" x 12" Vinyl Floor Tile, Blue	900	SF	Room 437, 331	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
15A	12" x 12" Vinyl Floor Tile, Blue Mastic	2,800	SF	Room 437, 331	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
16	12" x 12" Vinyl Floor Tile, Mottled Brown	900	SF	Room 213	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
16A	12" x 12" Vinyl Floor Tile, Mottled Brown Mastic	900	SF	Room 213	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
17	12" x 12" Vinyl Floor Tile, Mottled Tan	2,025	SF	Room 213, 416, main office, 217, 221	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
17A	12" x 12" Vinyl Floor Tile, Mottled Tan Mastic	2,025	SF	Room 213, 416, main office, 217, 221	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
18	12" x 12" Vinyl Floor Tile, Beige Mottled	1,100	SF	Room 334, 331 (Beneath New Tile), main office storage room	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		HIGH
18A	12" x 12" Vinyl Floor Tile, Beige Mottled Mastic	1,100	SF	Room 334, 331 (Beneath New Tile), main office storage room	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Tilden Academy **Unit** 53121 **Building ID** 1590
Address 4747 S. Union **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
19	12" x 12" Mottled Gray Vinyl Floor Tile			Room 440, 239a Bathroom	ASSUMED	MISC					Yes			
19A	12" x 12" Mottled Gray Vinyl Floor Tile Mastic			Room 440, 239a Bathroom	ASSUMED	MISC					Yes			
2	1' x 1' Ceiling Tile			Room 223	NO_ACBM	MISC					No			
20	12" x 12" Vinyl Floor Tile, Beige	900	SF	Rooms 418 408, 225	CHR	MISC	N	LOC	30	SF	No	ACBM with potential for significant damage	3	LOW
20A	12" x 12" Vinyl Floor Tile, Beige Mastic	900	SF	Rooms 418	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
21	9" x 9" Vinyl Floor Tile, Tan w/ Dark Streaks	4,500	SF	Room 332 407 303 301 102	ASSUMED	MISC	N	LOC	135	SF	No	ACBM with potential for significant damage	5	MODERATE
21A	9" x 9" Vinyl Floor Tile, Tan w/ Dark Streaks Mastic	4,500	SF	Room 332 407 303 301 102	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		MODERATE
22	9" x 9" Vinyl Floor Tile, Brown			Rotc Building, On Table	ASSUMED	MISC					No			
22A	9" x 9" Vinyl Floor Tile, Brown Mastic			Rotc Building, On Table	ASSUMED	MISC					No			
23	Bluish Gray Linoleum			3rd Floor Gym	NO_ACBM	MISC					Yes			
23A	Bluish Gray Linoleum Mastic			3rd Floor Gym	NO_ACBM	MISC					No			
24	Brick Mortar - Non-AHERA			Exterior	NO_ACBM	MISC					No			
25	Limestone Mortar - Non-AHERA			Exterior	NO_ACBM	MISC					No			
26	Brick Mortar, ROTC Building - Non-AHERA			ROTC Building Exterior	ASSUMED	MISC					No			
27	9" x 9" Sand Floor Tile	3,200	SF	Rooms 301, 303, 102, 407, 409, 102, 305 (Beneath New Tile)	CHR	MISC	N	LOC	35	SF	No	ACBM with potential for significant damage	5	LOW
27A	9" x 9" Sand Floor Tile Mastic	3,700	SF	Rooms 301, 303, 102, 407, 409, 102, 305 (Beneath New Tile)	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
28	Wall Board			Rooms 226 and 228, Electrical Foreman's Room	NO_ACBM	MISC					Yes			
29	Stage Curtains			Auditorium	NO_ACBM	MISC					No			
3	Plaster			Throughout	NO_ACBM	SURFACE					No			
30	Wire Insulation	1,000	LF	Throughout	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
31	12" x 12" Brown w/ White Specks Vinyl Floor Tile	100	SF	4th Floor Corridor North E/W Corridor by Stairwell 7, 3rd Floor North E/W Corridor by Stairwell 7	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Tilden Academy **Unit** 53121 **Building ID** 1590
Address 4747 S. Union **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
32	12" x 12" Brown w/ White Specks Vinyl Floor Tile Mastic	100	SF	4th Floor Corridor North E/W Corridor by Stairwell 7, 3rd Floor North E/W Corridor by Stairwell 7	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
33	12" x 12" Yellow w/ White Specks Vinyl Floor Tile	1,800	SF	Room 439, 120, 113, 115	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
34	12" x 12" Yellow w/ White Specks Vinyl Floor Tile Mastic	1,800	SF	Room 439, 120, 113, 115	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
35	12" x 12" Dark Blue Vinyl Floor Tile	3,500	SF	Room 120, 121, 331, and 333	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
36	12" x 12" Dark Blue Vinyl Floor Tile Mastic	3,500	SF	Room 120, 121, 331, and 333	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
37	12" x 12" Light Blue Vinyl Floor Tile	2,000	SF	Room 205, 317, 437, 117, 425	ASSUMED	MISC	N	LOC	17	SF	No	ACBM with potential for significant damage	5	LOW
38	12" x 12" Light Blue Vinyl Floor Tile Mastic	1,700	SF	Room 103, 117, 121, 205, 305, 335, 425	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
39	12" x 12" Yellow w/ White Streaks Vinyl Floor Tile	3,500	SF	Rooms 401, 115, 113	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
4	12" x 12" Vinyl Floor Tile, Dark Brown	375	SF	Engineer's Office	CHR	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
40	12" x 12" Yellow w/ White Streaks Vinyl Floor Tile Mastic	3,500	SF	Rooms 401, 115, 113	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
41	12" x 12" Tan w/ Dark Beige Specks Floor Tile			Rooms 329, 331 421	ASSUMED	MISC					Yes			
42	12" x 12" Tan w/ Dark Beige Specks Floor Tile Mastic			Rooms 329, 331, 421	ASSUMED	MISC					Yes			
43	12" x 12" Dark Gray w/ White Specks Vinyl Floor Tile	600	SF	Room 223 , Wood Closet	ASSUMED	MISC	N	LOC	60	SF	Yes	ACBM with the potential for damage	5	HIGH
44	12" x 12" Dark Gray w/ White Specks Vinyl Floor Tile Mastic	600	SF	Room 223	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		HIGH
45	12" x 12" Battleship Gray w/ White Specks Floor Tile	5,700	SF	Room 214, 215, 218, 220, 222, 226, 228, 234, 236, 239, 235	ASSUMED	MISC	N	LOC	5	SF	Yes	ACBM with the potential for damage	5	LOW
46	12" x 12" Battleship Gray w/ White Specks Floor Tile Mastic	5,700	SF	Room 214, 215, 218, 220, 222, 226, 228, 234, 236, 235	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
47	12" x 12" Beige w/ Dark Beige & White Specks Floor Tile	1,000	SF	Room 207, and 209	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
48	12" x 12" Beige w/ Dark Beige & Whitet Specks Floor Tile Mastic	1,000	SF	Room 207, and 209	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
49	12" x 12" Beige w/ Dark Beige & Whitet Specks Floor Tile Mastic	1,000	SF	Room 207, and 209	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Tilden Academy **Unit** 53121 **Building ID** 1590
Address 4747 S. Union **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
4A	12" x 12" Vinyl Floor Tile, Dark Brown Mastic	375	SF	Engineer's Office	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
5	9" x 9" Vinyl Floor Tile, Tan (Checkered)	11,000	SF	1st, 2nd and 3rd Floor Hallways	CHR	MISC	N	DIST	70	SF	No	ACBM with potential for significant damage	5	MODERATE
50	12" x 12" Baby Blue w/ Dark Blue Specks Floor Tile Mastic	500	SF	Room 205	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
51	12" x 12" Olive Green w/ Dark Green & White Specks Floor Tile	1,000	SF	1st Floor North E/W Corridor	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
52	12" x 12" Olive Grn w/ Dark Grn & Whitet Specks Floor Tile Mastic	1,000	SF	1st Floor North E/W Corridor	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
53	Boiler Breeching	900	SF	Boiler Room	ASSUMED	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
54	Two Tanks	900	SF	Boiler Room	ASSUMED	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
5A	9" x 9" Vinyl Floor Tile, Tan Mastic (Checkered)	11,000	SF	1st, 2nd and 3rd Floor Hallways	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
6	9" x 9" Vinyl Floor Tile, Brown (Checkered)	11,000	SF	1st, 2nd, 3rd and 4th Floor Hallways	CHR	MISC	N	DIST	70	SF	No	ACBM with potential for significant damage	5	MODERATE
60	Blue Linoleum and Associated Adhesive			Room 403	ASSUMED	MISC					No			
61	Lab Table Tops			Rooms 301, 303, 401, 403, 405, 407,	NO_ACBM	MISC					Yes			
62	Gray Rubber Flax Adhesive	2,500	SF	Southwest Gym	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
63	Green Carpet Adhesive	2,000	SF	Library, 2nd Floor Lobby	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
64	Multicolored Carpet Adhesive	2,500	SF	Room 320, 323	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
65	Black Carpet Mastic			Room 323	ASSUMED	MISC					Yes			
67	12" x 12" White w/ Dark Gray Specks Floor Tile	350	SF	Room 420 and 219, 413, 415 421 424	ASSUMED	MISC	N	DIST	61	SF	No	ACBM with potential for significant damage	3	LOW
68	Foam Type Insulation	100	LF	1st Floor Hall Outside Maintenance Dept.	ASSUMED	TSI	Y	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
69	12" x 12" White Floor Tile w/ Cream Streak			Office Next WomensMain Office	ASSUMED	MISC					Yes			
6A	9" x 9" Vinyl Floor Tile, Brown Mastic (Checkered)	11,000	SF	1st, 2nd and 3rd Floor Hallways	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
7	Brown Linoleum			425 Hallway	NO_ACBM	MISC					Yes			
70	Wood Flooring	2,000	SF	Northwest Gym, Main Gym, 440, 410, 411, 417, 419	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Tilden Academy **Unit** 53121 **Building ID** 1590
Address 4747 S. Union **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				423, 322, 316, 314, 306a, 239a, 229, Main Office, Main Gym Storage Room, Equipment Room										
71	2" x 2" White Ceramic Tile	600	SF	4th Floor Boys Bathroom in Locker Room, Throughout Washrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
72	2" x 2" White Ceramic Tile Mastic	600	SF	4th Floor Boys Bathroom in Locker Room, Throughout Washrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
73	Blue Carpet Adhesive	1,000	SF	Room 231	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
74	12" x 12" Blue, Gray, White Vinyl Floor Tile	1,500	SF	Rooms 405, 403, 409	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		MODERATE
75	12" x 12" Blue, Gray, White Vinyl Floor Tile Mastic	1,500	SF	Rooms 405, 403, 409	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		MODERATE
7A	Brown Linoleum Mastic			425 Hallway	NO_ACBM	MISC					No			
9	12" x 12" Vinyl Floor Tile, Off-White Mottled	375	SF	Engineer's Office	CHR	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
9A	12" x 12" Vinyl Floor Tile, Off-White Mottled Mastic	375	SF	Engineer's Office	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
A	Water Tank			ABATED	ABATED	TSI								
E	Boiler Gaskets	80	LF	Boiler Room	CHR	MISC	Y	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
F	Aircell Pipe Insulation	5,000	LF	North Boys Bathroom in Basement, Boiler Room, Fan Room 106	CHR	TSI	Y	DIST	25	LF	Yes	Damaged or significantly damaged friable thermal system insulating ACBM	3	MODERATE
G	Fittings Off Aircell Pipe Insulation	45	LF	North Boys' Bathroom in Basement, Boiler Room	CHR	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
HA-100	1' x 1' White Plain Ceiling Tile	1,000	SF	Kitchen	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
HA-101	Glue For 1' x 1' White Plain Ceiling Tile	1,000	SF	Kitchen	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
HA-102	Boiler Breeching Insulation	20	LF	Boiler Room	ASSUMED	TSI	Y	NONE			No	Any remaining friable ACBM or friable		MODERATE

Chicago Public Schools

School Tilden Academy **Unit** 53121 **Building ID** 1590
Address 4747 S. Union **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
L	Fittings Off Fiberglass Pipe Runs	25	LF	Pump Room	CHR	TSI	Y	NONE			No	suspect ACBM		MODERATE
M	Tan Carpet	200	SF	Auditorium	ASSUMED	MISC	N	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
N	Tan Carpet Mastic	200	SF	Auditorium	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW

Chicago Public Schools

School Tilden Academy Unit 53121 Building ID 1590
Address 4747 S. Union Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date <u>3/21/2025</u>
Inspector Name <u>Benyamen Maradkel</u>
<u>100-20411</u> <u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
1	
10	
103	
104	
105	
106	
107	
108	
109	
10A	
11	Damage in Rooms 425, 420, 227, 321 Not observed in 439, 309, MDF Room, 308, 311, 313, 317, 318 319
110	
111	
11A	
12	Damaged in room 230, 203, 211
12A	
13	
13A	
14	
14A	
15	
15A	

Chicago Public Schools

School Tilden Academy **Unit** 53121 **Building ID** 1590
Address 4747 S. Union **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
16	
16A	
17	
17A	
18	Not observed in Room 331
18A	Not observed in Room 331
19	Material not observed - 2025
19A	Material not observed - 2025
2	
20	Damage in 408
20A	
21	Damaged in room 407
21A	
22	Material not observed - 2025
22A	Material not observed - 2025
23	
23A	
24	
25	
26	
27	Damaged in Room 407
27A	
28	
29	
3	1000 SF damage in northwest gym, 2 SF of damage on 4th floor wall across from 407, 3 SF damage in 404
30	
31	
32	

Chicago Public Schools

School Tilden Academy **Unit** 53121 **Building ID** 1590
Address 4747 S. Union **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
33	
34	
35	
36	
37	Damage in 437
38	Not observed 333
39	Not observed in Room 405
4	
40	Not observed in Room 405
41	Material not observed - 2025
42	Material not observed - 2025
43	Damage in 223
44	
45	Damaged in 236, Damaged in 236
46	
47	
48	
49	
4A	
5	Damage in 1st floor corridors throughout
50	
51	
52	
53	
54	
5A	
6	Damage in 1st floor corridors throughout
60	Material not observed - 2025
61	

Chicago Public Schools

School Tilden Academy **Unit** 53121 **Building ID** 1590
Address 4747 S. Union **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
62	
63	
64	
65	Material not observed - 2025
67	Damaged in Rooms 415, 420, 421, 424
68	
69	Material not observed - 2025
6A	
7	
70	
71	
72	
73	
74	
75	
7A	
9	
9A	
A	
E	
F	Damage in: Boiler Room, Fan Room 106
G	
HA-100	
HA-101	
HA-102	
L	
M	
N	

Chicago Public Schools

School Tilden Academy **Unit** 53121 **Building ID** 1590
Address 4747 S. Union **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Table II
Management Planner's Review

Chicago Public Schools

School Tilden Academy

Unit 53121

Building ID 1590

Address 4747 S. Union

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	2' x 4' Ceiling Tile			4th Hall, 3rd Hall, 003, 228, 438, 439, 227, 433, 436, 437, 438, 440, 323, 320, 314, 313, 315, 311, Throughout Classrooms, 403, 411	No ACBM	MISC					
10	12" x 12" Vinyl Floor Tile, Yellowish Green	400	SF	1st Floor North Corridor	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
103	4" Tan Baseboard w/ Adhesive	40	LF	Room 401	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
104	1" x1" Tan & Brown Multicolor Ceramic Floor Tile & Grout	300	SF	Girls Locker Room Shower	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
105	4" Gray Baseboard w/ Adhesive	200	LF	Room 403, 405	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
106	4" Black Baseboard w/ Adhesive	100	LF	Room 407	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
107	Black Linoleum	1,500	SF	4th, 3rd, 2nd Floor Girls Restroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
108	12" x 12" Black w/ White Specks Floor Tile	700	SF	Boys Locker Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
109	12" x 12" Black w/ White Specks Floor Tile Mastic	700	SF	Boys Locker Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
10A	12" x 12" Vinyl Floor Tile, Yellowish Green Mastic	400	SF	1st Floor Corridor	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
11	12" x 12" Vinyl Floor Tile, Off-White w/ Tan Specks	7,500	SF	Rooms 227, 317, 420, 425, 429, 431, 433, 207, 209, 321, 330, 332, 306, 305, 325, 327, 329, 304, 238, 202, Main Office, 207, 209	Assumed	MISC	No	120	SF	5 ACBM with potential for significant damage	Remove
110	Black & Gray Terrazzo	10,000	SF	Main Entrance Corridors	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
111	Red & Brown Terrazzo	20,000	SF	4th, 3rd and 2nd Floor Corridors and Stairwells	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
11A	12" x 12" Vinyl Floor Tile, Off-White w/ Tan Specks Mastic	7,500	SF	Rooms 227, 317, 420, 425, 429, 431, 433, 207, 209, 321, 330, 332, 306, 305, 325, 327, 329, 304, 238, 202, Main Office, 207, 209	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
12	12" x 12" Vinyl Floor Tile, Off-White w/ Gray Specks	39,000	SF	1st, 2nd, 3rd and 4th Floor Classrooms 436, 438 201, 228, 426, 437 (patches), 211	Chrysotile	MISC	No	45	SF	5 ACBM with potential for significant damage	Remove
12A	12" x 12" Vinyl Floor Tile, Off-White w/ Gray Specks Mastic	39,000	SF	1st, 2nd, 3rd and 4th Floor Classrooms, 436, 438, 426, 437 (patches), 211	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
13	9" x 9" Vinyl Floor Tile, Beige w/ Dark Specks	2,800	SF	2nd and 3rd Floor N/E Hallways	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
13A	9" x 9" Vinyl Floor Tile, Beige w/ Dark Specks Mastic	2,800	SF	2nd and 3rd Floor N/E Hallways	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
14	12" x 12" Vinyl Floor Tile, Black	4,000	SF	Kitchen and Lunchroom, Gym Locker Room, Gym Teacher Washroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
14A	12" x 12" Vinyl Floor Tile, Black Mastic	3,400	SF	Kitchen and Lunchroom, Gym Locker	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Tilden Academy

Unit 53121

Building ID 1590

Address 4747 S. Union

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Room, Gym Teachers' Washroom							
15	12" x 12" Vinyl Floor Tile, Blue	900	SF	Room 437, 331	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
15A	12" x 12" Vinyl Floor Tile, Blue Mastic	2,800	SF	Room 437, 331	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
16	12" x 12" Vinyl Floor Tile, Mottled Brown	900	SF	Room 213	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
16A	12" x 12" Vinyl Floor Tile, Mottled Brown Mastic	900	SF	Room 213	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12" x 12" Vinyl Floor Tile, Mottled Tan	2,025	SF	Room 213, 416, main office, 217, 221	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
17A	12" x 12" Vinyl Floor Tile, Mottled Tan Mastic	2,025	SF	Room 213, 416, main office, 217, 221	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12" x 12" Vinyl Floor Tile, Beige Mottled	1,100	SF	Room 334, 331 (Beneath New Tile), main office storage room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
18A	12" x 12" Vinyl Floor Tile, Beige Mottled Mastic	1,100	SF	Room 334, 331 (Beneath New Tile), main office storage room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12" x 12" Mottled Gray Vinyl Floor Tile			Room 440, 239a Bathroom	Assumed	MISC					
19A	12" x 12" Mottled Gray Vinyl Floor Tile Mastic			Room 440, 239a Bathroom	Assumed	MISC					
2	1' x 1' Ceiling Tile			Room 223	No ACBM	MISC					
20	12" x 12" Vinyl Floor Tile, Beige	900	SF	Rooms 418 408, 225	Chrysotile	MISC	No	30	SF	5 ACBM with potential for significant damage	Remove
20A	12" x 12" Vinyl Floor Tile, Beige Mastic	900	SF	Rooms 418	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
21	9" x 9" Vinyl Floor Tile, Tan w/ Dark Streaks	4,500	SF	Room 332 407 303 301 102	Assumed	MISC	No	135	SF	5 ACBM with potential for significant damage	Remove
21A	9" x 9" Vinyl Floor Tile, Tan w/ Dark Streaks Mastic	4,500	SF	Room 332 407 303 301 102	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
22	9" x 9" Vinyl Floor Tile, Brown			Rotc Building, On Table	Assumed	MISC					
22A	9" x 9" Vinyl Floor Tile, Brown Mastic			Rotc Building, On Table	Assumed	MISC					
23	Bluish Gray Linoleum			3rd Floor Gym	No ACBM	MISC					
23A	Bluish Gray Linoleum Mastic			3rd Floor Gym	No ACBM	MISC					
24	Brick Mortar - Non-AHERA			Exterior	No ACBM	MISC					
25	Limestone Mortar - Non-AHERA			Exterior	No ACBM	MISC					
26	Brick Mortar, ROTC Building - Non-AHERA			ROTC Building Exterior	Assumed	MISC					
27	9" x 9" Sand Floor Tile	3,200	SF	Rooms 301, 303, 102, 407, 409, 102, 305 (Beneath New Tile)	Chrysotile	MISC	No	35	SF	5 ACBM with potential for significant damage	Remove
27A	9" x 9" Sand Floor Tile Mastic	3,700	SF	Rooms 301, 303, 102, 407, 409, 102, 305 (Beneath New Tile)	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Wall Board			Rooms 226 and 228, Electrical Foreman's Room	No ACBM	MISC					
29	Stage Curtains			Auditorium	No ACBM	MISC					
3	Plaster			Throughout	No ACBM	SURFACE					

Chicago Public Schools

School Tilden Academy

Unit 53121

Building ID 1590

Address 4747 S. Union

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
30	Wire Insulation	1,000	LF	Throughout	Chrysotile	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
31	12" x 12" Brown w/ White Specks Vinyl Floor Tile	100	SF	4th Floor Corridor North E/W Corridor by Stairwell 7, 3rd Floor North E/W Corridor by Stairwell 7	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
32	12" x 12" Brown w/ White Specks Vinyl Floor Tile Mastic	100	SF	4th Floor Corridor North E/W Corridor by Stairwell 7, 3rd Floor North E/W Corridor by Stairwell 7	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
33	12" x 12" Yellow w/ White Specks Vinyl Floor Tile	1,800	SF	Room 439, 120, 113, 115	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
34	12" x 12" Yellow w/ White Specks Vinyl Floor Tile Mastic	1,800	SF	Room 439, 120, 113, 115	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
35	12" x 12" Dark Blue Vinyl Floor Tile	3,500	SF	Room 120, 121, 331, and 333	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12" x 12" Dark Blue Vinyl Floor Tile Mastic	3,500	SF	Room 120, 121, 331, and 333	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12" x 12" Light Blue Vinyl Floor Tile	2,000	SF	Room 205, 317, 437, 117, 425	Assumed	MISC	No	17	SF	5 ACBM with potential for significant damage	Remove
38	12" x 12" Light Blue Vinyl Floor Tile Mastic	1,700	SF	Room 103, 117, 121, 205, 305, 335, 425	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
39	12" x 12" Yellow w/ White Streaks Vinyl Floor Tile	3,500	SF	Rooms 401, 115, 113	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
4	12" x 12" Vinyl Floor Tile, Dark Brown	375	SF	Engineer's Office	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
40	12" x 12" Yellow w/ White Streaks Vinyl Floor Tile Mastic	3,500	SF	Rooms 401, 115, 113	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
41	12" x 12" Tan w/ Dark Beige Specks Floor Tile			Rooms 329, 331 421	Assumed	MISC					
42	12" x 12" Tan w/ Dark Beige Specks Floor Tile Mastic			Rooms 329, 331, 421	Assumed	MISC					
43	12" x 12" Dark Gray w/ White Specks Vinyl Floor Tile	600	SF	Room 223 , Wood Closet	Assumed	MISC	No	60	SF	6 ACBM with the potential for damage	Remove
44	12" x 12" Dark Gray w/ White Specks Vinyl Floor Tile Mastic	600	SF	Room 223	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
45	12" x 12" Battleship Gray w/ White Specks Floor Tile	5,700	SF	Room 214, 215, 218, 220, 222, 226, 228, 234, 236, 239, 235	Assumed	MISC	No	5	SF	6 ACBM with the potential for damage	Remove
46	12" x 12" Battleship Gray w/ White Specks Floor Tile Mastic	5,700	SF	Room 214, 215, 218, 220, 222, 226, 228, 234, 236, 235	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
47	12" x 12" Beige w/ Dark Beige & White Specks Floor Tile	1,000	SF	Room 207, and 209	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
48	12" x 12" Beige w/ Dark Beige & Whitet Specks Floor Tile Mastic	1,000	SF	Room 207, and 209	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
49	12" x 12" Beige w/ Dark Beige & Whitet Specks	1,000	SF	Room 207, and 209	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Tilden Academy

Unit 53121

Building ID 1590

Address 4747 S. Union

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	Floor Tile Mastic										
4A	12" x 12" Vinyl Floor Tile, Dark Brown Mastic	375	SF	Engineer's Office	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
5	9" x 9" Vinyl Floor Tile, Tan (Checkered)	11,000	SF	1st, 2nd and 3rd Floor Hallways	Chrysotile	MISC	No	70	SF	5 ACBM with potential for significant damage	Remove
50	12" x 12" Baby Blue w/ Dark Blue Specks Floor Tile Mastic	500	SF	Room 205	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
51	12" x 12" Olive Green w/ Dark Green & Whitet Specks Floor Tile	1,000	SF	1st Floor North E/W Corridor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
52	12" x 12" Olive Grn w/ Dark Grn & Whitet Specks Floor Tile Mastic	1,000	SF	1st Floor North E/W Corridor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
53	Boiler Breeching	900	SF	Boiler Room	Assumed	TSI	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
54	Two Tanks	900	SF	Boiler Room	Assumed	TSI	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
5A	9" x 9" Vinyl Floor Tile, Tan Mastic (Checkered)	11,000	SF	1st, 2nd and 3rd Floor Hallways	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
6	9" x 9" Vinyl Floor Tile, Brown (Checkered)	11,000	SF	1st, 2nd, 3rd and 4th Floor Hallways	Chrysotile	MISC	No	70	SF	5 ACBM with potential for significant damage	Remove
60	Blue Linoleum and Associated Adhesive			Room 403	Assumed	MISC					
61	Lab Table Tops			Rooms 301, 303, 401, 403, 405, 407,	No ACBM	MISC					
62	Gray Rubber Flax Adhesive	2,500	SF	Southwest Gym	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
63	Green Carpet Adhesive	2,000	SF	Library, 2nd Floor Lobby	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
64	Multicolored Carpet Adhesive	2,500	SF	Room 320, 323	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
65	Black Carpet Mastic			Room 323	Assumed	MISC					
67	12" x 12" White w/ Dark Gray Specks Floor Tile	350	SF	Room 420 and 219, 413, 415 421 424	Assumed	MISC	No	61	SF	5 ACBM with potential for significant damage	Remove
68	Foam Type Insulation	100	LF	1st Floor Hall Outside Maintenance Dept.	Assumed	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
69	12" x 12" White Floor Tile w/ Cream Streak			Office Next WomensMain Office	Assumed	MISC					
6A	9" x 9" Vinyl Floor Tile, Brown Mastic (Checkered)	11,000	SF	1st, 2nd and 3rd Floor Hallways	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
7	Brown Linoleum			425 Hallway	No ACBM	MISC					
70	Wood Flooring	2,000	SF	Northwest Gym, Main Gym, 440, 410, 411, 417, 419 423, 322, 316, 314, 306a, 239a. 229, Main Office, Main Gym Storage Room, Equipment Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
71	2" x 2" White Ceramic Tile	600	SF	4th Floor Boys Bathroom in Locker Room, Throughout Washrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Tilden Academy

Unit 53121

Building ID 1590

Address 4747 S. Union

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
72	2" x 2" White Ceramic Tile Mastic	600	SF	4th Floor Boys Bathroom in Locker Room, Throughout Washrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
73	Blue Carpet Adhesive	1,000	SF	Room 231	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
74	12" x 12" Blue, Gray, White Vinyl Floor Tile	1,500	SF	Rooms 405, 403, 409	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
75	12" x 12" Blue, Gray, White Vinyl Floor Tile Mastic	1,500	SF	Rooms 405, 403, 409	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
7A	Brown Linoleum Mastic			425 Hallway	No ACBM	MISC					
9	12" x 12" Vinyl Floor Tile, Off-White Mottled	375	SF	Engineer's Office	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
9A	12" x 12" Vinyl Floor Tile, Off-White Mottled Mastic	375	SF	Engineer's Office	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Water Tank			ABATED	Abated	TSI					
E	Boiler Gaskets	80	LF	Boiler Room	Chrysotile	MISC	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	Aircell Pipe Insulation	5,000	LF	North Boys Bathroom in Basement, Boiler Room, Fan Room 106	Chrysotile	TSI	Yes	25	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
G	Fittings Off Aircell Pipe Insulation	45	LF	North Boys' Bathroom in Basement, Boiler Room	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
HA-100	1' x 1' White Plain Ceiling Tile	1,000	SF	Kitchen	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
HA-101	Glue For 1' x 1' White Plain Ceiling Tile	1,000	SF	Kitchen	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-102	Boiler Breeching Insulation	20	LF	Boiler Room	Assumed	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
L	Fittings Off Fiberglass Pipe Runs	25	LF	Pump Room	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
M	Tan Carpet	200	SF	Auditorium	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
N	Tan Carpet Mastic	200	SF	Auditorium	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Tilden Academy

Unit 53121

Building ID 1590

Address 4747 S. Union

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	4/18/2025
Manager Planner Name	Mike Serio
100-18488	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10	
103	Sample to determine ACM content prior to disturbance.
104	Sample to determine ACM content prior to disturbance.
105	Sample to determine ACM content prior to disturbance.
106	Sample to determine ACM content prior to disturbance.
107	Sample to determine ACM content prior to disturbance.
108	Sample to determine ACM content prior to disturbance.
109	Sample to determine ACM content prior to disturbance.
10A	
11	Remove or repair to intact.
110	Sample to determine ACM content prior to disturbance.
111	Sample to determine ACM content prior to disturbance.
11A	Sample to determine ACM content prior to disturbance.
12	Remove or repair to intact.
12A	

Chicago Public Schools

School Tilden Academy

Unit 53121

Building ID 1590

Address 4747 S. Union

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
13	
13A	
14	Sample to determine ACM content prior to disturbance.
14A	
15	Sample to determine ACM content prior to disturbance.
15A	
16	Sample to determine ACM content prior to disturbance.
16A	Sample to determine ACM content prior to disturbance.
17	Sample to determine ACM content prior to disturbance.
17A	Sample to determine ACM content prior to disturbance.
18	Sample to determine ACM content prior to disturbance.
18A	Sample to determine ACM content prior to disturbance.
19	
19A	
2	
20	Remove or repair to intact.
20A	
21	Remove or repair to intact.
21A	Sample to determine ACM content prior to disturbance.
22	
22A	
23	
23A	
24	
25	
26	Non-AHERA
27	Remove or repair to intact.

Chicago Public Schools

School Tilden Academy

Unit 53121

Building ID 1590

Address 4747 S. Union

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
27A	
28	
29	
3	Repair non-ACBM material.
30	
31	Sample to determine ACM content prior to disturbance.
32	Sample to determine ACM content prior to disturbance.
33	Sample to determine ACM content prior to disturbance.
34	Sample to determine ACM content prior to disturbance.
35	Sample to determine ACM content prior to disturbance.
36	Sample to determine ACM content prior to disturbance.
37	Remove or repair to intact.
38	Sample to determine ACM content prior to disturbance.
39	Sample to determine ACM content prior to disturbance.
4	Remove and replace damaged material.
40	Sample to determine ACM content prior to disturbance.
41	
42	
43	Remove or repair to intact.
44	Sample to determine ACM content prior to disturbance.
45	Remove or repair to intact.
46	Sample to determine ACM content prior to disturbance.
47	Sample to determine ACM content prior to disturbance.
48	Sample to determine ACM content prior to disturbance.
49	Sample to determine ACM content prior to disturbance.
4A	
5	Remove or repair to intact.

Chicago Public Schools

School Tilden Academy

Unit 53121

Building ID 1590

Address 4747 S. Union

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
50	Sample to determine ACM content prior to disturbance.
51	Sample to determine ACM content prior to disturbance.
52	Sample to determine ACM content prior to disturbance.
53	Sample to determine ACM content prior to disturbance.
54	Sample to determine ACM content prior to disturbance.
5A	
6	Remove or repair to intact.
60	
61	
62	Sample to determine ACM content prior to disturbance.
63	Sample to determine ACM content prior to disturbance.
64	Sample to determine ACM content prior to disturbance.
65	
67	Remove or repair to intact.
68	Sample to determine ACM content prior to disturbance.
69	
6A	
7	
70	Sample to determine ACM content prior to disturbance.
71	Sample to determine ACM content prior to disturbance.
72	Sample to determine ACM content prior to disturbance.
73	Sample to determine ACM content prior to disturbance.
74	Sample to determine ACM content prior to disturbance.
75	Sample to determine ACM content prior to disturbance.
7A	
9	
9A	

Chicago Public Schools

School Tilden Academy

Unit 53121

Building ID 1590

Address 4747 S. Union

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
A	
E	
F	Remove or repair damaged TSI to intact.
G	
HA-100	Sample to determine ACM content prior to disturbance.
HA-101	Sample to determine ACM content prior to disturbance.
HA-102	Sample to determine ACM content prior to disturbance.
L	
M	Sample to determine ACM content prior to disturbance.
N	Sample to determine ACM content prior to disturbance.

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA RE/INSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **4th Hall, 3rd Hall, 003, 228, 438, 439, 227, 433, 436, 437, 438, 440, 323, 320, 314, 313, 315, 311, Throughout Classrooms, 403, 411**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**

MATERIAL LOCATION: **4th Hall, 3rd Hall, 003, 228, 438, 439, 227, 433, 436, 437, 438, 440, 323, 320, 314, 313, 315, 311, Throughout Classrooms, 403, 411**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Yellowish Green		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor North Corridor		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Yellowish Green**

MATERIAL LOCATION: **1st Floor North Corridor**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 04/18/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10A		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Yellowish Green Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Corridor		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **10A**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Yellowish Green Mastic**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 04/18/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Off-White w/ Tan Specks		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Delamination		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	HIGH		
MATERIAL LOCATION:	Rooms 227, 317, 420, 425, 429, 431, 433, 207, 209, 321, 330, 332, 306, 305, 325, 327, 329, 304, 238, 202, Main Office, 207, 209		
MATERIAL QUANTITY:	7500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in Rooms 425, 420, 227, 321 Not observed in 439, 309, MDF Room, 308, 311, 313, 317, 318 319		

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Off-White w/ Tan Specks**

MATERIAL LOCATION: **Rooms 227, 317, 420, 425, 429, 431, 433, 207, 209, 321, 330, 332, 306, 305, 325, 327, 329, 304, 238, 202, Main Office, 207, 209**

MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **120** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

Repair

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11A		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Off-White w/ Tan Specks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 227, 317, 420, 425, 429, 431, 433, 207, 209, 321, 330, 332, 306, 305, 325, 327, 329, 304, 238, 202, Main Office, 207, 209**

MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **11A**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Off-White w/ Tan Specks Mastic**

MATERIAL LOCATION: **Rooms 227, 317, 420, 425, 429, 431, 433, 207, 209, 321, 330, 332, 306, 305, 325, 327, 329, 304, 238, 202, Main Office, 207, 209**

MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/18/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Off-White w/ Gray Specks		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 5. ACBM with potential for significant damage

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd, 3rd and 4th Floor Classrooms 436, 438 201, 228, 426, 437 (patches), 211		
MATERIAL QUANTITY:	39000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damaged in room 230, 203, 211		

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Off-White w/ Gray Specks**

MATERIAL LOCATION: **1st, 2nd, 3rd and 4th Floor Classrooms 436, 438 201, 228, 426, 437 (patches), 211**

MATERIAL QUANTITY: **39000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **45** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12A		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Off-White w/ Gray Specks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd, 3rd and 4th Floor Classrooms, 436, 438, 426, 437 (patches), 211		
MATERIAL QUANTITY:	39000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **12A**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Off-White w/ Gray Specks Mastic**

MATERIAL LOCATION: **1st, 2nd, 3rd and 4th Floor Classrooms, 436, 438, 426, 437 (patches), 211**

MATERIAL QUANTITY: **39000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 04/18/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	9" x 9" Vinyl Floor Tile, Beige w/ Dark Specks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd and 3rd Floor N/E Hallways		
MATERIAL QUANTITY:	2800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **9" x 9" Vinyl Floor Tile, Beige w/ Dark Specks**

MATERIAL LOCATION: **2nd and 3rd Floor N/E Hallways**

MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 04/18/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13A		
MATERIAL DESCRIPTION:	9" x 9" Vinyl Floor Tile, Beige w/ Dark Specks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd and 3rd Floor N/E Hallways		
MATERIAL QUANTITY:	2800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **13A**

MATERIAL DESCRIPTION: **9" x 9" Vinyl Floor Tile, Beige w/ Dark Specks Mastic**

MATERIAL LOCATION: **2nd and 3rd Floor N/E Hallways**

MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 04/18/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Black		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen and Lunchroom, Gym Locker Room, Gym Teacher Washroom**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Black**

MATERIAL LOCATION: **Kitchen and Lunchroom, Gym Locker Room, Gym Teacher Washroom**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14A		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Black Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen and Lunchroom, Gym Locker Room, Gym Teachers' Washroom		
MATERIAL QUANTITY:	3400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **14A**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Black Mastic**

MATERIAL LOCATION: **Kitchen and Lunchroom, Gym Locker Room, Gym Teachers' Washroom**

MATERIAL QUANTITY: **3400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 04/18/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Blue		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 437, 331		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Blue**

MATERIAL LOCATION: **Room 437, 331**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15A		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Blue Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 437, 331		
MATERIAL QUANTITY:	2800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **15A**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Blue Mastic**

MATERIAL LOCATION: **Room 437, 331**

MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 04/18/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Mottled Brown		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 213		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Mottled Brown**

MATERIAL LOCATION: **Room 213**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16A		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Mottled Brown Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 213		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **16A**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Mottled Brown Mastic**

MATERIAL LOCATION: **Room 213**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Mottled Tan		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 213, 416, main office, 217, 221		
MATERIAL QUANTITY:	2025	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Mottled Tan**

MATERIAL LOCATION: **Room 213, 416, main office, 217, 221**

MATERIAL QUANTITY: **2025** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17A		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Mottled Tan Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 213, 416, main office, 217, 221		
MATERIAL QUANTITY:	2025	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **17A**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Mottled Tan Mastic**

MATERIAL LOCATION: **Room 213, 416, main office, 217, 221**

MATERIAL QUANTITY: **2025** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Beige Mottled		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	HIGH		
MATERIAL LOCATION:	Room 334, 331 (Beneath New Tile), main office storage room		
MATERIAL QUANTITY:	1100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not observed in Room 331		

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Beige Mottled**

MATERIAL LOCATION: **Room 334, 331 (Beneath New Tile), main office storage room**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18A		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Beige Mottled Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 334, 331 (Beneath New Tile), main office storage room		
MATERIAL QUANTITY:	1100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not observed in Room 331		

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **18A**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Beige Mottled Mastic**

MATERIAL LOCATION: **Room 334, 331 (Beneath New Tile), main office storage room**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **12" x 12" Mottled Gray Vinyl Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 440, 239a Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **12" x 12" Mottled Gray Vinyl Floor Tile**

MATERIAL LOCATION: **Room 440, 239a Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19A**

MATERIAL DESCRIPTION: **12" x 12" Mottled Gray Vinyl Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 440, 239a Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **19A**

MATERIAL DESCRIPTION: **12" x 12" Mottled Gray Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 440, 239a Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 2

MATERIAL DESCRIPTION: 1' x 1' Ceiling Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 223

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**

MATERIAL LOCATION: **Room 223**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Beige		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Deterioration		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	Deterioration		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 418 408, 225		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in 408		

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Beige**

MATERIAL LOCATION: **Rooms 418 408, 225**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **30** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20A		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Beige Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 418		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **20A**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Beige Mastic**

MATERIAL LOCATION: **Rooms 418**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 04/18/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	9" x 9" Vinyl Floor Tile, Tan w/ Dark Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Remove		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 5. ACBM with potential for significant damage

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 332 407 303 301 102		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damaged in room 407		

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **9" x 9" Vinyl Floor Tile, Tan w/ Dark Streaks**

MATERIAL LOCATION: **Room 332 407 303 301 102**

MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **135** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21A		
MATERIAL DESCRIPTION:	9" x 9" Vinyl Floor Tile, Tan w/ Dark Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 332 407 303 301 102		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **21A**

MATERIAL DESCRIPTION: **9" x 9" Vinyl Floor Tile, Tan w/ Dark Streaks Mastic**

MATERIAL LOCATION: **Room 332 407 303 301 102**

MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 22
MATERIAL DESCRIPTION: 9" x 9" Vinyl Floor Tile, Brown
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rotc Building, On Table

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **9" x 9" Vinyl Floor Tile, Brown**

MATERIAL LOCATION: **Rotc Building, On Table**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 22A

MATERIAL DESCRIPTION: 9" x 9" Vinyl Floor Tile, Brown Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rotc Building, On Table

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **22A**

MATERIAL DESCRIPTION: **9" x 9" Vinyl Floor Tile, Brown Mastic**

MATERIAL LOCATION: **Rotc Building, On Table**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 23
MATERIAL DESCRIPTION: Bluish Gray Linoleum
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 3rd Floor Gym

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Bluish Gray Linoleum**

MATERIAL LOCATION: **3rd Floor Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 23A

MATERIAL DESCRIPTION: Bluish Gray Linoleum Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 3rd Floor Gym

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **23A**

MATERIAL DESCRIPTION: **Bluish Gray Linoleum Mastic**

MATERIAL LOCATION: **3rd Floor Gym**


MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 24
MATERIAL DESCRIPTION: Brick Mortar - Non-AHERA
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Brick Mortar - Non-AHERA**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 25
MATERIAL DESCRIPTION: Limestone Mortar - Non-AHERA
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Limestone Mortar - Non-AHERA**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Brick Mortar, ROTC Building - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROTC Building Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Brick Mortar, ROTC Building - Non-AHERA**

MATERIAL LOCATION: **ROTC Building Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Non-AHERA

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	9" x 9" Sand Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 5. ACBM with potential for significant damage

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 301, 303, 102. 407, 409 , 102, 305 (Beneath New Tile)		
MATERIAL QUANTITY:	3200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damaged in Room 407		

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **9" x 9" Sand Floor Tile**

MATERIAL LOCATION: **Rooms 301, 303, 102, 407, 409, 102, 305 (Beneath New Tile)**

MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **35** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27A		
MATERIAL DESCRIPTION:	9" x 9" Sand Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 301, 303, 102. 407, 409 , 102, 305 (Beneath New Tile)		
MATERIAL QUANTITY:	3700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **27A**

MATERIAL DESCRIPTION: **9" x 9" Sand Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 301, 303, 102, 407, 409, 102, 305 (Beneath New Tile)**

MATERIAL QUANTITY: **3700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 04/18/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28
MATERIAL DESCRIPTION: Wall Board
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 226 and 228, Electrical Foreman's Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Wall Board**

MATERIAL LOCATION: **Rooms 226 and 228, Electrical Foreman's Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 29
MATERIAL DESCRIPTION: Stage Curtains
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Auditorium

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Stage Curtains**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **Plaster**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS: **1000 SF damage in northwest gym, 2 SF of damage on 4th floor wall across from 407, 3 SF damage in 404**

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Repair non-ACBM material.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	Wire Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Wire Insulation**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31		
MATERIAL DESCRIPTION:	12" x 12" Brown w/ White Specks Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **4th Floor Corridor North E/W Corridor by Stairwell 7, 3rd Floor North E/W Corridor by Stairwell 7**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ White Specks Vinyl Floor Tile**

MATERIAL LOCATION: **4th Floor Corridor North E/W Corridor by Stairwell 7, 3rd Floor North E/W Corridor by Stairwell 7**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32		
MATERIAL DESCRIPTION:	12" x 12" Brown w/ White Specks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **4th Floor Corridor North E/W Corridor by Stairwell 7, 3rd Floor North E/W Corridor by Stairwell 7**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ White Specks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **4th Floor Corridor North E/W Corridor by Stairwell 7, 3rd Floor North E/W Corridor by Stairwell 7**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	12" x 12" Yellow w/ White Specks Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 439, 120, 113, 115		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **12" x 12" Yellow w/ White Specks Vinyl Floor Tile**

MATERIAL LOCATION: **Room 439, 120, 113, 115**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	12" x 12" Yellow w/ White Specks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 439, 120, 113, 115		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **12" x 12" Yellow w/ White Specks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 439, 120, 113, 115**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	12" x 12" Dark Blue Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 120, 121, 331, and 333		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **12" x 12" Dark Blue Vinyl Floor Tile**

MATERIAL LOCATION: **Room 120, 121, 331, and 333**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	12" x 12" Dark Blue Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 120, 121, 331, and 333		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **12" x 12" Dark Blue Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 120, 121, 331, and 333**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	12" x 12" Light Blue Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 5. ACBM with potential for significant damage

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 205, 317, 437, 117, 425		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in 437		

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **12" x 12" Light Blue Vinyl Floor Tile**

MATERIAL LOCATION: **Room 205, 317, 437, 117, 425**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **17** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	12" x 12" Light Blue Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 103, 117, 121, 205, 305, 335, 425		
MATERIAL QUANTITY:	1700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not observed 333		

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **12" x 12" Light Blue Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 103, 117, 121, 205, 305, 335, 425**

MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39		
MATERIAL DESCRIPTION:	12" x 12" Yellow w/ White Streaks Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 401, 115, 113		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not observed in Room 405		

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **12" x 12" Yellow w/ White Streaks Vinyl Floor Tile**

MATERIAL LOCATION: **Rooms 401, 115, 113**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	4		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Dark Brown		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office		
MATERIAL QUANTITY:	375	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Dark Brown**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **375** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Remove and replace damaged material.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	12" x 12" Yellow w/ White Streaks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 401, 115, 113		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not observed in Room 405		

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **12" x 12" Yellow w/ White Streaks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 401, 115, 113**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41	
MATERIAL DESCRIPTION:	12" x 12" Tan w/ Dark Beige Specks Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:	Deterioration	
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 329, 331 421**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **12" x 12" Tan w/ Dark Beige Specks Floor Tile**

MATERIAL LOCATION: **Rooms 329, 331 421**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42	
MATERIAL DESCRIPTION:	12" x 12" Tan w/ Dark Beige Specks Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 329, 331, 421**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **12" x 12" Tan w/ Dark Beige Specks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 329, 331, 421**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	12" x 12" Dark Gray w/ White Specks Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	HIGH		
MATERIAL LOCATION:	Room 223 , Wood Closet		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in 223		

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/ White Specks Vinyl Floor Tile**

MATERIAL LOCATION: **Room 223, Wood Closet**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **60** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	12" x 12" Dark Gray w/ White Specks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	HIGH		
MATERIAL LOCATION:	Room 223		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/ White Specks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 223**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	12" x 12" Battleship Gray w/ White Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 214, 215, 218, 220, 222, 226, 228, 234, 236, 239, 235		
MATERIAL QUANTITY:	5700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damaged in 236, Damaged in 235		

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **12" x 12" Battleship Gray w/ White Specks Floor Tile**

MATERIAL LOCATION: **Room 214, 215, 218, 220, 222, 226, 228, 234, 236, 239, 235**

MATERIAL QUANTITY: **5700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	12" x 12" Battleship Gray w/ White Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 214, 215, 218, 220, 222, 226, 228, 234, 236, 235		
MATERIAL QUANTITY:	5700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **12" x 12" Battleship Gray w/ White Specks Floor Tile Mastic**

MATERIAL LOCATION: **Room 214, 215, 218, 220, 222, 226, 228, 234, 236, 235**

MATERIAL QUANTITY: **5700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Dark Beige & White Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Deterioration		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 207, and 209**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Dark Beige & White Specks Floor Tile**

MATERIAL LOCATION: **Room 207, and 209**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Dark Beige & Whitet Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 207, and 209		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Dark Beige & White Specks Floor Tile Mastic**

MATERIAL LOCATION: **Room 207, and 209**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Dark Beige & Whitet Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 207, and 209		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Dark Beige & White Specks Floor Tile Mastic**

MATERIAL LOCATION: **Room 207, and 209**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	4A		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Dark Brown Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office		
MATERIAL QUANTITY:	375	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **4A**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Dark Brown Mastic**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **375** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 04/18/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	5		
MATERIAL DESCRIPTION:	9" x 9" Vinyl Floor Tile, Tan (Checkered)		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 5. ACBM with potential for significant damage

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Hallways		
MATERIAL QUANTITY:	11000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in 1st floor corridors throughout		

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **9" x 9" Vinyl Floor Tile, Tan (Checkered)**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Hallways**

MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **70** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

Repair

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	12" x 12" Baby Blue w/ Dark Blue Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 205		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **12" x 12" Baby Blue w/ Dark Blue Specks Floor Tile Mastic**

MATERIAL LOCATION: **Room 205**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	12" x 12" Olive Green w/ Dark Green & Whitet Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor North E/W Corridor		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **12" x 12" Olive Green w/ Dark Green & White Specks Floor Tile**

MATERIAL LOCATION: **1st Floor North E/W Corridor**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	12" x 12" Olive Grn w/ Dark Grn & Whitet Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor North E/W Corridor		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **12" x 12" Olive Grn w/ Dark Grn & Whitet Specks Floor Tile Mastic**

MATERIAL LOCATION: **1st Floor North E/W Corridor**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	Boiler Breeching		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **Boiler Breeching**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	Two Tanks		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Two Tanks**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	5A		
MATERIAL DESCRIPTION:	9" x 9" Vinyl Floor Tile, Tan Mastic (Checkered)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Hallways**

MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **5A**

MATERIAL DESCRIPTION: **9" x 9" Vinyl Floor Tile, Tan Mastic (Checkered)**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Hallways**

MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 04/18/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	6		
MATERIAL DESCRIPTION:	9" x 9" Vinyl Floor Tile, Brown (Checkered)		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 5. ACBM with potential for significant damage

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1st, 2nd, 3rd and 4th Floor Hallways		
MATERIAL QUANTITY:	11000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in 1st floor corridors throughout		

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **9" x 9" Vinyl Floor Tile, Brown (Checkered)**

MATERIAL LOCATION: **1st, 2nd, 3rd and 4th Floor Hallways**

MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **70** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **Blue Linoleum and Associated Adhesive**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 403**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **Blue Linoleum and Associated Adhesive**

MATERIAL LOCATION: **Room 403**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 61
MATERIAL DESCRIPTION: Lab Table Tops
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 301, 303, 401, 403, 405, 407,

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **Lab Table Tops**

MATERIAL LOCATION: **Rooms 301, 303, 401, 403, 405, 407,**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	62		
MATERIAL DESCRIPTION:	Gray Rubber Flax Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Southwest Gym		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Gray Rubber Flax Adhesive**

MATERIAL LOCATION: **Southwest Gym**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	63		
MATERIAL DESCRIPTION:	Green Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Library, 2nd Floor Lobby		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **Green Carpet Adhesive**

MATERIAL LOCATION: **Library, 2nd Floor Lobby**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	64		
MATERIAL DESCRIPTION:	Multicolored Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 320, 323		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **Multicolored Carpet Adhesive**

MATERIAL LOCATION: **Room 320, 323**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	65	
MATERIAL DESCRIPTION:	Black Carpet Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 323**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **Black Carpet Mastic**

MATERIAL LOCATION: **Room 323**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	67		
MATERIAL DESCRIPTION:	12" x 12" White w/ Dark Gray Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Deterioration		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	Deterioration		
	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 420 and 219, 413, 415 421 424		
MATERIAL QUANTITY:	350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damaged in Rooms 415, 420, 421, 424		

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **12" x 12" White w/ Dark Gray Specks Floor Tile**

MATERIAL LOCATION: **Room 420 and 219, 413, 415 421 424**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **61** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	68		
MATERIAL DESCRIPTION:	Foam Type Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Hall Outside Maintenance Dept.**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **Foam Type Insulation**

MATERIAL LOCATION: **1st Floor Hall Outside Maintenance Dept.**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	69	
MATERIAL DESCRIPTION:	12" x 12" White Floor Tile w/ Cream Streak	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:	Physical Damage	
HISTORICAL RESPONSE ACTION:	Repair	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Office Next WomensMain Office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Cream Streak**

MATERIAL LOCATION: **Office Next WomensMain Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature:  Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	6A		
MATERIAL DESCRIPTION:	9" x 9" Vinyl Floor Tile, Brown Mastic (Checkered)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Hallways		
MATERIAL QUANTITY:	11000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **6A**

MATERIAL DESCRIPTION: **9" x 9" Vinyl Floor Tile, Brown Mastic (Checkered)**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Hallways**

MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 04/18/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 7
MATERIAL DESCRIPTION: Brown Linoleum
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 425 Hallway

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **Brown Linoleum**

MATERIAL LOCATION: **425 Hallway**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	70		
MATERIAL DESCRIPTION:	Wood Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Northwest Gym, Main Gym, 440, 410, 411, 417, 419 423, 322, 316, 314, 306a, 239a. 229, Main Office, Main Gym Storage Room, Equipment Room**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **Wood Flooring**

MATERIAL LOCATION: **Northwest Gym, Main Gym, 440, 410, 411, 417, 419 423, 322, 316, 314, 306a, 239a. 229, Main Office, Main Gym Storage Room, Equipment Room**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	71		
MATERIAL DESCRIPTION:	2" x 2" White Ceramic Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	4th Floor Boys Bathroom in Locker Room, Throughout Washrooms		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **2" x 2" White Ceramic Tile**

MATERIAL LOCATION: **4th Floor Boys Bathroom in Locker Room, Throughout Washrooms**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	72		
MATERIAL DESCRIPTION:	2" x 2" White Ceramic Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	4th Floor Boys Bathroom in Locker Room, Throughout Washrooms		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **2" x 2" White Ceramic Tile Mastic**

MATERIAL LOCATION: **4th Floor Boys Bathroom in Locker Room, Throughout Washrooms**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	73		
MATERIAL DESCRIPTION:	Blue Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 231		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **Blue Carpet Adhesive**

MATERIAL LOCATION: **Room 231**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	74		
MATERIAL DESCRIPTION:	12" x 12" Blue, Gray, White Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Rooms 405, 403, 409		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **12" x 12" Blue, Gray, White Vinyl Floor Tile**

MATERIAL LOCATION: **Rooms 405, 403, 409**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	75		
MATERIAL DESCRIPTION:	12" x 12" Blue, Gray, White Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Rooms 405, 403, 409		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **12" x 12" Blue, Gray, White Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 405, 403, 409**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 7A
MATERIAL DESCRIPTION: Brown Linoleum Mastic
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 425 Hallway

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **7A**

MATERIAL DESCRIPTION: **Brown Linoleum Mastic**

MATERIAL LOCATION: **425 Hallway**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	9		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Off-White Mottled		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office		
MATERIAL QUANTITY:	375	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Off-White Mottled**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **375** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature:  Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	9A		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile, Off-White Mottled Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office		
MATERIAL QUANTITY:	375	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **9A**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile, Off-White Mottled Mastic**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **375** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 04/18/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: A
MATERIAL DESCRIPTION: Water Tank
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Water Tank**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	Boiler Gaskets		
HISTORICAL AHERA DAMAGE CATEGORY	7 Damaged or significantly damaged friable misc. ACBM		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Remove		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Boiler Gaskets**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature:  Date: 04/18/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	1 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:	Deterioration Water		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	North Boys Bathroom in Basement, Boiler Room, Fan Room 106		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	DAMAGE UNITS: LF		
COMMENTS:	Damage in: Boiler Room, Fan Room 106		

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **North Boys Bathroom in Basement, Boiler Room, Fan Room 106**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **25** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Remove or repair damaged TSI to intact.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G		
MATERIAL DESCRIPTION:	Fittings Off Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	North Boys' Bathroom in Basement, Boiler Room		
MATERIAL QUANTITY:	45	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Fittings Off Aircell Pipe Insulation**

MATERIAL LOCATION: **North Boys' Bathroom in Basement, Boiler Room**

MATERIAL QUANTITY: **45** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 04/18/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	HA-100		
MATERIAL DESCRIPTION:	1' x 1' White Plain Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **HA-100**

MATERIAL DESCRIPTION: **1' x 1' White Plain Ceiling Tile**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	HA-101		
MATERIAL DESCRIPTION:	Glue For 1' x 1' White Plain Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **HA-101**

MATERIAL DESCRIPTION: **Glue For 1' x 1' White Plain Ceiling Tile**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	HA-102		
MATERIAL DESCRIPTION:	Boiler Breeching Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	DAMAGE UNITS: LF		
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **HA-102**

MATERIAL DESCRIPTION: **Boiler Breeching Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	L		
MATERIAL DESCRIPTION:	Fittings Off Fiberglass Pipe Runs		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Pump Room		
MATERIAL QUANTITY:	25	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	DAMAGE UNITS: LF		
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Fittings Off Fiberglass Pipe Runs**

MATERIAL LOCATION: **Pump Room**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	M		
MATERIAL DESCRIPTION:	Tan Carpet		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Tan Carpet**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	N		
MATERIAL DESCRIPTION:	Tan Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUILDING ID:	1590
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Tilden Academy	REVIEW DATE:	4/18/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Tan Carpet Mastic**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/18/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	103			
MATERIAL DESCRIPTION:	4" Tan Baseboard w/ Adhesive			
MATERIAL LOCATION:	Room 401			
MATERIAL QUANTITY:	40	MATERIAL UNITS:	LF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	LF	
COMMENTS:				

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53121** BUIDLING ID: **1590**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Tilden Academy** REVIEW DATE: **4/18/2025**

ADDRESS: **4747 S. Union** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **103**

MATERIAL DESCRIPTION: **4" Tan Baseboard w/ Adhesive**

MATERIAL LOCATION: **Room 401**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/18/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	104			
MATERIAL DESCRIPTION:	1" x1" Tan & Brown Multicolor Ceramic Floor Tile & Grout			
MATERIAL LOCATION:	Girls Locker Room Shower			
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	

COMMENTS:

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53121** BUIDLING ID: **1590**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Tilden Academy** REVIEW DATE: **4/18/2025**

ADDRESS: **4747 S. Union** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **104**

MATERIAL DESCRIPTION: **1" x1" Tan & Brown Multicolor Ceramic Floor Tile & Grout**

MATERIAL LOCATION: **Girls Locker Room Shower**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/18/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	109			
MATERIAL DESCRIPTION:	12" x 12" Black w/ White Specks Floor Tile Mastic			
MATERIAL LOCATION:	Boys Locker Room			
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	

COMMENTS:

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53121** BULDING ID: **1590**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Tilden Academy** REVIEW DATE: **4/18/2025**

ADDRESS: **4747 S. Union** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **109**

MATERIAL DESCRIPTION: **12" x 12" Black w/ White Specks Floor Tile Mastic**

MATERIAL LOCATION: **Boys Locker Room**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/18/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	106			
MATERIAL DESCRIPTION:	4" Black Baseboard w/ Adhesive			
MATERIAL LOCATION:	Room 407			
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	LF	
COMMENTS:				

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53121** BUIDLING ID: **1590**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Tilden Academy** REVIEW DATE: **4/18/2025**

ADDRESS: **4747 S. Union** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **106**

MATERIAL DESCRIPTION: **4" Black Baseboard w/ Adhesive**

MATERIAL LOCATION: **Room 407**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/18/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	105			
MATERIAL DESCRIPTION:	4" Gray Baseboard w/ Adhesive			
MATERIAL LOCATION:	Room 403, 405			
MATERIAL QUANTITY:	200	MATERIAL UNITS:	LF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	LF	
COMMENTS:				

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53121** BUIDLING ID: **1590**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Tilden Academy** REVIEW DATE: **4/18/2025**

ADDRESS: **4747 S. Union** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **105**

MATERIAL DESCRIPTION: **4" Gray Baseboard w/ Adhesive**

MATERIAL LOCATION: **Room 403, 405**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/18/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	108			
MATERIAL DESCRIPTION:	12" x 12" Black w/ White Specks Floor Tile			
MATERIAL LOCATION:	Boys Locker Room			
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53121** BUIDLING ID: **1590**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Tilden Academy** REVIEW DATE: **4/18/2025**

ADDRESS: **4747 S. Union** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **108**

MATERIAL DESCRIPTION: **12" x 12" Black w/ White Specks Floor Tile**

MATERIAL LOCATION: **Boys Locker Room**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/18/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	107		
MATERIAL DESCRIPTION:	Black Linoleum		
MATERIAL LOCATION:	4th, 3rd, 2nd Floor Girls Restroom		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53121** BUIDLING ID: **1590**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Tilden Academy** REVIEW DATE: **4/18/2025**

ADDRESS: **4747 S. Union** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **107**

MATERIAL DESCRIPTION: **Black Linoleum**

MATERIAL LOCATION: **4th, 3rd, 2nd Floor Girls Restroom**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/18/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	111		
MATERIAL DESCRIPTION:	Red & Brown Terrazzo		
MATERIAL LOCATION:	4th, 3rd and 2nd Floor Corridors and Stairwells		
MATERIAL QUANTITY:	20000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53121** BUIDLING ID: **1590**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Tilden Academy** REVIEW DATE: **4/18/2025**

ADDRESS: **4747 S. Union** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **111**

MATERIAL DESCRIPTION: **Red & Brown Terrazzo**

MATERIAL LOCATION: **4th, 3rd and 2nd Floor Corridors and Stairwells**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/18/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	53121	BUIDLING ID:	1590
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Tilden Academy	INSPECTION DATE:	3/21/2025		
ADDRESS:	4747 S. Union	IDPH LICENSE NO:	100-20411		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	110		
MATERIAL DESCRIPTION:	Black & Gray Terrazzo		
MATERIAL LOCATION:	Main Entrance Corridors		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/21/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53121** BUIDLING ID: **1590**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Tilden Academy** REVIEW DATE: **4/18/2025**

ADDRESS: **4747 S. Union** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **110**

MATERIAL DESCRIPTION: **Black & Gray Terrazzo**

MATERIAL LOCATION: **Main Entrance Corridors**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/18/2025

APPENDIX B

Inspector and Management Planner Licenses



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2025

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Benyamen Maradkel

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 3/7/2025

Exam Date: 3/7/2025

Expiration Date: 3/7/2026


Certificate Number: BIR2503070918

Course Credit Hours: BIR 4 Hrs.

Kristina Miczek, Training Manager

Benyamen Maradkel

Illinois Licensed Building Inspector



ENDORSEMENTS

INSPECTOR

TC EXPIRES

3/7/2026

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.





OCCUPATIONAL TRAINING & SUPPLY, INC. **2024**
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Michael Serio

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/18/2024

Exam Date: 11/18/2024

Expiration Date: 11/18/2025

Certificate Number: MPR2411183328

Course Credit Hours: MPR 4 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

Kristina Miczek, Training Manager

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed