

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-  
SCHOOL NAME: The Academy for Global Citizenship NEW  
ADDRESS OF SCHOOL: 4647 West 47th Street  
CITY: Chicago, IL, 60632

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 11/4/2022

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II (Please type or print)**

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: \_\_\_\_\_ ENROLLMENT 491 \_\_\_\_\_

IDPH INSPECTOR LICENSE NUMBER: \_\_\_\_\_

IDPH LICENSED INSPECTOR NAME (Please Print): \_\_\_\_\_

IDPH MP LICENSE NUMBER: \_\_\_\_\_

IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): \_\_\_\_\_

DESIGNATED PERSON (Please Print): \_\_\_\_\_ PHONE: \_\_\_\_\_

**SECTION III**

**PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.**

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**The Academy for Global Citizenship NEW**

4647 West 47th Street  
Chicago, IL, 60632

Unit: 63011  
Building ID: 2025

IDPH ID Number: 14-016-2990-

**REPORT DATE:**

**Prepared for:**  
**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**

''

Phone

Fax

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region Elementary Schools. Please update your records with the following information.

School District: 299      Unit: 63011      Region: 04      IDPH ID: 14-016-2990-

School: The Academy for Global Citizenship NEW      Building ID: 2025

Address: 4647 West 47th Street

Chicago, IL, 60632

Building Contact:      Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date:

Review Date:

Inspector:      Inspector IDPH License:

Management Planner:      Management Planner IDPH License:

If you have any questions or comments, please contact us at

Sincerely,

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date:

RE: The Academy for Global Citizenship NEW, Unit 63011  
4647 West 47th Street  
Chicago, IL, 60632

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at The Academy for Global Citizenship NEW , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at The Academy for Global Citizenship NEW, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact , the designated Local Education Authority's Designated Person at .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: The Academy for Global Citizenship NEW  
Address: 4647 West 47th Street  
IDPH ID: 14-016-2990-  
Contact: Unit: 63011  
Chicago, IL, 60632  
Building ID: 2025  
Phone:

Region: 04

### 2. Description of Facility

Original Construction:  
Total Square Footage: 11000  
Current Occupancy: 491  
Additional Construction:  
No of Floors:

### 3. LEA Designated Person

Contact:  
Address: 42 West Madison Street  
Chicago, IL 60602  
Phone:

### 4. Managing Environmental Consultant

MEC:  
Contact:  
Address  
Phone:  
Fax:

### 5. Inspector

Inspector Name:  
  
Inspector IDPH license #  
Reinspection Date:  
Signature:  
Date:

### 6. Management Planner

Management Planner Name:  
  
Management Planner IDPH license #  
Signature:  
Date:

### 7. Review Date:

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Name:

---

Unit : 63011

The Academy for Global Citizenship NEW

Building: 2025

## II. EXECUTIVE SUMMARY

was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the The Academy for Global Citizenship NEW. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2025:

1	12" x 12" Gray w/ White Floor Tile
23	Vinyl wall covering adhesive
24	4" Gray vinyl baseboard
25	4" Gray vinyl baseboard adhesive
26	12" x 12" Slate Floor Tile
27	12" x 12" Slate Floor Tile Mastic
28	Duct vibration damper
3	12" x 12" Off-White w/ Gray Specks Floor Tile

B. The following new homogenous areas have been identified for Building 2025:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

1	12" x 12" Gray w/ White Floor Tile
10	12" x 12" Beige Mix Floor Tile Mastic
11	4" Beige vinyl baseboard
12	4" Beige vinyl baseboard mastic
13	4" White (painted brown) vinyl baseboard
14	4" White (painted brown) vinyl baseboard mastic
15	Carpet mastic
16	2' x 2' Lightly Textured Ceiling Tile
17	2' x 4' Fissured Pinhole Ceiling Tiles
18	Red pipe sealant
19	Interior door caulk
2	12" x 12" Gray w/ White Floor Tile Mastic
20	Drywall
21	Drywall compound
22	Drywall tape
23	Vinyl wall covering adhesive
24	4" Gray vinyl baseboard
25	4" Gray vinyl baseboard adhesive
26	12" x 12" Slate Floor Tile
27	12" x 12" Slate Floor Tile Mastic
28	Duct vibration damper
3	12" x 12" Off-White w/ Gray Specks Floor Tile
4	12" x 12" Off-White w/ Gray Specks Floor Tile Mastic
5	12" x 12" Gray Marbled Floor Tile
6	12" x 12" Gray Marbled Floor Tile Mastic
7	12" x 12" Light Gray w/ Dark Gray Specks Floor Tile
8	12" x 12" Light Gray w/ Dark Gray Specks Floor Tile Mastic
9	12" x 12" Beige Mix Floor Tile

The following areas were deemed to be inaccessible:

10	12" x 12" Beige Mix Floor Tile Mastic
12	4" Beige vinyl baseboard mastic
14	4" White (painted brown) vinyl baseboard mastic
15	Carpet mastic
2	12" x 12" Gray w/ White Floor Tile Mastic
28	Duct vibration damper

4	12" x 12" Off-White w/ Gray Specks Floor Tile Mastic
6	12" x 12" Gray Marbled Floor Tile Mastic
8	12" x 12" Light Gray w/ Dark Gray Specks Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by , IDPH License # . The Management Plan was updated by , IDPH License # . Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The The Academy for Global Citizenship NEW Building 2025 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

**School** The Academy for Global Citizenship NEW **Unit** 63011 **Building ID** 2025  
**Address** 4647 West 47th Street **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

#### Managing Environmental Consultant (MEC)

Phone: Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	12" x 12" Gray w/ White Floor Tile	4,000	SF	Rooms 104-106, Storage by 106, Conference Room A, Room 107 and B, Room 108, Office B (under carpet), Reception Area by Office B	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
10	12" x 12" Beige Mix Floor Tile Mastic	100	SF	East Entrance Vestibule	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	4" Beige vinyl baseboard	1,200	LF	Throughout Classrooms, Offices, and Hallways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	4" Beige vinyl baseboard mastic	1,200	LF	Throughout Classrooms, Offices, and Hallways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	4" White (painted brown) vinyl baseboard	200	LF	Multi-Purpose Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	4" White (painted brown) vinyl baseboard mastic	200	LF	Multi-Purpose Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	Carpet mastic	500	SF	Office's A, B, Cm Special Ed Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	2' x 2' Lightly Textured Ceiling Tile	5,000	SF	Rooms 101-103, Multi-Purpose Room, Reception Area, and Hallways	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
17	2' x 4' Fissured Pinhole Ceiling Tiles	600	SF	Office's A, B, C & South Hallway, Peace Room	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
18	Red pipe sealant	50	LF	Throughout Building Above Drop Ceilings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Interior door caulk	100	LF	All Doors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
2	12" x 12" Gray w/ White Floor Tile Mastic	4,000	SF	Rooms 104-106, Storage by 106, Conference Room A, Room 107 and B, Room 108, Office B (under carpet), Reception Area by Office B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Drywall	120,000	SF	Throughout Building	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

# Chicago Public Schools

**School** The Academy for Global Citizenship NEW **Unit** 63011 **Building ID** 2025  
**Address** 4647 West 47th Street **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

#### Managing Environmental Consultant (MEC)

Phone: Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
21	Drywall compound	60,000	LF	Throughout Building	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
22	Drywall tape	60,000	LF	Throughout Building	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
23	Vinyl wall covering adhesive	50	SF	Kitchen	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
24	4" Gray vinyl baseboard	25	SF	Room 104	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
25	4" Gray vinyl baseboard adhesive	25	SF	Room 104	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
26	12" x 12" Slate Floor Tile	120	SF	Kitchen Storage	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
27	12" x 12" Slate Floor Tile Mastic	120	SF	Kitchen Storage	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
28	Duct vibration damper	5	SF	Kitchen Storage	ASSUMED	TSI	N	NONE	0		Yes	ACBM with the potential for damage		LOW
3	12" x 12" Off-White w/ Gray Specks Floor Tile	5,000	SF	Rooms 101-103, Multi-Purpose Room, Kitchen, and Hallways, 106	ASSUMED	MISC	N	LOC	20		Yes	ACBM with the potential for damage	5	MODERATE
4	12" x 12" Off-White w/ Gray Specks Floor Tile Mastic	5,000	SF	Rooms 101-103, Multi-Purpose Room, Kitchen, and Hallways, 106	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
5	12" x 12" Gray Marbled Floor Tile	350	SF	Multi-Purpose Room Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
6	12" x 12" Gray Marbled Floor Tile Mastic	350	SF	Multi-Purpose Room Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
7	12" x 12" Light Gray w/ Dark Gray Specks Floor Tile	50	SF	Kitchen (Patching under sinks)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8	12" x 12" Light Gray w/ Dark Gray Specks Floor Tile Mastic	50	SF	Kitchen (Patching under sinks)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
9	12" x 12" Beige Mix Floor Tile	100	SF	East Entrance Vestibule	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** The Academy for Global Citizenship NEW **Unit** 63011 **Building ID** 2025  
**Address** 4647 West 47th Street **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)**

Phone: Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
1	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
2	
20	
21	
22	
23	
24	
25	
26	
27	
28	
3	
4	
5	



Reinspection Date Inspector Name  Inspector's IDPH License Number / Expiration Date	<b>Inspector's Comments</b>  <tbl_struct><tbl_header><tr><th>HA Number:</th><th>Inspector Comments:</th></tr></tbl_header><tbl_info cols="2"></tbl_info><tbl_r cells="2" ix="1" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="2" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="3" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="4" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="5" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="6" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="7" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="8" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="9" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="10" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="11" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="12" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="13" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="14" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="15" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="16" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="17" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="18" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="19" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="20" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="21" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="22" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="23" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="24" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="25" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="26" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="27" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="28" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="29" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="30" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="31" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="32" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="33" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="34" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="35" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="36" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="37" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="38" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="39" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="40" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="41" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="42" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="43" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="44" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="45" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="46" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="47" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="48" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="49" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="50" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="51" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="52" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="53" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="54" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="55" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="56" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="57" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="58" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="59" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="60" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="61" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="62" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="63" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="64" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="65" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="66" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="67" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="68" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="69" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="70" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="71" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="72" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="73" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="74" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="75" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="76" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="77" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="78" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="79" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="80" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="81" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="82" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="83" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="84" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="85" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="86" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="87" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="88" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="89" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="90" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="91" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="92" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="93" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="94" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="95" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="96" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="97" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="98" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="99" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r><tbl_r cells="2" ix="100" maxcspan="1" maxrspan="1" usedcols="2"></tbl_r></tbl_struct>	HA Number:	Inspector Comments:
HA Number:	Inspector Comments:		

# Chicago Public Schools

**School** The Academy for Global Citizenship NEW **Unit** 63011 **Building ID** 2025  
**Address** 4647 West 47th Street **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)**

Phone: Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
6	
7	
8	
9	

**Table II**  
**Management Planner's Review**

---

# Chicago Public Schools

**School** The Academy for Global Citizenship NEW

**Unit** 63011

**Building ID** 2025

**Address** 4647 West 47th Street

Chicago, IL, 60632

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

#### Managing Environmental Consultant (MEC)

Phone:

Fax:

#### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	12" x 12" Gray w/ White Floor Tile	4,000	SF	Rooms 104-106, Storage by 106, Conference Room A, Room 107 and B, Room 108, Office B (under carpet), Reception Area by Office B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
10	12" x 12" Beige Mix Floor Tile Mastic	100	SF	East Entrance Vestibule	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
11	4" Beige vinyl baseboard	1,200	LF	Throughout Classrooms, Offices, and Hallways	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
12	4" Beige vinyl baseboard mastic	1,200	LF	Throughout Classrooms, Offices, and Hallways	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
13	4" White (painted brown) vinyl baseboard	200	LF	Multi-Purpose Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
14	4" White (painted brown) vinyl baseboard mastic	200	LF	Multi-Purpose Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
15	Carpet mastic	500	SF	Office's A, B, Cm Special Ed Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
16	2' x 2' Lightly Textured Ceiling Tile	5,000	SF	Rooms 101-103, Multi-Purpose Room, Reception Area, and Hallways	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
17	2' x 4' Fissured Pinhole Ceiling Tiles	600	SF	Office's A, B, C & South Hallway. Peace Room	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
18	Red pipe sealant	50	LF	Throughout Building Above Drop Ceilings	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
19	Interior door caulk	100	LF	All Doors	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
2	12" x 12" Gray w/ White Floor Tile Mastic	4,000	SF	Rooms 104-106, Storage by 106, Conference Room A, Room 107 and B, Room 108, Office B (under carpet), Reception Area by Office B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
20	Drywall	120,000	SF	Throughout Building	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
21	Drywall compound	60,000	LF	Throughout Building	Assumed	MISC	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	
22	Drywall tape	60,000	LF	Throughout Building	Assumed	MISC	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	
23	Vinyl wall covering adhesive	50	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
24	4" Gray vinyl baseboard	25	SF	Room 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
25	4" Gray vinyl baseboard adhesive	25	SF	Room 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
26	12" x 12" Slate Floor Tile	120	SF	Kitchen Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
27	12" x 12" Slate Floor Tile Mastic	120	SF	Kitchen Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
28	Duct vibration damper	5	SF	Kitchen Storage	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	

# Chicago Public Schools

**School** The Academy for Global Citizenship NEW

**Unit** 63011

**Building ID** 2025

**Address** 4647 West 47th Street

Chicago, IL, 60632

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

#### Managing Environmental Consultant (MEC)

Phone:

Fax:

#### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
3	12" x 12" Off-White w/ Gray Specks Floor Tile	5,000	SF	Rooms 101-103, Multi-Purpose Room, Kitchen, and Hallways, 106	Assumed	MISC	No	20	SF	6 ACBM with the potential for damage	
4	12" x 12" Off-White w/ Gray Specks Floor Tile Mastic	5,000	SF	Rooms 101-103, Multi-Purpose Room, Kitchen, and Hallways, 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
5	12" x 12" Gray Marbled Floor Tile	350	SF	Multi-Purpose Room Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
6	12" x 12" Gray Marbled Floor Tile Mastic	350	SF	Multi-Purpose Room Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
7	12" x 12" Light Gray w/ Dark Gray Specks Floor Tile	50	SF	Kitchen (Patching under sinks)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
8	12" x 12" Light Gray w/ Dark Gray Specks Floor Tile Mastic	50	SF	Kitchen (Patching under sinks)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
9	12" x 12" Beige Mix Floor Tile	100	SF	East Entrance Vestibule	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	

# Chicago Public Schools

**School** The Academy for Global Citizenship NEW

**Address** 4647 West 47th Street

**Unit** 63011

Chicago, IL, 60632

**Building ID** 2025

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

#### Managing Environmental Consultant (MEC)

Phone:

Fax:

***Management Planner's Comments Summarized at the End of the Report***

Review Date	
Manager Planner Name	
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
2	
20	
21	
22	
23	
24	
25	
26	
27	
28	
3	
4	

# Chicago Public Schools

**School** The Academy for Global Citizenship NEW

**Unit** 63011

**Building ID** 2025

**Address** 4647 West 47th Street

Chicago, IL, 60632

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

#### Managing Environmental Consultant (MEC)

Phone:

Fax:

#### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
5	
6	
7	
8	
9	

## APPENDIX A

---

### Assessment Sheets, Drawings and Photos

# **Chicago Public Schools**

***2025 AHERA REINSPECTION***

# Chicago Public Schools

## 2025 AHERA REINSPECTION Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/ White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 104-106, Storage by 106, Conference Room A, Room 107 and B, Room 108, Office B (under carpet), Reception Area by Office B**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BULDING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ White Floor Tile**

MATERIAL LOCATION: **Rooms 104-106, Storage by 106, Conference Room A, Room 107 and B, Room 108, Office B  
(under carpet), Reception Area by Office B**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **East Entrance Vestibule**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile Mastic**

MATERIAL LOCATION: **East Entrance Vestibule**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **4" Beige vinyl baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Classrooms, Offices, and Hallways**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **4" Beige vinyl baseboard**

MATERIAL LOCATION: **Throughout Classrooms, Offices, and Hallways**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **4" Beige vinyl baseboard mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Classrooms, Offices, and Hallways**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **4" Beige vinyl baseboard mastic**

MATERIAL LOCATION: **Throughout Classrooms, Offices, and Hallways**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **4" White (painted brown) vinyl baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Multi-Purpose Room**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **4" White (painted brown) vinyl baseboard**

MATERIAL LOCATION: **Multi-Purpose Room**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **4" White (painted brown) vinyl baseboard mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Multi-Purpose Room**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **4" White (painted brown) vinyl baseboard mastic**

MATERIAL LOCATION: **Multi-Purpose Room**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **Carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Office's A, B, Cm Special Ed Room**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Carpet mastic**

MATERIAL LOCATION: **Office's A, B, Cm Special Ed Room**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **2' x 2' Lightly Textured Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 101-103, Multi-Purpose Room, Reception Area, and Hallways**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BULDING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **2' x 2' Lightly Textured Ceiling Tile**

MATERIAL LOCATION: **Rooms 101-103, Multi-Purpose Room, Reception Area, and Hallways**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **2' x 4' Fissured Pinhole Ceiling Tiles**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Office's A, B, C & South Hallway. Peace Room**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **2' x 4' Fissured Pinhole Ceiling Tiles**

MATERIAL LOCATION: **Office's A, B, C & South Hallway. Peace Room**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Red pipe sealant**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Building Above Drop Ceilings**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Red pipe sealant**

MATERIAL LOCATION: **Throughout Building Above Drop Ceilings**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Interior door caulk**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All Doors**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Interior door caulk**

MATERIAL LOCATION: **All Doors**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/ White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 104-106, Storage by 106, Conference Room A, Room 107 and B, Room 108, Office B (under carpet), Reception Area by Office B**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BULDING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ White Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 104-106, Storage by 106, Conference Room A, Room 107 and B, Room 108, Office B  
(under carpet), Reception Area by Office B**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **120000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **120000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Drywall compound**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Drywall compound**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **60000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Drywall tape**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Drywall tape**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **60000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Vinyl wall covering adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Vinyl wall covering adhesive**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **4" Gray vinyl baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 104**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **4" Gray vinyl baseboard**

MATERIAL LOCATION: **Room 104**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **4" Gray vinyl baseboard adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 104**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **4" Gray vinyl baseboard adhesive**

MATERIAL LOCATION: **Room 104**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12" x 12" Slate Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen Storage**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **12" x 12" Slate Floor Tile**

MATERIAL LOCATION: **Kitchen Storage**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12" x 12" Slate Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen Storage**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **12" x 12" Slate Floor Tile Mastic**

MATERIAL LOCATION: **Kitchen Storage**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Duct vibration damper**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen Storage**  
MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Duct vibration damper**

MATERIAL LOCATION: **Kitchen Storage**

MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**  
MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Gray Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 101-103, Multi-Purpose Room, Kitchen, and Hallways, 106**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BULDING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Gray Specks Floor Tile**

MATERIAL LOCATION: **Rooms 101-103, Multi-Purpose Room, Kitchen, and Hallways, 106**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**  
MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Gray Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 101-103, Multi-Purpose Room, Kitchen, and Hallways, 106**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BULDING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Gray Specks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 101-103, Multi-Purpose Room, Kitchen, and Hallways, 106**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**  
MATERIAL DESCRIPTION: **12" x 12" Gray Marbled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Multi-Purpose Room Storage**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **12" x 12" Gray Marbled Floor Tile**

MATERIAL LOCATION: **Multi-Purpose Room Storage**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**  
MATERIAL DESCRIPTION: **12" x 12" Gray Marbled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Multi-Purpose Room Storage**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **12" x 12" Gray Marbled Floor Tile Mastic**

MATERIAL LOCATION: **Multi-Purpose Room Storage**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**  
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Dark Gray Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen (Patching under sinks)**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BULDING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Dark Gray Specks Floor Tile**

MATERIAL LOCATION: **Kitchen (Patching under sinks)**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**  
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Dark Gray Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen (Patching under sinks)**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BULDING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Dark Gray Specks Floor Tile Mastic**

MATERIAL LOCATION: **Kitchen (Patching under sinks)**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:  
SCHOOL NAME: **The Academy for Global Citizenship  
NEW** INSPECTION DATE:  
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**  
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **East Entrance Vestibule**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# Chicago Public Schools

## 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **The Academy for  
Global Citizenship  
NEW** REVIEW DATE:

ADDRESS: **4647 West 47th Street** IDPH LICENSE NO:

---

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile**

MATERIAL LOCATION: **East Entrance Vestibule**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

# **Chicago Public Schools**

***2025 AHERA REINSPECTION***

## APPENDIX B

---

### Inspector and Management Planner Licenses

## APPENDIX C

---

### **Laboratory Accreditations**

## APPENDIX D

---

### Laboratory Results

## APPENDIX E

---

### Chain of Custody Forms

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>	Loc	Localized
	Dist	Distributed