

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0124
SCHOOL NAME: Chicago International Charter - Longwood (South)
ADDRESS OF SCHOOL: 1309 W.95th St (9500S) 43
CITY: Chicago, IL, 60643

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 9/13/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: _____ ENROLLMENT 1110 _____

IDPH INSPECTOR LICENSE NUMBER: _____

IDPH LICENSED INSPECTOR NAME (Please Print): _____

IDPH MP LICENSE NUMBER: _____

IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): _____

DESIGNATED PERSON (Please Print): _____ PHONE: _____

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Chicago International Charter - Longwood (South)

1309 W.95th St (9500S) 43
Chicago, IL, 60643

Unit: 66061
Building ID: 2420

IDPH ID Number: 14-016-2990-0124

REPORT DATE:

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

''

Phone

Fax

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 66061 Region: 02 IDPH ID: 14-016-2990-0124

School: Chicago International Charter - Longwood (South) Building ID: 2420

Address: 1309 W. 95th St (9500S) 43

Chicago, IL, 60643

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date:

Review Date:

Inspector: Inspector IDPH License:

Management Planner: Management Planner IDPH License:

If you have any questions or comments, please contact us at

Sincerely,

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date:

RE: Chicago International Charter - Longwood (South), Unit 66061
1309 W.95th St (9500S) 43
Chicago, IL, 60643

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Chicago International Charter - Longwood (South) , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Chicago International Charter - Longwood (South), there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact , the designated Local Education Authority's Designated Person at .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Chicago International Charter - Longwood (South) Unit: 66061 Region: 02
Address: 1309 W.95th St (9500S) 43 Chicago, IL, 60643
IDPH ID: 14-016-2990-0124 Building ID: 2420
Contact: Phone:

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: No of Floors:
Current Occupancy: 1110

3. LEA Designated Person

Contact: Phone:
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC:
Contact:
Address:
Phone: Fax:

5. Inspector

Inspector Name:

Inspector IDPH license # Signature:
Reinspection Date: Date:

6. Management Planner

Management Planner Name:

Management Planner IDPH license # Signature:
Date:

7. Review Date:

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Name:

Unit : 66061

Chicago International Charter - Longwood
(South)

Building: 2420

II. EXECUTIVE SUMMARY

was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Chicago International Charter - Longwood (South). This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2420:

141

Decorative Stucco

B. The following new homogenous areas have been identified for Building 2420:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

100	9 x 9 VFT Black w/ Camoflouge (under HA# 106 & 107)
101	9 x 9 VFT Black w/ Camouflouge Mastic (under HA 106 & 107)
102	9 x 9 VFT Brown (under HA 106 & 107)
103	9 x 9 VFT Brown Mastic (under HA 106 & 107)
104	9 x 9 Brown VFT (under HA 106 & 107)
105	9 x 9 Brown VFT & Mastic (under HA 106 & 107)
106	12 x 12 Gray VFT Speckled
107	12 x 12 Gray VFT Speckled Mastic
108	12 x 12 Gray w/ Red, White & Blue Specs VFT
109	12 x 12 Gray w/ Red, White and Blue Specs Mastic
110	Plaster
113	1 x 1 Ceiling Tile white w/ Swirls
114	Green Terrazzo
115	Spray On Fireproofing
116	Terrazzo
117	12 x 12 VFT Gray Speckled
118	12 x 12 VFT Gray Speckled Mastic
119	1 x 1 CT White w/ Pinhole
120	9 x9 VFT White w/ gray strks
121	9X9 VFT white with gray streaks
122	9 x 9 VFT Black
123	9 x 9 VFT Black Mastic
124	9 x 9 VFT Pink w/ Black Strks
125	9 x 9 VFT Pink w/ Black Strks Mastic
126	9 x 9 VFT Dark Gray w/ white strks
127	9 x 9 VFT Dark Gray w/ white strks Mastic
128	9 x 9 VFT Dark Pink w/ strks
129	9 x 9 VFT Dark Pink w/ strks Mastic
130	12 x 12 VFT Beige Mixed Speckled
131	12 x 12 VFT Beige Mixed Speckled Mastic
132	9 x 9 VFT Brown
133	9 x 9 VFT Brown Mastic
134	Plaster
135	12 x 12 VFT Purple Speckled
136	12 x 12 VFT Purple Speckled Mastic
137	12 x 12 VFT Tan w/ Lt Brown Specs
138	12 x 12 VFT Tan w/ Light Brown Specs Mastic
141	Decorative Stucco
142	12"x12" Gray w/ Black & Gray Specks VFT
142M	12"x12" Gray w/ Black & Gray Specks VFT Mastic

143	9"x9" Off White w/ Black Streaks VFT
143M	9"x9" Off White w/ Black Streaks VFT Mastic
144	12"x12" Light Blue w/ Streaks VFT
144M	12"x12" Light Blue w/ Streaks VFT Mastic
145	1'x1' Ceiling Tile w/ Holes
145M	1'x1' Ceiling Tile w/ Holes Mastic
146	Decoratrive Plaster
147	12"x12" Dark Gray w/ Black & Gray Specks VFT
147M	12"x12" Dark Gray w/ Black & Gray Specks VFT Mastic
148	Popcorn Plaster Ceiling
149	Green Carpet Mastic
150	12"x12" Light Blue w/ Dark & Light Streaks VFT & Mastic
150M	12"x12" Light Blue w/ Dark & Light Streaks VFT Mastic
151	Decorative Plaster
152	12"x12" Black w/ White Specks VFT
152M	12"x12" Black w/ White Specks VFT Mastic
153	12"x12" Sand VFT
153M	12"x12" Sand VFT Mastic
154	1'x1' White Ceiling Tile
154M	1'x1' White Ceiling Tile Mastic Pucks
155	12"x12" Dark Gray w/ Black & Gray Specks VFT & Mastic
155M	12"x12" Dark Gray w/ Black & Gray Specks VFT Mastic
156	2'x4' Ceiling Tile
157	Terrazzo Flooring
158	Attic Plaster
159	12"x12" Light Blue w/ Streaks VFT
159M	12"x12" Light Blue w/ Streaks VFT Mastic
160	12"x12" Dark Gray w/ Light Gray Specks VFT
160M	12"x12" Dark Gray w/ Light Gray Specks VFT Mastic
161	9"x9" Green w/ White Streaks VFT
161M	9"x9" Green w/ White Streaks VFT Mastic
162	Decorative Plaster
163	Troweled-on Plaster Walls
164	Spray-on Fireproofing
165	12"x12" White VFT
165M	12"X12" White VFT Mastic
166	12"x12" Black w/ White Specks VFT
166M	12"x12" Black w/ White Specks VFT Mastic
167	12"x12" Yellow Streaked VFT
167M	12"x12" Yellow Streaked VFT Mastic
168	12"x12" Maroon Streaked VFT
168M	12"x12" Maroon Streaked VFT Mastic

169	2'x2' Ceiling Tile w/ Pinholes
170	Pink Ceramic Tile Grout
171	Pink Ceramic Tile Adhesive
172	12X12 Light Blue specked floor tile
172M	12x12 Light Blue specked floor tile and Mastic
173	12X12 Gray with specks
173M	12X12 Gray with specks/ Mastic
19A	WRAP OVER FIBER GLASS
30	1'x1' Ceiling Tile (with Pinholes & Grooves)
30M	Mastic Associated with 1' x 1' White w/ Pinholes and Grooves Celing Tile
31	2'x4' Lay In Ceiling Tile
35	PLASTER
36	Blue Carpet Adhesive
37	Brown Carpet Adhesive
41	Terrazzo
42	Ceramic Tile Grout
43	Ceramic Tile Adhesive
44	Drywall
45	Drywall Compound
46	Tectum Ceiling Panels
47	Chalkboard/Whiteboard Adhesive
48	Vinyl Stair Treads
49	Vinyl Stair Thread Adhesive
50	4" Black Baseboard
51	4" Black Baseboard Adhesive
54	4" Brown Baseboard
55	4" Brown Baseboard Adhesive
58	4" x 4" Floor Tile
59	4" x 4" Floor Tile Mastic
60	Grey and Black Carpet Adhesive
61	Acoustical Ceiling Plaster
62	Pegboard on Walls
64	1 x 1 White w/ Gooves Spline Ceiling Tile
67	9 x 9 VFT Gray w/ streaks VFT
68	9 x 9 VFT Gray w/ Streaks Mastic
69	9 x 9 VFT Green
71	Plaster
72	12 x 12 VFT Gray w/ Balck & White Specks
73	12 x 12 VFT Gray w/ Black & White Specs Mastic
74	9 x 9 VFT Tan (Under HA 147 & 147M)
75	9 x 9 VFT Tan Mastic (Under HA 147 & 147M)
76	9 x9 VFT Dark Brown VFT (Under HA 147 & 147M)
77	9 x 9 VFT Dark Brown Mastic (Under HA 147 & 147M)
78	12 x 12 VFT Tan w/ Brown Specs (Under HA 147 & 147M)

79	12 x 12 VFT Tan w/ Brown Specs Mastic (Under HA 147 & 147M)
80	Gray Linoleum (Under HA 147 & 147M)
81	Gray Linoleum Mastic (Under HA 147 & 147M)
82	12 x 12 VFT Tan Mixed Speckled (Terrazzo Like)
83	12 x 12 VFT Tan Mixed Speckled Mastic (Terrazzo Like)
84	Plaster
85	12 x 12 VFT Beige w/ White Specs (Terrazzo Like)
86	12 x 12 VFT Beige w/ white Specs Mastic (Terrazzo Like)
87	2 x 4 CT White w/ Swirls
88	12 x 12 Black VFT (Terrazzo Like)
89	12 x 12 Black VFT & Mastic (Terrazzo Like)
90	9 x 9 VFT Lt. Brown w/ Specs
91	9 x 9 VFT Lt Brown w/ Specs Mastic
96	12 x 12 VFT Mixed Red Speckled
97	12 x 12 VFT Mixed Red Speckled Mastic
98	1'x1' CT White w/ Holes
99	Terrazzo

The following areas were deemed to be inaccessible:

46	Tectum Ceiling Panels
----	-----------------------

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by , IDPH License # . The Management Plan was updated by , IDPH License # . Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Chicago International Charter - Longwood (South) Building 2420 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	Aircell Pipe Insulation	701	LF	Incinerator Room , Closet by Main Shop, Kitchen, Men's Washroom Closet, 101-201-301 Janitor Closets, Aquinus Ground Floor Corridor, Tunnel leading to Convent, Weight Room & Attic Bldg 1890	AMO	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
05	Preform Pipe Cover (Mag Block Pipe Insulation)	367	LF	Incinerator Room, Tunnel, Main Shop Room, Electric Room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
07	Cardboard Pipe Cover	49	LF	Kitchen and Maintenance Closet	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
08	Aircell Pipe Joint Packing	67	LF	Tunnels and Corridors, Incinerator Room, Closet by Main Shop, Kitchen, Men's Washroom Closet, 101-201-301 Janitor Closets, Weight Room & Attic Bldg 1890	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
09	Preformed Pipe Joint Insulation	44	LF	Incinerator Room, Main Shop Room, Tunnel, Electrical Room, Ground Floor Corridor	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
10	Joint packing on Fiberglass Insulated Piping	30	EA	Incinerator Rm, Tunnel, Basement Sink Room, Pantry and East Lunchroom	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
100	9 x 9 VFT Black w/ Camouflage (under HA# 106 & 107)	400	SF	Rm 358 (A305) Bldg 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
101	9 x 9 VFT Black w/ Camouflage Mastic (under HA 106 & 107)	400	SF	Rm 358 (A305) Bldg. 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
102	9 x 9 VFT Brown (under HA 106 & 107)	400	SF	Rm 358 (A305) Bldg 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
103	9 x 9 VFT Brown Mastic (under HA 106 & 107)	400	SF	Rm 358 (A305) Bldg. 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
104	9 x 9 Brown VFT (under HA 106 & 107)	1,400	SF	Rm 356 and 354 Bldg. 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
105	9 x 9 Brown VFT & Mastic (under HA 106 & 107)	1,400	SF	Rm 356 and 354 Bldg 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
106	12 x 12 Gray VFT Speckled	3,700	SF	Rooms 358, 356, 350, 351, 352, 257, 255, 254, 253, 252, 251, 250, Basement Laundry RM. Bldg 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
107	12 x 12 Gray VFT Speckled Mastic	3,700	SF	Rooms 358, 356, 350, 351, 352, 257, 255, 254, 253, 252, 252, 250, Basement Laundry Rm. Bldg. 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
108	12 x 12 Gray w/ Red, White & Blue Specs VFT	800	SF	Stairwell Bldg 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
109	12 x 12 Gray w/ Red, White and Blue Specs Mastic	800	SF	Stairwell Bldg 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
110	Plaster	28,000	SF	Throughout Bldg 1920	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
111	12 x 12 VFT Beige w/ Black Streaks - (Abated)			Rm 255 Bldg 1920	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
112	12 x 12 VFT Beige w/ Black Streaks Mastic - (Abated)	0		Rm 255 Bldg 1920	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
113	1 x 1 Ceiling Tile white w/ Swirls	2,100	SF	Weight Room and Rm 51 Bldg 1920	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
114	Green Terrazzo	600	SF	Rm 51 Bldg 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
115	Spray On Fireproofing	2,300	SF	Attic Bldg 1890	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
116	Terrazzo	8,000	SF	Throughout Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
117	12 x 12 VFT Gray Speckled	1,200	SF	Rm 114 and 314 Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
118	12 x 12 VFT Gray Speckled Mastic	1,200	SF	Rm 114 and 314 Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
119	1 x 1 CT White w/ Pinhole	29,000	SF	L304, L302B, L306A, L306B, L302A, L307, L318, L317, L308, L313,	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				3rd Floor Corridor, L216, 201, L210, L209, L202, L221, L208, L207, L206, L204, 2nd Floor Corridor, L108, L107, Office L105, Office L104, L126, L121, 1st Floor Corridor, Basement Classroom by LULA Elevator, Book Storage L008, Fire Pump Room L031										
12	Stack Insulation			Incinerator Rm	ABATED	TSI	Y					Any remaining friable ACBM or friable suspect ACBM		
120	9 x9 VFT White w/ gray strks	1,400	SF	Rooms L303, L306A, L306B, L309, Electrical L311, L216, L117, Basement Room Across from Mechanical Room L018 - Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
121	9X9 VFT white with gray streaks	1,400	SF	L204, L303, L306B	ASSUMED	MISC	N	LOC	8		No	ACBM with the potential for damage	3	LOW
122	9 x 9 VFT Black	1,900	SF	Rooms L204, L318, L306B	ASSUMED	MISC	N	LOC	17		No	ACBM with the potential for damage	3	LOW
123	9 x 9 VFT Black Mastic	1,900	SF	Rooms L303, L306A, L306B, L216 - Bldg. 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
124	9 x 9 VFT Pink w/ Black Strks	900	SF	Rooms 307	ASSUMED	MISC	N	LOC	2		No	ACBM with the potential for damage	3	LOW
125	9 x 9 VFT Pink w/ Black Strks Mastic	900	SF	Rooms L307, L317, L221 - Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
126	9 x 9 VFT Dark Gray w/ white strks	600	SF	Rooms L307, L317, - Bldg. 1890	ASSUMED	MISC	N	DIST	22		No	ACBM with the potential for damage	3	LOW
127	9 x 9 VFT Dark Gray w/ white strks Mastic	600	SF	Rooms L307, L318, L317, 205 - Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
128	9 x 9 VFT Dark Pink w/ strks	600	SF	Rooms L318, L317 - Bldg 1890	ASSUMED	MISC	N	LOC	8		No	ACBM with the potential for damage	3	LOW
129	9 x 9 VFT Dark Pink w/ strks Mastic	600	SF	Rooms L318, 205 - Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
13	KEWANEE BOILER COVER - (Abated)	0		MAIN BOILER RM	ABATED	TSI	Y					Any remaining friable ACBM or friable suspect ACBM		
130	12 x 12 VFT Beige Mixed Speckled	2,600	SF	Rooms L213, L202, L107, L125, Teacher's Lounge L113, Copy Room L115 - Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
131	12 x 12 VFT Beige Mixed Speckled Mastic	2,600	SF	Rooms L213, L202, L107, L125, Teacher's Lounge L113, Copy Room L115 - Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
132	9 x 9 VFT Brown	500	SF	Room L209 - Bldg. 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
133	9 x 9 VFT Brown Mastic	500	SF	Room L209 - Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
134	Plaster	25,000	SF	Throughout Bldg 1890	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
135	12 x 12 VFT Purple Speckled	1,800	SF	Cafeteria L009, Basement Hall by Door 31, Basement Women's Toilet Vestibule by Door 31 - Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
136	12 x 12 VFT Purple Speckled Mastic	1,800	SF	Cafeteria L009, Basement Hall by Door 31, Basement Women's Toilet Vestibule near Door 31 - Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
137	12 x 12 VFT Tan w/ Lt Brown Specs	1,800	SF	Cafeteria L009, Basement Hall by Door 31, Basement Women's Toilet Vestibule near Door 31 - 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
138	12 x 12 VFT Tan w/ Light Brown Specs Mastic	1,800	SF	Cafeteria L009, Basement Hall by Door 31, Women's Toilet Vestibule near Door 31 - Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
139	12 x 12 VFT Black - (Abated)			Basement - Bldg 1890	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
140	12 x 12 VFT Black Mastic - (Abated)			Basement - Bldg 1890	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
141	Decorative Stucco	15,000	SF	Throughout Hackman Building	ASSUMED	SURFACE	Y	NONE	0		Yes	ACBM with the potential for damage		LOW
142	12"x12" Gray w/ Black & Gray Specks VFT	2,500	SF	Rooms H303 & Entry Vestibule, H304 & Entry Vestibule, H217, H216, H214, Electrical Room next to Toilet H119, Room H117, and Room by Door 15 - Hackman Building 1930	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
142M	12"x12" Gray w/ Black & Gray Specks VFT Mastic	2,500	SF	Rooms H303 & Entry Vestibule, Room H304 & Entry Vestibule, H217, H216, H214, Electrical Room next to Toilet H119, Room H117, and Room by Door 15 - Hackman Building 1930	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
143	9"x9" Off White w/ Black Streaks VFT	120	SF	Janitor's Closet H233 & H231, Janitor's Closet near Room H122, Janitor's Closet H128 - Hackman Building - 1930	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
143M	9"x9" Off White w/ Black Streaks VFT Mastic	120	SF	Janitor's Closet H233 & H231, Janitor's Closet near Room H122, Janitor's Closet H128 - Hackman Building 1930	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
144	12"x12" Light Blue w/ Streaks VFT	600	SF	2nd Floor Restroom H219, Room H126, 1st Floor Corridor by Door 11 -	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Hackman Building 1930										
144M	12"x12" Light Blue w/ Streaks VFT Mastic	600	SF	2nd Floor Restroom H219, Room H126, 1st Floor Corridor by Door 11 - Hackman Building - 1930	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
145	1'x1' Ceiling Tile w/ Holes	4,500	SF	Auditorium - Hackman Building 1930	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
145M	1'x1' Ceiling Tile w/ Holes Mastic	4,500	SF	Auditorium - Hackman Building 1930	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
146	Decorative Plaster	1,900	SF	Auditorium - Hackman Building 1930	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
147	12"x12" Dark Gray w/ Black & Gray Specks VFT	3,500	SF	Rooms E301, E302, Storage S303, E201, E202, Storage S203 - Edison Building 1955	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
147M	12"x12" Dark Gray w/ Black & Gray Specks VFT Mastic	3,500	SF	Rooms E301, E302, Storage S303, Rooms E201, E202, Storage S203 - Edison Building 1955	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
148	Popcorn Plaster Ceiling	1,600	SF	Rooms 356 & 358 - Aquinas Building 1920	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
149	Green Carpet Mastic	350	SF	Room 152 - Aquinas Building 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
150	12"x12" Light Blue w/ Dark & Light Streaks VFT & Mastic	2,200	SF	Weight Room (Under Rubber Mats) - Aquinas Building 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
150M	12"x12" Light Blue w/ Dark & Light Streaks VFT Mastic	2,200	SF	Weight Room (Under Rubber Mats) - Aquinas Building 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
151	Decorative Plaster	500	SF	1st Floor Corridor by Weight Room	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
152	12"x12" Black w/ White Specks VFT	100	SF	Basement Storage Room next to	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Laundry Room										
152M	12"x12" Black w/ White Specks VFT Mastic	100	SF	Basement Storage Room next to Laundry Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
153	12"x12" Sand VFT	2,100	SF	Basement Classroom A003, A004, and outside Elevator in Basement - Aquinas Building 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
153M	12"x12" Sand VFT Mastic	2,100	SF	Basement Classroom A003, A004, and outside Elevator in Basement - Aquinas Building 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
154	1'x1' White Ceiling Tile	1,200	SF	3rd Floor Corridors - Aquinas Building 1920	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
154M	1'x1' White Ceiling Tile Mastic Pucks	1,200	SF	3rd Floor Corridors - Aquinas Building 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
155	12"x12" Dark Gray w/ Black & Gray Specks VFT & Mastic	3,000	SF	Rooms 148, ND 114, ND 113A, ND 106, ND 105, ND 104, ND 103 - Notre Dame Building 1950	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
155M	12"x12" Dark Gray w/ Black & Gray Specks VFT Mastic	3,000	SF	Rooms 148, ND114, ND113, ND106, ND105, ND104, ND103	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
156	2'x4' Ceiling Tile	1,900	SF	1st Floor Corridor, Entry Vestibule Doors 24 & 3, Rooms 140 and 138 - Notre Dame Building 1950	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
157	Terrazzo Flooring	1,500	SF	1st Floor Corridors, Stairs, Entry Vestibules 24 / 3, Toilets - Notre Dame Building 1950	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
158	Attic Plaster	5,600	SF	Attic - Longwood 1890 Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
159	12"x12" Light Blue w/ Streaks VFT	4,500	SF	Rooms L215 &	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Electrical Room L215, L210, L206, L108, L107, Office L118, L121, Entrance Vestibule by Door 29 - Longwood 1890 Building								potential for damage		
159M	12"x12" Light Blue w/ Streaks VFT Mastic	4,500	SF	Rooms L215 & Electrical Room L215, L210, L206, L108, L107, Office L118, L121, Entrance Vestibule by Door 29 - Longwood 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	MAG BLOCK COVERING - (Abated)			Boiler Room	ABATED	TSI	Y					Any remaining friable ACBM or friable suspect ACBM		
160	12"x12" Dark Gray w/ Light Gray Specks VFT	1,900	SF	Rooms L302A, L302B, L304, L111 - Longwood 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
160M	12"x12" Dark Gray w/ Light Gray Specks VFT Mastic	1,900	SF	Rooms L302A, L302B, L304, L111 - Longwood 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
161	9"x9" Green w/ White Streaks VFT	1,300	SF	Room L209, Offices L105 & L104 (under carpet)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
161M	9"x9" Green w/ White Streaks VFT Mastic	1,300	SF	Room L209, Office L105 & L104 (under the carpet) - Longwood 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
162	Decorative Plaster	900	SF	Rooms L111, Office L112, Teacher's Lounge L113, Conference Room L110, Copy Room L115 - Longwood 1890 Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
163	Troweled-on Plaster Walls	2,500	SF	Basement Corridor, Classroom L006 -	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Longwood 1890 Building										
164	Spray-on Fireproofing	2,900	SF	Basement Small Classroom - Longwood 1890 Building	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
165	12"x12" White VFT	420	SF	Basement Classroom by LULA Elevator - Longwood 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
165M	12"X12" White VFT Mastic	420	SF	Basement Classroom by LULA Elevator - Longwood 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
166	12"x12" Black w/ White Specks VFT	420	SF	Basement Classroom by LULA Elevator - Longwood 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
166M	12"x12" Black w/ White Specks VFT Mastic	420	SF	Basement Classroom by LULA Elevator - Longwood 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
167	12"x12" Yellow Streaked VFT	2,500	SF	Basement Corridors, Hall by Room L006 and Hall by Mechanical Room L018 - Longwood - 1890 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
167M	12"x12" Yellow Streaked VFT Mastic	2,500	SF	Basement Corridors, Hall by Room L006 and Hall by Mechanical Room L018 - Longwood - 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
168	12"x12" Maroon Streaked VFT	1,900	SF	Basement Corridors, Hall by Classroom L006, Hall by Mechanical Room L018, JC L034, Basement JC by Door 31 -	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Longwood 1890 Building										
168M	12"x12" Maroon Streaked VFT Mastic	1,900	SF	Basement Corridors, Hall by Classroom L006, Hall by Mechanical Room L018, JC L034, Basement JC by Door 31 - Longwood 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
169	2'x2' Ceiling Tile w/ Pinholes	1,800	SF	Basement Corridors - Longwood 1890 Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
17	HAND PACKING-ABATED			BOILER RM	ABATED	TSI	Y					Any remaining friable ACBM or friable suspect ACBM		
170	Pink Ceramic Tile Grout	800	SF	Basement Kitchen, Serving Room, Small Lunchroom, Dish Wash Room, Book Storage L008 - Longwood 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
171	Pink Ceramic Tile Adhesive	2,500	SF	Basement Kitchen, Serving Room, Small Lunchroom, Dish Wash Room L025, Book Storage L008 - Longwood - 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
172	12X12 Light Blue specked floor tile	600	SF	L206	ASSUMED	MISC	N	LOC	9			ACBM with the potential for damage		
172M	12x12 Light Blue specked floor tile and Mastic	600	SF	L206	ASSUMED	MISC	N	LOC	9			ACBM with the potential for damage		
173	12X12 Gray with specks	650	SF	L202	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		
173M	12X12 Gray with specks/ Mastic	650	SF	L202	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		
18	HOT WATER HOLDING TANK - (Abated)			BOILER RM	ABATED	TSI	Y					Any remaining friable ACBM or friable suspect ACBM		
19	HOT WATER HOLDING TANK - (Abated)			BOILER ROOM	ABATED	TSI	Y					Any remaining friable ACBM or friable suspect ACBM		

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
19A	WRAP OVER FIBER GLASS	120	LF	HOT WATER HOLDING TANK-BOILER ROOM TUNNEL	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
20	TANK HARD PACKING (Abated)			CONVENT BOILER RM	ABATED	TSI	Y					Any remaining friable ACBM or friable suspect ACBM		
21	COVERED VENT SUPPLYNG COMBUSTION AIR - (Abated)			MAIN BOILER RM	ABATED	TSI	Y					Any remaining friable ACBM or friable suspect ACBM		
22	CANVAS COVERED BLOCK TYPE DUCT - (Abated)			BOILER RM	ABATED	TSI	Y					Any remaining friable ACBM or friable suspect ACBM		
23	PIPE JOINTS - (Abated)	0		BOILER ROOM	ABATED	TSI	Y					Any remaining friable ACBM or friable suspect ACBM		
26	LIGHT CORDS	150	LF	AUDITORIUM - Hackman Building 1930	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	ACOUSTIC PLASTER	2,500	SF	CONVENT CHAPEL	CHR	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
30	1'x1' Ceiling Tile (with Pinholes & Grooves)	6,500	SF	Cafeteria L009, Hall by Door 31	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
30M	Mastic Associated with 1' x 1' White w/ Pinholes and Grooves Ceiling Tile	6,500	SF	Cafeteria, L009, Hall by Door 31	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	2x4' Lay In Ceiling Tile	5,000	SF	Rooms 253, 251 250, 254, 255, 257, 356 - Aquinas Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
33	12" x 12" Floor Tile Tan Mixed Speckled	10,580	SF	Ground Floor Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116, 124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, m, Washrooms, Classrooms, Corridors, Stairs,	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	9"x9" Floor Tile	37,796	SF	Ground Floor	CHR	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116, 124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, Reading Room, Washrooms, 178, 282, Corridors, Stairs								potential for damage		
35	PLASTER	1,495,000	SF	Throughout All Buildings	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
36	Blue Carpet Adhesive	1,500	SF	Offices L105, L104, L132, L112 - 1890 Building Longwood	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	Brown Carpet Adhesive	120	SF	Office L212	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	Purple Carpet Adhesive - (Abated)			Music Room	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
39	Brown Striped Carpet Adhesive - (Abated)			Room 277	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
40	Purple Carpet Adhesive - (Abated)			Room 132	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
41	Terrazzo	12,000	SF	Stairwells, Basement Lunchroom, Book Storage 008, Fire Pump Room L031, Electrical Room L022, Kitchen Office L024, Kitchen Staff Toilet L029, Classroom L006	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	Ceramic Tile Grout	2,746	SF	Washrooms All Floors - 1890 Building Longwood	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	Ceramic Tile Adhesive	2,746	SF	Washrooms All Floors - 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
44	Drywall	1,350	SF	Building Longwood Throughout Facility Including: Ground Floor Pantry, Corridor by Rooms 402-404, Room 281	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	Drywall Compound	1,350	SF	Throughout Facility Including: Ground Floor Pantry, Corridor by Rooms 402-404, Room 281	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	Tectum Ceiling Panels	5,457	SF	Gym - 1920 Building Aquinas	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
47	Chalkboard/Whiteboard Adhesive	7,200	SF	Classrooms Throughout Facility	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	Vinyl Stair Treads	582	SF	Stairways - 1920 Building Aquinas	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	Vinyl Stair Thread Adhesive	582	SF	Stairways - 1920 Building Aquinas	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	4" Black Baseboard	701	LF	West Lunchroom, 051, 054, 281 - 1890 Building Longwood	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	4" Black Baseboard Adhesive	701	LF	West Lunchroom, 051, 054, 281 - 1890 Building Longwood	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	6" Brown Baseboard (Abated)			Women's Ground Floor Washroom	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
53	6" Brown Basebord Adhesive (Abated)			Women's Ground Floor Washroom	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
54	4" Brown Baseboard	316	LF	Ground Floor Security Office and East Cafeteria - 1890 Building Longwood	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	4" Brown Baseboard Adhesive	316	LF	Ground Floor Security Office and East Cafeteria - 1890 Building Longwood	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	4" Grey Baseboard (Abated)			Room 351	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
57	4" Gray Baseboard Adhesive (Abated)			Room 351	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
58	4" x 4" Floor Tile	25	SF	Elevator in Aquinas 1920 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	4" x 4" Floor Tile Mastic	25	SF	Elevator in Aquinus 1920 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60	Grey and Black Carpet Adhesive	2,156	SF	Auditorium - Hackman Building 1930	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	Acoustical Ceiling Plaster	1,725	SF	Auditorium - Hackman Building 1930	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
62	Pegboard on Walls	1,960	SF	Teacher's Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	1 x 1 CT White (Removed)			Rm 126, Bldg 1950-Notre Dame	ABATED	MISC	Y					Any remaining friable ACBM or friable suspect ACBM		
64	1 x 1 White w/ Grooves Spline Ceiling Tile	4,000	SF	Rooms 148, ND 114 (146), ND 113, ND 106, ND 122, ND 125, ND 104, ND 103 - 1950 Building Notre Dame	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
65	12 x 12 VFT Tan Mixed Speckled (Abated)			Rm 126 Bldg 1950 Notre Dame	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
66	12 x 12 VFT Tan Mixed Speckled Mastic (Abated)		SF	Rm 126 Bldg 1950 Notre Dame	ABATED	MISC	N				No	Any remaining friable ACBM or friable suspect ACBM		LOW
67	9 x 9 VFT Gray w/ streaks VFT	2,000	SF	L209	ASSUMED	MISC	N	LOC	13		No	ACBM with the potential for damage	3	LOW
68	9 x 9 VFT Gray w/ Streaks Mastic	600	SF	Rooms 146, 140, 138, 129 - Bldg 1950 Notre Dame	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69	9 x 9 VFT Green	1,000	SF	Rm L209	ASSUMED	MISC	N	LOC	12			ACBM with the potential for damage	3	
70	9 x 9 VFT Green Mastic (Abated)	0		Rm 128, 130, 144, 146 Bldg 1950 Notre Dame	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
71	Plaster	10,000	SF	Throughout Bldg 1950 Notre Dame	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
72	12 x 12 VFT Gray w/ Balck & White Specks	500	SF	Stairway Bldg 1955 Eddison	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
73	12 x 12 VFT Gray w/ Black & White Specs Mastic	500	SF	Stairway Bldg 1955 Edison	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
74	9 x 9 VFT Tan (Under HA 147 & 147M)	100	SF	Rooms E201 and E202 - Bldg 1955 Edison	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
75	9 x 9 VFT Tan Mastic (Under HA 147 & 147M)	100	SF	Rooms E201 and E202 - Bldg 1955 Edison	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
76	9 x9 VFT Dark Brown VFT (Under HA 147 & 147M)	1,200	SF	Rooms E201 and E202 - Bldg 1955 Edison	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
77	9 x 9 VFT Dark Brown Mastic (Under HA 147 & 147M)	1,200	SF	Rooms E201 and E202 - Bldg 1955 Edison	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
78	12 x 12 VFT Tan w/ Brown Specs (Under HA 147 & 147M)	1,200	SF	Rooms E301 & E302 - Bldg. 1955 Edison	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
79	12 x 12 VFT Tan w/ Brown Specs Mastic (Under HA 147 & 147M)	1,200	SF	Rooms E301 and E302 - Bldg 1955 Edison	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
80	Gray Linoleum (Under HA 147 & 147M)	60	SF	Rm 330 Closet Bldg 1955 (Edison)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
81	Gray Linoleum Mastic (Under HA 147 & 147M)	60	SF	Rm 330 Closet Bldg 1955 (Edison)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
82	12 x 12 VFT Tan Mixed Speckled (Terrazzo Like)	2,000	SF	Rm 54, 56, 22 HH, 03 HH, Bldg 1930 Hackman	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
83	12 x 12 VFT Tan Mixed Speckled Mastic (Terrazzo Like)	2,000	SF	Rm 54, 56, 22HH, 03 HH, Bldg 1930 Hackman	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
84	Plaster	14,000	SF	Throughout Bldg 1930 Hackman	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
85	12 x 12 VFT Beige w/ White Specs (Terrazzo Like)	17,000	SF	1st and 2nd Floor Corridor, Auditorium and Stairs and 23H - 1930 Hackman Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
86	12 x 12 VFT Beige w/ white Specs Mastic (Terrazzo Like)	17,000	SF	1st and 2nd Floor Corridor, Auditorium and Stairs and 23H 1930 Hackman Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
87	2 x 4 CT White w/ Swirls	1,300	SF	Rooms H303 and	ASSUMED	MISC	Y	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				H304 - Bldg 1930 Hackman								potential for damage		
88	12 x 12 Black VFT (Terrazzo Like)	7,800	SF	1st and 2nd Flr Corridor and Auditorium Bldg 1930 Hackman	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
89	12 x 12 Black VFT & Mastic (Terrazzo Like)	7,800	SF	1st and 2nd Floor Corridor and Auditorium - Bldg 1930 Hackman	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
90	9 x 9 VFT Lt. Brown w/ Specs	350	SF	Rooms H212, 215, H122 - Bldg 1930 Hackman	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
91	9 x 9 VFT Lt Brown w/ Specs Mastic	350	SF	Rooms H212, 215, H122 - Bldg 1930 Hackman	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
92	12 x 12 VFT Lt Brown w/ Mixed Specs (Abated)			Rm HH-1 Bldg 1930	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
93	12 x 12 VFT Lt Brown w/ mixed specs Mastic (Abated)			Rm HH-1 Bldg 1930	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
94	12 x 12 VFT Gray w/ white & Black Specs (Abated)			HH - 13 Bldg 1930	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
95	12 x12 VFT Gray w/ White & Black Specs Mastic (Abated)		SF	HH - 13 Bldg 1930	ABATED	MISC	N	NONE			No			
96	12 x 12 VFT Mixed Red Speckled	500	SF	Rm 362 - Bldg 1920 Aquinas	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
97	12 x 12 VFT Mixed Red Speckled Mastic	500	SF	Rm 362 - Bldg 1920 Aquinas	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
98	1'x1' CT White w/ Holes	2,600	SF	Throughout 1920 Bldg Aquinas	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
99	Terrazzo	6,500	SF	Rooms 363, 352, 350, 3rd Floor East Stairwell - Bldg 1920 Aquinas	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
MM1	9" x 9" Floor Tile Mastic	37,796	SF	Ground Floor Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116,	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, Reading Room, Washrooms, 178, 282, Corridors, Stairs										
MM2	12" x 12" Floor Tile Mastic			Classrooms, Teachers Lounge, W Cafeteria, Ground Floor Corridor & Entries, Auditorium Entrance & Foyer, Reading Room, Staff Washrooms, Corridors, and Classrooms	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

Reinspection Date Inspector Name Inspector's IDPH License Number / Expiration Date	Inspector's Comments
HA Number:	Inspector Comments:
01	
05	
07	
08	
09	
10	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
110	
111	
112	
113	
114	
115	
116	
117	

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
118	
119	
12	
120	
121	
122	
123	
124	
125	
126	
127	
128	
129	
13	
130	
131	
132	
133	
134	
135	
136	
137	
138	
139	
140	
141	
142	
142M	
143	

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
143M	
144	
144M	
145	
145M	
146	
147	
147M	
148	
149	
150	
150M	
151	
152	
152M	
153	
153M	
154	
154M	
155	
155M	
156	
157	
158	
159	
159M	
16	
160	
160M	

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
161	
161M	
162	
163	
164	
165	
165M	
166	
166M	
167	
167M	
168	
168M	
169	
17	
170	
171	
172	
172M	
173	
173M	
18	
19	
19A	
20	
21	
22	
23	
26	

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
29	
30	
30M	
31	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
80	
81	
82	
83	
84	
85	
86	

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
87	
88	
89	
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
MM1	
MM2	

Table II
Management Planner's Review

Chicago Public Schools

School Chicago International Charter - Longwood (South)
Address 1309 W.95th St (9500S) 43

Unit 66061

Building ID 2420

Chicago, IL, 60643

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	Aircell Pipe Insulation	701	LF	Incinerator Room , Closet by Main Shop, Kitchen, Men's Washrrom Closet, 101-201-301 Janitor Closets, Aquinus Ground Floor Corridor, Tunnel leading to Convent, Weight Room & Attic Bldg 1890	Amosite	TSI	Yes	0	LF	6 ACBM with the potential for damage	
05	Preform Pipe Cover (Mag Block Pipe Insulation)	367	LF	Incinerator Room, Tunnel, Main Shop Room, Electric Room	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	
07	Cardboard Pipe Cover	49	LF	Kitchen and Maintenance Closet	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	
08	Aircell Pipe Joint Packing	67	LF	Tunnels and Corridors, Incinerator Room, Closet by Main Shop, Kitchen, Men's Washroom Closet, 101-201-301 Janitor Closets, Weight Room & Attic Bldg 1890	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	
09	Preformed Pipe Joint Insulation	44	LF	Incinerator Room, Main Shop Room, Tunnel, Electrical Room, Ground Floor Corridor	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	
10	Joint packing on Fiberglass Insulated Piping	30	EA	Incinerator Rm, Tunnel, Basement Sink Room, Pantry and East Lunchroom	Chrysotile	TSI	Yes	0	EA	6 ACBM with the potential for damage	
100	9 x 9 VFT Black w/ Camoflouge (under HA# 106 & 107)	400	SF	Rm 358 (A305) Bldg 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
101	9 x 9 VFT Black w/ Camouflouge Mastic (under HA 106 & 107)	400	SF	Rm 358 (A305) Bldg. 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
102	9 x 9 VFT Brown (under HA 106 & 107)	400	SF	Rm 358 (A305) Bldg 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
103	9 x 9 VFT Brown Mastic (under HA 106 & 107)	400	SF	Rm 358 (A305) Bldg. 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
104	9 x 9 Brown VFT (under HA 106 & 107)	1,400	SF	Rm 356 and 354 Bldg. 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
105	9 x 9 Brown VFT & Mastic (under HA 106 & 107)	1,400	SF	Rm 356 and 354 Bldg 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
106	12 x 12 Gray VFT Speckled	3,700	SF	Rooms 358, 356, 350, 351, 352, 257, 255, 254, 253, 252, 251, 250, Basement Laundry RM. Bldg 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
107	12 x 12 Gray VFT Speckled Mastic	3,700	SF	Rooms 358, 356, 350, 351, 352, 257, 255, 254, 253, 252, 252, 250, Basement Laundry Rm. Bldg. 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
108	12 x 12 Gray w/ Red, White & Blue Specs VFT	800	SF	Stairwell Bldg 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	

Chicago Public Schools

School Chicago International Charter - Longwood (South)
Address 1309 W.95th St (9500S) 43

Unit 66061

Building ID 2420

Chicago, IL, 60643

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
109	12 x 12 Gray w/ Red, White and Blue Specs Mastic	800	SF	Stairwell Bldg 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
110	Plaster	28,000	SF	Throughout Bldg 1920	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	
111	12 x 12 VFT Beige w/ Black Streaks - (Abated)			Rm 255 Bldg 1920	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
112	12 x 12 VFT Beige w/ Black Streaks Mastic - (Abated)	0		Rm 255 Bldg 1920	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
113	1 x 1 Ceiling Tile white w/ Swirls	2,100	SF	Weight Room and Rm 51 Bldg 1920	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	
114	Green Terrazzo	600	SF	Rm 51 Bldg 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
115	Spray On Fireproofing	2,300	SF	Attic Bldg 1890	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	
116	Terrazzo	8,000	SF	Throughout Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
117	12 x 12 VFT Gray Speckled	1,200	SF	Rm 114 and 314 Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
118	12 x 12 VFT Gray Speckled Mastic	1,200	SF	Rm 114 and 314 Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
119	1 x 1 CT White w/ Pinhole	29,000	SF	L304, L302B, L306A, L306B, L302A, L307, L318, L317, L308, L313, 3rd Floor Corridor, L216, 201, L210, L209, L202, L221, L208, L207, L206, L204, 2nd Floor Corridor, L108, L107, Office L105, Office L104, L126, L121, 1st Floor Corridor, Basement Classroom by LULA Elevator, Book Storage L008, Fire Pump Room L031	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	
12	Stack Insulation			Incinerator Rm	Abated	TSI	Yes			7 Any remaining friable ACBM or friable suspect ACBM	
120	9 x9 VFT White w/ gray strks	1,400	SF	Rooms L303, L306A, L306B, L309, Electrical L311, L216, L117, Basement Room Across from Mechanical Room L018 - Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
121	9X9 VFT white with gray streaks	1,400	SF	L204, L303, L306B	Assumed	MISC	No	8	SF	6 ACBM with the potential for damage	
122	9 x 9 VFT Black	1,900	SF	Rooms L204, L318, L306B	Assumed	MISC	No	17	SF	6 ACBM with the potential for damage	
123	9 x 9 VFT Black Mastic	1,900	SF	Rooms L303, L306A, L306B, L216 - Bldg. 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
124	9 x 9 VFT Pink w/ Black Strks	900	SF	Rooms 307	Assumed	MISC	No	2	SF	6 ACBM with the potential for damage	
125	9 x 9 VFT Pink w/ Black Strks Mastic	900	SF	Rooms L307, L317, L221 - Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
126	9 x 9 VFT Dark Gray w/ white strks	600	SF	Rooms L307, L317, - Bldg. 1890	Assumed	MISC	No	22	SF	6 ACBM with the potential for damage	

Chicago Public Schools

School Chicago International Charter - Longwood (South)
Address 1309 W.95th St (9500S) 43

Unit 66061

Chicago, IL, 60643

Building ID 2420

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
127	9 x 9 VFT Dark Gray w/ white strks Mastic	600	SF	Rooms L307, L318, L317, 205 - Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
128	9 x 9 VFT Dark Pink w/ strks	600	SF	Rooms L318, L317 - Bldg 1890	Assumed	MISC	No	8	SF	6 ACBM with the potential for damage	
129	9 x 9 VFT Dark Pink w/ strks Mastic	600	SF	Rooms L318, 205 - Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
13	KEWANEE BOILER COVER - (Abated)	0		MAIN BOILER RM	Abated	TSI	Yes			7 Any remaining friable ACBM or friable suspect ACBM	
130	12 x 12 VFT Beige Mixed Speckled	2,600	SF	Rooms L213, L202, L107, L125, Teacher's Lounge L113, Copy Room L115 - Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
131	12 x 12 VFT Beige Mixed Speckled Mastic	2,600	SF	Rooms L213, L202, L107, L125, Teacher's Lounge L113, Copy Room L115 - Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
132	9 x 9 VFT Brown	500	SF	Room L209 - Bldg. 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
133	9 x 9 VFT Brown Mastic	500	SF	Room L209 - Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
134	Plaster	25,000	SF	Throughout Bldg 1890	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	
135	12 x 12 VFT Purple Speckled	1,800	SF	Cafeteria L009, Basement Hall by Door 31, Basement Women's Toilet Vestibule by Door 31 - Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
136	12 x 12 VFT Purple Speckled Mastic	1,800	SF	Cafeteria L009, Basement Hall by Door 31, Basement Women's Toilet Vestibule near Door 31 - Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
137	12 x 12 VFT Tan w/ Lt Brown Specs	1,800	SF	Cafeteria L009, Basement by Door 31, Basement Women's Toilet Vestibule near Door 31 - 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
138	12 x 12 VFT Tan w/ Light Brown Specs Mastic	1,800	SF	Cafeteria L009, Basement Hall by Door 31, Women's Toilet Vestibule near Door 31 - Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
139	12 x 12 VFT Black - (Abated)			Basement - Bldg 1890	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
140	12 x 12 VFT Black Mastic - (Abated)			Basement - Bldg 1890	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
141	Decorative Stucco	15,000	SF	Throughout Hackman Building	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	
142	12"x12" Gray w/ Black & Gray Specks VFT	2,500	SF	Rooms H303 & Entry Vestibule, H304 & Entry Vestibule, H217, H216, H214,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	

Chicago Public Schools

School Chicago International Charter - Longwood (South)
Address 1309 W.95th St (9500S) 43

Unit 66061

Chicago, IL, 60643

Building ID 2420

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Electrical Room next to Toilet H119, Room H117, and Room by Door 15 - Hackman Building 1930							
142M	12"x12" Gray w/ Black & Gray Specks VFT Mastic	2,500	SF	Rooms H303 & Entry Vestibule, Room H304 & Entry Vestibule, H217, H216, H214, Electrical Room next to Toilet H119, Room H117, and Room by Door 15 - Hackman Building 1930	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
143	9"x9" Off White w/ Black Streaks VFT	120	SF	Janitor's Closet H233 & H231, Janitor's Closet near Room H122, Janitor's Closet H128 - Hackman Building - 1930	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
143M	9"x9" Off White w/ Black Streaks VFT Mastic	120	SF	Janitor's Closet H233 & H231, Janitor's Closet near Room H122, Janitor's Closet H128 - Hackman Building 1930	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
144	12"x12" Light Blue w/ Streaks VFT	600	SF	2nd Floor Restroom H219, Room H126, 1st Floor Corridor by Door 11 - Hackman Building 1930	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
144M	12"x12" Light Blue w/ Streaks VFT Mastic	600	SF	2nd Floor Restroom H219, Room H126, 1st Floor Corridor by Door 11 - Hackman Building - 1930	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
145	1'x1' Ceiling Tile w/ Holes	4,500	SF	Auditorium - Hackman Building 1930	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	
145M	1'x1' Ceiling Tile w/ Holes Mastic	4,500	SF	Auditorium - Hackman Building 1930	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
146	Decorative Plaster	1,900	SF	Auditorium - Hackman Building 1930	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	
147	12"x12" Dark Gray w/ Black & Gray Specks VFT	3,500	SF	Rooms E301, E302, Storage S303, E201, E202, Storage S203 - Edison Building 1955	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
147M	12"x12" Dark Gray w/ Black & Gray Specks VFT Mastic	3,500	SF	Rooms E301, E302, Storage S303, Rooms E201, E202, Storage S203 - Edison Building 1955	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
148	Popcorn Plaster Ceiling	1,600	SF	Rooms 356 & 358 - Aquinas Building 1920	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	
149	Green Carpet Mastic	350	SF	Room 152 - Aquinas Building 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
150	12"x12" Light Blue w/ Dark & Light Streaks VFT & Mastic	2,200	SF	Weight Room (Under Rubber Mats) - Aquinas Building 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	

Chicago Public Schools

School Chicago International Charter - Longwood (South)
Address 1309 W.95th St (9500S) 43

Unit 66061

Building ID 2420

Chicago, IL, 60643

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
150M	12"x12" Light Blue w/ Dark & Light Streaks VFT Mastic	2,200	SF	Weight Room (Under Rubber Mats) - Aquinas Building 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
151	Decorative Plaster	500	SF	1st Floor Corridor by Weight Room	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	
152	12"x12" Black w/ White Specks VFT	100	SF	Basement Storage Room next to Laundry Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
152M	12"x12" Black w/ White Specks VFT Mastic	100	SF	Basement Storage Room next to Laundry Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
153	12"x12" Sand VFT	2,100	SF	Basement Classroom A003, A004, and outside Elevator in Basement - Aquinas Building 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
153M	12"x12" Sand VFT Mastic	2,100	SF	Basement Classroom A003, A004, and outside Elevator in Basement - Aquinas Building 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
154	1'x1' White Ceiling Tile	1,200	SF	3rd Floor Corridors - Aquinas Building 1920	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	
154M	1'x1' White Ceiling Tile Mastic Pucks	1,200	SF	3rd Floor Corridors - Aquinas Building 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
155	12"x12" Dark Gray w/ Black & Gray Specks VFT & Mastic	3,000	SF	Rooms 148, ND 114, ND 1134, ND 106, ND 105, ND 104, ND 103 - Notre Dame Building 1950	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
155M	12"x12" Dark Gray w/ Black & Gray Specks VFT Mastic	3,000	SF	Rooms 148, ND114, ND113, ND106, ND105, ND104, ND103	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
156	2'x4' Ceiling Tile	1,900	SF	1st Floor Corridor, Entry Vestibule Doors 24 & 3, Rooms 140 and 138 - Notre Dame Building 1950	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	
157	Terrazzo Flooring	1,500	SF	1st Floor Corridors, Stairs, Entry Vestibules 24 / 3, Toilets - Notre Dame Building 1950	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
158	Attic Plaster	5,600	SF	Attic - Longwood 1890 Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	
159	12"x12" Light Blue w/ Streaks VFT	4,500	SF	Rooms L215 & Electrical Room L215, L210, L206, L108, L107, Office L118, L121, Entrance Vestibule by Door 29 - Longwood 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
159M	12"x12" Light Blue w/ Streaks VFT Mastic	4,500	SF	Rooms L215 & Electrical Room L215,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	

Chicago Public Schools

School Chicago International Charter - Longwood (South)
Address 1309 W.95th St (9500S) 43

Unit 66061

Building ID 2420

Chicago, IL, 60643

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				L210, L206, L108, L107, Office L118, L121, Entrance Vestibule by Door 29 - Longwood 1890 Building							
16	MAG BLOCK COVERING - (Abated)			Boiler Room	Abated	TSI	Yes			7 Any remaining friable ACBM or friable suspect ACBM	
160	12"x12" Dark Gray w/ Light Gray Specks VFT	1,900	SF	Rooms L302A, L302B, L304, L111 - Longwood 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
160M	12"x12" Dark Gray w/ Light Gray Specks VFT Mastic	1,900	SF	Rooms L302A, L302B, L304, L111 - Longwood 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
161	9"x9" Green w/ White Streaks VFT	1,300	SF	Room L209, Offices L105 & L104 (under carpet)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
161M	9"x9" Green w/ White Streaks VFT Mastic	1,300	SF	Room L209, Office L105 & L104 (under the carpet) - Longwood 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
162	Decorative Plaster	900	SF	Rooms L111, Office L112, Teacher's Lounge L113, Conference Room L110, Copy Room L115 - Longwood 1890 Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	
163	Troweled-on Plaster Walls	2,500	SF	Basement Corridor, Classroom L006 - Longwood 1890 Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	
164	Spray-on Fireproofing	2,900	SF	Basement Small Lunchroom - Longwood 1890 Building	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	
165	12"x12" White VFT	420	SF	Basement Classroom by LULA Elevator - Longwood 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
165M	12"X12" White VFT Mastic	420	SF	Basement Classroom by LULA Elevator - Longwood 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
166	12"x12" Black w/ White Specks VFT	420	SF	Basement Classroom by LULA Elevator - Longwood 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
166M	12"x12" Black w/ White Specks VFT Mastic	420	SF	Basement Classroom by LULA Elevator - Longwood 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
167	12"x12" Yellow Streaked VFT	2,500	SF	Basement Corridors, Hall by Room L006 and Hall by Mechanical Room L018 - Longwood - 1890 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
167M	12"x12" Yellow Streaked VFT Mastic	2,500	SF	Basement Corridors, Hall by Room L006 and Hall by Mechanical Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	

Chicago Public Schools

School Chicago International Charter - Longwood (South)
Address 1309 W.95th St (9500S) 43

Unit 66061

Chicago, IL, 60643

Building ID 2420

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				L018 - Longwood 1890 Building							
168	12"x12" Maroon Streaked VFT	1,900	SF	Basement Corridors, Hall by Classroom L006, Hall by Mechanical Room L018, JC L034, Basement JC by Door 31 - Longwood 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
168M	12"x12" Maroon Streaked VFT Mastic	1,900	SF	Basement Corridors, Hall by Classroom L006, Hall by Mechanical Room L018, JC L034, Basement JC by Door 31 - Longwood 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
169	2'x2' Ceiling Tile w/ Pinholes	1,800	SF	Basement Corridors - Longwood 1890 Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	
17	HAND PACKING-ABATED			BOILER RM	Abated	TSI	Yes			7 Any remaining friable ACBM or friable suspect ACBM	
170	Pink Ceramic Tile Grout	800	SF	Basement Kitchen, Serving Room, Small Lunchroom, Dish Wash Room, Book Storage L008 - Longwood 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
171	Pink Ceramic Tile Adhesive	2,500	SF	Basement Kitchen, Serving Room, Small Lunchroom, Dish Wash Room L025, Book Storage L008 - Longwood - 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
172	12X12 Light Blue specked floor tile	600	SF	L206	Assumed	MISC	No	9	SF	6 ACBM with the potential for damage	
172M	12x12 Light Blue specked floor tile and Mastic	600	SF	L206	Assumed	MISC	No	9	SF	6 ACBM with the potential for damage	
173	12X12 Gray with specks	650	SF	L202	Assumed	MISC	No		SF	6 ACBM with the potential for damage	
173M	12X12 Gray with specks/ Mastic	650	SF	L202	Assumed	MISC	No		SF	6 ACBM with the potential for damage	
18	HOT WATER HOLDING TANK - (Abated)			BOILER RM	Abated	TSI	Yes			7 Any remaining friable ACBM or friable suspect ACBM	
19	HOT WATER HOLDING TANK - (Abated)			BOILER ROOM	Abated	TSI	Yes			7 Any remaining friable ACBM or friable suspect ACBM	
19A	WRAP OVER FIBER GLASS	120	LF	HOT WATER HOLDING TANK- BOILER ROOM TUNNEL	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	
20	TANK HARD PACKING (Abated)			CONVENT BOILER RM	Abated	TSI	Yes			7 Any remaining friable ACBM or friable suspect ACBM	
21	COVERED VENT SUPPLYNG COMBUSTION AIR			MAIN BOILER RM	Abated	TSI	Yes			7 Any remaining friable ACBM or friable	

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Chicago, IL, 60643** **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone: _____ Fax: _____

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	- (Abated)									suspect ACBM	
22	CANVAS COVERED BLOCK TYPE DUCT - (Abated)			BOILER RM	Abated	TSI	Yes			7 Any remaining friable ACBM or friable suspect ACBM	
23	PIPE JOINTS - (Abated)	0		BOILER ROOM	Abated	TSI	Yes			7 Any remaining friable ACBM or friable suspect ACBM	
26	LIGHT CORDS	150	LF	AUDITORIUM - Hackman Building 1930	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	
29	ACOUSTIC PLASTER	2,500	SF	CONVENT CHAPEL	Chrysotile	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	
30	1'x1' Ceiling Tile (with Pinholes & Grooves)	6,500	SF	Cafeteria L009, Hall by Door 31	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	
30M	Mastic Associated with 1' x 1' White w/ Pinholes and Grooves Ceiling Tile	6,500	SF	Cafeteria, L009, Hall by Door 31	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
31	2'x4' Lay In Ceiling Tile	5,000	SF	Rooms 253, 251 250, 254, 255, 257, 356 - Aquinas Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	
33	12" x 12" Floor Tile Tan Mixed Speckled	10,580	SF	Ground Floor Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116, 124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, m, Washrooms, Classrooms, Corridors, Stairs,	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
34	9"x9" Floor Tile	37,796	SF	Ground Floor Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116, 124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, Reading Room, Washrooms, 178, 282, Corridors, Stairs	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
35	PLASTER	1,495,000	SF	Throughout All Buildings	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	
36	Blue Carpet Adhesive	1,500	SF	Offices L105, L104, L132, L112 - 1890 Building Longwood	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
37	Brown Carpet Adhesive	120	SF	Office L212	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
38	Purple Carpet Adhesive - (Abated)			Music Room	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
39	Brown Striped Carpet Adhesive - (Abated)			Room 277	Abated	MISC	No			7 Any remaining friable ACBM or friable	

Chicago Public Schools

School Chicago International Charter - Longwood (South)
Address 1309 W.95th St (9500S) 43

Unit 66061

Building ID 2420

Chicago, IL, 60643

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
40	Purple Carpet Adhesive - (Abated)			Room 132	Abated	MISC	No			suspect ACBM	
41	Terrazzo	12,000	SF	Stairwells, Basement Lunchroom, Book Storage 008, Fire Pump Room L031, Electrical Room L022, Kitchen Office L024, Kitchen Staff Toilet L029, Classroom L006	Assumed	MISC	No	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
42	Ceramic Tile Grout	2,746	SF	Washrooms All Floors - 1890 Building Longwood	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
43	Ceramic Tile Adhesive	2,746	SF	Washrooms All Floors - 1890 Building Longwood	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
44	Drywall	1,350	SF	Throughout Facility Including: Ground Floor Pantry, Corridor by Rooms 402-404, Room 281	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
45	Drywall Compound	1,350	SF	Throughout Facility Including: Ground Floor Pantry, Corridor by Rooms 402-404, Room 281	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
46	Tectum Ceiling Panels	5,457	SF	Gym - 1920 Building Aquinas	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	
47	Chalkboard/Whiteboard Adhesive	7,200	SF	Classrooms Throughout Facility	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
48	Vinyl Stair Treads	582	SF	Stairways - 1920 Building Aquinas	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
49	Vinyl Stair Thread Adhesive	582	SF	Stairways - 1920 Building Aquinas	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
50	4" Black Baseboard	701	LF	West Lunchroom, 051, 054, 281 - 1890 Building Longwood	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
51	4" Black Baseboard Adhesive	701	LF	West Lunchroom, 051, 054, 281 - 1890 Building Longwood	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
52	6" Brown Baseboard (Abated)			Women's Ground Floor Washroom	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
53	6" Brown Basebord Adhesive (Abated)			Women's Ground Floor Washroom	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
54	4" Brown Baseboard	316	LF	Ground Floor Security Office and East Cafeteria - 1890 Building Longwood	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
55	4" Brown Baseboard Adhesive	316	LF	Ground Floor Security Office and East Cafeteria - 1890 Building Longwood	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	

Chicago Public Schools

School Chicago International Charter - Longwood (South)
Address 1309 W.95th St (9500S) 43

Unit 66061

Chicago, IL, 60643

Building ID 2420

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
56	4" Grey Baseboard (Abated)			Room 351	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
57	4" Gray Baseboard Adhesive (Abated)			Room 351	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
58	4" x 4" Floor Tile	25	SF	Elevator in Aquinas 1920 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
59	4" x 4" Floor Tile Mastic	25	SF	Elevator in Aquinas 1920 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
60	Grey and Black Carpet Adhesive	2,156	SF	Auditorium - Hackman Building 1930	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
61	Acoustical Ceiling Plaster	1,725	SF	Auditorium - Hackman Building 1930	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	
62	Pegboard on Walls	1,960	SF	Teacher's Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
63	1 x 1 CT White (Removed)			Rm 126, Bldg 1950- Notre Dame	Abated	MISC	Yes			7 Any remaining friable ACBM or friable suspect ACBM	
64	1 x 1 White w/ Grooves Spline Ceiling Tile	4,000	SF	Rooms 148, ND 114 (146), ND 113, ND 106, ND 122, ND 125, ND 104, ND 103 - 1950 Building Notre Dame	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	
65	12 x 12 VFT Tan Mixed Speckled (Abated)			Rm 126 Bldg 1950 Notre Dame	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
66	12 x 12 VFT Tan Mixed Speckled Mastic (Abated)		SF	Rm 126 Bldg 1950 Notre Dame	Abated	MISC	No		SF	7 Any remaining friable ACBM or friable suspect ACBM	
67	9 x 9 VFT Gray w/ streaks VFT	2,000	SF	L209	Assumed	MISC	No	13	SF	6 ACBM with the potential for damage	
68	9 x 9 VFT Gray w/ Streaks Mastic	600	SF	Rooms 146, 140, 138, 129 - Bldg 1950 Notre Dame	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
69	9 x 9 VFT Green	1,000	SF	Rm L209	Assumed	MISC	No	12	SF	6 ACBM with the potential for damage	
70	9 x 9 VFT Green Mastic (Abated)	0		Rm 128, 130, 144, 146 Bldg 1950 Notre Dame	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
71	Plaster	10,000	SF	Throughout Bldg 1950 Notre Dame	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	
72	12 x 12 VFT Gray w/ Balck & White Specks	500	SF	Stairway Bldg 1955 Eddison	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
73	12 x 12 VFT Gray w/ Black & White Specs Mastic	500	SF	Stairway Bldg 1955 Eddison	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
74	9 x 9 VFT Tan (Under HA 147 & 147M)	100	SF	Rooms E201 and E202 - Bldg 1955 Edison	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
75	9 x 9 VFT Tan Mastic (Under HA 147 & 147M)	100	SF	Rooms E201 and E202 - Bldg 1955 Edison	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
76	9x9 VFT Dark Brown VFT (Under HA 147 & 147M)	1,200	SF	Rooms E201 and E202 - Bldg 1955 Edison	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
77	9 x 9 VFT Dark Brown Mastic (Under HA 147 &	1,200	SF	Rooms E201 and E202 - Bldg 1955	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	

Chicago Public Schools

School Chicago International Charter - Longwood (South)
Address 1309 W.95th St (9500S) 43

Unit 66061

Chicago, IL, 60643

Building ID 2420

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	147M)			Edison							
78	12 x 12 VFT Tan w/ Brown Specs (Under HA 147 & 147M)	1,200	SF	Rooms E301 & E302 - Bldg. 1955 Edison	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
79	12 x 12 VFT Tan w/ Brown Specs Mastic (Under HA 147 & 147M)	1,200	SF	Rooms E301 and E302 - Bldg 1955 Edison	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
80	Gray Linoleum (Under HA 147 & 147M)	60	SF	Rm 330 Closet Bldg 1955 (Edison)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
81	Gray Linoleum Mastic (Under HA 147 & 147M)	60	SF	Rm 330 Closet Bldg 1955 (Edison)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
82	12 x 12 VFT Tan Mixed Speckled (Terrazzo Like)	2,000	SF	Rm 54, 56, 22 HH, 03 HH, Bldg 1930 Hackman	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
83	12 x 12 VFT Tan Mixed Speckled Mastic (Terrazzo Like)	2,000	SF	Rm 54, 56, 22HH, 03 HH, Bldg 1930 Hackman	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
84	Plaster	14,000	SF	Throughout Bldg 1930 Hackman	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	
85	12 x 12 VFT Beige w/ White Specs (Terrazzo Like)	17,000	SF	1st and 2nd Floor Corridor, Auditorium and Stairs and 23H - 1930 Hackman Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
86	12 x 12 VFT Beige w/ white Specs Mastic (Terrazzo Like)	17,000	SF	1st and 2nd Floor Corridor, Auditorium and Stairs and 23H 1930 Hackman Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
87	2 x 4 CT White w/ Swirls	1,300	SF	Rooms H303 and H304 - Bldg 1930 Hackman	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	
88	12 x 12 Black VFT (Terrazzo Like)	7,800	SF	1st and 2nd Flr Corridor and Auditorium Bldg 1930 Hackman	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
89	12 x 12 Black VFT & Mastic (Terrazzo Like)	7,800	SF	1st and 2nd Floor Corridor and Auditorium - Bldg 1930 Hackman	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
90	9 x 9 VFT Lt. Brown w/ Specs	350	SF	Rooms H212, 215, H122 - Bldg 1930 Hackman	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
91	9 x 9 VFT Lt Brown w/ Specs Mastic	350	SF	Rooms H212, 215, H122 - Bldg 1930 Hackman	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
92	12 x 12 VFT Lt Brown w/ Mixed Specs (Abated)			Rm HH-1 Bldg 1930	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
93	12 x 12 VFT Lt Brown w/ mixed specs Mastic (Abated)			Rm HH-1 Bldg 1930	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
94	12 x 12 VFT Gray w/ white & Black Specs (Abated)			HH - 13 Bldg 1930	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	

Chicago Public Schools

School Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420
Address 1309 W.95th St (9500S) 43 **Chicago, IL, 60643** **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
95	12 x12 VFT Gray w/ White & Black Specs Mastic (Abated)		SF	HH - 13 Bldg 1930	Abated	MISC	No		SF		
96	12 x 12 VFT Mixed Red Speckled	500	SF	Rm 362 - Bldg 1920 Aquinas	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
97	12 x 12 VFT Mixed Red Speckled Mastic	500	SF	Rm 362 - Bldg 1920 Aquinas	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
98	1'x1' CT White w/ Holes	2,600	SF	Throughout 1920 Bldg Aquinas	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	
99	Terrazzo	6,500	SF	Rooms 363, 352, 350, 3rd Floor East Stairwell - Bldg 1920 Aquinas	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
MM1	9" x 9" Floor Tile Mastic	37,796	SF	Ground Floor Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116, 124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, Reading Room, Washrooms, 178, 282, Corridors, Stairs	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
MM2	12" x 12" Floor Tile Mastic			Classrooms, Teachers Lounge, W Cafeteria, Ground Floor Corridor & Entries, Auditorium Entrance & Foyer, Reading Room, Staff Washrooms, Corridors, and Classrooms	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	

Chicago Public Schools

School Chicago International Charter - Longwood (South)
Address 1309 W.95th St (9500S) 43

Unit 66061

Chicago, IL, 60643

Building ID 2420

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

Review Date	
Manager Planner Name	
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
05	
07	
08	
09	
10	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	

Chicago Public Schools

School Chicago International Charter - Longwood (South)
Address 1309 W.95th St (9500S) 43

Unit 66061

Chicago, IL, 60643

Building ID 2420

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
110	
111	
112	
113	
114	
115	
116	
117	
118	
119	
12	
120	
121	
122	
123	
124	
125	
126	
127	
128	
129	
13	
130	
131	
132	
133	

Chicago Public Schools

School Chicago International Charter - Longwood (South)
Address 1309 W.95th St (9500S) 43

Unit 66061

Chicago, IL, 60643

Building ID 2420

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
134	
135	
136	
137	
138	
139	
140	
141	
142	
142M	
143	
143M	
144	
144M	
145	
145M	
146	
147	
147M	
148	
149	
150	
150M	
151	
152	
152M	

Chicago Public Schools

School Chicago International Charter - Longwood (South)
Address 1309 W.95th St (9500S) 43

Unit 66061

Chicago, IL, 60643

Building ID 2420

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
153	
153M	
154	
154M	
155	
155M	
156	
157	
158	
159	
159M	
16	
160	
160M	
161	
161M	
162	
163	
164	
165	
165M	
166	
166M	
167	
167M	
168	

Chicago Public Schools

School Chicago International Charter - Longwood (South)
Address 1309 W.95th St (9500S) 43

Unit 66061

Chicago, IL, 60643

Building ID 2420

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
168M	
169	
17	
170	
171	
172	
172M	
173	
173M	
18	
19	
19A	
20	
21	
22	
23	
26	
29	
30	
30M	
31	
33	
34	
35	
36	
37	

Chicago Public Schools

School Chicago International Charter - Longwood (South)
Address 1309 W.95th St (9500S) 43

Unit 66061

Chicago, IL, 60643

Building ID 2420

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	

Chicago Public Schools

School Chicago International Charter - Longwood (South)
Address 1309 W.95th St (9500S) 43

Unit 66061

Building ID 2420

Chicago, IL, 60643

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	

Chicago Public Schools

School Chicago International Charter - Longwood (South)
Address 1309 W.95th St (9500S) 43

Unit 66061

Chicago, IL, 60643

Building ID 2420

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
MM1	
MM2	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

2025 AHERA REINSPECTION

Chicago Public Schools

2025 AHERA REINSPECTION Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Incinerator Room , Closet by Main Shop, Kitchen, Men's Washrrom Closet, 101-201-301 Janitor Closets, Aquinus Ground Floor Corridor, Tunnel leading to Convent, Weight Room & Attic Bldg 1890**

MATERIAL QUANTITY: **701** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Incinerator Room , Closet by Main Shop, Kitchen, Men's Washrrom Closet, 101-201-301 Janitor Closets, Aquinus Ground Floor Corridor, Tunnel leading to Convent, Weight Room & Attic Bldg 1890**

MATERIAL QUANTITY: **701**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **Preform Pipe Cover (Mag Block Pipe Insulation)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Incinerator Room, Tunnel, Main Shop Room, Electric Room**
MATERIAL QUANTITY: **367** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **Preform Pipe Cover (Mag Block Pipe Insulation)**

MATERIAL LOCATION: **Incinerator Room, Tunnel, Main Shop Room, Electric Room**

MATERIAL QUANTITY: **367** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **Cardboard Pipe Cover**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen and Maintenance Closet**
MATERIAL QUANTITY: **49** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **49** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **07**

MATERIAL DESCRIPTION: **Cardboard Pipe Cover**

MATERIAL LOCATION: **Kitchen and Maintenance Closet**

MATERIAL QUANTITY: **49** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **Aircell Pipe Joint Packing**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Tunnels and Corridors, Incinerator Room, Closet by Main Shop, Kitchen, Men's Washroom Closet, 101-201-301 Janitor Closets, Weight Room & Attic Bldg 1890**

MATERIAL QUANTITY: **67** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **Aircell Pipe Joint Packing**

MATERIAL LOCATION: **Tunnels and Corridors, Incinerator Room, Closet by Main Shop, Kitchen, Men's Washroom Closet, 101-201-301 Janitor Closets, Weight Room & Attic Bldg 1890**

MATERIAL QUANTITY: **67** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **Preformed Pipe Joint Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Incinerator Room, Main Shop Room, Tunnel, Electrical Room, Ground Floor Corridor**
MATERIAL QUANTITY: **44** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **44** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **Preformed Pipe Joint Insulation**
MATERIAL LOCATION: **Incinerator Room, Main Shop Room, Tunnel, Electrical Room, Ground Floor Corridor**
MATERIAL QUANTITY: **44** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Joint packing on Fiberglass Insulated Piping**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Incinerator Rm, Tunnel, Basement Sink Room, Pantry and East Lunchroom**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: DAMAGE UNITS: **EA**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Joint packing on Fiberglass Insulated Piping**

MATERIAL LOCATION: **Incinerator Rm, Tunnel, Basement Sink Room, Pantry and East Lunchroom**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **9 x 9 VFT Black w/ Camoflouge (under HA# 106 & 107)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 358 (A305) Bldg 1920**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **400** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **100**

MATERIAL DESCRIPTION: **9 x 9 VFT Black w/ Camoflouge (under HA# 106 & 107)**

MATERIAL LOCATION: **Rm 358 (A305) Bldg 1920**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **9 x 9 VFT Black w/ Camouflouge Mastic (under HA 106 & 107)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 358 (A305) Bldg. 1920**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **400** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **101**

MATERIAL DESCRIPTION: **9 x 9 VFT Black w/ Camouflouge Mastic (under HA 106 & 107)**

MATERIAL LOCATION: **Rm 358 (A305) Bldg. 1920**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **9 x 9 VFT Brown (under HA 106 & 107)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 358 (A305) Bldg 1920**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **400** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **102**

MATERIAL DESCRIPTION: **9 x 9 VFT Brown (under HA 106 & 107)**

MATERIAL LOCATION: **Rm 358 (A305) Bldg 1920**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **9 x 9 VFT Brown Mastic (under HA 106 & 107)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 358 (A305) Bldg. 1920**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **400** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **103**

MATERIAL DESCRIPTION: **9 x 9 VFT Brown Mastic (under HA 106 & 107)**

MATERIAL LOCATION: **Rm 358 (A305) Bldg. 1920**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **9 x 9 Brown VFT (under HA 106 & 107)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 356 and 354 Bldg. 1920**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **104**

MATERIAL DESCRIPTION: **9 x 9 Brown VFT (under HA 106 & 107)**

MATERIAL LOCATION: **Rm 356 and 354 Bldg. 1920**

MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **9 x 9 Brown VFT & Mastic (under HA 106 & 107)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 356 and 354 Bldg 1920**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **105**

MATERIAL DESCRIPTION: **9 x 9 Brown VFT & Mastic (under HA 106 & 107)**

MATERIAL LOCATION: **Rm 356 and 354 Bldg 1920**

MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **12 x 12 Gray VFT Speckled**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 358, 356, 350, 351, 352, 257, 255, 254, 253, 252, 251, 250, Basement Laundry RM. Bldg 1920**
MATERIAL QUANTITY: **3700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **12 x 12 Gray VFT Speckled**
MATERIAL LOCATION: **Rooms 358, 356, 350, 351, 352, 257, 255, 254, 253, 252, 251, 250, Basement Laundry RM. Bldg 1920**
MATERIAL QUANTITY: **3700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **12 x 12 Gray VFT Speckled Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 358, 356, 350, 351, 352, 257, 255, 254, 253, 252, 252, 250, Basement Laundry Rm. Bldg. 1920**
MATERIAL QUANTITY: **3700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **12 x 12 Gray VFT Speckled Mastic**
MATERIAL LOCATION: **Rooms 358, 356, 350, 351, 352, 257, 255, 254, 253, 252, 252, 250, Basement Laundry Rm. Bldg. 1920**
MATERIAL QUANTITY: **3700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **12 x 12 Gray w/ Red, White & Blue Specs VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Stairwell Bldg 1920**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **108**

MATERIAL DESCRIPTION: **12 x 12 Gray w/ Red, White & Blue Specs VFT**

MATERIAL LOCATION: **Stairwell Bldg 1920**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **12 x 12 Gray w/ Red, White and Blue Specs Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Stairwell Bldg 1920**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **109**

MATERIAL DESCRIPTION: **12 x 12 Gray w/ Red, White and Blue Specs Mastic**

MATERIAL LOCATION: **Stairwell Bldg 1920**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Bldg 1920**
MATERIAL QUANTITY: **28000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **110**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout Bldg 1920**

MATERIAL QUANTITY: **28000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **12 x 12 VFT Beige w/ Black Streaks - (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rm 255 Bldg 1920**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **111**

MATERIAL DESCRIPTION: **12 x 12 VFT Beige w/ Black Streaks - (Abated)**

MATERIAL LOCATION: **Rm 255 Bldg 1920**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **12 x 12 VFT Beige w/ Black Streaks Mastic - (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rm 255 Bldg 1920**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **112**

MATERIAL DESCRIPTION: **12 x 12 VFT Beige w/ Black Streaks Mastic - (Abated)**

MATERIAL LOCATION: **Rm 255 Bldg 1920**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **1 x 1 Ceiling Tile white w/ Swirls**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Weight Room and Rm 51 Bldg 1920**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **113**

MATERIAL DESCRIPTION: **1 x 1 Ceiling Tile white w/ Swirls**

MATERIAL LOCATION: **Weight Room and Rm 51 Bldg 1920**

MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **Green Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 51 Bldg 1920**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **114**

MATERIAL DESCRIPTION: **Green Terrazzo**

MATERIAL LOCATION: **Rm 51 Bldg 1920**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **Spray On Fireproofing**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Attic Bldg 1890**
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **115**

MATERIAL DESCRIPTION: **Spray On Fireproofing**

MATERIAL LOCATION: **Attic Bldg 1890**

MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Bldg 1890**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **116**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **Throughout Bldg 1890**

MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117**
MATERIAL DESCRIPTION: **12 x 12 VFT Gray Speckled**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 114 and 314 Bldg 1890**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **117**

MATERIAL DESCRIPTION: **12 x 12 VFT Gray Speckled**

MATERIAL LOCATION: **Rm 114 and 314 Bldg 1890**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **12 x 12 VFT Gray Speckled Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 114 and 314 Bldg 1890**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **118**

MATERIAL DESCRIPTION: **12 x 12 VFT Gray Speckled Mastic**

MATERIAL LOCATION: **Rm 114 and 314 Bldg 1890**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **119**
MATERIAL DESCRIPTION: **1 x 1 CT White w/ Pinhole**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **L304, L302B, L306A, L306B, L302A, L307, L318, L317, L308, L313, 3rd Floor Corridor, L216, 201, L210, L209, L202, L221, L208, L207, L206, L204, 2nd Floor Corridor, L108, L107, Office L105, Office L104, L126, L121, 1st Floor Corridor, Basement Classroom by LULA Elevator, Book Storage L008, Fire Pump Room L031**

MATERIAL QUANTITY: **29000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **119**
MATERIAL DESCRIPTION: **1 x 1 CT White w/ Pinhole**
MATERIAL LOCATION: **L304, L302B, L306A, L306B, L302A, L307, L318, L317, L308, L313, 3rd Floor Corridor, L216, 201, L210, L209, L202, L221, L208, L207, L206, L204, 2nd Floor Corridor, L108, L107, Office L105, Office L104, L126, L121, 1st Floor Corridor, Basement Classroom by LULA Elevator, Book Storage L008, Fire Pump Room L031**
MATERIAL QUANTITY: **29000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Stack Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Incinerator Rm**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Stack Insulation**

MATERIAL LOCATION: **Incinerator Rm**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **120**
MATERIAL DESCRIPTION: **9 x9 VFT White w/ gray strks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms L303, L306A, L306B, L309, Electrical L311, L216, L117, Basement Room Across from Mechanical Room L018 - Bldg 1890**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **120**
MATERIAL DESCRIPTION: **9 x9 VFT White w/ gray strks**
MATERIAL LOCATION: **Rooms L303, L306A, L306B, L309, Electrical L311, L216, L117, Basement Room Across from Mechanical Room L018 - Bldg 1890**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **121**
MATERIAL DESCRIPTION: **9X9 VFT white with gray streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **L204, L303, L306B**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **121**

MATERIAL DESCRIPTION: **9X9 VFT white with gray streaks**

MATERIAL LOCATION: **L204, L303, L306B**

MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **8** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **122**
MATERIAL DESCRIPTION: **9 x 9 VFT Black**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms L204, L318, L306B**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **122**

MATERIAL DESCRIPTION: **9 x 9 VFT Black**

MATERIAL LOCATION: **Rooms L204, L318, L306B**

MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **17** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **123**
MATERIAL DESCRIPTION: **9 x 9 VFT Black Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms L303, L306A, L306B, L216 - Bldg. 1890**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **123**

MATERIAL DESCRIPTION: **9 x 9 VFT Black Mastic**

MATERIAL LOCATION: **Rooms L303, L306A, L306B, L216 - Bldg. 1890**

MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **124**
MATERIAL DESCRIPTION: **9 x 9 VFT Pink w/ Black Strks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 307**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **124**

MATERIAL DESCRIPTION: **9 x 9 VFT Pink w/ Black Strks**

MATERIAL LOCATION: **Rooms 307**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **125**
MATERIAL DESCRIPTION: **9 x 9 VFT Pink w/ Black Strks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms L307, L317, L221 - Bldg 1890**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **900** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **125**

MATERIAL DESCRIPTION: **9 x 9 VFT Pink w/ Black Strks Mastic**

MATERIAL LOCATION: **Rooms L307, L317, L221 - Bldg 1890**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **126**
MATERIAL DESCRIPTION: **9 x 9 VFT Dark Gray w/ white strks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms L307, L317, - Bldg. 1890**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **126**

MATERIAL DESCRIPTION: **9 x 9 VFT Dark Gray w/ white strks**

MATERIAL LOCATION: **Rooms L307, L317, - Bldg. 1890**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **22** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **127**
MATERIAL DESCRIPTION: **9 x 9 VFT Dark Gray w/ white strks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms L307, L318, L317, 205 - Bldg 1890**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **600** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **127**

MATERIAL DESCRIPTION: **9 x 9 VFT Dark Gray w/ white strks Mastic**

MATERIAL LOCATION: **Rooms L307, L318, L317, 205 - Bldg 1890**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **128**
MATERIAL DESCRIPTION: **9 x 9 VFT Dark Pink w/ strks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms L318, L317 - Bldg 1890**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **128**

MATERIAL DESCRIPTION: **9 x 9 VFT Dark Pink w/ strks**

MATERIAL LOCATION: **Rooms L318, L317 - Bldg 1890**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **8** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **129**
MATERIAL DESCRIPTION: **9 x 9 VFT Dark Pink w/ strks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms L318, 205 - Bldg 1890**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **600** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **129**

MATERIAL DESCRIPTION: **9 x 9 VFT Dark Pink w/ strks Mastic**

MATERIAL LOCATION: **Rooms L318, 205 - Bldg 1890**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **KEWANEE BOILER COVER - (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **MAIN BOILER RM**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **KEWANEE BOILER COVER - (Abated)**

MATERIAL LOCATION: **MAIN BOILER RM**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **130**
MATERIAL DESCRIPTION: **12 x 12 VFT Beige Mixed Speckled**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms L213, L202, L107, L125, Teacher's Lounge L113, Copy Room L115 - Bldg 1890**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **130**
MATERIAL DESCRIPTION: **12 x 12 VFT Beige Mixed Speckled**
MATERIAL LOCATION: **Rooms L213, L202, L107, L125, Teacher's Lounge L113, Copy Room L115 - Bldg 1890**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **131**
MATERIAL DESCRIPTION: **12 x 12 VFT Beige Mixed Speckled Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms L213, L202, L107, L125, Teacher's Lounge L113, Copy Room L115 - Bldg 1890**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **131**
MATERIAL DESCRIPTION: **12 x 12 VFT Beige Mixed Speckled Mastic**
MATERIAL LOCATION: **Rooms L213, L202, L107, L125, Teacher's Lounge L113, Copy Room L115 - Bldg 1890**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **132**
MATERIAL DESCRIPTION: **9 x 9 VFT Brown**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room L209 - Bldg. 1890**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **500** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **132**

MATERIAL DESCRIPTION: **9 x 9 VFT Brown**

MATERIAL LOCATION: **Room L209 - Bldg. 1890**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **133**
MATERIAL DESCRIPTION: **9 x 9 VFT Brown Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room L209 - Bldg 1890**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **500** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **133**

MATERIAL DESCRIPTION: **9 x 9 VFT Brown Mastic**

MATERIAL LOCATION: **Room L209 - Bldg 1890**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **134**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Bldg 1890**
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **134**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout Bldg 1890**

MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **135**
MATERIAL DESCRIPTION: **12 x 12 VFT Purple Speckled**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Cafeteria L009, Basement Hall by Door 31, Basement Women's Toilet Vestibule by Door 31 - Bldg 1890**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **135**
MATERIAL DESCRIPTION: **12 x 12 VFT Purple Speckled**
MATERIAL LOCATION: **Cafeteria L009, Basement Hall by Door 31, Basement Women's Toilet Vestibule by Door 31 - Bldg 1890**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **136**
MATERIAL DESCRIPTION: **12 x 12 VFT Purple Speckled Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Cafeteria L009, Basement Hall by Door 31, Basement Women's Toilet Vestibule near Door 31 - Bldg 1890**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **136**
MATERIAL DESCRIPTION: **12 x 12 VFT Purple Speckled Mastic**
MATERIAL LOCATION: **Cafeteria L009, Basement Hall by Door 31, Basement Women's Toilet Vestibule near Door 31 - Bldg 1890**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **137**
MATERIAL DESCRIPTION: **12 x 12 VFT Tan w/ Lt Brown Specs**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Cafeteria L009, Basement by Door 31, Basement Women's Toilet Vestibule near Door 31 - 1890**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **137**
MATERIAL DESCRIPTION: **12 x 12 VFT Tan w/ Lt Brown Specs**
MATERIAL LOCATION: **Cafeteria L009, Basement by Door 31, Basement Women's Toilet Vestibule near Door 31 - 1890**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **138**
MATERIAL DESCRIPTION: **12 x 12 VFT Tan w/ Light Brown Specs Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Cafeteria L009, Basement Hall by Door 31, Women's Toilet Vestibule near Door 31 - Bldg 1890**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **138**
MATERIAL DESCRIPTION: **12 x 12 VFT Tan w/ Light Brown Specs Mastic**
MATERIAL LOCATION: **Cafeteria L009, Basement Hall by Door 31, Women's Toilet Vestibule near Door 31 - Bldg 1890**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **139**
MATERIAL DESCRIPTION: **12 x 12 VFT Black - (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement - Bldg 1890**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date:

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **139**

MATERIAL DESCRIPTION: **12 x 12 VFT Black - (Abated)**

MATERIAL LOCATION: **Basement - Bldg 1890**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **140**
MATERIAL DESCRIPTION: **12 x 12 VFT Black Mastic - (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement - Bldg 1890**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date:

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **140**

MATERIAL DESCRIPTION: **12 x 12 VFT Black Mastic - (Abated)**

MATERIAL LOCATION: **Basement - Bldg 1890**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **141**
MATERIAL DESCRIPTION: **Decorative Stucco**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Hackman Building**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **141**

MATERIAL DESCRIPTION: **Decorative Stucco**

MATERIAL LOCATION: **Throughout Hackman Building**

MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **142**
MATERIAL DESCRIPTION: **12"x12" Gray w/ Black & Gray Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms H303 & Entry Vestibule, H304 & Entry Vestibule, H217, H216, H214, Electrical Room next to Toilet H119, Room H117, and Room by Door 15 - Hackman Building 1930**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **142**
MATERIAL DESCRIPTION: **12"x12" Gray w/ Black & Gray Specks VFT**
MATERIAL LOCATION: **Rooms H303 & Entry Vestibule, H304 & Entry Vestibule, H217, H216, H214, Electrical Room next to Toilet H119, Room H117, and Room by Door 15 - Hackman Building 1930**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **142M**
MATERIAL DESCRIPTION: **12"x12" Gray w/ Black & Gray Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms H303 & Entry Vestibule, Room H304 & Entry Vestibule, H217, H216, H214, Electrical Room next to Toilet H119, Room H117, and Room by Door 15 - Hackman Building 1930**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **142M**

MATERIAL DESCRIPTION: **12"x12" Gray w/ Black & Gray Specks VFT Mastic**

MATERIAL LOCATION: **Rooms H303 & Entry Vestibule, Room H304 & Entry Vestibule, H217, H216, H214, Electrical Room next to Toilet H119, Room H117, and Room by Door 15 - Hackman Building 1930**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **143**
MATERIAL DESCRIPTION: **9"x9" Off White w/ Black Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Janitor's Closet H233 & H231, Janitor's Closet near Room H122, Janitor's Closet H128 - Hackman Building - 1930**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **143**
MATERIAL DESCRIPTION: **9"x9" Off White w/ Black Streaks VFT**
MATERIAL LOCATION: **Janitor's Closet H233 & H231, Janitor's Closet near Room H122, Janitor's Closet H128 - Hackman Building - 1930**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **143M**
MATERIAL DESCRIPTION: **9"x9" Off White w/ Black Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Janitor's Closet H233 & H231, Janitor's Closet near Room H122, Janitor's Closet H128 - Hackman Building 1930**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **143M**

MATERIAL DESCRIPTION: **9"x9" Off White w/ Black Streaks VFT Mastic**

MATERIAL LOCATION: **Janitor's Closet H233 & H231, Janitor's Closet near Room H122, Janitor's Closet H128 - Hackman Building 1930**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **144**
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Restroom H219, Room H126, 1st Floor Corridor by Door 11 - Hackman Building 1930**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **144**
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ Streaks VFT**
MATERIAL LOCATION: **2nd Floor Restroom H219, Room H126, 1st Floor Corridor by Door 11 - Hackman Building 1930**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **144M**
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Restroom H219, Room H126, 1st Floor Corridor by Door 11 - Hackman Building - 1930**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **144M**
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ Streaks VFT Mastic**
MATERIAL LOCATION: **2nd Floor Restroom H219, Room H126, 1st Floor Corridor by Door 11 - Hackman Building - 1930**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **145**
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile w/ Holes**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium - Hackman Building 1930**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **145**

MATERIAL DESCRIPTION: **1'x1' Ceiling Tile w/ Holes**

MATERIAL LOCATION: **Auditorium - Hackman Building 1930**

MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **145M**
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile w/ Holes Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium - Hackman Building 1930**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **145M**

MATERIAL DESCRIPTION: **1'x1' Ceiling Tile w/ Holes Mastic**

MATERIAL LOCATION: **Auditorium - Hackman Building 1930**

MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **146**
MATERIAL DESCRIPTION: **Decoratrive Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium - Hackman Building 1930**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **146**

MATERIAL DESCRIPTION: **Decorative Plaster**

MATERIAL LOCATION: **Auditorium - Hackman Building 1930**

MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **147**
MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ Black & Gray Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms E301, E302, Storage S303, E201, E202, Storage S203 - Edison Building 1955**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **147**
MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ Black & Gray Specks VFT**
MATERIAL LOCATION: **Rooms E301, E302, Storage S303, E201, E202, Storage S203 - Edison Building 1955**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **147M**
MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ Black & Gray Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms E301, E302, Storage S303, Rooms E201, E202, Storage S203 - Edison Building 1955**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **147M**
MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ Black & Gray Specks VFT Mastic**
MATERIAL LOCATION: **Rooms E301, E302, Storage S303, Rooms E201, E202, Storage S203 - Edison Building 1955**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **148**
MATERIAL DESCRIPTION: **Popcorn Plaster Ceiling**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 356 & 358 - Aquinas Building 1920**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **148**

MATERIAL DESCRIPTION: **Popcorn Plaster Ceiling**

MATERIAL LOCATION: **Rooms 356 & 358 - Aquinas Building 1920**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **149**
MATERIAL DESCRIPTION: **Green Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 152 - Aquinas Building 1920**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **350** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **149**

MATERIAL DESCRIPTION: **Green Carpet Mastic**

MATERIAL LOCATION: **Room 152 - Aquinas Building 1920**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **150**
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ Dark & Light Streaks VFT & Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Weight Room (Under Rubber Mats) - Aquinas Building 1920**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **150**

MATERIAL DESCRIPTION: **12"x12" Light Blue w/ Dark & Light Streaks VFT & Mastic**

MATERIAL LOCATION: **Weight Room (Under Rubber Mats) - Aquinas Building 1920**

MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **150M**
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ Dark & Light Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Weight Room (Under Rubber Mats) - Aquinas Building 1920**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **150M**

MATERIAL DESCRIPTION: **12"x12" Light Blue w/ Dark & Light Streaks VFT Mastic**

MATERIAL LOCATION: **Weight Room (Under Rubber Mats) - Aquinas Building 1920**

MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **151**
MATERIAL DESCRIPTION: **Decorative Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor by Weight Room**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **500** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **151**

MATERIAL DESCRIPTION: **Decorative Plaster**

MATERIAL LOCATION: **1st Floor Corridor by Weight Room**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **152**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Storage Room next to Laundry Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **152**

MATERIAL DESCRIPTION: **12"x12" Black w/ White Specks VFT**

MATERIAL LOCATION: **Basement Storage Room next to Laundry Room**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **152M**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Storage Room next to Laundry Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **152M**

MATERIAL DESCRIPTION: **12"x12" Black w/ White Specks VFT Mastic**

MATERIAL LOCATION: **Basement Storage Room next to Laundry Room**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **153**
MATERIAL DESCRIPTION: **12"x12" Sand VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Classroom A003, A004, and outside Elevator in Basement - Aquinas Building 1920**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **153**
MATERIAL DESCRIPTION: **12"x12" Sand VFT**
MATERIAL LOCATION: **Basement Classroom A003, A004, and outside Elevator in Basement - Aquinas Building 1920**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **153M**
MATERIAL DESCRIPTION: **12"x12" Sand VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Classroom A003, A004, and outside Elevator in Basement - Aquinas Building 1920**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **153M**
MATERIAL DESCRIPTION: **12"x12" Sand VFT Mastic**
MATERIAL LOCATION: **Basement Classroom A003, A004, and outside Elevator in Basement - Aquinas Building 1920**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **154**
MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Corridors - Aquinas Building 1920**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **154**

MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile**

MATERIAL LOCATION: **3rd Floor Corridors - Aquinas Building 1920**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **154M**
MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile Mastic Pucks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Corridors - Aquinas Building 1920**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **154M**

MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile Mastic Pucks**

MATERIAL LOCATION: **3rd Floor Corridors - Aquinas Building 1920**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **155**
MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ Black & Gray Specks VFT & Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 148, ND 114, ND 1134, ND 106, ND 105, ND 104, ND 103 - Notre Dame Building 1950**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **155**
MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ Black & Gray Specks VFT & Mastic**
MATERIAL LOCATION: **Rooms 148, ND 114, ND 1134, ND 106, ND 105, ND 104, ND 103 - Notre Dame Building 1950**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **155M**
MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ Black & Gray Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 148, ND114, ND113, ND106, ND105, ND104, ND103**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **155M**

MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ Black & Gray Specks VFT Mastic**

MATERIAL LOCATION: **Rooms 148, ND114, ND113, ND106, ND105, ND104, ND103**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **156**
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor, Entry Vestibule Doors 24 & 3, Rooms 140 and 138 - Notre Dame Building 1950**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **156**
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**
MATERIAL LOCATION: **1st Floor Corridor, Entry Vestibule Doors 24 & 3, Rooms 140 and 138 - Notre Dame Building 1950**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **157**
MATERIAL DESCRIPTION: **Terrazzo Flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridors, Stairs, Entry Vestibules 24 / 3, Toilets - Notre Dame Building 1950**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **1500** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **157**

MATERIAL DESCRIPTION: **Terrazzo Flooring**

MATERIAL LOCATION: **1st Floor Corridors, Stairs, Entry Vestibules 24 / 3, Toilets - Notre Dame Building 1950**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **158**
MATERIAL DESCRIPTION: **Attic Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Attic - Longwood 1890 Building**
MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **158**

MATERIAL DESCRIPTION: **Attic Plaster**

MATERIAL LOCATION: **Attic - Longwood 1890 Building**

MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **159**
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms L215 & Electrical Room L215, L210, L206, L108, L107, Office L118, L121, Entrance Vestibule by Door 29 - Longwood 1890 Building**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **159**
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ Streaks VFT**
MATERIAL LOCATION: **Rooms L215 & Electrical Room L215, L210, L206, L108, L107, Office L118, L121, Entrance Vestibule by Door 29 - Longwood 1890 Building**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **159M**
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms L215 & Electrical Room L215, L210, L206, L108, L107, Office L118, L121, Entrance Vestibule by Door 29 - Longwood 1890 Building**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **159M**

MATERIAL DESCRIPTION: **12"x12" Light Blue w/ Streaks VFT Mastic**

MATERIAL LOCATION: **Rooms L215 & Electrical Room L215, L210, L206, L108, L107, Office L118, L121, Entrance Vestibule by Door 29 - Longwood 1890 Building**

MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **MAG BLOCK COVERING - (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **MAG BLOCK COVERING - (Abated)**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **160**
MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ Light Gray Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms L302A, L302B, L304, L111 - Longwood 1890 Building**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **160**

MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ Light Gray Specks VFT**

MATERIAL LOCATION: **Rooms L302A, L302B, L304, L111 - Longwood 1890 Building**

MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **160M**
MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ Light Gray Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms L302A, L302B, L304, L111 - Longwood 1890 Building**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **160M**

MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ Light Gray Specks VFT Mastic**

MATERIAL LOCATION: **Rooms L302A, L302B, L304, L111 - Longwood 1890 Building**

MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **161**
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room L209, Offices L105 & L104 (under carpet)**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **161**

MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT**

MATERIAL LOCATION: **Room L209, Offices L105 & L104 (under carpet)**

MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **161M**
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room L209, Office L105 & L104 (under the carpet) - Longwood 1890 Building**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **161M**

MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT Mastic**

MATERIAL LOCATION: **Room L209, Office L105 & L104 (under the carpet) - Longwood 1890 Building**

MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **162**
MATERIAL DESCRIPTION: **Decorative Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms L111, Office L112, Teacher's Lounge L113, Conference Room L110, Copy Room L115 - Longwood 1890 Building**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **162**
MATERIAL DESCRIPTION: **Decorative Plaster**
MATERIAL LOCATION: **Rooms L111, Office L112, Teacher's Lounge L113, Conference Room L110, Copy Room L115 - Longwood 1890 Building**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **163**
MATERIAL DESCRIPTION: **Troweled-on Plaster Walls**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Corridor, Classroom L006 - Longwood 1890 Building**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **163**

MATERIAL DESCRIPTION: **Troweled-on Plaster Walls**

MATERIAL LOCATION: **Basement Corridor, Classroom L006 - Longwood 1890 Building**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **164**
MATERIAL DESCRIPTION: **Spray-on Fireproofing**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Small Lunchroom - Longwood 1890 Building**
MATERIAL QUANTITY: **2900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **164**

MATERIAL DESCRIPTION: **Spray-on Fireproofing**

MATERIAL LOCATION: **Basement Small Lunchroom - Longwood 1890 Building**

MATERIAL QUANTITY: **2900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **165**
MATERIAL DESCRIPTION: **12"x12" White VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Classroom by LULA Elevator - Longwood 1890 Building**
MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **165**

MATERIAL DESCRIPTION: **12"x12" White VFT**

MATERIAL LOCATION: **Basement Classroom by LULA Elevator - Longwood 1890 Building**

MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **165M**
MATERIAL DESCRIPTION: **12"X12" White VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Classroom by LULA Elevator - Longwood 1890 Building**
MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **165M**

MATERIAL DESCRIPTION: **12"X12" White VFT Mastic**

MATERIAL LOCATION: **Basement Classroom by LULA Elevator - Longwood 1890 Building**

MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **166**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Classroom by LULA Elevator - Longwood 1890 Building**
MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **166**

MATERIAL DESCRIPTION: **12"x12" Black w/ White Specks VFT**

MATERIAL LOCATION: **Basement Classroom by LULA Elevator - Longwood 1890 Building**

MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **166M**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Classroom by LULA Elevator - Longwood 1890 Building**
MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **166M**

MATERIAL DESCRIPTION: **12"x12" Black w/ White Specks VFT Mastic**

MATERIAL LOCATION: **Basement Classroom by LULA Elevator - Longwood 1890 Building**

MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **167**
MATERIAL DESCRIPTION: **12"x12" Yellow Streaked VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Corridors, Hall by Room L006 and Hall by Mechanical Room L018 - Longwood - 1890 Bldg.**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **167**
MATERIAL DESCRIPTION: **12"x12" Yellow Streaked VFT**
MATERIAL LOCATION: **Basement Corridors, Hall by Room L006 and Hall by Mechanical Room L018 - Longwood - 1890 Bldg.**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **167M**
MATERIAL DESCRIPTION: **12"x12" Yellow Streaked VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Corridors, Hall by Room L006 and Hall by Mechanical Room L018 - Longwood 1890 Building**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **167M**
MATERIAL DESCRIPTION: **12"x12" Yellow Streaked VFT Mastic**
MATERIAL LOCATION: **Basement Corridors, Hall by Room L006 and Hall by Mechanical Room L018 - Longwood 1890 Building**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **168**
MATERIAL DESCRIPTION: **12"x12" Maroon Streaked VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Corridors, Hall by Classroom L006, Hall by Mechanical Room L018, JC L034, Basement JC by Door 31 - Longwood 1890 Building**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **168**
MATERIAL DESCRIPTION: **12"x12" Maroon Streaked VFT**
MATERIAL LOCATION: **Basement Corridors, Hall by Classroom L006, Hall by Mechanical Room L018, JC L034, Basement JC by Door 31 - Longwood 1890 Building**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **168M**
MATERIAL DESCRIPTION: **12"x12" Maroon Streaked VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Corridors, Hall by Classroom L006, Hall by Mechanical Room L018, JC L034, Basement JC by Door 31 - Longwood 1890 Building**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **168M**

MATERIAL DESCRIPTION: **12"x12" Maroon Streaked VFT Mastic**

MATERIAL LOCATION: **Basement Corridors, Hall by Classroom L006, Hall by Mechanical Room L018, JC L034, Basement JC by Door 31 - Longwood 1890 Building**

MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **169**
MATERIAL DESCRIPTION: **2'x2' Ceiling Tile w/ Pinholes**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Corridors - Longwood 1890 Building**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **169**

MATERIAL DESCRIPTION: **2'x2' Ceiling Tile w/ Pinholes**

MATERIAL LOCATION: **Basement Corridors - Longwood 1890 Building**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **HAND PACKING-ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **BOILER RM**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **HAND PACKING-ABATED**

MATERIAL LOCATION: **BOILER RM**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **170**
MATERIAL DESCRIPTION: **Pink Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Kitchen, Serving Room, Small Lunchroom, Dish Wash Room, Book Storage L008 - Longwood 1890 Building**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **170**
MATERIAL DESCRIPTION: **Pink Ceramic Tile Grout**
MATERIAL LOCATION: **Basement Kitchen, Serving Room, Small Lunchroom, Dish Wash Room, Book Storage L008 - Longwood 1890 Building**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **171**
MATERIAL DESCRIPTION: **Pink Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Kitchen, Serving Room, Small Lunchroom, Dish Wash Room L025, Book Storage L008 - Longwood - 1890 Building**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **171**
MATERIAL DESCRIPTION: **Pink Ceramic Tile Adhesive**
MATERIAL LOCATION: **Basement Kitchen, Serving Room, Small Lunchroom, Dish Wash Room L025, Book Storage L008 - Longwood - 1890 Building**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **172**
MATERIAL DESCRIPTION: **12X12 Light Blue specked floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **L206**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **172**

MATERIAL DESCRIPTION: **12X12 Light Blue specked floor tile**

MATERIAL LOCATION: **L206**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **9** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **172M**
MATERIAL DESCRIPTION: **12x12 Light Blue specked floor tile and Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **L206**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **172M**

MATERIAL DESCRIPTION: **12x12 Light Blue specked floor tile and Mastic**

MATERIAL LOCATION: **L206**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **9** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **173**
MATERIAL DESCRIPTION: **12X12 Gray with specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **L202**

MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **173**

MATERIAL DESCRIPTION: **12X12 Gray with specks**

MATERIAL LOCATION: **L202**

MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **173M**
MATERIAL DESCRIPTION: **12X12 Gray with specks/ Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **L202**

MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **173M**

MATERIAL DESCRIPTION: **12X12 Gray with specks/ Mastic**

MATERIAL LOCATION: **L202**

MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **HOT WATER HOLDING TANK - (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **BOILER RM**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **HOT WATER HOLDING TANK - (Abated)**

MATERIAL LOCATION: **BOILER RM**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **HOT WATER HOLDING TANK - (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **BOILER ROOM**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **HOT WATER HOLDING TANK - (Abated)**

MATERIAL LOCATION: **BOILER ROOM**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19A**
MATERIAL DESCRIPTION: **WRAP OVER FIBER GLASS**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **HOT WATER HOLDING TANK-BOILER ROOM TUNNEL**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **120** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **19A**

MATERIAL DESCRIPTION: **WRAP OVER FIBER GLASS**

MATERIAL LOCATION: **HOT WATER HOLDING TANK-BOILER ROOM TUNNEL**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **TANK HARD PACKING (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **CONVENT BOILER RM**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **TANK HARD PACKING (Abated)**

MATERIAL LOCATION: **CONVENT BOILER RM**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **COVERED VENT SUPPLYNG COMBUSTION AIR - (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **MAIN BOILER RM**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **COVERED VENT SUPPLYNG COMBUSTION AIR - (Abated)**

MATERIAL LOCATION: **MAIN BOILER RM**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **CANVAS COVERED BLOCK TYPE DUCT - (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **BOILER RM**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **CANVAS COVERED BLOCK TYPE DUCT - (Abated)**

MATERIAL LOCATION: **BOILER RM**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **PIPE JOINTS - (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **BOILER ROOM**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **PIPE JOINTS - (Abated)**

MATERIAL LOCATION: **BOILER ROOM**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **LIGHT CORDS**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **AUDITORIUM - Hackman Building 1930**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **150** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **LIGHT CORDS**

MATERIAL LOCATION: **AUDITORIUM - Hackman Building 1930**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **ACOUSTIC PLASTER**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **CONVENT CHAPEL**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **ACOUSTIC PLASTER**

MATERIAL LOCATION: **CONVENT CHAPEL**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile (with Pinholes & Grooves)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Cafeteria L009, Hall by Door 31**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **6500** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **1'x1' Ceiling Tile (with Pinholes & Grooves)**

MATERIAL LOCATION: **Cafeteria L009, Hall by Door 31**

MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30M**
MATERIAL DESCRIPTION: **Mastic Associated with 1' x 1' White w/ Pinholes and Grooves Celing Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Cafeteria, L009, Hall by Door 31**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **6500** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **30M**

MATERIAL DESCRIPTION: **Mastic Associated with 1' x 1' White w/ Pinholes and Grooves Ceiling Tile**

MATERIAL LOCATION: **Cafeteria, L009, Hall by Door 31**

MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **2'x4' Lay In Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 253, 251 250, 254, 255, 257, 356 - Aquinas Building**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **2'x4' Lay In Ceiling Tile**

MATERIAL LOCATION: **Rooms 253, 251 250, 254, 255, 257, 356 - Aquinas Building**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **12" x 12" Floor Tile Tan Mixed Speckled**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Ground Floor Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116, 124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, m, Washrooms, Classrooms, Corridors, Stairs,**

MATERIAL QUANTITY: **10580** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **12" x 12" Floor Tile Tan Mixed Speckled**

MATERIAL LOCATION: **Ground Floor Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116, 124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, m, Washrooms, Classrooms, Corridors, Stairs,**

MATERIAL QUANTITY: **10580** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **9"x9" Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Ground Floor Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116, 124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, Reading Room, Washrooms, 178, 282, Corridors, Stairs**

MATERIAL QUANTITY: **37796** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **9"x9" Floor Tile**

MATERIAL LOCATION: **Ground Floor Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116, 124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, Reading Room, Washrooms, 178, 282, Corridors, Stairs**

MATERIAL QUANTITY: **37796** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **PLASTER**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout All Buildings**
MATERIAL QUANTITY: **1495000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **PLASTER**

MATERIAL LOCATION: **Throughout All Buildings**

MATERIAL QUANTITY: **1495000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Blue Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Offices L105, L104, L132, L112 - 1890 Building Longwood**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Blue Carpet Adhesive**

MATERIAL LOCATION: **Offices L105, L104, L132, L112 - 1890 Building Longwood**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Brown Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office L212**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **120** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Brown Carpet Adhesive**

MATERIAL LOCATION: **Office L212**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Purple Carpet Adhesive - (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Music Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Purple Carpet Adhesive - (Abated)**

MATERIAL LOCATION: **Music Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Brown Striped Carpet Adhesive - (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 277**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Brown Striped Carpet Adhesive - (Abated)**

MATERIAL LOCATION: **Room 277**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Purple Carpet Adhesive - (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 132**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Purple Carpet Adhesive - (Abated)**

MATERIAL LOCATION: **Room 132**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Stairwells, Basement Lunchroom, Book Storage 008, Fire Pump Room L031, Electrical Room L022, Kitchen Office L024, Kitchen Staff Toilet L029, Classroom L006**
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **Stairwells, Basement Lunchroom, Book Storage 008, Fire Pump Room L031, Electrical Room L022, Kitchen Office L024, Kitchen Staff Toilet L029, Classroom L006**

MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Washrooms All Floors - 1890 Building Longwood**
MATERIAL QUANTITY: **2746** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Ceramic Tile Grout**

MATERIAL LOCATION: **Washrooms All Floors - 1890 Building Longwood**

MATERIAL QUANTITY: **2746** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Washrooms All Floors - 1890 Building Longwood**
MATERIAL QUANTITY: **2746** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Ceramic Tile Adhesive**

MATERIAL LOCATION: **Washrooms All Floors - 1890 Building Longwood**

MATERIAL QUANTITY: **2746** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Facility Including: Ground Floor Pantry, Corridor by Rooms 402-404, Room 281**
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Throughout Facility Including: Ground Floor Pantry, Corridor by Rooms 402-404, Room 281**
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **Drywall Compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Facility Including: Ground Floor Pantry, Corridor by Rooms 402-404, Room 281**
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **Drywall Compound**
MATERIAL LOCATION: **Throughout Facility Including: Ground Floor Pantry, Corridor by Rooms 402-404, Room 281**
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **Tectum Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym - 1920 Building Aquinas**
MATERIAL QUANTITY: **5457** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Tectum Ceiling Panels**

MATERIAL LOCATION: **Gym - 1920 Building Aquinas**

MATERIAL QUANTITY: **5457** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **Chalkboard/Whiteboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms Throughout Facility**
MATERIAL QUANTITY: **7200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Chalkboard/Whiteboard Adhesive**

MATERIAL LOCATION: **Classrooms Throughout Facility**

MATERIAL QUANTITY: **7200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Vinyl Stair Treads**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Stairways - 1920 Building Aquinas**
MATERIAL QUANTITY: **582** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Vinyl Stair Treads**

MATERIAL LOCATION: **Stairways - 1920 Building Aquinas**

MATERIAL QUANTITY: **582** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Vinyl Stair Thread Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Stairways - 1920 Building Aquinas**
MATERIAL QUANTITY: **582** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Vinyl Stair Thread Adhesive**

MATERIAL LOCATION: **Stairways - 1920 Building Aquinas**

MATERIAL QUANTITY: **582** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **4" Black Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **West Lunchroom, 051, 054, 281 - 1890 Building Longwood**
MATERIAL QUANTITY: **701** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **4" Black Baseboard**

MATERIAL LOCATION: **West Lunchroom, 051, 054, 281 - 1890 Building Longwood**

MATERIAL QUANTITY: **701** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **4" Black Baseboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **West Lunchroom, 051, 054, 281 - 1890 Building Longwood**
MATERIAL QUANTITY: **701** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **4" Black Baseboard Adhesive**

MATERIAL LOCATION: **West Lunchroom, 051, 054, 281 - 1890 Building Longwood**

MATERIAL QUANTITY: **701** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **6" Brown Baseboard (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Women's Ground Floor Washroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **6" Brown Baseboard (Abated)**

MATERIAL LOCATION: **Women's Ground Floor Washroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **6" Brown Basebord Adhesive (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Women's Ground Floor Washroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **6" Brown Basebord Adhesive (Abated)**

MATERIAL LOCATION: **Women's Ground Floor Washroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **4" Brown Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Ground Floor Security Office and East Cafeteria - 1890 Building Longwood**
MATERIAL QUANTITY: **316** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **316** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **4" Brown Baseboard**

MATERIAL LOCATION: **Ground Floor Security Office and East Cafeteria - 1890 Building Longwood**

MATERIAL QUANTITY: **316** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **4" Brown Baseboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Ground Floor Security Office and East Cafeteria - 1890 Building Longwood**
MATERIAL QUANTITY: **316** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **316** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **4" Brown Baseboard Adhesive**

MATERIAL LOCATION: **Ground Floor Security Office and East Cafeteria - 1890 Building Longwood**

MATERIAL QUANTITY: **316** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **4" Grey Baseboard (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 351**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **4" Grey Baseboard (Abated)**

MATERIAL LOCATION: **Room 351**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **4" Gray Baseboard Adhesive (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 351**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **4" Gray Baseboard Adhesive (Abated)**

MATERIAL LOCATION: **Room 351**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **4" x 4" Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Elevator in Aquinas 1920 Building**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **4" x 4" Floor Tile**

MATERIAL LOCATION: **Elevator in Aquinas 1920 Building**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **4" x 4" Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Elevator in Aquinus 1920 Building**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **4" x 4" Floor Tile Mastic**

MATERIAL LOCATION: **Elevator in Aquinus 1920 Building**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **Grey and Black Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium - Hackman Building 1930**
MATERIAL QUANTITY: **2156** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **Grey and Black Carpet Adhesive**

MATERIAL LOCATION: **Auditorium - Hackman Building 1930**

MATERIAL QUANTITY: **2156** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **Acoustical Ceiling Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium - Hackman Building 1930**
MATERIAL QUANTITY: **1725** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **Acoustical Ceiling Plaster**

MATERIAL LOCATION: **Auditorium - Hackman Building 1930**

MATERIAL QUANTITY: **1725** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Pegboard on Walls**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Teacher's Lounge**
MATERIAL QUANTITY: **1960** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Pegboard on Walls**

MATERIAL LOCATION: **Teacher's Lounge**

MATERIAL QUANTITY: **1960** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **1 x 1 CT White (Removed)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rm 126, Bldg 1950- Notre Dame**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date:

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **1 x 1 CT White (Removed)**

MATERIAL LOCATION: **Rm 126, Bldg 1950- Notre Dame**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **1 x 1 White w/ Grooves Spline Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 148, ND 114 (146), ND 113, ND 106, ND 122, ND 125, ND 104, ND 103 - 1950 Building Notre Dame**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **1 x 1 White w/ Grooves Spline Ceiling Tile**

MATERIAL LOCATION: **Rooms 148, ND 114 (146), ND 113, ND 106, ND 122, ND 125, ND 104, ND 103 - 1950 Building Notre Dame**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **12 x 12 VFT Tan Mixed Speckled (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rm 126 Bldg 1950 Notre Dame**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date:

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **12 x 12 VFT Tan Mixed Speckled (Abated)**

MATERIAL LOCATION: **Rm 126 Bldg 1950 Notre Dame**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **12 x 12 VFT Tan Mixed Speckled Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rm 126 Bldg 1950 Notre Dame**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **12 x 12 VFT Tan Mixed Speckled Mastic (Abated)**

MATERIAL LOCATION: **Rm 126 Bldg 1950 Notre Dame**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **9 x 9 VFT Gray w/ streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **L209**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **9 x 9 VFT Gray w/ streaks VFT**

MATERIAL LOCATION: **L209**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **13** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **9 x 9 VFT Gray w/ Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 146, 140, 138, 129 - Bldg 1950 Notre Dame**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **9 x 9 VFT Gray w/ Streaks Mastic**

MATERIAL LOCATION: **Rooms 146, 140, 138, 129 - Bldg 1950 Notre Dame**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **9 x 9 VFT Green**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL:
MATERIAL LOCATION: **Rm L209**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **9 x 9 VFT Green**

MATERIAL LOCATION: **Rm L209**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **12** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **9 x 9 VFT Green Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rm 128, 130, 144, 146 Bldg 1950 Notre Dame**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **9 x 9 VFT Green Mastic (Abated)**

MATERIAL LOCATION: **Rm 128, 130, 144, 146 Bldg 1950 Notre Dame**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Bldg 1950 Notre Dame**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout Bldg 1950 Notre Dame**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **12 x 12 VFT Gray w/ Balck & White Specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Stairway Bldg 1955 Eddison**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **500** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **12 x 12 VFT Gray w/ Balck & White Specks**
MATERIAL LOCATION: **Stairway Bldg 1955 Eddison**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **12 x 12 VFT Gray w/ Black & White Specs Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Stairway Bldg 1955 Eddison**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **12 x 12 VFT Gray w/ Black & White Specs Mastic**

MATERIAL LOCATION: **Stairway Bldg 1955 Eddison**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **9 x 9 VFT Tan (Under HA 147 & 147M)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms E201 and E202 - Bldg 1955 Edison**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **9 x 9 VFT Tan (Under HA 147 & 147M)**

MATERIAL LOCATION: **Rooms E201 and E202 - Bldg 1955 Edison**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **9 x 9 VFT Tan Mastic (Under HA 147 & 147M)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms E201 and E202 - Bldg 1955 Edison**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **9 x 9 VFT Tan Mastic (Under HA 147 & 147M)**

MATERIAL LOCATION: **Rooms E201 and E202 - Bldg 1955 Edison**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **9 x9 VFT Dark Brown VFT (Under HA 147 & 147M)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms E201 and E202 - Bldg 1955 Edison**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **9 x9 VFT Dark Brown VFT (Under HA 147 & 147M)**

MATERIAL LOCATION: **Rooms E201 and E202 - Bldg 1955 Edison**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **9 x 9 VFT Dark Brown Mastic (Under HA 147 & 147M)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms E201 and E202 - Bldg 1955 Edison**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **9 x 9 VFT Dark Brown Mastic (Under HA 147 & 147M)**

MATERIAL LOCATION: **Rooms E201 and E202 - Bldg 1955 Edison**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **12 x 12 VFT Tan w/ Brown Specs (Under HA 147 & 147M)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms E301 & E302 - Bldg. 1955 Edison**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **12 x 12 VFT Tan w/ Brown Specs (Under HA 147 & 147M)**

MATERIAL LOCATION: **Rooms E301 & E302 - Bldg. 1955 Edison**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **12 x 12 VFT Tan w/ Brown Specs Mastic (Under HA 147 & 147M)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms E301 and E302 - Bldg 1955 Edison**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **12 x 12 VFT Tan w/ Brown Specs Mastic (Under HA 147 & 147M)**

MATERIAL LOCATION: **Rooms E301 and E302 - Bldg 1955 Edison**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **Gray Linoleum (Under HA 147 & 147M)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 330 Closet Bldg 1955 (Edison)**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **Gray Linoleum (Under HA 147 & 147M)**

MATERIAL LOCATION: **Rm 330 Closet Bldg 1955 (Edison)**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **Gray Linoleum Mastic (Under HA 147 & 147M)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 330 Closet Bldg 1955 (Edison)**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **60** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **Gray Linoleum Mastic (Under HA 147 & 147M)**

MATERIAL LOCATION: **Rm 330 Closet Bldg 1955 (Edison)**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **12 x 12 VFT Tan Mixed Speckled (Terrazzo Like)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 54, 56, 22 HH, 03 HH, Bldg 1930 Hackman**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **12 x 12 VFT Tan Mixed Speckled (Terrazzo Like)**

MATERIAL LOCATION: **Rm 54, 56, 22 HH, 03 HH, Bldg 1930 Hackman**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **12 x 12 VFT Tan Mixed Speckled Mastic (Terrazzo Like)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 54, 56, 22HH, 03 HH, Bldg 1930 Hackman**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **12 x 12 VFT Tan Mixed Speckled Mastic (Terrazzo Like)**

MATERIAL LOCATION: **Rm 54, 56, 22HH, 03 HH, Bldg 1930 Hackman**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Bldg 1930 Hackman**
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout Bldg 1930 Hackman**

MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **12 x 12 VFT Beige w/ White Specs (Terrazzo Like)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd Floor Corridor, Auditorium and Stairs and 23H - 1930 Hackman Bldg.**
MATERIAL QUANTITY: **17000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **85**

MATERIAL DESCRIPTION: **12 x 12 VFT Beige w/ White Specs (Terrazzo Like)**

MATERIAL LOCATION: **1st and 2nd Floor Corridor, Auditorium and Stairs and 23H - 1930 Hackman Bldg.**

MATERIAL QUANTITY: **17000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **12 x 12 VFT Beige w/ white Specs Mastic (Terrazzo Like)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd Floor Corridor, Auditorium and Stairs and 23H 1930 Hackman Bldg.**
MATERIAL QUANTITY: **17000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **86**

MATERIAL DESCRIPTION: **12 x 12 VFT Beige w/ white Specs Mastic (Terrazzo Like)**

MATERIAL LOCATION: **1st and 2nd Floor Corridor, Auditorium and Stairs and 23H 1930 Hackman Bldg.**

MATERIAL QUANTITY: **17000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **2 x 4 CT White w/ Swirls**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms H303 and H304 - Bldg 1930 Hackman**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **87**

MATERIAL DESCRIPTION: **2 x 4 CT White w/ Swirls**

MATERIAL LOCATION: **Rooms H303 and H304 - Bldg 1930 Hackman**

MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88**
MATERIAL DESCRIPTION: **12 x 12 Black VFT (Terrazzo Like)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd Flr Corridor and Auditorium Bldg 1930 Hackman**
MATERIAL QUANTITY: **7800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **12 x 12 Black VFT (Terrazzo Like)**

MATERIAL LOCATION: **1st and 2nd Flr Corridor and Auditorium Bldg 1930 Hackman**

MATERIAL QUANTITY: **7800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89**
MATERIAL DESCRIPTION: **12 x 12 Black VFT & Mastic (Terrazzo Like)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd Floor Corridor and Auditorium - Bldg 1930 Hackman**
MATERIAL QUANTITY: **7800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **89**

MATERIAL DESCRIPTION: **12 x 12 Black VFT & Mastic (Terrazzo Like)**

MATERIAL LOCATION: **1st and 2nd Floor Corridor and Auditorium - Bldg 1930 Hackman**

MATERIAL QUANTITY: **7800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90**
MATERIAL DESCRIPTION: **9 x 9 VFT Lt. Brown w/ Specs**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms H212, 215, H122 - Bldg 1930 Hackman**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **9 x 9 VFT Lt. Brown w/ Specs**

MATERIAL LOCATION: **Rooms H212, 215, H122 - Bldg 1930 Hackman**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **91**
MATERIAL DESCRIPTION: **9 x 9 VFT Lt Brown w/ Specs Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms H212, 215, H122 - Bldg 1930 Hackman**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **91**

MATERIAL DESCRIPTION: **9 x 9 VFT Lt Brown w/ Specs Mastic**

MATERIAL LOCATION: **Rooms H212, 215, H122 - Bldg 1930 Hackman**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **92**
MATERIAL DESCRIPTION: **12 x 12 VFT Lt Brown w/ Mixed Specs (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rm HH-1 Bldg 1930**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date:

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **12 x 12 VFT Lt Brown w/ Mixed Specs (Abated)**

MATERIAL LOCATION: **Rm HH-1 Bldg 1930**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **93**
MATERIAL DESCRIPTION: **12 x 12 VFT Lt Brown w/ mixed specs Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rm HH-1 Bldg 1930**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date:

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **93**

MATERIAL DESCRIPTION: **12 x 12 VFT Lt Brown w/ mixed specs Mastic (Abated)**

MATERIAL LOCATION: **Rm HH-1 Bldg 1930**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **94**
MATERIAL DESCRIPTION: **12 x 12 VFT Gray w/ white & Black Specs (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **HH - 13 Bldg 1930**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **94**

MATERIAL DESCRIPTION: **12 x 12 VFT Gray w/ white & Black Specs (Abated)**

MATERIAL LOCATION: **HH - 13 Bldg 1930**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **95**
MATERIAL DESCRIPTION: **12 x12 VFT Gray w/ White & Black Specs Mastic (Abated)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **HH - 13 Bldg 1930**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **95**

MATERIAL DESCRIPTION: **12 x12 VFT Gray w/ White & Black Specs Mastic (Abated)**

MATERIAL LOCATION: **HH - 13 Bldg 1930**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **96**
MATERIAL DESCRIPTION: **12 x 12 VFT Mixed Red Speckled**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 362 - Bldg 1920 Aquinas**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **500** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **96**

MATERIAL DESCRIPTION: **12 x 12 VFT Mixed Red Speckled**

MATERIAL LOCATION: **Rm 362 - Bldg 1920 Aquinas**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **97**
MATERIAL DESCRIPTION: **12 x 12 VFT Mixed Red Speckled Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm 362 - Bldg 1920 Aquinas**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **500** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **97**

MATERIAL DESCRIPTION: **12 x 12 VFT Mixed Red Speckled Mastic**

MATERIAL LOCATION: **Rm 362 - Bldg 1920 Aquinas**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **98**
MATERIAL DESCRIPTION: **1'x1' CT White w/ Holes**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1920 Bldg Aquinas**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **98**

MATERIAL DESCRIPTION: **1'x1' CT White w/ Holes**

MATERIAL LOCATION: **Throughout 1920 Bldg Aquinas**

MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 363, 352, 350, 3rd Floor East Stairwell - Bldg 1920 Aquinas**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **99**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **Rooms 363, 352, 350, 3rd Floor East Stairwell - Bldg 1920 Aquinas**

MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MM1**
MATERIAL DESCRIPTION: **9" x 9" Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Ground Floor Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116, 124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, Reading Room, Washrooms, 178, 282, Corridors, Stairs**

MATERIAL QUANTITY: **37796** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **MM1**

MATERIAL DESCRIPTION: **9" x 9" Floor Tile Mastic**

MATERIAL LOCATION: **Ground Floor Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116, 124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, Reading Room, Washrooms, 178, 282, Corridors, Stairs**

MATERIAL QUANTITY: **37796** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE:
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MM2**
MATERIAL DESCRIPTION: **12" x 12" Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms, Teachers Lounge, W Cafeteria, Ground Floor Corridor & Entries, Auditorium Entrance & Foyer, Reading Room, Staff Washrooms, Corridors, and Classrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BULDING ID: **2420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE:
ADDRESS: **1309 W.95th St (9500S)** IDPH LICENSE NO:
43

HOMOGENEOUS AREA: **MM2**

MATERIAL DESCRIPTION: **12" x 12" Floor Tile Mastic**

MATERIAL LOCATION: **Classrooms, Teachers Lounge, W Cafeteria, Ground Floor Corridor & Entries, Auditorium Entrance & Foyer, Reading Room, Staff Washrooms, Corridors, and Classrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed