

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-3534
SCHOOL NAME: Youth Connection - Ada McKinley Lakeside
ADDRESS OF SCHOOL: 2920 S. Wabash Ave.
CITY: Chicago, IL, 60616

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: _____ ENROLLMENT 83 _____

IDPH INSPECTOR LICENSE NUMBER: _____

IDPH LICENSED INSPECTOR NAME (Please Print): _____

IDPH MP LICENSE NUMBER: _____

IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): _____

DESIGNATED PERSON (Please Print): _____ PHONE: _____

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Youth Connection - Ada McKinley Lakeside

2920 S. Wabash Ave.
Chicago, IL, 60616

Unit: 66107
Building ID: 1121G

IDPH ID Number: 14-016-2990-3534

REPORT DATE:

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

 ,,

Phone

Fax

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 66107 Region: IDPH ID: 14-016-2990-3534

School: Youth Connection - Ada McKinley Lakeside Building ID: 1121G

Address: 2920 S. Wabash Ave.

Chicago, IL, 60616

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date:

Review Date:

Inspector: Inspector IDPH License:

Management Planner: Management Planner IDPH License:

If you have any questions or comments, please contact us at

Sincerely,

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date:

RE: Youth Connection - Ada McKinley Lakeside, Unit 66107
2920 S. Wabash Ave.
Chicago, IL, 60616

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Youth Connection - Ada McKinley Lakeside , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Youth Connection - Ada McKinley Lakeside, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact , the designated Local Education Authority's Designated Person at .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Youth Connection - Ada
McKinley Lakeside
Address: 2920 S. Wabash Ave.
IDPH ID: 14-016-2990-3534
Contact:

Unit: 66107
Chicago, IL, 60616
Building ID: 1121G
Phone:

Region:

2. Description of Facility

Original Construction:
Total Square Footage: 18907
Current Occupancy: 83

Additional Construction:
No of Floors:

3. LEA Designated Person

Contact:
Address: 42 West Madison Street
Chicago, IL 60602

Phone:

4. Managing Environmental Consultant

MEC:
Contact:
Address:
Phone:

Fax:

5. Inspector

Inspector Name:

Inspector IDPH license #
Reinspection Date:

Signature:
Date:

6. Management Planner

Management Planner Name:

Management Planner IDPH license #

Signature:
Date:

7. Review Date:

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Name:

Unit : 66107

Youth Connection - Ada McKinley
Lakeside

Building: 1121G

II. EXECUTIVE SUMMARY

was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Youth Connection - Ada McKinley Lakeside. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

- A. The following HAs have changed assessment categories for Building 1121G:

B. The following new homogenous areas have been identified for Building 1121G:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

- 1 12" x 12" Teal Floor Tile
- 10 9" x 9" Beige w/ White Streaks Floor Tile Mastic
- 11 9" x 9" Green w/ White and Black Streaks Floor Tile
- 12 9" x 9" Green w/ White and Black Streaks Floor Tile Mastic
- 13 9" x 9" Dark Green w/ White Streaks Floor Tile
- 14 9" x 9" Dark Green w/ White Streaks Floor Tile Mastic
- 15 9" x 9" White w/ Black Floor Tile
- 16 9" x 9" White w/ Black Floor Tile Mastic
- 17 12" x 12" White w/ Brown Floor Tile
- 18 12" x 12" White w/ Brown Floor Tile Mastic
- 19 12" x 12" Green w/ White Streaks Floor Tile
- 2 12" x 12" Teal Floor Tile Mastic
- 20 12" x 12" Green w/ White Streaks Floor Tile Mastic
- 21 6" Vinyl Baseboard
- 22 6" Vinyl Baseboard Mastic
- 23 1' x 1' Ceiling Tile
- 24 1' x 1' Ceiling Tile w/ Fissures
- 25 Carpet Mastic
- 26 Drywall
- 27 TSI on Water Heater
- 28 Hard Elbows on Fiberglass Pipe Insulation
- 29 Roofing Material- Not AHERA
- 3 9" x 9" Green w/ Beige Floor Tile
- 30 12" x 12" Teal Floor Tile
- 31 12" x 12" Teal Floor Tile Mastic
- 32 12" x 12" Beige Mix Floor Tile
- 33 12" x 12" Beige Mix Floor Tile Mastic
- 34 9" x 9" Dark Green w/ Beige Floor Tile
- 35 9" x 9" Dark Green w/ Beige Floor Tile Mastic
- 36 9" x 9" Beige w/ Green Specks Floor Tile
- 37 9" x 9" Beige w/ Green Specks Floor Tile Mastic
- 38 9" X 9" Brown w/ Tan Floor Tile
- 39 9" X 9" Brown w/ Tan Floor Tile Mastic
- 4 9" x 9" Green w/ Beige Floor Tile Mastic
- 40 9" x 9" Tan w/ Brown Floor Tile
- 41 9" x 9" Tan w/ Brown Floor Tile Mastic
- 42 9" x 9" Red Floor Tile
- 43 9" x 9" Red Floor Tile Mastic
- 44 9" x 9" Grey w/ Black Streaks Floor Tile
- 45 9" x 9" Grey w/ Black Streaks Floor Tile Mastic

46	12" x 12" White w/ Green Specks Floor Tile
47	12" x 12" White w/ Green Specks Floor Tile Mastic
48	12" x 12" Light Brown Mix Floor Tile
49	12" x 12" Light Brown Mix Floor Tile Mastic
5	9" x 9" Beige w/ Green Specks Floor Tile
50	12" x 12" White w/ Black Specks Floor Tile
51	12" x 12" White w/ Black Specks Floor Tile Mastic
52	12" x 12" Pink Mix Floor Tile
53	12" x 12" Pink Mix Floor Tile Mastic
54	9" x 9" Beige w/ Black and Brown Floor Tile
55	9" x 9" Beige w/ Black and Brown Floor Tile Mastic
56	9" x 9" Blue w/ White Floor Tile
57	9" x 9" Blue w/ White Floor Tile Mastic
58	9" x 9" Green w/ White and Black Streaks Floor Tile
59	9" x 9" Green w/ White and Black Streaks Floor Tile Mastic
6	9" x 9" Beige w/ Green Specks Floor Tile Mastic
60	9" x 9" Beige w/ White Streaks Floor Tile
61	9" x 9" Beige w/ White Streaks Floor Tile Mastic
62	9" x 9" Brown w/ Red and White Floor Tile
63	9" x 9" Brown w/ Red and White Floor Tile Mastic
64	Carpet Mastic
65	1' x 1' Ceiling Tile
66	Drywall
67	Plaster
68	Aircell Pipe Insulation
69	Aircell Pipe Fitting Insulation
7	12" x 12" Beige Mix Floor Tile
70	Fittings on Fiberglass Pipe Insulation
71	Vault Door Insulation
72	Roofing Material- Not AHERA
73	Plaster
8	12" x 12" Beige Mix Floor Tile Mastic
9	9" x 9" Beige w/ White Streaks Floor Tile

The following areas were deemed to be inaccessible:

10	9" x 9" Beige w/ White Streaks Floor Tile Mastic
12	9" x 9" Green w/ White and Black Streaks Floor Tile Mastic
14	9" x 9" Dark Green w/ White Streaks Floor Tile Mastic
16	9" x 9" White w/ Black Floor Tile Mastic
18	12" x 12" White w/ Brown Floor Tile Mastic
2	12" x 12" Teal Floor Tile Mastic
20	12" x 12" Green w/ White Streaks Floor Tile Mastic

22	6" Vinyl Baseboard Mastic
25	Carpet Mastic
31	12" x 12" Teal Floor Tile Mastic
33	12" x 12" Beige Mix Floor Tile Mastic
35	9" x 9" Dark Green w/ Beige Floor Tile Mastic
37	9" x 9" Beige w/ Green Specks Floor Tile Mastic
39	9" X 9" Brown w/ Tan Floor Tile Mastic
4	9" x 9" Green w/ Beige Floor Tile Mastic
41	9" x 9" Tan w/ Brown Floor Tile Mastic
43	9" x 9" Red Floor Tile Mastic
45	9" x 9" Grey w/ Black Streaks Floor Tile Mastic
47	12" x 12" White w/ Green Specks Floor Tile Mastic
49	12" x 12" Light Brown Mix Floor Tile Mastic
51	12" x 12" White w/ Black Specks Floor Tile Mastic
53	12" x 12" Pink Mix Floor Tile Mastic
55	9" x 9" Beige w/ Black and Brown Floor Tile Mastic
57	9" x 9" Blue w/ White Floor Tile Mastic
59	9" x 9" Green w/ White and Black Streaks Floor Tile Mastic
6	9" x 9" Beige w/ Green Specks Floor Tile Mastic
61	9" x 9" Beige w/ White Streaks Floor Tile Mastic
63	9" x 9" Brown w/ Red and White Floor Tile Mastic
64	Carpet Mastic
71	Vault Door Insulation
8	12" x 12" Beige Mix Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by , IDPH License # . The Management Plan was updated by , IDPH License # . Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Youth Connection - Ada McKinley Lakeside Building 1121G Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Youth Connection - Ada McKinley Lakeside **Unit** 66107 **Building ID** 1121G
Address 2920 S. Wabash Ave. **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	12" x 12" Teal Floor Tile	220	SF	North Building- Rm. 17, Patching in Hallway, Patching in Lunchroom	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
10	9" x 9" Beige w/ White Streaks Floor Tile Mastic	6	SF	North Building- Rm. 12	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
11	9" x 9" Green w/ White and Black Streaks Floor Tile	90	SF	North Building- Rm. 14 and Storage	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
12	9" x 9" Green w/ White and Black Streaks Floor Tile Mastic	90	SF	North Building- Rm. 14 and Storage	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
13	9" x 9" Dark Green w/ White Streaks Floor Tile	8	SF	North Building- Storage	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
14	9" x 9" Dark Green w/ White Streaks Floor Tile Mastic	8	SF	North Building- Storage	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
15	9" x 9" White w/ Black Floor Tile	8	SF	North Building- Rm. 10	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
16	9" x 9" White w/ Black Floor Tile Mastic	8	SF	North Building- Rm. 10	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
17	12" x 12" White w/ Brown Floor Tile	20	SF	North Building- Custodian Room	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
18	12" x 12" White w/ Brown Floor Tile Mastic	20	SF	North Building- Custodian Room	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
19	12" x 12" Green w/ White Streaks Floor Tile	25	SF	North Building- Custodian Room	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
2	12" x 12" Teal Floor Tile Mastic	220	SF	North Building- Rm. 17, Patching in Hallway, Patching in Lunchroom	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
20	12" x 12" Green w/ White Streaks Floor Tile Mastic	25	SF	North Building- Custodian Room	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
21	6" Vinyl Baseboard	955	LF	North Building- Rm. 11, 12, Hallway, Rm. 13, 16, and Girls' and Boys' Washrooms	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
22	6" Vinyl Baseboard Mastic	955	LF	North Building- Rm. 11, 12, Hallway, Rm. 13, 16, and Girls' and Boys' Washrooms	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
23	1' x 1' Ceiling Tile	3,800	SF	North Building- Throughout	ASSUMED	MISC	Y	NONE	0			Any remaining friable ACBM or friable suspect ACBM		LOW
24	1' x 1' Ceiling Tile w/ Fissures	1,000	SF	North Building- Rm.	ASSUMED	MISC	Y	NONE	0			Any remaining friable		LOW

Chicago Public Schools

School Youth Connection - Ada McKinley Lakeside **Unit** 66107 **Building ID** 1121G
Address 2920 S. Wabash Ave. **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				13								ACBM or friable suspect ACBM		
25	Carpet Mastic	300	SF	North Building- Rm. 17	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
26	Drywall	500	SF	North Building- Rm. 16 and 17 Washrooms, Storage, and Custodian Closet	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
27	TSI on Water Heater	15	SF	North Building- Storage/Mechanical Room	ASSUMED	TSI	Y	NONE	0			Any remaining friable ACBM or friable suspect ACBM		LOW
28	Hard Elbows on Fiberglass Pipe Insulation	3	EA	North Building- Storage/ Mechanical Room	ASSUMED	TSI	Y	NONE	0			Any remaining friable ACBM or friable suspect ACBM		LOW
29	Roofing Material- Not AHERA			North Building- Exterior Roof	ASSUMED									
3	9" x 9" Green w/ Beige Floor Tile	3,000	SF	North Building- Rm. 10, 11, 12, Hallway Rm. 15, 16, 14, Storage, Library	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
30	12" x 12" Teal Floor Tile	280	SF	South Building- Entry Foyer and Janitor's Room	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
31	12" x 12" Teal Floor Tile Mastic	280	SF	South Building- Entry Foyer and Janitor's Room	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
32	12" x 12" Beige Mix Floor Tile	250	SF	South Building- Entry Foyer	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
33	12" x 12" Beige Mix Floor Tile Mastic	250	SF	South Building- Entry Foyer	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
34	9" x 9" Dark Green w/ Beige Floor Tile	1,540	SF	South Building- Entry Foyer, Under Bench, Reception Area, Safe, Hallway, Computer Room, and North Social Science Classroom	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
35	9" x 9" Dark Green w/ Beige Floor Tile Mastic	1,540	SF	South Building- Entry Foyer, Under Bench, Reception Area, Safe, Hallway, Computer Room, and North Social Science Classroom	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW

Chicago Public Schools

School Youth Connection - Ada McKinley Lakeside **Unit** 66107 **Building ID** 1121G
Address 2920 S. Wabash Ave. **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
36	9" x 9" Beige w/ Green Specks Floor Tile	450	SF	South Building- Reception Area and Hallway	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
37	9" x 9" Beige w/ Green Specks Floor Tile Mastic	450	SF	South Building- Reception Area and Hallway	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
38	9" X 9" Brown w/ Tan Floor Tile	1,560	SF	South Building- Office and Science Classroom	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
39	9" X 9" Brown w/ Tan Floor Tile Mastic	1,560	SF	South Building- Office and Science Classroom	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
4	9" x 9" Green w/ Beige Floor Tile Mastic	3,000	SF	North Building- Rm. 10, 11, 12, Hallway Rm. 15, 16, 14, Storage, Library	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
40	9" x 9" Tan w/ Brown Floor Tile	80	SF	South Building- Office and Science Classroom	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
41	9" x 9" Tan w/ Brown Floor Tile Mastic	80	SF	South Building- Office and Science Classroom	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
42	9" x 9" Red Floor Tile	850	SF	South Building- Math/Science Room	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
43	9" x 9" Red Floor Tile Mastic	850	SF	South Building- Math/Science Room	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
44	9" x 9" Grey w/ Black Streaks Floor Tile	80	SF	South Building- Computer Room	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
45	9" x 9" Grey w/ Black Streaks Floor Tile Mastic	80	SF	South Building- Computer Room	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
46	12" x 12" White w/ Green Specks Floor Tile	210	SF	South Building- Hallway and Foyer	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
47	12" x 12" White w/ Green Specks Floor Tile Mastic	210	SF	South Building- Hallway and Foyer	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
48	12" x 12" Light Brown Mix Floor Tile	8	SF	South Building- Janitor's Closet	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
49	12" x 12" Light Brown Mix Floor Tile Mastic	8	SF	South Building- Janitor's Closet	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
5	9" x 9" Beige w/ Green Specks Floor Tile	3,570	SF	North Building- Rm. 10, 11, 12, Hallway Rm. 15, 16, 14, Library	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
50	12" x 12" White w/ Black Specks Floor Tile	290	SF	South Building- South Social Science	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Youth Connection - Ada McKinley Lakeside **Unit** 66107 **Building ID** 1121G
Address 2920 S. Wabash Ave. **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
51	12" x 12" White w/ Black Specks Floor Tile Mastic	290	SF	Room and Office South Building- South Social Science Room and Office	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
52	12" x 12" Pink Mix Floor Tile	660	SF	South Building- South Social Science Room and Office	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
53	12" x 12" Pink Mix Floor Tile Mastic	660	SF	South Building- South Social Science Room and Office	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
54	9" x 9" Beige w/ Black and Brown Floor Tile	80	SF	South Building- South Social Science Room	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
55	9" x 9" Beige w/ Black and Brown Floor Tile Mastic	80	SF	South Building- South Social Science Room	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
56	9" x 9" Blue w/ White Floor Tile	15	SF	South Building- Hallway	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
57	9" x 9" Blue w/ White Floor Tile Mastic	15	SF	South Building- Hallway	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
58	9" x 9" Green w/ White and Black Streaks Floor Tile	10	SF	South Building- Hallway	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
59	9" x 9" Green w/ White and Black Streaks Floor Tile Mastic	10	SF	South Building- Hallway	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
6	9" x 9" Beige w/ Green Specks Floor Tile Mastic	3,570	SF	North Building- Rm. 10, 11, 12, Hallway Rm. 15, 16, 14, Library	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
60	9" x 9" Beige w/ White Streaks Floor Tile	6	SF	South Building- Hallway	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
61	9" x 9" Beige w/ White Streaks Floor Tile Mastic	6	SF	South Building- Hallway	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
62	9" x 9" Brown w/ Red and White Floor Tile	10	SF	South Building- Math/Science Room	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
63	9" x 9" Brown w/ Red and White Floor Tile Mastic	10	SF	South Building- Math/Science Room	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
64	Carpet Mastic	1,000	SF	South Building- Office by Reception, Washroom in Office, and Math Room	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
65	1' x 1' Ceiling Tile	720	SF	South Building- Hallway	ASSUMED	MISC	Y	NONE	0			Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Youth Connection - Ada McKinley Lakeside **Unit** 66107 **Building ID** 1121G
Address 2920 S. Wabash Ave. **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
66	Drywall	1,225	SF	South Building- Office and Washroom in Office next to Reception Area	ASSUMED	MISC	Y	NONE	0			Any remaining friable ACBM or friable suspect ACBM		LOW
67	Plaster	6,680	SF	South Building- Throughout	ASSUMED	SURFACE	Y	NONE	0			Any remaining friable ACBM or friable suspect ACBM		MODERATE
68	Aircell Pipe Insulation	15	LF	South Building- Safe Room	ASSUMED	TSI	Y	NONE	0			Any remaining friable ACBM or friable suspect ACBM		LOW
69	Aircell Pipe Fitting Insulation	6	EA	South Building- Safe Room	ASSUMED	TSI	Y	NONE	0			Any remaining friable ACBM or friable suspect ACBM		LOW
7	12" x 12" Beige Mix Floor Tile	1,200	SF	North Building- Rm. 11, Hallway, and 13	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
70	Fittings on Fiberglass Pipe Insulation	35	EA	South Building- Office by Reception, Math/Science Room, Computer Room, Boys and Girls Washroom, Math Room, Science Walls, South Social Science, Office, and North Social Science Room	ASSUMED	TSI	Y	NONE	0			Any remaining friable ACBM or friable suspect ACBM		LOW
71	Vault Door Insulation	35	SF	South Building- Safe Room	ASSUMED	TSI	Y	NONE	0			Any remaining friable ACBM or friable suspect ACBM		LOW
72	Roofing Material- Not AHERA			South Building- Exterior Roof	ASSUMED									
73	Plaster	13,680	SF	Church- Main Floor	ASSUMED	SURFACE	Y	NONE	0			Any remaining friable ACBM or friable suspect ACBM		LOW
8	12" x 12" Beige Mix Floor Tile Mastic	1,200	SF	North Building- Rm. 11, Hallway, and 13	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
9	9" x 9" Beige w/ White Streaks Floor Tile	6	SF	North Building- Rm. 12	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Youth Connection - Ada McKinley Lakeside **Unit** 66107 **Building ID** 1121G
Address 2920 S. Wabash Ave. **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

Reinspection Date	Inspector's Comments	
Inspector Name		
Inspector's IDPH License Number / Expiration Date		
HA Number:	Inspector Comments:	
1		
10		
11		
12		
13		
14		
15		
16		
17		
18		
19		
2		
20		
21		
22		
23		
24		
25		
26		
27		
28		
29		
3		

Chicago Public Schools

School Youth Connection - Ada McKinley Lakeside **Unit** 66107 **Building ID** 1121G
Address 2920 S. Wabash Ave. **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
31	
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
5	
50	
51	
52	
53	
54	
55	
56	
57	

Chicago Public Schools

School Youth Connection - Ada McKinley Lakeside **Unit** 66107 **Building ID** 1121G
Address 2920 S. Wabash Ave. **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
58	
59	
6	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
7	
70	
71	
72	
73	
8	
9	

Table II
Management Planner's Review

Chicago Public Schools

School Youth Connection - Ada
McKinley Lakeside

Address 2920 S. Wabash Ave.

Unit 66107

Chicago, IL, 60616

Building ID 1121G

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	12" x 12" Teal Floor Tile	220	SF	North Building- Rm. 17, Patching in Hallway, Patching in Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
10	9" x 9" Beige w/ White Streaks Floor Tile Mastic	6	SF	North Building- Rm. 12	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
11	9" x 9" Green w/ White and Black Streaks Floor Tile	90	SF	North Building- Rm. 14 and Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
12	9" x 9" Green w/ White and Black Streaks Floor Tile Mastic	90	SF	North Building- Rm. 14 and Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
13	9" x 9" Dark Green w/ White Streaks Floor Tile	8	SF	North Building- Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
14	9" x 9" Dark Green w/ White Streaks Floor Tile Mastic	8	SF	North Building- Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
15	9" x 9" White w/ Black Floor Tile	8	SF	North Building- Rm. 10	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
16	9" x 9" White w/ Black Floor Tile Mastic	8	SF	North Building- Rm. 10	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
17	12" x 12" White w/ Brown Floor Tile	20	SF	North Building- Custodian Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
18	12" x 12" White w/ Brown Floor Tile Mastic	20	SF	North Building- Custodian Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
19	12" x 12" Green w/ White Streaks Floor Tile	25	SF	North Building- Custodian Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
2	12" x 12" Teal Floor Tile Mastic	220	SF	North Building- Rm. 17, Patching in Hallway, Patching in Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
20	12" x 12" Green w/ White Streaks Floor Tile Mastic	25	SF	North Building- Custodian Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
21	6" Vinyl Baseboard	955	LF	North Building- Rm. 11, 12, Hallway, Rm. 13, 16, and Girls' and Boys' Washrooms	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
22	6" Vinyl Baseboard Mastic	955	LF	North Building- Rm. 11, 12, Hallway, Rm. 13, 16, and Girls' and Boys' Washrooms	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
23	1' x 1' Ceiling Tile	3,800	SF	North Building- Throughout	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
24	1' x 1' Ceiling Tile w/ Fissures	1,000	SF	North Building- Rm. 13	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
25	Carpet Mastic	300	SF	North Building- Rm. 17	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
26	Drywall	500	SF	North Building- Rm. 16 and 17 Washrooms, Storage, and Custodian Closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
27	TSI on Water Heater	15	SF	North Building- Storage/Mechanical Room	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
28	Hard Elbows on Fiberglass Pipe Insulation	3	EA	North Building- Storage/ Mechanical Room	Assumed	TSI	Yes	0	EA	7 Any remaining friable ACBM or friable suspect ACBM	

Chicago Public Schools

School Youth Connection - Ada
McKinley Lakeside

Address 2920 S. Wabash Ave.

Unit 66107

Chicago, IL, 60616

Building ID 1121G

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
29	Roofing Material- Not AHERA			North Building- Exterior Roof	Assumed						
3	9" x 9" Green w/ Beige Floor Tile	3,000	SF	North Building- Rm. 10, 11, 12, Hallway Rm. 15, 16, 14, Storage, Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
30	12" x 12" Teal Floor Tile	280	SF	South Building- Entry Foyer and Janitor's Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
31	12" x 12" Teal Floor Tile Mastic	280	SF	South Building- Entry Foyer and Janitor's Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
32	12" x 12" Beige Mix Floor Tile	250	SF	South Building- Entry Foyer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
33	12" x 12" Beige Mix Floor Tile Mastic	250	SF	South Building- Entry Foyer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
34	9" x 9" Dark Green w/ Beige Floor Tile	1,540	SF	South Building- Entry Foyer, Under Bench, Reception Area, Safe, Hallway, Computer Room, and North Social Science Classroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
35	9" x 9" Dark Green w/ Beige Floor Tile Mastic	1,540	SF	South Building- Entry Foyer, Under Bench, Reception Area, Safe, Hallway, Computer Room, and North Social Science Classroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
36	9" x 9" Beige w/ Green Specks Floor Tile	450	SF	South Building- Reception Area and Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
37	9" x 9" Beige w/ Green Specks Floor Tile Mastic	450	SF	South Building- Reception Area and Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
38	9" X 9" Brown w/ Tan Floor Tile	1,560	SF	South Building- Office and Science Classroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
39	9" X 9" Brown w/ Tan Floor Tile Mastic	1,560	SF	South Building- Office and Science Classroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
4	9" x 9" Green w/ Beige Floor Tile Mastic	3,000	SF	North Building- Rm. 10, 11, 12, Hallway Rm. 15, 16, 14, Storage, Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
40	9" x 9" Tan w/ Brown Floor Tile	80	SF	South Building- Office and Science Classroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
41	9" x 9" Tan w/ Brown Floor Tile Mastic	80	SF	South Building- Office and Science Classroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
42	9" x 9" Red Floor Tile	850	SF	South Building- Math/Science Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
43	9" x 9" Red Floor Tile Mastic	850	SF	South Building- Math/Science Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
44	9" x 9" Grey w/ Black Streaks Floor Tile	80	SF	South Building- Computer Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
45	9" x 9" Grey w/ Black Streaks Floor Tile Mastic	80	SF	South Building- Computer Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	

Chicago Public Schools

School Youth Connection - Ada
McKinley Lakeside

Address 2920 S. Wabash Ave.

Unit 66107

Chicago, IL, 60616

Building ID 1121G

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
46	12" x 12" White w/ Green Specks Floor Tile	210	SF	South Building- Hallway and Foyer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
47	12" x 12" White w/ Green Specks Floor Tile Mastic	210	SF	South Building- Hallway and Foyer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
48	12" x 12" Light Brown Mix Floor Tile	8	SF	South Building- Janitor's Closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
49	12" x 12" Light Brown Mix Floor Tile Mastic	8	SF	South Building- Janitor's Closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
5	9" x 9" Beige w/ Green Specks Floor Tile	3,570	SF	North Building- Rm. 10, 11, 12, Hallway Rm. 15, 16, 14, Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
50	12" x 12" White w/ Black Specks Floor Tile	290	SF	South Building- South Social Science Room and Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
51	12" x 12" White w/ Black Specks Floor Tile Mastic	290	SF	South Building- South Social Science Room and Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
52	12" x 12" Pink Mix Floor Tile	660	SF	South Building- South Social Science Room and Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
53	12" x 12" Pink Mix Floor Tile Mastic	660	SF	South Building- South Social Science Room and Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
54	9" x 9" Beige w/ Black and Brown Floor Tile	80	SF	South Building- South Social Science Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
55	9" x 9" Beige w/ Black and Brown Floor Tile Mastic	80	SF	South Building- South Social Science Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
56	9" x 9" Blue w/ White Floor Tile	15	SF	South Building- Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
57	9" x 9" Blue w/ White Floor Tile Mastic	15	SF	South Building- Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
58	9" x 9" Green w/ White and Black Streaks Floor Tile	10	SF	South Building- Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
59	9" x 9" Green w/ White and Black Streaks Floor Tile Mastic	10	SF	South Building- Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
6	9" x 9" Beige w/ Green Specks Floor Tile Mastic	3,570	SF	North Building- Rm. 10, 11, 12, Hallway Rm. 15, 16, 14, Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
60	9" x 9" Beige w/ White Streaks Floor Tile	6	SF	South Building- Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
61	9" x 9" Beige w/ White Streaks Floor Tile Mastic	6	SF	South Building- Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
62	9" x 9" Brown w/ Red and White Floor Tile	10	SF	South Building- Math/Science Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
63	9" x 9" Brown w/ Red and White Floor Tile Mastic	10	SF	South Building- Math/Science Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
64	Carpet Mastic	1,000	SF	South Building- Office by Reception, Washroom in Office, and Math Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
65	1' x 1' Ceiling Tile	720	SF	South Building- Hallway	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
66	Drywall	1,225	SF	South Building- Office and Washroom in Office next to Reception Area	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	

Chicago Public Schools

School Youth Connection - Ada
McKinley Lakeside

Address 2920 S. Wabash Ave.

Unit 66107

Chicago, IL, 60616

Building ID 1121G

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
67	Plaster	6,680	SF	South Building- Throughout	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
68	Aircell Pipe Insulation	15	LF	South Building- Safe Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	
69	Aircell Pipe Fitting Insulation	6	EA	South Building- Safe Room	Assumed	TSI	Yes	0	EA	7 Any remaining friable ACBM or friable suspect ACBM	
7	12" x 12" Beige Mix Floor Tile	1,200	SF	North Building- Rm. 11, Hallway, and 13	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
70	Fittings on Fiberglass Pipe Insulation	35	EA	South Building- Office by Reception, Math/Science Room, Computer Room, Boys and Girls Washroom, Math Room, Science Walls, South Social Science, Office, and North Social Science Room	Assumed	TSI	Yes	0	EA	7 Any remaining friable ACBM or friable suspect ACBM	
71	Vault Door Insulation	35	SF	South Building- Safe Room	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
72	Roofing Material- Not AHERA			South Building- Exterior Roof	Assumed						
73	Plaster	13,680	SF	Church- Main Floor	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
8	12" x 12" Beige Mix Floor Tile Mastic	1,200	SF	North Building- Rm. 11, Hallway, and 13	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
9	9" x 9" Beige w/ White Streaks Floor Tile	6	SF	North Building- Rm. 12	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	

Chicago Public Schools

School Youth Connection - Ada
McKinley Lakeside
Address 2920 S. Wabash Ave.

Unit 66107
Chicago, IL, 60616

Building ID 1121G
Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

Review Date	_____
Manager Planner Name	_____
Manager IDPH License No/Expiration	_____

HA Number	Management Comments
1	_____
10	_____
11	_____
12	_____
13	_____
14	_____
15	_____
16	_____
17	_____
18	_____
19	_____
2	_____
20	_____
21	_____
22	_____
23	_____
24	_____

Chicago Public Schools

School Youth Connection - Ada
McKinley Lakeside

Address 2920 S. Wabash Ave.

Unit 66107

Chicago, IL, 60616

Building ID 1121G

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
25	
26	
27	
28	
29	
3	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	

Chicago Public Schools

School Youth Connection - Ada
McKinley Lakeside

Address 2920 S. Wabash Ave.

Unit 66107

Chicago, IL, 60616

Building ID 1121G

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
49	
5	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
6	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
7	
70	
71	

Chicago Public Schools

School Youth Connection - Ada
McKinley Lakeside

Address 2920 S. Wabash Ave.

Unit 66107

Chicago, IL, 60616

Building ID 1121G

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
72	
73	
8	
9	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

2025 AHERA REINSPECTION

Chicago Public Schools

2025 AHERA REINSPECTION Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **12" x 12" Teal Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **North Building- Rm. 17, Patching in Hallway, Patching in Lunchroom**
MATERIAL QUANTITY: **220** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **12" x 12" Teal Floor Tile**

MATERIAL LOCATION: **North Building- Rm. 17, Patching in Hallway, Patching in Lunchroom**

MATERIAL QUANTITY: **220** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **9" x 9" Beige w/ White Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Building- Rm. 12**
MATERIAL QUANTITY: **6** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **6** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **9" x 9" Beige w/ White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **North Building- Rm. 12**

MATERIAL QUANTITY: **6** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **9" x 9" Green w/ White and Black Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **North Building- Rm. 14 and Storage**
MATERIAL QUANTITY: **90** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **9" x 9" Green w/ White and Black Streaks Floor Tile**

MATERIAL LOCATION: **North Building- Rm. 14 and Storage**

MATERIAL QUANTITY: **90** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **9" x 9" Green w/ White and Black Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Building- Rm. 14 and Storage**
MATERIAL QUANTITY: **90** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **9" x 9" Green w/ White and Black Streaks Floor Tile Mastic**

MATERIAL LOCATION: **North Building- Rm. 14 and Storage**

MATERIAL QUANTITY: **90** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **9" x 9" Dark Green w/ White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **North Building- Storage**
MATERIAL QUANTITY: **8** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **9" x 9" Dark Green w/ White Streaks Floor Tile**

MATERIAL LOCATION: **North Building- Storage**

MATERIAL QUANTITY: **8** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **9" x 9" Dark Green w/ White Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Building- Storage**
MATERIAL QUANTITY: **8** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **9" x 9" Dark Green w/ White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **North Building- Storage**

MATERIAL QUANTITY: **8** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **9" x 9" White w/ Black Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **North Building- Rm. 10**
MATERIAL QUANTITY: **8** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **9" x 9" White w/ Black Floor Tile**

MATERIAL LOCATION: **North Building- Rm. 10**

MATERIAL QUANTITY: **8** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **9" x 9" White w/ Black Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Building- Rm. 10**
MATERIAL QUANTITY: **8** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **9" x 9" White w/ Black Floor Tile Mastic**

MATERIAL LOCATION: **North Building- Rm. 10**

MATERIAL QUANTITY: **8** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **North Building- Custodian Room**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Floor Tile**

MATERIAL LOCATION: **North Building- Custodian Room**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Building- Custodian Room**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12" x 12" White w/ Brown Floor Tile Mastic**

MATERIAL LOCATION: **North Building- Custodian Room**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12" x 12" Green w/ White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **North Building- Custodian Room**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **12" x 12" Green w/ White Streaks Floor Tile**

MATERIAL LOCATION: **North Building- Custodian Room**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **12" x 12" Teal Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Building- Rm. 17, Patching in Hallway, Patching in Lunchroom**
MATERIAL QUANTITY: **220** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **12" x 12" Teal Floor Tile Mastic**

MATERIAL LOCATION: **North Building- Rm. 17, Patching in Hallway, Patching in Lunchroom**

MATERIAL QUANTITY: **220** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12" x 12" Green w/ White Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Building- Custodian Room**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **12" x 12" Green w/ White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **North Building- Custodian Room**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **6" Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Building- Rm. 11, 12, Hallway, Rm. 13, 16, and Girls' and Boys' Washrooms**
MATERIAL QUANTITY: **955** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **6" Vinyl Baseboard**

MATERIAL LOCATION: **North Building- Rm. 11, 12, Hallway, Rm. 13, 16, and Girls' and Boys' Washrooms**

MATERIAL QUANTITY: **955** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **6" Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Building- Rm. 11, 12, Hallway, Rm. 13, 16, and Girls' and Boys' Washrooms**
MATERIAL QUANTITY: **955** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **6" Vinyl Baseboard Mastic**

MATERIAL LOCATION: **North Building- Rm. 11, 12, Hallway, Rm. 13, 16, and Girls' and Boys' Washrooms**

MATERIAL QUANTITY: **955** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Building- Throughout**
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**

MATERIAL LOCATION: **North Building- Throughout**

MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile w/ Fissures**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Building- Rm. 13**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile w/ Fissures**

MATERIAL LOCATION: **North Building- Rm. 13**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Building- Rm. 17**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **300** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **North Building- Rm. 17**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **North Building- Rm. 16 and 17 Washrooms, Storage, and Custodian Closet**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **North Building- Rm. 16 and 17 Washrooms, Storage, and Custodian Closet**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **TSI on Water Heater**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Building- Storage/Mechanical Room**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **TSI on Water Heater**

MATERIAL LOCATION: **North Building- Storage/Mechanical Room**

MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Hard Elbows on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Building- Storage/ Mechanical Room**
MATERIAL QUANTITY: **3** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **3** DAMAGE UNITS: **EA**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Hard Elbows on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **North Building- Storage/ Mechanical Room**

MATERIAL QUANTITY: **3** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Roofing Material- Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **North Building- Exterior Roof**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Roofing Material- Not AHERA**

MATERIAL LOCATION: **North Building- Exterior Roof**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**
MATERIAL DESCRIPTION: **9" x 9" Green w/ Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **North Building- Rm. 10, 11, 12, Hallway Rm. 15, 16, 14, Storage, Library**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **9" x 9" Green w/ Beige Floor Tile**

MATERIAL LOCATION: **North Building- Rm. 10, 11, 12, Hallway Rm. 15, 16, 14, Storage, Library**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12" x 12" Teal Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **South Building- Entry Foyer and Janitor's Room**
MATERIAL QUANTITY: **280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **12" x 12" Teal Floor Tile**

MATERIAL LOCATION: **South Building- Entry Foyer and Janitor's Room**

MATERIAL QUANTITY: **280** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12" x 12" Teal Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building- Entry Foyer and Janitor's Room**
MATERIAL QUANTITY: **280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12" x 12" Teal Floor Tile Mastic**

MATERIAL LOCATION: **South Building- Entry Foyer and Janitor's Room**

MATERIAL QUANTITY: **280** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **South Building- Entry Foyer**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile**

MATERIAL LOCATION: **South Building- Entry Foyer**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building- Entry Foyer**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile Mastic**

MATERIAL LOCATION: **South Building- Entry Foyer**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **9" x 9" Dark Green w/ Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **South Building- Entry Foyer, Under Bench, Reception Area, Safe, Hallway, Computer Room, and North Social Science Classroom**

MATERIAL QUANTITY: **1540** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **9" x 9" Dark Green w/ Beige Floor Tile**

MATERIAL LOCATION: **South Building- Entry Foyer, Under Bench, Reception Area, Safe, Hallway, Computer Room, and North Social Science Classroom**

MATERIAL QUANTITY: **1540** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **9" x 9" Dark Green w/ Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building- Entry Foyer, Under Bench, Reception Area, Safe, Hallway, Computer Room, and North Social Science Classroom**
MATERIAL QUANTITY: **1540** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **9" x 9" Dark Green w/ Beige Floor Tile Mastic**

MATERIAL LOCATION: **South Building- Entry Foyer, Under Bench, Reception Area, Safe, Hallway, Computer Room, and North Social Science Classroom**

MATERIAL QUANTITY: **1540** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **9" x 9" Beige w/ Green Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **South Building- Reception Area and Hallway**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **9" x 9" Beige w/ Green Specks Floor Tile**

MATERIAL LOCATION: **South Building- Reception Area and Hallway**

MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **9" x 9" Beige w/ Green Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building- Reception Area and Hallway**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **9" x 9" Beige w/ Green Specks Floor Tile Mastic**

MATERIAL LOCATION: **South Building- Reception Area and Hallway**

MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **9" X 9" Brown w/ Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **South Building- Office and Science Classroom**
MATERIAL QUANTITY: **1560** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **9" X 9" Brown w/ Tan Floor Tile**

MATERIAL LOCATION: **South Building- Office and Science Classroom**

MATERIAL QUANTITY: **1560** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **9" X 9" Brown w/ Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building- Office and Science Classroom**
MATERIAL QUANTITY: **1560** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **9" X 9" Brown w/ Tan Floor Tile Mastic**

MATERIAL LOCATION: **South Building- Office and Science Classroom**

MATERIAL QUANTITY: **1560** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **9" x 9" Green w/ Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Building- Rm. 10, 11, 12, Hallway Rm. 15, 16, 14, Storage, Library**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **9" x 9" Green w/ Beige Floor Tile Mastic**

MATERIAL LOCATION: **North Building- Rm. 10, 11, 12, Hallway Rm. 15, 16, 14, Storage, Library**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **9" x 9" Tan w/ Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **South Building- Office and Science Classroom**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **9" x 9" Tan w/ Brown Floor Tile**

MATERIAL LOCATION: **South Building- Office and Science Classroom**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **9" x 9" Tan w/ Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building- Office and Science Classroom**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **9" x 9" Tan w/ Brown Floor Tile Mastic**

MATERIAL LOCATION: **South Building- Office and Science Classroom**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **South Building- Math/Science Room**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile**

MATERIAL LOCATION: **South Building- Math/Science Room**

MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building- Math/Science Room**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile Mastic**

MATERIAL LOCATION: **South Building- Math/Science Room**

MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **9" x 9" Grey w/ Black Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **South Building- Computer Room**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **9" x 9" Grey w/ Black Streaks Floor Tile**

MATERIAL LOCATION: **South Building- Computer Room**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **9" x 9" Grey w/ Black Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building- Computer Room**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **80** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **9" x 9" Grey w/ Black Streaks Floor Tile Mastic**

MATERIAL LOCATION: **South Building- Computer Room**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **12" x 12" White w/ Green Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **South Building- Hallway and Foyer**
MATERIAL QUANTITY: **210** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **12" x 12" White w/ Green Specks Floor Tile**

MATERIAL LOCATION: **South Building- Hallway and Foyer**

MATERIAL QUANTITY: **210** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **12" x 12" White w/ Green Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building- Hallway and Foyer**
MATERIAL QUANTITY: **210** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **12" x 12" White w/ Green Specks Floor Tile Mastic**

MATERIAL LOCATION: **South Building- Hallway and Foyer**

MATERIAL QUANTITY: **210** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building- Janitor's Closet**
MATERIAL QUANTITY: **8** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Mix Floor Tile**

MATERIAL LOCATION: **South Building- Janitor's Closet**

MATERIAL QUANTITY: **8** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building- Janitor's Closet**
MATERIAL QUANTITY: **8** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **8** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Mix Floor Tile Mastic**

MATERIAL LOCATION: **South Building- Janitor's Closet**

MATERIAL QUANTITY: **8** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **9" x 9" Beige w/ Green Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **North Building- Rm. 10, 11, 12, Hallway Rm. 15, 16, 14, Library**
MATERIAL QUANTITY: **3570** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **9" x 9" Beige w/ Green Specks Floor Tile**

MATERIAL LOCATION: **North Building- Rm. 10, 11, 12, Hallway Rm. 15, 16, 14, Library**

MATERIAL QUANTITY: **3570** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **12" x 12" White w/ Black Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **South Building- South Social Science Room and Office**
MATERIAL QUANTITY: **290** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **12" x 12" White w/ Black Specks Floor Tile**

MATERIAL LOCATION: **South Building- South Social Science Room and Office**

MATERIAL QUANTITY: **290** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **12" x 12" White w/ Black Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building- South Social Science Room and Office**
MATERIAL QUANTITY: **290** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **12" x 12" White w/ Black Specks Floor Tile Mastic**

MATERIAL LOCATION: **South Building- South Social Science Room and Office**

MATERIAL QUANTITY: **290** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12" x 12" Pink Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **South Building- South Social Science Room and Office**
MATERIAL QUANTITY: **660** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **12" x 12" Pink Mix Floor Tile**

MATERIAL LOCATION: **South Building- South Social Science Room and Office**

MATERIAL QUANTITY: **660** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **12" x 12" Pink Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building- South Social Science Room and Office**
MATERIAL QUANTITY: **660** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **12" x 12" Pink Mix Floor Tile Mastic**

MATERIAL LOCATION: **South Building- South Social Science Room and Office**

MATERIAL QUANTITY: **660** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **9" x 9" Beige w/ Black and Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **South Building- South Social Science Room**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **9" x 9" Beige w/ Black and Brown Floor Tile**

MATERIAL LOCATION: **South Building- South Social Science Room**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **9" x 9" Beige w/ Black and Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building- South Social Science Room**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **9" x 9" Beige w/ Black and Brown Floor Tile Mastic**

MATERIAL LOCATION: **South Building- South Social Science Room**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **9" x 9" Blue w/ White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **South Building- Hallway**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **9" x 9" Blue w/ White Floor Tile**

MATERIAL LOCATION: **South Building- Hallway**

MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **9" x 9" Blue w/ White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building- Hallway**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **9" x 9" Blue w/ White Floor Tile Mastic**

MATERIAL LOCATION: **South Building- Hallway**

MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **9" x 9" Green w/ White and Black Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **South Building- Hallway**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **9" x 9" Green w/ White and Black Streaks Floor Tile**

MATERIAL LOCATION: **South Building- Hallway**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **9" x 9" Green w/ White and Black Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building- Hallway**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **9" x 9" Green w/ White and Black Streaks Floor Tile Mastic**

MATERIAL LOCATION: **South Building- Hallway**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **9" x 9" Beige w/ Green Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Building- Rm. 10, 11, 12, Hallway Rm. 15, 16, 14, Library**
MATERIAL QUANTITY: **3570** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **9" x 9" Beige w/ Green Specks Floor Tile Mastic**

MATERIAL LOCATION: **North Building- Rm. 10, 11, 12, Hallway Rm. 15, 16, 14, Library**

MATERIAL QUANTITY: **3570** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **9" x 9" Beige w/ White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **South Building- Hallway**
MATERIAL QUANTITY: **6** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **6** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **9" x 9" Beige w/ White Streaks Floor Tile**

MATERIAL LOCATION: **South Building- Hallway**

MATERIAL QUANTITY: **6** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **9" x 9" Beige w/ White Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building- Hallway**
MATERIAL QUANTITY: **6** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **6** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **9" x 9" Beige w/ White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **South Building- Hallway**

MATERIAL QUANTITY: **6** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **9" x 9" Brown w/ Red and White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **South Building- Math/Science Room**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **9" x 9" Brown w/ Red and White Floor Tile**

MATERIAL LOCATION: **South Building- Math/Science Room**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **9" x 9" Brown w/ Red and White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building- Math/Science Room**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **9" x 9" Brown w/ Red and White Floor Tile Mastic**

MATERIAL LOCATION: **South Building- Math/Science Room**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building- Office by Reception, Washroom in Office, and Math Room**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **South Building- Office by Reception, Washroom in Office, and Math Room**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building- Hallway**
MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**

MATERIAL LOCATION: **South Building- Hallway**

MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building- Office and Washroom in Office next to Reception Area**
MATERIAL QUANTITY: **1225** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **South Building- Office and Washroom in Office next to Reception Area**

MATERIAL QUANTITY: **1225** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **South Building- Throughout**
MATERIAL QUANTITY: **6680** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **South Building- Throughout**

MATERIAL QUANTITY: **6680** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building- Safe Room**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **15** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **South Building- Safe Room**

MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **Aircell Pipe Fitting Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building- Safe Room**
MATERIAL QUANTITY: **6** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **6** DAMAGE UNITS: **EA**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **Aircell Pipe Fitting Insulation**

MATERIAL LOCATION: **South Building- Safe Room**

MATERIAL QUANTITY: **6** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUILDING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **North Building- Rm. 11, Hallway, and 13**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile**

MATERIAL LOCATION: **North Building- Rm. 11, Hallway, and 13**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Fittings on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **South Building- Office by Reception, Math/Science Room, Computer Room, Boys and Girls Washroom, Math Room, Science Walls, South Social Science, Office, and North Social Science Room**

MATERIAL QUANTITY: **35** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **Fittings on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **South Building- Office by Reception, Math/Science Room, Computer Room, Boys and Girls Washroom, Math Room, Science Walls, South Social Science, Office, and North Social Science Room**

MATERIAL QUANTITY: **35** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **Vault Door Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building- Safe Room**
MATERIAL QUANTITY: **35** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **Vault Door Insulation**

MATERIAL LOCATION: **South Building- Safe Room**

MATERIAL QUANTITY: **35** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **Roofing Material- Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **South Building- Exterior Roof**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **Roofing Material- Not AHERA**

MATERIAL LOCATION: **South Building- Exterior Roof**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Church- Main Floor**
MATERIAL QUANTITY: **13680** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Church- Main Floor**

MATERIAL QUANTITY: **13680** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Building- Rm. 11, Hallway, and 13**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile Mastic**

MATERIAL LOCATION: **North Building- Rm. 11, Hallway, and 13**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BUIDLING ID: **1121G**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** INSPECTION DATE:
ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **9" x 9" Beige w/ White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **North Building- Rm. 12**
MATERIAL QUANTITY: **6** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **6** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66107** BULDING ID: **1121G**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Youth Connection - Ada McKinley Lakeside** REVIEW DATE:

ADDRESS: **2920 S. Wabash Ave.** IDPH LICENSE NO:

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **9" x 9" Beige w/ White Streaks Floor Tile**

MATERIAL LOCATION: **North Building- Rm. 12**

MATERIAL QUANTITY: **6** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed