

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-381X
SCHOOL NAME: Acero - Carlos Fuentes Campus Charter
ADDRESS OF SCHOOL: 2845 West Barry
CITY: Chicago, IL,

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **2/5/2024**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: _____ ENROLLMENT 239 _____

IDPH INSPECTOR LICENSE NUMBER: _____

IDPH LICENSED INSPECTOR NAME (Please Print): _____

IDPH MP LICENSE NUMBER: _____

IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): _____

DESIGNATED PERSON (Please Print): _____ PHONE: _____

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Acero - Carlos Fuentes Campus Charter

2845 West Barry
Chicago, IL,

Unit: 66393
Building ID: 3342

IDPH ID Number: 14-016-2990-381X

REPORT DATE:

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

''

Phone

Fax

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 66393 Region: IDPH ID: 14-016-2990-381X

School: Acero - Carlos Fuentes Campus Charter Building ID: 3342

Address: 2845 West Barry

Chicago, IL,

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date:

Review Date:

Inspector: Inspector IDPH License:

Management Planner: Management Planner IDPH License:

If you have any questions or comments, please contact us at

Sincerely,

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date:

RE: Acero - Carlos Fuentes Campus Charter, Unit 66393
2845 West Barry
Chicago, IL,

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Acero - Carlos Fuentes Campus Charter , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Acero - Carlos Fuentes Campus Charter, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact , the designated Local Education Authority's Designated Person at .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Acero - Carlos Fuentes Unit: 66393 Region:
Campus Charter
Address: 2845 West Barry Chicago, IL,
IDPH ID: 14-016-2990-381X Building ID: 3342
Contact: Phone:

2. Description of Facility

Original Construction: 1906 Additional Construction: 1906
Total Square Footage: 13600 No of Floors:
Current Occupancy: 239

3. LEA Designated Person

Contact: Phone:
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC:
Contact:
Address
Phone: Fax:

5. Inspector

Inspector Name:

Inspector IDPH license # Signature:
Reinspection Date: Date:

6. Management Planner

Management Planner Name:

Management Planner IDPH license # Signature:
Date:

7. Review Date:

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Name:

II. EXECUTIVE SUMMARY

was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Acero - Carlos Fuentes Campus Charter. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

- A. The following HAs have changed assessment categories for Building 3342:

B. The following new homogenous areas have been identified for Building 3342:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

008	Acoustical Plaster
012	9"x9" Tan & Red Vinyl Floor Tile
013	9"x9" Tan Vinyl Floor Tile
015	9"x9" Tan Vinyl Floor Tile Mastic
017	9"x9" Tan & Red Vinyl Floor Tile Mastic
018	9"x9" Tan Floor Tile Mastic - Not Observed
019	9"x9" Tan and Red Vinyl Floor Tile
020	9"x9" Tan and Red Vinyl Floor Tile Mastic
022	12"x12" Cream w/ White Floor Tile
023	12"x12" Cream w/ White Floor Tile Mastic
024	12"x12" Ceiling Tile w/ Glue Pucks
025	Hard Plaster
026	12"x12" Brown w/Brown & White Streaks Floor Tile
027	12"x12" Brown w/Brown & White Streaks Floor Tile Mastic
028	12"x12" Cream Floor Tile
029	12"x12" Cream Floor Tile Mastic
030	12"x12" Beige w/Brown Floor Tile
031	12"x12" Beige w/Brown Floor Tile Mastic
034	12"x12" Brown Streaked Floor Tile
035	12"x12" Brown Streaked Floor Tile Mastic
036	12"x12" Blue Floor Tile
037	12"x12" Blue Floor Tile Mastic
038	12"x12" Blue Floor Tile
039	12"x12" Blue Floor Tile Mastic
040	12"x12" Blue Floor Tile
041	12"x12" Blue Floor Tile Mastic
042	12"x12" Beige Floor Tile
043	12"x12" Beige Floor Tile Mastic
044	2'x4' Lay In Ceiling Panels w/2'x2' Design
045	4" Blue Vinyl Baseboard
046	4" Blue Vinyl Baseboard Adhesive
048	Blue Vinyl Stair Treads
049	Blue Vinyl Stair Tread Adhesive
050	Purple Vinyl Stair Treads
051	Purple Vinyl Stair Tread Adhesive
052	Linoleum on Counters
053	Linoleum Adhesive on Counters
054	Chalkboards
055	Chalkboard Adhesive
056	Marker Board Adhesive

057	4" Brown Vinyl Baseboard
058	4" Brown Vinyl Baseboard Adhesive
60	12" x 12" Tan Floor Tile
60A	12" x 12" Tan Floor Tile Mastic
62	12" x 12" Beige Speckled VFT
63	12" x 12" Beige Speckled VFT Mastic
64	12" x 12" Yellow w/ Red VFT
65	12" x 12" Yellow w/ Red Specks Mastic
66	Drywall System
67	Black Baseboard
68	Black Baseboard Mastic
69	2' x 2' Pinhole Ceiling Tiles
70	MJP on Fiberglass Pipe Insulation
71	Drywall System
72	6" Black Baseboard Mastic
73	2' x 4' Smooth Ceiling Tile
74	4" Blue Baseboard Mastic
75	2' x 2' Pinhole Ceiling Tiles
76	12" x 12" Light Sand VFT
77	12" x 12" Light Sand VFT Mastic
78	Terrazzo Mixed Colors
79	Terrazzo Green

The following areas were deemed to be inaccessible:

055	Chalkboard Adhesive
056	Marker Board Adhesive

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by , IDPH License # . The Management Plan was updated by , IDPH License # . Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Acero - Carlos Fuentes Campus Charter Building 3342 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Acero - Carlos Fuentes Campus Charter **Unit** 66393 **Building ID** 3342
Address 2845 West Barry **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
001	Low Pressure Steam Pipe Insulation	155	LF	Basement Throughout, Cafeteria - Building B	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
002	Low Pressure Steam Pipe Fitting Insulation	21	LF	Basement Throughout, Cafeteria - Building B	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
004	Joint Insulation (MJP) Associated/w Aircell Pipe Insulation	140	LF	Basement Throughout, Cafeteria - Building B	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
005	Paperwrap Pipe Insulation on Chilled Water Piping	75	LF	Basement Throughout, Cafeteria - Building B	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
006	Joint Insulation (MJP) on Paperwrap Insulated Piping	8	LF	Basement Throughout - Building A	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
007	Joint Insulation (MJP) on Paperwrap Insulated Piping	60	LF	Basement Throughout - Building B	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
008	Acoustical Plaster	6,300	SF	Basement Lunchroom Ceiling	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
010	9"x9" Tan Floor Tile - ABATED		SF	Boiler Room Foyer	ABATED	MISC	N	NONE	0		No			
011	12"x 12" Gray Floor Tile - Abated			Tunnel Between Buildings - Abated	ABATED	MISC								
012	9"x9" Tan & Red Vinyl Floor Tile	5,040	SF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
013	9"x9" Tan Vinyl Floor Tile	1,260	SF	Lunchroom, Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
015	9"x9" Tan Vinyl Floor Tile Mastic	1,260	SF	Lunchroom, Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
016	12"x 12" Gray Floor Tile Mastic - Abated			Tunnel Between Buildings - Abated	ABATED	MISC								
017	9"x9" Tan & Red Vinyl Floor Tile Mastic	5,040	SF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
018	9"x9" Tan Floor Tile Mastic - Not Observed		SF	Boiler Room Foyer	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
019	9"x9" Tan and Red Vinyl Floor Tile	12,000	SF	Building A Corridors and Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
020	9"x9" Tan and Red Vinyl Floor Tile Mastic	12,000	SF	Building A Corridors and	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Acero - Carlos Fuentes Campus Charter **Unit** 66393 **Building ID** 3342
Address 2845 West Barry **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Classrooms										
021	Joint Insulaiton (MJP) Assoc/w Fiberglass Insulated Pipe - Abated			Boiler Room 1 in B Building - Abated	ABATED	TSI								
022	12"x12" Cream w/ White Floor Tile	130	SF	Building A Foyer	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
023	12"x12" Cream w/ White Floor Tile Mastic	130	SF	Building A Foyer	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
024	12"x12" Ceiling Tile w/ Glue Pucks	4,000	SF	Building A Throughout	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
025	Hard Plaster	20,000	SF	Throughout Buildings A & B	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
026	12"x12" Brown w/Brown & White Streaks Floor Tile	80	SF	Entrance of Building A- Stair Landing	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
027	12"x12" Brown w/Brown & White Streaks Floor Tile Mastic	80	SF	Entrance of Building A- Stair Landing	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
028	12"x12" Cream Floor Tile	300	SF	Classroom 004 in A Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
029	12"x12" Cream Floor Tile Mastic	300	SF	Classroom 004 in A Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
030	12"x12" Beige w/Brown Floor Tile	40	SF	A Building Stair Landing Between 1st & 2nd Floors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
031	12"x12" Beige w/Brown Floor Tile Mastic	40	SF	A Building Stair Landing Between 1st & 2nd Floors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
032	9"x9" Dark Brown Floor Tile - Abated			A Building Janitor Closet 107 - Abated	ABATED	MISC								
033	9"x9" Dark Brown Floor Tile Mastic - Abated			A Building Janitor Closet 107 - Abated	ABATED	MISC								
034	12"x12" Brown Streaked Floor Tile	60	SF	A Building Southeast Stair Landing	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
035	12"x12" Brown Streaked Floor Tile Mastic	60	SF	A Building Southeast Stair Landing	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
036	12"x12" Blue Floor Tile	408	SF	A Building Room 101, Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
037	12"x12" Blue Floor Tile Mastic	408	SF	A Building Room 101, Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
038	12"x12" Blue Floor Tile	406	SF	Kitchen / Pantry	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
039	12"x12" Blue Floor Tile Mastic	406	SF	Kitchen & Washroom by B206 AND Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Acero - Carlos Fuentes Campus Charter **Unit** 66393 **Building ID** 3342
Address 2845 West Barry **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
040	12"x12" Blue Floor Tile	1,760	SF	B Building 1st & 2nd Floor Corridors, B200, 1st and 2nd Floor Janitor's Closets	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
041	12"x12" Blue Floor Tile Mastic	1,760	SF	B Building 1st & 2nd Floor Corridors, B200, 1st and 2nd Floor Janitor's Closets	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
042	12"x12" Beige Floor Tile	250	SF	B Building 1st & 2nd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
043	12"x12" Beige Floor Tile Mastic	250	SF	B Building 1st & 2nd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
044	2'x4' Lay In Ceiling Panels w/2'x2' Design	42	SF	Washroom by B-206	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
045	4" Blue Vinyl Baseboard	975	LF	A Building Corridors, B200, B206, Kitchen, Washroom by 206, 003, 004	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
046	4" Blue Vinyl Baseboard Adhesive	975	LF	A Building Corridors, B200, B206, Kitchen, Washroom by 206, 003, 004	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
047	Insulation in Divider Wall - REMOVED			Cafeteria	ABATED	MISC								
048	Blue Vinyl Stair Treads	1,636	SF	South Stairway and Stage Stairs	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
049	Blue Vinyl Stair Tread Adhesive	1,636	SF	South Stairway and Stage Stairs	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
050	Purple Vinyl Stair Treads	1,600	SF	North Stairway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
051	Purple Vinyl Stair Tread Adhesive	1,600	SF	North Stairway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
052	Linoleum on Counters	360	SF	Rooms 105, 106, 204A, 205A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
053	Linoleum Adhesive on Counters	360	SF	Rooms 105, 106, 204A, 205A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
054	Chalkboards	200	SF	Rooms 105, 205A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
055	Chalkboard Adhesive	200	SF	Rooms 105, 205A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
056	Marker Board Adhesive	100	SF	Room 204A	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Acero - Carlos Fuentes Campus Charter **Unit** 66393 **Building ID** 3342
Address 2845 West Barry **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
057	4" Brown Vinyl Baseboard	60	LF	Tunnel Between Buildings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
058	4" Brown Vinyl Baseboard Adhesive	60	LF	Tunnel Between Buildings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60	12" x 12" Tan Floor Tile	100	SF	Building A - Boiler Foyer	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60A	12" x 12" Tan Floor Tile Mastic	100	SF	Building A - Boiler Foyer	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	12" x 12" Blue Floor Tile with Streaks - Removed			Building B - Teacher's Lounge	ABATED	MISC								
61A	12" x 12" Blue with Streaks Floor Tile Mastic - Removed			Building B - Teacher's Lounge	ABATED	MISC								
62	12" x 12" Beige Speckled VFT	2,500	SF	3rd Flr Corridor and Janitors Closet, 2nd Flr Janitor Closet & Corridor, 1st Floor Corridor, Basement Corridor and Entry Vestibule by Elevator Machine Room, Elevator	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
63	12" x 12" Beige Speckled VFT Mastic	2,500	SF	3rd Flr Corridor and Janitors Closet, 2nd Flr Janitor Closet & Corridor, 1st Floor Corridor, Basement Corridor and Entry Vestibule by Elevator Machine Room, Elevator	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
64	12" x 12" Yellow w/ Red VFT	600	SF	Lunchroom / Gym Corridor Bldg B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
65	12" x 12" Yellow w/ Red Specks Mastic	600	SF	Lunchroom / Gym Corridor Bldg B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
66	Drywall System	10,000	SF	Rooms A201, A203, A201A (School Director), A003, A004 - Bldg A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
67	Black Baseboard	150	LF	Main Office - Bldg A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
68	Black Baseboard Mastic	150	LF	Main Office - Bldg A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69	2' x 2' Pinhole Ceiling Tiles	500	SF	Main Office Staff	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Acero - Carlos Fuentes Campus Charter **Unit** 66393 **Building ID** 3342
Address 2845 West Barry **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Toilet, Ground Floor Entrance vestibule by Elevator Machine Room- Bldg A								potential for damage		
70	MJP on Fiberglass Pipe Insulation	140	FITTING	Storage Room Under North Stairwell, A005 (Mechanical) - Bldg A	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
71	Drywall System	20,000	SF	Storage B013, Music Rm B100A, Pantry Storage B006, B102, B101A, B106 & Toilet, Passage behind Stage, Basement Boys & Girls Toilet, 1st & 2nd Flr Janitors Closet, 1st & 2nd Flr Elevator Lobby - Bldg B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
72	6" Black Baseboard Mastic	100	LF	Music Room (B100A), B100B - Bldg B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
73	2' x 4' Smooth Ceiling Tile	150	SF	Kitchen Pantry (B005), Pantry Storage (B006) - Bldg B	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
74	4" Blue Baseboard Mastic	500	LF	North Stairwell, 1st Flr Corridor, Pantry Storage (B006) - Bldg B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
75	2' x 2' Pinhole Ceiling Tiles	250	SF	B106 Toilet, Unisex Toilet (Near B105), B102, B001 - Bldg B	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
76	12" x 12" Light Sand VFT	600	SF	Passage Behind Stage (Basement) - Bldg B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
77	12" x 12" Light Sand VFT Mastic	600	SF	Passage Behind Stage (Basement) - Bldg B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
78	Terrazzo Mixed Colors	400	SF	Basement Boys & Girls Toilet - Bldg B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Acero - Carlos Fuentes Campus Charter **Unit** 66393 **Building ID** 3342
Address 2845 West Barry **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
79	Terrazzo Green	150	SF	Basement Boys & Girls Toilet - Bldg B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Acero - Carlos Fuentes Campus Charter **Unit** 66393 **Building ID** 3342
Address 2845 West Barry **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

Reinspection Date Inspector Name Inspector's IDPH License Number / Expiration Date	Inspector's Comments
HA Number:	Inspector Comments:
001	
002	
004	
005	
006	
007	
008	
010	
011	
012	
013	
015	
016	
017	
018	
019	
020	
021	
022	
023	
024	
025	
026	
027	

Chicago Public Schools

School Acero - Carlos Fuentes Campus Charter **Unit** 66393 **Building ID** 3342
Address 2845 West Barry **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
028	
029	
030	
031	
032	
033	
034	
035	
036	
037	
038	
039	
040	
041	
042	
043	
044	
045	
046	
047	
048	
049	
050	
051	
052	
053	
054	
055	
056	

Chicago Public Schools

School Acero - Carlos Fuentes Campus Charter **Unit** 66393 **Building ID** 3342
Address 2845 West Barry **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
057	
058	
60	
60A	
61	
61A	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	

Chicago Public Schools

School Acero - Carlos Fuentes Campus Charter **Unit** 66393 **Building ID** 3342
Address 2845 West Barry **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

Table II
Management Planner's Review

Chicago Public Schools

School Acero - Carlos Fuentes
Campus Charter

Address 2845 West Barry

Unit 66393

Chicago, IL,

Building ID 3342

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
001	Low Pressure Steam Pipe Insulation	155	LF	Basement Throughout, Cafeteria - Building B	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	
002	Low Pressure Steam Pipe Fitting Insulation	21	LF	Basement Throughout, Cafeteria - Building B	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	
004	Joint Insulation (MJP) Associated/w Aircell Pipe Insulation	140	LF	Basement Throughout, Cafeteria - Building B	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	
005	Paperwrap Pipe Insulation on Chilled Water Piping	75	LF	Basement Throughout, Cafeteria - Building B	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	
006	Joint Insulation (MJP) on Paperwrap Insulated Piping	8	LF	Basement Throughout - Building A	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	
007	Joint Insulation (MJP) on Paperwrap Insulated Piping	60	LF	Basement Throughout - Building B	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	
008	Acoustical Plaster	6,300	SF	Basement Lunchroom Ceiling	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	
010	9"x9" Tan Floor Tile - ABATED		SF	Boiler Room Foyer	Abated	MISC	No	0	SF		
011	12"x 12" Gray Floor Tile - Abated			Tunnel Between Buildings - Abated	Abated	MISC					
012	9"x9" Tan & Red Vinyl Floor Tile	5,040	SF	Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
013	9"x9" Tan Vinyl Floor Tile	1,260	SF	Lunchroom, Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
015	9"x9" Tan Vinyl Floor Tile Mastic	1,260	SF	Lunchroom, Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
016	12"x 12" Gray Floor Tile Mastic - Abated			Tunnel Between Buildings - Abated	Abated	MISC					
017	9"x9" Tan & Red Vinyl Floor Tile Mastic	5,040	SF	Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
018	9"x9" Tan Floor Tile Mastic - Not Observed		SF	Boiler Room Foyer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
019	9"x9" Tan and Red Vinyl Floor Tile	12,000	SF	Building A Corridors and Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
020	9"x9" Tan and Red Vinyl Floor Tile Mastic	12,000	SF	Building A Corridors and Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
021	Joint Insulaiton (MJP) Assoc/w Fiberglass Insulated Pipe - Abated			Boiler Room 1 in B Building - Abated	Abated	TSI					
022	12"x12" Cream w/ White Floor Tile	130	SF	Building A Foyer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
023	12"x12" Cream w/ White Floor Tile Mastic	130	SF	Building A Foyer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
024	12"x12" Ceiling Tile w/ Glue Pucks	4,000	SF	Building A Throughout	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	
025	Hard Plaster	20,000	SF	Throughout Buildings A & B	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	
026	12"x12" Brown w/Brown & White Streaks Floor Tile	80	SF	Entrance of Building A- Stair Landing	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
027	12"x12" Brown w/Brown & White Streaks Floor Tile Mastic	80	SF	Entrance of Building A- Stair Landing	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
028	12"x12" Cream Floor Tile	300	SF	Classroom 004 in A Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
029	12"x12" Cream Floor Tile Mastic	300	SF	Classroom 004 in A Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
030	12"x12" Beige w/Brown Floor Tile	40	SF	A Building Stair Landing Between 1st &	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	

Chicago Public Schools

School Acero - Carlos Fuentes
Campus Charter

Address 2845 West Barry

Unit 66393

Chicago, IL,

Building ID 3342

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
031	12"x12" Beige w/Brown Floor Tile Mastic	40	SF	2nd Floors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
032	9"x9" Dark Brown Floor Tile - Abated			A Building Janitor Closet 107 - Abated	Abated	MISC					
033	9"x9" Dark Brown Floor Tile Mastic - Abated			A Building Janitor Closet 107 - Abated	Abated	MISC					
034	12"x12" Brown Streaked Floor Tile	60	SF	A Building Southeast Stair Landing	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
035	12"x12" Brown Streaked Floor Tile Mastic	60	SF	A Building Southeast Stair Landing	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
036	12"x12" Blue Floor Tile	408	SF	A Building Room 101, Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
037	12"x12" Blue Floor Tile Mastic	408	SF	A Building Room 101, Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
038	12"x12" Blue Floor Tile	406	SF	Kitchen / Pantry	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
039	12"x12" Blue Floor Tile Mastic	406	SF	Kitchen & Washroom by B206 AND Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
040	12"x12" Blue Floor Tile	1,760	SF	B Building 1st & 2nd Floor Corridors, B200, 1st and 2nd Floor Janitor's Closets	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
041	12"x12" Blue Floor Tile Mastic	1,760	SF	B Building 1st & 2nd Floor Corridors, B200, 1st and 2nd Floor Janitor's Closets	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
042	12"x12" Beige Floor Tile	250	SF	B Building 1st & 2nd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
043	12"x12" Beige Floor Tile Mastic	250	SF	B Building 1st & 2nd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
044	2'x4' Lay In Ceiling Panels w/2'x2' Design	42	SF	Washroom by B-206	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	
045	4" Blue Vinyl Baseboard	975	LF	A Building Corridors, B200, B206, Kitchen, Washroom by 206, 003, 004	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
046	4" Blue Vinyl Baseboard Adhesive	975	LF	A Building Corridors, B200, B206, Kitchen, Washroom by 206, 003, 004	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
047	Insulation in Divider Wall - REMOVED			Cafeteria	Abated	MISC					
048	Blue Vinyl Stair Treads	1,636	SF	South Stairway and Stage Stairs	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
049	Blue Vinyl Stair Tread Adhesive	1,636	SF	South Stairway and Stage Stairs	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
050	Purple Vinyl Stair Treads	1,600	SF	North Stairway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
051	Purple Vinyl Stair Tread Adhesive	1,600	SF	North Stairway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
052	Linoleum on Counters	360	SF	Rooms 105, 106, 204A, 205A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
053	Linoleum Adhesive on Counters	360	SF	Rooms 105, 106, 204A, 205A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
054	Chalkboards	200	SF	Rooms 105, 205A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
055	Chalkboard Adhesive	200	SF	Rooms 105, 205A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
056	Marker Board Adhesive	100	SF	Room 204A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	

Chicago Public Schools

School Acero - Carlos Fuentes
Campus Charter

Address 2845 West Barry

Unit 66393

Chicago, IL,

Building ID 3342

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
057	4" Brown Vinyl Baseboard	60	LF	Tunnel Between Buildings	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
058	4" Brown Vinyl Baseboard Adhesive	60	LF	Tunnel Between Buildings	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
60	12" x 12" Tan Floor Tile	100	SF	Building A - Boiler Foyer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
60A	12" x 12" Tan Floor Tile Mastic	100	SF	Building A - Boiler Foyer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
61	12" x 12" Blue Floor Tile with Streaks - Removed			Building B - Teacher's Lounge	Abated	MISC					
61A	12" x 12" Blue with Streaks Floor Tile Mastic - Removed			Building B - Teacher's Lounge	Abated	MISC					
62	12" x 12" Beige Speckled VFT	2,500	SF	3rd Flr Corridor and Janitors Closet, 2nd Flr Janitor Closet & Corridor, 1st Floor Corridor, Basement Corridor and Entry Vestibule by Elevator Machine Room, Elevator	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
63	12" x 12" Beige Speckled VFT Mastic	2,500	SF	3rd Flr Corridor and Janitors Closet, 2nd Flr Janitor Closet & Corridor, 1st Floor Corridor, Basement Corridor and Entry Vestibule by Elevator Machine Room, Elevator	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
64	12" x 12" Yellow w/ Red VFT	600	SF	Lunchroom / Gym Corridor Bldg B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
65	12" x 12" Yellow w/ Red Specks Mastic	600	SF	Lunchroom / Gym Corridor Bldg B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
66	Drywall System	10,000	SF	Rooms A201, A203, A201A (School Director), A003, A004 - Bldg A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
67	Black Baseboard	150	LF	Main Office - Bldg A	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
68	Black Baseboard Mastic	150	LF	Main Office - Bldg A	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
69	2' x 2' Pinhole Ceiling Tiles	500	SF	Main Office Staff Toilet, Ground Floor Entrance vestibule by Elevator Machine Room- Bldg A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
70	MJP on Fiberglass Pipe Insulation	140	FITTING	Storage Room Under North Stairwell, A005 (Mechanical) - Bldg A	Assumed	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	
71	Drywall System	20,000	SF	Storage B013, Music Rm B100A, Pantry Storage B006, B102, B101A, B106 & Toilet, Passage behind Stage, Basement Boys & Girls Toilet, 1st & 2nd Flr Janitors Closet, 1st & 2nd Flr Elevator Lobby - Bldg B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
72	6" Black Baseboard Mastic	100	LF	Music Room (B100A), B100B - Bldg B	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	

Chicago Public Schools

School Acero - Carlos Fuentes
Campus Charter

Unit 66393

Building ID 3342

Address 2845 West Barry

Chicago, IL,

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
73	2' x 4' Smooth Ceiling Tile	150	SF	Kitchen Pantry (B005), Pantry Storage (B006) - Bldg B	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	
74	4" Blue Baseboard Mastic	500	LF	North Stairwell, 1st Flr Corridor, Pantry Storage (B006) - Bldg B	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
75	2' x 2' Pinhole Ceiling Tiles	250	SF	B106 Toilet, Unisex Toilet (Near B105), B102, B001 - Bldg B	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	
76	12" x 12" Light Sand VFT	600	SF	Passage Behind Stage (Basement) - Bldg B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
77	12" x 12" Light Sand VFT Mastic	600	SF	Passage Behind Stage (Basement) - Bldg B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
78	Terrazzo Mixed Colors	400	SF	Basement Boys & Girls Toilet - Bldg B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
79	Terrazzo Green	150	SF	Basement Boys & Girls Toilet - Bldg B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	

Chicago Public Schools

School Acero - Carlos Fuentes
Campus Charter

Address 2845 West Barry

Unit 66393

Chicago, IL,

Building ID 3342

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

Review Date	
Manager Planner Name	
Manager IDPH License No/Expiration	

HA Number	Management Comments
001	
002	
004	
005	
006	
007	
008	
010	
011	
012	
013	
015	
016	
017	
018	
019	
020	
021	
022	
023	
024	
025	
026	

Chicago Public Schools

School Acero - Carlos Fuentes
Campus Charter

Address 2845 West Barry

Unit 66393

Chicago, IL,

Building ID 3342

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
027	
028	
029	
030	
031	
032	
033	
034	
035	
036	
037	
038	
039	
040	
041	
042	
043	
044	
045	
046	
047	
048	
049	
050	
051	
052	

Chicago Public Schools

School Acero - Carlos Fuentes
Campus Charter

Address 2845 West Barry

Unit 66393

Chicago, IL,

Building ID 3342

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
053	
054	
055	
056	
057	
058	
60	
60A	
61	
61A	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	

Chicago Public Schools

School Acero - Carlos Fuentes
Campus Charter

Address 2845 West Barry

Unit 66393

Chicago, IL,

Building ID 3342

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
78	
79	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

2025 AHERA REINSPECTION

Chicago Public Schools

2025 AHERA REINSPECTION Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **001**
MATERIAL DESCRIPTION: **Low Pressure Steam Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Throughout, Cafeteria - Building B**
MATERIAL QUANTITY: **155** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **001**

MATERIAL DESCRIPTION: **Low Pressure Steam Pipe Insulation**

MATERIAL LOCATION: **Basement Throughout, Cafeteria - Building B**

MATERIAL QUANTITY: **155** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002**
MATERIAL DESCRIPTION: **Low Pressure Steam Pipe Fitting Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Basement Throughout, Cafeteria - Building B**
MATERIAL QUANTITY: **21** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **21** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **002**

MATERIAL DESCRIPTION: **Low Pressure Steam Pipe Fitting Insulation**

MATERIAL LOCATION: **Basement Throughout, Cafeteria - Building B**

MATERIAL QUANTITY: **21** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **004**
MATERIAL DESCRIPTION: **Joint Insulation (MJP) Associated/w Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Basement Throughout, Cafeteria - Building B**
MATERIAL QUANTITY: **140** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **140** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **004**

MATERIAL DESCRIPTION: **Joint Insulation (MJP) Associated/w Aircell Pipe Insulation**

MATERIAL LOCATION: **Basement Throughout, Cafeteria - Building B**

MATERIAL QUANTITY: **140** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **005**
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation on Chilled Water Piping**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Basement Throughout, Cafeteria - Building B**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **75** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **005**

MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation on Chilled Water Piping**

MATERIAL LOCATION: **Basement Throughout, Cafeteria - Building B**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006**
MATERIAL DESCRIPTION: **Joint Insulation (MJP) on Paperwrap Insulated Piping**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Basement Throughout - Building A**
MATERIAL QUANTITY: **8** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **8** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **006**

MATERIAL DESCRIPTION: **Joint Insulation (MJP) on Paperwrap Insulated Piping**

MATERIAL LOCATION: **Basement Throughout - Building A**

MATERIAL QUANTITY: **8** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **007**
MATERIAL DESCRIPTION: **Joint Insulation (MJP) on Paperwrap Insulated Piping**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Basement Throughout - Building B**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **60** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **007**

MATERIAL DESCRIPTION: **Joint Insulation (MJP) on Paperwrap Insulated Piping**

MATERIAL LOCATION: **Basement Throughout - Building B**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **008**
MATERIAL DESCRIPTION: **Acoustical Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Lunchroom Ceiling**
MATERIAL QUANTITY: **6300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **6300** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **008**

MATERIAL DESCRIPTION: **Acoustical Plaster**

MATERIAL LOCATION: **Basement Lunchroom Ceiling**

MATERIAL QUANTITY: **6300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **010**
MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room Foyer**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **010**

MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile - ABATED**

MATERIAL LOCATION: **Boiler Room Foyer**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **011**
MATERIAL DESCRIPTION: **12"x 12" Gray Floor Tile - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Tunnel Between Buildings - Abated**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **011**

MATERIAL DESCRIPTION: **12"x 12" Gray Floor Tile - Abated**

MATERIAL LOCATION: **Tunnel Between Buildings - Abated**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **012**
MATERIAL DESCRIPTION: **9"x9" Tan & Red Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Cafeteria**
MATERIAL QUANTITY: **5040** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **012**

MATERIAL DESCRIPTION: **9"x9" Tan & Red Vinyl Floor Tile**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY: **5040** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **013**
MATERIAL DESCRIPTION: **9"x9" Tan Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom, Kitchen**
MATERIAL QUANTITY: **1260** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **013**

MATERIAL DESCRIPTION: **9"x9" Tan Vinyl Floor Tile**

MATERIAL LOCATION: **Lunchroom, Kitchen**

MATERIAL QUANTITY: **1260** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **015**
MATERIAL DESCRIPTION: **9"x9" Tan Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom, Kitchen**
MATERIAL QUANTITY: **1260** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **015**

MATERIAL DESCRIPTION: **9"x9" Tan Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom, Kitchen**

MATERIAL QUANTITY: **1260** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **016**
MATERIAL DESCRIPTION: **12"x 12" Gray Floor Tile Mastic - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Tunnel Between Buildings - Abated**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **016**

MATERIAL DESCRIPTION: **12"x 12" Gray Floor Tile Mastic - Abated**

MATERIAL LOCATION: **Tunnel Between Buildings - Abated**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **017**
MATERIAL DESCRIPTION: **9"x9" Tan & Red Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Cafeteria**
MATERIAL QUANTITY: **5040** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **017**

MATERIAL DESCRIPTION: **9"x9" Tan & Red Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY: **5040** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **018**
MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile Mastic - Not Observed**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room Foyer**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **018**

MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile Mastic - Not Observed**

MATERIAL LOCATION: **Boiler Room Foyer**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **019**
MATERIAL DESCRIPTION: **9"x9" Tan and Red Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Building A Corridors and Classrooms**
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **019**

MATERIAL DESCRIPTION: **9"x9" Tan and Red Vinyl Floor Tile**

MATERIAL LOCATION: **Building A Corridors and Classrooms**

MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **020**
MATERIAL DESCRIPTION: **9"x9" Tan and Red Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Building A Corridors and Classrooms**
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **020**

MATERIAL DESCRIPTION: **9"x9" Tan and Red Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Building A Corridors and Classrooms**

MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **021**
MATERIAL DESCRIPTION: **Joint Insulaiton (MJP) Assoc/w Fiberglass Insulated Pipe - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room 1 in B Building - Abated**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **021**

MATERIAL DESCRIPTION: **Joint Insulaiton (MJP) Assoc/w Fiberglass Insulated Pipe - Abated**

MATERIAL LOCATION: **Boiler Room 1 in B Building - Abated**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **022**
MATERIAL DESCRIPTION: **12"x12" Cream w/ White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Building A Foyer**
MATERIAL QUANTITY: **130** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **022**

MATERIAL DESCRIPTION: **12"x12" Cream w/ White Floor Tile**

MATERIAL LOCATION: **Building A Foyer**

MATERIAL QUANTITY: **130** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **023**
MATERIAL DESCRIPTION: **12"x12" Cream w/ White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Building A Foyer**
MATERIAL QUANTITY: **130** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **023**

MATERIAL DESCRIPTION: **12"x12" Cream w/ White Floor Tile Mastic**

MATERIAL LOCATION: **Building A Foyer**

MATERIAL QUANTITY: **130** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **024**
MATERIAL DESCRIPTION: **12"x12" Ceiling Tile w/ Glue Pucks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Building A Throughout**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **024**

MATERIAL DESCRIPTION: **12"x12" Ceiling Tile w/ Glue Pucks**

MATERIAL LOCATION: **Building A Throughout**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **025**
MATERIAL DESCRIPTION: **Hard Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Buildings A & B**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **025**

MATERIAL DESCRIPTION: **Hard Plaster**

MATERIAL LOCATION: **Throughout Buildings A & B**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **026**
MATERIAL DESCRIPTION: **12"x12" Brown w/Brown & White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Entrance of Building A- Stair Landing**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **026**

MATERIAL DESCRIPTION: **12"x12" Brown w/Brown & White Streaks Floor Tile**

MATERIAL LOCATION: **Entrance of Building A- Stair Landing**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **027**
MATERIAL DESCRIPTION: **12"x12" Brown w/Brown & White Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Entrance of Building A- Stair Landing**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **027**

MATERIAL DESCRIPTION: **12"x12" Brown w/Brown & White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Entrance of Building A- Stair Landing**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **028**
MATERIAL DESCRIPTION: **12"x12" Cream Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Classroom 004 in A Building**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **028**

MATERIAL DESCRIPTION: **12"x12" Cream Floor Tile**

MATERIAL LOCATION: **Classroom 004 in A Building**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **029**
MATERIAL DESCRIPTION: **12"x12" Cream Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classroom 004 in A Building**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **029**

MATERIAL DESCRIPTION: **12"x12" Cream Floor Tile Mastic**

MATERIAL LOCATION: **Classroom 004 in A Building**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **030**
MATERIAL DESCRIPTION: **12"x12" Beige w/Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **A Building Stair Landing Between 1st & 2nd Floors**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **030**

MATERIAL DESCRIPTION: **12"x12" Beige w/Brown Floor Tile**

MATERIAL LOCATION: **A Building Stair Landing Between 1st & 2nd Floors**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **031**
MATERIAL DESCRIPTION: **12"x12" Beige w/Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **A Building Stair Landing Between 1st & 2nd Floors**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **031**

MATERIAL DESCRIPTION: **12"x12" Beige w/Brown Floor Tile Mastic**

MATERIAL LOCATION: **A Building Stair Landing Between 1st & 2nd Floors**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **032**
MATERIAL DESCRIPTION: **9"x9" Dark Brown Floor Tile - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **A Building Janitor Closet 107 - Abated**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **032**

MATERIAL DESCRIPTION: **9"x9" Dark Brown Floor Tile - Abated**

MATERIAL LOCATION: **A Building Janitor Closet 107 - Abated**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **033**
MATERIAL DESCRIPTION: **9"x9" Dark Brown Floor Tile Mastic - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **A Building Janitor Closet 107 - Abated**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **033**

MATERIAL DESCRIPTION: **9"x9" Dark Brown Floor Tile Mastic - Abated**

MATERIAL LOCATION: **A Building Janitor Closet 107 - Abated**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **034**
MATERIAL DESCRIPTION: **12"x12" Brown Streaked Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **A Building Southeast Stair Landing**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **60** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **034**

MATERIAL DESCRIPTION: **12"x12" Brown Streaked Floor Tile**

MATERIAL LOCATION: **A Building Southeast Stair Landing**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **035**
MATERIAL DESCRIPTION: **12"x12" Brown Streaked Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **A Building Southeast Stair Landing**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **60** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **035**

MATERIAL DESCRIPTION: **12"x12" Brown Streaked Floor Tile Mastic**

MATERIAL LOCATION: **A Building Southeast Stair Landing**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **036**
MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **A Building Room 101, Main Office**
MATERIAL QUANTITY: **408** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **408** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **036**

MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile**

MATERIAL LOCATION: **A Building Room 101, Main Office**

MATERIAL QUANTITY: **408** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **037**
MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **A Building Room 101, Main Office**
MATERIAL QUANTITY: **408** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **408** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **037**

MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile Mastic**

MATERIAL LOCATION: **A Building Room 101, Main Office**

MATERIAL QUANTITY: **408** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **038**
MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Kitchen / Pantry**
MATERIAL QUANTITY: **406** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **038**

MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile**

MATERIAL LOCATION: **Kitchen / Pantry**

MATERIAL QUANTITY: **406** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **039**
MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen & Washroom by B206 AND Boiler Room**
MATERIAL QUANTITY: **406** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **039**

MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile Mastic**

MATERIAL LOCATION: **Kitchen & Washroom by B206 AND Boiler Room**

MATERIAL QUANTITY: **406** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **040**
MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **B Building 1st & 2nd Floor Corridors, B200, 1st and 2nd Floor Janitor's Closets**
MATERIAL QUANTITY: **1760** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **040**

MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile**

MATERIAL LOCATION: **B Building 1st & 2nd Floor Corridors, B200, 1st and 2nd Floor Janitor's Closets**

MATERIAL QUANTITY: **1760** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **041**
MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **B Building 1st & 2nd Floor Corridors, B200, 1st and 2nd Floor Janitor's Closets**
MATERIAL QUANTITY: **1760** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **041**

MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile Mastic**

MATERIAL LOCATION: **B Building 1st & 2nd Floor Corridors, B200, 1st and 2nd Floor Janitor's Closets**

MATERIAL QUANTITY: **1760** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **042**
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **B Building 1st & 2nd Floor Corridors**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **042**

MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile**

MATERIAL LOCATION: **B Building 1st & 2nd Floor Corridors**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **043**
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **B Building 1st & 2nd Floor Corridors**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **043**

MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile Mastic**

MATERIAL LOCATION: **B Building 1st & 2nd Floor Corridors**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **044**
MATERIAL DESCRIPTION: **2'x4' Lay In Ceiling Panels w/2'x2' Design**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Washroom by B-206**
MATERIAL QUANTITY: **42** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **044**

MATERIAL DESCRIPTION: **2'x4' Lay In Ceiling Panels w/2'x2' Design**

MATERIAL LOCATION: **Washroom by B-206**

MATERIAL QUANTITY: **42** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **045**
MATERIAL DESCRIPTION: **4" Blue Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **A Building Corridors, B200, B206, Kitchen, Washroom by 206, 003, 004**
MATERIAL QUANTITY: **975** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **975** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **045**

MATERIAL DESCRIPTION: **4" Blue Vinyl Baseboard**

MATERIAL LOCATION: **A Building Corridors, B200, B206, Kitchen, Washroom by 206, 003, 004**

MATERIAL QUANTITY: **975** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **046**
MATERIAL DESCRIPTION: **4" Blue Vinyl Baseboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **A Building Corridors, B200, B206, Kitchen, Washroom by 206, 003, 004**
MATERIAL QUANTITY: **975** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **975** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **046**

MATERIAL DESCRIPTION: **4" Blue Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **A Building Corridors, B200, B206, Kitchen, Washroom by 206, 003, 004**

MATERIAL QUANTITY: **975** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **047**
MATERIAL DESCRIPTION: **Insulation in Divider Wall - REMOVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **047**

MATERIAL DESCRIPTION: **Insulation in Divider Wall - REMOVED**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **048**
MATERIAL DESCRIPTION: **Blue Vinyl Stair Treads**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **South Stairway and Stage Stairs**
MATERIAL QUANTITY: **1636** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **048**

MATERIAL DESCRIPTION: **Blue Vinyl Stair Treads**

MATERIAL LOCATION: **South Stairway and Stage Stairs**

MATERIAL QUANTITY: **1636** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **049**
MATERIAL DESCRIPTION: **Blue Vinyl Stair Tread Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Stairway and Stage Stairs**
MATERIAL QUANTITY: **1636** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **049**

MATERIAL DESCRIPTION: **Blue Vinyl Stair Tread Adhesive**

MATERIAL LOCATION: **South Stairway and Stage Stairs**

MATERIAL QUANTITY: **1636** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **050**
MATERIAL DESCRIPTION: **Purple Vinyl Stair Treads**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **North Stairway**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **050**

MATERIAL DESCRIPTION: **Purple Vinyl Stair Treads**

MATERIAL LOCATION: **North Stairway**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **051**
MATERIAL DESCRIPTION: **Purple Vinyl Stair Tread Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Stairway**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **051**

MATERIAL DESCRIPTION: **Purple Vinyl Stair Tread Adhesive**

MATERIAL LOCATION: **North Stairway**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **052**
MATERIAL DESCRIPTION: **Linoleum on Counters**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 105, 106, 204A, 205A**
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **052**

MATERIAL DESCRIPTION: **Linoleum on Counters**

MATERIAL LOCATION: **Rooms 105, 106, 204A, 205A**

MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **053**
MATERIAL DESCRIPTION: **Linoleum Adhesive on Counters**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 105, 106, 204A, 205A**
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **360** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **053**

MATERIAL DESCRIPTION: **Linoleum Adhesive on Counters**

MATERIAL LOCATION: **Rooms 105, 106, 204A, 205A**

MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **054**
MATERIAL DESCRIPTION: **Chalkboards**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 105, 205A**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **054**

MATERIAL DESCRIPTION: **Chalkboards**

MATERIAL LOCATION: **Rooms 105, 205A**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **055**
MATERIAL DESCRIPTION: **Chalkboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 105, 205A**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **055**

MATERIAL DESCRIPTION: **Chalkboard Adhesive**

MATERIAL LOCATION: **Rooms 105, 205A**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **056**
MATERIAL DESCRIPTION: **Marker Board Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 204A**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **056**

MATERIAL DESCRIPTION: **Marker Board Adhesive**

MATERIAL LOCATION: **Room 204A**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **057**
MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Tunnel Between Buildings**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **60** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **057**

MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard**

MATERIAL LOCATION: **Tunnel Between Buildings**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **058**
MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Tunnel Between Buildings**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **60** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **058**

MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Tunnel Between Buildings**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Building A - Boiler Foyer**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile**

MATERIAL LOCATION: **Building A - Boiler Foyer**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60A**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Building A - Boiler Foyer**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **60A**

MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile Mastic**

MATERIAL LOCATION: **Building A - Boiler Foyer**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile with Streaks - Removed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B - Teacher's Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile with Streaks - Removed**

MATERIAL LOCATION: **Building B - Teacher's Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61A**
MATERIAL DESCRIPTION: **12" x 12" Blue with Streaks Floor Tile Mastic - Removed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B - Teacher's Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **61A**

MATERIAL DESCRIPTION: **12" x 12" Blue with Streaks Floor Tile Mastic - Removed**

MATERIAL LOCATION: **Building B - Teacher's Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **12" x 12" Beige Speckled VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **3rd Flr Corridor and Janitors Closet, 2nd Flr Janitor Closet & Corridor, 1st Floor Corridor, Basement Corridor and Entry Vestibule by Elevator Machine Room, Elevator**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **12" x 12" Beige Speckled VFT**

MATERIAL LOCATION: **3rd Flr Corridor and Janitors Closet, 2nd Flr Janitor Closet & Corridor, 1st Floor Corridor,
Basement Corridor and Entry Vestibule by Elevator Machine Room, Elevator**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **12" x 12" Beige Speckled VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Flr Corridor and Janitors Closet, 2nd Flr Janitor Closet & Corridor, 1st Floor Corridor, Basement Corridor and Entry Vestibule by Elevator Machine Room, Elevator**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **12" x 12" Beige Speckled VFT Mastic**

MATERIAL LOCATION: **3rd Flr Corridor and Janitors Closet, 2nd Flr Janitor Closet & Corridor, 1st Floor Corridor,
Basement Corridor and Entry Vestibule by Elevator Machine Room, Elevator**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **12" x 12" Yellow w/ Red VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Lunchroom / Gym Corridor Bldg B**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **600** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **12" x 12" Yellow w/ Red VFT**

MATERIAL LOCATION: **Lunchroom / Gym Corridor Bldg B**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **12" x 12" Yellow w/ Red Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom / Gym Corridor Bldg B**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **600** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **12" x 12" Yellow w/ Red Specks Mastic**

MATERIAL LOCATION: **Lunchroom / Gym Corridor Bldg B**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **Drywall System**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms A201, A203, A201A (School Director), A003, A004 - Bldg A**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **Drywall System**

MATERIAL LOCATION: **Rooms A201, A203, A201A (School Director), A003, A004 - Bldg A**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **Black Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office - Bldg A**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **150** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **Black Baseboard**

MATERIAL LOCATION: **Main Office - Bldg A**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office - Bldg A**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **150** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **Black Baseboard Mastic**

MATERIAL LOCATION: **Main Office - Bldg A**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **2' x 2' Pinhole Ceiling Tiles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office Staff Toilet, Ground Floor Entrance vestibule by Elevator Machine Room-Bldg A**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **2' x 2' Pinhole Ceiling Tiles**

MATERIAL LOCATION: **Main Office Staff Toilet, Ground Floor Entrance vestibule by Elevator Machine Room- Bldg A**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Storage Room Under North Stairwell, A005 (Mechanical) - Bldg A**
MATERIAL QUANTITY: **140** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **140** DAMAGE UNITS: **FITTING**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Storage Room Under North Stairwell, A005 (Mechanical) - Bldg A**

MATERIAL QUANTITY: **140** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **Drywall System**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Storage B013, Music Rm B100A, Pantry Storage B006, B102, B101A, B106 & Toilet, Passage behind Stage, Basement Boys & Girls Toilet, 1st & 2nd Flr Janitors Closet, 1st & 2nd Flr Elevator Lobby - Bldg B**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Acero - Carlos Fuentes** REVIEW DATE:
Campus Charter
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **Drywall System**
MATERIAL LOCATION: **Storage B013, Music Rm B100A, Pantry Storage B006, B102, B101A, B106 & Toilet, Passage behind Stage, Basement Boys & Girls Toilet, 1st & 2nd Flr Janitors Closet, 1st & 2nd Flr Elevator Lobby - Bldg B**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **6" Black Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Music Room (B100A), B100B - Bldg B**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **6" Black Baseboard Mastic**

MATERIAL LOCATION: **Music Room (B100A), B100B - Bldg B**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **2' x 4' Smooth Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen Pantry (B005), Pantry Storage (B006) - Bldg B**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **2' x 4' Smooth Ceiling Tile**

MATERIAL LOCATION: **Kitchen Pantry (B005), Pantry Storage (B006) - Bldg B**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **4" Blue Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Stairwell, 1st Flr Corridor, Pantry Storage (B006) - Bldg B**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **500** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **4" Blue Baseboard Mastic**

MATERIAL LOCATION: **North Stairwell, 1st Flr Corridor, Pantry Storage (B006) - Bldg B**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **2' x 2' Pinhole Ceiling Tiles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **B106 Toilet, Unisex Toilet (Near B105), B102, B001 - Bldg B**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **2' x 2' Pinhole Ceiling Tiles**

MATERIAL LOCATION: **B106 Toilet, Unisex Toilet (Near B105), B102, B001 - Bldg B**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **12" x 12" Light Sand VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Passage Behind Stage (Basement) - Bldg B**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **600** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **12" x 12" Light Sand VFT**

MATERIAL LOCATION: **Passage Behind Stage (Basement) - Bldg B**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **12" x 12" Light Sand VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Passage Behind Stage (Basement) - Bldg B**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **600** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **12" x 12" Light Sand VFT Mastic**

MATERIAL LOCATION: **Passage Behind Stage (Basement) - Bldg B**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **Terrazzo Mixed Colors**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Boys & Girls Toilet - Bldg B**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BULDING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **Terrazzo Mixed Colors**

MATERIAL LOCATION: **Basement Boys & Girls Toilet - Bldg B**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Acero - Carlos Fuentes Campus Charter** INSPECTION DATE:
ADDRESS: **2845 West Barry** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **Terrazzo Green**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Boys & Girls Toilet - Bldg B**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66393** BUIDLING ID: **3342**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Acero - Carlos Fuentes
Campus Charter** REVIEW DATE:

ADDRESS: **2845 West Barry** IDPH LICENSE NO:

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **Terrazzo Green**

MATERIAL LOCATION: **Basement Boys & Girls Toilet - Bldg B**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed