

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-005C
SCHOOL NAME: Noble Street Charter - Muchin College Prep Campus
ADDRESS OF SCHOOL: 1 N State Street
CITY: Chicago, IL, 60602

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 7/22/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: _____ ENROLLMENT 919 _____

IDPH INSPECTOR LICENSE NUMBER: _____

IDPH LICENSED INSPECTOR NAME (Please Print): _____

IDPH MP LICENSE NUMBER: _____

IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): _____

DESIGNATED PERSON (Please Print): _____ PHONE: _____

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: N

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Noble Street Charter - Muchin College Prep Campus

1 N State Street
Chicago, IL, 60602

Unit: 66573
Building ID: 1137

IDPH ID Number: 14-016-2990-005C

REPORT DATE:

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

''

Phone

Fax

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 66573 Region: IDPH ID: 14-016-2990-005C

School: Noble Street Charter - Muchin College Prep Campus Building ID: 1137

Address: 1 N State Street

Chicago, IL, 60602

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date:

Review Date:

Inspector: Inspector IDPH License:

Management Planner: Management Planner IDPH License:

If you have any questions or comments, please contact us at

Sincerely,

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date:

RE: Noble Street Charter - Muchin College Prep Campus, Unit 66573
1 N State Street
Chicago, IL, 60602

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Noble Street Charter - Muchin College Prep Campus , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Noble Street Charter - Muchin College Prep Campus, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact , the designated Local Education Authority's Designated Person at .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Noble Street Charter - Unit: 66573 Region:
Muchin College Prep Campus
Address: 1 N State Street Chicago, IL, 60602
IDPH ID: 14-016-2990-005C Building ID: 1137
Contact: Phone:

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: 57600 No of Floors:
Current Occupancy: 919

3. LEA Designated Person

Contact: Phone:
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC:
Contact:
Address:
Phone: Fax:

5. Inspector

Inspector Name: Signature:
Inspector IDPH license #: Date:
Reinspection Date:

6. Management Planner

Management Planner Name: Signature:
Management Planner IDPH license #: Date:

7. Review Date:

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Name:

Unit : 66573

Noble Street Charter - Muchin College
Prep Campus

Building: 1137

II. EXECUTIVE SUMMARY

was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Noble Street Charter - Muchin College Prep Campus. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1137:

BB4B	4" Brown vinyl baseboard
BB4BM	Brown mastic behind 4" brown vinyl baseboard
CFT3G	Gray Grout for 3" x 3" Brown Ceramic Floor Tile
CL-1	Duct caulk
CT1	1' x 1' White Fissured Ceiling Tile
DWEO	Drywall
DWJCEO	Drywall joint compound
DWJCWO	Drywall joint compound
DWWO	Drywall

FP	Sprayed-on fireproofing
FT-1	12" x 12" Gray w/ Dark Gray Floor Tile
FT-2	12" x 12" Gray w/ Dark Gray Floor Tile Mastic
FT-3	12" x 12" Gray w/ Dark Gray Spots Floor Tile
FT-4	12" x 12" Gray w/ Dark Gray Spots Floor Tile Mastic
MJP	Muddled joint packings
OCFTG	Gray Grout for Octagon-shaped Ceramic Floor Tile
PLE	Plaster walls/ceilings
PLW	Plaster walls/ceilings
SST	Slate stair treads
VJC	Vibration joint cloths

B. The following new homogenous areas have been identified for Building 1137:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

BB4B	4" Brown vinyl baseboard
BB4BM	Brown mastic behind 4" brown vinyl baseboard
CFT3G	Gray Grout for 3" x 3" Brown Ceramic Floor Tile
CL-1	Duct caulk
CT1	1' x 1' White Fissured Ceiling Tile
DWE0	Drywall
DWJCEO	Drywall joint compound
DWJCWO	Drywall joint compound
DWWO	Drywall
FP	Sprayed-on fireproofing
FT-1	12" x 12" Gray w/ Dark Gray Floor Tile
FT-2	12" x 12" Gray w/ Dark Gray Floor Tile Mastic
FT-3	12" x 12" Gray w/ Dark Gray Spots Floor Tile
FT-4	12" x 12" Gray w/ Dark Gray Spots Floor Tile Mastic
MJP	Muddled joint packings
OCFTG	Gray Grout for Octagon-shaped Ceramic Floor Tile
PLE	Plaster walls/ceilings
PLW	Plaster walls/ceilings
SST	Slate stair treads
VJC	Vibration joint cloths
VSF2G	Gray 2' x 2" Vinyl Sheet Floor Squares

The following areas were deemed to be inaccessible:

BB4BM	Brown mastic behind 4" brown vinyl baseboard
FT-2	12" x 12" Gray w/ Dark Gray Floor Tile Mastic
FT-4	12" x 12" Gray w/ Dark Gray Spots Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by , IDPH License # . The Management Plan was updated by , IDPH License # . Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Noble Street Charter - Muchin College Prep Campus Building 1137 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Noble Street Charter - Muchin College Prep Campus **Unit** 66573 **Building ID** 1137
Address 1 N State Street **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
9GFT+M	9" x 9" Green Floor Tile w/ Streaks and Associated Black Mastic			West portion of seventh floor	ABATED	MISC								
9TFT+M	9" x 9" Tan Floor Tile w/ Streaks and Associated Black Mastic			West portion of seventh floor	ABATED	MISC								
BB3B	3" Brown vinyl baseboard			U09, U10, 701, 702	UNDEFINE D									
BB3BM	Tan mastic behind 3" brown vinyl baseboard			U09, U10, 701, 702	UNDEFINE D									
BB4B	4" Brown vinyl baseboard	44	SF	Vestibule 744, U35, U36	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
BB4BM	Brown mastic behind 4" brown vinyl baseboard	44	SF	Vestibule 744, U35, U36	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
BB4G	4" Gray vinyl baseboard			Classrooms, offices, hallways throughout	UNDEFINE D									
BB4GM	Yellow mastic behind 4" gray vinyl baseboard			Classrooms, offices, hallways throughout	UNDEFINE D									
BB6G	6" Gray vinyl baseboard			Center area of east upper hallway at lockers	UNDEFINE D									
BB6GM	Yellow mastic behind 6" gray vinyl baseboard			Center area of east upper hallway at lockers	UNDEFINE D									
CFT1G	Blue Grout for 1" x 1" Black Ceramic Floor Tile			Bathroom rooms: L35, L36, L67, L68, U30, U31, U37, U38, 732, 733	UNDEFINE D									
CFT3G	Gray Grout for 3" x 3" Brown Ceramic Floor Tile	25	SF	L65	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
CG	Clear carpet glue			Classrooms and offices on both levels of 7th floor (Rooms 703, 704, 705, 706, 707, 708, 716, 720, 721, 722, 723, 724, U00, U01, U02, U03, U04, U06, U07, U08, U20, U21, Lower 7th north hallway, L00, L01, L02, L04, L50, L51, L52, L53, L54, L55, L56, L57, L58, L59, L60, L61)	UNDEFINE D									
CL-1	Duct caulk	50	LF	Mechanical Room	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the		LOW

Chicago Public Schools

School Noble Street Charter - Muchin College Prep Campus **Unit** 66573 **Building ID** 1137
Address 1 N State Street **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
CT1	1' x 1' White Fissured Ceiling Tile	25	SF	L33	ASSUMED	MISC	N	NONE	0		Yes	potential for damage		
CT2	2' x 2' White Fissured Ceiling Tile (Replacement)			Vestibule L37	UNDEFINE D						Any remaining friable ACBM or friable suspect ACBM			LOW
CT3	2' x 2' White Ceiling Tile w/ Fiberglass Backing			Lower 7th floor ceilings (except south hall, toilets, mech. Spaces); Upper 7th floor ceilings (except halls, toilets, kitchen, mech. Spaces, reception)	UNDEFINE D									
CT4	2' x 4' White Smooth Ceiling Tile			West hallways	UNDEFINE D									
CWT1G	Blue Grout for 1" x 1" Blue Ceramic Accent Wall Tile			Bathroom rooms: L35, L36, L67, L68, U30, U31, U37, U38, 732, 733	UNDEFINE D									
CWT4G	Blue Grout for 4" x 4" Gray Ceramic Wall Tile			Bathroom rooms: L35, L36, L67, L68, U30, U31, U37, U38, 732, 733	UNDEFINE D									
DC	Gray caulk			At seams of new ductwork above ceilings throughout renovated spaces	UNDEFINE D									
DWEO	Drywall	1,600	SF	East Portion - U34, U35, U36L32, L33, L34	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
DWJCE O	Drywall joint compound	1,600	SF	East Portion - U34, U35, U36L32, L33, L34	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
DWJCN	Drywall joint compound			Interior classrooms, offices, corridors, washrooms	UNDEFINE D									
DWJCWO	Drywall joint compound	50,000	SF	Throughout building	ASSUMED	MISC	N	LOC	10		Yes	ACBM with the potential for damage	5	LOW
DWN	Drywall			Interior classrooms, offices, corridors, washrooms	UNDEFINE D									
DWWO	Drywall	1,415	SF	West Portion -	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the		LOW

Chicago Public Schools

School Noble Street Charter - Muchin College Prep Campus **Unit** 66573 **Building ID** 1137
Address 1 N State Street **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Vestibule 744, 742, 743, 738 (Closet)								potential for damage		
FD1	Solid flush wood fire door insulation			700, 703-708, 715, 716, 720-724, 738, L00-L04, L35, L36, L62, L63, L66-L72, U01-U04, U30-U32, U41, U42	UNDEFINE D									
FD2	Metal fire door insulation			731-733, 735-737, 742-744, L7L, L7W, L7U, L30-L34, L40, L64, L65, L74, LE29, LE30, U33-U38, U40, UE29, UE30	UNDEFINE D									
FD3	Glazed metal fire door insulation			701, 702, 709-715, L04, L50, L52-L61, U05-U10, U20, U21	UNDEFINE D									
FP	Sprayed-on fireproofing	1,930	SF	Mechanical room, hall 7E, U34, U35, Kitchen, L32, L33	ASSUMED	SURFACE	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
FT-1	12" x 12" Gray w/ Dark Gray Floor Tile	70	SF	Mop room by boys washroom	ASSUMED	MISC	N	LOC	10		Yes	ACBM with potential for significant damage	2	LOW
FT-2	12" x 12" Gray w/ Dark Gray Floor Tile	70	SF	Mop room by boys washroom	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
FT-3	12" x 12" Gray w/ Dark Gray Spots Floor Tile	500	SF	Room L-04	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
FT-4	12" x 12" Gray w/ Dark Gray Spots Floor Tile	500	SF	Room L-04	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
LT	Lab table top			709, 713, 714, 715	UNDEFINE D									
MJP	Mudded joint packings	50	LF	Perimeter columns and shafts	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
MM	Mirror mastic			U09, Bathroom rooms (L35, L36, L67, L68, U30, U31, U37, U38, 732, 733)	UNDEFINE D									
OCFTG	Gray Grout for Octagon-shaped Ceramic Floor Tile	604	SF	Northeast stairwell landing, stairwell landing by U39	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
PLE	Plaster walls/ceilings	65,000	SF	Original perimeter walls & original ceilings in east	ASSUMED	SURFACE	N	LOC	20		Yes	ACBM with the potential for damage	5	LOW

Chicago Public Schools

School Noble Street Charter - Muchin College Prep Campus **Unit** 66573 **Building ID** 1137
Address 1 N State Street **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

Chicago Public Schools

School Noble Street Charter - Muchin College Prep Campus **Unit** 66573 **Building ID** 1137
Address 1 N State Street **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

Chicago Public Schools

School Noble Street Charter - Muchin College Prep Campus **Unit** 66573 **Building ID** 1137
Address 1 N State Street **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

Chicago Public Schools

School Noble Street Charter - Muchin College Prep Campus **Unit** 66573 **Building ID** 1137
Address 1 N State Street **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

Reinspection Date Inspector Name	Inspector's Comments
Inspector's IDPH License Number / Expiration Date	HA Number: Inspector Comments:
	9GFT+M
	9TFT+M
	BB3B
	BB3BM
	BB4B
	BB4BM
	BB4G
	BB4GM
	BB6G
	BB6GM
	CFT1G
	CFT3G
	CG
	CL-1
	CT1
	CT2
	CT3
	CT4
	CWT1G
	CWT4G
	DC
	DWE0
	DWJCEO
	DWJCN

Chicago Public Schools

School Noble Street Charter - Muchin College Prep Campus **Unit** 66573 **Building ID** 1137
Address 1 N State Street **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
DWJCWO	
DWN	
DWWO	
FD1	
FD2	
FD3	
FP	
FT-1	
FT-2	
FT-3	
FT-4	
LT	
MJP	
MM	
OCFTG	
PLE	
PLW	
RFM	
SST	
STG	
STGM	
VJC	
VSF2B	
VSF2DG	
VSF2G	
VSF2M	
VSF2T	
VSFB	
VSFC	

Chicago Public Schools

School Noble Street Charter - Muchin College Prep Campus **Unit** 66573 **Building ID** 1137
Address 1 N State Street **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
VSFDG	
VSFG	
VSFM	
VSFP	
VSFPC	
VSFPL	
VSFPM	
VSFT	
WCE	
WCW	
WFG	
WGE	
WGW	

Table II
Management Planner's Review

Chicago Public Schools

School Noble Street Charter -
Muchin College Prep
Campus

Address 1 N State Street

Unit 66573

Chicago, IL, 60602

Building ID 1137

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
9GFT+M	9" x 9" Green Floor Tile w/ Streaks and Associated Black Mastic			West portion of seventh floor	Abated	MISC					
9TFT+M	9" x 9" Tan Floor Tile w/ Streaks and Associated Black Mastic			West portion of seventh floor	Abated	MISC					
BB3B	3" Brown vinyl baseboard			U09, U10, 701, 702	Undefined						
BB3BM	Tan mastic behind 3" brown vinyl baseboard			U09, U10, 701, 702	Undefined						
BB4B	4" Brown vinyl baseboard	44	SF	Vestibule 744, U35, U36	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
BB4BM	Brown mastic behind 4" brown vinyl baseboard	44	SF	Vestibule 744, U35, U36	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
BB4G	4" Gray vinyl baseboard			Classrooms, offices, hallways throughout	Undefined						
BB4GM	Yellow mastic behind 4" gray vinyl baseboard			Classrooms, offices, hallways throughout	Undefined						
BB6G	6" Gray vinyl baseboard			Center area of east upper hallway at lockers	Undefined						
BB6GM	Yellow mastic behind 6" gray vinyl baseboard			Center area of east upper hallway at lockers	Undefined						
CFT1G	Blue Grout for 1" x 1" Black Ceramic Floor Tile			Bathroom rooms: L35, L36, L67, L68, U30, U31, U37, U38, 732, 733	Undefined						
CFT3G	Gray Grout for 3" x 3" Brown Ceramic Floor Tile	25	SF	L65	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
CG	Clear carpet glue			Classrooms and offices on both levels of 7th floor (Rooms 703, 704, 705, 706, 707, 708, 716, 720, 721, 722, 723, 724, U00, U01, U02, U03, U04, U06, U07, U08, U20, U21, Lower 7th north hallway, L00, L01, L02, L04, L50, L51, L52, L53, L54, L55, L56, L57, L58, L59, L60, L61)	Undefined						
CL-1	Duct caulk	50	LF	Mechanical Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
CT1	1' x 1' White Fissured Ceiling Tile	25	SF	L33	Assumed	MISC	No	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
CT2	2' x 2' White Fissured Ceiling Tile (Replacement)			Vestibule L37	Undefined						
CT3	2' x 2' White Ceiling Tile w/ Fiberglass Backing			Lower 7th floor ceilings (except south hall, toilets, mech. Spaces); Upper 7th floor ceilings (except halls, toilets,	Undefined						

Chicago Public Schools

School Noble Street Charter -
Muchin College Prep
Campus
Address 1 N State Street

Unit 66573

Building ID 1137

Chicago, IL, 60602

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
CT4	2' x 4' White Smooth Ceiling Tile			kitchen, mech. Spaces, reception)	Undefined						
CWT1G	Blue Grout for 1" x 1" Blue Ceramic Accent Wall Tile			Bathroom rooms: L35, L36, L67, L68, U30, U31, U37, U38, 732, 733	Undefined						
CWT4G	Blue Grout for 4" x 4" Gray Ceramic Wall Tile			Bathroom rooms: L35, L36, L67, L68, U30, U31, U37, U38, 732, 733	Undefined						
DC	Gray caulk			At seams of new ductwork above ceilings throughout renovated spaces	Undefined						
DWEO	Drywall	1,600	SF	East Portion - U34, U35, U36L32, L33, L34	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
DWJCE_O	Drywall joint compound	1,600	SF	East Portion - U34, U35, U36L32, L33, L34	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
DWJCN	Drywall joint compound			Interior classrooms, offices, corridors, washrooms	Undefined						
DWJC_WO	Drywall joint compound	50,000	SF	Throughout building	Assumed	MISC	No	10	SF	6 ACBM with the potential for damage	
DWN	Drywall			Interior classrooms, offices, corridors, washrooms	Undefined						
DWVO	Drywall	1,415	SF	West Portion - Vestibule 744, 742, 743, 738 (Closet)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
FD1	Solid flush wood fire door insulation			700, 703-708, 715, 716, 720-724, 738, L00-L04, L35, L36, L62, L63, L66-L72, U01-U04, U30-U32, U41, U42	Undefined						
FD2	Metal fire door insulation			731-733, 735-737, 742-744, L7L, L7W, L7U, L30-L34, L40, L64, L65, L74, LE29, LE30, U33-U38, U40, UE29, UE30	Undefined						
FD3	Glazed metal fire door insulation			701, 702, 709-715, L04, L50, L52-L61, U05-U10, U20, U21	Undefined						
FP	Sprayed-on fireproofing	1,930	SF	Mechanical room, hall 7E, U34, U35, Kitchen, L32, L33	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
FT-1	12" x 12" Gray w/ Dark Gray Floor Tile	70	SF	Mop room by boys washroom	Assumed	MISC	No	10	SF	5 ACBM with potential for significant damage	
FT-2	12" x 12" Gray w/ Dark Gray Floor Tile Mastic	70	SF	Mop room by boys washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	

Chicago Public Schools

School Noble Street Charter -
Muchin College Prep
Campus
Address 1 N State Street

Unit 66573

Building ID 1137

Chicago, IL, 60602

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
FT-3	12" x 12" Gray w/ Dark Gray Spots Floor Tile	500	SF	Room L-04	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
FT-4	12" x 12" Gray w/ Dark Gray Spots Floor Tile Mastic	500	SF	Room L-04	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
LT	Lab table top			709, 713, 714, 715	Undefined						
MJP	Muddled joint packings	50	LF	Perimeter columns and shafts	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	
MM	Mirror mastic			U09, Bathroom rooms (L35, L36, L67, L68, U30, U31, U37, U38, 732, 733)	Undefined						
OCFTG	Gray Grout for Octagon-shaped Ceramic Floor Tile	604	SF	Northeast stairwell landing, stairwell landing by U39	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
PLE	Plaster walls/ceilings	65,000	SF	Original perimeter walls & original ceilings in east portion	Assumed	SURFACE	No	20	SF	6 ACBM with the potential for damage	
PLW	Plaster walls/ceilings	27,800	SF	Original perimeter walls & original ceilings in west portion	Assumed	SURFACE	No	10	SF	6 ACBM with the potential for damage	
RFM	Raised floor stand black mastic pods			West portion of seventh floor	No ACBM	MISC					
SST	Slate stair treads	262	SF	Northeast stairwell landing, stairwell landing by U39	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
STG	Gray vinyl stair treads			Center stairways in north and south hallways	Undefined						
STGM	Clear mastic below gray vinyl stair tread			Center stairways in north and south hallways	Undefined						
VJC	Vibration joint cloths	50	SF	Mechanical Room 741	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
VSF2B	Blue 2' x 2' Vinyl Sheet Floor Squares			West corridors, Reception (700), 709, 710, 711, 712, 713, 714, 715, 742, 743 (this material is part of a four (4) color pattern)	Undefined						
VSF2D G	Dark Gray 2' x 2' Vinyl Sheet Floor Squares			West corridors, Reception (700), 709, 710, 711, 712, 713, 714, 715, 742, 743 (this material is part of a four (4) color pattern)	Undefined						
VSF2G	Gray 2' x 2" Vinyl Sheet Floor Squares	20,000	SF	West corridors, Reception (700), 709, 710, 711, 712, 713, 714, 715, 742, 743 (this material is part of a four (4) color pattern)	Assumed	MISC	No	1	SF	6 ACBM with the potential for damage	

Chicago Public Schools

School Noble Street Charter -
Muchin College Prep
Campus

Address 1 N State Street

Unit 66573

Chicago, IL, 60602

Building ID 1137

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
VSF2M	Clear mastic			Below Multi-Colored 2' x 2' Vinyl Sheet Floor Squares	Undefined						
VSF2T	Tan 2' x 2' Vinyl Sheet Floor Squares			West corridors, Reception (700), 709, 710, 711, 712, 713, 714, 715, 742, 743 (this material is part of a four (4) color pattern)	Undefined						
VSFB	Blue vinyl sheet flooring			East upper corridors, lower south corridor, U05,U32, U39, L03, L62, L69, L70, L71 (this material is part of a four (4) color pattern)	Undefined						
VSFC	Gray Caulk at Seams of Multi-colored Vinyl Sheet Flooring			East upper corridors, lower south corridor, U05,U32, U39, L03, L62, L69, L70, L71 (this material is part of a four (4) color pattern)	Undefined						
VSFDG	Dark gray vinyl sheet flooring			East upper corridors, lower south corridor, U05,U32, U39, L03, L62, L69, L70, L71 (this material is part of a four (4) color pattern)	Undefined						
VSFG	Gray vinyl sheet flooring			East upper corridors, lower south corridor, U05,U32, U39, L03, L62, L69, L70, L71 (this material is part of a four (4) color pattern)	Undefined						
VSFM	Yellow mastic			Below Multi-colored Vinyl Sheet Flooring	Undefined						
VSFP	Pink vinyl sheet safety flooring			Kitchen (U33), L30, L31	Undefined						
VSFPC	Pink caulk			Seams of Pink Vinyl Sheet Safety Flooring	Undefined						
VSFPL	Lip at Edge of Pink Vinyl Sheet Safety Flooring			Kitchen (U33), L30, L31	Undefined						
VSFPM	White mastic			Below Pink Vinyl Sheet Safety Flooring	Undefined						
VSFT	Tan vinyl sheet flooring			East upper corridors, lower south corridor, U05,U32, U39, L03, L62, L69, L70, L71 (this material is part of a four (4) color pattern)	Undefined						
WCE	Interior window caulk			East Portion	No ACBM	MISC					

Chicago Public Schools

School Noble Street Charter -
Muchin College Prep
Campus
Address 1 N State Street
Unit 66573
Building ID 1137
Region Chicago, IL, 60602

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
WCW	Interior window caulk			West Portion	No ACBM	MISC					
WFG	Yellow glue			Below maple Flooring and Athletic Flooring Systems	Undefined						
WGE	Interior window glazing			West Portion	No ACBM	MISC					
WGW	Interior window glazing			West Portion	No ACBM	MISC					

Chicago Public Schools

School Noble Street Charter -
Muchin College Prep
Campus
Address 1 N State Street

Unit 66573

Chicago, IL, 60602

Building ID 1137

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

Review Date	
Manager Planner Name	
Manager IDPH License No/Expiration	

HA Number	Management Comments
9GFT+M	
9TFT+M	
BB3B	
BB3BM	
BB4B	
BB4BM	
BB4G	
BB4GM	
BB6G	
BB6GM	
CFT1G	
CFT3G	
CG	
CL-1	
CT1	
CT2	
CT3	
CT4	
CWT1G	
CWT4G	
DC	
DWE0	
DWJCEO	
DWJCN	

Chicago Public Schools

School Noble Street Charter -
Muchin College Prep
Campus
Address 1 N State Street

Unit 66573

Building ID 1137

Chicago, IL, 60602

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
DWJCWO	
DWN	
DWWO	
FD1	
FD2	
FD3	
FP	
FT-1	
FT-2	
FT-3	
FT-4	
LT	
MJP	
MM	
OCFTG	
PLE	
PLW	
RFM	
SST	
STG	
STGM	
VJC	
VSF2B	
VSF2DG	
VSF2G	
VSF2M	

Chicago Public Schools

School Noble Street Charter -
Muchin College Prep
Campus
Address 1 N State Street

Unit 66573

Chicago, IL, 60602

Building ID 1137

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
VSF2T	
VSFB	
VSFC	
VSFDG	
VSFG	
VSFM	
VSFP	
VSFPC	
VSFPL	
VSFPM	
VSFT	
WCE	
WCW	
WFG	
WGE	
WGW	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

2025 AHERA REINSPECTION

Chicago Public Schools

2025 AHERA REINSPECTION Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9GFT+M**
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile w/ Streaks and Associated Black Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **West portion of seventh floor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **9GFT+M**

MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile w/ Streaks and Associated Black Mastic**

MATERIAL LOCATION: **West portion of seventh floor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9TFT+M**
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/ Streaks and Associated Black Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **West portion of seventh floor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **9TFT+M**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/ Streaks and Associated Black Mastic**

MATERIAL LOCATION: **West portion of seventh floor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BB3B**
MATERIAL DESCRIPTION: **3" Brown vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **U09, U10, 701, 702**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **BB3B**

MATERIAL DESCRIPTION: **3" Brown vinyl baseboard**

MATERIAL LOCATION: **U09, U10, 701, 702**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BB3BM**
MATERIAL DESCRIPTION: **Tan mastic behind 3" brown vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **U09, U10, 701, 702**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **BB3BM**

MATERIAL DESCRIPTION: **Tan mastic behind 3" brown vinyl baseboard**

MATERIAL LOCATION: **U09, U10, 701, 702**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BB4B**
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Vestibule 744, U35, U36**
MATERIAL QUANTITY: **44** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **BB4B**

MATERIAL DESCRIPTION: **4" Brown vinyl baseboard**

MATERIAL LOCATION: **Vestibule 744, U35, U36**

MATERIAL QUANTITY: **44** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BB4BM**
MATERIAL DESCRIPTION: **Brown mastic behind 4" brown vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Vestibule 744, U35, U36**
MATERIAL QUANTITY: **44** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **BB4BM**

MATERIAL DESCRIPTION: **Brown mastic behind 4" brown vinyl baseboard**

MATERIAL LOCATION: **Vestibule 744, U35, U36**

MATERIAL QUANTITY: **44** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BB4G**
MATERIAL DESCRIPTION: **4" Gray vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms, offices, hallways throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **BB4G**

MATERIAL DESCRIPTION: **4" Gray vinyl baseboard**

MATERIAL LOCATION: **Classrooms, offices, hallways throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BB4GM**
MATERIAL DESCRIPTION: **Yellow mastic behind 4' gray vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms, offices, hallways throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **BB4GM**

MATERIAL DESCRIPTION: **Yellow mastic behind 4' gray vinyl baseboard**

MATERIAL LOCATION: **Classrooms, offices, hallways throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BB6G**
MATERIAL DESCRIPTION: **6" Gray vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Center area of east upper hallway at lockers**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **BB6G**

MATERIAL DESCRIPTION: **6" Gray vinyl baseboard**

MATERIAL LOCATION: **Center area of east upper hallway at lockers**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BB6GM**
MATERIAL DESCRIPTION: **Yellow mastic behind 6" gray vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Center area of east upper hallway at lockers**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **BB6GM**

MATERIAL DESCRIPTION: **Yellow mastic behind 6" gray vinyl baseboard**

MATERIAL LOCATION: **Center area of east upper hallway at lockers**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CFT1G**
MATERIAL DESCRIPTION: **Blue Grout for 1" x 1" Black Ceramic Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Bathroom rooms: L35, L36, L67, L68, U30, U31, U37, U38, 732, 733**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **CFT1G**

MATERIAL DESCRIPTION: **Blue Grout for 1" x 1" Black Ceramic Floor Tile**

MATERIAL LOCATION: **Bathroom rooms: L35, L36, L67, L68, U30, U31, U37, U38, 732, 733**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CFT3G**
MATERIAL DESCRIPTION: **Gray Grout for 3" x 3" Brown Ceramic Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **L65**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **CFT3G**

MATERIAL DESCRIPTION: **Gray Grout for 3" x 3" Brown Ceramic Floor Tile**

MATERIAL LOCATION: **L65**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CG**
MATERIAL DESCRIPTION: **Clear carpet glue**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms and offices on both levels of 7th floor (Rooms 703, 704, 705, 706, 707, 708, 716, 720, 721, 722, 723, 724, U00, U01, U02, U03, U04, U06, U07, U08, U20, U21, Lower 7th north hallway, L00, L01, L02, L04, L50, L51, L52, L53, L54, L55, L56, L57, L58, L59, L60, L61)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date:

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **CG**

MATERIAL DESCRIPTION: **Clear carpet glue**

MATERIAL LOCATION: **Classrooms and offices on both levels of 7th floor (Rooms 703, 704, 705, 706, 707, 708, 716, 720, 721, 722, 723, 724, U00, U01, U02, U03, U04, U06, U07, U08, U20, U21, Lower 7th north hallway, L00, L01, L02, L04, L50, L51, L52, L53, L54, L55,L56,L57, L58,L59,L60,L61)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CL-1**
MATERIAL DESCRIPTION: **Duct caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Mechanical Room**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **50** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **CL-1**

MATERIAL DESCRIPTION: **Duct caulk**

MATERIAL LOCATION: **Mechanical Room**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CT1**
MATERIAL DESCRIPTION: **1' x 1' White Fissured Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **L33**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **CT1**

MATERIAL DESCRIPTION: **1' x 1' White Fissured Ceiling Tile**

MATERIAL LOCATION: **L33**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CT2**
MATERIAL DESCRIPTION: **2' x 2' White Fissured Ceiling Tile (Replacement)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Vestibule L37**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **CT2**

MATERIAL DESCRIPTION: **2' x 2' White Fissured Ceiling Tile (Replacement)**

MATERIAL LOCATION: **Vestibule L37**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CT3**
MATERIAL DESCRIPTION: **2' x 2' White Ceiling Tile w/ Fiberglass Backing**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lower 7th floor ceilings (except south hall, toilets, mech. Spaces); Upper 7th floor ceilings (except halls, toilets, kitchen, mech. Spaces, reception)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date:

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **CT3**

MATERIAL DESCRIPTION: **2' x 2' White Ceiling Tile w/ Fiberglass Backing**

MATERIAL LOCATION: **Lower 7th floor ceilings (except south hall, toilets, mech. Spaces); Upper 7th floor ceilings (except halls, toilets, kitchen, mech. Spaces, reception)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CT4**
MATERIAL DESCRIPTION: **2' x 4' White Smooth Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **West hallways**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **CT4**

MATERIAL DESCRIPTION: **2' x 4' White Smooth Ceiling Tile**

MATERIAL LOCATION: **West hallways**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CWT1G**
MATERIAL DESCRIPTION: **Blue Grout for 1" x 1" Blue Ceramic Accent Wall Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Bathroom rooms: L35, L36, L67, L68, U30, U31, U37, U38, 732, 733**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **CWT1G**

MATERIAL DESCRIPTION: **Blue Grout for 1" x 1" Blue Ceramic Accent Wall Tile**

MATERIAL LOCATION: **Bathroom rooms: L35, L36, L67, L68, U30, U31, U37, U38, 732, 733**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CWT4G**
MATERIAL DESCRIPTION: **Blue Grout for 4" x 4" Gray Ceramic Wall Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Bathroom rooms: L35, L36, L67, L68, U30, U31, U37, U38, 732, 733**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **CWT4G**

MATERIAL DESCRIPTION: **Blue Grout for 4" x 4" Gray Ceramic Wall Tile**

MATERIAL LOCATION: **Bathroom rooms: L35, L36, L67, L68, U30, U31, U37, U38, 732, 733**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **DC**
MATERIAL DESCRIPTION: **Gray caulk**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **At seams of new ductwork above ceilings throughout renovated spaces**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **DC**

MATERIAL DESCRIPTION: **Gray caulk**

MATERIAL LOCATION: **At seams of new ductwork above ceilings throughout renovated spaces**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **DWEO**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **East Portion - U34, U35, U36L32, L33, L34**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **DWEO**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **East Portion - U34, U35, U36L32, L33, L34**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **DWJCEO**
MATERIAL DESCRIPTION: **Drywall joint compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **East Portion - U34, U35, U36L32, L33, L34**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **DWJCEO**

MATERIAL DESCRIPTION: **Drywall joint compound**

MATERIAL LOCATION: **East Portion - U34, U35, U36L32, L33, L34**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **DWJCN**
MATERIAL DESCRIPTION: **Drywall joint compound**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Interior classrooms, offices, corridors, washrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **DWJCN**

MATERIAL DESCRIPTION: **Drywall joint compound**

MATERIAL LOCATION: **Interior classrooms, offices, corridors, washrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **DWJCWO**
MATERIAL DESCRIPTION: **Drywall joint compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout building**
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **DWJCWO**

MATERIAL DESCRIPTION: **Drywall joint compound**

MATERIAL LOCATION: **Throughout building**

MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **DWN**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Interior classrooms, offices, corridors, washrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **DWN**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Interior classrooms, offices, corridors, washrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **DWWO**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **West Portion - Vestibule 744, 742, 743, 738 (Closet)**
MATERIAL QUANTITY: **1415** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **DWWO**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **West Portion - Vestibule 744, 742, 743, 738 (Closet)**

MATERIAL QUANTITY: **1415** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FD1**
MATERIAL DESCRIPTION: **Solid flush wood fire door insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **700, 703-708, 715, 716, 720-724, 738, L00-L04, L35, L36, L62, L63, L66-L72, U01-U04, U30-U32, U41, U42**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date:

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **FD1**

MATERIAL DESCRIPTION: **Solid flush wood fire door insulation**

MATERIAL LOCATION: **700, 703-708, 715, 716, 720-724, 738, L00-L04, L35, L36, L62, L63, L66-L72, U01-U04, U30-U32, U41,
U42**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FD2**
MATERIAL DESCRIPTION: **Metal fire door insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **731-733, 735-737, 742-744, L7L, L7W, L7U, L30-L34, L40, L64, L65, L74, LE29, LE30, U33-U38, U40, UE29, UE30**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date:

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **FD2**

MATERIAL DESCRIPTION: **Metal fire door insulation**

MATERIAL LOCATION: **731-733, 735-737, 742-744, L7L, L7W, L7U, L30-L34, L40, L64, L65, L74, LE29, LE30, U33-U38, U40,
UE29, UE30**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FD3**
MATERIAL DESCRIPTION: **Glazed metal fire door insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **701, 702, 709-715, L04, L50, L52-L61, U05-U10, U20, U21**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **FD3**

MATERIAL DESCRIPTION: **Glazed metal fire door insulation**

MATERIAL LOCATION: **701, 702, 709-715, L04, L50, L52-L61, U05-U10, U20, U21**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FP**
MATERIAL DESCRIPTION: **Sprayed-on fireproofing**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Mechanical room, hall 7E, U34, U35, Kitchen, L32, L33**
MATERIAL QUANTITY: **1930** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **FP**

MATERIAL DESCRIPTION: **Sprayed-on fireproofing**

MATERIAL LOCATION: **Mechanical room, hall 7E, U34, U35, Kitchen, L32, L33**

MATERIAL QUANTITY: **1930** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-1**
MATERIAL DESCRIPTION: **12" x 12" Gray w/ Dark Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON: **Delamination
Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Delamination
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Mop room by boys washroom**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **FT-1**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Dark Gray Floor Tile**

MATERIAL LOCATION: **Mop room by boys washroom**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-2**
MATERIAL DESCRIPTION: **12" x 12" Gray w/ Dark Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Mop room by boys washroom**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **70** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **FT-2**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Dark Gray Floor Tile Mastic**

MATERIAL LOCATION: **Mop room by boys washroom**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-3**
MATERIAL DESCRIPTION: **12" x 12" Gray w/ Dark Gray Spots Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room L-04**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **500** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **FT-3**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Dark Gray Spots Floor Tile**

MATERIAL LOCATION: **Room L-04**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-4**
MATERIAL DESCRIPTION: **12" x 12" Gray w/ Dark Gray Spots Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room L-04**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **500** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **FT-4**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Dark Gray Spots Floor Tile Mastic**

MATERIAL LOCATION: **Room L-04**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **LT**
MATERIAL DESCRIPTION: **Lab table top**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **709, 713, 714, 715**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **LT**

MATERIAL DESCRIPTION: **Lab table top**

MATERIAL LOCATION: **709, 713, 714, 715**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MJP**
MATERIAL DESCRIPTION: **Muddled joint packings**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Perimeter columns and shafts**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **50** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **MJP**

MATERIAL DESCRIPTION: **Muddled joint packings**

MATERIAL LOCATION: **Perimeter columns and shafts**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MM**
MATERIAL DESCRIPTION: **Mirror mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **U09, Bathroom rooms (L35, L36, L67, L68, U30, U31, U37, U38, 732, 733)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **MM**

MATERIAL DESCRIPTION: **Mirror mastic**

MATERIAL LOCATION: **U09, Bathroom rooms (L35, L36, L67, L68, U30, U31, U37, U38, 732, 733)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **OCFTG**
MATERIAL DESCRIPTION: **Gray Grout for Octagon-shaped Ceramic Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Northeast stairwell landing, stairwell landing by U39**
MATERIAL QUANTITY: **604** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **OCFTG**

MATERIAL DESCRIPTION: **Gray Grout for Octagon-shaped Ceramic Floor Tile**

MATERIAL LOCATION: **Northeast stairwell landing, stairwell landing by U39**

MATERIAL QUANTITY: **604** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **PLE**
MATERIAL DESCRIPTION: **Plaster walls/ceilings**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Original perimeter walls & original ceilings in east portion**
MATERIAL QUANTITY: **65000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **PLE**

MATERIAL DESCRIPTION: **Plaster walls/ceilings**

MATERIAL LOCATION: **Original perimeter walls & original ceilings in east portion**

MATERIAL QUANTITY: **65000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **PLW**
MATERIAL DESCRIPTION: **Plaster walls/ceilings**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Original perimeter walls & original ceilings in west portion**
MATERIAL QUANTITY: **27800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **PLW**

MATERIAL DESCRIPTION: **Plaster walls/ceilings**

MATERIAL LOCATION: **Original perimeter walls & original ceilings in west portion**

MATERIAL QUANTITY: **27800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **RFM**
MATERIAL DESCRIPTION: **Raised floor stand black mastic pods**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **West portion of seventh floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **RFM**

MATERIAL DESCRIPTION: **Raised floor stand black mastic pods**

MATERIAL LOCATION: **West portion of seventh floor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **SST**
MATERIAL DESCRIPTION: **Slate stair treads**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Northeast stairwell landing, stairwell landing by U39**
MATERIAL QUANTITY: **262** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **SST**

MATERIAL DESCRIPTION: **Slate stair treads**

MATERIAL LOCATION: **Northeast stairwell landing, stairwell landing by U39**

MATERIAL QUANTITY: **262** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **STG**
MATERIAL DESCRIPTION: **Gray vinyl stair treads**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Center stairways in north and south hallways**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **STG**

MATERIAL DESCRIPTION: **Gray vinyl stair treads**

MATERIAL LOCATION: **Center stairways in north and south hallways**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **STGM**
MATERIAL DESCRIPTION: **Clear mastic below gray vinyl stair tread**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Center stairways in north and south hallways**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **STGM**

MATERIAL DESCRIPTION: **Clear mastic below gray vinyl stair tread**

MATERIAL LOCATION: **Center stairways in north and south hallways**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **VJC**
MATERIAL DESCRIPTION: **Vibration joint cloths**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Mechanical Room 741**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **VJC**

MATERIAL DESCRIPTION: **Vibration joint cloths**

MATERIAL LOCATION: **Mechanical Room 741**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **VSF2B**
MATERIAL DESCRIPTION: **Blue 2' x 2' Vinyl Sheet Floor Squares**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **West corridors, Reception (700), 709, 710, 711, 712, 713, 714, 715, 742, 743 (this material is part of a four (4) color pattern)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date:

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **VSF2B**

MATERIAL DESCRIPTION: **Blue 2' x 2' Vinyl Sheet Floor Squares**

MATERIAL LOCATION: **West corridors, Reception (700), 709, 710, 711, 712, 713, 714, 715, 742, 743 (this material is part of
a four (4) color pattern)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **VSF2DG**
MATERIAL DESCRIPTION: **Dark Gray 2' x 2' Vinyl Sheet Floor Squares**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **West corridors, Reception (700), 709, 710, 711, 712, 713, 714, 715, 742, 743 (this material is part of a four (4) color pattern)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date:

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **VSF2DG**

MATERIAL DESCRIPTION: **Dark Gray 2' x 2' Vinyl Sheet Floor Squares**

MATERIAL LOCATION: **West corridors, Reception (700), 709, 710, 711, 712, 713, 714, 715, 742, 743 (this material is part of
a four (4) color pattern)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **VSF2G**
MATERIAL DESCRIPTION: **Gray 2' x 2" Vinyl Sheet Floor Squares**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **West corridors, Reception (700), 709, 710, 711, 712, 713, 714, 715, 742, 743 (this material is part of a four (4) color pattern)**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **VSF2G**

MATERIAL DESCRIPTION: **Gray 2' x 2" Vinyl Sheet Floor Squares**

MATERIAL LOCATION: **West corridors, Reception (700), 709, 710, 711, 712, 713, 714, 715, 742, 743 (this material is part of
a four (4) color pattern)**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **1** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **VSF2M**
MATERIAL DESCRIPTION: **Clear mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Below Multi-Colored 2' x 2' Vinyl Sheet Floor Squares**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **VSF2M**

MATERIAL DESCRIPTION: **Clear mastic**

MATERIAL LOCATION: **Below Multi-Colored 2' x 2' Vinyl Sheet Floor Squares**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **VSF2T**
MATERIAL DESCRIPTION: **Tan 2' x 2' Vinyl Sheet Floor Squares**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **West corridors, Reception (700), 709, 710, 711, 712, 713, 714, 715, 742, 743 (this material is part of a four (4) color pattern)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date:

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **VSF2T**

MATERIAL DESCRIPTION: **Tan 2' x 2' Vinyl Sheet Floor Squares**

MATERIAL LOCATION: **West corridors, Reception (700), 709, 710, 711, 712, 713, 714, 715, 742, 743 (this material is part of
a four (4) color pattern)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **VSFB**
MATERIAL DESCRIPTION: **Blue vinyl sheet flooring**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **East upper corridors, lower south corridor, U05,U32, U39, L03, L62, L69, L70, L71 (this material is part of a four (4) color pattern)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date:

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **VSFB**

MATERIAL DESCRIPTION: **Blue vinyl sheet flooring**

MATERIAL LOCATION: **East upper corridors, lower south corridor, U05, U32, U39, L03, L62, L69, L70, L71 (this material is
part of a four (4) color pattern)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **VSFC**
MATERIAL DESCRIPTION: **Gray Caulk at Seams of Multi-colored Vinyl Sheet Flooring**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **East upper corridors, lower south corridor, U05,U32, U39, L03, L62, L69, L70, L71 (this material is part of a four (4) color pattern)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date:

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **VSFC**

MATERIAL DESCRIPTION: **Gray Caulk at Seams of Multi-colored Vinyl Sheet Flooring**

MATERIAL LOCATION: **East upper corridors, lower south corridor, U05, U32, U39, L03, L62, L69, L70, L71 (this material is
part of a four (4) color pattern)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **VSFDG**
MATERIAL DESCRIPTION: **Dark gray vinyl sheet flooring**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **East upper corridors, lower south corridor, U05,U32, U39, L03, L62, L69, L70, L71 (this material is part of a four (4) color pattern)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date:

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **VSFDG**

MATERIAL DESCRIPTION: **Dark gray vinyl sheet flooring**

MATERIAL LOCATION: **East upper corridors, lower south corridor, U05, U32, U39, L03, L62, L69, L70, L71 (this material is
part of a four (4) color pattern)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **VSFG**
MATERIAL DESCRIPTION: **Gray vinyl sheet flooring**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **East upper corridors, lower south corridor, U05,U32, U39, L03, L62, L69, L70, L71 (this material is part of a four (4) color pattern)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date:

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **VSFG**

MATERIAL DESCRIPTION: **Gray vinyl sheet flooring**

MATERIAL LOCATION: **East upper corridors, lower south corridor, U05, U32, U39, L03, L62, L69, L70, L71 (this material is
part of a four (4) color pattern)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **VSFM**
MATERIAL DESCRIPTION: **Yellow mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Below Multi-colored Vinyl Sheet Flooring**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **VSFM**

MATERIAL DESCRIPTION: **Yellow mastic**

MATERIAL LOCATION: **Below Multi-colored Vinyl Sheet Flooring**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **VSFP**
MATERIAL DESCRIPTION: **Pink vinyl sheet safety flooring**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen (U33), L30, L31**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **VSFP**

MATERIAL DESCRIPTION: **Pink vinyl sheet safety flooring**

MATERIAL LOCATION: **Kitchen (U33), L30, L31**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **VSFPC**
MATERIAL DESCRIPTION: **Pink caulk**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Seams of Pink Vinyl Sheet Safety Flooring**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **VSFPC**

MATERIAL DESCRIPTION: **Pink caulk**

MATERIAL LOCATION: **Seams of Pink Vinyl Sheet Safety Flooring**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **VSFPL**
MATERIAL DESCRIPTION: **Lip at Edge of Pink Vinyl Sheet Safety Flooring**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen (U33), L30, L31**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **VSFPL**

MATERIAL DESCRIPTION: **Lip at Edge of Pink Vinyl Sheet Safety Flooring**

MATERIAL LOCATION: **Kitchen (U33), L30, L31**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **VSFPM**
MATERIAL DESCRIPTION: **White mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Below Pink Vinyl Sheet Safety Flooring**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **VSFPM**

MATERIAL DESCRIPTION: **White mastic**

MATERIAL LOCATION: **Below Pink Vinyl Sheet Safety Flooring**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **VSFT**
MATERIAL DESCRIPTION: **Tan vinyl sheet flooring**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **East upper corridors, lower south corridor, U05,U32, U39, L03, L62, L69, L70, L71 (this material is part of a four (4) color pattern)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date:

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **VSFT**

MATERIAL DESCRIPTION: **Tan vinyl sheet flooring**

MATERIAL LOCATION: **East upper corridors, lower south corridor, U05, U32, U39, L03, L62, L69, L70, L71 (this material is
part of a four (4) color pattern)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **WCE**
MATERIAL DESCRIPTION: **Interior window caulk**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **East Portion**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **WCE**

MATERIAL DESCRIPTION: **Interior window caulk**

MATERIAL LOCATION: **East Portion**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **WCW**
MATERIAL DESCRIPTION: **Interior window caulk**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **West Portion**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **WCW**

MATERIAL DESCRIPTION: **Interior window caulk**

MATERIAL LOCATION: **West Portion**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **WFG**
MATERIAL DESCRIPTION: **Yellow glue**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Below maple Flooring and Athletic Flooring Systems**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **WFG**

MATERIAL DESCRIPTION: **Yellow glue**

MATERIAL LOCATION: **Below maple Flooring and Athletic Flooring Systems**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **WGE**
MATERIAL DESCRIPTION: **Interior window glazing**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **West Portion**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **WGE**

MATERIAL DESCRIPTION: **Interior window glazing**

MATERIAL LOCATION: **West Portion**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BUIDLING ID: **1137**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Noble Street Charter - Muchin College Prep Campus** INSPECTION DATE:
ADDRESS: **1 N State Street** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **WGW**
MATERIAL DESCRIPTION: **Interior window glazing**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **West Portion**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66573** BULDING ID: **1137**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:

SCHOOL NAME: **Noble Street Charter -
Muchin College Prep
Campus** REVIEW DATE:

ADDRESS: **1 N State Street** IDPH LICENSE NO:

HOMOGENEOUS AREA: **WGW**

MATERIAL DESCRIPTION: **Interior window glazing**

MATERIAL LOCATION: **West Portion**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed