

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-3006  
SCHOOL NAME: Youth Connection - Olive Harvey Middle College  
High School  
ADDRESS OF SCHOOL: 10001 Woodlawn  
CITY: Chicago, IL, 60628

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 7/18/2024

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 7/18/2024 ENROLLMENT 121  
IDPH INSPECTOR LICENSE NUMBER: 100-20837  
IDPH LICENSED INSPECTOR NAME (Please Print): Mitch Kurka  
IDPH MP LICENSE NUMBER: 100-01934  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Randy Livingston

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

7/24/2024

Richard J. Schleyer  
Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_  
School has been closed. Date closed: \_\_\_\_\_  
School building has been demolished. Date: \_\_\_\_\_  
School building is asbestos free since last reinspection: N

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either and exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Youth Connection - Olive Harvey Middle College High School**

10001 Woodlawn  
Chicago, IL, 60628

Unit: 66621  
Building ID: 1121V

IDPH ID Number: 14-016-2990-3006

**REPORT DATE:**  
Wednesday, July 24, 2024

**Prepared for:**  
**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**  
**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

07/24/2024

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299      Unit: 66621      Region:      IDPH ID: 14-016-2990-3006

School: Youth Connection - Olive Harvey Middle College High School      Building ID: 1121V

Address: 10001 Woodlawn

Chicago, IL, 60628

Building Contact:      Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date: 7/18/2024

Review Date: 07/24/2024

Inspector: Mitch Kurka

Inspector IDPH License: 100-20837

Management Planner: Randy Livingston

Management Planner IDPH License: 100-01934

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates



Randy Livingston  
100-01934

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: July 24, 2024

RE: Youth Connection - Olive Harvey Middle College High School, Unit 66621  
10001 Woodlawn  
Chicago, IL, 60628

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Youth Connection - Olive Harvey Middle College High School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Youth Connection - Olive Harvey Middle College High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J. Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Youth Connection - Olive Harvey Middle College High School  
Address: 10001 Woodlawn  
IDPH ID: 14-016-2990-3006  
Contact: \_\_\_\_\_

Unit: 66621  
Chicago, IL, 60628  
Building ID: 1121V  
Phone: \_\_\_\_\_

Region: \_\_\_\_\_

### 2. Description of Facility

Original Construction: \_\_\_\_\_  
Total Square Footage: 397700  
Current Occupancy: 121

Additional Construction: \_\_\_\_\_  
No of Floors: \_\_\_\_\_

### 3. LEA Designated Person

Contact: Richard J.Schleyer  
Address: 42 West Madison Street  
Chicago, IL 60602

Phone: (773) 251-7074

### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Doug McCormick  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900

Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Mitch Kurka

Inspector IDPH license # 100-20837  
Reinspection Date: 7/18/2024

Signature:  
Date: 7/18/2024

### 6. Management Planner

Management Planner Name: Randy Livingston

Management Planner IDPH license # 100-01934



Signature:  
Date: 07/24/2024

### 7. Review Date: 07/24/2024

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.



Richard J. Schleyer

Signature:

Date: 7/24/2024

Name: Richard J.Schleyer



## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Youth Connection - Olive Harvey Middle College High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1121V:

08	5'x5' Ceiling Panels
10	2'x4' White Ceiling Tile

B. The following new homogenous areas have been identified for Building 1121V:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	12x12 White w/Brown Specks Vinyl Floor Tile
01A	12x12 White w/Brown Specks Vinyl Floor Tile Mastic
03	Drywall
04	Drywall Tape/Joint Compound
05	4" Light Brown Baseboard
05A	4" Light Brown Baseboard Mastic
06	4" Dark Brown Baseboard
06A	4" Dark Brown Baseboard Mastic
07	Brown & White Specked Terrazzo
08	5'x5' Ceiling Panels
09	Brown Mosaic Ceramic Tile Grout
09A	Brown Mosaic Ceramic Tile Mastic
10	2'x4' White Ceiling Tile
BB-1	4" Dark Gray Vinyl Baseboard

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Mitch Kurka, IDPH License # 100-20837. The Management Plan was updated by Randy Livingston, IDPH License # 100-01934. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Youth Connection - Olive Harvey Middle College High School Building 1121V Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

**School** Youth Connection - Olive Harvey Middle College High School **Unit** 66621 **Building ID** 1121V  
**Address** 10001 Woodlawn **Region**

## **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

## Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

## *Inspector's Comments are Summarized at the End of the Report*

# Chicago Public Schools

**School** Youth Connection - Olive Harvey Middle College High School **Unit** 66621 **Building ID** 1121V  
**Address** 10001 Woodlawn **Region**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date	<u>7/18/2024</u>
Inspector Name	<u>Mitch Kurka</u>
<b>100-20837</b>	<b>5/15/2025</b>
Inspector's IDPH License Number / Expiration Date	

#### Inspector's Comments

HA Number:	Inspector Comments:
01	
01A	
02	
03	
04	
05	
05A	
06	
06A	
07	
08	
09	
09A	
10	
BB-1	

**Table II**  
**Management Planner's Review**

---

# Chicago Public Schools

**School** Youth Connection - Olive  
 Harvey Middle College  
 High School  
**Address** 10001 Woodlawn  
**Unit** 66621  
**Building ID** 1121V  
**Region**  
 Chicago, IL, 60628

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	12x12 White w/Brown Specks Vinyl Floor Tile	8,000	SF	Throughout All Rooms in School	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
01A	12x12 White w/Brown Specks Vinyl Floor Tile Mastic	8,000	SF	Throughout All Rooms in School	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
02	18"x4' White Pinholed Ceiling Tile ABATED	0		Rooms L104, L105, L109, L111, L112, L113, L114	Abated	MISC					
03	Drywall	7,500	SF	Rooms L104, L105, L109, L110, L111, L112, L113, L114	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
04	Drywall Tape/Joint Compound	7,500	SF	Rooms L104, L105, L109, L110, L111, L112, L113, L114	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
05	4" Light Brown Baseboard	440	LF	L109 - L114	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
05A	4" Light Brown Baseboard Mastic	440	LF	L109 - L114	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
06	4" Dark Brown Baseboard	480	LF	L104 and L105	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
06A	4" Dark Brown Baseboard Mastic	480	LF	L104 and L105	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
07	Brown & White Specked Terrazzo	3,000	SF	Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
08	5'x5' Ceiling Panels	3,000	SF	Corridor Ceilings	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	
09	Brown Mosaic Ceramic Tile Grout			Men's and Women's Bathrooms	Assumed	MISC	No			6 ACBM with the potential for damage	
09A	Brown Mosaic Ceramic Tile Mastic			Men's and Women's Bathroom	Assumed	MISC	No	0		6 ACBM with the potential for damage	
10	2'x4' White Ceiling Tile	11,000	SF	All Rooms Throughout School & Corridors	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
BB-1	4" Dark Gray Vinyl Baseboard			Building 7- Rooms 7A-7L, 706A, 707, 708	Assumed	MISC					

# Chicago Public Schools

**School** Youth Connection - Olive  
Harvey Middle College  
High School  
**Address** 10001 Woodlawn  
**Unit** 66621  
**Building ID** 1121V  
**Region**  
Chicago, IL, 60628

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

***Management Planner's Comments Summarized at the End of the Report***

Review Date	7/24/2024
Manager Planner Name	Randy Livingston
100-01934	5/15/2025
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
01A	
02	
03	
04	
05	
05A	
06	
06A	
07	
08	
09	
09A	
10	

# Chicago Public Schools

**School** Youth Connection - Olive  
Harvey Middle College  
High School      **Unit** 66621      **Building ID** 1121V  
**Address** 10001 Woodlawn      **Chicago, IL, 60628**      **Region**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

*Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
BB-1	

## APPENDIX A

---

### Assessment Sheets, Drawings and Photos

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2025 AHERA REINSPECTION***

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	66621	BUIDLING ID:	1121V
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mitch Kurka		
SCHOOL NAME:	Youth Connection - Olive Harvey Middle College High School	INSPECTION DATE:	7/18/2024		
ADDRESS:	10001 Woodlawn	IDPH LICENSE NO:	100-20837		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	01		
MATERIAL DESCRIPTION:	12x12 White w/Brown Specks Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout All Rooms in School		
MATERIAL QUANTITY:	8000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 07/18/2024

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>66621</b>	BUILDING ID:	<b>1121V</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Randy Livingston</b>		
SCHOOL NAME:	<b>Youth Connection - Olive Harvey Middle College High School</b>	REVIEW DATE:	<b>7/24/2024</b>		
ADDRESS:	<b>10001 Woodlawn</b>	IDPH LICENSE NO:	<b>100-20837</b>		

---

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **12x12 White w/Brown Specks Vinyl Floor Tile**

MATERIAL LOCATION: **Throughout All Rooms in School**

MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/24/2024**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	66621	BUILDING ID:	1121V
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mitch Kurka		
SCHOOL NAME:	Youth Connection - Olive Harvey Middle College High School	INSPECTION DATE:	7/18/2024		
ADDRESS:	10001 Woodlawn	IDPH LICENSE NO:	100-20837		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	01A		
MATERIAL DESCRIPTION:	12x12 White w/Brown Specks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout All Rooms in School**

MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:

Date: **07/18/2024**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>66621</b>	BUILDING ID:	<b>1121V</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Randy Livingston</b>		
SCHOOL NAME:	<b>Youth Connection - Olive Harvey Middle College High School</b>	REVIEW DATE:	<b>7/24/2024</b>		
ADDRESS:	<b>10001 Woodlawn</b>	IDPH LICENSE NO:	<b>100-20837</b>		

---

HOMOGENEOUS AREA: **01A**

MATERIAL DESCRIPTION: **12x12 White w/Brown Specks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Throughout All Rooms in School**

MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/24/2024**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	66621	BUILDING ID:	1121V
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mitch Kurka		
SCHOOL NAME:	Youth Connection - Olive Harvey Middle College High School	INSPECTION DATE:	7/18/2024		
ADDRESS:	10001 Woodlawn	IDPH LICENSE NO:	100-20837		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 02

MATERIAL DESCRIPTION: 18"x4' White Pinholed Ceiling Tile ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Rooms L104, L105, L109, L111, L112, L113, L114

MATERIAL QUANTITY: 0 MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/18/2024

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>66621</b>	BUILDING ID:	<b>1121V</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Randy Livingston</b>		
SCHOOL NAME:	<b>Youth Connection - Olive Harvey Middle College High School</b>	REVIEW DATE:	<b>7/24/2024</b>		
ADDRESS:	<b>10001 Woodlawn</b>	IDPH LICENSE NO:	<b>100-20837</b>		

---

HOMOGENEOUS AREA: **02**

MATERIAL DESCRIPTION: **18"x4' White Pinholed Ceiling Tile ABATED**

MATERIAL LOCATION: **Rooms L104, L105, L109, L111, L112, L113, L114**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/24/2024**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA RE/INSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	66621	BUIDLING ID:	1121V
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mitch Kurka		
SCHOOL NAME:	Youth Connection - Olive Harvey Middle College High School	INSPECTION DATE:	7/18/2024		
ADDRESS:	10001 Woodlawn	IDPH LICENSE NO:	100-20837		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03		
MATERIAL DESCRIPTION:	Drywall		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms L104, L105, L109, L110, L111, L112, L113, L114		
MATERIAL QUANTITY:	7500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 07/18/2024

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>66621</b>	BUILDING ID:	<b>1121V</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Randy Livingston</b>		
SCHOOL NAME:	<b>Youth Connection - Olive Harvey Middle College High School</b>	REVIEW DATE:	<b>7/24/2024</b>		
ADDRESS:	<b>10001 Woodlawn</b>	IDPH LICENSE NO:	<b>100-20837</b>		

---

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Rooms L104, L105, L109, L110, L111, L112, L113, L114**

MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/24/2024**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA RE/INSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	66621	BUIDLING ID:	1121V
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mitch Kurka		
SCHOOL NAME:	Youth Connection - Olive Harvey Middle College High School	INSPECTION DATE:	7/18/2024		
ADDRESS:	10001 Woodlawn	IDPH LICENSE NO:	100-20837		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	04		
MATERIAL DESCRIPTION:	Drywall Tape/Joint Compound		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms L104, L105, L109, L110, L111, L112, L113, L114**

MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:

Date: **07/18/2024**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>66621</b>	BUILDING ID:	<b>1121V</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Randy Livingston</b>		
SCHOOL NAME:	<b>Youth Connection - Olive Harvey Middle College High School</b>	REVIEW DATE:	<b>7/24/2024</b>		
ADDRESS:	<b>10001 Woodlawn</b>	IDPH LICENSE NO:	<b>100-20837</b>		

---

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **Drywall Tape/Joint Compound**

MATERIAL LOCATION: **Rooms L104, L105, L109, L110, L111, L112, L113, L114**

MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/24/2024**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA RE/INSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	66621	BUIDLING ID:	1121V
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mitch Kurka		
SCHOOL NAME:	Youth Connection - Olive Harvey Middle College High School	INSPECTION DATE:	7/18/2024		
ADDRESS:	10001 Woodlawn	IDPH LICENSE NO:	100-20837		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05		
MATERIAL DESCRIPTION:	4" Light Brown Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	L109 - L114		
MATERIAL QUANTITY:	440	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 07/18/2024

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUILDING ID: **1121V**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**

SCHOOL NAME: **Youth Connection -  
Olive Harvey Middle  
College High School** REVIEW DATE: **7/24/2024**

ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-20837**

---

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **4" Light Brown Baseboard**

MATERIAL LOCATION: **L109 - L114**

MATERIAL QUANTITY: **440** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/24/2024**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	66621	BUILDING ID:	1121V
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mitch Kurka		
SCHOOL NAME:	Youth Connection - Olive Harvey Middle College High School	INSPECTION DATE:	7/18/2024		
ADDRESS:	10001 Woodlawn	IDPH LICENSE NO:	100-20837		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05A		
MATERIAL DESCRIPTION:	4" Light Brown Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW	
MATERIAL LOCATION:	L109 - L114	
MATERIAL QUANTITY:	440	MATERIAL UNITS: LF
DAMAGE QUANTITY:	DAMAGE UNITS: LF	
COMMENTS:		

Inspector's Signature: \_\_\_\_\_ Date: 07/18/2024

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>66621</b>	BUILDING ID:	<b>1121V</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Randy Livingston</b>		
SCHOOL NAME:	<b>Youth Connection - Olive Harvey Middle College High School</b>	REVIEW DATE:	<b>7/24/2024</b>		
ADDRESS:	<b>10001 Woodlawn</b>	IDPH LICENSE NO:	<b>100-20837</b>		

---

HOMOGENEOUS AREA: **05A**

MATERIAL DESCRIPTION: **4" Light Brown Baseboard Mastic**

MATERIAL LOCATION: **L109 - L114**

MATERIAL QUANTITY: **440** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/24/2024**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	66621	BUIDLING ID:	1121V
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mitch Kurka		
SCHOOL NAME:	Youth Connection - Olive Harvey Middle College High School	INSPECTION DATE:	7/18/2024		
ADDRESS:	10001 Woodlawn	IDPH LICENSE NO:	100-20837		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06		
MATERIAL DESCRIPTION:	4" Dark Brown Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **L104 and L105**

MATERIAL QUANTITY: **480** MATERIAL UNITS: **LF**

DAMAGE QUANTITY:  DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

Date: **07/18/2024**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>66621</b>	BUILDING ID:	<b>1121V</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Randy Livingston</b>		
SCHOOL NAME:	<b>Youth Connection - Olive Harvey Middle College High School</b>	REVIEW DATE:	<b>7/24/2024</b>		
ADDRESS:	<b>10001 Woodlawn</b>	IDPH LICENSE NO:	<b>100-20837</b>		

---

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **4" Dark Brown Baseboard**

MATERIAL LOCATION: **L104 and L105**

MATERIAL QUANTITY: **480** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/24/2024**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA RE/INSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	66621	BUIDLING ID:	1121V
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mitch Kurka		
SCHOOL NAME:	Youth Connection - Olive Harvey Middle College High School	INSPECTION DATE:	7/18/2024		
ADDRESS:	10001 Woodlawn	IDPH LICENSE NO:	100-20837		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06A		
MATERIAL DESCRIPTION:	4" Dark Brown Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW	
MATERIAL LOCATION:	L104 and L105	
MATERIAL QUANTITY:	480	MATERIAL UNITS: LF
DAMAGE QUANTITY:	DAMAGE UNITS: LF	
COMMENTS:		

Inspector's Signature: \_\_\_\_\_ Date: 07/18/2024

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>66621</b>	BUILDING ID:	<b>1121V</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Randy Livingston</b>		
SCHOOL NAME:	<b>Youth Connection - Olive Harvey Middle College High School</b>	REVIEW DATE:	<b>7/24/2024</b>		
ADDRESS:	<b>10001 Woodlawn</b>	IDPH LICENSE NO:	<b>100-20837</b>		

---

HOMOGENEOUS AREA: **06A**

MATERIAL DESCRIPTION: **4" Dark Brown Baseboard Mastic**

MATERIAL LOCATION: **L104 and L105**

MATERIAL QUANTITY: **480** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/24/2024**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA RE/INSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	66621	BUIDLING ID:	1121V
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mitch Kurka		
SCHOOL NAME:	Youth Connection - Olive Harvey Middle College High School	INSPECTION DATE:	7/18/2024		
ADDRESS:	10001 Woodlawn	IDPH LICENSE NO:	100-20837		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07		
MATERIAL DESCRIPTION:	Brown & White Specked Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Corridors**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:

Date: **07/18/2024**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>66621</b>	BUILDING ID:	<b>1121V</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Randy Livingston</b>		
SCHOOL NAME:	<b>Youth Connection - Olive Harvey Middle College High School</b>	REVIEW DATE:	<b>7/24/2024</b>		
ADDRESS:	<b>10001 Woodlawn</b>	IDPH LICENSE NO:	<b>100-20837</b>		

---

HOMOGENEOUS AREA: **07**

MATERIAL DESCRIPTION: **Brown & White Speckled Terrazzo**

MATERIAL LOCATION: **Corridors**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/24/2024**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>66621</b>	BUIDLING ID:	<b>1121V</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mitch Kurka</b>		
SCHOOL NAME:	<b>Youth Connection - Olive Harvey Middle College High School</b>		INSPECTION DATE:	<b>7/18/2024</b>	
ADDRESS:	<b>10001 Woodlawn</b>		IDPH LICENSE NO:	<b>100-20837</b>	

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>08</b>		
MATERIAL DESCRIPTION:	<b>5'x5' Ceiling Panels</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Corridor Ceilings**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:

Date: **07/18/2024**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>66621</b>	BUILDING ID:	<b>1121V</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Randy Livingston</b>		
SCHOOL NAME:	<b>Youth Connection - Olive Harvey Middle College High School</b>	REVIEW DATE:	<b>7/24/2024</b>		
ADDRESS:	<b>10001 Woodlawn</b>	IDPH LICENSE NO:	<b>100-20837</b>		

---

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **5'x5' Ceiling Panels**

MATERIAL LOCATION: **Corridor Ceilings**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/24/2024**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	66621	BUIDLING ID:	1121V
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mitch Kurka		
SCHOOL NAME:	Youth Connection - Olive Harvey Middle College High School	INSPECTION DATE:	7/18/2024		
ADDRESS:	10001 Woodlawn	IDPH LICENSE NO:	100-20837		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09		
MATERIAL DESCRIPTION:	Brown Mosaic Ceramic Tile Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Men's and Women's Bathrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **07/18/2024**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>66621</b>	BUILDING ID:	<b>1121V</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Randy Livingston</b>		
SCHOOL NAME:	<b>Youth Connection - Olive Harvey Middle College High School</b>	REVIEW DATE:	<b>7/24/2024</b>		
ADDRESS:	<b>10001 Woodlawn</b>	IDPH LICENSE NO:	<b>100-20837</b>		

---

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Grout**

MATERIAL LOCATION: **Men's and Women's Bathrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/24/2024**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	66621	BUILDING ID:	1121V
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mitch Kurka		
SCHOOL NAME:	Youth Connection - Olive Harvey Middle College High School	INSPECTION DATE:	7/18/2024		
ADDRESS:	10001 Woodlawn	IDPH LICENSE NO:	100-20837		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09A		
MATERIAL DESCRIPTION:	Brown Mosaic Ceramic Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Men's and Women's Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **07/18/2024**

# Chicago Public Schools

**Carnow, Conibear and Associates**  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>66621</b>	BUIDLING ID:	<b>1121V</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:			<b>Randy Livingston</b>
SCHOOL NAME:	<b>Youth Connection - Olive Harvey Middle College High School</b>	REVIEW DATE:	<b>7/24/2024</b>		
ADDRESS:	<b>10001 Woodlawn</b>	IDPH LICENSE NO:	<b>100-20837</b>		

**HOMOGENEOUS AREA: 09A**

MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Mastic**

**MATERIAL LOCATION: Men's and Women's Bathroom**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: **0**      DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Comments:

Management Planner's Signature:

Randolph Livingston

Date: 07/24/2024

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA RE/INSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	66621	BUILDING ID:	1121V
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mitch Kurka		
SCHOOL NAME:	Youth Connection - Olive Harvey Middle College High School	INSPECTION DATE:	7/18/2024		
ADDRESS:	10001 Woodlawn	IDPH LICENSE NO:	100-20837		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	2'x4' White Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **All Rooms Throughout School & Corridors**

MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:

Date: **07/18/2024**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>66621</b>	BUILDING ID:	<b>1121V</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Randy Livingston</b>		
SCHOOL NAME:	<b>Youth Connection - Olive Harvey Middle College High School</b>	REVIEW DATE:	<b>7/24/2024</b>		
ADDRESS:	<b>10001 Woodlawn</b>	IDPH LICENSE NO:	<b>100-20837</b>		

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **2'x4' White Ceiling Tile**

MATERIAL LOCATION: **All Rooms Throughout School & Corridors**

MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/24/2024**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	66621	BUILDING ID:	1121V
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mitch Kurka		
SCHOOL NAME:	Youth Connection - Olive Harvey Middle College High School	INSPECTION DATE:	7/18/2024		
ADDRESS:	10001 Woodlawn	IDPH LICENSE NO:	100-20837		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: BB-1

MATERIAL DESCRIPTION: 4" Dark Gray Vinyl Baseboard

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Building 7- Rooms 7A-7L, 706A, 707, 708

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/18/2024

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>66621</b>	BUILDING ID:	<b>1121V</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Randy Livingston</b>		
SCHOOL NAME:	<b>Youth Connection - Olive Harvey Middle College High School</b>	REVIEW DATE:	<b>7/24/2024</b>		
ADDRESS:	<b>10001 Woodlawn</b>	IDPH LICENSE NO:	<b>100-20837</b>		

---

HOMOGENEOUS AREA: **BB-1**

MATERIAL DESCRIPTION: **4" Dark Gray Vinyl Baseboard**

MATERIAL LOCATION: **Building 7- Rooms 7A-7L, 706A, 707, 708**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/24/2024**

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2025 AHERA REINSPECTION***

## APPENDIX B

---

### Inspector and Management Planner Licenses



7233 S. Adams Street | Willowbrook, IL 60527  
(630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2022



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

## Randolph Livingston

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: MPR2210113266

A handwritten signature in black ink that reads "Kathy DeSalvo".

Kathy DeSalvo, Director



ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
**IDPH**  
PROTECTING HEALTH. IMPROVING LIVES.

## ASBESTOS PROFESSIONAL LICENSE


ID NUMBER  
100 - 01934

ISSUED  
4/5/2022

EXPIRES  
05/15/2023

**RANDOLPH LIVINGSTON**  
9549 S. EUCLID AVE  
CHICAGO, IL 60617

Environmental Health



### ENDORSEMENTS

### TC EXPIRES

INSPECTOR

2/9/2023

MANAGEMENT PLANNER

10/5/2022

PROJECT MANAGER

7/22/2022

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois

Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.

7233 S. Adams Street | Willowbrook, IL 60527  
(630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2022



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

## Randolph Livingston

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/9/2022

Exam Date: 2/9/2022

Expiration Date: 2/9/2023

Certificate Number: BIR2202090433

Kathy DeSalvo, Director

## APPENDIX C

---

### **Laboratory Accreditations**

## APPENDIX D

---

### Laboratory Results

## APPENDIX E

---

### Chain of Custody Forms

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>	Loc	Localized
	Dist	Distributed