

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2233
SCHOOL NAME: Guggenheim School
ADDRESS OF SCHOOL: 7141 S. Morgan
CITY: Chicago, IL, 60621

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/22/2010

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 5/9/2013 ENROLLMENT 0
IDPH INSPECTOR LICENSE NUMBER: 100-18099
IDPH LICENSED INSPECTOR NAME (Please Print): Rondell Adams
IDPH MP LICENSE NUMBER: 100-05171
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Stephen Diblik

DESIGNATED PERSON (Please Print): Ms. Lynn Crivello PHONE: (773) 553-3113



5/9/2013

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Guggenheim School

7141 S. Morgan
Chicago, IL, 60621

Unit: 26311
Building ID: 7050

IDPH ID Number: 14-016-2990-2233

REPORT DATE:

Thursday, May 09, 2013

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

May 2, 2013

Mr. R. Kent Cook
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2013 Three-Year Reinspections

Dear Mr. Cook:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3,4,5 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 26311 Region: 05 IDPH ID: 14-016-2990-2233

School: Guggenheim School Building ID: 7050

Address: 7141 S. Morgan
Chicago, IL, 60621

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 5/9/2013

Inspector: Rondell Adams Inspector IDPH License: 100-18099
Management Planner: Stephen Diblik Management Planner IDPH License: 100-05171

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Stephen Diblik
100-05171

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: May 02, 2013

RE: Guggenheim School, Unit 26311
7141 S. Morgan
Chicago, IL, 60621

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2013 asbestos three year re-inspection has been completed at Guggenheim School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Guggenheim School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Ms. Lynn Crivello, the designated Local Education Authority's Designated Person at (773) 553-3113 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Guggenheim School Unit: 26311 Region: 05
Address: 7141 S. Morgan Chicago, IL, 60621
IDPH ID: 14-016-2990-2233 Building ID: 7050
Contact: Phone:

2. Description of Facility

Original Construction: 1965 Additional Construction:
Total Square Footage: 37800 No of Floors: 1
Current Occupancy: 0

3. LEA Designated Person

Contact: Ms. Lynn Crivello Phone: (773) 553-3113
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603


4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Dan Juneau
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Rondell Adams


Inspector IDPH license # 100-18099


Signature:
Date: 5/2/2013

6. Management Planner

Management Planner Name: Stephen Diblik

Management Planner IDPH license # 100-05171


Signature:
Date: 5/9/2013

7. Review Date: 5/9/2013

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.


Signature:

Date: 5/9/2013

Name: Ms. Lynn Crivello

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Guggenheim School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 7050:

02	12x12 ceiling tiles
03A	hard plaster White coat
03B	Hard Plaster
05A	12x12 taupe VAT
05B	12x12 crème VAT
05C	12x12 pink VAT
05D	12x12 white VAT
05E	12x12 beige VAT
05F	12x12 pink speckled VAT

07	spray-on acoustic plaster
12	drywall
13	vibration isolators
15F	12x12 pink speckled VAT mastic
16	12x12 Acoustic ceiling tile mastic
17	vault door lining
D-2	hot water holding tank insulation
FTM-2	9x9 taupe vt mastic
G	fiberglass joints & elbows

B. The following new homogenous areas have been identified for Building 7050:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

02	12x12 ceiling tiles
03A	hard plaster White coat
03B	Hard Plaster
05A	12x12 taupe VAT
05B	12x12 crème VAT
05C	12x12 pink VAT
05D	12x12 white VAT
05E	12x12 beige VAT
05F	12x12 pink speckled VAT
09	vinyl baseboard mastic
10	firebrick
11	fire doors
12	drywall
13	vibration isolators
14	drywall compound
15F	12x12 pink speckled VAT matic
16	12x12 Acoustic ceiling tile mastic
18	Linoleum
19	Linoleum mastic
47	ceiling tile
48	12"x12" White w/Light Brown Floor Tile
48M	12"x12" White w/Light Brown Floor Tile Mastic
49	Redd and Tan Terrazzo
CM-1	brown carpet
FT-1	12x12 black floor tile
FTM-1	12x12 black mastic
FTM-2	9x9 taupe vt mastic

The following areas were deemed to be inaccessible:

03A	hard plaster White coat
03B	Hard Plaster
19	Linoleum mastic
48M	12"x12" White w/Light Brown Floor Tile Mastic
D-1	heat exchanger tank insulation
D-2	hot water holding tank insulation
FTM-1	12x12 black mastic
FTM-2	9x9 taupe vt mastic
G	fiberglass joints & elbows

Materials were also listed as "assumed" if they were in good condition and sampling was not

conducted to avoid damage.

This reinspection was conducted by Rondell Adams, IDPH License # 100-18099. The Management Plan was updated by Stephen Diblik, IDPH License # 100-05171. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Guggenheim School Building 7050 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Guggenheim School Unit 26311 Building ID 7050

Address 7141 S. Morgan Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
02	12x12 ceiling tiles	10,000	SF	library, lunchroom, corridors	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
03A	hard plaster White coat	1,500	SF	boiler room ceiling	ASSUMED	SURFACE	N	NONE	0		Yes	ACBM with the potential for damage		LOW
03B	Hard Plaster	60,000	SF	Throughout	ASSUMED	SURFACE	N	NONE	0		Yes	ACBM with potential for significant damage		LOW
04	9x9 VAT	200	SF	2nd floor storage, 2nd floor teachers toilet	CHR	MISC	N	DIST	45		No	ACBM with the potential for damage	3	MODERATE
05A	12x12 taupe VAT	7,000	SF	janitor's closet at north hall corridor, corridors & classrooms, main office	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
05B	12x12 crème VAT	7,000	SF	janitor's closet at north hall corridor, corridors & classrooms, main office	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
05C	12x12 pink VAT	600	SF	state pre-K room 116	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
05D	12x12 white VAT	600	SF	state pre-K room 116	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
05E	12x12 beige VAT	2,250	SF	2nd floor corridor	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
05F	12x12 pink speckled VAT	450	SF	kitchen	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
07	spray-on acoustic plaster	18,900	SF	classrooms throughout BLDG, gym	CHR	SURFACE	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
09	vinyl baseboard mastic	2,000	LF	throughout building (no baseboard or mastic was observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	firebrick			boiler room - incinerator (incinerator disabled)	ASSUMED	MISC								
11	fire doors	4	EA	throughout building (doors are sealed, interior inaccessible)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	drywall	640	SF	library & kitchen	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
13	vibration isolators	10	SF	gym fan room	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the		LOW

Chicago Public Schools

School Guggenheim School Unit 26311 Building ID 7050

Address 7141 S. Morgan Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
14	drywall compound	640	SF	lunchroom & kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15A	12x12 taupe VAT mastic	7,000	SF	corridors & classrooms, main office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15B	12x12 crème VAT mastic	7,000	SF	corridors & classrooms, main office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15C	12x12 pink VAT mastic	600	SF	State pre-K room 116	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15D	12x12 white VAT mastic	600	SF	State pre-K, room 116	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15E	12x12 beige VAT mastic	2,250	SF	2nd floor corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15F	12x12 pink speckled VAT mastic	450	SF	kitchen	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
16	12x12 Acoustic ceiling tile mastic	10,000	SF	libray, lunch room, corridors	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
17	vault door lining	24	SF	school office	CHR	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
18	Linoleum	4,600	SF	Gym and lunchroom and library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Linoleum mastic	4,600	SF	Gym and lunchroom and library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	12x12 beige floor tile mastic (1959)	4,050	SF	classroom 124, music room, room 220, 222	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	ceiling tile	2,600	SF	basement (music room)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	12"x12" White w/Light Brown Floor Tile	75	SF	Janitors Closet by Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48M	12"x12" White w/Light Brown Floor Tile Mastic	75	SF	Janitors Closet By Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	Redd and Tan Terrazzo	1,200	SF	Entrance and Stairways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
CM-1	brown carpet	570	SF	Principal's office, corridor, main office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
D-1	heat exchanger tank insulation	45	SF	boiler room	AMO	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
D-2	hot water holding tank insulation	145	SF	boiler room	AMO	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable		LOW

Chicago Public Schools

School Guggenheim School Unit 26311 Building ID 7050

Address 7141 S. Morgan Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												suspect ACBM		
FT-1	12x12 black floor tile	250	SF	2nd floor ladies toilet, room 116 toilet, 1st floor staff toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-1	12x12 black mastic	250	SF	2nd floor ladies toilet, rm 116 toilet, 1st floor staff toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-2	9x9 taupe vt mastic	45	SF	vault, room 116 closet	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
G	fiberglass joints & elbows	85	LF	boiler room & crawl space	AMO	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Guggenheim School Unit 26311 Building ID 7050

Address 7141 S. Morgan Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 5/2/2013
Inspector Name Rondell Adams
100-18099 5/15/2014
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
02	
03A	
03B	
04	
05A	
05B	
05C	
05D	
05E	
05F	
07	
09	
10	Material Not Observed 2013
11	
12	
13	
14	
15A	
15B	
15C	
15D	
15E	
15F	
16	

Chicago Public Schools

School Guggenheim School Unit 26311 Building ID 7050

Address 7141 S. Morgan Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
17	
18	
19	
33	
47	
48	
48M	
49	
CM-1	
D-1	
D-2	
FT-1	
FTM-1	
FTM-2	
G	

Table II

Management Planner's Review

Chicago Public Schools

School Guggenheim School

Unit 26311

Building ID 7050

Address 7141 S. Morgan

Chicago, IL, 60621

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
02	12x12 ceiling tiles	10,000	SF	library, lunchroom, corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
03A	hard plaster White coat	1,500	SF	boiler room ceiling	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
03B	Hard Plaster	60,000	SF	Throughout	Assumed	SURFACE	No	0	SF	5 ACBM with potential for significant damage	Operations and Maintenance
04	9x9 VAT	200	SF	2nd floor storage, 2nd floor teachers toilet	Chrysotile	MISC	No	45	SF	6 ACBM with the potential for damage	Repair
05A	12x12 taupe VAT	7,000	SF	janitor's closet at north hall corridor, corridors & classrooms, main office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
05B	12x12 crème VAT	7,000	SF	janitor's closet at north hall corridor, corridors & classrooms, main office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
05C	12x12 pink VAT	600	SF	state pre-K room 116	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
05D	12x12 white VAT	600	SF	state pre-K room 116	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
05E	12x12 beige VAT	2,250	SF	2nd floor corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
05F	12x12 pink speckled VAT	450	SF	kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
07	spray-on acoustic plaster	18,900	SF	classrooms throughout BLDG, gym	Chrysotile	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
09	vinyl baseboard mastic	2,000	LF	throughout building (no baseboard or mastic was observed)	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
10	firebrick			boiler room - incinerator (incinerator disabled)	Assumed	MISC					
11	fire doors	4	EA	throughout building (doors are sealed, interior inaccessible)	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Operations and Maintenance
12	drywall	640	SF	library & kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
13	vibration isolators	10	SF	gym fan room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
14	drywall compound	640	SF	lunchroom & kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
15A	12x12 taupe VAT mastic	7,000	SF	corridors & classrooms, main office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
15B	12x12 crème VAT mastic	7,000	SF	corridors & classrooms, main office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
15C	12x12 pink VAT mastic	600	SF	State pre-K room 116	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
15D	12x12 white VAT mastic	600	SF	State pre-K, room 116	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
15E	12x12 beige VAT mastic	2,250	SF	2nd floor corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
15F	12x12 pink speckled VAT matic	450	SF	kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
16	12x12 Acoustic ceiling tile mastic	10,000	SF	libray, lunch room, corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
17	vault door lining	24	SF	school office	Chrysotile	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
18	Linoleum	4,600	SF	Gym and lunchroom and library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School Guggenheim School

Unit 26311

Building ID 7050

Address 7141 S. Morgan

Chicago, IL, 60621

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
19	Linoleum mastic	4,600	SF	Gym and lunchroom and library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
33	12x12 beige floor tile mastic (1959)	4,050	SF	classroom 124, music room, room 220, 222	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
47	ceiling tile	2,600	SF	basement (music room)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
48	12"x12" White w/Light Brown Floor Tile	75	SF	Janitors Closet by Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
48M	12"x12" White w/Light Brown Floor Tile Mastic	75	SF	Janitors Closet By Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
49	Redd and Tan Terrazzo	1,200	SF	Entrance and Stairways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
CM-1	brown carpet	570	SF	Principal's office, corridor, main office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
D-1	heat exchanger tank insulation	45	SF	boiler room	Amosite	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
D-2	hot water holding tank insulation	145	SF	boiler room	Amosite	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
FT-1	12x12 black floor tile	250	SF	2nd floor ladies toilet, room 116 toilet, 1st floor staff toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FTM-1	12x12 black mastic	250	SF	2nd floor ladies toilet, rm 116 toilet, 1st floor staff toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FTM-2	9x9 taupe vt mastic	45	SF	vault, room 116 closet	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
G	fiberglass joints & elbows	85	LF	boiler room & crawl space	Amosite	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance

Chicago Public Schools

School Guggenheim School
Address 7141 S. Morgan

Unit 26311
 Chicago, IL, 60621

Building ID 7050
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	5/9/2013
Manager Planner Name	Stephen Diblik
100-05171	5/15/2013
Manager IDPH License No/Expiration	

HA Number	Management Comments
02	
03A	
03B	
04	Repair damaged material and continue O&M
05A	
05B	
05C	
05D	
05E	
05F	
07	
09	
10	
11	
12	
13	
14	
15A	

Chicago Public Schools

School Guggenheim School
Address 7141 S. Morgan

Unit 26311
 Chicago, IL, 60621

Building ID 7050
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
15B	
15C	
15D	
15E	
15F	
16	
17	
18	
19	
33	
47	
48	
48M	
49	
CM-1	
D-1	
D-2	
FT-1	
FTM-1	
FTM-2	
G	

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **12x12 ceiling tiles**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **library, lunchroom, corridors**

MATERIAL QUANTITY: **10000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **12x12 ceiling tiles**
MATERIAL LOCATION: **library, lunchroom, corridors**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03A**
MATERIAL DESCRIPTION: **hard plaster White coat**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **boiler room ceiling**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUILDING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **03A**
MATERIAL DESCRIPTION: **hard plaster White coat**
MATERIAL LOCATION: **boiler room ceiling**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03B**
MATERIAL DESCRIPTION: **Hard Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **5**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout**
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 05/02/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **03B**
MATERIAL DESCRIPTION: **Hard Plaster**
MATERIAL LOCATION: **Throughout**
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 05/09/2013

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **9x9 VAT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **2nd floor storage, 2nd floor teachers toilet**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **200** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **9x9 VAT**
MATERIAL LOCATION: **2nd floor storage, 2nd floor teachers toilet**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **45** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Repair damaged material and continue O&M

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05A**
MATERIAL DESCRIPTION: **12x12 taupe VAT**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **janitor's closet at north hall corridor, corridors & classrooms, main office**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **05A**
MATERIAL DESCRIPTION: **12x12 taupe VAT**
MATERIAL LOCATION: **janitor's closet at north hall corridor, corridors & classrooms, main office**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05B**
MATERIAL DESCRIPTION: **12x12 crème VAT**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **janitor's closet at north hall corridor, corridors & classrooms, main office**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 05/02/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **05B**
MATERIAL DESCRIPTION: **12x12 crème VAT**
MATERIAL LOCATION: **janitor's closet at north hall corridor, corridors & classrooms, main office**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05C**
MATERIAL DESCRIPTION: **12x12 pink VAT**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **state pre-K room 116**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **05C**
MATERIAL DESCRIPTION: **12x12 pink VAT**
MATERIAL LOCATION: **state pre-K room 116**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05D**
MATERIAL DESCRIPTION: **12x12 white VAT**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **state pre-K room 116**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **05D**
MATERIAL DESCRIPTION: **12x12 white VAT**
MATERIAL LOCATION: **state pre-K room 116**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05E**
MATERIAL DESCRIPTION: **12x12 beige VAT**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd floor corridor**
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **05E**
MATERIAL DESCRIPTION: **12x12 beige VAT**
MATERIAL LOCATION: **2nd floor corridor**
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05F**
MATERIAL DESCRIPTION: **12x12 pink speckled VAT**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **kitchen**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **05F**
MATERIAL DESCRIPTION: **12x12 pink speckled VAT**
MATERIAL LOCATION: **kitchen**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **spray-on acoustic plaster**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **classrooms throughout BLDG, gym**
MATERIAL QUANTITY: **18900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **spray-on acoustic plaster**
MATERIAL LOCATION: **classrooms throughout BLDG, gym**
MATERIAL QUANTITY: **18900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **vinyl baseboard mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **throughout building (no baseboard or mastic was observed)**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 05/02/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **vinyl baseboard mastic**
MATERIAL LOCATION: **throughout building (no baseboard or mastic was observed)**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **firebrick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **boiler room - incinerator (incinerator disabled)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material Not Observed 2013**

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **firebrick**

MATERIAL LOCATION: **boiler room - incinerator (incinerator disabled)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 05/09/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **fire doors**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **throughout building (doors are sealed, interior inaccessible)**
MATERIAL QUANTITY: **4** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____



Date: 05/02/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **fire doors**
MATERIAL LOCATION: **throughout building (doors are sealed, interior inaccessible)**
MATERIAL QUANTITY: **4** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **library & kitchen**
MATERIAL QUANTITY: **640** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **drywall**
MATERIAL LOCATION: **library & kitchen**
MATERIAL QUANTITY: **640** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 05/09/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **vibration isolators**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **gym fan room**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **vibration isolators**
MATERIAL LOCATION: **gym fan room**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 05/09/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **drywall compound**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **lunchroom & kitchen**
MATERIAL QUANTITY: **640** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **drywall compound**
MATERIAL LOCATION: **lunchroom & kitchen**
MATERIAL QUANTITY: **640** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15A**
MATERIAL DESCRIPTION: **12x12 taupe VAT mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **corridors & classrooms, main office**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 05/02/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **15A**
MATERIAL DESCRIPTION: **12x12 taupe VAT mastic**
MATERIAL LOCATION: **corridors & classrooms, main office**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15B**
MATERIAL DESCRIPTION: **12x12 crème VAT mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **corridors & classrooms, main office**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **15B**
MATERIAL DESCRIPTION: **12x12 crème VAT mastic**
MATERIAL LOCATION: **corridors & classrooms, main office**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15C**
MATERIAL DESCRIPTION: **12x12 pink VAT mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **State pre-K room 116**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **15C**
MATERIAL DESCRIPTION: **12x12 pink VAT mastic**
MATERIAL LOCATION: **State pre-K room 116**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 05/09/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15D**
MATERIAL DESCRIPTION: **12x12 white VAT mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **State pre-K, room 116**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **15D**
MATERIAL DESCRIPTION: **12x12 white VAT mastic**
MATERIAL LOCATION: **State pre-K, room 116**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15E**
MATERIAL DESCRIPTION: **12x12 beige VAT mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd floor corridor**
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **15E**
MATERIAL DESCRIPTION: **12x12 beige VAT mastic**
MATERIAL LOCATION: **2nd floor corridor**
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15F**
MATERIAL DESCRIPTION: **12x12 pink speckled VAT matic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **kitchen**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **15F**
MATERIAL DESCRIPTION: **12x12 pink speckled VAT matic**
MATERIAL LOCATION: **kitchen**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12x12 Acoustic ceiling tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **libray, lunch room, corridors**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 05/02/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12x12 Acoustic ceiling tile mastic**
MATERIAL LOCATION: **libray, lunch room, corridors**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **vault door lining**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **school office**
MATERIAL QUANTITY: **24** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **vault door lining**
MATERIAL LOCATION: **school office**
MATERIAL QUANTITY: **24** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym and lunchroom and library**
MATERIAL QUANTITY: **4600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Linoleum**
MATERIAL LOCATION: **Gym and lunchroom and library**
MATERIAL QUANTITY: **4600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Linoleum mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym and lunchroom and library**
MATERIAL QUANTITY: **4600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 05/02/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Linoleum mastic**
MATERIAL LOCATION: **Gym and lunchroom and library**
MATERIAL QUANTITY: **4600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **12x12 beige floor tile mastic (1959)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **classroom 124, music room, room 220, 222**

MATERIAL QUANTITY: **4050**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **12x12 beige floor tile mastic (1959)**
MATERIAL LOCATION: **classroom 124, music room, room 220, 222**
MATERIAL QUANTITY: **4050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **basement (music room)**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **ceiling tile**
MATERIAL LOCATION: **basement (music room)**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **12"x12" White w/Light Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Janitors Closet by Boiler Room**

MATERIAL QUANTITY: **75**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **12"x12" White w/Light Brown Floor Tile**
MATERIAL LOCATION: **Janitors Closet by Boiler Room**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48M**
MATERIAL DESCRIPTION: **12"x12" White w/Light Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Janitors Closet By Boiler Room**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **48M**
MATERIAL DESCRIPTION: **12"x12" White w/Light Brown Floor Tile Mastic**
MATERIAL LOCATION: **Janitors Closet By Boiler Room**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 05/09/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Redd and Tan Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Entrance and Stairways**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Redd and Tan Terrazzo**
MATERIAL LOCATION: **Entrance and Stairways**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM-1**
MATERIAL DESCRIPTION: **brown carpet**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Principal's office, corridor, main office**
MATERIAL QUANTITY: **570** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUILDING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **CM-1**
MATERIAL DESCRIPTION: **brown carpet**
MATERIAL LOCATION: **Principal's office, corridor, main office**
MATERIAL QUANTITY: **570** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D-1**
MATERIAL DESCRIPTION: **heat exchanger tank insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **boiler room**
MATERIAL QUANTITY: **45** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUILDING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **D-1**
MATERIAL DESCRIPTION: **heat exchanger tank insulation**
MATERIAL LOCATION: **boiler room**
MATERIAL QUANTITY: **45** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 05/09/2013

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D-2**
MATERIAL DESCRIPTION: **hot water holding tank insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **boiler room**
MATERIAL QUANTITY: **145** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **D-2**
MATERIAL DESCRIPTION: **hot water holding tank insulation**
MATERIAL LOCATION: **boiler room**
MATERIAL QUANTITY: **145** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-1**
MATERIAL DESCRIPTION: **12x12 black floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd floor ladies toilet, room 116 toilet, 1st floor staff toilet**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **FT-1**
MATERIAL DESCRIPTION: **12x12 black floor tile**
MATERIAL LOCATION: **2nd floor ladies toilet, room 116 toilet, 1st floor staff toilet**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 05/09/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-1**
MATERIAL DESCRIPTION: **12x12 black mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd floor ladies toilet, rm 116 toilet, 1st floor staff toilet**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **FTM-1**
MATERIAL DESCRIPTION: **12x12 black mastic**
MATERIAL LOCATION: **2nd floor ladies toilet, rm 116 toilet, 1st floor staff toilet**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-2**
MATERIAL DESCRIPTION: **9x9 taupe vt mastic**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **vault, room 116 closet**
MATERIAL QUANTITY: **45** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/02/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **FTM-2**
MATERIAL DESCRIPTION: **9x9 taupe vt mastic**
MATERIAL LOCATION: **vault, room 116 closet**
MATERIAL QUANTITY: **45** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Rondell Adams**
SCHOOL NAME: **Guggenheim School** INSPECTION DATE: **5/2/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **fiberglass joints & elbows**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **boiler room & crawl space**
MATERIAL QUANTITY: **85** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 05/02/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26311** BUIDLING ID: **7050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Guggenheim School** REVIEW DATE: **5/9/2013**
ADDRESS: **7141 S. Morgan** IDPH LICENSE NO: **100-18099**

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **fiberglass joints & elbows**
MATERIAL LOCATION: **boiler room & crawl space**
MATERIAL QUANTITY: **85** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/09/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 18099

ISSUED
3/4/2013

EXPIRES
05/15/2014

RONDELL ADAMS
1025 TANEY ST
GARY, IN 46404

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

2/27/2014

PROJECT MANAGER
AIR SAMPLING PROFESSIONAL

5/24/2013

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training and Supply, Inc. certifies that

Rondell Adams

has successfully completed the 4 hour Asbestos Building Inspector Refresher Course
and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: BIR1302270758

Exam Date: 2/27/2013

Course Date: 2/27/2013

Expiration Date: 2/27/2014


Kathy DeSalvo, Director

2013



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 18099

ISSUED
3/4/2013

EXPIRES
05/15/2014

RONDELL ADAMS
1025 TANEY ST
GARY, IN 46404

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

2/27/2014

PROJECT MANAGER
AIR SAMPLING PROFESSIONAL

5/24/2013

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training and Supply, Inc. certifies that

Rondell Adams

has successfully completed the 4 hour Asbestos Building Inspector Refresher Course
and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: BIR1302270758

Exam Date: 2/27/2013

Course Date: 2/27/2013

Expiration Date: 2/27/2014


Kathy DeSalvo, Director

2013



Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Steve Diblik

has successfully completed the 4 hour Asbestos Building Inspector Refresher Course and has passed the competency exam with a minimum score of 70%. This course is accredited by the **Illinois Department of Public Health** and the **Indiana Department of Environmental Management** for purposes of accreditation in accordance with EPA 40 CFR763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II. This training course complies with the requirements of TSCA Title II and is accredited by the state of Wisconsin **Department of Health Services** under CH.DHS159, Wisconsin Administration Code.

Asbestos Abatement Building Inspector Refresher

Certificate: BIRWI1301110170

Location: 12304 75th Street Kenosha, WI 53142

Course Date: 1/11/2013

Examination Date: 1/11/2013

Expiration Date: 1/11/2014

Issue Date: 1/11/2013



Duplicate Original

Kathy DeSalvo, Director

2013

Stephen Diblik

Illinois Licensed Asbestos Inspector, Management Planner,
Project Manager and Air Sampling Professional



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 05171

ISSUED
4/4/2012

EXPIRES
05/15/2013

STEPHEN C DIBLIK
300 W. Adams Street, Suite 120
Chicago, IL 60606

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

1/13/2013

MANAGEMENT PLANNER

1/19/2013

PROJECT MANAGER

12/15/2012

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

**CARNOW
CONIBEAR**



Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training and Supply, Inc. certifies that

Stephen Diblik

has successfully completed the 4 hour Asbestos Management Planner Refresher Course
and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department
of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance
with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: MPR1302250732

Exam Date: 2/25/2013

Course Date: 2/25/2013

Expiration Date: 2/25/2014


Kathy DeSalvo
Director

2013

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed