

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-002C  
SCHOOL NAME: Chicago International Charter - Bucktown School  
ADDRESS OF SCHOOL: 2235 N. Hamilton (2132W) 47  
CITY: Chicago, IL, 606473360

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/12/2010

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 3/26/2013 ENROLLMENT 655

IDPH INSPECTOR LICENSE NUMBER: 100-09725

IDPH LICENSED INSPECTOR NAME (Please Print): Patrick Hrycyk

IDPH MP LICENSE NUMBER: 100-09870

IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer

DESIGNATED PERSON (Please Print): Ms. Lynn Crivello PHONE: (773) 553-3113



3/26/2013

*Signature of Designated Person*

*Date*

---

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Chicago International Charter - Bucktown School**

2235 N. Hamilton (2132W) 47  
Chicago, IL, 606473360

Unit: 66071  
Building ID: 4910

IDPH ID Number: 14-016-2990-002C

**REPORT DATE:**

Tuesday, March 26, 2013

**Prepared for:**

**Chicago Public Schools  
125 S. Clark Street  
Chicago, IL 60603**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**



## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: March 04, 2013

RE: Chicago International Charter - Bucktown School, Unit 66071  
2235 N. Hamilton (2132W) 47  
Chicago, IL, 606473360

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2013 asbestos three year re-inspection has been completed at Chicago International Charter - Bucktown School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Chicago International Charter - Bucktown School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Ms. Lynn Crivello, the designated Local Education Authority's Designated Person at (773) 553-3113 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Chicago International Charter - Bucktown School Unit: 66071 Region: 02  
Address: 2235 N. Hamilton (2132W) Chicago, IL, 606473360  
47  
IDPH ID: 14-016-2990-002C Building ID: 4910  
Contact: Phone:

### 2. Description of Facility

Original Construction: Additional Construction:  
Total Square Footage: No of Floors:  
Current Occupancy: 655

### 3. LEA Designated Person

Contact: Ms. Lynn Crivello Phone: (773) 553-3113  
Address: 125 South Clark Street, 17th Floor  
Chicago, IL 60603


### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Dan Juneau  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900 Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Patrick Hrycyk


Inspector IDPH license # 100-09725

Signature:   
Date: 3/4/2013

### 6. Management Planner

Management Planner Name: Todd Huffer


Management Planner IDPH license # 100-09870

Signature:   
Date: 3/26/2013

### 7. Review Date: 3/26/2013

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 3/26/2013

Name: Ms. Lynn Crivello



## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Chicago International Charter - Bucktown School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4910:



B. The following new homogenous areas have been identified for Building 4910:

- 59                      12" x 12" Dark Gray w/ Black Streaks
- 59M                    12" x 12" Dark Gray w/ Black Streaks Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	12" x 12" White w/Grey Specks VFT
02	12" x 12" Black with White Streaks Floor Tile Mastic
03	12" x 12" Light blue w/Specks VFT
04	2" x 12" Light blue w/Specks VFT Mastic
05	12" x 12" Gray VFT
06	12 " x 12" Gray VFT Mastic
07	12" x 12" White w/Black Specks VFT
08	12" x 12" White w/Black Specks VFT Mastic
09	12" x 12" Beige w/Tan Streaks VFT
10	12" x 12" Beige w/Tan Streaks VFT Mastic
13	12" x 12" Tan VFT
14	12" x 12" Tan VFT Mastic
15	VFT under the carpet
16	VFT Mastic
17	2' x 4' White Grooved Ceiling Tile
18	Popcorn Type Plaster Ceiling
19	Hard Coat Plaster
20	Dry wall
21	Drywall Joint Compound
22	Carpet Mastic
23	Pipe Insulation
24	MJP E/V/F on Pipe Insulation
25	12" x 12" White w/Peach & Blue Specks VFT
26	12" x 12" White w/Peach & Blue Specks VFT Mastic
27	Texture Plaster Wall
28	12" x 12" Green VFT
29	12" x 12" Green VFT Mastic
30	12" x 12" Black VFT
31	12" x 12" Black VFT Mastic
32	12" x 12" Blue w/White Specks VFT
33	12" x 12" Blue w/White Specks VFT Mastic
34	12" x 12" White w/Color Spots VFT
35	12" x 12" White w/Color Spots VFT Mastic
36	12"X12" Lt Gray w/Dark Specks Floor Tile
37	12"X12" Lt Gray w/Dark Specks Floor Tile Mastic
38	12"X12" Dk Gray w/Lt Gray Floor Tile
39	12"X12" Dk Gray w/Lt Gray Floor Tile Mastic
40	Light Gray Carpet Adhesive
41	White w/Color Spots Floor Tile
42	White w/Color Spots Floor Tile mastic
43	12"X12" Green Floor Tile
44	12"X12" Green Floor Tile Mastic
45	12"X12" White Floor Tile
46	12"X12" White Floor Tile Mastic

47	12" x 12" Tan and Brown Specks Floor Tile
48	12" x 12" Tan and Brown Specks Floor Tile Mastic
49	9"X9" Brown Floor Tile
50	9"X9" Brown Floor Tile Mastic
51	Gray/Pink Carpet Adhesive
52	RED Ceramic Tile & Grout
53	Red Ceramic Tile Adhesive
54	White Ceramic Tile and Grout
55	White Ceramic Tile Adhesive
56	Brown Ceramic Tile and Grout
57	Brown Ceramic Tile Mastic
58	12" x 12" Black with White Streaks Floor Tile
58M	12" x 12" Black with White Streaks Floor Tile Mastic
59	12" x 12" Dark Gray w/ Black Streaks
59M	12" x 12" Dark Gray w/ Black Streaks Mastic

The following areas were deemed to be inaccessible:

02	12" x 12" Black with White Streaks Floor Tile Mastic
26	12" x 12" White w/Peach & Blue Specks VFT Mastic
33	12" x 12" Blue w/White Specks VFT Mastic
35	12" x 12" White w/Color Spots VFT Mastic
37	12"X12" Lt Gray w/Dark Specks Floor Tile Mastic
39	12"X12" Dk Gray w/Lt Gray Floor Tile Mastic
40	Light Gray Carpet Adhesive
42	White w/Color Spots Floor Tile mastic
44	12"X12" Green Floor Tile Mastic
46	12"X12" White Floor Tile Mastic
48	12" x 12" Tan and Brown Specks Floor Tile Mastic
53	Red Ceramic Tile Adhesive
55	White Ceramic Tile Adhesive
57	Brown Ceramic Tile Mastic
58M	12" x 12" Black with White Streaks Floor Tile Mastic
59M	12" x 12" Dark Gray w/ Black Streaks Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Patrick Hrycyk, IDPH License # 100-09725. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Chicago International Charter - Bucktown School Building 4910 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Chicago International Charter - Bucktown School Unit 66071 Building ID 4910

Address 2235 N. Hamilton (2132W) 47 Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	12" x 12" White w/Grey Specks VFT	2,100	SF	Throughout Building	ASSUMED	MISC		None						Low
02	12" x 12" Black with White Streaks Floor Tile Mastic	1,500	SF	Stage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03	12" x 12" Light blue w/Specks VFT	1,100	SF	Throughout Building	ASSUMED	MISC		None						Low
04	2" x 12" Light blue w/Specks VFT Mastic	1,100	SF	Throughout Building	ASSUMED	MISC		None						Low
05	12" x 12" Gray VFT	480	SF	Room 200	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
06	12" x 12" Gray VFT Mastic	480	SF	Room 200	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	12" x 12" White w/Black Specks VFT	20	SF	2nd Floor Office, MDF Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
08	12" x 12" White w/Black Specks VFT Mastic	20	SF	2nd Floor Office, MDF Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
09	12" x 12" Beige w/Tan Streaks VFT			Stage	ASSUMED	MISC	N	None						
10	12" x 12" Beige w/Tan Streaks VFT Mastic			Stage	ASSUMED	MISC	N	None						Low
11	9" x 9" Tan w/White Streaks VFT			Storage 119 and Vestibule by 119	ABATED	MISC		None						High
12	9" x 9" Tan w/White Streaks VFT Mastic			Storage 119 and Vestibule by Storage 119	ABATED	MISC		None						Low
13	12" x 12" Tan VFT	200	SF	Storage 114	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
14	12" x 12" Tan VFT Mastic	200	SF	Storage 114	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	VFT under the carpet	36,400	SF	Throughout Building	ASSUMED	MISC	N	None						LOW
16	VFT Mastic	36,400	SF	Throughout Building Under Carpet	ASSUMED	MISC	N	None						LOW
17	2' x 4' White Grooved Ceiling Tile	1,800	SF	Throughout	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
18	Popcorn Type Plaster Ceiling	34,600	SF	Throughout	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
19	Hard Coat Plaster	45,000	SF	Throughout Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
20	Dry wall	8,500	SF	Throughout Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
21	Drywall Joint Compound	2,500	SF	Throughout Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

# Chicago Public Schools

School Chicago International Charter - Bucktown School Unit 66071 Building ID 4910

Address 2235 N. Hamilton (2132W) 47 Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
22	Carpet Mastic	36,400	SF	Throughout Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Pipe Insulation	1,400	LF	Throughout Building	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
24	MJP E/V/F on Pipe Insulation	160	LF	Throughout Building	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
25	12" x 12" White w/Peach & Blue Specks VFT	1,400	SF	Basement Serving Area, Basement Kitchen Storage Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	12" x 12" White w/Peach & Blue Specks VFT Mastic	1,400	SF	Basement Serving Area, Basement Kitchen Storage Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	Texture Plaster Wall	3,000	SF	Basement Serving Area, Basement Kitchen Storage, and Lunch Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
28	12" x 12" Green VFT	25	SF	Kitchen	ASSUMED	MISC	N							
29	12" x 12" Green VFT Mastic	25	SF	Kitchen	ASSUMED	MISC	N							
30	12" x 12" Black VFT	20	SF	Kitchen	ASSUMED	MISC	N							
31	12" x 12" Black VFT Mastic	20	SF	Kitchen	ASSUMED	MISC	N							
32	12" x 12" Blue w/White Specks VFT	340	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with potential for significant damage		MODERATE
33	12" x 12" Blue w/White Specks VFT Mastic	250	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with potential for significant damage		LOW
34	12" x 12" White w/Color Spots VFT	700	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with potential for significant damage		LOW
35	12" x 12" White w/Color Spots VFT Mastic	700	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with potential for significant damage		LOW
36	12"X12" Lt Gray w/Dark Specks Floor Tile	88	SF	Room 007	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
37	12"X12" Lt Gray w/Dark Specks Floor Tile Mastic	88	SF	Room 007	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	12"X12" Dk Gray w/Lt Gray Floor Tile	1,052	SF	Rooms 007 and 200	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
39	12"X12" Dk Gray w/Lt Gray Floor Tile Mastic	1,052	SF	Rooms 007 and 200	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	Light Gray Carpet Adhesive	2,820	SF	Rms 316, 309, 3rd Fl Hall, 001, 003, 310, 311, 313	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	White w/Color Spots Floor Tile	3,500	SF	Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the		HIGH

# Chicago Public Schools

School Chicago International Charter - Bucktown School Unit 66071 Building ID 4910

Address 2235 N. Hamilton (2132W) 47 Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
42	White w/Color Spots Floor Tile mastic	3,500	SF	Lunch Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	12"X12" Green Floor Tile	700	SF	Room 207 and all Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
44	12"X12" Green Floor Tile Mastic	700	SF	Room 207 and all Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	12"X12" White Floor Tile	700	SF	Room 207 and all Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
46	12"X12" White Floor Tile Mastic	700	SF	Room 207 and all Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	12" x 12" Tan and Brown Specks Floor Tile	1,680	SF	Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
48	12" x 12" Tan and Brown Specks Floor Tile Mastic	1,680	SF	Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	9"X9" Brown Floor Tile	380	SF	Gym Office, Hall to Gym Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
50	9"X9" Brown Floor Tile Mastic	380	SF	Gym Office, Hall to Gym Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	Gray/Pink Carpet Adhesive	3,620	SF	1st Floor Corridor, Rooms 107, 104, 103	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	RED Ceramic Tile & Grout	1,355	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	Red Ceramic Tile Adhesive	1,355	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	White Ceramic Tile and Grout	150	SF	North South Entrance	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	White Ceramic Tile Adhesive	150	SF	North South Entrance	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	Brown Ceramic Tile and Grout	625	SF	Main Entrance	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	Brown Ceramic Tile Mastic	625	SF	Main Entrance	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	12" x 12" Black with White Streaks Floor Tile	1,500	SF	Stage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
58M	12" x 12" Black with White Streaks Floor Tile Mastic	1,500	SF	Stage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	12" x 12" Dark Gray w/ Black Streaks	2,250	SF	Rooms 312, 314, 316	ASSUMED	MISC	N	NONE	0			ACBM with potential for significant damage		MODERATE
59M	12" x 12" Dark Gray w/ Black Streaks Mastic	2,250	SF	Rooms 312, 314, 316	ASSUMED	MISC	N	NONE	0			ACBM with potential for significant damage		LOW



# Chicago Public Schools

School Chicago International Charter - Bucktown School Unit 66071 Building ID 4910  
Address 2235 N. Hamilton (2132W) 47 Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>3/4/2013</b>
Inspector Name <b>Patrick Hrycyk</b>
<b>100-09725</b> <b>5/15/2013</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
01	Material Not Observed 2013- May be under carpet
02	
03	Material Not Observed 2013- May be under carpet
04	Material Not Observed 2013- May be under carpet
05	
06	
07	
08	
09	Material Not Observed 2013- Only HA58
10	Material Not Observed 2013- Only HA58M
11	Abated per engineer- no abatement records
12	Abated per engineer- no abatement records
13	
14	
15	Material Not Observed 2013
16	Material Not Observed 2013
17	
18	
19	
20	
21	
22	
23	
24	

# Chicago Public Schools

**School** Chicago International Charter - Bucktown School **Unit** 66071 **Building ID** 4910  
**Address** 2235 N. Hamilton (2132W) 47 **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
25	
26	
27	
28	Material Not Observed 2013- No Abatement Records
29	Material Not Observed 2013- No Abatement Records
30	Material Not Observed 2013- No Abatement Records
31	Material Not Observed 2013- No Abatement Records
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	

# Chicago Public Schools

**School** Chicago International Charter - Bucktown School **Unit** 66071 **Building ID** 4910

**Address** 2235 N. Hamilton (2132W) 47 **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
54	
55	
56	
57	
58	
58M	
59	
59M	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Chicago International  
Charter - Bucktown School

Unit 66071

Building ID 4910

Address 2235 N. Hamilton (2132W) 47

Chicago, IL, 606473360

Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	12" x 12" White w/Grey Specks VFT	2,100	SF	Throughout Building	Assumed	MISC			SF		Operations and Maintenance
02	12" x 12" Black with White Streaks Floor Tile Mastic	1,500	SF	Stage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
03	12" x 12" Light blue w/Specks VFT	1,100	SF	Throughout Building	Assumed	MISC			SF		Operations and Maintenance
04	2" x 12" Light blue w/Specks VFT Mastic	1,100	SF	Throughout Building	Assumed	MISC			SF		Operations and Maintenance
05	12" x 12" Gray VFT	480	SF	Room 200	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
06	12" x 12" Gray VFT Mastic	480	SF	Room 200	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
07	12" x 12" White w/Black Specks VFT	20	SF	2nd Floor Office, MDF Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
08	12" x 12" White w/Black Specks VFT Mastic	20	SF	2nd Floor Office, MDF Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
09	12" x 12" Beige w/Tan Streaks VFT			Stage	Assumed	MISC	No				
10	12" x 12" Beige w/Tan Streaks VFT Mastic			Stage	Assumed	MISC	No				
11	9" x 9" Tan w/White Streaks VFT			Storage 119 and Vestibule by 119	Abated	MISC					
12	9" x 9" Tan w/White Streaks VFT Mastic			Storage 119 and Vestibule by Storage 119	Abated	MISC					
13	12" x 12" Tan VFT	200	SF	Storage 114	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
14	12" x 12" Tan VFT Mastic	200	SF	Storage 114	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
15	VFT under the carpet	36,400	SF	Throughout Building	Assumed	MISC	No		SF		Operations and Maintenance
16	VFT Mastic	36,400	SF	Throughout Building Under Carpet	Assumed	MISC	No		SF		Operations and Maintenance
17	2' x 4' White Grooved Ceiling Tile	1,800	SF	Throughout	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
18	Popcorn Type Plaster Ceiling	34,600	SF	Throughout	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
19	Hard Coat Plaster	45,000	SF	Throughout Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
20	Dry wall	8,500	SF	Throughout Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
21	Drywall Joint Compound	2,500	SF	Throughout Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
22	Carpet Mastic	36,400	SF	Throughout Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
23	Pipe Insulation	1,400	LF	Throughout Building	Assumed	MISC	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
24	MJP E/V/F on Pipe Insulation	160	LF	Throughout Building	Assumed	MISC	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
25	12" x 12" White w/Peach & Blue Specks VFT	1,400	SF	Basement Serving Area, Basement Kitchen Storage Area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
26	12" x 12" White w/Peach & Blue Specks VFT Mastic	1,400	SF	Basement Serving Area, Basement Kitchen Storage Area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
27	Texture Plaster Wall	3,000	SF	Basement Serving Area, Basement	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

# Chicago Public Schools

School Chicago International  
Charter - Bucktown School

Unit 66071

Building ID 4910

Address 2235 N. Hamilton (2132W) 47

Chicago, IL, 606473360

Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Kitchen Storage, and Lunch Room							
28	12" x 12" Green VFT	25	SF	Kitchen	Assumed	MISC	No		SF		
29	12" x 12" Green VFT Mastic	25	SF	Kitchen	Assumed	MISC	No		SF		
30	12" x 12" Black VFT	20	SF	Kitchen	Assumed	MISC	No		SF		
31	12" x 12" Black VFT Mastic	20	SF	Kitchen	Assumed	MISC	No		SF		
32	12" x 12" Blue w/White Specks VFT	340	SF	Kitchen	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Operations and Maintenance
33	12" x 12" Blue w/White Specks VFT Mastic	250	SF	Kitchen	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Operations and Maintenance
34	12" x 12" White w/Color Spots VFT	700	SF	Kitchen	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Operations and Maintenance
35	12" x 12" White w/Color Spots VFT Mastic	700	SF	Kitchen	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Operations and Maintenance
36	12"X12" Lt Gray w/Dark Specks Floor Tile	88	SF	Room 007	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
37	12"X12" Lt Gray w/Dark Specks Floor Tile Mastic	88	SF	Room 007	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
38	12"X12" Dk Gray w/Lt Gray Floor Tile	1,052	SF	Rooms 007 and 200	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
39	12"X12" Dk Gray w/Lt Gray Floor Tile Mastic	1,052	SF	Rooms 007 and 200	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
40	Light Gray Carpet Adhesive	2,820	SF	Rms 316, 309, 3rd Fl Hall, 001, 003, 310, 311, 313	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
41	White w/Color Spots Floor Tile	3,500	SF	Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
42	White w/Color Spots Floor Tile mastic	3,500	SF	Lunch Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
43	12"X12" Green Floor Tile	700	SF	Room 207 and all Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
44	12"X12" Green Floor Tile Mastic	700	SF	Room 207 and all Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
45	12"X12" White Floor Tile	700	SF	Room 207 and all Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
46	12"X12" White Floor Tile Mastic	700	SF	Room 207 and all Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
47	12" x 12" Tan and Brown Specks Floor Tile	1,680	SF	Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
48	12" x 12" Tan and Brown Specks Floor Tile Mastic	1,680	SF	Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
49	9"X9" Brown Floor Tile	380	SF	Gym Office, Hall to Gym Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
50	9"X9" Brown Floor Tile Mastic	380	SF	Gym Office, Hall to Gym Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
51	Gray/Pink Carpet Adhesive	3,620	SF	1st Floor Corridor, Rooms 107, 104, 103	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
52	RED Ceramic Tile & Grout	1,355	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
53	Red Ceramic Tile Adhesive	1,355	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
54	White Ceramic Tile and Grout	150	SF	North South Entrance	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

# Chicago Public Schools

**School** Chicago International  
Charter - Bucktown School

**Unit** 66071

**Building ID** 4910

**Address** 2235 N. Hamilton (2132W) 47

Chicago, IL, 606473360

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
55	White Ceramic Tile Adhesive	150	SF	North South Entrance	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
56	Brown Ceramic Tile and Grout	625	SF	Main Entrance	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
57	Brown Ceramic Tile Mastic	625	SF	Main Entrance	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
58	12" x 12" Black with White Streaks Floor Tile	1,500	SF	Stage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
58M	12" x 12" Black with White Streaks Floor Tile Mastic	1,500	SF	Stage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
59	12" x 12" Dark Gray w/ Black Streaks	2,250	SF	Rooms 312, 314, 316	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Operations and Maintenance
59M	12" x 12" Dark Gray w/ Black Streaks Mastic	2,250	SF	Rooms 312, 314, 316	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Operations and Maintenance

# Chicago Public Schools

**School** Chicago International  
Charter - Bucktown School

**Unit** 66071

**Building ID** 4910

**Address** 2235 N. Hamilton (2132W) 47

Chicago, IL, 606473360

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

Review Date	3/26/2013
Manager Planner Name	Todd Huffer
100-09870	5/15/2013
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	Material Not Observed. May be under Carpet. Maintain O&M
02	
03	material not observed. May be under Carpet. Maintain O&M
04	material not observed. May be under Carpet. Maintain O&M
05	
06	
07	
08	
09	Material Not Observed. See HA 58
10	Material Not Observed. See HA 58
11	Abated per engineer - no abatement records
12	Abated per engineer - no abatement records
13	
14	
15	material not observed. May be under Carpet. Maintain O&M
16	material not observed. May be under Carpet. Maintain O&M
17	
18	
19	
20	
21	
22	
23	
24	
25	



# Chicago Public Schools

**School** Chicago International  
Charter - Bucktown School

**Unit** 66071

**Building ID** 4910

**Address** 2235 N. Hamilton (2132W) 47

Chicago, IL, 606473360

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
26	
27	
28	material not observed. No abatement records
29	material not observed. No abatement records
30	material not observed. No abatement records
31	material not observed. No abatement records
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	

# Chicago Public Schools

**School** Chicago International  
Charter - Bucktown School

**Unit** 66071

**Building ID** 4910

**Address** 2235 N. Hamilton (2132W) 47

Chicago, IL, 606473360

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
52	
53	
54	
55	
56	
57	
58	
58M	
59	
59M	

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **12" x 12" White w/Grey Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **2100**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed 2013- May be under carpet**

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **12" x 12" White w/Grey Specks VFT**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Material Not Observed. May be under Carpet. Maintain O&M

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **12" x 12" Black with White Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Stage**

MATERIAL QUANTITY: **1500**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **12" x 12" Black with White Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Stage**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **12" x 12" Light blue w/Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **1100**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed 2013- May be under carpet**

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **12" x 12" Light blue w/Specks VFT**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

material not observed. May be under Carpet. Maintain O&M

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **2" x 12" Light blue w/Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **1100**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed 2013- May be under carpet**

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **2" x 12" Light blue w/Specks VFT Mastic**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

material not observed. May be under Carpet. Maintain O&M

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **12" x 12" Gray VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **Room 200**  
MATERIAL QUANTITY: **480** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **12" x 12" Gray VFT**  
MATERIAL LOCATION: **Room 200**  
MATERIAL QUANTITY: **480** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **12 " x 12" Gray VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 200**

MATERIAL QUANTITY: **480**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **12 " x 12" Gray VFT Mastic**  
MATERIAL LOCATION: **Room 200**  
MATERIAL QUANTITY: **480** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **12" x 12" White w/Black Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**

MATERIAL LOCATION: **2nd Floor Office, MDF Room**

MATERIAL QUANTITY: **20**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **12" x 12" White w/Black Specks VFT**  
MATERIAL LOCATION: **2nd Floor Office, MDF Room**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **12" x 12" White w/Black Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**

MATERIAL LOCATION: **2nd Floor Office, MDF Room**

MATERIAL QUANTITY: **20**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **12" x 12" White w/Black Specks VFT Mastic**  
MATERIAL LOCATION: **2nd Floor Office, MDF Room**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/Tan Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Stage**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material Not Observed 2013- Only HA58**

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/Tan Streaks VFT**  
MATERIAL LOCATION: **Stage**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Material Not Observed. See HA 58

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/Tan Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Stage**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material Not Observed 2013- Only HA58M**

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/Tan Streaks VFT Mastic**  
MATERIAL LOCATION: **Stage**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Material Not Observed. See HA 58

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **9" x 9" Tan w/White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **High**


MATERIAL LOCATION: **Storage 119 and Vestibule by 119**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Abated per engineer- no abatement records**

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **9" x 9" Tan w/White Streaks VFT**  
MATERIAL LOCATION: **Storage 119 and Vestibule by 119**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Abated per engineer - no abatement records

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **9" x 9" Tan w/White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**


MATERIAL LOCATION: **Storage 119 and Vestibule by Storage 119**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Abated per engineer- no abatement records**

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **9" x 9" Tan w/White Streaks VFT Mastic**  
MATERIAL LOCATION: **Storage 119 and Vestibule by Storage 119**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Abated per engineer - no abatement records

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **12" x 12" Tan VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **Storage 114**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **12" x 12" Tan VFT**  
MATERIAL LOCATION: **Storage 114**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **12" x 12" Tan VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Storage 114**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **12" x 12" Tan VFT Mastic**  
MATERIAL LOCATION: **Storage 114**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **VFT under the carpet**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **36400**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed 2013**

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **VFT under the carpet**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **36400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

material not observed. May be under Carpet. Maintain O&M

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building Under Carpet**

MATERIAL QUANTITY: **36400**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed 2013**

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **VFT Mastic**  
MATERIAL LOCATION: **Throughout Building Under Carpet**  
MATERIAL QUANTITY: **36400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

material not observed. May be under Carpet. Maintain O&M

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **2' x 4' White Grooved Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **2' x 4' White Grooved Ceiling Tile**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Popcorn Type Plaster Ceiling**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **34600**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Popcorn Type Plaster Ceiling**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **34600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **45000**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **45000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Dry wall**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **8500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Dry wall**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **8500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Drywall Joint Compound**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **2500**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Drywall Joint Compound**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **36400**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **36400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

## Carnow, Conibear and Associates 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **1400**


MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Pipe Insulation**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **MJP E/V/F on Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **160**


MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **MJP E/V/F on Pipe Insulation**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12" x 12" White w/Peach & Blue Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Basement Serving Area, Basement Kitchen Storage Area**

MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12" x 12" White w/Peach & Blue Specks VFT**  
MATERIAL LOCATION: **Basement Serving Area, Basement Kitchen Storage Area**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12" x 12" White w/Peach & Blue Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Basement Serving Area, Basement Kitchen Storage Area**

MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12" x 12" White w/Peach & Blue Specks VFT Mastic**  
MATERIAL LOCATION: **Basement Serving Area, Basement Kitchen Storage Area**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Texture Plaster Wall**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **Basement Serving Area, Basement Kitchen Storage, and Lunch Room**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Texture Plaster Wall**  
MATERIAL LOCATION: **Basement Serving Area, Basement Kitchen Storage, and Lunch Room**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12" x 12" Green VFT**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **25**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed 2013- No Abatement Records**

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12" x 12" Green VFT**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

material not observed. No abatement records

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12" x 12" Green VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **25**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed 2013- No Abatement Records**

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12" x 12" Green VFT Mastic**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

material not observed. No abatement records

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12" x 12" Black VFT**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **20**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed 2013- No Abatement Records**

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12" x 12" Black VFT**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

material not observed. No abatement records

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12" x 12" Black VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **20**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed 2013- No Abatement Records**

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12" x 12" Black VFT Mastic**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

material not observed. No abatement records

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 66071 BUIDLING ID: 4910  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Patrick Hrycyk  
SCHOOL NAME: Chicago International Charter - Bucktown School INSPECTION DATE: 3/4/2013  
ADDRESS: 2235 N. Hamilton (2132W) 47 IDPH LICENSE NO: 100-09725

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32  
MATERIAL DESCRIPTION: 12" x 12" Blue w/White Specks VFT  
HISTORICAL AHERA DAMAGE CATEGORY 5  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE

MATERIAL LOCATION: Kitchen

MATERIAL QUANTITY: 340


MATERIAL UNITS: SF

DAMAGE QUANTITY:

DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:



Date: 03/04/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **12" x 12" Blue w/White Specks VFT**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **340** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **12" x 12" Blue w/White Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **5**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **12" x 12" Blue w/White Specks VFT Mastic**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 66071 BUIDLING ID: 4910  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Patrick Hrycyk  
SCHOOL NAME: Chicago International Charter - Bucktown School INSPECTION DATE: 3/4/2013  
ADDRESS: 2235 N. Hamilton (2132W) 47 IDPH LICENSE NO: 100-09725

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 34  
MATERIAL DESCRIPTION: 12" x 12" White w/Color Spots VFT  
HISTORICAL AHERA DAMAGE CATEGORY 5  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Kitchen  
MATERIAL QUANTITY: 700 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:



Date: 03/04/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **12" x 12" White w/Color Spots VFT**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **12" x 12" White w/Color Spots VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **5**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **12" x 12" White w/Color Spots VFT Mastic**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12"X12" Lt Gray w/Dark Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**

MATERIAL LOCATION: **Room 007**

MATERIAL QUANTITY: **88**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12"X12" Lt Gray w/Dark Specks Floor Tile**  
MATERIAL LOCATION: **Room 007**  
MATERIAL QUANTITY: **88** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **12"X12" Lt Gray w/Dark Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 007**

MATERIAL QUANTITY: **88**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **12"X12" Lt Gray w/Dark Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 007**  
MATERIAL QUANTITY: **88** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **12"X12" Dk Gray w/Lt Gray Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**

MATERIAL LOCATION: **Rooms 007 and 200**

MATERIAL QUANTITY: **1052**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **12"X12" Dk Gray w/Lt Gray Floor Tile**  
MATERIAL LOCATION: **Rooms 007 and 200**  
MATERIAL QUANTITY: **1052** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **12"X12" Dk Gray w/Lt Gray Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 007 and 200**

MATERIAL QUANTITY: **1052**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **12"X12" Dk Gray w/Lt Gray Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 007 and 200**  
MATERIAL QUANTITY: **1052** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Light Gray Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Rms 316, 309, 3rd Fl Hall, 001, 003, 310, 311, 313**

MATERIAL QUANTITY: **2820** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Light Gray Carpet Adhesive**  
MATERIAL LOCATION: **Rms 316, 309, 3rd Fl Hall, 001, 003, 310, 311, 313**  
MATERIAL QUANTITY: **2820** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **White w/Color Spots Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **Lunchroom**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **White w/Color Spots Floor Tile**  
MATERIAL LOCATION: **Lunchroom**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **White w/Color Spots Floor Tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunch Room**

MATERIAL QUANTITY: **3500**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **White w/Color Spots Floor Tile mastic**  
MATERIAL LOCATION: **Lunch Room**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12"X12" Green Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**

MATERIAL LOCATION: **Room 207 and all Washrooms**

MATERIAL QUANTITY: **700**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12"X12" Green Floor Tile**  
MATERIAL LOCATION: **Room 207 and all Washrooms**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**



# Chicago Public Schools

## Carnow, Conibear and Associates 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **12"X12" Green Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 207 and all Washrooms**

MATERIAL QUANTITY: **700**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **12"X12" Green Floor Tile Mastic**  
MATERIAL LOCATION: **Room 207 and all Washrooms**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

## Carnow, Conibear and Associates 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12"X12" White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**

MATERIAL LOCATION: **Room 207 and all Washrooms**

MATERIAL QUANTITY: **700**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12"X12" White Floor Tile**  
MATERIAL LOCATION: **Room 207 and all Washrooms**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **12"X12" White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 207 and all Washrooms**

MATERIAL QUANTITY: **700**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **12"X12" White Floor Tile Mastic**  
MATERIAL LOCATION: **Room 207 and all Washrooms**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **12" x 12" Tan and Brown Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **Gym**  
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **12" x 12" Tan and Brown Specks Floor Tile**  
MATERIAL LOCATION: **Gym**  
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12" x 12" Tan and Brown Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gym**  
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12" x 12" Tan and Brown Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Gym**  
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **9"X9" Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**

MATERIAL LOCATION: **Gym Office, Hall to Gym Office**

MATERIAL QUANTITY: **380**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **9"X9" Brown Floor Tile**  
MATERIAL LOCATION: **Gym Office, Hall to Gym Office**  
MATERIAL QUANTITY: **380** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **9"X9" Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Gym Office, Hall to Gym Office**

MATERIAL QUANTITY: **380**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **9"X9" Brown Floor Tile Mastic**  
MATERIAL LOCATION: **Gym Office, Hall to Gym Office**  
MATERIAL QUANTITY: **380** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **Gray/Pink Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Corridor, Rooms 107, 104, 103**

MATERIAL QUANTITY: **3620**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **Gray/Pink Carpet Adhesive**  
MATERIAL LOCATION: **1st Floor Corridor, Rooms 107, 104, 103**  
MATERIAL QUANTITY: **3620** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **RED Ceramic Tile & Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **1355** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **RED Ceramic Tile & Grout**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **1355** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **Red Ceramic Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **1355** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **Red Ceramic Tile Adhesive**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **1355** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **White Ceramic Tile and Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **North South Entrance**

MATERIAL QUANTITY: **150**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **White Ceramic Tile and Grout**  
MATERIAL LOCATION: **North South Entrance**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **White Ceramic Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **North South Entrance**

MATERIAL QUANTITY: **150**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **White Ceramic Tile Adhesive**  
MATERIAL LOCATION: **North South Entrance**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter -  
Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **Brown Ceramic Tile and Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Entrance**

MATERIAL QUANTITY: **625**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **Brown Ceramic Tile and Grout**  
MATERIAL LOCATION: **Main Entrance**  
MATERIAL QUANTITY: **625** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **Brown Ceramic Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Entrance**

MATERIAL QUANTITY: **625**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **Brown Ceramic Tile Mastic**  
MATERIAL LOCATION: **Main Entrance**  
MATERIAL QUANTITY: **625** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **12" x 12" Black with White Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **Stage**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **12" x 12" Black with White Streaks Floor Tile**  
MATERIAL LOCATION: **Stage**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58M**  
MATERIAL DESCRIPTION: **12" x 12" Black with White Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Stage**

MATERIAL QUANTITY: **1500**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUIDLING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

---

HOMOGENEOUS AREA: **58M**  
MATERIAL DESCRIPTION: **12" x 12" Black with White Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Stage**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/26/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)


LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66071**      BUILDING ID: **4910**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter - Bucktown School**      INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47**      IDPH LICENSE NO: **100-09725**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/ Black Streaks**  
MATERIAL LOCATION: **Rooms 312, 314, 316**  
MATERIAL QUANTITY: **2250**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **MODERATE**      CONDITION:  
AHERA DAMAGE CATEGORY: **5 ACBM with potential for significant damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/04/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUILDING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/ Black Streaks**  
MATERIAL LOCATION: **Rooms 312, 314, 316**  
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:


COMMENTS:

Management Planner's Signature: \_\_\_\_\_




Date: 03/26/2013


MCPD 08112013 Three Year's Good Drawings/Region 3/0/Chicago International Charter - Bucktown Third Floor



**ASBESTOS REINSPECTION KEY NOTES:**

 HA-59 12"x 12" Dark Grey with Black Streaks Floor Tile

Chicago Intl Charter - Bucktown Third Floor  
2013 Asbestos Reinspection



CLIENT:  
Chicago Public Schools  
125 South Clark Street,  
Chicago, Illinois 60603

PROJECT NAME:  
2013 AHERA Reinspection  
Chicago International Charter -  
Bucktown  
2235 N Hamilton Ave.  
Chicago, IL 60647

SHEET NAME:  
Chicago Intl Charter -  
Bucktown Third Floor - HA-59  
INSPECTED BY:  
Pat Hrycyk

DRAWN BY: MJW	DATE: 3/22/2013	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:

INSPECTED BY:  
Pat Hrycyk

IDPH License #:100- 09725

Carnow, Conibear & Assoc., Ltd.  
Environmental Consulting Services  
600 W. Van Buren St., Suite 500, Chicago, IL 60607  
t: 312.782.4486 f: 312.782.5145  
www.ccaatd.com

**CARNOW  
CONIBEAR**

CCA PROJECT NUMBER  
A320130001-15  
DATE  
03/04/2013  
SHEET NUMBER  
**HA-59**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)


LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66071**      BUILDING ID: **4910**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Patrick Hrycyk**  
SCHOOL NAME: **Chicago International Charter - Bucktown School**      INSPECTION DATE: **3/4/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47**      IDPH LICENSE NO: **100-09725**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **59M**  
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/ Black Streaks Mastic**  
MATERIAL LOCATION: **Rooms 312, 314, 316**  
MATERIAL QUANTITY: **2250**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **5 ACBM with potential for significant damage**  
ACCESSIBILITY: **Not Reachable**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **03/04/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66071** BUILDING ID: **4910**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago International Charter - Bucktown School** REVIEW DATE: **3/26/2013**  
ADDRESS: **2235 N. Hamilton (2132W) 47** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **59M**  
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/ Black Streaks Mastic**  
MATERIAL LOCATION: **Rooms 312, 314, 316**  
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:


COMMENTS:

Management Planner's Signature: \_\_\_\_\_




Date: **03/26/2013**

MCPD 08112013 Three Year Asbestos Reinspection Region 3-0 Chicago International Charter - Bucktown Third Floor



**ASBESTOS REINSPECTION KEY NOTES:**

 HA-59M Mastic Associated with 12"x 12" Dark Grey with Black Streaks Floor Tile

Chicago Intl Charter - Bucktown Third Floor  
2013 Asbestos Reinspection



CLIENT:  
Chicago Public Schools  
125 South Clark Street,  
Chicago, Illinois 60603

PROJECT NAME:  
2013 AHERA Reinspection  
Chicago International Charter -  
Bucktown  
2235 N Hamilton Ave.  
Chicago, IL 60647

SHEET NAME:  
Chicago Intl Charter -  
Bucktown Third Floor -  
HA-59M  
DRAWN BY:  
Pat Hrycyk

DRAWN BY: MJW	DATE: 3/22/2013	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:

IDPH License #: 100- 09725

Carnow, Conibear & Assoc., Ltd.  
Environmental Consulting Services  
600 W. Van Buren St., Suite 500, Chicago, IL 60607  
t: 312.782.4486 f: 312.782.5145  
www.ccaatltd.com

**CARNOW  
CONIBEAR**

CCA PROJECT NUMBER  
A320130001-15  
DATE  
03/04/2013  
SHEET NUMBER  
**HA-59M**

# APPENDIX B

## Inspector and Management Planner Licenses

---

ENDORSEMENTS	TC EXPIRES
INSPECTOR	12/9/2012
PROJECT MANAGER	11/2/2012
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.


Illinois Department of  
**PUBLIC HEALTH**

**ASBESTOS PROFESSIONAL LICENSE**

ID NUMBER	ISSUED	EXPIRES
100 - 09725	5/31/2012	05/15/2013

PATRICK L HRYCIK  
2942 N. MASON AVE  
CHICAGO, IL 60634

Environmental Health





# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that PATRICK HRYCYK  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 12/07/2012 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools;  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



*N. Penoff*

12/07/2012

Course Dates:

12/07/2013

Expires:

1212BIR02

Certificate Number:

Phone Number: (312) 491-0081

Director of Training

Nicholas J. Penoff

Doctor of Public Health

FORM # A-010



# Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

## Asbestos Building Inspector Refresher

Occupational Training and Supply, Inc. certifies that

# Todd Huffer

**has successfully completed the 4 hour Asbestos Building Inspector Refresher Course** and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: BIR1212042317

Exam Date: 12/4/2012

Course Date: 12/4/2012


Expiration Date: 12/4/2013

Kathy DeSalvo, Director

# 2012



# Todd Huffer

Illinois Licensed Asbestos Inspector, Management Planner,  
Project Manager, and Air Sampling Professional

 **ASBESTOS  
PROFESSIONAL  
LICENSE**

<b>ID NUMBER</b> <b>100 - 09870</b>	<b>ISSUED</b> <b>4/4/2012</b>	<b>EXPIRES</b> <b>05/15/2013</b>
--	----------------------------------	-------------------------------------

**TODD T HUFFER**  
918 N WOLCOTT UNIT 6  
CHICAGO, IL 60622

Environmental Health

<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
INSPECTOR	12/8/2012
MANAGEMENT PLANNER	1/19/2013
PROJECT MANAGER	9/8/2012
AIR SAMPLING PROFESSIONAL	

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

**CARNOW  
CONIBEAR**



# Occupational Training & Supply, Inc.

7233 Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

## Asbestos Management Planner Refresher

*Occupational Training and Supply, Inc. certifies that*

# Todd Huffer

**has successfully completed the 4 hour Asbestos Management Planner Refresher Course**  
and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: MPRI302250735

Exam Date: 2/25/2013

Course Date: 2/25/2013

Expiration Date: 2/25/2014

  
Kathy DeSalvo, Director

2013

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed