

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-3013  
SCHOOL NAME: Youth Connection - El Cuarto Ano High School-  
Association House  
ADDRESS OF SCHOOL: 1116 N. Kedzie Ave, 4th Floor  
CITY: Chicago, IL, 60651

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 3/8/2010


**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 5/8/2013 ENROLLMENT 150  
IDPH INSPECTOR LICENSE NUMBER: 100-08023  
IDPH LICENSED INSPECTOR NAME (Please Print): Tommy Thompson  
IDPH MP LICENSE NUMBER: 100-07342  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah  
  
DESIGNATED PERSON (Please Print): Ms. Lynn Crivello PHONE: (773) 553-3113



5/8/2013

*Signature of Designated Person*

*Date*

---

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_  
School has been closed. Date closed: \_\_\_\_\_  
School building has been demolished. Date: \_\_\_\_\_  
School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Youth Connection - El Cuarto Ano High School-Association House**

1116 N. Kedzie Ave, 4th Floor  
Chicago, IL, 60651

Unit: 66109  
Building ID: 1121PA

IDPH ID Number: 14-016-2990-3013

**REPORT DATE:**

Wednesday, May 08, 2013

**Prepared for:**

**Chicago Public Schools**  
**125 S. Clark Street**  
**Chicago, IL 60603**

**Prepared by:**

**GSG Consultants, Inc.**

855 W. Adams St., Ste. 200

Phone (312) 733-6262

Fax (312) 733-5612

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**



## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: April 08, 2013

RE: Youth Connection - El Cuarto Ano High School-Association House, Unit 66109  
1116 N. Kedzie Ave, 4th Floor  
Chicago, IL, 60651

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2013 asbestos three year re-inspection has been completed at Youth Connection - El Cuarto Ano High School-Association House , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Youth Connection - El Cuarto Ano High School-Association House, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Ms. Lynn Crivello, the designated Local Education Authority's Designated Person at (773) 553-3113 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Youth Connection - El Cuarto Ano High School-Association House  
Unit: 66109 Region:  
Address: 1116 N. Kedzie Ave, 4th Floor Chicago, IL, 60651  
IDPH ID: 14-016-2990-3013 Building ID: 1121PA  
Contact: Phone:

### 2. Description of Facility

Original Construction: Additional Construction:  
Total Square Footage: No of Floors:  
Current Occupancy: 150

### 3. LEA Designated Person

Contact: Ms. Lynn Crivello Phone: (773) 553-3113  
Address: 125 South Clark Street, 17th Floor  
Chicago, IL 60603

### 4. Managing Environmental Consultant

MEC: GSG Consultants, Inc.  
Contact: Arturo Saenz  
Address 855 W. Adams St., Ste. 200  
Phone: (312) 733-6262 Fax: (312) 733-5612

### 5. Inspector

Inspector Name: Tommy Thompson



Signature:  
Date: 4/8/2013

Inspector IDPH license # 100-08023

### 6. Management Planner

Management Planner Name: Jigar Shah



Signature:  
Date: 5/8/2013

Management Planner IDPH license # 100-07342

### 7. Review Date: 5/8/2013

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.



Signature:

Date: 5/8/2013

Name: Ms. Lynn Crivello



## II. EXECUTIVE SUMMARY

GSG Consultants, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Youth Connection - El Cuarto Ano High School-Association House. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1121PA:



B. The following new homogenous areas have been identified for Building 1121PA:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	12" X 12" White w/ Rainbow Streaks Floor Tile
01A	12" X 12" White w/ Rainbow Streaks Floor Tile Mastic
02	2' X 4' Ceiling Tile with Pinholes
03	12" X 12" Gray with Light and Dark Streaks Floor Tile
03A	12" X 12" Gray with Light and Dark Streaks Floor Tile Mastic
04	12" x 12" Off-White w/Beige Streaks Floor Tile
04A	2' X 2' White Grooved Ceiling Tile
05	2' X 4' White Pinhole Ceiling Tile
06	12" X 12" White w/Black Streaks Floor Tile
07	2' X 2' Ceiling Tile
12	12" X 12" Off-White w/Beige Streaks Floor Tile
13	2' X 2' White Grooved Ceiling Tile
14	12" X 12" White w/Black Streaks Floor Tile
16	Drywall
17	Drywall Compound
18	Plaster
19	Drywall
20	Drywall Compound
21	Plaster
23	12 x 12 White with Beige and Tan Streaks Floor Tile
23A	12 x 12 White with Beige and Tan Streaks Floor Tile
24	2 x 4 Grooved Lay-in Ceiling Panels
25	Ceramic Tile Grout
25A	Ceramic Tile Adhesive
26	12 x 12 Tan with Tan Streaks Floor Tile
26A	12 x 12 Tan with Tan Streaks Floor Tile Mastic
27	12 x 12 White with Black Specs Floor Tile
27A	12 x 12 White with Black Specs Floor Tile Mastic
28	12 x 12 Black with White Specs Floor Tile
28A	12 x 12 Black with White Specs Floor Tile Mastic
29	Insulation Above 1 x 1 Ceiling Tile Metal Pan
30	12 x 12 White with Tan Streaks Floor Tile
30A	12 x 12 White with Tan Streaks Floor Tile Mastic

The following areas were deemed to be inaccessible:

11	Insulation Above 1'x1' Metal Pan Ceiling (ABATED)
13	2' X 2' White Grooved Ceiling Tile
23A	12 x 12 White with Beige and Tan Streaks Floor Tile

25A	Ceramic Tile Adhesive
26A	12 x 12 Tan with Tan Streaks Floor Tile Mastic
27A	12 x 12 White with Black Specs Floor Tile Mastic
28A	12 x 12 Black with White Specs Floor Tile Mastic
30A	12 x 12 White with Tan Streaks Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Tommy Thompson, IDPH License # 100-08023. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Youth Connection - El Cuarto Ano High School-Association House Building 1121PA Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Youth Connection - El Cuarto Ano High School-Association House Unit 66109 Building ID 1121PA  
 Address 1116 N. Kedzie Ave, 4th Floor Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	12" X 12" White w/ Rainbow Streaks Floor Tile	2,500	SF	1921 Corridor, Bathroom, Kitchen & Classroom 404	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
01A	12" X 12" White w/ Rainbow Streaks Floor Tile Mastic	2,500	SF	1921 Corridor, Bathroom, Kitchen & Classroom 404	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02	2' X 4' Ceiling Tile with Pinholes	1,300	SF	Throughout Facility	ASSUMED	MISC		NONE			No	ACBM with the potential for damage		
03	12" X 12" Gray with Light and Dark Streaks Floor Tile	800	SF	Room 403 & 404	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03A	12" X 12" Gray with Light and Dark Streaks Floor Tile Mastic	800	SF	Room 403 & 404	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04	12" x 12" Off-White w/Beige Streaks Floor Tile	1	SF	Washrooms, Classrooms and Xerox Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04A	2' X 2' White Grooved Ceiling Tile	1,300	SF	Throughout Facility	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
05	2' X 4' White Pinhole Ceiling Tile	800	SF	Throughout Facility	ASSUMED	MISC		NONE	0		No	ACBM with the potential for damage		LOW
06	12" X 12" White w/Black Streaks Floor Tile	800	SF	CORRIDOR BY ROOM 450 & SERVICE ELEVATOR	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06A	12" X 12" White w/Black Streaks Floor Tile Mastic	800	SF	CORRIDOR BY ROOM 450 & SERVICE ELEVATOR	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	2' X 2' Ceiling Tile	500	SF	CLASSROOMS & CORRIDORS	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
08	9" X 9" Cream w/Black Streaks Floor Tile (ABATED)	0	SF	ROOM 405 STORAGE	ABATED	MISC					No			
08A	9" X 9" Cream w/Black Streaks Floor Tile Mastic (ABATED)	0	SF	ROOM 450 & STORAGE ROOM	ABATED	MISC					No			
09	Mudded Joint Packing- E/ F/ V	150	FITTING	450 Storage Room Above Ceiling	CHR	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
10	9" X 9" Gray w/White Strips Floor Tile (ABATED)	0	SF	Northeast Staircase and Classrooms	ABATED	MISC					No			
10A	9" X 9" Gray w/White Strips Floor Tile Mastic (ABATED)	0	SF	Northeast Staircase and Classrooms	ABATED	MISC					No			
11	Insulation Above 1'x1' Metal Pan Ceiling (ABATED)	0	SF	Kitchen and Reception	ABATED	TSI	Y				No			
12	12" X 12" Off-White w/Beige Streaks Floor Tile	1,800	SF	Corridor and Rooms 403 & 424, East Classes and Offices	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Youth Connection - El Cuarto Ano High School-Association House Unit 66109 Building ID 1121PA  
 Address 1116 N. Kedzie Ave, 4th Floor Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
12A	12" X 12" Off-White w/Beige Streaks Floor Tile Mastic	1,800	SF	Corridor and Rooms 403 & 424, East Classes and Offices	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	2' X 2' White Grooved Ceiling Tile	800	SF	4th Floor Hall by Elevator	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
14	12" X 12" White w/Black Streaks Floor Tile	400	SF	Corridor and Elevator	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14A	12" X 12" White w/Black Streaks Floor Tile Mastic	400	SF	Corridor and Elevator	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	MJP E/F/V on Fiberglass Pipe Insulation	120	LF	Above Suspended Ceilings	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
16	Drywall	10,000	SF	Throughout Classrooms and Corridors	ASSUMED	SURFACE		NONE	0		No	ACBM with the potential for damage		LOW
17	Drywall Compound	1,000	SF	Throughout Classrooms and Corridors	ASSUMED	SURFACE		NONE	0		No	ACBM with the potential for damage		LOW
18	Plaster	7,000	SF	Stairwells, Walls, Ceilings, & Above Suspended Ceilings	ASSUMED	SURFACE		NONE	0		No	ACBM with the potential for damage		LOW
19	Drywall	8,000	SF	Throughout Classrooms and Corridors, 1st Floor Kitchen	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
20	Drywall Compound	1,000	SF	Throughout Classrooms and Corridors, 1st Floor Kitchen	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
21	Plaster	11,000	SF	Throughout Classrooms and Corridors	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
22	Aircell Pipe Insulation- NOT OBSERVED	10	LF	405 Storage	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
23	12 x 12 White with Beige and Tan Streaks Floor Tile	4,500	SF	Corridor Wes End, Room 450 Storage, NE Staircase Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23A	12 x 12 White with Beige and Tan Streaks Floor Tile	4,500	SF	Corridor Wes End, Room 450 Storage, NE Staircase Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	2 x 4 Grooved Lay-in Ceiling Panels	50	SF	Kitchen and Reception in 4th Floor	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Youth Connection - El Cuarto Ano High School-Association House Unit 66109 Building ID 1121PA  
 Address 1116 N. Kedzie Ave, 4th Floor Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
25	Ceramic Tile Grout	600	SF	Kitchen 4th Floor, 450 Storage Area, Kitchen 1st Floor, janitor Closet next to Elevators	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
25A	Ceramic Tile Adhesive	600	SF	Kitchen 4th Floor, 450 Storage Area, Kitchen 1st Floor, janitor Closet next to Elevators	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	12 x 12 Tan with Tan Streaks Floor Tile	525	SF	Room 425	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26A	12 x 12 Tan with Tan Streaks Floor Tile Mastic	525	SF	Room 425	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12 x 12 White with Black Specs Floor Tile	900	SF	1st Floor Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27A	12 x 12 White with Black Specs Floor Tile Mastic	900	SF	1st Floor Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	12 x 12 Black with White Specs Floor Tile	900	SF	1st Floor Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28A	12 x 12 Black with White Specs Floor Tile Mastic	900	SF	1st Floor Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	Insulation Above 1 x 1 Ceiling Tile Metal Pan	1,800	SF	1st Floor Lunchroom Manager Office	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
30	12 x 12 White with Tan Streaks Floor Tile	200	SF	1st Floor Kitchen Manager Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30A	12 x 12 White with Tan Streaks Floor Tile Mastic	200	SF	1st Floor Kitchen Manager Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW



# Chicago Public Schools

School Youth Connection - El Cuarto Ano High School-Association House Unit 66109 Building ID 1121PA  
Address 1116 N. Kedzie Ave, 4th Floor Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>4/8/2013</b>
Inspector Name <b>Tommy Thompson</b>
<b>100-08023</b> <b>5/15/2013</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
01	
01A	
02	
03	
03A	
04	
04A	
05	
06	
06A	
07	
08	
08A	
09	
10	
10A	
11	
12	
12A	
13	
14	
14A	
15	
16	

# Chicago Public Schools

**School** Youth Connection - El Cuarto Ano High School-Association House **Unit** 66109 **Building ID** 1121PA  
**Address** 1116 N. Kedzie Ave, 4th Floor **Region**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
17	
18	
19	
20	
21	
22	
23	
23A	
24	
25	
25A	
26	
26A	
27	
27A	
28	
28A	
29	
30	
30A	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Youth Connection - El  
Cuarto Ano High School-  
Association House  
**Address** 1116 N. Kedzie Ave, 4th Floor

**Unit** 66109  
Chicago, IL, 60651

**Building ID** 1121PA  
**Region**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	12" X 12" White w/ Rainbow Streaks Floor Tile	2,500	SF	1921 Corridor, Bathroom, Kitchen & Classroom 404	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Operations and Maintenance
01A	12" X 12" White w/ Rainbow Streaks Floor Tile Mastic	2,500	SF	1921 Corridor, Bathroom, Kitchen & Classroom 404	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
02	2' X 4' Ceiling Tile with Pinholes	1,300	SF	Throughout Facility	Assumed	MISC			SF	6 ACBM with the potential for damage	Operations and Maintenance
03	12" X 12" Gray with Light and Dark Streaks Floor Tile	800	SF	Room 403 & 404	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
03A	12" X 12" Gray with Light and Dark Streaks Floor Tile Mastic	800	SF	Room 403 & 404	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
04	12" x 12" Off-White w/Beige Streaks Floor Tile	1	SF	Washrooms, Classrooms and Xerox Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
04A	2' X 2' White Grooved Ceiling Tile	1,300	SF	Throughout Facility	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
05	2' X 4' White Pinhole Ceiling Tile	800	SF	Throughout Facility	Assumed	MISC		0	SF	6 ACBM with the potential for damage	Operations and Maintenance
06	12" X 12" White w/Black Streaks Floor Tile	800	SF	CORRIDOR BY ROOM 450 & SERVICE ELEVATOR	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
06A	12" X 12" White w/Black Streaks Floor Tile Mastic	800	SF	CORRIDOR BY ROOM 450 & SERVICE ELEVATOR	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
07	2' X 2' Ceiling Tile	500	SF	CLASSROOMS & CORRIDORS	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
08	9" X 9" Cream w/Black Streaks Floor Tile (ABATED)	0	SF	ROOM 405 STORAGE	Abated	MISC			SF		
08A	9" X 9" Cream w/Black Streaks Floor Tile Mastic (ABATED)	0	SF	ROOM 450 & STORAGE ROOM	Abated	MISC			SF		
09	Mudded Joint Packing- E/ F/ V	150	FITTING	450 Storage Room Above Ceiling	Chrysotile	MISC	Yes	0	FITTING	6 ACBM with the potential for damage	Operations and Maintenance
10	9" X 9" Gray w/White Strips Floor Tile (ABATED)	0	SF	Northeast Staircase and Classrooms	Abated	MISC			SF		
10A	9" X 9" Gray w/White Strips Floor Tile Mastic (ABATED)	0	SF	Northeast Staircase and Classrooms	Abated	MISC			SF		
11	Insulation Above 1'x1' Metal Pan Ceiling (ABATED)	0	SF	Kitchen and Reception	Abated	TSI	Yes		SF		
12	12" X 12" Off-White w/Beige Streaks Floor Tile	1,800	SF	Corridor and Rooms 403 & 424, East Classes and Offices	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
12A	12" X 12" Off-White w/Beige Streaks Floor Tile Mastic	1,800	SF	Corridor and Rooms 403 & 424, East Classes and Offices	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
13	2' X 2' White Grooved Ceiling Tile	800	SF	4th Floor Hall by Elevator	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
14	12" X 12" White w/Black Streaks Floor Tile	400	SF	Corridor and Elevator	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

# Chicago Public Schools

**School** Youth Connection - El Cuarto Ano High School- Association House  
**Unit** 66109  
**Building ID** 1121PA  
**Address** 1116 N. Kedzie Ave, 4th Floor Chicago, IL, 60651  
**Region**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
14A	12" X 12" White w/Black Streaks Floor Tile Mastic	400	SF	Corridor and Elevator	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
15	MJP E/F/V on Fiberglass Pipe Insulation	120	LF	Above Suspended Ceilings	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
16	Drywall	10,000	SF	Throughout Classrooms and Corridors	Assumed	SURFACE		0	SF	6 ACBM with the potential for damage	Operations and Maintenance
17	Drywall Compound	1,000	SF	Throughout Classrooms and Corridors	Assumed	SURFACE		0	SF	6 ACBM with the potential for damage	Operations and Maintenance
18	Plaster	7,000	SF	Stairwells, Walls, Ceilings, & Above Suspended Ceilings	Assumed	SURFACE		0	SF	6 ACBM with the potential for damage	Operations and Maintenance
19	Drywall	8,000	SF	Throughout Classrooms and Corridors, 1st Floor Kitchen	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
20	Drywall Compound	1,000	SF	Throughout Classrooms and Corridors, 1st Floor Kitchen	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
21	Plaster	11,000	SF	Throughout Classrooms and Corridors	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
22	Aircell Pipe Insulation- NOT OBSERVED	10	LF	405 Storage	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
23	12 x 12 White with Beige and Tan Streaks Floor Tile	4,500	SF	Corridor Wes End, Room 450 Storage, NE Staircase Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
23A	12 x 12 White with Beige and Tan Streaks Floor Tile	4,500	SF	Corridor Wes End, Room 450 Storage, NE Staircase Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
24	2 x 4 Grooved Lay-in Ceiling Panels	50	SF	Kitchen and Reception in 4th Floor	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
25	Ceramic Tile Grout	600	SF	Kitchen 4th Floor, 450 Storage Area, Kitchen 1st Floor, janitor Closet next to Elevators	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
25A	Ceramic Tile Adhesive	600	SF	Kitchen 4th Floor, 450 Storage Area, Kitchen 1st Floor, janitor Closet next to Elevators	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
26	12 x 12 Tan with Tan Streaks Floor Tile	525	SF	Room 425	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
26A	12 x 12 Tan with Tan Streaks Floor Tile Mastic	525	SF	Room 425	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
27	12 x 12 White with Black Specs Floor Tile	900	SF	1st Floor Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
27A	12 x 12 White with Black Specs Floor Tile Mastic	900	SF	1st Floor Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
28	12 x 12 Black with White Specs Floor Tile	900	SF	1st Floor Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
28A	12 x 12 Black with White Specs Floor Tile Mastic	900	SF	1st Floor Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
29	Insulation Above 1 x 1 Ceiling Tile Metal Pan	1,800	SF	1st Floor Lunchroom Manager Office	Assumed	TSI	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
30	12 x 12 White with Tan Streaks Floor Tile	200	SF	1st Floor Kitchen Manager Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
30A	12 x 12 White with Tan Streaks Floor Tile Mastic	200	SF	1st Floor Kitchen Manager Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

# Chicago Public Schools

**School** Youth Connection - El  
Cuarto Ano High School-  
Association House  
**Address** 1116 N. Kedzie Ave, 4th Floor

**Unit** 66109  
Chicago, IL, 60651

**Building ID** 1121PA  
**Region**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.  
855 W. Adams St., Ste. 200  
Phone: (312) 733-6262

Fax: (312) 733-5612

*Management Planner's Comments Summarized at the End of the Report*

Review Date	5/8/2013
Manager Planner Name	Jigar Shah
100-07342	5/15/2013
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
01A	
02	
03	
03A	
04	

# Chicago Public Schools

**School** Youth Connection - El  
Cuarto Ano High School-  
Association House  
**Address** 1116 N. Kedzie Ave, 4th Floor

**Unit** 66109  
Chicago, IL, 60651

**Building ID** 1121PA  
**Region**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

***Management Planner's Comments Summarized at the End of the Report***

HA Number	Management Comments
04A	
05	
06	
06A	
07	
08	
08A	
09	
10	
10A	
11	
12	
12A	
13	
14	
14A	
15	
16	
17	
18	
19	
20	
21	
22	
23	

# Chicago Public Schools

**School** Youth Connection - El  
Cuarto Ano High School-  
Association House  
**Address** 1116 N. Kedzie Ave, 4th Floor

**Unit** 66109  
Chicago, IL, 60651

**Building ID** 1121PA  
**Region**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

*Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
23A	
24	
25	
25A	
26	
26A	
27	
27A	
28	
28A	
29	
30	
30A	



# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **12" X 12" White w/ Rainbow Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1921 Corridor, Bathroom, Kitchen & Classroom 404**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **12" X 12" White w/ Rainbow Streaks Floor Tile**  
MATERIAL LOCATION: **1921 Corridor, Bathroom, Kitchen & Classroom 404**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01A**  
MATERIAL DESCRIPTION: **12" X 12" White w/ Rainbow Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1921 Corridor, Bathroom, Kitchen & Classroom 404**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **01A**  
MATERIAL DESCRIPTION: **12" X 12" White w/ Rainbow Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1921 Corridor, Bathroom, Kitchen & Classroom 404**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 66109 BUIDLING ID: 1121PA  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Tommy Thompson  
SCHOOL NAME: Youth Connection - El Cuarto Ano High School-Association House INSPECTION DATE: 4/8/2013  
ADDRESS: 1116 N. Kedzie Ave, 4th Floor IDPH LICENSE NO: 100-08023

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 02  
MATERIAL DESCRIPTION: 2' X 4' Ceiling Tile with Pinholes  
HISTORICAL AHERA DAMAGE CATEGORY 6  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Facility

MATERIAL QUANTITY: 1300

MATERIAL UNITS: SF

DAMAGE QUANTITY:

DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **2' X 4' Ceiling Tile with Pinholes**  
MATERIAL LOCATION: **Throughout Facility**  
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**

# Chicago Public Schools

## GSG Consultants, Inc. 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **12" X 12" Gray with Light and Dark Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 403 & 404**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **12" X 12" Gray with Light and Dark Streaks Floor Tile**  
MATERIAL LOCATION: **Room 403 & 404**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**



# Chicago Public Schools

## GSG Consultants, Inc. 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03A**  
MATERIAL DESCRIPTION: **12" X 12" Gray with Light and Dark Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 403 & 404**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **03A**  
MATERIAL DESCRIPTION: **12" X 12" Gray with Light and Dark Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 403 & 404**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 66109 BUIDLING ID: 1121PA  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Tommy Thompson  
SCHOOL NAME: Youth Connection - El Cuarto Ano High School-Association House INSPECTION DATE: 4/8/2013  
ADDRESS: 1116 N. Kedzie Ave, 4th Floor IDPH LICENSE NO: 100-08023

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 04  
MATERIAL DESCRIPTION: 12" x 12" Off-White w/Beige Streaks Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Washrooms, Classrooms and Xerox Room**

MATERIAL QUANTITY: **1** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Beige Streaks Floor Tile**  
MATERIAL LOCATION: **Washrooms, Classrooms and Xerox Room**  
MATERIAL QUANTITY: **1** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04A**  
MATERIAL DESCRIPTION: **2' X 2' White Grooved Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Facility**  
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **04/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **04A**  
MATERIAL DESCRIPTION: **2' X 2' White Grooved Ceiling Tile**  
MATERIAL LOCATION: **Throughout Facility**  
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 66109 BUIDLING ID: 1121PA  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Tommy Thompson  
SCHOOL NAME: Youth Connection - El Cuarto Ano High School-Association House INSPECTION DATE: 4/8/2013  
ADDRESS: 1116 N. Kedzie Ave, 4th Floor IDPH LICENSE NO: 100-08023

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 05  
MATERIAL DESCRIPTION: 2' X 4' White Pinhole Ceiling Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Throughout Facility  
MATERIAL QUANTITY: 800 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS:

Inspector's Signature:



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **2' X 4' White Pinhole Ceiling Tile**  
MATERIAL LOCATION: **Throughout Facility**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**



# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 66109 BUIDLING ID: 1121PA  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Tommy Thompson  
SCHOOL NAME: Youth Connection - El Cuarto Ano High School-Association House INSPECTION DATE: 4/8/2013  
ADDRESS: 1116 N. Kedzie Ave, 4th Floor IDPH LICENSE NO: 100-08023

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 06  
MATERIAL DESCRIPTION: 12" X 12" White w/Black Streaks Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **CORRIDOR BY ROOM 450 & SERVICE ELEVATOR**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **12" X 12" White w/Black Streaks Floor Tile**  
MATERIAL LOCATION: **CORRIDOR BY ROOM 450 & SERVICE ELEVATOR**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06A**  
MATERIAL DESCRIPTION: **12" X 12" White w/Black Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **CORRIDOR BY ROOM 450 & SERVICE ELEVATOR**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **06A**  
MATERIAL DESCRIPTION: **12" X 12" White w/Black Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **CORRIDOR BY ROOM 450 & SERVICE ELEVATOR**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 66109    BUILDING ID: 1121PA  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Tommy Thompson  
SCHOOL NAME: Youth Connection - El Cuarto Ano High School-Association House    INSPECTION DATE: 4/8/2013  
ADDRESS: 1116 N. Kedzie Ave, 4th Floor    IDPH LICENSE NO: 100-08023

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 07  
MATERIAL DESCRIPTION: 2' X 2' Ceiling Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed    FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: CLASSROOMS & CORRIDORS  
MATERIAL QUANTITY: 500    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013 \_\_\_\_\_

# Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **2' X 2' Ceiling Tile**  
MATERIAL LOCATION: **CLASSROOMS & CORRIDORS**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **9" X 9" Cream w/Black Streaks Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:


DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROOM 405 STORAGE**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: 

Date: **04/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **9" X 9" Cream w/Black Streaks Floor Tile (ABATED)**  
MATERIAL LOCATION: **ROOM 405 STORAGE**  
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**



# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08A**  
MATERIAL DESCRIPTION: **9" X 9" Cream w/Black Streaks Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROOM 450 & STORAGE ROOM**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **08A**  
MATERIAL DESCRIPTION: **9" X 9" Cream w/Black Streaks Floor Tile Mastic (ABATED)**  
MATERIAL LOCATION: **ROOM 450 & STORAGE ROOM**  
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**

# Chicago Public Schools

## GSG Consultants, Inc. 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **Mudded Joint Packing- E/ F/ V**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **450 Storage Room Above Ceiling**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **Mudded Joint Packing- E/ F/ V**  
MATERIAL LOCATION: **450 Storage Room Above Ceiling**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **9" X 9" Gray w/White Strips Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Northeast Staircase and Classrooms**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **9" X 9" Gray w/White Strips Floor Tile (ABATED)**  
MATERIAL LOCATION: **Northeast Staircase and Classrooms**  
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10A**  
MATERIAL DESCRIPTION: **9" X 9" Gray w/White Strips Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Northeast Staircase and Classrooms**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **10A**  
MATERIAL DESCRIPTION: **9" X 9" Gray w/White Strips Floor Tile Mastic (ABATED)**  
MATERIAL LOCATION: **Northeast Staircase and Classrooms**  
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/08/2013**



# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **Insulation Above 1'x1' Metal Pan Ceiling (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen and Reception**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **Insulation Above 1'x1' Metal Pan Ceiling (ABATED)**  
MATERIAL LOCATION: **Kitchen and Reception**  
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **12" X 12" Off-White w/Beige Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Corridor and Rooms 403 & 424, East Classes and Offices**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **12" X 12" Off-White w/Beige Streaks Floor Tile**  
MATERIAL LOCATION: **Corridor and Rooms 403 & 424, East Classes and Offices**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12A**  
MATERIAL DESCRIPTION: **12" X 12" Off-White w/Beige Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Corridor and Rooms 403 & 424, East Classes and Offices**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **12A**  
MATERIAL DESCRIPTION: **12" X 12" Off-White w/Beige Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Corridor and Rooms 403 & 424, East Classes and Offices**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**

# Chicago Public Schools

## GSG Consultants, Inc. 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **2' X 2' White Grooved Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **4th Floor Hall by Elevator**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **2' X 2' White Grooved Ceiling Tile**  
MATERIAL LOCATION: **4th Floor Hall by Elevator**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**



# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 66109    BUILDING ID: 1121PA  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Tommy Thompson  
SCHOOL NAME: Youth Connection - El Cuarto Ano High School-Association House    INSPECTION DATE: 4/8/2013  
ADDRESS: 1116 N. Kedzie Ave, 4th Floor    IDPH LICENSE NO: 100-08023

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 14  
MATERIAL DESCRIPTION: 12" X 12" White w/Black Streaks Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Corridor and Elevator  
MATERIAL QUANTITY: 400    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013 \_\_\_\_\_

# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **12" X 12" White w/Black Streaks Floor Tile**  
MATERIAL LOCATION: **Corridor and Elevator**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14A**  
MATERIAL DESCRIPTION: **12" X 12" White w/Black Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Corridor and Elevator**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **14A**  
MATERIAL DESCRIPTION: **12" X 12" White w/Black Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Corridor and Elevator**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Above Suspended Ceilings**

MATERIAL QUANTITY: **120**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **Above Suspended Ceilings**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 66109    BUILDING ID: 1121PA  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Tommy Thompson  
SCHOOL NAME: Youth Connection - El Cuarto Ano High School-Association House    INSPECTION DATE: 4/8/2013  
ADDRESS: 1116 N. Kedzie Ave, 4th Floor    IDPH LICENSE NO: 100-08023

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 16  
MATERIAL DESCRIPTION: Drywall  
HISTORICAL AHERA DAMAGE CATEGORY 6  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Throughout Classrooms and Corridors  
MATERIAL QUANTITY: 10000    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013 \_\_\_\_\_

# Chicago Public Schools

## GSG Consultants, Inc. 2013 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **Throughout Classrooms and Corridors**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**



# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 66109    BUILDING ID: 1121PA  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Tommy Thompson  
SCHOOL NAME: Youth Connection - El Cuarto Ano High School-Association House    INSPECTION DATE: 4/8/2013  
ADDRESS: 1116 N. Kedzie Ave, 4th Floor    IDPH LICENSE NO: 100-08023

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 17  
MATERIAL DESCRIPTION: Drywall Compound  
HISTORICAL AHERA DAMAGE CATEGORY 6  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Throughout Classrooms and Corridors  
MATERIAL QUANTITY: 1000    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Drywall Compound**  
MATERIAL LOCATION: **Throughout Classrooms and Corridors**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stairwells, Walls, Ceilings, & Above Suspended Ceilings**  
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Plaster**  
MATERIAL LOCATION: **Stairwells, Walls, Ceilings, & Above Suspended Ceilings**  
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 66109 BUIDLING ID: 1121PA  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Tommy Thompson  
SCHOOL NAME: Youth Connection - El Cuarto Ano High School-Association House INSPECTION DATE: 4/8/2013  
ADDRESS: 1116 N. Kedzie Ave, 4th Floor IDPH LICENSE NO: 100-08023

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 19  
MATERIAL DESCRIPTION: Drywall  
HISTORICAL AHERA DAMAGE CATEGORY 6  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Throughout Classrooms and Corridors, 1st Floor Kitchen  
MATERIAL QUANTITY: 8000 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **Throughout Classrooms and Corridors, 1st Floor Kitchen**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**

# Chicago Public Schools

## GSG Consultants, Inc. 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano  
High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Drywall Compound**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Classrooms and Corridors, 1st Floor Kitchen**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Drywall Compound**  
MATERIAL LOCATION: **Throughout Classrooms and Corridors, 1st Floor Kitchen**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**



# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Classrooms and Corridors**  
MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Plaster**  
MATERIAL LOCATION: **Throughout Classrooms and Corridors**  
MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**

# Chicago Public Schools

## GSG Consultants, Inc. 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano  
High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **405 Storage**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation- NOT OBSERVED**  
MATERIAL LOCATION: **405 Storage**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **12 x 12 White with Beige and Tan Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Corridor Wes End, Room 450 Storage, NE Staircase Classrooms**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **12 x 12 White with Beige and Tan Streaks Floor Tile**  
MATERIAL LOCATION: **Corridor Wes End, Room 450 Storage, NE Staircase Classrooms**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23A**  
MATERIAL DESCRIPTION: **12 x 12 White with Beige and Tan Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Corridor Wes End, Room 450 Storage, NE Staircase Classrooms**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **23A**  
MATERIAL DESCRIPTION: **12 x 12 White with Beige and Tan Streaks Floor Tile**  
MATERIAL LOCATION: **Corridor Wes End, Room 450 Storage, NE Staircase Classrooms**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/08/2013**



# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **2 x 4 Grooved Lay-in Ceiling Panels**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen and Reception in 4th Floor**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **2 x 4 Grooved Lay-in Ceiling Panels**  
MATERIAL LOCATION: **Kitchen and Reception in 4th Floor**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 66109 BUIDLING ID: 1121PA  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Tommy Thompson  
SCHOOL NAME: Youth Connection - El Cuarto Ano High School-Association House INSPECTION DATE: 4/8/2013  
ADDRESS: 1116 N. Kedzie Ave, 4th Floor IDPH LICENSE NO: 100-08023

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 25  
MATERIAL DESCRIPTION: Ceramic Tile Grout  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Operations and Maintenance  
ASBESTOS TYPE: Assumed FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Kitchen 4th Floor, 450 Storage Area, Kitchen 1st Floor, janitor Closet next to Elevators

MATERIAL QUANTITY: 600 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Ceramic Tile Grout**  
MATERIAL LOCATION: **Kitchen 4th Floor, 450 Storage Area, Kitchen 1st Floor, janitor Closet next to Elevators**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25A**  
MATERIAL DESCRIPTION: **Ceramic Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen 4th Floor, 450 Storage Area, Kitchen 1st Floor, janitor Closet next to Elevators**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **25A**  
MATERIAL DESCRIPTION: **Ceramic Tile Adhesive**  
MATERIAL LOCATION: **Kitchen 4th Floor, 450 Storage Area, Kitchen 1st Floor, janitor Closet next to Elevators**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12 x 12 Tan with Tan Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 425**

MATERIAL QUANTITY: **525**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12 x 12 Tan with Tan Streaks Floor Tile**  
MATERIAL LOCATION: **Room 425**  
MATERIAL QUANTITY: **525** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**



# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26A**  
MATERIAL DESCRIPTION: **12 x 12 Tan with Tan Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 425**  
MATERIAL QUANTITY: **525** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **26A**  
MATERIAL DESCRIPTION: **12 x 12 Tan with Tan Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 425**  
MATERIAL QUANTITY: **525** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12 x 12 White with Black Specs Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Cafeteria**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12 x 12 White with Black Specs Floor Tile**  
MATERIAL LOCATION: **1st Floor Cafeteria**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27A**  
MATERIAL DESCRIPTION: **12 x 12 White with Black Specs Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Cafeteria**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **27A**  
MATERIAL DESCRIPTION: **12 x 12 White with Black Specs Floor Tile Mastic**  
MATERIAL LOCATION: **1st Floor Cafeteria**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12 x 12 Black with White Specs Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Cafeteria**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12 x 12 Black with White Specs Floor Tile**  
MATERIAL LOCATION: **1st Floor Cafeteria**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**



# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28A**  
MATERIAL DESCRIPTION: **12 x 12 Black with White Specs Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Cafeteria**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **28A**  
MATERIAL DESCRIPTION: **12 x 12 Black with White Specs Floor Tile Mastic**  
MATERIAL LOCATION: **1st Floor Cafeteria**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Insulation Above 1 x 1 Celing Tile Metal Pan**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Lunchroom Manager Office**

MATERIAL QUANTITY: **1800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Insulation Above 1 x 1 Celing Tile Metal Pan**  
MATERIAL LOCATION: **1st Floor Lunchroom Manager Office**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12 x 12 White with Tan Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Kitchen Manager Office**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12 x 12 White with Tan Streaks Floor Tile**  
MATERIAL LOCATION: **1st Floor Kitchen Manager Office**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**

# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE: **4/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30A**  
MATERIAL DESCRIPTION: **12 x 12 White with Tan Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Kitchen Manager Office**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/08/2013

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE: **5/8/2013**  
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO: **100-08023**

---

HOMOGENEOUS AREA: **30A**  
MATERIAL DESCRIPTION: **12 x 12 White with Tan Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1st Floor Kitchen Manager Office**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/08/2013**



# Chicago Public Schools

GSG Consultants, Inc.  
*2013 AHERA REINSPECTION*

# APPENDIX B

## Inspector and Management Planner Licenses

---




**ASBESTOS  
PROFESSIONAL  
LICENSE**

ID NUMBER	ISSUED	EXPIRES
100 - 08023	4/20/2012	05/15/2013

**TOMMY THOMPSON**  
14814 SOUTH ELLIS  
DOLTON, IL 60419



Environmental Health



ENDORSEMENTS	TC EXPIRES
SUPERVISOR/WORKER	3/1/2013
INSPECTOR	3/18/2013
PROJECT MANAGER	3/1/2013
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action  
This license issued under authority of the State of Illinois

Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Approved by the Illinois Department of Public Health and Indiana Department of Environmental Management

This is to certify that TOMMY R. THOMPSON  
has completed the Contractor/Supervisor Recertification course and passed the examination  
on 02/09/2013 with a minimum score of 70% or better. Training was in accordance with U.S.  
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model  
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA and Indiana Rule 326 IAC  
18-2.



*Nicholas J. Peneff*

02/09/2013

Course Dates:

02/09/2014

Expires:

1302CSR35

Certificate Number:

Phone Number: (312) 491-0081

Director of Training

Nicholas J. Peneff

Director of Public Health

FORM # A-008



# ASBESTOS PROFESSIONAL LICENSE

## INCREMENTS

## TO EXPIRES

ID NUMBER

100 - 07342

ISSUED

3/21/2013

EXPIRES

05/15/2014

INSPECTOR

3/21/2014

PROJECT DESIGNER

3/21/2014

MANAGEMENT PLANNER

3/21/2014

PROJECT MANAGER

3/21/2014

AIR SAMPLING PROFESSIONAL

JIGAR M SHAH

855 W ADAMS ST, SUITE 200

CHICAGO, IL 60607

Environmental Health



Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois

Department of Public Health

This license is valid only when accompanied by a valid

training course certificate.

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that JIGAR SHAH  
has completed the **ASBESTOS INSPECTOR'S REFRESHER** course and successfully passed the  
examination on 02/16/2013 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



*N. Kung'ya*

02/16/2013

Course Dates:

02/16/2014

Expires:

1302BIR29

Certificate Number:

Phone Number: (312) 491-0081

Director of Training  
Nicholas J. Peneff  
Doctor of Public Health

FORM # A-010

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---



# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed