

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2164
SCHOOL NAME: University of Chicago-Donoghue
ADDRESS OF SCHOOL: 707 E. 37th Street
CITY: Chicago, IL, 60653

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/16/2010**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 4/29/2013 ENROLLMENT 0
IDPH INSPECTOR LICENSE NUMBER: 100-09725
IDPH LICENSED INSPECTOR NAME (Please Print): Patrick Hrycyk
IDPH MP LICENSE NUMBER: 100-05171
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Stephen Diblik

DESIGNATED PERSON (Please Print): Ms. Lynn Crivello PHONE: (773) 553-3113



4/29/2013

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

University of Chicago-Donoghue

707 E. 37th Street
Chicago, IL, 60653

Unit: 26071
Building ID: 6790

IDPH ID Number: 14-016-2990-2164

REPORT DATE:

Monday, April 29, 2013

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: April 18, 2013

RE: University of Chicago-Donoghue, Unit 26071
707 E. 37th Street
Chicago, IL, 60653

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2013 asbestos three year re-inspection has been completed at University of Chicago-Donoghue , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at University of Chicago-Donoghue, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Ms. Lynn Crivello, the designated Local Education Authority's Designated Person at (773) 553-3113 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the University of Chicago-Donoghue. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 6790:

11	12"x12" Blue Floor Tile
12	Replacement 12"x12" Ceiling Tiles
13	Insulation on Duct
2	12"x12" Tan Floor Tile
21	Mastic under 12" x 12" Blue Floor Tile (11)
33	Clay Tile
34	Clay Tile Mortar
37	Patch of Window Caulk

B. The following new homogenous areas have been identified for Building 6790:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

11	12"x12" Blue Floor Tile
12	Replacement 12"x12" Ceiling Tiles
13	Insulation on Duct
2	12"x12" Tan Floor Tile
21	Mastic under 12" x 12" Blue Floor Tile (11)
29	Green Carpet Mastic
30	Pegboard
33	Clay Tile
34	Clay Tile Mortar
36	Vibration Absorbers on Duct (3)
37	Patch of Window Caulk
38	Blue Carpet Mastic
41	Green/Brown Carpet Mastic
42	Terrazzo Sinks
45	Purple Carpet Mastic
46	Green Carpet Mastic
47	Insulation Inside of Fire Doors
50	Ceramic Floor Tile Grout
51	9"x9" Brown Floor Tile Mastic
60	Transite Replacement Ceiling Panels
63	Stage Curtain (Replacement)
64	Boiler Gaskets
65	2' x 4' Lay-in Ceiling Panels
66	Green Mix Carpet Adhesive
67	12" x 12" Brown Mix Floor Tile as Patches
68	12" x 12" Brown Mix Floor Tile as Patches Mastic
69	12" x 12" Spline Ceiling Tiles
70	Vault Door Lining
71	12" x 12" Light Brown w/Brown Floor Tile
72	12" x 12" Light Brown w/ Brown Floor Tile Mastic
73	12" x 12" White w/ Black Floor Tile
74	12" x 12" White w/ Black Floor Tile Mastic
75	12" x 12" Black w/Gray Specks Floor Tile
76	12" x 12" Black w/Gray Specks Floor Tile Mastic
77	Linoleum on Counters
78	Linoleum on Counters Adhesive
79	Linoleum
80	Linoleum Adhesive
81	Sink Undercoat
82	Chalk Board/Poster Board Adhesive
83	Green Carpet Mastic
84	12"x12" Light Brown Mix Floor Tile
85	12"x12" Light Brown Mix Floor Tile Mastic

The following areas were deemed to be inaccessible:

16	Mastic under 9"x9" Bright Green Floor Tile
18	Mastic under 9"x9" White Floor Tile (3B)
19	Mastic under 9"x9" Aqua and White Floor Tile
20	Mastic under 9"x9" Green Floor Tile (13)
21	Mastic under 12" x 12" Blue Floor Tile (11)
23	9"x9" Green Floor Tile Mastic (23)
2M	12"x12" Tan Floor Tile Mastic
31	9"x9" Green Floor Tile Mastic
32	9"x9" Green Floor Tile Mastic
34	Clay Tile Mortar
37	Patch of Window Caulk
38	Blue Carpet Mastic
3A	9"x9" Gray Floor Tile w/ White Streaks
3B	9"x9" White Floor Tile w/ Gray Streaks
4	9"x9" Green Floor Tile
40	9"x9" Brown Floor Tile Mastic
41	Green/Brown Carpet Mastic
46	Green Carpet Mastic
47	Insulation Inside of Fire Doors
51	9"x9" Brown Floor Tile Mastic
5M	9"x9" Brown Floor Tile Mastic
68	12" x 12" Brown Mix Floor Tile as Patches Mastic
70	Vault Door Lining
72	12" x 12" Light Brown w/ Brown Floor Tile Mastic
78	Linoleum on Counters Adhesive
80	Linoleum Adhesive
82	Chalk Board/Poster Board Adhesive
85	12"x12" Light Brown Mix Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Patrick Hrycyk, IDPH License # 100-09725. The Management Plan was updated by Stephen Diblik, IDPH License # 100-05171. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The University of Chicago-Donoghue Building 6790 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School University of Chicago-Donoghue Unit 26071 Building ID 6790

Address 707 E. 37th Street Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	9"x9" Brown Floor Tile (Under Carpet)	170	SF	Engineers Office	CHR	MISC	N	None				ACBM with the potential for damage		Low
10	Stage Curtain			Auditorium-Removed before 1998	UNDEFINED									
11	12"x12" Blue Floor Tile	800	SF	Auditorium	ASSUMED	MISC	N	LOC	0		Yes	ACBM with the potential for damage		LOW
12	Replacement 12"x12" Ceiling Tiles	5,000	SF	Classrooms	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
13	Insulation on Duct	35	SF	2nd Floor Mechanical Room	ASSUMED	TSI	N	NONE	0		Yes	ACBM with the potential for damage		LOW
14	9"x9" Green Floor Tile Patches	143	SF	Kitchen	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
15	9"x9" Bright Green Floor Tile	200	SF	As Patches in 1st & 2nd Floor Corridors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
16	Mastic under 9"x9" Bright Green Floor Tile	200	SF	As Patches in 1st and 2nd Floor Corridors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	Mastic under 9"x9" Gray Floor Tiles (3A)	1,835	SF	1st Floor Corridors & Lobby	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	Mastic under 9"x9" White Floor Tile (3B)	1,835	SF	1st Floor Corridors & Lobby	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Mastic under 9"x9" Aqua and White Floor Tile	1,900	SF	1st Floor Corridors, Lobby & Stairways, Library Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
2	12"x12" Tan Floor Tile	4,800	SF	2nd Floor Corridor	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
20	Mastic under 9"x9" Green Floor Tile (13)	866	SF	Kitchen	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Mastic under 12" x 12" Blue Floor Tile (11)	800	SF	Auditorium	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
22	9"x9" Green Floor Tile	866	SF	Kitchen	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	9"x9" Green Floor Tile Mastic (23)	143	SF	Kitchen	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	9"x9" White Floor Tile	480	SF	Rooms 119 and 125	CHR	MISC	N	None						High
26	9"x9" White Floor Tile Mastic (25)	480	SF	Rooms 119 and 125	CHR	MISC	N	None						Low
27	9"x9" Black Floor Tiles	1,750	SF	Rooms 119 and 125	CHR	MISC	N	None						Low
28	9"x9" Black Floor Tile Mastic	1,750	SF	Rooms 119 and 125	CHR	MISC	N	None						Low
29	Green Carpet Mastic	1,250	SF	Room 210, 226 and Auditorium	ASSUMED	MISC	N	None						Low
2M	12"x12" Tan Floor Tile Mastic	4,800	SF	2nd Floor Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	Pegboard	56	SF	Room 210, 226	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School University of Chicago-Donoghue Unit 26071 Building ID 6790

Address 707 E. 37th Street Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
31	9"x9" Green Floor Tile Mastic	2,700	SF	Lunchroom, Boy's Shop, and Security	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	9"x9" Green Floor Tile Mastic	800	SF	Teacher's Lunchroom and Counselor's Office, Rm 116	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	Clay Tile	1,200	SF	Kitchen	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
34	Clay Tile Mortar	1,200	SF	Kitchen	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
35	Cinderblock Mortar			Throughout Building	NO_ACBM	MISC								
36	Vibration Absorbers on Duct (3)	4	SF	2nd Floor Mechanical Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	Patch of Window Caulk	10	LF	Rooms 119 and 125	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
38	Blue Carpet Mastic	2,000	SF	Library, Engineer's Office, Counselor's Office, and Offices	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	9"x9" Brown Floor Tile	400	SF	Principals Office & Auditorium	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
3A	9"x9" Gray Floor Tile w/ White Streaks	1,835	SF	1st Floor Corridor and Lobby	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
3B	9"x9" White Floor Tile w/ Gray Streaks	4,165	SF	1st Floor Corridor and Lobby	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
3C	9"x9" Aqua Floor Tile w/ White Streaks	4,165	SF	1st Floor Corridor and Lobby	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
4	9"x9" Green Floor Tile	2,700	SF	Lunchroom, Boy's Shop and Security Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
40	9"x9" Brown Floor Tile Mastic	350	SF	Principal's Office and Auditorium	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	Green/Brown Carpet Mastic	200	SF	Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	Terrazzo Sinks	200	SF	Girl's and Boy's Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	9"x9" Flesh Colored Floor Tile	150	SF	Kitchen Locker Room, Stairs and Various Janitors Closets	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
44	9"x9" Flesh Colored Floor Tile Mastic	100	SF	Kitchen Locker Room, Janitor's Closet & Stairs	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School University of Chicago-Donoghue Unit 26071 Building ID 6790

Address 707 E. 37th Street Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
45	Purple Carpet Mastic	1,100	SF	Room 216	ASSUMED	MISC	N							
46	Green Carpet Mastic	1,500	SF	Room 102 and Computer Lab	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	Insulation Inside of Fire Doors	1,000	SF	Exit Doors and Boiler Room	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
48	Firebrick Inside Incinerator - Abated			Boiler Room	ABATED	MISC								
49	Insulation Beneath Metal Shell of Incinerator			Boiler Room	UNDEFINED									
5	9"x9" Brown Floor Tile	29,200	SF	All Classrooms	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
50	Ceramic Floor Tile Grout	3,000	SF	All Washroom Floors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	9"x9" Brown Floor Tile Mastic	170	SF	Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	Beige Brick (Exterior) Non AHERA			Rear Portion of Building	NO_ACBM	MISC								
53	Beige Brick Mortar (Exterior) Non AHERA			Rear Portion of Building	NO_ACBM	MISC								
54	Blue Face Brick Non AHERA			NW Exterior of Building	NO_ACBM	MISC								
55	Blue Face Brick Mortar Non AHERA			NW Exterior of Building	NO_ACBM	MISC								
56	Exterior Window Caulk - Non AHERA			Exterior Windows	NO_ACBM	MISC								
57	Glazing Non AHERA			Exterior Metal Panels Below Windows	NO_ACBM	MISC								
58	Window Glazing - Non AHERA			Exterior Windows	NO_ACBM	MISC								
59	See HA50- Same Material				UNDEFINED									
5M	9"x9" Brown Floor Tile Mastic	29,200	SF	All Classrooms	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
6	9"x9" Green Floor Tile	800	SF	Teacher's Lunchroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
60	Transite Replacement Ceiling Panels	18	SF	Gym Entrance	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	Brick			Boiler Room	NO_ACBM	MISC								
62	Brick Mortar			Boiler Room	NO_ACBM	MISC								
63	Stage Curtain (Replacement)	800	SF	Stage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
64	Boiler Gaskets	30	LF	Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
65	2' x 4' Lay-in Ceiling Panels	15,000	SF	Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School University of Chicago-Donoghue Unit 26071 Building ID 6790

Address 707 E. 37th Street Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
66	Green Mix Carpet Adhesive	750	SF	Room 221	ASSUMED	MISC	N	None						Low
67	12" x 12" Brown Mix Floor Tile as Patches	500	SF	Rms. 101, 104, 107, 108, 211, 212, 207, 208 & 220	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
68	12" x 12" Brown Mix Floor Tile as Patches Mastic	500	SF	Rms. 101, 104, 107, 108, 211, 212, 207, 208 & 220	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69	12" x 12" Spline Ceiling Tiles	37,000	SF	All Classrooms, Offices, Auditorium, Library, Lunchroom and (2nd Floor)Teacher's Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
7	Plaster	2,000	SF	Throughout facility	NO_ACBM	SURFACE								
70	Vault Door Lining	32	SF	Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
71	12" x 12" Light Brown w/Brown Floor Tile	126	SF	Landings and Storage on Sides of Stage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
72	12" x 12" Light Brown w/ Brown Floor Tile Mastic	126	SF	Landings and Storage on Sides of Stage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
73	12" x 12" White w/ Black Floor Tile	39	SF	Rooms 110 & 111	ASSUMED	MISC	N	None						High
74	12" x 12" White w/ Black Floor Tile Mastic	39	SF	Rooms 110 & 111	ASSUMED	MISC	N	None						Low
75	12" x 12" Black w/Gray Specks Floor Tile	119	SF	Rooms 110 & 111	ASSUMED	MISC	N	None						High
76	12" x 12" Black w/Gray Specks Floor Tile Mastic	119	SF	Rooms 110 & 111	ASSUMED	MISC	N	None						Low
77	Linoleum on Counters	120	SF	On Outside Walls in all Rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
78	Linoleum on Counters Adhesive	120	SF	On Outside Walls in all Rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
79	Linoleum	225	SF	Room 118	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
8	Transite Ceiling Panels-Abated			1st Floor Corridor	ABATED	MISC								
80	Linoleum Adhesive	225	SF	Room 104	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
81	Sink Undercoat	22	SF	Room 104, Custodian Staff Room, 111 & 110	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
82	Chalk Board/Poster Board Adhesive	340	SF	Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
83	Green Carpet Mastic	170	SF	Engineer's Office	ASSUMED	MISC	N	None						Low
84	12"x12" Light Brown Mix Floor Tile	10,000	SF	1st Floor Corridor, 118,119,125,126,12	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School University of Chicago-Donoghue Unit 26071 Building ID 6790

Address 707 E. 37th Street Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 4/18/2013
Inspector Name Patrick Hrycyk
100-09725 5/15/2013
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
1	Carpet removed and replaced with 12"x12" brown FT on top of the 9"x9"
10	Material has been removed.
11	
12	
13	
14	
15	
16	
17	
18	
19	
2	
20	
21	
22	
23	
25	Material Not Observed. Room 110 is now 119 and room 111 is now room 125.
26	Material Not Observed. Room 110 is now 119 and room 111 is now room 125.
27	Material Not Observed. Room 110 is now 119 and room 111 is now room 125.
28	Material Not Observed. Room 110 is now 119 and room 111 is now room 125.
29	Material Not Observed. Not in 210 or 226, Throw rugs on floor, no mastic on the rugs.
2M	
30	
31	

Chicago Public Schools

School University of Chicago-Donoghue Unit 26071 Building ID 6790

Address 707 E. 37th Street Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
32	
33	
34	
35	
36	
37	Room numbers changed from 110 and 111 to 119 and 125.
38	
39	
3A	
3B	
3C	
4	
40	
41	
42	
43	
44	
45	Material Not Observed.
46	
47	
48	Abated.
49	Abated in 2001.
5	
50	
51	
52	
53	
54	
55	

Chicago Public Schools

School University of Chicago-Donoghue Unit 26071 Building ID 6790

Address 707 E. 37th Street Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
56	
57	
58	
59	
5M	
6	
60	
61	
62	
63	
64	
65	
66	Material Not Observed.
67	
68	
69	
7	
70	
71	
72	
73	Material Not Observed.
74	Material Not Observed.
75	Material Not Observed.
76	Material Not Observed.
77	
78	
79	
8	Abated.
80	

Chicago Public Schools

School University of Chicago-Donoghue **Unit** 26071 **Building ID** 6790

Address 707 E. 37th Street **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
81	
82	
83	Carpet Has Been Removed.
84	
85	
9	Abated.
A	Material Not Observed. 12"x12" ceiling tiles glued
B	
C	
D	

Table II

Management Planner's Review

Chicago Public Schools

School University of Chicago-
Donoghue

Unit 26071

Building ID 6790

Address 707 E. 37th Street

Chicago, IL, 60653

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	9"x9" Brown Floor Tile (Under Carpet)	170	SF	Engineers Office	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Operations and Maintenance
10	Stage Curtain			Auditorium- Removed before 1998	Undefined						
11	12"x12" Blue Floor Tile	800	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
12	Replacement 12"x12" Ceiling Tiles	5,000	SF	Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
13	Insulation on Duct	35	SF	2nd Floor Mechanical Room	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
14	9"x9" Green Floor Tile Patches	143	SF	Kitchen	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
15	9"x9" Bright Green Floor Tile	200	SF	As Patches in 1st & 2nd Floor Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
16	Mastic under 9"x9" Bright Green Floor Tile	200	SF	As Patches in 1st and 2nd Floor Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
17	Mastic under 9"x9" Gray Floor Tiles (3A)	1,835	SF	1st Floor Corridors & Lobby	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
18	Mastic under 9"x9" White Floor Tile (3B)	1,835	SF	1st Floor Corridors & Lobby	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
19	Mastic under 9"x9" Aqua and White Floor Tile	1,900	SF	1st Floor Corridors, Lobby& Stairways, Library Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
2	12"x12" Tan Floor Tile	4,800	SF	2nd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
20	Mastic under 9"x9" Green Floor Tile (13)	866	SF	Kitchen	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
21	Mastic under 12" x 12" Blue Floor Tile (11)	800	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
22	9"x9" Green Floor Tile	866	SF	Kitchen	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
23	9"x9" Green Floor Tile Mastic (23)	143	SF	Kitchen	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
25	9"x9" White Floor Tile	480	SF	Rooms 119 and 125	Chrysotile	MISC	No		SF		
26	9"x9" White Floor Tile Mastic (25)	480	SF	Rooms 119 and 125	Chrysotile	MISC	No		SF		
27	9"x9" Black Floor Tiles	1,750	SF	Rooms 119 and 125	Chrysotile	MISC	No		SF		
28	9"x9" Black Floor Tile Mastic	1,750	SF	Rooms 119 and 125	Chrysotile	MISC	No		SF		
29	Green Carpet Mastic	1,250	SF	Room 210, 226 and Auditorium	Assumed	MISC	No		SF		
2M	12"x12" Tan Floor Tile Mastic	4,800	SF	2nd Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
30	Pegboard	56	SF	Room 210, 226	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
31	9"x9" Green Floor Tile Mastic	2,700	SF	Lunchroom, Boy's Shop, and Security	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
32	9"x9" Green Floor Tile Mastic	800	SF	Teacher's Lunchroom and Counselor's Office, Rm 116	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
33	Clay Tile	1,200	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
34	Clay Tile Mortar	1,200	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
35	Cinderblock Mortar			Throughout Building	No ACBM	MISC					
36	Vibration Absorbers on Duct (3)	4	SF	2nd Floor Mechanical Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
37	Patch of Window Caulk	10	LF	Rooms 119 and 125	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
38	Blue Carpet Mastic	2,000	SF	Library, Engineer's Office, Counselor's	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School University of Chicago-
Donoghue

Unit 26071

Building ID 6790

Address 707 E. 37th Street

Chicago, IL, 60653

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Office, and Offices							
39	9"x9" Brown Floor Tile	400	SF	Principals Office & Auditorium	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
3A	9"x9" Gray Floor Tile w/ White Streaks	1,835	SF	1st Floor Corridor and Lobby	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
3B	9"x9" White Floor Tile w/ Gray Streaks	4,165	SF	1st Floor Corridor and Lobby	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
3C	9"x9" Aqua Floor Tile w/ White Streaks	4,165	SF	1st Floor Corridor and Lobby	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
4	9"x9" Green Floor Tile	2,700	SF	Lunchroom, Boy's Shop and Security Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
40	9"x9" Brown Floor Tile Mastic	350	SF	Principal's Office and Auditorium	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
41	Green/Brown Carpet Mastic	200	SF	Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
42	Terrazzo Sinks	200	SF	Girl's and Boy's Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
43	9"x9" Flesh Colored Floor Tile	150	SF	Kitchen Locker Room, Stairs and Various Janitors Closets	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
44	9"x9" Flesh Colored Floor Tile Mastic	100	SF	Kitchen Locker Room, Janitor's Closet & Stairs	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
45	Purple Carpet Mastic	1,100	SF	Room 216	Assumed	MISC	No		SF		
46	Green Carpet Mastic	1,500	SF	Room 102 and Computer Lab	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
47	Insulation Inside of Fire Doors	1,000	SF	Exit Doors and Boiler Room	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
48	Firebrick Inside Incinerator - Abated			Boiler Room	Abated	MISC					
49	Insulation Beneath Metal Shell of Incinerator			Boiler Room	Undefined						
5	9"x9" Brown Floor Tile	29,200	SF	All Classrooms	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
50	Ceramic Floor Tile Grout	3,000	SF	All Washroom Floors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
51	9"x9" Brown Floor Tile Mastic	170	SF	Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
52	Beige Brick (Exterior) Non AHERA			Rear Portion of Building	No ACBM	MISC					
53	Beige Brick Mortar (Exterior) Non AHERA			Rear Portion of Building	No ACBM	MISC					
54	Blue Face Brick Non AHERA			NW Exterior of Building	No ACBM	MISC					
55	Blue Face Brick Mortar Non AHERA			NW Exterior of Building	No ACBM	MISC					
56	Exterior Window Caulk - Non AHERA			Exterior Windows	No ACBM	MISC					
57	Glazing Non AHERA			Exterior Metal Panels Below Windows	No ACBM	MISC					
58	Window Glazing - Non AHERA			Exterior Windows	No ACBM	MISC					
59	See HA50- Same Material				Undefined						
5M	9"x9" Brown Floor Tile Mastic	29,200	SF	All Classrooms	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
6	9"x9" Green Floor Tile	800	SF	Teacher's Lunchroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
60	Transite Replacement Ceiling Panels	18	SF	Gym Entrance	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
61	Brick			Boiler Room	No ACBM	MISC					

Chicago Public Schools

School University of Chicago-
Donoghue

Unit 26071

Building ID 6790

Address 707 E. 37th Street

Chicago, IL, 60653

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
62	Brick Mortar			Boiler Room	No ACBM	MISC					
63	Stage Curtain (Replacement)	800	SF	Stage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
64	Boiler Gaskets	30	LF	Boiler Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
65	2' x 4' Lay-in Ceiling Panels	15,000	SF	Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
66	Green Mix Carpet Adhesive	750	SF	Room 221	Assumed	MISC	No		SF		
67	12" x 12" Brown Mix Floor Tile as Patches	500	SF	Rms. 101, 104, 107, 108, 211, 212, 207, 208 & 220	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
68	12" x 12" Brown Mix Floor Tile as Patches Mastic	500	SF	Rms. 101, 104, 107, 108, 211, 212, 207, 208 & 220	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
69	12" x 12" Spline Ceiling Tiles	37,000	SF	All Classrooms, Offices, Auditorium, Library, Lunchroom and (2nd Floor)Teacher's Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
7	Plaster	2,000	SF	Throughout facility	No ACBM	SURFACE			SF		
70	Vault Door Lining	32	SF	Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
71	12" x 12" Light Brown w/Brown Floor Tile	126	SF	Landings and Storage on Sides of Stage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
72	12" x 12" Light Brown w/ Brown Floor Tile Mastic	126	SF	Landings and Storage on Sides of Stage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
73	12" x 12" White w/ Black Floor Tile	39	SF	Rooms 110 & 111	Assumed	MISC	No		SF		
74	12" x 12" White w/ Black Floor Tile Mastic	39	SF	Rooms 110 & 111	Assumed	MISC	No		SF		
75	12" x 12" Black w/Gray Specks Floor Tile	119	SF	Rooms 110 & 111	Assumed	MISC	No		SF		
76	12" x 12" Black w/Gray Specks Floor Tile Mastic	119	SF	Rooms 110 & 111	Assumed	MISC	No		SF		
77	Linoleum on Counters	120	SF	On Outside Walls in all Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
78	Linoleum on Counters Adhesive	120	SF	On Outside Walls in all Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
79	Linoleum	225	SF	Room 118	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
8	Transite Ceiling Panels-Abated			1st Floor Corridor	Abated	MISC					
80	Linoleum Adhesive	225	SF	Room 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
81	Sink Undercoat	22	SF	Room 104, Custodian Staff Room, 111 & 110	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
82	Chalk Board/Poster Board Adhesive	340	SF	Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
83	Green Carpet Mastic	170	SF	Engineer's Office	Assumed	MISC	No		SF		
84	12"x12" Light Brown Mix Floor Tile	10,000	SF	1st Floor Corridor, 118,119,125,126,127,128, 202,206,208,209,215,Stairs	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School University of Chicago-
Donoghue

Unit 26071

Building ID 6790

Address 707 E. 37th Street

Chicago, IL, 60653

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
85	12"x12" Light Brown Mix Floor Tile Mastic	10,000	SF	1st Floor Corridor, 118,119,125,126,127,128, 202,206,208,209,215,Stairs	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
9	1x1 Fissured Ceiling Tile - Abated			Throughout the Building	Abated	MISC					
A	Pipe Joint Insulation	200	SF	Above ceilings	Chrysotile	TSI	Yes		SF		
B	Boiler Breeching			Boiler Room- Abated 1994	Abated						
C	Boiler Insulation			Boiler Room- Abated 1994	Abated						
D	Tank Insulation			Boiler Room- Abated 1994	Abated						

Chicago Public Schools

School University of Chicago-
Donoghue
Address 707 E. 37th Street

Unit 26071
Chicago, IL, 60653

Building ID 6790
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	4/29/2013
Manager Planner Name	Stephen Diblik
100-05171	5/15/2013
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
2	
20	
21	
22	
23	
25	
26	
27	
28	
29	
2M	
30	
31	
32	

Chicago Public Schools

School University of Chicago-
Donoghue

Unit 26071

Building ID 6790

Address 707 E. 37th Street

Chicago, IL, 60653

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
33	
34	
35	
36	
37	
38	
39	
3A	
3B	
3C	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
5	
50	
51	
52	
53	

Chicago Public Schools

School University of Chicago-
Donoghue

Unit 26071

Building ID 6790

Address 707 E. 37th Street

Chicago, IL, 60653

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
54	
55	
56	
57	
58	
59	
5M	
6	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
7	
70	
71	
72	
73	
74	
75	
76	

Chicago Public Schools

School University of Chicago-
Donoghue

Unit 26071

Building ID 6790

Address 707 E. 37th Street

Chicago, IL, 60653

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
77	
78	
79	
8	
80	
81	
82	
83	
84	
85	
9	
A	
B	
C	
D	

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile (Under Carpet)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**
MATERIAL LOCATION: **Engineers Office**
MATERIAL QUANTITY: **170** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Carpet removed and replaced with 12"x12" brown FT on top of the 9"x9"**

Inspector's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile (Under Carpet)**
MATERIAL LOCATION: **Engineers Office**
MATERIAL QUANTITY: **170** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **04/29/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Stage Curtain**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium- Removed before 1998**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material has been removed.**

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Stage Curtain**
MATERIAL LOCATION: **Auditorium- Removed before 1998**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **800**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Replacement 12"x12" Ceiling Tiles**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Replacement 12"x12" Ceiling Tiles**
MATERIAL LOCATION: **Classrooms**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Insulation on Duct**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd Floor Mechanical Room**

MATERIAL QUANTITY: **35**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Insulation on Duct**
MATERIAL LOCATION: **2nd Floor Mechanical Room**
MATERIAL QUANTITY: **35** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile Patches**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **143**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile Patches**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **143** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **04/29/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **9"x9" Bright Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **As Patches in 1st & 2nd Floor Corridors**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **9"x9" Bright Green Floor Tile**
MATERIAL LOCATION: **As Patches in 1st & 2nd Floor Corridors**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Mastic under 9"x9" Bright Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **As Patches in 1st and 2nd Floor Corridors**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Mastic under 9"x9" Bright Green Floor Tile**
MATERIAL LOCATION: **As Patches in 1st and 2nd Floor Corridors**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Mastic under 9"x9" Gray Floor Tiles (3A)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridors & Lobby**
MATERIAL QUANTITY: **1835** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Mastic under 9"x9" Gray Floor Tiles (3A)**
MATERIAL LOCATION: **1st Floor Corridors & Lobby**
MATERIAL QUANTITY: **1835** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Mastic under 9"x9" White Floor Tile (3B)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Corridors & Lobby**

MATERIAL QUANTITY: **1835**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Mastic under 9"x9" White Floor Tile (3B)**
MATERIAL LOCATION: **1st Floor Corridors & Lobby**
MATERIAL QUANTITY: **1835** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Mastic under 9"x9" Aqua and White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **1st Floor Corridors, Lobby & Stairways, Library Office**

MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Mastic under 9"x9" Aqua and White Floor Tile**
MATERIAL LOCATION: **1st Floor Corridors, Lobby& Stairways, Library Office**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **04/29/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Corridor**
MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile**
MATERIAL LOCATION: **2nd Floor Corridor**
MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Mastic under 9"x9" Green Floor Tile (13)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **866** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Mastic under 9"x9" Green Floor Tile (13)**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **866** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **04/29/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 26071 BUIDLING ID: 6790
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Patrick Hrycyk
SCHOOL NAME: University of Chicago-Donoghue INSPECTION DATE: 4/18/2013
ADDRESS: 707 E. 37th Street IDPH LICENSE NO: 100-09725

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 21
MATERIAL DESCRIPTION: Mastic under 12" x 12" Blue Floor Tile (11)
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **800**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Mastic under 12" x 12" Blue Floor Tile (11)**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **04/29/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **866** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **866** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile Mastic (23)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **143** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile Mastic (23)**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **143** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **04/29/2013**

Chicago Public Schools

Carnow, Conibear and Associates
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **9"x9" White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **High**
MATERIAL LOCATION: **Rooms 119 and 125**
MATERIAL QUANTITY: **480** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed. Room 110 is now 119 and room 111 is now room 125.**

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **9"x9" White Floor Tile**
MATERIAL LOCATION: **Rooms 119 and 125**
MATERIAL QUANTITY: **480** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **04/29/2013**

Chicago Public Schools

Carnow, Conibear and Associates
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **9"x9" White Floor Tile Mastic (25)**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Rooms 119 and 125**

MATERIAL QUANTITY: **480**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed. Room 110 is now 119 and room 111 is now room 125.**

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **9"x9" White Floor Tile Mastic (25)**
MATERIAL LOCATION: **Rooms 119 and 125**
MATERIAL QUANTITY: **480** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **9"x9" Black Floor Tiles**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Rooms 119 and 125**

MATERIAL QUANTITY: **1750**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed. Room 110 is now 119 and room 111 is now room 125.**

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **9"x9" Black Floor Tiles**
MATERIAL LOCATION: **Rooms 119 and 125**
MATERIAL QUANTITY: **1750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/29/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **9"x9" Black Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Rooms 119 and 125**

MATERIAL QUANTITY: **1750**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed. Room 110 is now 119 and room 111 is now room 125.**

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **9"x9" Black Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 119 and 125**
MATERIAL QUANTITY: **1750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **04/29/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Green Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 210, 226 and Auditorium**

MATERIAL QUANTITY: **1250**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed. Not in 210 or 226, Throw rugs on floor, no mastic on the rugs.**

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Green Carpet Mastic**
MATERIAL LOCATION: **Room 210, 226 and Auditorium**
MATERIAL QUANTITY: **1250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2M**
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Corridor**
MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **2M**
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile Mastic**
MATERIAL LOCATION: **2nd Floor Corridor**
MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **04/29/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Pegboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 210, 226**
MATERIAL QUANTITY: **56** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Pegboard**
MATERIAL LOCATION: **Room 210, 226**
MATERIAL QUANTITY: **56** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunchroom, Boy's Shop, and Security**

MATERIAL QUANTITY: **2700**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile Mastic**
MATERIAL LOCATION: **Lunchroom, Boy's Shop, and Security**
MATERIAL QUANTITY: **2700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Teacher's Lunchroom and Counselor's Office, Rm 116**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile Mastic**
MATERIAL LOCATION: **Teacher's Lunchroom and Counselor's Office, Rm 116**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Clay Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Clay Tile**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **04/29/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Clay Tile Mortar**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Clay Tile Mortar**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Cinderblock Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Cinderblock Mortar**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Vibration Absorbers on Duct (3)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Mechanical Room**
MATERIAL QUANTITY: **4** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Vibration Absorbers on Duct (3)**
MATERIAL LOCATION: **2nd Floor Mechanical Room**
MATERIAL QUANTITY: **4** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **04/29/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 26071 BUILDING ID: 6790
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Patrick Hrycyk
SCHOOL NAME: University of Chicago-Donoghue INSPECTION DATE: 4/18/2013
ADDRESS: 707 E. 37th Street IDPH LICENSE NO: 100-09725

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 37
MATERIAL DESCRIPTION: Patch of Window Caulk
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Rooms 119 and 125
MATERIAL QUANTITY: 10 MATERIAL UNITS: LF
DAMAGE QUANTITY: DAMAGE UNITS: LF

COMMENTS: Room numbers changed from 110 and 111 to 119 and 125.

Inspector's Signature:



Date: 04/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Patch of Window Caulk**
MATERIAL LOCATION: **Rooms 119 and 125**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Library, Engineer's Office, Counselor's Office, and Offices**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
MATERIAL LOCATION: **Library, Engineer's Office, Counselor's Office, and Offices**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **04/29/2013**

Chicago Public Schools

Carnow, Conibear and Associates
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Principals Office & Auditorium**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile**
MATERIAL LOCATION: **Principals Office & Auditorium**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3A**
MATERIAL DESCRIPTION: **9"x9" Gray Floor Tile w/ White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **1st Floor Corridor and Lobby**

MATERIAL QUANTITY: **1835**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **3A**
MATERIAL DESCRIPTION: **9"x9" Gray Floor Tile w/ White Streaks**
MATERIAL LOCATION: **1st Floor Corridor and Lobby**
MATERIAL QUANTITY: **1835** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3B**
MATERIAL DESCRIPTION: **9"x9" White Floor Tile w/ Gray Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **1st Floor Corridor and Lobby**
MATERIAL QUANTITY: **4165** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **3B**
MATERIAL DESCRIPTION: **9"x9" White Floor Tile w/ Gray Streaks**
MATERIAL LOCATION: **1st Floor Corridor and Lobby**
MATERIAL QUANTITY: **4165** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3C**
MATERIAL DESCRIPTION: **9"x9" Aqua Floor Tile w/ White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **1st Floor Corridor and Lobby**
MATERIAL QUANTITY: **4165** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **3C**
MATERIAL DESCRIPTION: **9"x9" Aqua Floor Tile w/ White Streaks**
MATERIAL LOCATION: **1st Floor Corridor and Lobby**
MATERIAL QUANTITY: **4165** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**

MATERIAL LOCATION: **Lunchroom, Boy's Shop and Security Office**

MATERIAL QUANTITY: **2700**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile**
MATERIAL LOCATION: **Lunchroom, Boy's Shop and Security Office**
MATERIAL QUANTITY: **2700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Principal's Office and Auditorium**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile Mastic**
MATERIAL LOCATION: **Principal's Office and Auditorium**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Green/Brown Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Green/Brown Carpet Mastic**
MATERIAL LOCATION: **Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Terrazzo Sinks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Girl's and Boy's Washrooms**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Terrazzo Sinks**
MATERIAL LOCATION: **Girl's and Boy's Washrooms**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **04/29/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **9"x9" Flesh Colored Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **Kitchen Locker Room, Stairs and Various Janitors Closets**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **9"x9" Flesh Colored Floor Tile**
MATERIAL LOCATION: **Kitchen Locker Room, Stairs and Various Janitors Closets**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **9"x9" Flesh Colored Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Kitchen Locker Room, Janitor's Closet & Stairs**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **9"x9" Flesh Colored Floor Tile Mastic**
MATERIAL LOCATION: **Kitchen Locker Room, Janitor's Closet & Stairs**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **Purple Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 216**

MATERIAL QUANTITY: **1100**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed.**

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **Purple Carpet Mastic**
MATERIAL LOCATION: **Room 216**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **Green Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 102 and Computer Lab**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **Green Carpet Mastic**
MATERIAL LOCATION: **Room 102 and Computer Lab**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **Insulation Inside of Fire Doors**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Exit Doors and Boiler Room**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **Insulation Inside of Fire Doors**
MATERIAL LOCATION: **Exit Doors and Boiler Room**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Firebrick Inside Incinerator - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Abated.**

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Firebrick Inside Incinerator - Abated**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Insulation Beneath Metal Shell of Incinerator**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Abated in 2001.**

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Insulation Beneath Metal Shell of Incinerator**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **All Classrooms**
MATERIAL QUANTITY: **29200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile**
MATERIAL LOCATION: **All Classrooms**
MATERIAL QUANTITY: **29200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **Ceramic Floor Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All Washroom Floors**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **Ceramic Floor Tile Grout**
MATERIAL LOCATION: **All Washroom Floors**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **04/29/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **170**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile Mastic**
MATERIAL LOCATION: **Engineer's Office**
MATERIAL QUANTITY: **170** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **Beige Brick (Exterior) Non AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rear Portion of Building**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **Beige Brick (Exterior) Non AHERA**

MATERIAL LOCATION: **Rear Portion of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Beige Brick Mortar (Exterior) Non AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rear Portion of Building**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Beige Brick Mortar (Exterior) Non AHERA**
MATERIAL LOCATION: **Rear Portion of Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Blue Face Brick Non AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **NW Exterior of Building**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Blue Face Brick Non AHERA**
MATERIAL LOCATION: **NW Exterior of Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/29/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Blue Face Brick Mortar Non AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **NW Exterior of Building**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Blue Face Brick Mortar Non AHERA**
MATERIAL LOCATION: **NW Exterior of Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Exterior Window Caulk - Non AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior Windows**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Exterior Window Caulk - Non AHERA**
MATERIAL LOCATION: **Exterior Windows**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **Glazing Non AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior Metal Panels Below Windows**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **Glazing Non AHERA**

MATERIAL LOCATION: **Exterior Metal Panels Below Windows**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **Window Glazing - Non AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior Windows**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **Window Glazing - Non AHERA**

MATERIAL LOCATION: **Exterior Windows**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **See HA50- Same Material**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **See HA50- Same Material**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5M**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All Classrooms**
MATERIAL QUANTITY: **29200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **5M**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile Mastic**
MATERIAL LOCATION: **All Classrooms**
MATERIAL QUANTITY: **29200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **04/29/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **Teacher's Lunchroom**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile**
MATERIAL LOCATION: **Teacher's Lunchroom**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **Transite Replacement Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym Entrance**
MATERIAL QUANTITY: **18** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **Transite Replacement Ceiling Panels**
MATERIAL LOCATION: **Gym Entrance**
MATERIAL QUANTITY: **18** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **Brick**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Brick Mortar**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **Stage Curtain (Replacement)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Stage**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **Stage Curtain (Replacement)**
MATERIAL LOCATION: **Stage**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **Boiler Gaskets**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **Boiler Gaskets**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **2' x 4' Lay-in Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Corridors**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **2' x 4' Lay-in Ceiling Panels**
MATERIAL LOCATION: **Corridors**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **Green Mix Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 221**

MATERIAL QUANTITY: **750**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed.**

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **Green Mix Carpet Adhesive**
MATERIAL LOCATION: **Room 221**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile as Patches**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rms. 101, 104, 107, 108, 211, 212, 207, 208 & 220**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile as Patches**
MATERIAL LOCATION: **Rms. 101, 104, 107, 108, 211, 212, 207, 208 & 220**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile as Patches Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Rms. 101, 104, 107, 108, 211, 212, 207, 208 & 220**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile as Patches Mastic**
MATERIAL LOCATION: **Rms. 101, 104, 107, 108, 211, 212, 207, 208 & 220**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **12" x 12" Spline Ceiling Tiles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**


MATERIAL LOCATION: **All Classrooms, Offices, Auditorium, Library, Lunchroom and (2nd Floor)Teacher's Lounge**

MATERIAL QUANTITY: **37000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **12" x 12" Spline Ceiling Tiles**
MATERIAL LOCATION: **All Classrooms, Offices, Auditorium, Library, Lunchroom and (2nd Floor)Teacher's Lounge**
MATERIAL QUANTITY: **37000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **04/29/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout facility**

MATERIAL QUANTITY: **2000**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **Plaster**
MATERIAL LOCATION: **Throughout facility**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **04/29/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Vault Door Lining**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office**
MATERIAL QUANTITY: **32** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Vault Door Lining**
MATERIAL LOCATION: **Office**
MATERIAL QUANTITY: **32** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**

MATERIAL LOCATION: **Landings and Storage on Sides of Stage**

MATERIAL QUANTITY: **126**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/Brown Floor Tile**
MATERIAL LOCATION: **Landings and Storage on Sides of Stage**
MATERIAL QUANTITY: **126** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Landings and Storage on Sides of Stage**
MATERIAL QUANTITY: **126** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ Brown Floor Tile Mastic**
MATERIAL LOCATION: **Landings and Storage on Sides of Stage**
MATERIAL QUANTITY: **126** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **12" x 12" White w/ Black Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **High**

MATERIAL LOCATION: **Rooms 110 & 111**

MATERIAL QUANTITY: **39**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed.**

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **12" x 12" White w/ Black Floor Tile**
MATERIAL LOCATION: **Rooms 110 & 111**
MATERIAL QUANTITY: **39** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **12" x 12" White w/ Black Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Rooms 110 & 111**

MATERIAL QUANTITY: **39**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed.**

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **12" x 12" White w/ Black Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 110 & 111**
MATERIAL QUANTITY: **39** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **12" x 12" Black w/Gray Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **High**

MATERIAL LOCATION: **Rooms 110 & 111**

MATERIAL QUANTITY: **119**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed.**

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **12" x 12" Black w/Gray Specks Floor Tile**
MATERIAL LOCATION: **Rooms 110 & 111**
MATERIAL QUANTITY: **119** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **12" x 12" Black w/Gray Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Rooms 110 & 111**

MATERIAL QUANTITY: **119**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed.**

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **12" x 12" Black w/Gray Specks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 110 & 111**
MATERIAL QUANTITY: **119** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **Linoleum on Counters**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **On Outside Walls in all Rooms**

MATERIAL QUANTITY: **120**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **Linoleum on Counters**
MATERIAL LOCATION: **On Outside Walls in all Rooms**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **Linoleum on Counters Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **On Outside Walls in all Rooms**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **Linoleum on Counters Adhesive**
MATERIAL LOCATION: **On Outside Walls in all Rooms**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **Room 118**
MATERIAL QUANTITY: **225** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **Linoleum**
MATERIAL LOCATION: **Room 118**
MATERIAL QUANTITY: **225** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **Transite Ceiling Panels-Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Abated.**

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **Transite Ceiling Panels-Abated**
MATERIAL LOCATION: **1st Floor Corridor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **Linoleum Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 104**
MATERIAL QUANTITY: **225** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **Linoleum Adhesive**
MATERIAL LOCATION: **Room 104**
MATERIAL QUANTITY: **225** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **Sink Undercoat**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 104, Custodian Staff Room, 111 & 110**
MATERIAL QUANTITY: **22** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **Sink Undercoat**
MATERIAL LOCATION: **Room 104, Custodian Staff Room, 111 & 110**
MATERIAL QUANTITY: **22** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **Chalk Board/Poster Board Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY: **340**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **Chalk Board/Poster Board Adhesive**
MATERIAL LOCATION: **Classrooms**
MATERIAL QUANTITY: **340** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **04/29/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **Green Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **170**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Carpet Has Been Removed.**

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **Green Carpet Mastic**
MATERIAL LOCATION: **Engineer's Office**
MATERIAL QUANTITY: **170** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **12"x12" Light Brown Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor, 118,119,125,126,127,128, 202,206,208,209,215,Stairs**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **12"x12" Light Brown Mix Floor Tile**
MATERIAL LOCATION: **1st Floor Corridor, 118,119,125,126,127,128, 202,206,208,209,215,Stairs**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **12"x12" Light Brown Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor, 118,119,125,126,127,128, 202,206,208,209,215,Stairs**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **12"x12" Light Brown Mix Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Corridor, 118,119,125,126,127,128, 202,206,208,209,215,Stairs**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **1x1 Fissured Ceiling Tile - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Throughout the Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Abated.**

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **1x1 Fissured Ceiling Tile - Abated**
MATERIAL LOCATION: **Throughout the Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Pipe Joint Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Above ceilings**

MATERIAL QUANTITY: **200**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed. 12"x12" ceiling tiles glued**

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Pipe Joint Insulation**
MATERIAL LOCATION: **Above ceilings**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Boiler Breeching**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room- Abated 1994**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Boiler Breeching**
MATERIAL LOCATION: **Boiler Room- Abated 1994**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Boiler Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room- Abated 1994**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Boiler Insulation**

MATERIAL LOCATION: **Boiler Room- Abated 1994**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/29/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Patrick Hrycyk**
SCHOOL NAME: **University of Chicago-Donoghue** INSPECTION DATE: **4/18/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Tank Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room- Abated 1994**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26071** BUIDLING ID: **6790**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **University of Chicago-
Donoghue** REVIEW DATE: **4/29/2013**
ADDRESS: **707 E. 37th Street** IDPH LICENSE NO: **100-09725**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Tank Insulation**
MATERIAL LOCATION: **Boiler Room- Abated 1994**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: *Stephen Diblik* Date: **04/29/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

ENDORSEMENTS	TC EXPIRES
INSPECTOR	12/9/2012
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	11/2/2012

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.


Illinois Department of
PUBLIC HEALTH

ASBESTOS PROFESSIONAL LICENSE

ID NUMBER	ISSUED	EXPIRES
100 - 09725	5/31/2012	05/15/2013

PATRICK L HRYCIK
2942 N. MASON AVE
CHICAGO, IL 60634

Environmental Health



CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that PATRICK HRYCYK
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 12/07/2012 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools;
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



N. Penoff

12/07/2012

Course Dates:

12/07/2013

Expires:

1212BIR02

Certificate Number:

Phone Number: (312) 491-0081

Director of Training

Nicholas J. Penoff

Doctor of Public Health

FORM # A-010



Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Steve Diblik

has successfully completed the 4 hour Asbestos Building Inspector Refresher Course and has passed the competency exam with a minimum score of 70%. This course is accredited by the **Illinois Department of Public Health** and the **Indiana Department of Environmental Management** for purposes of accreditation in accordance with EPA 40 CFR763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II. This training course complies with the requirements of TSCA Title II and is accredited by the state of Wisconsin **Department of Health Services** under CH.DHS159, Wisconsin Administration Code.

Asbestos Abatement Building Inspector Refresher

Certificate: BIRWI1301110170

Location: 12304 75th Street Kenosha, WI 53142

Course Date: 1/11/2013

Examination Date: 1/11/2013

Expiration Date: 1/11/2014

Issue Date: 1/11/2013



Duplicate Original

Kathy DeSalvo, Director

2013

Stephen Diblik

Illinois Licensed Asbestos Inspector, Management Planner,
Project Manager and Air Sampling Professional



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 05171

ISSUED
4/4/2012

EXPIRES
05/15/2013

STEPHEN C DIBLIK
300 W. Adams Street, Suite 120
Chicago, IL 60606

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

1/13/2013

MANAGEMENT PLANNER

1/19/2013

PROJECT MANAGER

12/15/2012

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

**CARNOW
CONIBEAR**



Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training and Supply, Inc. certifies that

Stephen Diblik

has successfully completed the 4 hour Asbestos Management Planner Refresher Course
and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department
of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance
with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: MPR1302250732

Exam Date: 2/25/2013

Course Date: 2/25/2013

Expiration Date: 2/25/2014


Kathy DeSalvo
Director

2013

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed