

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Leased-Main	1953	2	58,580
Campus Total			58,580

Category : Exterior Building : Leased-Main

aicgo	I y . LAIGHOI		Building . Leased-Main					
						Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
ntrance)							
	Entrance Control - Audio and Video	1	1	EA	7	6-10 years		
	Exterior Doors - Exterior Steel Door	1	4	EA	7	10+ years		
	Exterior Doors - Exterior Steel Door	2	2	EA	7	10+ years		
	Exterior Stairs - Concrete	2	6	LF	7	10+ years		
	Entrance Control - Audio	3	1	EA	7	6-10 years		
	Exterior Doors - Exterior Steel Door	3	2	EA	6	6-10 years		
	Exterior Stairs - Concrete	3	7	LF	7	10+ years		
	Exterior Doors - Exterior Wood Door	4	2	EΑ	6	10+ years		
	Exterior Stairs - Stone	4	6	LF	7	10+ years		
	Entrance Control - Audio and Video	5 - Main	1	EΑ	7	10+ years		
	Exterior Doors - Exterior Steel Door	5 - Main	4	EΑ	6	10+ years		
	Exterior Doors - Side lite	5 - Main	1	EΑ	7	10+ years		
	Exterior Stairs - Concrete	5 - Main	15	LF	7	10+ years		
	Exterior Doors - Exterior Steel Door	6	2	EA	6	10+ years		
	Ramps - Concrete	6	2	LF	7	10+ years		
	Exterior Doors - Side lite	6 northeast side	1	EA	6	6-10 years		
	Exterior Doors - Store Front	6 northeast side	2	EA	7	10+ years		
	Exterior Doors - Transom Lite	6 northeast side	3	EA	6	6-10 years		
	Exterior Stairs - Concrete	6 northeast side	6	LF	7	10+ years		
	Exterior Doors - Exterior Steel Door	8 - Boiler Room	1	EA	7	10+ years		
	Exterior Doors - Transom Lite	8 - Boiler Room	1	EA	7	10+ years		
	Exterior Stairs - Concrete	8 - Boiler Room	45	LF	7	10+ years		
	Stair Handrail - Steel_Stair Handrail	8 - Boiler Room	14	LF	6	6-10 years		



Category : Exterior			Building : Leased-Main				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Foundati	on						
	Foundation - Concrete	Entire Building	988	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	58,560	SF	7	10+ years	
	Superstructure - Concrete	Entire Building	20	SF	7	10+ years	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	7	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	7	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	4	EA	6	10+ years	
Roof Sys	atem						
Ţ.	Coping - Metal	1 - South Roof	355	LF	7	10+ years	
	Downspouts - Exterior Downspouts	1 - South Roof	156	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	1 - South Roof	6,540	SF	5	0-1 year	Missing ballast/exposed bubbling ta
	Roof Structure - Concrete	1 - South Roof	6,540	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	2- Central Upper Roof	40	LF	5	6-10 years	
	Liner					, , , , , , ,	
	Coping - Metal	2- Central Upper Roof	452	LF	7	10+ years	
	Coping - Stone	2- Central Upper Roof	15	LF	7	10+ years	
	Downspouts - Interior Downspouts	2- Central Upper Roof	213	LF	7	10+ years	
	Roof - Modified Bitumen	2- Central Upper Roof	10,465	SF	6	6-10 years	
	Roof Hatch - Metal	2- Central Upper Roof	1	ĒΑ	3	0-1 year	Not used.
	Roof Structure - Concrete	2- Central Upper Roof	10,465	SF	7	10+ years	
	Coping - Metal	3 - Northwest Roof	305	LF	7	10+ years	
	Downspouts - Interior Downspouts	3 - Northwest Roof	59	LF	7	10+ years	
	Roof - Modified Bitumen	3 - Northwest Roof	5,760	SF	6	6-10 years	Minor ponding stains.
	Roof Structure - Concrete	3 - Northwest Roof	5,760	SF	7	10+ years	will of portaining stainles.
	Coping - Metal	4 - North Roof	81	LF	7	10+ years	
	Downspouts - Interior Downspouts	4 - North Roof	43	LF	6	2-5 years	
	Roof - Asphalt Gravel Ballast	4 - North Roof	1,620	SF	5	0-1 year	Missing Ballast/exposed bubbling ta
	Roof Hatch - Metal	4 - North Roof	•	EA	3	1-2 years	Not used.
	Roof Structure - Concrete		1 620	SF	3 7		Not used.
		4 - North Roof	1,620			10+ years	
	Coping - Metal	5 - North Roof	68	LF	7	10+ years	
	Downspouts - Interior Downspouts	5 - North Roof	9	LF	6	10+ years	AR THE COLUMN
	Roof - Asphalt Gravel Ballast	5 - North Roof	1,035	SF	5	0-1 year	Missing ballast/bubbling tar exposed
	Roof Structure - Concrete	5 - North Roof	1,035	SF	7	10+ years	
Walls							
	Canopy - Concrete/ Stucco	Entire Building	245	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	20,546	SF	7	10+ years	
	Exterior Walls - Precast Panel Wall	Entire Building	2,200	SF	7	10+ years	



Catego	ry : Exterior		В	Building : Leased-Main				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Windows								
v v ii i i i i i i i i	Clerestory - Glass Double-Pane	Entire Building	90	SF	7	10+ years		
	Curtain wall - Glazed Double Pane	Entire Building	528	SF	7	10+ years		
	Lintels - Steel	Entire Building	1,469	LF	7			
		Entire Building				10+ years		
	Skylite - Lexan Skylite - Lexan		36 6	SF SF	7 7	10+ years		
		Entire Building		SF	7	10+ years		
	Skylite - Lexan	Entire Building	18			10+ years		
	Windows - Insulated Panel	Entire Building	327	SF	7	10+ years		
	Windows - Louver	Entire Building	60	SF	7	10+ years		
	Windows - Sash Aluminum Double-pane	Entire Building	9,341	SF	7	10+ years		
Catego	ry : Electrical		В	uilding	: Lease	d-Main		
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Emerger	ncy System		•			•		
	Security System - CCTV	Entire Building	58,580	SF	6	6-10 years		
	Security System - Intrusion Detection	Entire Building	58,580	SF	6	6-10 years		
	Exit Signs - Corridors and Stairs	Entire Building	27	EA	6	6-10 years		
	Exit Signs - Multipurpose Room	Entire Building	5	EA	4	0-10 years	Hard to read.	
	Emergency Battery Packs - Corridors and	Entire Building	25	EA	6	6-10 years	riaid to read.	
	Stairs	· ·				•		
	Emergency Battery Packs - Multipurpose Room	Entire Building	3	EA	6	6-10 years		
	Emergency Battery Packs - Students Toilets	Entire Building	15	EA	6	6-10 years		
	Emergency A/C Power - Corridors and	Entire Building	4,450	SF	6	10+ years		
	Stairs	g	1,122		-	, , , , , , , , , , , , , , , , , , , ,		
	Emergency A/C Power - Multipurpose	Entire Building	900	SF	6	10+ years		
	Room	g			-	, , , , , , , , , , , , , , , , , , , ,		
	Emergency A/C Power - Students Toilets	Entire Building	1,100	SF	6	10+ years		
	•	C	·			•		
Main Se		Fatina Duildina	F0 F00			0.40.4005		
	PA System	Entire Building	58,580	SF	6	6-10 years		
	Main Electrical Service - 1200 A 120/240/3PH	West Facade	1	EA	6	10+ years		
Power D	istribution							
	Main Distribution Panels - 400 - 600 amp	Basement	1	EA	7	10+ years		
	Main Distribution Panels - Greater than 600 amp	Basement	1	EA	7	10+ years		
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years		
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Older panel.	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	10+ years	Oldor pariol.	
	Lighting and Power Panels - Above 100 A Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	10+ years		
	LIGHTHING AND FOWER FAILERS - ADDIVE TOU A		4	$-\Lambda$	U	IUT VEAIS		



	pry : Electrical			Building	· 6366		300 S St Louis AVENUE, Chicago, IL 60652
Jaiego	y . Lieuticai			Junung	. Lease	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group	Lighting and Power Panels - Above 100 A	Entire Building	2		6	10+ years	Comments
	gg	g			-	, , , , , , , , , , , , , , , , , , , ,	
Catego	ry : Fire Protection		E	Building	: Lease	d-Main	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	·m						
	Fire Alarm Panel	Entire Building	1	EA	6	10+ years	
	Fire Alarm Strobe Lights	Entire Building	58,580	SF	6	10+ years	
	Fire Alarm_System	Entire Building	58,580	SF	5	6-10 years	Previously not assessed
Catago	ry . Machanical			Duildina		d Main	
Calego	ry : Mechanical			Building	. Lease	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond		Location	Quantity	COM	Italik	Replacement	Comments
All Conc	Condensing Unit- Ground Mounted - 5-10	Site North	1	EA	5	2-5 years	
	tons	Site Notifi	ı	LA	3	2-5 years	
	Condensing Unit- Ground Mounted - 5-10	Site North	2	EA	4	1-2 years	Older units, rusted.
	tons					,	
Air Hand	lling Systems						
	Fan Coil Unit- Celing Mounted - Steam	2nd Floor	1	EA	5	6-10 years	Located in a large closet, ceiling
					_	0.40	mounted
	Make Up Air Unit- Indoor Mounted- Steam	Basement	1	EA	5	6-10 years	Heating only, serves kitchen, located
	Coils and Chilled Water Coils - Less than						in a storage room.
	6000 cfm	Dagament	2	Γ.	4	1 2 40000	Deterioreted ald soiling mounted in
	Fan Coil Unit- Celing Mounted - Electric	Basement	3	EA	4	1-2 years	Deteriorated, old, ceiling mounted in basement multipurpose room.
	Fan Coil Unit- Celing Mounted - Electric	Basement	2	EA	4	1-2 years	Older unit, rusted.
	Fan Coil Unit- Celing Mounted - Steam	Basement	1	EA	5	•	Cylindrical, previously not assessed
	Fair Coil Offit- Ceiling Mounted - Steam	Dasement	'	EA	3	6-10 years	Cylindrical, previously flot assessed
Boiler S	ystems						
•	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	2	EA	4	1-2 years	Deteriorated, requires frequent
	Pressure Boiler - 76 - 100 HP						maintenance.
	Chemical Feed System	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	2	EA	6	10+ years	
	Condensate Pump	Boiler Room	1	EA	5	6-10 years	Previously not assessed
	Feed Water Pumps and Tank	Boiler Room	2	EA	6	6-10 years	•
	Non Condensing- Fire Tube- Scotch Marine-		2	EA	4	1-2 years	Frequent maintenance required, old
	Steam- Low Pressure Boiler - 76 - 100 HP		_			,	and deteriorated.
	Piping - Condensate Pipe- Steel	Boiler Room	200	LF	4	1-2 years	There are pipe clamps. Occasional
	. •					•	leaks are repaired. Previously not
							assessed
	Piping - Steam Pipe- Steel	Boiler Room	200	LF	4	1-2 years	There are pipe clamps. Occasional

Campus Name: Ashburn Page : 4 of 30 Assessment Date: 03/03/2022



Catego	ry : Mechanical		В	Building : Leased-Main				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
							leaks are repaired	
	Steam Traps	Boiler Room	6	EA	5	6-10 years		
	Vacuum Pump	Boiler Room	2	EA	5	6-10 years		
Heat Exc	changers							
	Heat Exchanger - Steam to Hot Water Shell	Boiler Room	1	EA	6	6-10 years	Serves univents	
	Туре							
Heating								
	Fin Tube - Steam	Entire Building	36	LF	5	6-10 years		
	Fin Tube - Steam	Entire Building	379	LF	5	6-10 years		
	Unit Heater - Hot Water	Entire Building	6	EA	5	6-10 years	No steam trap	
	Unit Heater - Steam	Entire Building	4	EA	5	6-10 years	With steam trap	
	Cabinet Heaters - With Steam Coil	Entire Building	11	EA	5	6-10 years	Previously not assessed	
Mechani	cal Plumbing							
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	10+ years	Serves heat exchanger	
	Hydronic Supply and Return - Steel	Entire Building	400	LF	5	10+ years	Serve heat exchanger	
Tempera	ture Control							
	Electric Thermostat	Entire Building	10	EA	5	6-10 years	Serve unit heaters, previously not	
			=====	0.5			assessed	
	Pneumatic System	Entire Building	58,580	SF	4	1-2 years	Mostly manually operated	
	Thermostats - Pneumatic	Entire Building	43	EA	4	1-2 years	Not calibrated, leak	
Unit Ven	tilation							
OTHE VOI	Unit Ventilators- Floor Mounted- Hot Water	Entire Building	11	EA	5	6-10 years	With internal thermostats	
	Heating Coils Only	Zimio Danamg	• • • • • • • • • • • • • • • • • • • •	_, `	Ü	o io youro	With internal trioring state	
	ricaming cons crity							
Ventilatio	on							
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	2	EA	5	6-10 years	Previously not assessed	
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	3	EA	6	6-10 years		
	CFM		· ·		-	3 . ,		
	Exhaust Fans- Roof Mounted - Less than	Entire Building	2	EA	5	6-10 years	Belts recently replaced	
	500 CFM	3				,	, ,	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	No fire suppression equipment	
Catego	ry : Plumbing		В	uilding	: Lease			
_					_	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Hot Wate								
	Gas Heater - 150000 - 300000 BTU/HR	Entire Building	1	EΑ	6	6-10 years		



Catego	ry : Plumbing		В	uilding	: Lease	d-Main	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Gas Heater - Less than 150000 BTU/HR	Entire Building	1	EA	6	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	58,580	SF	6	6-10 years	Minor leaks are occasionally repaired
	Domestic Piping-Hot Water Return Risers	Entire Building	58,580	SF	6	6-10 years	• •
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	58,580	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	58,580	SF	6	6-10 years	1953 installation, functional
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	58,580	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	58,580	SF	6	6-10 years	There are a few pipe clamps
	Sanitary Piping	Entire Building	58,580	SF	6	6-10 years	
	Storm Piping	Entire Building	58,580	SF	6	6-10 years	
	Vent Piping	Entire Building	58,580	SF	6	6-10 years	
Pumps							
	Pumps - Sump-Duplex	Boiler Room	1	EA	5	6-10 years	

Category : Room Building · Leased-Main

Jatego	ry : Room	Building : Leased-Main							
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Administ	trative Suites/Offices								
	AC Unit	001 - Principal's Office	1	EA	7	6-10 years			
	Ceiling - Splined	001 - Principal's Office	176	SF	7	10+ years			
	Doors - Wood Doors inclu hw	001 - Principal's Office	3	EA	7	10+ years			
	Floor - Carpet	001 - Principal's Office	166	SF	7	6-10 years			
	Floor - Carpet	001 - Principal's Office	10	SF	4	0-1 year	Ripped carpet		
	Lighting - Lay-in	001 - Principal's Office	1	EA	7	10+ years			
	Power Distribution	001 - Principal's Office	2	EA	7	10+ years			
	Storage/ Closet	001 - Principal's Office	4	SF	7	10+ years			
	Walls - Plaster/Drywall	001 - Principal's Office	540	SF	7	10+ years			
	AC Unit	002 - Conference Room	1	EA	7	6-10 years			
	Ceiling - Splined	002 - Conference Room	252	SF	7	10+ years			
	Doors - Wood Doors inclu hw	002 - Conference Room	2	EA	7	10+ years			
	Floor - Carpet	002 - Conference Room	252	SF	7	6-10 years			
	Lighting - Lay-in	002 - Conference Room	4	EA	7	10+ years			
	Power Distribution	002 - Conference Room	8	EA	7	10+ years			
	Storage/ Closet	002 - Conference Room	6	SF	7	10+ years			
	Walls - Metal Panel	002 - Conference Room	192	SF	7	10+ years			
	Walls - Plaster/Drywall	002 - Conference Room	448	SF	7	10+ years			
	Ceiling - Splined	003	148	SF	7	10+ years			

Campus Name: Ashburn Page : 6 of 30 Assessment Date: 03/03/2022



Catego	ry : Room		В	uilding	: Lease	d-Main	· • • • • • • • • • • • • • • • • • • •
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Splined	003	6	SF	4	0-1 year	Broken Tiles
	Doors - Wood Doors inclu hw	003	1	EA	7	10+ years	
	Floor - Carpet	003	154	SF	7	6-10 years	
	Lighting - Lay-in	003	2	EA	7	10+ years	
	Power Distribution	003	4	EA	7	10+ years	
	Walls - Plaster/Drywall	003	500	SF	7	10+ years	
	Ceiling - Splined	004	126	SF	7	10+ years	
	Doors - Wood Doors inclu hw	004	1	EA	7	10+ years	
	Floor - Carpet	004	126	SF	7	6-10 years	
	Lighting - Lay-in	004	2	ĒΑ	7	10+ years	
	Power Distribution	004	2	EΑ	7	10+ years	
	Walls - Plaster/Drywall	004	460	SF	7	10+ years	
	Ceiling - Splined	005	125	SF	7	10+ years	
	Ceiling - Splined	005	1	SF	4	0-1 year	Broken
	Doors - Wood Doors inclu hw	005	2	EA	7	10+ years	Diokeii
	Floor - Carpet	005	126	SF	6	6-10 years	
	Lighting - Lay-in	005	4	EA	7	•	
	Power Distribution		4	EA	7	10+ years	
		005		SF		10+ years	
	Walls - Plaster/Drywall	005	460		7	10+ years	
	AC Unit	108	1	EA	7	6-10 years	
	Ceiling - Splined	108	713	SF	7	10+ years	
	Ceiling - Splined	108	7	SF	4	0-1 year	Loose tiles
	Doors - Transom Window	108	3	SF	7	10+ years	
	Doors - Wood Doors inclu hw	108	1	EA	7	10+ years	
	Floor - Carpet	108	720	SF	7	6-10 years	
	Lighting - Pendent/Surface	108	12	EA	7	10+ years	
	Power Distribution	108	4	EA	7	10+ years	
	Storage/ Closet	108	10	SF	7	10+ years	
	Walls - Plaster/Drywall	108	720	SF	7	10+ years	
	Walls - Structural Glazed Tile	108	110	SF	7	10+ years	
	AC Unit	111 - Teacher's Lounge	1	EA	7	6-10 years	
	Ceiling - Splined	111 - Teacher's Lounge	522	SF	7	10+ years	
	Ceiling - Splined	111 - Teacher's Lounge	6	SF	4	0-1 year	Missing Tiles
	Doors - Transom Window	111 - Teacher's Lounge	3	SF	7	10+ years	-
	Doors - Wood Doors inclu hw	111 - Teacher's Lounge	1	EA	7	10+ years	
	Floor - Carpet	111 - Teacher's Lounge	528	SF	6	6-10 years	
	Lighting - Pendent/Surface	111 - Teacher's Lounge	10	EA	7	10+ years	
	Power Distribution	111 - Teacher's Lounge	10	EA	7	10+ years	
	Storage/ Closet	111 - Teacher's Lounge	150	SF	7	10+ years	
	Walls - Metal Panel	111 - Teacher's Lounge	522	SF	7	10+ years	
	Walls - Plaster/Drywall	111 - Teacher's Lounge	178	SF	7	10+ years	
	Ceiling - Splined	111A - North Faculty	104	SF	7	10+ years	
	Doors - Wood Doors inclu hw	111A - North Faculty	104	EA	7	10+ years	
	Floor - Tile	111A - North Faculty	104	SF	7	10+ years	
	11001 1110	Title Notall dodity	104	O.	,	ioi youis	



Catego	ry : Room		В	uilding	: Lease	d-Main	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	111A - North Faculty	1	EA	7	10+ years	
	Power Distribution	111A - North Faculty	2	EA	7	10+ years	
	Walls - Plaster/Drywall	111A - North Faculty	380	SF	7	10+ years	
	Ceiling - Exposed	113 engineer	396	SF	7	10+ years	
	Doors - Wood Doors inclu hw	113 engineer	1	EA	7	10+ years	
	Floor - Tile	113 engineer	376	SF	6	10+ years	
	Floor - Tile	113 engineer	20	SF	4	0-1 year	Missing Tiles
	Lighting - Pendent/Surface	113 engineer	4	EA	6	6-10 years	
	Power Distribution	113 engineer	10	EA	7	10+ years	
	Walls - Concrete Block	113 engineer	900	SF	7	10+ years	
	Work SInk	113 engineer	1	EA	7	10+ years	
	AC Unit	218 - Assistant Principal	1	EA	7	6-10 years	
	Ceiling - Splined	218 - Assistant Principal	265	SF	7	10+ years	
	Doors - Wood Doors inclu hw	218 - Assistant Principal	1	EA	7	10+ years	
	Floor - Carpet	218 - Assistant Principal	265	SF	7	6-10 years	
	Lighting - Pendent/Surface	218 - Assistant Principal	10	EA	7	10+ years	
	Power Distribution	218 - Assistant Principal	12	EA	7	10+ years	
	Walls - Concrete Block	218 - Assistant Principal	677	SF	7	10+ years	
	AC Unit	2nd Floor - Faculty Lounge	1	ĒΑ	7	6-10 years	
	Ceiling - Splined	2nd Floor - Faculty Lounge	276	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Faculty Lounge	2	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor - Faculty Lounge	276	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor - Faculty Lounge	6	EA	7	10+ years	
	Power Distribution	2nd Floor - Faculty Lounge	6	EΑ	7	10+ years	
	Walls - Concrete Block	2nd Floor - Faculty Lounge	700	SF	7	10+ years	
	Work SInk	2nd Floor - Faculty Lounge	1	EA	7	10+ years	
	Ceiling - Lay-in	Kitchen	299	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Kitchen	1	EA	7	10+ years	
	Floor - Tile	Kitchen	299	SF	6	10+ years	
	Lighting - Lay-in	Kitchen	299	EA	7	10+ years	
	Power Distribution	Kitchen	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Kitchen	710	SF	7	10+ years	
	Walls - Plaster/Drywall	Kitchen	10	SF	6	10+ years	
	Walls - Flastel/Drywall	Kitchen	10	Si	O	10+ years	
Mitala a :-							
Kitchen	Opilian Disease/Description	Decement	440			40	
	Ceiling - Plaster/Drywall	Basement	410	SF	7	10+ years	11-1-
	Ceiling - Plaster/Drywall	Basement	4	SF	4	0-1 year	Hole.
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Tile	Basement	402	SF	7	10+ years	
	Floor - Tile	Basement	12	SF	4	0-1 year	Broken Tiles
	Lighting - Pendent/Surface	Basement	4	EA	7	10+ years	
	Serving Line	Basement	6	LF	7	10+ years	
	Walls - Structural Glazed Tile	Basement	820	SF	7	10+ years	



Categor	y : Room		В	uilding	: Lease	d-Main	, , ,
	•					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Library							
	AC Unit	110/112	2	EA	7	6-10 years	
	Casework	110/112	150	LF	6	10+ years	
	Ceiling - Splined	110/112	1,560	SF	7	10+ years	
	Doors - Transom Window	110/112	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	110/112	2	EA	7	10+ years	
	Floor - Carpet	110/112	1,535	SF	7	6-10 years	
	Floor - Carpet	110/112	25	SF	4	0-10 years 0-1 year	Ripped carpet
	Lighting - Pendent/Surface	110/112	24	EA	7	10+ years	Ripped Calpet
	Storage/ Closet	110/112	10	SF	7		
			_	SF		10+ years	
	Walls - Plaster/Drywall	110/112	1,107		7	10+ years	
	Walls - Structural Glazed Tile	110/112	180	SF	7	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Splined	Basement	5,641	SF	6	10+ years	
	Ceiling - Splined	Basement	2	SF	4	0-1 year	Missing Tiles
	Floor - Tile	Basement	5,621	SF	7	10+ years	Wildeling Tiles
	Floor - Tile	Basement	22	SF	4	0-1 year	Missing Tiles
	Lighting - Lay-in	Basement	60	EA	7	10+ years	Wissing Tiles
	Serving Line	Basement	12	LF	7	10+ years	
	Walls - Masonry	Basement	1,020	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	1,350	SF	7	•	
	Walls - Plastel/Drywall	Dasement	1,330	SF	,	10+ years	
_MDF_IDE	=						
	Doors - Steel Doors incl hw	111B	1	EA	7	10+ years	
	Finishes	111B	380	SF	7	6-10 years	
	Window AC Unit	111B	1	EA	7	6-10 years	
Machania	cal/ Service Rooms						
_wechanic	Janitor's Closet	1st Floor	51	SF	7	10+ years	
	Janitor's Closet	1st Floor	14	SF	5	10+ years	Missing floor tiles
	Storage Room	1st Floor	100	SF	7	10+ years	Rank Changed to match current
	Storage Room	13(1100)	100	OI .	,	10+ years	observation
	Storage Room	1st Floor	320	SF	7	10+ years	
	Janitor's Closet	2nd Floor	66	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	50	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	5	SF	5	10+ years	
	Boiler Room	Basement	552	SF	7	10+ years	
	Janitor's Closet	Basement	12	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	103	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	50	SF	7	10+ years	Rank Changed to match current
	Modridinoal Colvide Rooms	Dascinett	30	01	,	ioi yeais	observation
	Storage Room	Basement	747	SF	7	10+ years	
						-	



atego	ry : Room		Building : Leased-Main					
						Recommend	_	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
estroor		OOAA Dringingle Office	4.5	SF	7	0.40		
	Accessories	001A - Principal's Office	15		7	6-10 years		
	Ceiling - Plaster/Drywall	001A - Principal's Office	15	SF	7	10+ years		
	Doors - Wood Doors inclu hw	001A - Principal's Office	1	EA	7	10+ years		
	Floor - Carpet	001A - Principal's Office	15	SF	7	6-10 years		
	Hand Dryer	001A - Principal's Office	1	EA	7	6-10 years		
	Lavatory	001A - Principal's Office	1	EA	7	10+ years		
	Lighting - Pendent/Surface	001A - Principal's Office	1	EA	7	10+ years		
	Walls - Plaster/Drywall	001A - Principal's Office	80	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	001A - Principal's Office	80	SF	7	10+ years		
	Water Closet	001A - Principal's Office	1	EA	7	10+ years		
	Accessories	006 - 1st Floor	240	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	006 - 1st Floor	240	SF	7	10+ years		
	Doors - Wood Doors inclu hw	006 - 1st Floor	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	006 - 1st Floor	240	SF	7	10+ years		
	Hand Dryer	006 - 1st Floor	1	EA	7	6-10 years		
	Lavatory	006 - 1st Floor	1	EA	7	10+ years		
	Lighting - Pendent/Surface	006 - 1st Floor	2	EA	7	10+ years		
	Partitions	006 - 1st Floor	2	EA	7	10+ years		
	Urinals	006 - 1st Floor	6	ΕA	7	10+ years		
	Walls - Plaster/Drywall	006 - 1st Floor	260	SF	7	10+ years		
	Walls - Structural Glazed Tile	006 - 1st Floor	450	SF	7	10+ years		
	Water Closet	006 - 1st Floor	2	EA	7	10+ years		
	Accessories	007 - 1st Floor	240	SF	7	6-10 years		
	Ceiling - Lay-in	007 - 1st Floor	240	SF	7	10+ years		
	Doors - Wood Doors inclu hw	007 - 13t 1001 007 - 1st Floor	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	007 - 1st Floor	240	SF	7	10+ years		
	Floor Drain	007 - 1st Floor	1	EA	7	10+ years		
		007 - 1st Floor	1	EA	7	•		
	Hand Dryer		1	EA	7	6-10 years		
	Lavatory	007 - 1st Floor				10+ years		
	Lighting - Lay-in	007 - 1st Floor	2	EΑ	7	10+ years		
	Partitions	007 - 1st Floor	8	EA	7	10+ years		
	Walls - Plaster/Drywall	007 - 1st Floor	272	SF	7	10+ years		
	Walls - Structural Glazed Tile	007 - 1st Floor	408	SF	7	10+ years		
	Water Closet	007 - 1st Floor	8	EA	7	10+ years		
	Accessories	008 - 2nd Floor	210	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	008 - 2nd Floor	210	SF	6	10+ years		
	Doors - Wood Doors inclu hw	008 - 2nd Floor	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	008 - 2nd Floor	210	SF	6	10+ years		
	Hand Dryer	008 - 2nd Floor	1	EA	7	6-10 years		
	Lavatory	008 - 2nd Floor	1	EA	7	10+ years		
	Lighting - Lay-in	008 - 2nd Floor	3	EA	7	10+ years		
	Partitions	008 - 2nd Floor	2	EA	7	10+ years		

Campus Name: Ashburn Page : 10 of 30 Assessment Date: 03/03/2022



Catego	Category : Room			Building : Leased-Main				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Urinals	008 - 2nd Floor	6	EA	7	10+ years		
	Walls - Plaster/Drywall	008 - 2nd Floor	272	SF	7	10+ years		
	Walls - Structural Glazed Tile	008 - 2nd Floor	408	SF	7	10+ years		
	Water Closet	008 - 2nd Floor	2	EA	7	10+ years		
	Accessories	009 - 2nd Floor	210	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	009 - 2nd Floor	210	SF	7	10+ years		
	Doors - Wood Doors inclu hw	009 - 2nd Floor	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	009 - 2nd Floor	210	SF	7	10+ years		
	Floor Drain	009 - 2nd Floor	1	EA	7	10+ years		
	Hand Dryer	009 - 2nd Floor	1	EA	7	6-10 years		
	Lavatory	009 - 2nd Floor	5	EA	7	10+ years		
	Lighting - Lay-in	009 - 2nd Floor	1	EA	7	10+ years		
	Lighting - Pendent/Surface	009 - 2nd Floor	1	EA	7	10+ years		
	Partitions	009 - 2nd Floor	5	EA	7	10+ years		
	Walls - Plaster/Drywall	009 - 2nd Floor	272	SF	7	10+ years		
	Walls - Structural Glazed Tile	009 - 2nd Floor	408	SF	7	10+ years		
	Water Closet	009 - 2nd Floor	5	EA	7	10+ years		
	Accessories	009A - 2nd Floor	30	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	009A - 2nd Floor	30	SF	6	10+ years		
	Doors - Wood Doors inclu hw	009A - 2nd Floor	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	009A - 2nd Floor	30	SF	7	10+ years		
	Lavatory	009A - 2nd Floor	1	EA	7	10+ years		
	Lighting - Pendent/Surface	009A - 2nd Floor	1	EA	7	10+ years		
	Walls - Plaster/Drywall	009A - 2nd Floor	88	SF	6	10+ years		
	Walls - Structural Glazed Tile	009A - 2nd Floor	132	SF	7	10+ years		
	Water Closet	009A - 2nd Floor	132	EA	7	10+ years		
	Accessories	011 - 1.5 North	114	SF	7	6-10 years		
	Ceiling - Splined	011 - 1.5 North	114	SF	7	10+ years		
	Doors - Wood Doors inclu hw	011 - 1.5 North	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	011 - 1.5 North	114	SF	7	10+ years		
	Hand Dryer	011 - 1.5 North	1 14	EA	7	6-10 years		
	Lavatory	011 - 1.5 North	2	EA	7	10+ years		
	Lighting - Lay-in	011 - 1.5 North	2	EA	7	10+ years		
	Partitions	011 - 1.5 North	3	EA	5	6-10 years		
	Walls - Concrete Block	011 - 1.5 North	184	SF	7	10+ years		
	Walls - Concrete Block Walls - Structural Glazed Tile	011 - 1.5 North	336	SF	7	•		
	Water Closet	011 - 1.5 North	330	EA	7	10+ years		
				SF		10+ years		
	Accessories Ceiling - Splined	0125 North 0125 North	120 120	SF SF	7 6	6-10 years		
				EA		10+ years		
	Doors - Wood Doors inclu hw	0125 North	2		7	10+ years		
	Floor - Tile Ceramic/ Porcelain	0125 North	120	SF	7	10+ years		
	Hand Dryer	0125 North	1	EΑ	7	6-10 years		
	Lavatory	0125 North	2	EΑ	7	10+ years		
	Lighting - Lay-in	0125 North	3	EA	7	10+ years		



Catego	Category : Room		В	uilding	: Lease	d-Main	<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	0125 North	1	EA	7	10+ years	
	Urinals	0125 North	2	EA	7	10+ years	
	Walls - Concrete Block	0125 North	216	SF	7	10+ years	
	Walls - Structural Glazed Tile	0125 North	324	SF	7	10+ years	
	Water Closet	0125 North	1	EA	7	10+ years	
	Accessories	0135 North	120	SF	7	6-10 years	
	Ceiling - Splined	0135 North	110	SF	7	10+ years	
	Ceiling - Splined	0135 North	10	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	0135 North	2	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	0135 North	120	SF	7	10+ years	
	Hand Dryer	0135 North	1	EA	7	10+ years	
	Lavatory	0135 North	2	EA	7	10+ years	
	Lighting - Lay-in	0135 North	3	EA	7	10+ years	
	Partitions	0135 North	3	EA	7	10+ years	
	Walls - Concrete Block	0135 North	216	SF	7	10+ years	
	Walls - Concrete Block Walls - Structural Glazed Tile	0135 North	324	SF	7	10+ years	
	Water Closet	0135 North		EA	7	•	
			3			10+ years	
	Accessories	014 - 1.5 South	169	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	014 - 1.5 South	169	SF	6	10+ years	
	Doors - Wood Doors inclu hw	014 - 1.5 South	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	014 - 1.5 South	169	SF	6	10+ years	
	Floor Drain	014 - 1.5 South	1	EA	7	10+ years	
	Hand Dryer	014 - 1.5 South	1	EA	7	6-10 years	
	Lavatory	014 - 1.5 South	1	EA	7	10+ years	
	Lighting - Lay-in	014 - 1.5 South	1	EA	7	10+ years	
	Partitions	014 - 1.5 South	1	EΑ	7	10+ years	
	Urinals	014 - 1.5 South	3	EΑ	7	10+ years	
	Walls - Concrete Block	014 - 1.5 South	292	SF	7	10+ years	
	Walls - Concrete Block	014 - 1.5 South	8	SF	6	10+ years	
	Walls - Structural Glazed Tile	014 - 1.5 South	300	SF	7	10+ years	
	Water Closet	014 - 1.5 South	1	EA	7	10+ years	
	Accessories	015 - 1.5 South	169	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	015 - 1.5 South	169	SF	7	10+ years	
	Doors - Wood Doors inclu hw	015 - 1.5 South	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	015 - 1.5 South	169	SF	7	10+ years	
	Floor Drain	015 - 1.5 South	1	EΑ	7	10+ years	
	Hand Dryer	015 - 1.5 South	1	EA	7	6-10 years	
	Lavatory	015 - 1.5 South	1	ΕA	7	10+ years	
	Lighting - Pendent/Surface	015 - 1.5 South	1	EA	7	10+ years	
	Partitions	015 - 1.5 South	4	EA	7	10+ years	
	Walls - Concrete Block	015 - 1.5 South	310	SF	7	10+ years	
	Walls - Structural Glazed Tile	015 - 1.5 South	310	SF	7	10+ years	
	Water Closet	015 - 1.5 South	4	EA	7	10+ years	
	Accessories	016 - 1.5 South	102	SF	7	6-10 years	
	A0063301163	010 - 1.0 30util	102	Oi.	,	o-10 years	

Campus Name: Ashburn Page: 12 of 30 Assessment Date: 03/03/2022



Catego	Category : Room			uilding	: Lease	d-Main	· • • • • • • • • • • • • • • • • • • •
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	016 - 1.5 South	102	SF	6	10+ years	
	Doors - Wood Doors inclu hw	016 - 1.5 South	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	016 - 1.5 South	102	SF	7	10+ years	
	Hand Dryer	016 - 1.5 South	1	EA	7	6-10 years	
	Lavatory	016 - 1.5 South	1	EA	7	10+ years	
	Lighting - Lay-in	016 - 1.5 South	1	EA	7	10+ years	
	Partitions	016 - 1.5 South	3	EA	7	10+ years	
	Walls - Concrete Block	016 - 1.5 South	210	SF	7	10+ years	
	Walls - Structural Glazed Tile	016 - 1.5 South	210	SF	7	10+ years	
	Water Closet	016 - 1.5 South	3	EA	7	10+ years	
	Accessories	0175 South	169	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	0175 South	154	SF	7	10+ years	
	Ceiling - Plaster/Drywall	0175 South	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	0175 South	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	0175 South	169	SF	7	10+ years	
	Floor Drain	0175 South	1	EA	7	10+ years	
	Hand Dryer	0175 South	1	EA	7	6-10 years	
	Lavatory	0175 South	1	EA	7	10+ years	
	Lighting - Lay-in	0175 South	3	EA	7	10+ years	
	Partitions	0175 South	1	ĒΑ	7	10+ years	
	Urinals	0175 South	3	EA	7	10+ years	
	Walls - Concrete Block	0175 South	310	SF	7	10+ years	
	Walls - Structural Glazed Tile	0175 South	310	SF	7	10+ years	
	Water Closet	0175 South	1	ĒΑ	7	10+ years	
	Accessories	0185 South	169	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	0185 South	169	SF	7	10+ years	
	Doors - Wood Doors inclu hw	0185 South	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	0185 South	169	SF	7	10+ years	
	Floor Drain	0185 South	1	EA	7	10+ years	
	Hand Dryer	0185 South	1	EΑ	7	6-10 years	
	Lavatory	0185 South	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	0185 South	1	EA	7	10+ years	
	Partitions	0185 South	4	EΑ	7	10+ years	
	Walls - Concrete Block	0185 South	310	SF	7	10+ years	
	Walls - Structural Glazed Tile	0185 South	310	SF	7	10+ years	
	Water Closet	0185 South	4	EA	7	10+ years	
	Accessories	110 - 1.5 North	130	SF	7	6-10 years	
	Ceiling - Splined	110 - 1.5 North	130	SF	4	0-1 year	Worn, water damage, falling.
	Doors - Wood Doors inclu hw	110 - 1.5 North	130	EA	7	10+ years	Trom, water damage, railing.
	Floor - Tile Ceramic/ Porcelain	110 - 1.5 North	130	SF	6	10+ years	
	Hand Dryer	110 - 1.5 North	1	EA	7	6-10 years	
	Lavatory	110 - 1.5 North	2	EA	7	10+ years	
	Lighting - Lay-in	110 - 1.5 North	2	EA	7	10+ years	
	Partitions	110 - 1.5 North	2	EA	7	10+ years	
	i aitaono	110 1.0140101	2	LA	,	TOT years	

Campus Name: Ashburn Page: 13 of 30 Assessment Date: 03/03/2022



Catego	ry : Room		В	uilding	: Lease	d-Main	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Urinals	110 - 1.5 North	3	EΑ	7	10+ years	
	Walls - Concrete Block	110 - 1.5 North	184	SF	7	10+ years	
	Walls - Structural Glazed Tile	110 - 1.5 North	276	SF	7	10+ years	
	Water Closet	110 - 1.5 North	2	EA	7	10+ years	
	Accessories	219A - North restroom - Staff	20	SF	7	6-10 years	
	Ceiling - Splined	219A - North restroom - Staff	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	219A - North restroom - Staff	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	219A - North restroom - Staff	20	SF	7	10+ years	
	Lavatory	219A - North restroom - Staff	1	EA	7	10+ years	
	Lighting - Pendent/Surface	219A - North restroom - Staff	1	EA	7	10+ years	
	Walls - Concrete Block	219A - North restroom - Staff	108	SF	7	10+ years	
	Walls - Structural Glazed Tile	219A - North restroom - Staff	72	SF	7	10+ years	
	Water Closet	219A - North restroom - Staff	1	EA	7	10+ years	
	Accessories	B-008 - Basement	120	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	B-008 - Basement	120	SF	7	10+ years	
	Doors - Wood Doors inclu hw	B-008 - Basement	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	B-008 - Basement	120	SF	7	10+ years	
	Hand Dryer	B-008 - Basement	1	EA	7	6-10 years	
	Lavatory	B-008 - Basement	1	EA	7	10+ years	
	Lighting - Pendent/Surface	B-008 - Basement	1	EA	7	10+ years	
	Partitions	B-008 - Basement	1	EA	7	10+ years	
	Urinals	B-008 - Basement	3	EA	7	10+ years	
	Walls - Plaster/Drywall	B-008 - Basement	220	SF	7	10+ years	
	Walls - Structural Glazed Tile	B-008 - Basement	278	SF	7	10+ years	
	Walls - Structural Glazed Tile	B-008 - Basement	5	SF	4	0-1 year	Missing Wall
	Water Closet	B-008 - Basement	1	EA	7	10+ years	
	Accessories	B-009 - Basement	144	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	B-009 - Basement	134	SF	7	10+ years	
	Ceiling - Plaster/Drywall	B-009 - Basement	10	SF	5	0-1 year	Water damage.
	Doors - Wood Doors inclu hw	B-009 - Basement	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	B-009 - Basement	144	SF	7	10+ years	
	Floor Drain	B-009 - Basement	1	EA	7	10+ years	
	Hand Dryer	B-009 - Basement	1	EA	7	6-10 years	
	Lavatory	B-009 - Basement	1	EA	7	10+ years	
	Lighting - Lay-in	B-009 - Basement	1	EA	7	10+ years	
	Lighting - Pendent/Surface	B-009 - Basement	1	EA	7	10+ years	
	Partitions	B-009 - Basement	2	EA	7	10+ years	
	Walls - Plaster/Drywall	B-009 - Basement	240	SF	7	10+ years	
	Walls - Structural Glazed Tile	B-009 - Basement	348	SF	7	10+ years	
	Water Closet	B-009 - Basement	2	EA	7	10+ years	



Catego	ry : Classroom		В	uilding	: Lease		100 O Ot Louis AVENOE, Officago, IE 00002
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #101 (Special Education)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	54	LF	7	10+ years	
	Ceiling - Splined	1st Floor	732	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	732	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	892	SF	7	10+ years	
Classroo	om #102 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	54	LF	6	10+ years	
	Ceiling - Splined	1st Floor	732	SF	6	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	732	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	6-10 years	
	Student Lockers - One Tier	1st Floor	24	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	892	SF	7	10+ years	
Classroo	om #103 (Kindergarten)						
Oldooroc	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	54	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	732	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	732	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	10+ years	
	Student Lockers - One Tier	1st Floor	24	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	892	SF	7	10+ years	
Classroo	om #104 (Regular Classroom)						
	Casework	1st Floor	54	LF	7	10+ years	
	Casework Ceiling - Splined	1st Floor	732	SF	6	10+ years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	10	EA	7	10+ years	
	Floor - Tile	1st Floor	732	SF	7	10+ years 10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	10+ years	
	Storage/ Cluset	151 11001	10	SI-	,	10+ years	



Category : Classroom			В	uilding	: Lease		
					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Student Lockers - One Tier	1st Floor	24	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	772	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	120	SF	7	10+ years	
Classroo	m #105 (Regular Classroom)						
	Casework	1st Floor	54	LF	7	10+ years	
	Ceiling - Splined	1st Floor	727	SF	6	10+ years	
	Ceiling - Splined	1st Floor	5	SF	4	0-1 year	Broken Tiles
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	732	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	10+ years	
	Student Lockers - One Tier	1st Floor	24	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	772	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	120	SF	7	10+ years	
Classroo	m #106 (Music Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	30	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	920	SF	6	6-10 years	
	Ceiling - Splined	1st Floor	10	SF	4	0-1 year	Loose tiles
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	930	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	10+ years	
	Student Lockers - One Tier	1st Floor	24	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	810	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	120	SF	7	10+ years	
Classroo	m #107 (Art Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	28	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	930	SF	6	6-10 years	
	Chalk Board	1st Floor	16	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	3	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	910	SF	7	6-10 years	
	Floor - Tile	1st Floor	20	SF	4	0-1 year	Missing Tiles
	Lighting - Pendent/Surface	1st Floor	12	ĒΑ	6	6-10 years	.
	Marker Board	1st Floor	8	LF	6	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	6-10 years	
	Student Lockers - One Tier	1st Floor	24	ĒΑ	7	10+ years	



Category : Classroom			Building : Leased-Main					
_			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Plaster/Drywall	1st Floor	810	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor	120	SF	7	10+ years		
Classroo	om #109 (Computer Lab)							
	AC Units	1st Floor	2	EA	7	6-10 years		
	Casework	1st Floor	30	LF	7	10+ years		
	Ceiling - Splined	1st Floor	920	SF	6	6-10 years		
	Ceiling - Splined	1st Floor	10	SF	4	0-1 year	Broken Tiles	
	Doors - Transom Window	1st Floor	3	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years		
	Floor - Carpet	1st Floor	930	SF	7	6-10 years		
	Lighting - Pendent/Surface	1st Floor	12	ĒΑ	6	6-10 years		
	Marker Board	1st Floor	12	LF	7	6-10 years		
	Storage/ Closet	1st Floor	10	SF	7	10+ years		
	Student Lockers - One Tier	1st Floor	24	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	810	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor	120	SF	7	10+ years		
Classroo	om #113 (Computer Lab)							
0.000.00	AC Units	1st Floor	2	EA	7	6-10 years		
	Casework	1st Floor	54	LF	6	10+ years		
	Ceiling - Splined	1st Floor	930	SF	6	10+ years		
	Doors - Transom Window	1st Floor	3	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Carpet	1st Floor	930	SF	7	6-10 years		
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years		
	Storage/ Closet	1st Floor	10	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	690	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor	120	SF	7	10+ years		
Classroo	om #114 (Regular Classroom)							
CIGOOIOC	AC Units	1st Floor	1	EA	7	6-10 years		
	Casework	1st Floor	23	LF	6	10+ years		
	Casework Ceiling - Splined	1st Floor	805	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	805	SF	7	6-10 years		
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years		
	Marker Board	1st Floor	8	LF	7	6-10 years		
	Storage/ Closet	1st Floor	12	SF	7	10+ years		
	Student Lockers - One Tier	1st Floor	26	SF EA	7 7			
	Walls - Concrete Block	1st Floor		SF		10+ years		
			540	SF SF	7 7	10+ years		
	Walls - Structural Glazed Tile	1st Floor	150	5F	1	10+ years		



Catego	Category : Classroom			Building : Leased-Main					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroo	m #115 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	78	LF	7	10+ years			
	Ceiling - Splined	1st Floor	805	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years			
	Floor - Tile	1st Floor	805	SF	7	6-10 years			
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years			
	Marker Board	1st Floor	16	LF	6	6-10 years			
	Storage/ Closet	1st Floor	12	SF	7	10+ years			
	Student Lockers - One Tier	1st Floor	26	EA	7	10+ years			
	Walls - Concrete Block	1st Floor	540	SF	7	10+ years			
	Walls - Structural Glazed Tile	1st Floor	150	SF	7	10+ years			
_Classroo	om #116 (Regular Classroom)	4 . 🗖				0.40			
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	23	LF	7	10+ years			
	Ceiling - Splined	1st Floor	790	SF	6	6-10 years	W . B		
	Ceiling - Splined	1st Floor	15	SF	4	0-1 year	Water Damaged		
	Chalk Board	1st Floor	12	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	785	SF	7	6-10 years	A4: : T1		
	Floor - Tile	1st Floor	20	SF	4	0-1 year	Missing Tiles		
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years			
	Marker Board	1st Floor	8	LF.	6	6-10 years			
	Student Lockers - One Tier	1st Floor	26	EA	7	10+ years			
	Walls - Concrete Block	1st Floor 1st Floor	873 165	SF SF	7 7	10+ years			
	Walls - Structural Glazed Tile	1St Floor	100	SF	/	10+ years			
Classroo	om #117 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	23	LF	7	10+ years			
	Ceiling - Splined	1st Floor	805	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	775	SF	7	6-10 years			
	Floor - Tile	1st Floor	30	SF	4	0-1 year	Missing Tiles		
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years			
	Marker Board	1st Floor	8	LF	7	6-10 years			
	Student Lockers - One Tier	1st Floor	26	EA	6	10+ years			
	Walls - Concrete Block	1st Floor	873	SF	7	10+ years			
	Walls - Structural Glazed Tile	1st Floor	165	SF	7	10+ years			
Classroo	om #201 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	VO OHIG	2110 1 1001	1	ĽA	,	0-10 years			



Catego	ry : Classroom		В	uilding	: Lease		500 S St Louis Avenue, Chicago, il 60052
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	54	LF	7	10+ years	
	Ceiling - Splined	2nd Floor	744	SF	6	6-10 years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	734	SF	7	6-10 years	
	Floor - Tile	2nd Floor	10	SF	4	0-1 year	Damaged tiles
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Student Lockers - One Tier	2nd Floor	24	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	640	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	135	SF	7	10+ years	
Classroo	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	54	LF	7	10+ years	
	Ceiling - Splined	2nd Floor	744	SF	7	6-10 years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	744	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Student Lockers - One Tier	2nd Floor	24	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	640	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	135	SF	7	10+ years	
Classia	was #202 (De suiter Classes and						
Classroc	om #203 (Regular Classroom)	0 15				0.40	_
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	54	LF	7	10+ years	
	Ceiling - Splined	2nd Floor	744	SF	6	6-10 years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	734	SF	7	6-10 years	
	Floor - Tile	2nd Floor	10	SF	4	0-1 year	Missing tiles
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Student Lockers - One Tier	2nd Floor	24	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	640	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	135	SF	7	10+ years	
Classroo	om #204 (Special Education)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	54	LF	7	10+ years	
						,	

Campus Name: Ashburn Page: 19 of 30 Assessment Date: 03/03/2022



Category : Classroom			В	Building : Leased-Main					
<u> </u>					Recommend				
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
•	Ceiling - Splined	2nd Floor	744	SF	6	10+ years			
	Chalk Board	2nd Floor	24	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	744	SF	7	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	12	EΑ	6	6-10 years			
	Storage/ Closet	2nd Floor	10	SF	7	10+ years			
	Walls - Concrete Block	2nd Floor	640	SF	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	135	SF	7	10+ years			
lassroc	om #205 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	54	LF	7	10+ years			
	Ceiling - Splined	2nd Floor	744	SF	6	6-10 years			
	Chalk Board	2nd Floor	24	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	744	SF	7	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years			
	Storage/ Closet	2nd Floor 2nd Floor	10	SF	7	10+ years			
	Walls - Concrete Block	2nd Floor	640	SF	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor 2nd Floor	135	SF	7	10+ years 10+ years			
lassroc	om #206 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	30	LF	7	10+ years			
	Ceiling - Splined	2nd Floor	744	SF	7	10+ years			
	Chalk Board	2nd Floor	18	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	3	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	724	SF	7	6-10 years			
	Floor - Tile	2nd Floor	20	SF	4	0-10 years 0-1 year	Damaged tiles		
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	Damaged tiles		
	Marker Board	2nd Floor	8	LF	7	•			
	Storage/ Closet			SF	7	6-10 years			
		2nd Floor	10			10+ years			
	Student Lockers - One Tier	2nd Floor	24	EA	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	850	SF	7	10+ years			
lassroc	om #207 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	30	LF	7	10+ years			
	Ceiling - Splined	2nd Floor	724	SF	7	10+ years			
	Ceiling - Splined	2nd Floor	20	SF	4	0-1 year	Missing tiles		
	Chalk Board	2nd Floor	32	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	3	SF	7	10+ years			

Campus Name: Ashburn Page : 20 of 30 Assessment Date: 03/03/2022



Category : Classroom				Building : Leased-Main					
				9		Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
•	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	744	SF	7	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years			
	Storage/ Closet	2nd Floor	10	SF	7	10+ years			
	Student Lockers - One Tier	2nd Floor	24	ĒΑ	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	850	SF	7	10+ years			
Classroc	om #208 (Science Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	36	LF	7	10+ years			
	Ceiling - Splined	2nd Floor	744	SF	7	10+ years			
	Chalk Board	2nd Floor	8	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	3	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	739	SF	7	6-10 years			
	Floor - Tile	2nd Floor	5	SF	4	0-1 year	Damaged		
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	Danlaged		
	Marker Board	2nd Floor	8	LF	7	6-10 years			
	Storage/ Closet	2nd Floor	10	SF	7	10+ years			
	Student Lockers - One Tier	2nd Floor	24	EA	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	850	SF	7	10+ years			
	vvalis i laster/Drywaii	2110 1 1001	000	O.	,	101 years			
Classroc	om #209 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	30	LF	7	10+ years			
	Ceiling - Splined	2nd Floor	744	SF	7	10+ years			
	Chalk Board	2nd Floor	24	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	3	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	744	SF	7	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years			
	Marker Board	2nd Floor	12	LF	7	6-10 years			
	Storage/ Closet	2nd Floor	10	SF	7	10+ years			
	Student Lockers - One Tier	2nd Floor	24	EA	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	850	SF	7	10+ years			
lassroc	om #210 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	30	LF	7	10+ years			
	Ceiling - Splined	2nd Floor	739	SF	7	10+ years			
	Ceiling - Splined	2nd Floor	5	SF	4	0-1 year	Cracked tile		
	Chalk Board	2nd Floor	12	LF	4	2-5 years	Ordonod tilo		
	Doors - Transom Window	2nd Floor	3	SF	7	10+ years			
	Doors - Hanson William	ZIIU I IOOI	3	J-	,	TOT YEARS			



Catego	ry : Classroom	В	uilding	: Lease	d-Main		
						Recommend	
≩roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	744	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Student Lockers - One Tier	2nd Floor	24	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	850	SF	7	10+ years	
Classroo	om #211 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	30	LF	7	10+ years	
	Ceiling - Splined	2nd Floor	744	SF	6	6-10 years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	3	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	744	SF	7	•	
	Lighting - Pendent/Surface	2nd Floor 2nd Floor				6-10 years	
	Marker Board	2nd Floor 2nd Floor	12 8	EA LF	7 7	6-10 years	
						6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Student Lockers - One Tier	2nd Floor	24	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	850	SF	7	10+ years	
Classroo	om #212 (Office)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	30	LF	7	10+ years	
	Ceiling - Splined	2nd Floor	744	SF	6	6-10 years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	3	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Carpet	2nd Floor	744	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Student Lockers - One Tier	2nd Floor	24	EΑ	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	24	SF	7	10+ years	
Classroo	om #213 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	30	LF	7	10+ years	
	Casework Ceiling - Splined	2nd Floor 2nd Floor	744	SF	7		
	Chalk Board	2nd Floor 2nd Floor	24	LF	4	10+ years	
						2-5 years	
	Doors - Transom Window	2nd Floor	3	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	

Campus Name: Ashburn Page : 22 of 30 Assessment Date: 03/03/2022



Catego	ry : Classroom		Building : Leased-Main					
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Tile	2nd Floor	744	SF	7	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years		
	Marker Board	2nd Floor	12	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	10	SF	7	10+ years		
	Student Lockers - One Tier	2nd Floor	24	EA	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	850	SF	7	10+ years		
Classroc	om #214 (Special Education)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	21	LF	7	10+ years		
	Ceiling - Splined	2nd Floor	756	SF	6	6-10 years		
	Chalk Board	2nd Floor	18	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	756	SF	7	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years		
	Marker Board	2nd Floor	8	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	12	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor 2nd Floor	558	SF	7	10+ years		
	Walls - Structural Glazed Tile	2nd Floor	147	SF	7	•		
	Walls - Structural Glazed Tile	2110 11001	147	SF	,	10+ years		
Classroc	om #215 (Regular Classroom)							
	AC Units	2nd Floor	1	EΑ	7	6-10 years		
	Casework	2nd Floor	21	LF	7	10+ years		
	Ceiling - Splined	2nd Floor	751	SF	6	6-10 years		
	Ceiling - Splined	2nd Floor	5	SF	4	0-1 year	Water damage.	
	Chalk Board	2nd Floor	16	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	756	SF	7	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	22	EA	7	6-10 years		
	Marker Board	2nd Floor	8	LF	7	6-10 years		
	Student Lockers - One Tier	2nd Floor	26	EA	7	10+ years		
	Walls - Concrete Block	2nd Floor	558	SF	7	10+ years		
	Walls - Structural Glazed Tile	2nd Floor	147	SF	7	10+ years		
lassroc	om #216 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	21	LF	7	10+ years		
	Ceiling - Splined	2nd Floor	756	SF	7	10+ years		
	Chalk Board	2nd Floor	14	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	2nd Floor	14	EA	7	10+ years		
	Floor - Tile	2nd Floor 2nd Floor	756	SF	7	6-10 years		
	Lighting - Pendent/Surface	2nd Floor 2nd Floor	22	SF EA	7 7	6-10 years		
			8	LF	7	-		
	Marker Board	2nd Floor	8	ᄕ	1	6-10 years		

Campus Name: Ashburn Page : 23 of 30 Assessment Date: 03/03/2022



Catego	ory : Classroom		Building : Leased-Main						
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Storage/ Closet	2nd Floor	12	SF	7	10+ years			
	Student Lockers - One Tier	2nd Floor	26	EΑ	7	10+ years			
	Walls - Concrete Block	2nd Floor	558	SF	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	147	SF	7	10+ years			
Classro	om #217 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	57	LF	6	10+ years			
	Ceiling - Splined	2nd Floor	756	SF	7	10+ years			
	Chalk Board	2nd Floor	24	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	756	SF	7	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	22		7	6-10 years			
	Storage/ Closet	2nd Floor 2nd Floor	12	EA SF		•			
				_	7	10+ years			
	Student Lockers - One Tier	2nd Floor	26	EA	7	10+ years			
	Walls - Concrete Block	2nd Floor	558	SF	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	147	SF	7	10+ years			
lassro	om #B006 (Store Room)								
	Ceiling - Splined	1st Floor	440	SF	6	10+ years			
	Doors - Steel Doors incl hw	1st Floor	1	EΑ	7	10+ years			
	Floor - Tile	1st Floor	440	SF	7	6-10 years			
	Lighting - Lay-in	1st Floor	6	EA	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	320	SF	7	10+ years			
Catego	ory : Interior		В	uilding	: Lease	d-Main			
				Recommend					
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
orridor	r								
	Ceiling - Splined	Basement B-010	800	SF	7	10+ years			
	Floor - Tile/Sheet	Basement B-010	800	SF	7	6-10 years			
	Lighting - Lay-in	Basement B-010	4	EΑ	7	6-10 years			
	Walls - Plaster/Drywall	Basement B-010	1,485	SF	7	10+ years			
	Ceiling - Splined	Basement B-011	323	SF	7	10+ years			
		Basement B-011	318	SF	7	6-10 years			
	Floor - Tile/Sheet	Dasement D-011			•				
	Floor - Tile/Sheet Floor - Tile/Sheet			SF	4	0-1 vear	Broken Tiles		
	Floor - Tile/Sheet	Basement B-011	5	SF FA	4 7	0-1 year 6-10 years	Broken Tiles		
	Floor - Tile/Sheet Lighting - Lay-in	Basement B-011 Basement B-011	5 2	EA	7	6-10 years	Broken Tiles		
	Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall	Basement B-011 Basement B-011 Basement B-011	5 2 705	EA SF	7	6-10 years 10+ years			
	Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall Walls - Plaster/Drywall	Basement B-011 Basement B-011 Basement B-011 Basement B-011	5 2 705 10	EA SF SF	7 7 5	6-10 years 10+ years 0-1 year	Broken Tiles Cracking.		
	Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall Walls - Plaster/Drywall Ceiling - Splined	Basement B-011 Basement B-011 Basement B-011 Basement B-011 Corridor 1	5 2 705 10 1,070	EA SF SF SF	7 7 5 7	6-10 years 10+ years 0-1 year 10+ years	Cracking.		
	Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall Walls - Plaster/Drywall Ceiling - Splined Ceiling - Splined	Basement B-011 Basement B-011 Basement B-011 Basement B-011 Corridor 1 Corridor 1	5 2 705 10 1,070 10	EA SF SF SF	7 7 5 7 4	6-10 years 10+ years 0-1 year 10+ years 0-1 year			
	Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall Walls - Plaster/Drywall Ceiling - Splined	Basement B-011 Basement B-011 Basement B-011 Basement B-011 Corridor 1	5 2 705 10 1,070	EA SF SF SF	7 7 5 7	6-10 years 10+ years 0-1 year 10+ years	Cracking.		



Catego	ry : Interior		Building : Leased-Main						
	_					Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Pendent/Surface	Corridor 1	9	EA	7	6-10 years			
	Walls - Concrete Block	Corridor 1	1,200	SF	7	10+ years			
	Walls - Structural Glazed Tile	Corridor 1	1,200	SF	7	10+ years			
	Ceiling - Splined	Corridor 2	1,782	SF	7	10+ years			
	Drinking Fountains - Single Fountain	Corridor 2	1	EA	7	10+ years			
	Floor - Terrazzo	Corridor 2	1,782	SF	7	10+ years			
	Lighting - Pendent/Surface	Corridor 2	9	EA	7	6-10 years			
	Walls - Plaster/Drywall	Corridor 2	1,175	SF	7	10+ years			
	Walls - Structural Glazed Tile	Corridor 2	1,175	SF	7	10+ years			
	Ceiling - Splined	Corridor 3	666	SF	7	10+ years			
	Drinking Fountains - Single Fountain	Corridor 3	1	EA	7	10+ years			
	Floor - Terrazzo	Corridor 3	666	SF	7	10+ years			
	Lighting - Pendent/Surface	Corridor 3	11	EA	7	6-10 years			
	Walls - Concrete Block	Corridor 3	830	SF	7	10+ years			
	Walls - Structural Glazed Tile	Corridor 3	830	SF	7	10+ years			
	Ceiling - Splined	Corridor 4	1,772	SF	6	6-10 years			
	Ceiling - Splined	Corridor 4	10	SF	4	0-1 year	Damaged tile		
	Drinking Fountains - Single Fountain	Corridor 4	1	EA	7	10+ years			
	Floor - Terrazzo	Corridor 4	1,782	SF	7	10+ years			
	Lighting - Pendent/Surface	Corridor 4	9	EA	7	6-10 years			
	Walls - Plaster/Drywall	Corridor 4	1,175	SF	7	10+ years			
	Walls - Structural Glazed Tile	Corridor 4	1,175	SF	7	10+ years			
	Ceiling - Splined	Corridor 5	1,080	SF	7	10+ years			
	Drinking Fountains - Single Fountain	Corridor 5	2	EA	7	10+ years			
	Floor - Terrazzo	Corridor 5	1,080	SF	7	10+ years			
	Lighting - Lay-in	Corridor 5	4	EA	6	6-10 years			
	Lighting - Pendent/Surface	Corridor 5	5	EA	7	6-10 years			
	Walls - Concrete Block	Corridor 5	1,200	SF	7	10+ years			
	Walls - Structural Glazed Tile	Corridor 5	1,200	SF	7	10+ years			
	Ceiling - Splined	Corridor 6	666	SF	7	10+ years			
	Drinking Fountains - Single Fountain	Corridor 6	2	EA	7	10+ years			
	Floor - Terrazzo	Corridor 6	666	SF	7	6-10 years			
	Lighting - Pendent/Surface	Corridor 6	10	EA	7	6-10 years			
	Walls - Concrete Block	Corridor 6	830	SF	7	10+ years			
	Walls - Structural Glazed Tile	Corridor 6	830	SF	7	10+ years			
Safety									
•	Camera Viewing Station	1st Floor	1	EA	7	6-10 years			
	Security Cameras	1st Floor	5	EA	7	6-10 years			
Stairs									
Jidiio	Ceiling - Plaster/Drywall	#2	162	SF	7	10+ years			
	Ceiling - Splined	#2	420	SF	7	10+ years			
	Floor - Terrazzo	#2	540	SF	7	10+ years			

Campus Name: Ashburn Page : 25 of 30 Assessment Date: 03/03/2022



Catego	ry : Interior	Building : Leased-Main						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Handrails	#2	113	LF	7	10+ years		
	Lighting - Lay-in	#2	4	EA	7	10+ years		
	Lighting - Pendent/Surface	#2	4	EA	7	10+ years		
	Stairs - Terrazzo	#2	312	LF	7	10+ years		
	Walls - Plaster/Drywall	#2	2,469	SF	7	10+ years		
	Walls - Structural Glazed Tile	#2	915	SF	7	10+ years		
	Ceiling - Plaster/Drywall	#4	540	SF	6	10+ years		
	Ceiling - Plaster/Drywall	#4	162	SF	6	10+ years		
	Ceiling - Splined	#4	420	SF	6	10+ years		
	Floor - Terrazzo	#4	540	SF	7	10+ years		
	Handrails	#4	113	LF	7	10+ years		
	Lighting - Pendent/Surface	#4	6	EA	7	10+ years		
	Stairs - Terrazzo	#4	312	LF	6	10+ years		
	Walls - Plaster/Drywall	#4	2,469	SF	7	10+ years		
	Walls - Structural Glazed Tile	#4	915	SF	7	10+ years		
	Ceiling - Plaster/Drywall	#5	50	SF	7	10+ years		
	Ceiling - Splined	#5	374	SF	7	10+ years		
	Ceiling - Splined	#5	10	SF	4	0-1 year	Damaged tiles	
	Floor - Terrazzo	#5	403	SF	7	10+ years		
	Handrails	#5	54	LF	7	10+ years		
	Lighting - Pendent/Surface	#5	3	EA	7	10+ years		
	Stairs - Terrazzo	#5	96	LF	7	10+ years		
	Walls - Concrete Block	#5	940	SF	7	10+ years		
	Walls - Structural Glazed Tile	#5	625	SF	7	10+ years		
	Ceiling - Splined	6A	119	SF	6	10+ years		
	Floor - Terrazzo	6A	21	SF	7	10+ years		
	Handrails	6A	26	LF	7	10+ years		
	Lighting - Pendent/Surface	6A	1	EA	7	10+ years		
	Stairs - Terrazzo	6A	105	LF	7	10+ years		
	Walls - Structural Glazed Tile	6A	441	SF	7	10+ years		
	Walls - Structural Glazed Tile	6A	10	SF	4	0-1 year	Cracking near edges.	
	Ceiling - Splined	6B	250	SF	6	10+ years		
	Floor - Terrazzo	6B	176	SF	7	10+ years		
	Handrails	6B	40	LF	7	10+ years		
	Lighting - Pendent/Surface	6B	3	EA	7	10+ years		
	Stairs - Terrazzo	6B	100	LF	7	10+ years		
	Walls - Plaster/Drywall	6B	180	SF	7	10+ years		
	Walls - Structural Glazed Tile	6B	420	SF	7	10+ years		
	Ceiling - Plaster/Drywall	Stairs #1	35	SF	7	10+ years		
	Ceiling - Splined	Stairs #1	243	SF	7	10+ years		
	Floor - Terrazzo	Stairs #1	99	SF	7	10+ years		
	Handrails	Stairs #1	45	LF	7	10+ years		
	Lighting - Lay-in	Stairs #1	2	EA	6	6-10 years		
	Stairs - Terrazzo	Stairs #1	92	LF	7	10+ years		
	J.S TOTTQLLO		02		•	10. 300.0		



Catego	ry : Interior	В					
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	Stairs #1	745	SF	7	10+ years	
	Walls - Structural Glazed Tile	Stairs #1	335	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Stairs #3	65	SF	7	10+ years	
	Ceiling - Splined	Stairs #3	420	SF	6	10+ years	
	Floor - Terrazzo	Stairs #3	240	SF	7	10+ years	
	Handrails	Stairs #3	54	LF	7	10+ years	
	Lighting - Lay-in	Stairs #3	4	EΑ	6	6-10 years	
	Stairs - Terrazzo	Stairs #3	115	LF	7	10+ years	
	Walls - Masonry	Stairs #3	816	SF	7	10+ years	
	Ceiling - Splined	Vestibule #1	63	SF	6	10+ years	
	Floor - Terrazzo	Vestibule #1	63	SF	7	10+ years	
	Lighting - Lay-in	Vestibule #1	1	EA	6	6-10 years	
	Walls - Masonry	Vestibule #1	112	SF	7	10+ years	
	Ceiling - Splined	Vestibule #4	217	SF	7	10+ years	
	Ceiling - Splined	Vestibule #4	4	SF	4	0-1 year	Cracked.
	Floor - Terrazzo	Vestibule #4	221	SF	7	10+ years	
	Lighting - Lay-in	Vestibule #4	6	EA	7	6-10 years	
	Walls - Concrete Block	Vestibule #4	108	SF	7	10+ years	
	Walls - Structural Glazed Tile	Vestibule #4	180	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Vestibule #6	352	SF	7	10+ years	
	Floor - Terrazzo	Vestibule #6	352	SF	7	10+ years	
	Lighting - Pendent/Surface	Vestibule #6	4	EA	7	6-10 years	
	Walls - Masonry	Vestibule #6	480	SF	7	10+ years	





Category : Site **Building: Site**

_Civil/Draina ((Item - Type age Civil/ Drainage - Catch Basin	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Civil/Draina ((age	Location	Quantity	UOM	Kank	Reniacement	Comments
(Replacement	Comments
(Civil/ Drainage Catch Pagin						
(Entire Site	4	EA	7	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	4	0-1 year	Sinking
	Civil/ Drainage - Site Drain	Entire Site	1	EA	7	10+ years	
(Civil/ Drainage - Site Manhole	Entire Site	9	EA	7	10+ years	
-							
Fencing	F						
	Fencing - Chain Link	Entire Site	445	LF	4	0-1 year	Falling over, bending.
	Fencing - Old Standard Ornamental	Entire Site	87	LF	7	10+ years	
Landscape	9						
	Irrigation	Entire Site	5,010	SF	7	10+ years	
	Landscape - Grass	Entire Site	5,010	SF	7	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	2,415	SF	4	0-1 year	Cracking, holes, and patches
			_,		-	- · , - · · ·	throughout.
I	Landscape - Hardscape- Concrete	Entire Site	4,750	SF	6	10+ years	
	Parkway trees	Entire Site	8	EA	7	10+ years	
	Planting Beds/ Area	Entire Site	1,250	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	11,900	SF	4	0-1 year	Per Principal and Building Engineer:
		5	,	0.	·	o . , jou	The Southeast section of Parking lot is deemed Play area for kids. Broker cracking, and holes throughout.
	Retaining Wall - Concrete	Entire Site	405	SF	7	10+ years	3,
	Trash Receptacles	Entire Site	3	EA	7	10+ years	
Parking Lo	nt .						
•	Surface - Asphalt	West	31,000	SF	4	0-1 year	Broken, cracking, and gaps
							throughout.
;	Surface - Asphalt	West	8,000	SF	4	0-1 year	Broken, cracking, and gaps throughout.
Sidewalks							
	Sidewalks - Perimeter Sidewalks	Entire Site	13,266	SF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	600	SF	4	0-1 year	Cracking and uneven throughout.
`	Cidewalks Terrificier Cidewalks	Litting Oile	000	O.	7	o i youi	Gracking and uneven unoughout.
Signage							
	Flag Pole - Flag Pole	East	1	EA	7	10+ years	
	Marquee - Free Standing Back Lighted	East	1	EA	7	6-10 years	
1	Monument - Building Mounted Cut Letter Sign	East	1	EA	7	6-10 years	

Campus Name: Ashburn Page : 28 of 30 Assessment Date: 03/03/2022



Ashburn Community Elementary School

8300 S St Louis AVENUE, Chicago, IL 60652

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- · Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Ashburn Page : 29 of 30 Assessment Date: 03/03/2022



Classroom Summary

Classicom Summary			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Leased-Main	intended Osage	Room Location	Number	Number	(31)	Alea	Alea	Зюр	Doard
Art Room	Regular Classroom	1st Floor	107	106-4	930	185	58	Υ	Υ
Computer Lab	Computer Lab	1st Floor	109	108	930	167	167	Y	Ý
Computer Lab	Regular Classroom	1st Floor	113	112	930	167	49	Y	Y
Kindergarten	Regular Classroom	1st Floor	102	102-1	732	176	54	Y	Y
Kindergarten	Regular Classroom	1st Floor	103	103-K	732	176	54	Y	Y
Music Room	Regular Classroom	1st Floor	106	107-3	930	185	58	Y	Y
Office	Regular Classroom	2nd Floor	212	NA	744	176	54	Υ	Y
Regular Classroom	Art Room	2nd Floor	201	201-Art	744	176	54	Υ	Y
Regular Classroom	Regular Classroom	1st Floor	104		732	176	54		
Regular Classroom	Regular Classroom	1st Floor	105		732	176	54		
Regular Classroom	Regular Classroom	1st Floor	114	NA	805	161	53	Υ	Y
Regular Classroom	Regular Classroom	1st Floor	115	NA	805	161	53	Υ	Y
Regular Classroom	Regular Classroom	1st Floor	116	NA	805	161	53	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	117	NA	805	161	53	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	202-8	744	176	54	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	203-7	744	176	54	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	205	205-5	744	176	54	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	NA	744	176	54	Y	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	744	162	46	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	209	209	744	176	54	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	210	NA	744	176	54	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	211	211	744	176	54	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	213	213	744	176	54	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	215	NA	756	168	51	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	216	NA	756	168	51	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	217	NA	756	168	51	Υ	Υ
Science Classroom	Regular Classroom	2nd Floor	208	NA	744	176	57	Υ	Υ
Special Education	Regular Classroom	1st Floor	101	101-2	732	160	46	Υ	Υ
Special Education	Regular Classroom	2nd Floor	204	204-6	744	162	46	Y	Υ
Special Education	Regular Classroom	2nd Floor	214	NA	756	163	53	Y	Υ
Store Room	Office	1st Floor	B006	B006	440	42	14	Y	N