

### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition<sup>1</sup>. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <u>http://www.cps.edu/facilityassessment</u>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1928	3	53,503
Addition	1973	2	28,700
Campus Total			82,203

Catego	ry : Exterior	В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	#1 - main - SE	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#1 - main - SE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1 - main - SE	2	EA	7	10+ years	
	Exterior Stairs - Concrete	#1 - main - SE	75	LF	7	10+ years	
	Ramps - Concrete	#1 - main - SE	30	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#1 - main - SE	18	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	#2 - SE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#2 - SE	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#2 - SE	10	LF	4	0-1 year	Cracking and displacement
	Exterior Stairs - Concrete	#2 - SE	70	LF	4	0-1 year	Cracking and displacement
	Exterior Stairs - Stone	#2 - SE	54	LF	4	0-1 year	Significant gape between steps
	Exterior Doors - Exterior Steel Door	#3 - SW	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#3 - SW	1	EA	5	0-1 year	Rusting.
	Exterior Doors - Overhead Rolling/ Garage	#3.5 - SW	1	EA	7	10+ years	C
	Door					2	
	Exterior Doors - Exterior Steel Door	#7 - NE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#7 - NE	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#7 - NE	1	EA	5	6-10 years	
	Exterior Stairs - Concrete	#7 - NE	20	LF	4	0-1 year	Cracking and broken pieces
	Exterior Stairs - Stone	#7 - NE	42	LF	4	0-1 year	Significantly distressed
	Exterior Doors - Exterior Steel Door	#8 - NE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#8 - NE	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#8 - NE	75	LF	7	10+ years	



Exterior n - Type r Handrail - Steel_Stair Handrail Indation - Concrete ndation - Concrete berstructure - Steel with Clay Tile Arch erior Lighting - Parapet or Roof Mounted erior Lighting - Wall Mounted wnspouts - Exterior Downspouts of - Modified Bitumen	Location #8 - NE Entire Building Entire Building Entire Building Entire Building Entire Building	Quantity 12 876 20 53,503 11 2	UOM LF LF LF SF EA	Rank 7 7 4 7	Recommend Replacement 10+ years 0-1 year 10+ years	Comments Interior playground area. Concrete missing
r Handrail - Steel_Stair Handrail ndation - Concrete ndation - Concrete erstructure - Steel with Clay Tile Arch erior Lighting - Parapet or Roof Mounted erior Lighting - Wall Mounted	#8 - NE Entire Building Entire Building Entire Building Entire Building	12 876 20 53,503 11	LF LF LF SF	7 7 4	Replacement 10+ years 10+ years 0-1 year	Interior playground area. Concre
r Handrail - Steel_Stair Handrail ndation - Concrete ndation - Concrete erstructure - Steel with Clay Tile Arch erior Lighting - Parapet or Roof Mounted erior Lighting - Wall Mounted	#8 - NE Entire Building Entire Building Entire Building Entire Building	12 876 20 53,503 11	LF LF LF SF	7 7 4	10+ years 10+ years 0-1 year	Interior playground area. Concre
ndation - Concrete ndation - Concrete perstructure - Steel with Clay Tile Arch erior Lighting - Parapet or Roof Mounted erior Lighting - Wall Mounted	Entire Building Entire Building Entire Building Entire Building	876 20 53,503 11	LF LF SF	7 4	10+ years 0-1 year	
ndation - Concrete berstructure - Steel with Clay Tile Arch erior Lighting - Parapet or Roof Mounted erior Lighting - Wall Mounted	Entire Building Entire Building Entire Building	20 53,503 11	LF SF	4	0-1 year	
ndation - Concrete berstructure - Steel with Clay Tile Arch erior Lighting - Parapet or Roof Mounted erior Lighting - Wall Mounted	Entire Building Entire Building Entire Building	20 53,503 11	LF SF	4	0-1 year	
erstructure - Steel with Clay Tile Arch erior Lighting - Parapet or Roof Mounted erior Lighting - Wall Mounted	Entire Building	53,503	SF		-	
erior Lighting - Parapet or Roof Mounted erior Lighting - Wall Mounted	Entire Building	11	_	7	10+ years	missing
erior Lighting - Wall Mounted			FA			
erior Lighting - Wall Mounted			FA			
vnspouts - Exterior Downspouts	Entire Building	2	<b>-</b> / `	7	10+ years	
			EA	7	10+ years	
of - Modified Bitumen	Low CT YD	30	LF	6	10+ years	
	Low CT YD	355	SF	6	2-5 years	
of Structure - Concrete	Low CT YD	355	SF	7	10+ years	
ess Ladder - Metal	Low N	1	EA	5	6-10 years	
ping - Terra Cotta	Low N	381	LF	6	10+ years	
vnspouts - Interior Downspouts	Low N	160	LF	6	10+ years	
apet - 16" - 30" Height	Low N	90	LF	6	10+ years	
apet - Parapet < 16" Height	Low N	280	LF	6	10+ years	
apet - Parapet > 30"	Low N	5	LF	6	10+ years	
of - Modified Bitumen	Low N	6,700	SF	6	2-5 years	
of Hatch - Metal	Low N	1	EA	7	10+ years	
of Hatch - Metal	Low N	2	EA	4	0-1 year	Not in use
of Structure - Concrete	Low N	6,700	SF	7	10+ years	
bing - Terra Cotta	Low S	193	LF	6	10+ years	
vnspouts - Interior Downspouts	Low S	60	LF	6	10+ years	
apet - 16" - 30" Height	Low S	50	LF	6	10+ years	
apet - Parapet < 16" Height	Low S Low S	143	LF	6	10+ years	
of - Modified Bitumen	Low S	3,864	SF	5		
					2-5 years	
of Structure - Concrete	Low S	3,864	SF	7	10+ years	
bing - Terra Cotta	Low W	130	LF	6	10+ years	
vnspouts - Interior Downspouts	Low W	36	LF	6	10+ years	
of Structure - Concrete		,				
ess Ladder - Metal						
mney - Brick Chimney- Stainless Steel	Main Roof	80	LF	6	10+ years	
	Main Roof	455	IF	6	10+ vears	
er						
er ving - Terra Cotta						
ap of - of S es	et - Parapet < 16" Height Modified Bitumen Structure - Concrete s Ladder - Metal ney - Brick Chimney- Stainless Steel g - Terra Cotta spouts - Interior Downspouts	et- Parapet < 16" HeightLow WModified BitumenLow WStructure - ConcreteLow Ws Ladder - MetalMain Roofney - Brick Chimney- Stainless SteelMain Roofg - Terra CottaMain Roofspouts - Interior DownspoutsMain Roof	et- Parapet < 16" HeightLow W130Modified BitumenLow W1,800Structure - ConcreteLow W1,800s Ladder - MetalMain Roof2ney - Brick Chimney- Stainless SteelMain Roof80g - Terra CottaMain Roof455	et- Parapet < 16" HeightLow W130LFModified BitumenLow W1,800SFStructure - ConcreteLow W1,800SFs Ladder - MetalMain Roof2EAney - Brick Chimney- Stainless SteelMain Roof80LFg - Terra CottaMain Roof455LFspouts - Interior DownspoutsMain Roof240LF	et- Parapet < 16" HeightLow W130LF6Modified BitumenLow W1,800SF5Structure - ConcreteLow W1,800SF7s Ladder - MetalMain Roof2EA7ney - Brick Chimney- Stainless SteelMain Roof80LF6g - Terra CottaMain Roof455LF6spouts - Interior DownspoutsMain Roof240LF6	et- Parapet < 16" HeightLow W130LF610+ yearsModified BitumenLow W1,800SF52-5 yearsStructure - ConcreteLow W1,800SF710+ yearss Ladder - MetalMain Roof2EA710+ yearsney - Brick Chimney- Stainless SteelMain Roof80LF610+ yearsg - Terra CottaMain Roof455LF610+ yearsspouts - Interior DownspoutsMain Roof240LF610+ years



7650 S Wolcott AVENUE, Chicago, IL 60620 **Category : Exterior Building : Main** Recommend Item - Type Group Location Quantity UOM Rank Replacement Comments Parapet - Parapet > 30" LF Main Roof 245 5 10+ years Roof - Modified Bitumen Main Roof 11.050 SF 5 2-5 years Minor leaks reported by engineer Roof Hatch - Metal Main Roof 2 ΕA 7 10+ years Roof Structure - Concrete SF 7 Main Roof 11.050 10+ years Walls Cheek-Wall - Stone Entire Building 144 SF 6 10+ years LF Cornice - Terra Cotta Entire Building 1,018 6 10+ years SF Exterior Walls - Brick Entire Building 31.277 6 10+ years SF Exterior Walls - Brick Entire Building 400 6 10+ years Exterior Walls - Brick Entire Building 100 SF 4 0-1 year Cracking Exterior Walls - Concrete Block Entire Building 80 SF 4 0-1 year Cracking SF Exterior Walls - Stone-Cast Entire Building 6 10+ years 1,406 SF Exterior Walls - Terra Cotta Entire Building 3,550 6 10+ years Windows Guard - Guards perforated 2,652 SF 6 Entire Building 10+ years Lintels - Steel 897 LF 6 10+ years Entire Building SF 7 Windows - Sash Aluminum Double-pane Entire Building 8,598 10+ years

### **Category : Electrical**

oulogo				ananig	· mann				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
•	ncy System	Location	Quantity	0011	Nank	Replacement	Comments		
merger	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	4	EA	6	6-10 years	Quantity adjusted to match current observations.		
	Emergency Battery Packs - Corridors and Stairs	Entire Building	5	EA	6	6-10 years			
	Exit Signs - Auditoium	Entire Building	6	EA	6	6-10 years			
	Exit Signs - Corridors and Stairs	Entire Building	16	EA	6	6-10 years	Upgraded since last assessment		
	Exit Signs - Gym	Entire Building	1	EA	6	6-10 years	Expired light bulb(s)		
	Exit Signs - Gym	Entire Building	1	EA	5	0-1 year	Exit sign is not illuminated		
	Security System - CCTV	Entire Building	60,000	SF	7	6-10 years			
	Security System - Intrusion Detection	Entire Building	60,000	SF	6	6-10 years			
	Automatic Transfer Switch	Mechanical Room	· 1	EA	6	6-10 years	ATS-2.		
	Automatic Transfer Switch	Mechanical Room	1	EA	4	0-1 year	ATS-1. Nonfunctional. Replaced b ATS-2.		
	Emergency Generator- Outdoor- Diesel - Below 60 KW	Site West	1	EA	6	6-10 years	Serves EM circuits in Main and Addition.		
lain Sei	vice								
	PA System	Entire Building	60,000	SF	6	6-10 years	Serves Main and Addition		
	Main Electrical Service - 1200 A	Mechanical Room	1	EA	4	2-5 years	60-plus years old, showing signs of		

Building : Main



Catego	ry : Electrical		В	uilding	: Main		
_						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	120/240/3PH						corrosion.
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	5	EA	7	10+ years	3F, 2F, Bsmt
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	2-5 years	Damaged door. Quantity adjusted to match current observations.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	2F, Bsmt
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	4	2-5 years	Damaged door, missing breaker. Quantity adjusted to match current observations.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	4	2-5 years	60-plus years old, showing signs of corrosion.
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - Less than 400 amp	Entire Building	2	EA	6	6-10 years	
	Transformers - 277/480 - 120/240	Entire Building	1	EA	6	6-10 years	
Catego	ry : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	Entire Building	1	EA	6	2-5 years	Serves Main and Addition
	Fire Alarm Strobe Lights	Entire Building	48,000	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	48,000	SF	5	2-5 years	
Catago	m. Maahaniaal		Р		. Main		
Catego	ry : Mechanical		D	uilding		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•		Location	Quantity		INALIK	Replacement	Comments
Air Cond	0	Lauran Dalaf	4	۳.	-	0.5	Net dive the second black a set
	Condensing Unit- Roof Mounted - Less than 5 tons	Lower Roof	1	EA	5	2-5 years	Not directly accessible in a safe manner at the time of assessment.
Air Hand	ling Systems						
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm	Basement	1	EA	5	6-10 years	S-2. Serves the south section of the building.
	Air Intake	Basement	1	EA	6	6-10 years	
	Auxiliaries - 15001 - 25000 cfm	Basement	1	EA	6	6-10 years	
	Reheat Boxes - Reheat Boxes with Steam Coil	Basement	4	EA	6	6-10 years	Quantity changed to match current observations.
	Return Duct Work - Masonry and Ducts-	Basement	40	LF	6	6-10 years	



	ry : Mechanical		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Missing or Existing Shaft						
	Zone Dampers	Basement	12	EA	6	2-5 years	Quantity adjusted to match current observations.
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm	Basement	1	EA	5	6-10 years	S-1. Serves the auditorium.
	Air Intake	Basement	1	EA	6	6-10 years	
	Auxiliaries - 8001 - 15000 cfm	Basement	1	EA	6	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement	40	LF	6	6-10 years	
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm	Basement	1	EA	5	6-10 years	Original to the building. S-4. Serves the gym.
	Air Intake	Basement	1	EA	6	6-10 years	
	Auxiliaries - 4000 - 8000 cfm	Basement	1	EA	6	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement	40	LF	6	6-10 years	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	Basement	1	EA	5	6-10 years	Original to the building. S-3. Serves north section of the building.
	Air Intake	Basement	1	EA	6	6-10 years	
	Auxiliaries - 25001 - 35000 cfm	Basement	1	EA	6	6-10 years	
	Reheat Boxes - Reheat Boxes with Steam Coil	Basement	6	EA	6	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement	50	LF	6	6-10 years	
	Zone Dampers	Basement	16	EA	6	6-10 years	
	Outdoor Return Fans- Air Handling Unit Type - 10001 - 20000 CFM	Roof	1	EA	6	6-10 years	
	Outdoor Return Fans- Air Handling Unit Type - 10001 - 20000 CFM	Roof	1	EA	6	6-10 years	
	Outdoor Return Fans- Air Handling Unit Type - 10001 - 20000 CFM	Roof	1	EA	6	6-10 years	
	Outdoor Return Fans- Air Handling Unit Type - 5000 - 10000 CFM	Roof	1	EA	6	6-10 years	Not directly accessible in a safe manner at the time of assessment.
Boiler Sy	stems						
,	Boiler Auxiliary- Steam Boiler - 76 - 100 HP	Boiler Room	2	EA	6	6-10 years	
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	1	EA	6	6-10 years	
	Condensate Pump	Boiler Room	2	EA	6	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	6-10 years	
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Steam Boiler - 76 - 100 HP	Boiler Room	2	EA	6	6-10 years	
	Piping - Condensate Pipe- Steel	Boiler Room	800	LF	6	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	800	LF	6	6-10 years	



Categor	y : Mechanical		В	uilding	: Main	•	000 S WOROU AVENOL, Chicago, ie 00020
e legel	, · ······		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Steam Traps	Boiler Room	65	EA	5	6-10 years	Quantity adjusted as total has been divided/aggregated.
	Vacuum Pump	Boiler Room	1	EA	6	6-10 years	
Gas Boos	ster						
	Gas Booster	Boiler Room	2	EA	6	10+ years	
Heating [	Devices						
	Fin Tube - Steam	1st Floor	2	LF	7	10+ years	
	Unit Heater - Electric	Boiler Room	2	EA	7	6-10 years	Quantity and location changed to match current observations.
	Unit Heater - Steam	Boiler Room	2	EA	6	6-10 years	
	Radiators - Steam	Entire Building	34	EA	6	6-10 years	
	Wall Heater - Electric	Room 310	2	EA	6	6-10 years	
Mechanic	cal Plumbing						
	Condensate-Steel or Galvanized	Entire Building	1,200	LF	5	6-10 years	
Temperat	ture Control						
	DDC System	Entire Building	53,503	SF	6	6-10 years	Software upgrade being performed b the technician on the day of assessment.
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	Temperature control for the two steam unit heaters.
	Thermostats - DDC	Entire Building	36	EA	6	6-10 years	
Ventilatio	n						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	2	EA	6	6-10 years	
Categor	y : Plumbing		В	uilding	: Main		
•		1				Recommend	0
Group Hot Wate	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	10+ years	Four years old at the time of assessment; Priority Rep adjusted based on current observations.
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	53,503	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	53,503	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to	Entire Building	53,503	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to	Entire Building	53,503	SF	6	6-10 years	



	Schools					/	650 S Wolcott AVENUE, Chicago, IL 60620
Catego	ory : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	53,503	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	53,503	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	53,503	SF	6	6-10 years	
	Sanitary Piping	Entire Building	53,503	SF	6	6-10 years	
	Storm Piping	Entire Building	53,503	SF	6	6-10 years	
	Vent Piping	Entire Building	53,503	SF	6	6-10 years	Inside the walls; not directly accessible at the time of assessment.
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Mechanical Room	1	EA	7	10+ years	For domestic cold water.
	Pumps - Domestic Booster Pump-Simplex	Mechanical Room	1	EA	7	10+ years	For domestic hot water. Quantity changed to match current observations.
	Pumps - Sump-Simplex	Mechanical Room	1	EA	7	10+ years	Upgraded since last assessment
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Adminis	trative Suites/Offices						
	Ceiling - Plaster/Drywall	1st floor engineers offices next to boiler room	273	SF	4	0-1 year	Cracked
	Doors - Wood Doors inclu hw	1st floor engineers offices next to boiler room	1	EA	7	10+ years	
	Floor - Tile	1st floor engineers offices next to boiler room	273	SF	6	2-5 years	
	Lighting - Pendent/Surface	1st floor engineers offices next to boiler room	4	EA	6	2-5 years	No damage observed
	Power Distribution	1st floor engineers offices next to boiler room	12	EA	7	10+ years	
	Walls - Plaster/Drywall	1st floor engineers offices next to boiler room	890	SF	5	6-10 years	No damage observed
	Ceiling - Plaster/Drywall	1st floor main office	743	SF	7	10+ years	
	Doors - Transom Window	1st floor main office	4	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor main office	2	EA	7	10+ years	
		1st floor main office	743	SF	7	10+ years	
	Floor - Wood						
	Floor - Wood Lighting - Pendent/Surface	1st floor main office	12	EA	6	2-5 years	No damage observed
	Lighting - Pendent/Surface Power Distribution		12 18	EA	7	2-5 years 10+ years	No damage observed
	Lighting - Pendent/Surface	1st floor main office		EA SF			No damage observed
	Lighting - Pendent/Surface Power Distribution	1st floor main office 1st floor main office	18	EA	7	10+ years	No damage observed



Catego	ry : Room		В	uilding	: Main		
J				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st floor next to auditorium	1	EA	7	10+ years	
	Floor - Carpet	1st floor next to auditorium	331	SF	6	2-5 years	
	Lighting - Pendent/Surface	1st floor next to auditorium	5	EA	6	2-5 years	No damage observed
	Power Distribution	1st floor next to auditorium	6	EA	7	10+ years	5
	Walls - Plaster/Drywall	1st floor next to auditorium	1,025	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st floor next to room 110	237	SF	7	10+ years	
	Doors - Transom Window	1st floor next to room 110	4	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor next to room 110	1	ĒA	7	10+ years	
	Floor - Carpet	1st floor next to room 110	237	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st floor next to room 110	4	EA	6	2-5 years	No damage observed
	Power Distribution	1st floor next to room 110	6	EA	7	10+ years	ne aamage obeented
	Walls - Plaster/Drywall	1st floor next to room 110	877	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd floor next to auditorium #202	331	SF	7	10+ years	
	Doors - Transom Window	2nd floor next to auditorium #202	4	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd floor next to auditorium #202	1	EA	7	10+ years	
	Floor - Tile	2nd floor next to auditorium #202	331	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd floor next to auditorium #202	5	EA	6	2-5 years	No damage observed
	Power Distribution	2nd floor next to auditorium #202	5	EA	7	10+ years	No damage observed
	Walls - Plaster/Drywall		1,025	SF	7	,	
	Ceiling - Plaster/Drywall	2nd floor next to auditorium #202	358	SF		10+ years	
		3rd floor north end of corridor		SF	7	10+ years	
	Doors - Transom Window	3rd floor north end of corridor	4		7	10+ years	
	Doors - Wood Doors inclu hw	3rd floor north end of corridor	1	EA	7	10+ years	
	Floor - Wood	3rd floor north end of corridor	358	SF	7	10+ years	<b>N N N N</b>
	Lighting - Pendent/Surface	3rd floor north end of corridor	4	EA	6	2-5 years	No damage observed
	Power Distribution	3rd floor north end of corridor	6	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd floor north end of corridor	1,056	SF	7	10+ years	
uditoriu	um & Theater						
	Balcony Seating	1st floor	80	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st floor	2,875	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor	10	EA	7	10+ years	
	Floor - Concrete	1st floor	2,875	SF	7	10+ years	
	Lighting - Chandelier, Incandescent	1st floor	6	EA	7	10+ years	
	Main Floor Seating	1st floor	208	EA	7	10+ years	
	Sound System	1st floor	1	EA	4	2-5 years	
	Stage	1st floor	445	SF	7	10+ years	
	Stage Curtain	1st floor	2	EA	7	10+ years	
	Stage Lighting System	1st floor	1	EA	7	6-10 years	
	Stage-Stairs - Wood	1st floor	20	LF	7	10+ years	
	Walls - Plaster/Drywall	1st floor	5,800	SF	7	10+ years	
iymnas	ia						
	Ceiling - Plaster/Drywall	1st Floor	2,996	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	2,330	SF	4	0-1 year	Damaged
			20	5	<b>T</b>	U i yeai	Damagou



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	3,016	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	7	6-10 years	
	Scoreboards	1st Floor	1	EA	7	10+ years	
	Sound System	1st Floor	1	EA	4	2-5 years	Not found
	Walls - Plaster/Drywall	1st Floor	4,315	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	20	SF	4	0-1 year	Damaged
	Walls - Structural Glazed Tile	1st Floor	1,445	SF	7	10+ years	
brary							
<u>orary</u>	AC Unit	1st Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,254	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,254	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	24	EA	6	2-5 years	No damage observed
	Storage/ Closet	1st Floor	115	SF	7	10+ years	te aamage encorrea
	Walls - Plaster/Drywall	1st Floor	1,956	SF	7	10+ years	
			.,		-	,	
1DF_ID							
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Finishes	2nd Floor	85	SF	7	10+ years	
	Other Cooling Unit	2nd Floor	1	EA	7	6-10 years	
echani	cal/ Service Rooms						
	Janitor's Closet	2nd Floor	90	SF	7	10+ years	
	Janitor's Closet	3rd Floor	90	SF	7	10+ years	
	Storage Room	3rd Floor	245	SF	7	10+ years	
	Air Tunnel	Entire Building	2,000	SF	7	10+ years	
	Boiler Room	Entire Building	1,875	SF	7	10+ years	
	Coal Room	Entire Building	475	SF	7	10+ years	
	Loading Docks	Entire Building	125	SF	7	10+ years	
	Mechanical/ Service Rooms	Entire Building	2,000	SF	7	10+ years	
	Vaults	Entire Building	85	SF	5	10+ years	
				01	Ū	ior youro	
estroor				05	-	0.40	
	Accessories	1st floor 2 restrooms inside engineer's offices	60	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor 2 restrooms inside	60	SF	4	0-1 year	Peeling
	Doors - Wood Doors inclu hw	engineer's offices 1st floor 2 restrooms inside	1	EA	7	10+ years	
		engineer's offices				2	



Catego	ry : Room		B	uilding	· Main	,	550 S WORCOU AVENDE, Chicago, ie 60620
Calego	ry . Room			unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Oroup	Floor - Tile	1st floor 2 restrooms inside	60	SF	7	10+ years	Comments
		engineer's offices	00	01	,	Tor yourd	
	Lavatory	1st floor 2 restrooms inside	2	EA	7	10+ years	
		engineer's offices	-	_/ `	•	let jeale	
	Lighting - Pendent/Surface	1st floor 2 restrooms inside	2	EA	6	2-5 years	No damage observed
	5 5	engineer's offices				,	5
	Walls - Plaster/Drywall	1st floor 2 restrooms inside	290	SF	5	0-1 year	Cracked
	-	engineer's offices				-	
	Water Closet	1st floor 2 restrooms inside	2	EA	7	10+ years	
		engineer's offices					
	Accessories	1st floor boys	317	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor boys	317	SF	7	10+ years	
	Doors - Transom Window	1st floor boys	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor boys	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor boys	317	SF	7	10+ years	
	Floor Drain	1st floor boys	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st floor boys	3	EA	6	6-10 years	No damage observed
	Partitions	1st floor boys	2	EA	7	10+ years	
	Urinals	1st floor boys	4	EA	7	10+ years	
	Walls - Plaster/Drywall	1st floor boys	505	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st floor boys	505	SF	7	10+ years	
	Water Closet	1st floor boys	2	EA	7	10+ years	
	Accessories	1st floor girl's	341	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor girl's	341	SF	7	10+ years	
	Doors - Transom Window	1st floor girl's	8	SF	7		
				SF		10+ years	
	Floor - Tile/Sheet	1st floor girl's	341	EA	7	10+ years	
	Floor Drain	1st floor girl's	1		7	10+ years	
	Lavatory	1st floor girl's	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st floor girl's	6	EA	6	6-10 years	No damage observed
	Partitions	1st floor girl's	6	EA	7	10+ years	
	Walls - Plaster/Drywall	1st floor girl's	534	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st floor girl's	534	SF	7	10+ years	
	Water Closet	1st floor girl's	6	EA	7	10+ years	
	Accessories	1st floor inside of gym used as	68	SF	4	0-1 year	
	Ceiling - Plaster/Drywall	storage 1st floor inside of gym used as	68	SF	5	1-2 years	
	<b>C</b>	storage		0.	Ũ		
	Doors - Wood Doors inclu hw	1st floor inside of gym used as storage	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st floor inside of gym used as storage	68	SF	7	10+ years	
	Lavatory	1st floor inside of gym used as storage	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st floor inside of gym used as	1	EA	6	2-5 years	No damage observed



**Building : Main** Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments storage 1st floor inside of ovm used as ΕA Partitions 5 6-10 years 1 storage 1st floor inside of gym used as 330 SF Walls - Plaster/Drywall 5 2-5 years No damage observed storage 1st floor inside of gym used as Water Closet EΑ 6 1 10+ years storage SF Accessories 1st floor men's inside auditorium 86 5 0-1 vear Damaged bathroom not in use Ceiling - Plaster/Drvwall 1st floor men's inside auditorium 86 SF 4 0-1 year Damaged Doors - Wood Doors inclu hw 1st floor men's inside auditorium 1 FΑ 6 6-10 vears Floor - Tile Ceramic/ Porcelain 1st floor men's inside auditorium 86 SF 7 10+ vears Lavatorv 1st floor men's inside auditorium 1 ΕA 6 10+ years Lighting - Pendent/Surface 2 ΕA 4 1-2 years 1st floor men's inside auditorium ΕA 5 Partitions 1st floor men's inside auditorium 1 6-10 years 6 Urinals 1st floor men's inside auditorium 1 EΑ 6-10 years Walls - Plaster/Drywall 360 SF 4 Damaged 1st floor men's inside auditorium 0-1 year ΕA 4 Water Closet 1st floor men's inside auditorium 1 0-1 vear Damaged 7 Accessories 1st floor teachers toilet 127 SF 6-10 years SF Ceiling - Plaster/Drvwall 1st floor teachers toilet 127 7 10+ vears Doors - Transom Window 1st floor teachers toilet SF 4 7 10+ years Doors - Wood Doors inclu hw 1st floor teachers toilet 1 ΕA 7 10+ years Floor - Tile Ceramic/ Porcelain 1st floor teachers toilet SF 7 10+ years 127 7 Lavatorv 1st floor teachers toilet 1 EA 10+ years 2 Lighting - Pendent/Surface 1st floor teachers toilet FΑ 6 2-5 years No damage observed Walls - Plaster/Drvwall 585 SF 7 1st floor teachers toilet 10+ years Water Closet 1st floor teachers toilet 1 EΑ 7 10+ vears SF Accessories 1st floor women inside auditorium 128 4 0-1 year Damaged not in use Ceiling - Plaster/Drywall 128 SF 3 0-1 year 1st floor women inside auditorium Doors - Wood Doors inclu hw ΕA 5 1st floor women inside auditorium 1 1-2 years Floor - Tile Ceramic/ Porcelain 1st floor women inside auditorium 128 SF 4 0-1 year 1st floor women inside auditorium FΑ 4 0-1 year Lavatorv 1 Lighting - Pendent/Surface 1st floor women inside auditorium 2 FΑ 4 2-5 vears Partitions 1st floor women inside auditorium 1 FΑ 4 0-1 vear Walls - Plaster/Drvwall 1st floor women inside auditorium 452 SF 4 0-1 year ΕA Water Closet 1st floor women inside auditorium 1 4 0-1 year SF 7 Accessories 2nd floor boys 317 6-10 years SF Ceiling - Plaster/Drywall 2nd floor boys 317 7 10+ years Doors - Transom Window SF 7 2nd floor boys 8 10+ years Doors - Wood Doors inclu hw 2nd floor boys 2 EΑ 7 10+ years SF Floor - Tile Ceramic/ Porcelain 2nd floor boys 317 7 10+ vears Floor Drain 2nd floor boys 1 FΑ 7 10+ years 3 FΑ 2nd floor boys 6 2-5 vears No damage observed Lighting - Pendent/Surface Partitions 2nd floor boys 2 EA 7 10+ years 7 Urinals 2nd floor boys 4 EΑ 10+ years



Catego	ry : Room		В	uilding	: Main		
Ŭ				U		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd floor boys	505	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd floor boys	505	SF	7	10+ years	
	Water Closet	2nd floor boys	2	EA	7	10+ years	
	Accessories	2nd floor girl's	341	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor girl's	341	SF	7	10+ years	
	Doors - Transom Window	2nd floor girl's	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd floor girl's	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd floor girl's	341	SF	7	10+ years	
	Lavatory	2nd floor girl's	2	ĒA	7	10+ years	
	Lighting - Pendent/Surface	2nd floor girl's	6	EA	6	2-5 years	No damage observed
	Partitions	2nd floor girl's	8	EA	5	2-5 years	No damage observed
	Walls - Plaster/Drywall	2nd floor girl's	534	SF	7	10+ years	No damago obcorrod
	Walls - Structural Glazed Tile	2nd floor girl's	534	SF	7	10+ years	
	Water Closet	2nd floor girl's	8	EA	7	10+ years	
	Accessories	2nd floor teachers toilet	127	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor teachers toilet	127	SF	7	10+ years	
	Doors - Transom Window	2nd floor teachers toilet	4	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd floor teachers toilet	4	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor teachers toilet	127	SF	7	10+ years	
		2nd floor teachers toilet	2	EA	7	10+ years	
	Lavatory			EA	5		Missing cover
	Lighting - Pendent/Surface Partitions	2nd floor teachers toilet	2	EA	5 7	1-2 years	Missing cover
		2nd floor teachers toilet		SF		10+ years	No demons shoet ad
	Walls - Plaster/Drywall	2nd floor teachers toilet	585		5	6-10 years	No damage observed
	Water Closet	2nd floor teachers toilet	1	EA	7	10+ years	
	Accessories	3rd floor boys	317	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor boys	317	SF	7	10+ years	
	Doors - Transom Window	3rd floor boys	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd floor boys	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd floor boys	317	SF	7	10+ years	
	Floor Drain	3rd floor boys	1	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd floor boys	3	EA	6	2-5 years	No damage observed
	Lighting - Pendent/Surface	3rd floor boys	1	EA	5	0-1 year	Missing cover
	Partitions	3rd floor boys	2	EA	7	10+ years	
	Urinals	3rd floor boys	4	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd floor boys	505	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd floor boys	505	SF	7	10+ years	
	Water Closet	3rd floor boys	2	EA	7	10+ years	
	Accessories	3rd floor girls	325	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor girls	325	SF	7	10+ years	
	Doors - Transom Window	3rd floor girls	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd floor girls	2	EA	7	10+ years	
	Floor - Tile	3rd floor girls	325	SF	7	10+ years	
	Floor Drain	3rd floor girls	1	EA	7	10+ years	
	Lavatory	3rd floor girls	3	EA	7	10+ years	
	-	-					



Catego	ry : Room		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd floor girls	4	EA	6	2-5 years	No damage observed
	Partitions	3rd floor girls	8	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd floor girls	505	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd floor girls	505	SF	7	10+ years	
	Water Closet	3rd floor girls	8	EA	7	10+ years	
atego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #101 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	16	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,147	SF	7	10+ years	
	Chalk Board	1st Floor	16	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,147	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	22	EA	6	2-5 years	No damage observed
	Marker Board	1st Floor	8	LF	7	6-10 years	-
	Storage/ Closet	1st Floor	240	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,581	SF	7	10+ years	
Classroo	om #103 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	. 8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	722	SF	7	10+ years	
			•==		-		

44 LF

4

2-5 years

	Onalic Doard	13(1100)	77			20 yours	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	722	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	2-5 years	No damage observed
	Marker Board	1st Floor	24	LF	7	6-10 years	Ū.
	Walls - Plaster/Drywall	1st Floor	1,225	SF	7	10+ years	
Class	sroom #104 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	722	SF	6	10+ years	
	Chalk Board	1st Floor	22	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	722	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	2-5 years	No damage observed

1st Floor

Chalk Board



atego	ry : Classroom		В	uilding	· Main		650 S Wolcott AVENUE, Chicago, IL 606
Jalego				unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
noup	Marker Board	1st Floor	22	LF	7	6-10 years	Commente
	Walls - Plaster/Drywall	1st Floor	1,225	SF	6	10+ years	
			1,220	0.	U	ior youro	
lassroc	om #106 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	713	SF	7	10+ years	
	Chalk Board	1st Floor	16	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	713	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	2-5 years	No damage observed
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,225	SF	7	10+ years	
assroo	om #110 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	728	SF	7	10+ years	
	Chalk Board	1st Floor	22	LF	4	2-5 years	
	Doors - Transom Window	1st Floor		SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	ĒA	7	10+ years	
	Floor - Tile	1st Floor	728	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	ĒA	6	2-5 years	No damage observed
	Walls - Plaster/Drywall	1st Floor	1,225	SF	7	10+ years	
assroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	722	SF	7	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	722	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	6	2-5 years	No damage observed
	Marker Board	2nd Floor	22	LF	7	6-10 years	No damage observed
	Walls - Plaster/Drywall	2nd Floor	1,225	SF	7	10+ years	
		21011001	1,220	01	,	TOF years	
assroc	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall Chalk Board	2nd Floor 2nd Floor	722	SF LF	7	10+ years	
			42		4	2-5 years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	722	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	2-5 years	No damage observed
	Marker Board	2nd Floor	6	LF	7	6-10 years	C C
	Walls - Plaster/Drywall	2nd Floor	1,225	SF	7	10+ years	
Classroo	m #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	720	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	ËA	6	2-5 years	No damage observed
	Marker Board	2nd Floor	58	LF	7	6-10 years	the damage encorred
	Walls - Plaster/Drywall	2nd Floor	1,225	SF	7	10+ years	
lassroo	m #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	722	SF	7	10+ years	
	Chalk Board	2nd Floor	42	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	722	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	2-5 years	No damage observed
	Marker Board	2nd Floor	6	LF	7	6-10 years	No damago obcorrod
	Walls - Plaster/Drywall	2nd Floor	1,225	SF	7	10+ years	
Classroo	m #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	7	10+ years	
	Chalk Board	2nd Floor	48	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	-0	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	2-5 years	No damage observed
	Storage/ Closet	2nd Floor	40	SF			No damage observed
	Storage/ Closet Walls - Plaster/Drywall	2nd Floor 2nd Floor	40 1,225	SF	7 6	10+ years	
	Valis - Flastel/Diywali		1,220	35	0	10+ years	

Classroom #207 (Regular Classroom)



atego	ry : Classroom		В	uilding	: Main		
aloge				anang	. main	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	722	SF	7	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	722	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	2-5 years	No damage observed
	Marker Board	2nd Floor	32	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,225	SF	7	10+ years	
assroc	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	682	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	10	SF	5	1-2 years	Cracked
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	692	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	2-5 years	No damage observed
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,177	SF	7	10+ years	
assroc	om #209 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	674	SF	7	10+ years	
	Chalk Board	2nd Floor	32	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	4	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	674	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	2-5 years	No damage observed
	Walls - Plaster/Drywall	2nd Floor	1,125	SF	7	10+ years	
assroc	om #210 (Music Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	32	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	881	SF	7	10+ years	
	Chalk Board	2nd Floor	4	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
			004	SF	4	1.0	Disperdence t
	Floor - Carpet Lighting - Pendent/Surface	2nd Floor	881	SF	4	1-2 years	Ripped carpet



Catego	ry : Classroom		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,400	SF	7	10+ years	
assroo	m #211 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	23	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	766	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	4	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	766	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	2-5 years	No damage observed
	Marker Board	1st Floor	6	LF	7	6-10 years	C
	Walls - Plaster/Drywall	1st Floor	1,289	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
lassroo	m #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	713	SF	7	10+ years	
	Chalk Board	3rd Floor	45	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	2	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	
	Floor - Wood	3rd Floor	713	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	2-5 years	No damage observed
	Marker Board	3rd Floor	24	LF	7	6-10 years	No damago obcorred
	Walls - Plaster/Drywall	3rd Floor	1,205	SF	7	10+ years	
assroo	m #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	718	SF	7	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	718	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	2-5 years	No damage observed
	Marker Board	3rd Floor	9	LF	7	6-10 years	No damage observed
	Walls - Plaster/Drywall	3rd Floor	1,205	SF	7	10+ years	
lassroo	m #304 (Faculty Lounge)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
			1	LF	'	Jiuyoura	



Group	ry : Classroom			uilding			
Group						Recommend	
	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	3rd Floor	713	SF	7	10+ years	
	Chalk Board	3rd Floor	45	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	1-2 years	Missing handle
	Floor - Wood	3rd Floor	713	SF	7	10+ years	No damage observed
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	2-5 years	
	Marker Board	3rd Floor	13	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,211	SF	7	10+ years	
lassroo	m #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	705	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	5	1-2 years	Peeling drywall
	Chalk Board	3rd Floor	46	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒΑ	7	10+ years	
	Floor - Wood	3rd Floor	715	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒA	6	2-5 years	No damage observed
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,205	SF	7	10+ years	
lassroo	m #306 (Store Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	718	SF	7	10+ years	
	Chalk Board	3rd Floor	44	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	718	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	11	EA	6	2-5 years	No damage observed
	Lighting - Pendent/Surface	3rd Floor	3	EA	5	1-2 years	Missing cover
	Marker Board	3rd Floor	24	LF	7	6-10 years	incomy coror
	Walls - Plaster/Drywall	3rd Floor	1,205	SF	7	10+ years	
lassroo	m #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	716	SF	7	10+ years	
	Chalk Board	3rd Floor	47	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	-1/	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	



Catana				ي ما ام از ر	Mair		650 S Wolcott AVENUE, Chicago, IL 60620
Catego	ry : Classroom		В	uilding	: Main	_	
			•			Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	3rd Floor	716	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	2-5 years	No damage observed
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,205	SF	6	10+ years	
Classroc	om #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	705	SF	6	10+ years	cracks
	Chalk Board	3rd Floor	46	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒA	7	10+ years	
	Floor - Wood	3rd Floor	705	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	2-5 years	No damage observed
	Walls - Plaster/Drywall	3rd Floor	1,205	SF	6	10+ years	
	Walls Thaster/Drywall		1,200	01	0	for years	
Catego	ry : Interior		В	uilding	: Main		
-			<b>-</b>			Recommend	<b>.</b>
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	4,250	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	4	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	8	EA	7	10+ years	
	Floor - Terrazzo	1st Floor	4,250	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	38	EA	6	2-5 years	No damage observed
	Student Lockers - One Tier	1st Floor	170	EA	7	10+ years	-
	Walls - Plaster/Drywall	1st Floor	4,076	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	4,076	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	4,250	SF	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	8	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor	4,250	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	44	EA	6	2-5 years	No damage observed
	Student Lockers - One Tier	2nd Floor	156	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	4,076	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	4,076	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	2,651	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	5	1-2 years	Damaged
	Drinking Fountains - Single Fountain	3rd Floor	6	EA	7	10+ years	Lanagoa
	Floor - Terrazzo	3rd Floor	2,661	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	2,001	EA	6	2-5 years	No damage observed
	Lighting - Pendent/Surface	3rd Floor	21	EA	5	0-1 year	Missing cover
	Student Lockers - One Tier		91	EA	5 7	-	
	Walls - Plaster/Drywall	3rd Floor 3rd Floor	2,795	SF	7	10+ years 10+ years	



Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Structural Glazed Tile	3rd Floor	2,795	SF	7	10+ years	
Safety							
	Camera Viewing Station	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	1	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	North East	440	SF	7	10+ years	
	Floor - Terrazzo	North East	150	SF	7	10+ years	
	Handrails	North East	68	LF	7	10+ years	
	Lighting - Chandelier, Incandescent	North East	2	EA	7	10+ years	
	Stairs - Terrazzo	North East	34	LF	7	10+ years	
	Walls - Plaster/Drywall	North East	450	SF	7	10+ years	
	Walls - Plaster/Drywall	North East	10	SF	5	0-1 year	Damaged
	Ceiling - Plaster/Drywall	North West	440	SF	7	10+ years	5
	Floor - Terrazzo	North West	140	SF	7	10+ years	
	Handrails	North West	68	LF	7	10+ years	
	Lighting - Chandelier, Incandescent	North West	2	EA	7	6-10 years	
	Stairs - Terrazzo	North West	32	LF	7	10+ years	
	Walls - Plaster/Drywall	North West	460	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South West	440	SF	7	10+ years	
	Floor - Terrazzo	South West	140	SF	7	10+ years	
	Handrails	South West	68	LF	7	10+ years	
	Lighting - Chandelier, Incandescent	South West	2	EA	7	10+ years	
	Stairs - Terrazzo	South West	34	LF	7	10+ years	
	Walls - Plaster/Drywall	South West	560	SF	7	10+ years	
	····· , ···			-		- ,	



Category : Exterior			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Intrance							
	Exterior Doors - Exterior Steel Door	#4	3	EA	4	0-1 year	Not latching. Per engineer need replacement
	Exterior Stairs - Concrete	#4	6	LF	4	0-1 year	Cracking throughout and chipped pieces / trip hazard
	Exterior Doors - Exterior Steel Door	#5 - NW	3	EA	6	10+ years	
	Exterior Stairs - Concrete	#5 - NW	20	LF	6	10+ years	
	Stair Handrail - Steel Stair Handrail	#5 - NW	6	LF	4	0-1 year	Leaning rail
	Exterior Doors - Exterior Steel Door	#6 - E	3	EA	6	10+ years	5
	Exterior Doors - Side lite	#6 - E	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#6 - E	20	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#6 - E	12	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#6.5 - SE	1	EA	5	2-5 years	
	Exterior Doors - Exterior Steel Door	#0.5 - 3∟ 5.5	1	EA	6	6-10 years	Missed in prior assessment
	Exterior Stairs - Concrete	5.5	4	LF	5	2-5 years	Missed in prior assessment
	Exterior Doors - Exterior Steel Door	7.5	4	EA	5 6	,	
				EA	6	2-5 years	
	Exterior Doors - Exterior Steel Door	8.5	2		-	6-10 years	
	Exterior Doors - Side lite	8.5	2	EA	6	10+ years	
	Exterior Stairs - Concrete	8.5	5	LF	6	6-10 years	
	Stair Handrail - Steel_Stair Handrail	8.5	5	LF	6	6-10 years	
Foundati	on						
	Foundation - Concrete	Entire Building	653	LF	6	10+ years	
	Superstructure - Steel	Entire Building	28,700	SF	7	10+ years	
ighting							
Ignung	Exterior Lighting - Parapet or Roof Mounted	Entire Building	4	EA	7	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	4	EA	6	6-10 years	
		Entre Dananig		273	Ũ	e re yeare	
Roof Sys							
	Coping - Metal	Low W	297	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low W	52	LF	6	10+ years	
	Roof - Modified Bitumen	Low W	5,921	SF	6	2-5 years	
	Roof - Modified Bitumen	Low W	450	SF	5	0-1 year	Water stains at art room.
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Low W	6,371	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
	Coping - Metal	Main Roof	430	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	430 60	LF	6	10+ years	
	Roof - Modified Bitumen	Main Roof	10,087	SF	5	0-1 year	Per engineer, minor leaks
	Roof Hatch - Metal	Main Roof	10,007	EA	5 7	10+ years	
	Roof Structure - Steel / Metal Deck/	Main Roof	10,087	SF	7	10+ years 10+ years	



Catego	ry : Exterior		В	uilding	: Additi	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Concrete Topping						
Walls							
	Exterior Walls - Precast Panel Wall	Entire Building	14,356	SF	6	10+ years	
Windows	3						
	Guard - Guards perforated	Entire Building	903	SF	6	10+ years	
	Lintels - Steel	Entire Building	324	LF	6	10+ years	
	Windows - Louver	Entire Building	123	SF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	1,912	SF	7	10+ years	
Catego	ry : Electrical		В	uilding	: Additie	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	5	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	8	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	2	EA	6	6-10 years	Quantity adjusted to match current observations
	Security System - CCTV	Entire Building	28,700	SF	7	6-10 years	
	Security System - Intrusion Detection	Entire Building	28,700	SF	6	6-10 years	
Main Se	vice						
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	4	2-5 years	Not quite 50 years old (49) but corroded and deteriorated
	PA System	Entire Building	28,700	SF	6	6-10 years	Served by Main
	Independent Electrical Service for	Entire Building	20,700	EA	6	10+ years	
	emergency power	Entro Banang		<b>L</b> / (	Ū	ior youro	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	8	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	EM panel
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Panel is in good condition but is missing many breakers which exposes live conductors, and they a covered with a flammable piece of a cardboard box.
•			_				
-	ry : Fire Protection				: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments



7650 S Wolcott AVENUE, Chicago, IL 60620 Replacement Fire Alarm Fire Alarm Strobe Lights Entire Building 16.900 SF 6 2-5 years Fire Alarm System Entire Building 16,900 SF 6 6-10 years Served by Main **Category : Mechanical Building : Addition** Recommend Group Item - Type Location Quantity UOM Rank Replacement **Comments** Air Handling Systems Make Up Air Unit- Roof Mounted- Electric Roof 1 FΑ 5 Unit is operational but is deteriorated 2-5 years Coils - Less than 6000 cfm and vibrating. Priority Rep adjusted based on current observations. 2 ΕA Roof Top Unit-Single Zone-Roof Mounted-Roof 6 2-5 years Units are operational but approaching Electric Coil - 5 - 10 tons the end of expected service life. Priority Rep adjusted based on current observations. Heating Devices Wall Heater - Electric Entire Building 14 EΑ 6 6-10 years Wall Heater - Electric Entire Building ΕA 5 2-5 years 1 10+ years PTAC - Electric Heating and Self Contained Office 1 EΑ 6 Cooling Cabinet Heaters - With Electric Coil Office FΑ 6 1 10+ years Unit Ventilation Unit Ventilators- Floor Mounted- Electric ΕA 5 Entire Building 14 6-10 years Quantity adjusted as total has been Heating & DX Cooling Coil W/ Self divided/aggregated **Contained Compressor** Unit Ventilators- Floor Mounted- Electric Entire Building 4 ΕA 4 2-5 years Quantity adjusted as total has been Heating & DX Cooling Coil W/ Self divided/aggregated. Four units were Contained Compressor not operational at the time of assessment. Ventilation ΕA Exhaust Fans- Roof Mounted - 500 - 1500 Entire Building 4 6 6-10 years CFM FΑ Exhaust Fans- Roof Mounted - Less than Entire Building 1 3 0-1 year Unit has reached breakdown and is 500 CFM beyond reasonable repair. Type II Exhaust Hood- Warming Kitchen Entire Building 1 ΕA 4 0-1 year Requires a fire suppression system for this application **Category : Plumbing Building : Addition** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Hot Water



**Category : Plumbing Building : Addition** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Electric Heater - 20 - 50 KW Mechanical Room 2 FΑ 7 6-10 vears Piping SF 6 **Domestic Piping-Hot Water Return Lines** Entire Building 28.700 6-10 years Domestic Piping-Hot Water Return Risers 28,700 SF 6 6-10 years Entire Building Domestic Piping-Hot Water from Risers to SF 6 6-10 years Entire Building 28.700 Fixtures Domestic Piping-Hot/Cold Water Supply **Entire Building** 28.700 SF 6 6-10 years (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply Entire Building 28,700 SF 6 6-10 years (Risers) Domestic Piping-Hot/Cold Water Supply Entire Building 28,700 SF 6 6-10 years (from Risers to Fixtures) Sanitary Piping Entire Building 28.700 SF 6 6-10 vears Storm Piping SF 6 Entire Building 28.700 6-10 vears Vent Piping Entire Building 28.700 SF 6 6-10 years Category : Room **Building : Addition** Recommend Item - Type Location Quantity UOM Rank Replacement Comments Group Administrative Suites/Offices SF Ceiling - Lay-in 1st floor adjacent 114 301 7 10+ years Ceiling - Lay-in 1st floor adjacent 114 2 SF 4 0-1 year Water damage \\ falling ceiling tile Doors - Steel Doors incl hw 1st floor adjacent 114 2 EΑ 7 10+ years Floor - Tile 1st floor adjacent 114 SF 7 10+ vears 301 1st floor adjacent 114 ΕA Lighting - Lay-in 4 6 2-5 years Power Distribution 1st floor adjacent 114 6 ΕA 7 10+ vears SF Walls - Concrete Block 1st floor adjacent 114 140 7 10+ years SF 7 Walls - Plaster/Drywall 1st floor adjacent 114 480 10+ years SF Walls - Plaster/Drywall 1st floor adjacent 114 2 5 0-1 year Water damage SF 7 Ceiling - Lay-in 1st floor kitchen break 93 10+ years Ceiling - Lay-in 1st floor kitchen break 10 SF 4 0-1 year Water damage Doors - Steel Doors incl hw 1st floor kitchen break EΑ 7 10+ years 1 Floor - Tile/Sheet 1st floor kitchen break 103 SF 7 10+ years Lighting - Lay-in FΑ 6 2-5 vears 1st floor kitchen break 1 Power Distribution 1st floor kitchen break 2 ΕA 7 10+ vears SF Walls - Concrete Block 1st floor kitchen break 348 7 10+ years Walls - Concrete Block 20 SF 0-1 year 1st floor kitchen break 4 Cracked SF 7 Ceiling - Lay-in 1st floor kitchen office 78 10+ years Ceiling - Lay-in 2 SF 1st floor kitchen office 4 0-1 year Damaged SF Doors - Side-lite 1st floor kitchen office 36 7 10+ years Doors - Steel Doors incl hw 1st floor kitchen office 1 ΕA 7 10+ years SF Floor - Tile 1st floor kitchen office 80 7 10+ years Lighting - Lay-in 1st floor kitchen office EΑ 4 2-5 years 1



Catego	ry : Room		В	uilding	: Additi		
calege			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Power Distribution	1st floor kitchen office	4	EA	7	10+ years	
	Walls - Concrete Block	1st floor kitchen office	320	SF	7	10+ years	
	Ceiling - Lay-in	1st floor northeast copy room	538	SF	5	2-5 years	
	Ceiling - Lay-in	1st floor northeast copy room	14	SF	4	0-1 year	Water damage
	Doors - Side-lite	1st floor northeast copy room	72	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st floor northeast copy room	1	EA	7	10+ years	
	Floor - Tile	1st floor northeast copy room	542	SF	7	10+ years	
	Lighting - Lay-in	1st floor northeast copy room	10	EA	6	2-5 years	
	Power Distribution	1st floor northeast copy room	8	EA	7	10+ years	
	Walls - Plaster/Drywall	1st floor northeast copy room	904	SF	7	10+ years	
	Ceiling - Lay-in	1st floor northwest asst. principal	384	SF	7	10+ years	
		office					
	Ceiling - Lay-in	1st floor northwest asst. principal	4	SF	4	0-1 year	Damaged
		office					
	Doors - Steel Doors incl hw	1st floor northwest asst. principal	1	EA	7	10+ years	
		office					
	Floor - Tile	1st floor northwest asst. principal	388	SF	7	6-10 years	
		office					
	Lighting - Lay-in	1st floor northwest asst. principal	4	EA	7	6-10 years	
		office					
	Power Distribution	1st floor northwest asst. principal	6	EA	7	10+ years	
		office					
	Storage/ Closet	1st floor northwest asst. principal	58	SF	7	10+ years	
		office					
	Walls - Concrete Block	1st floor northwest asst. principal	660	SF	7	10+ years	
		office					
	Walls - Concrete Block	1st floor northwest asst. principal	4	SF	5	0-1 year	
		office					
	Walls - Plaster/Drywall	1st floor northwest asst. principal	220	SF	7	10+ years	
		office					
	AC Unit	1st floor northwest business	1	EA	7	6-10 years	
		managers office					
	Ceiling - Lay-in	1st floor northwest business	136	SF	7	10+ years	
		managers office					
	Ceiling - Lay-in	1st floor northwest business	4	SF	4	0-1 year	Water damage
		managers office					
	Doors - Steel Doors incl hw	1st floor northwest business	1	EA	7	10+ years	
		managers office					
	Floor - Carpet	1st floor northwest business	140	SF	7	6-10 years	
		managers office					
	Lighting - Lay-in	1st floor northwest business	2	EA	4	2-5 years	Broken light fixtur
		managers office					
	Power Distribution	1st floor northwest business	4	EA	7	10+ years	
		managers office					



Catego	ategory : Room			Building : Addition						
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Walls - Concrete Block	1st floor northwest business managers office	424	SF	7	10+ years				
Kitchen										
	Ceiling - Lay-in	1st Floor	1,282	SF	6	10+ years				
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years				
	Floor - Tile Quarry	1st Floor	1,282	SF	7	10+ years				
	Lighting - Lay-in	1st Floor	15	EA	6	2-5 years				
	Serving Line	1st Floor	23	LF	7	10+ years				
	Storage/ Closet	1st Floor	122	SF	5	10+ years				
	Storage/ Closet	1st Floor	175	SF	5	10+ years				
	Walls - Concrete Block	1st Floor	30	SF	7	10+ years				
	Walls - Concrete Block	1st Floor	1,412	SF	7	10+ years				
			.,			, every every				
unch &	Multipurpose Room		0.005			40				
	Ceiling - Lay-in	1st Floor	2,965	SF	7	10+ years				
	Ceiling - Lay-in	1st Floor	192	SF	5	0-1 year	Water damage			
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years				
	Floor - Tile	1st Floor	3,110	SF	7	10+ years				
	Floor - Tile	1st Floor	47	SF	4	0-1 year	Damaged tile			
	Lighting - Pendent/Surface	1st Floor	32	EA	6	2-5 years				
	Serving Line	1st Floor	23	LF	7	10+ years				
	Storage/ Closet	1st Floor	54	SF	5	10+ years				
	Walls - Concrete Block	1st Floor	3,158	SF	7	10+ years				
MDF_ID	F									
_	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years				
	Finishes	2nd Floor	390	SF	7	10+ years				
	Finishes	2nd Floor	10	SF	5	0-1 year				
	Other Cooling Unit	2nd Floor	1	EA	7	6-10 years				
Vechani	cal/ Service Rooms									
	Mechanical/ Service Rooms	1st Floor	78	SF	5	10+ years				
	Storage Room	1st Floor	120	SF	5	10+ years				
	Storage Room	1st Floor	132	SF	5	10+ years				
	Vaults	1st Floor	120	SF	7	10+ years				
	Janitor's Closet	2nd Floor	50	SF	5	10+ years				
			50	0	5	ior years				
Restroor										
	Accessories	1st floor boys	298	SF	7	6-10 years				
	Ceiling - Lay-in	1st floor boys	296	SF	7	10+ years				
	Ceiling - Lay-in	1st floor boys	2	SF	4	0-1 year	Water damage			
	Floor - Tile Ceramic/ Porcelain	1st floor boys	298	SF	7	10+ years				



Catego	ry : Room		В	uildina	: Additi		too o wolcon Avenue, onleago, ie ooozo
0	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	1st floor boys	1	EA	7	10+ years	
	Lavatory	1st floor boys	2	EA	7	10+ years	
	Lighting - Lay-in	1st floor boys	5	EA	7	6-10 years	
	Partitions	1st floor boys	2	EA	7	10+ years	
	Urinals	1st floor boys	3	EA	7	10+ years	
	Walls - Concrete Block	1st floor boys	252	SF	7	10+ years	
	Water Closet	1st floor boys	2	EA	7	10+ years	
	Accessories	1st floor girls	316	SF	7	6-10 years	
	Ceiling - Lay-in	1st floor girls	301	SF	7	10+ years	
	Ceiling - Lay-in	1st floor girls	15	SF	4	0-1 year	Water stain
	Floor - Tile	1st floor girls	316	SF	7	10+ years	
	Floor Drain	1st floor girls	1	EA	7	10+ years	
	Lavatory	1st floor girls	2	EA	7	10+ years	
	Lighting - Lay-in	1st floor girls	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st floor girls	4	EA	7	6-10 years	
	Partitions	1st floor girls	5	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st floor girls	345	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st floor girls	345	SF	7	10+ years	
	Water Closet	1st floor girls	5	EA	7	10+ years	
	Accessories	1st floor kitchen staff restroom	40	SF	7	6-10 years	
	Ceiling - Lay-in	1st floor kitchen staff restroom	34	SF	7	10+ years	
	Ceiling - Lay-in	1st floor kitchen staff restroom	6	SF	4	0-1 year	Damaged
	Doors - Steel Doors incl hw	1st floor kitchen staff restroom	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor kitchen staff restroom	40	SF	7	10+ years	
	Lavatory	1st floor kitchen staff restroom	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st floor kitchen staff restroom	1	EA	6	2-5 years	
	Walls - Concrete Block	1st floor kitchen staff restroom	252	SF	7	10+ years	
	Water Closet	1st floor kitchen staff restroom	1	EA	7	10+ years	
	Accessories	1st floor room 113	35	SF	7	6-10 years	
	Ceiling - Lay-in	1st floor room 113	35	SF	5	2-5 years	
	Doors - Steel Doors incl hw	1st floor room 113	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor room 113	35	SF	7	10+ years	
	Lavatory	1st floor room 113	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st floor room 113	1	EA	7	6-10 years	
	Walls - Concrete Block	1st floor room 113	214	SF	7	10+ years	
	Water Closet	1st floor room 113	1	EA	7	10+ years	
	Accessories	1st floor room 115	35	SF	7	6-10 years	
	Ceiling - Lay-in	1st floor room 115	35	SF	5	2-5 vears	
	Doors - Steel Doors incl hw	1st floor room 115	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor room 115	35	SF	7	10+ years	
	Lavatory	1st floor room 115	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st floor room 115	1	EA	7	2-5 years	
	Walls - Concrete Block	1st floor room 115	214	SF	7	10+ years	
	Water Closet	1st floor room 115	1	EA	7	10+ years	
		-				<b>,</b>	



Catego	ry : Room		В	uildina	: Additi		650 S WORCON AVENUE, Chicago, il 60620
outogo				anang	. / toultr	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	2nd floor boys	684	SF	7	6-10 years	
	Ceiling - Lay-in	2nd floor boys	298	SF	7	6-10 years	
	Doors - Steel Doors incl hw	2nd floor boys	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor boys	298	SF	7	10+ years	
	Floor Drain	2nd floor boys	1	EA	7	10+ years	
	Lavatory	2nd floor boys	2	EA	7	10+ years	
	Lighting - Lay-in	2nd floor boys	2	EA	7	2-5 years	
	Partitions	2nd floor boys	2	EA	7	10+ years	
	Urinals	2nd floor boys	3	EA	7	10+ years	
	Walls - Concrete Block	2nd floor boys	100	SF	7	10+ years	
	Walls - Concrete Block	2nd floor boys	152	SF	7	10+ years	
	Water Closet	2nd floor boys	1	EA	7	10+ years	
	Water Closet	2nd floor boys	1	EA	3	0-1 year	Missing fixture
	Accessories	2nd floor girls	316	SF	7	6-10 years	
	Ceiling - Lay-in	2nd floor girls	316	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd floor girls	2	EA	7	10+ years	
	Floor - Tile	2nd floor girls	316	SF	7	10+ years	
	Floor Drain	2nd floor girls	1	EA	7	10+ years	
	Lavatory	2nd floor girls	2	EA	7	10+ years	
	Lighting - Lay-in	2nd floor girls	2	EA	7	2-5 years	
	Partitions	2nd floor girls	5	EA	7	6-10 years	
	Walls - Concrete Block	2nd floor girls	690	SF	7	10+ years	
	Water Closet	2nd floor girls	5	EA	7	10+ years	
	Accessories	2nd floor staff restroom	50	SF	7	6-10 years	
	Ceiling - Lay-in	2nd floor staff restroom	50	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd floor staff restroom	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor staff restroom	50	SF	7	10+ years	
	Lavatory	2nd floor staff restroom	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd floor staff restroom	1	EA	7	2-5 years	
	Walls - Concrete Block	2nd floor staff restroom	252	SF	7	10+ years	
	Water Closet	2nd floor staff restroom	1	EA	7	10+ years	
	Accessories	Teacher's Lounge A	32	SF	7	6-10 years	
	Ceiling - Lay-in	Teacher's Lounge A	24	SF	7	10+ years	
	Ceiling - Lay-in	Teacher's Lounge A	8	SF	7	10+ years	
	Doors - Steel Doors incl hw	Teacher's Lounge A	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Teacher's Lounge A	32	SF	7	10+ years	
	Lavatory	Teacher's Lounge A	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Teacher's Lounge A	1	EA	7	6-10 years	
	Walls - Concrete Block	Teacher's Lounge A	210	SF	7	10+ years	
	Water Closet	Teacher's Lounge A	1	EA	7	10+ years	
	Accessories	Teacher's Lounge B	32	SF	7	6-10 years	
	Ceiling - Lay-in	Teacher's Lounge B	32	SF	7	10+ years	
	Doors - Steel Doors incl hw	Teacher's Lounge B	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Teacher's Lounge B	32	SF	7	10+ years	



Catego	ry : Room		В						
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lavatory	Teacher's Lounge B	1	EA	7	10+ years			
	Lighting - Pendent/Surface	Teacher's Lounge B	1	EA	7	6-10 years			
	Walls - Concrete Block	Teacher's Lounge B	210	SF	7	10+ years			
	Water Closet	Teacher's Lounge B	1	EA	7	10+ years			

### Category : Classroom

Catego	Category : Classroom			uilding						
Group	Item - Type	Location	Recommend Location Quantity UOM Rank Replacement Comm							
	om #113 (Kindergarten)	Eocation	Quantity		Nain	Replacement	Comments			
	Casework	1st Floor	18	LF	7	10+ years				
	Ceiling - Lay-in	1st Floor	1,111	SF	7	10+ years				
	Chalk Board	1st Floor	8	LF	4	2-5 years				
	Doors - Steel Doors incl hw	1st Floor	0	EA	7	10+ years				
	Floor - Tile	1st Floor	1,111	SF	7	10+ years				
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years				
	Storage/ Closet	1st Floor	50	SF	7	10+ years				
	Walls - Concrete Block	1st Floor	254	SF	7	10+ years				
	Walls - Metal Panel	1st Floor	831	SF	7	10+ years				
	Work Sink	1st Floor	1	EA	7	10+ years				
		13(1100)	I	L/	'	Tor years				
Classroo	om #114 (Office)									
	Casework	1st Floor	10	LF	7	10+ years				
	Ceiling - Lay-in	1st Floor	589	SF	5	2-5 years				
	Ceiling - Lay-in	1st Floor	6	SF	4	0-1 year	Water damage			
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years				
	Floor - Tile	1st Floor	603	SF	7	10+ years				
	Floor - Tile	1st Floor	2	SF	4	1-2 years	Damaged tile			
	Lighting - Lay-in	1st Floor	10	EA	6	2-5 years				
	Walls - Metal Panel	1st Floor	730	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor	174	SF	7	10+ years				
Classro	om #115 (Kindergarten)									
	Casework	1st Floor	18	LF	7	10+ years				
	Ceiling - Lay-in	1st Floor	1,104	SF	7	10+ years				
	Chalk Board	1st Floor	8	LF	4	2-5 years				
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years				
	Floor - Tile	1st Floor	1,104	SF	7	10+ years				
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years				
	Storage/ Closet	1st Floor	50	SF	7	10+ years				
	Walls - Concrete Block	1st Floor	254	SF	7	10+ years				
	Walls - Metal Panel	1st Floor	831	SF	7	10+ years				
	Work Sink	1st Floor	1	EA	7	10+ years				
			•			,				



Catego	ry : Classroom		В	uilding	: Additi	on	
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #116 (Regular Classroom)						
	Casework	1st Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	727	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	4	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	731	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	2-5 years	
	Walls - Metal Panel	1st Floor	556	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	314	SF	7	10+ years	
Classroo	m #117 (Regular Classroom)						
	Casework	1st Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	745	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	4	SF	4	0-1 year	Water damage
	Chalk Board	1st Floor	8	LF	4	2-5 years	C
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	749	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	9	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	6	2-5 years	
	Storage/ Closet	1st Floor	80	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	254	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	616	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	m #118 (Regular Classroom)						
	Casework	1st Floor	12	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	726	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	2	SF	4	0-1 year	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	728	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	6	2-5 years	
	Walls - Concrete Block	1st Floor	314	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	278	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	556	SF	7	10+ years	
Classroo	m #120 (Regular Classroom)						
	Casework	1st Floor	12	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	696	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	6	SF	4	0-1 year	Water damage
	Chalk Board	1st Floor	6	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	702	SF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Additi	on	
5				5		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Lighting - Lay-in	1st Floor	10	EA	6	2-5 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	280	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	560	SF	7	10+ years	
Classroo	om #212 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	502	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	5	1-2 years	Water stain
	Chalk Board	2nd Floor	32	LF	4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	502	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	8	EA	6	2-5 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	150	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	398	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	400	SF	6	10+ years	
Classroo	om #213 (Faculty Lounge)						
	Casework	2nd Floor	12	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	729	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	729	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	6	2-5 years	
	Walls - Concrete Block	2nd Floor	314	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	278	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	278	SF	7	10+ years	
Classroo	om #214 (Regular Classroom)						
	Casework	2nd Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	615	SF	5	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	615	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	6	2-5 years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	739	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	177	SF	6	10+ years	
Classroo	om #215 (Regular Classroom)						
	Casework	2nd Floor	12	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	736	SF	5	2-5 years	
	Ceiling - Lay-in	2nd Floor	4	SF	4	0-1 year	Water damage
	Chalk Board	2nd Floor	10	LF	4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	



Catego	ry : Classroom		В	uilding	: Additio		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	741	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	6	2-5 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	600	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2	SF	5	0-1 year	Water damage
Classroo	m #216 (Regular Classroom)						
	Casework	2nd Floor	12	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	727	SF	7	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	727	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	6	2-5 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
		2nd Floor	870	SF	7		
	Walls - Metal Panel	2110 F1001	870	эг	/	10+ years	
Classroo	m #217 (Store Room)						
	Ceiling - Lay-in	2nd Floor	737	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	3	SF	4	0-1 year	Water stain
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	740	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	10	EA	6	2-5 years	
	Walls - Metal Panel	2nd Floor	845	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	35	SF	5	0-1 year	Water damage
Classroo	m #218 (Regular Classroom)						
	Casework	2nd Floor	12	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	722	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	2	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	2nd Floor	_ 1	EA	7	10+ years	
	Floor - Tile	2nd Floor	724	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	6	2-5 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	870	SF	7	10+ years	
Classroo	m #219 (Regular Classroom)						
	Casework	2nd Floor	12	LF	7	10+ years	
	Casework Ceiling - Lay-in	2nd Floor	749	SF	5	•	
	Doors - Steel Doors incl hw					2-5 years	
		2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	749	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	6	2-5 years	
	Marker Board	2nd Floor 2nd Floor	20	LF SF	7	6-10 years	
	Walls - Concrete Block		256		7	10+ years	



**Category : Classroom Building : Addition** Recommend Item - Type Location Quantity Group UOM Rank **Replacement** Comments Walls - Metal Panel SF 2nd Floor 634 7 10+ years Classroom #220 (Store Room) 2nd Floor Casework 12 LF 7 10+ years Ceiling - Lay-in 2nd Floor 737 SF 5 2-5 years Doors - Steel Doors incl hw 2nd Floor ΕA 7 1 10+ years Floor - Tile 2nd Floor 737 SF 7 10+ years Lighting - Lay-in 2nd Floor 10 ΕA 6 2-5 years LF 7 Marker Board 2nd Floor 20 6-10 years SF Walls - Metal Panel 2nd Floor 880 6 10+ years Classroom #222 (Regular Classroom) 2nd Floor LF Casework 12 7 10+ years SF Ceiling - Lay-in 2nd Floor 700 7 6-10 years Ceiling - Lay-in 2nd Floor 2 SF 0-1 year Damaged tile 4 Doors - Steel Doors incl hw 2nd Floor 1 ΕA 7 10+ years Floor - Tile 2nd Floor 702 SF 7 10+ years Lighting - Lay-in 2nd Floor 10 ΕA 6 2-5 years Marker Board 2nd Floor 8 LF 7 6-10 years SF Walls - Metal Panel 2nd Floor 820 6 10+ years

### **Category : Interior**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	3,485	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	192	SF	4	0-1 year	Water stain
	Doors - Steel Doors incl hw	1st Floor	8	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	6	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	1,174	SF	7	2-5 years	
	Floor - Tile/Sheet	1st Floor	3,671	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	27	EA	6	2-5 years	
	Stairs - Concrete Stairs	1st Floor	5	LF	7	10+ years	
	Walls - Concrete Block	1st Floor	3,490	SF	7	10+ years	
	Walls - Masonry	1st Floor	96	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,039	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,872	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	92	SF	4	0-1 year	Damaged tile
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	9	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,964	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	11	EA	7	2-5 years	
	Walls - Concrete Block	2nd Floor	1,097	SF	7	10+ years	

**Building : Addition** 



Catego	ry : Interior		Building : Addition							
	Recommend									
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Walls - Plaster/Drywall	2nd Floor	3,047	SF	7	10+ years				
Safety										
	Security Cameras	Entire Building	3	EA	7	6-10 years				
Stairs										
	Ceiling - Lay-in	Door 5	200	SF	7	10+ years				
	Floor - Terrazzo	Door 5	58	SF	7	10+ years				
	Floor - Tile	Door 5	278	SF	7	10+ years				
	Handrails	Door 5	50	LF	7	10+ years				
	Lighting - Lay-in	Door 5	1	EA	7	2-5 years				
	Stairs - Terrazzo	Door 5	19	LF	7	10+ years				
	Walls - Plaster/Drywall	Door 5	906	SF	7	10+ years				
	Ceiling - Lay-in	Door 6	180	SF	5	2-5 years				
	Ceiling - Lay-in	Door 6	20	SF	4	0-1 year	Water damage			
	Floor - Terrazzo	Door 6	58	SF	7	10+ years	-			
	Floor - Tile	Door 6	278	SF	7	10+ years				
	Handrails	Door 6	50	LF	7	10+ years				
	Lighting - Lay-in	Door 6	1	EA	6	2-5 years				
	Stairs - Terrazzo	Door 6	19	LF	7	10+ years				
	Walls - Concrete Block	Door 6	806	SF	7	10+ years				
	Walls - Concrete Block	Door 6	100	SF	6	10+ years	Pealing paint on CMU			



Catego	ry : Site		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Surface - Asphalt	East	6,527	SF	4	0-1 year	Cracking and vegetation growth.
Civil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	2	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	3	EA	5	0-1 year	One completely covered in vegetation growth and two sinking.
Fencing							
- 3-	Fencing - Chain Link	Entire Site	45	LF	6	10+ years	
	Fencing - Chain Link	Entire Site	45	LF	6	10+ years	
	Fencing - Chain Link	Entire Site	94	LF	6	10+ years	
	Fencing - Guard Rail	Entire Site	20	LF	6	10+ years	Missed in prior assessment
	Fencing - New Standard Ornamental	Entire Site	2,055	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	4	LF	4	0-1 year	Bent at lower portion of fence.
Landsca	De						
	Benches	Entire Site	7	EA	6	10+ years	In paver area next to planting beds, seats.
	Landscape - Grass	Entire Site	15,054	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	4,608	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	200	SF	4	0-1 year	By door 7, cracking throughout
	Landscape - Hardscape- Pavers	Entire Site	949	SF	6	10+ years	
	Parkway trees	Entire Site	36	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	190	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	385	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	53,575	SF	4	0-1 year	Cracking and vegetation growth.
	Trash Receptacles	Entire Site	4	EA	6	10+ years	
Parking I							
	Surface - Asphalt	Parking Lot- West	24,085	SF	5	2-5 years	
	Surface - Asphalt	Parking Lot- West	1,000	SF	4	0-1 year	Significant alligator cracking
	Surface - Concrete	Parking Lot- West	1,309	SF	6	2-5 years	
	Vehicular Screening	Parking Lot- West	160	LF	6	10+ years	
Playgrou							
	Equipment - Combo 3-12	Courtyard	1	EA	7	10+ years	
	Surface - Square Rubber Mats	Courtyard	2,840	SF	7	10+ years	
Sidewalk	6						



**Category : Site Building : Site** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Entire Site LF Sidewalks - Internal Walks 200 6 10+ years Sidewalks - Internal Walks Entire Site LF 4 0-1 year 40 Severe cracking Sidewalks - Perimeter Sidewalks Entire Site 14.788 SF 7 10+ years Signage Flag Pole - Flag Pole Entire Site 1 FΑ 7 10+ years Marguee - Free Standing Back lighted w/ Entire Site ΕA 6 10+ years 1 LED Monument - Building Mounted Cut Letter Entire Site ΕA 6 Missed in prior assessment 1 10+ years Sign

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

#### Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



### Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main					(- )				
Faculty Lounge	Regular Classroom	3rd Floor	304	304	713	195	20	Y	Y
Kindergarten	Kindergarten	1st Floor	101	101	1,147	240	64	Y	Y
Kindergarten	Kindergarten	1st Floor	110	110	728	150	40	Y	Y
Music Room	Music Room	2nd Floor	210	210	881	180	48	Y	N
Office	Regular Classroom	1st Floor	104	104	722	150	40	Y	Y
Regular Classroom	Computer Lab	1st Floor	106	106	713	100	27	Y	Y
Regular Classroom	Regular Classroom	1st Floor	103	103	722	150	40	Y	Y
Regular Classroom	Regular Classroom	1st Floor	211	211	766	150	40	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	201	201	722	150	40	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	203	203	722	150	40	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	204	204	720	150	40	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	205	205	722	150	40	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	206	206	720	150	40	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	207	207	722	150	40	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	208	208	692	150	40	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	209	209	674	150	40	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	301	301	713	195	20	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	303	303	718	195	20	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	305	305	715	195	20	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	307	307	716	195	20	Y	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	705	195	20	Y	N
Store Room	Regular Classroom	3rd Floor	306	306	718	195	20	Y	N
Building : Addition Faculty Lounge	Regular Classroom	2nd Floor	213	205	729	56	50	N	N
Kindergarten	Kindergarten	1st Floor	113	110	1,111	65	60	N	N Y
		1st Floor	113	10	1,111	56	50	N N	Y Y
Kindergarten Office	Kindergarten Regular Classroom	1st Floor	115	105	605	56	50	N N	ř N
Regular Classroom	Regular Classroom Regular Classroom	1st Floor	114	116	731	56	50	N N	N Y
Regular Classroom	Regular Classroom	1st Floor	117	104	749	56	50	N	r N
Regular Classroom		1st Floor	117	115	749	56	50	N	N Y
Regular Classroom	Regular Classroom Regular Classroom	1st Floor	120	115	728	56	50	N	r N
		2nd Floor	212	216	502	45			N N
Regular Classroom	Regular Classroom	2nd Floor 2nd Floor			615	45 56	40 50	N N	
Regular Classroom	Regular Classroom		214	215					N Y
Regular Classroom	Regular Classroom	2nd Floor	215	204	741	56	50	N	Y Y
Regular Classroom	Regular Classroom	2nd Floor	216	214	727	56	50	N	
Regular Classroom	Regular Classroom	2nd Floor	218	213	724	56	50	N	Y
Regular Classroom	Regular Classroom	2nd Floor	219	202	749	56	50	N	Y



### **Classroom Summary**

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Regular Classroom	2nd Floor	222	211	702	56	50	N	Y
Store Room	Regular Classroom	2nd Floor	217	203	740	56	50	N	N
Store Room	Regular Classroom	2nd Floor	220	212	737	56	50	N	N