

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

| Campus Summary | | | |
|----------------|------------------|------------------|-----------------------|
| BuildingName | Year Constructed | Number of Floors | Building Area (Sq Ft) |
| Main | 1899 | 3 | 61,160 |
| Addition | 1913 | 2 | 8,320 |
| Campus Total | | | 69,480 |

| Catego | Category : Exterior | | | Building : Main | | | |
|----------|---------------------------------------|------------------------|----------|-----------------|------|-------------|-----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Entrance | 9 | | | | | | |
| | Entrance Control - Audio and Video | Door 1 - North | 1 | EA | 7 | 6-10 years | |
| | Exterior Doors - Store Front | Door 1 - North | 2 | EA | 6 | 10+ years | |
| | Exterior Stairs - Concrete | Door 1 - North | 24 | LF | 7 | 10+ years | |
| | Ramp Handrail - Steel_Ramp Handrail | Door 1 - North | 66 | LF | 7 | 10+ years | |
| | Ramps - Concrete | Door 1 - North | 35 | LF | 7 | 10+ years | |
| | Stair Handrail - Steel_Stair Handrail | Door 1 - North | 20 | LF | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Door 1.5 - Northwest | 1 | EA | 6 | 10+ years | |
| | Exterior Stairs - Stone | Door 1.5 - Northwest | 3 | LF | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Door 10- Northeast | 1 | EA | 6 | 10+ years | |
| | Entrance Control - Audio and Video | Door 2 - Northwest | 1 | EA | 7 | 6-10 years | |
| | Exterior Doors - Store Front | Door 2 - Northwest | 3 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | Door 2 - Northwest | 3 | EA | 7 | 10+ years | |
| | Exterior Stairs - Concrete | Door 2 - Northwest | 21 | LF | 5 | 0-1 year | Cracking. |
| | Exterior Doors - Exterior Steel Door | Door 2.5 - West center | 1 | EA | 6 | 10+ years | |
| | Exterior Stairs - Stone | Door 2.5 - West center | 3 | LF | 7 | 10+ years | |
| | Entrance Control - Audio and Video | Door 3 - Southwest | 1 | EA | 7 | 10+ years | |
| | Exterior Doors - Store Front | Door 3 - Southwest | 3 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | Door 3 - Southwest | 3 | EA | 7 | 10+ years | |
| | Exterior Stairs - Concrete | Door 3 - Southwest | 21 | LF | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Door 7 - Southeast | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Door 8- South boiler | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Door 9- East boiler | 1 | EA | 6 | 10+ years | |



| | y : Exterior | | D | uilding | : Main | | |
|------------|---|-----------------|----------|---------|--------|-------------|----------|
| • | | | • | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Foundatio | | | | | | | |
| | Foundation - Masonry | Entire Building | 675 | LF | 7 | 10+ years | |
| | Superstructure - Heavy Timber | Entire Building | 61,160 | SF | 7 | 10+ years | |
| Link the e | | | | | | | |
| Lighting | Exterior Lighting - Parapet or Roof Mounted | Entire Building | 4 | EA | 7 | 6-10 years | |
| | Extend Eighting Tatapet of Roof Modified | Entrie Ballanig | 7 | L/ | , | o roycars | |
| Roof Sys | tem | | | | | | |
| | Access Ladder - Metal | Roof 1 | 2 | EA | 7 | 10+ years | |
| | Coping - Clay Tile | Roof 1 | 304 | LF | 6 | 10+ years | |
| | Coping - Stone | Roof 1 | 276 | LF | 6 | 10+ years | |
| | Downspouts - Exterior Downspouts | Roof 1 | 240 | LF | 6 | 10+ years | |
| | Parapet - Parapet > 30" | Roof 1 | 580 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | Roof 1 | 10,985 | SF | 6 | 10+ years | |
| | Roof Hatch - Metal | Roof 1 | 2 | EA | 7 | 10+ years | |
| | Roof Structure - Heavy Timber | Roof 1 | 10,985 | SF | 7 | 10+ years | |
| | Chimney - Brick Chimney- Concrete/ Mortar | Roof 2 | 91 | LF | 6 | 10+ years | |
| | Liner | | 31 | LI | 0 | 10+ years | |
| | Coping - Clay Tile | Roof 2 | 131 | LF | 6 | 10+ years | |
| | Downspouts - Exterior Downspouts | Roof 2 | 50 | LF | 6 | 10+ years | |
| | Parapet - Parapet < 16" Height | Roof 2 | 131 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | Roof 2 | 1,867 | SF | 6 | 10+ years | |
| | Roof Structure - Heavy Timber | Roof 2 | 1,867 | SF | 7 | 10+ years | |
| | Access Ladder - Metal | Roof 3 | 1,001 | EA | 7 | 10+ years | |
| | Coping - Clay Tile | Roof 3 | 32 | LF | 6 | 10+ years | |
| | Downspouts - Exterior Downspouts | Roof 3 | 12 | LF | 6 | 10+ years | |
| | | Roof 3 | 32 | LF | | | |
| | Parapet - Parapet < 16" Height | | | | 6 | 10+ years | |
| | Roof - Modified Bitumen | Roof 3 | 470 | SF | 6 | 10+ years | |
| | Roof Structure - Heavy Timber | Roof 3 | 470 | SF | 7 | 10+ years | |
| | Downspouts - Exterior Downspouts | Roof 4 | 30 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | Roof 4 | 50 | SF | 5 | 2-5 years | |
| | Roof Structure - Heavy Timber | Roof 4 | 50 | SF | 7 | 10+ years | |
| | Access Ladder - Metal | Roof 5 | 1 | EA | 7 | 10+ years | |
| | Coping - Clay Tile | Roof 5 | 28 | LF | 6 | 10+ years | |
| | Downspouts - Exterior Downspouts | Roof 5 | 20 | LF | 6 | 10+ years | |
| | Parapet - Parapet < 16" Height | Roof 5 | 28 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | Roof 5 | 540 | SF | 6 | 10+ years | |
| | Roof Structure - Heavy Timber | Roof 5 | 540 | SF | 7 | 10+ years | |
| | Downspouts - Exterior Downspouts | Roof 6 | 30 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | Roof 6 | 50 | SF | 5 | 2-5 years | |
| | Roof Structure - Heavy Timber | Roof 6 | 50 | SF | 7 | 10+ years | |
| | Coping - Stone | Roof 7 | 60 | LF | 6 | 10+ years | |
| | Downspouts - Exterior Downspouts | Roof 7 | 36 | LF | 6 | 10+ years | |



| Catego | ry : Exterior | | В | uilding | : Main | | |
|---------|---|-----------------|----------|---------|--------|--------------------------|-----------------------------------|
| Ţ | | | | 5 | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Parapet - 16" - 30" Height | Roof 7 | 60 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | Roof 7 | 120 | SF | 6 | 10+ years | |
| | Roof Structure - Heavy Timber | Roof 7 | 120 | SF | 7 | 10+ years | |
| | ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, | | | | | -) | |
| Valls | | | | | | | |
| | Exterior Walls - Brick | Entire Building | 30,734 | SF | 7 | 10+ years | |
| | Exterior Walls - Stone-Cast | Entire Building | 1,550 | SF | 7 | 10+ years | |
| | Exterior Walls - Stone-Cut | Entire Building | 252 | SF | 7 | 10+ years | |
| Vindows | | | | | | | |
| vindow, | Guard - Guards perforated | Entire Building | 1,262 | SF | 7 | 10+ years | |
| | Lintels - Steel | Entire Building | 181 | LF | 7 | 10+ years | |
| | Lintels - Stone | Entire Building | 418 | LF | 7 | 10+ years | |
| | Skylite - Glass Single-Pane | Entire Building | 78 | SF | 7 | 10+ years | |
| | Windows - Decorative | Entire Building | 140 | SF | 7 | 10+ years | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 4,913 | SF | 7 | 10+ years | |
| | | | | | - | jeule | |
| Catego | ry : Electrical | | В | uilding | : Main | December | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| meraer | ncy System | | - | | | - | |
| 0 | Automatic Transfer Switch | Electrical Room | 2 | EA | 7 | 6-10 years | |
| | Security System - CCTV | Entire Building | 61.160 | SF | 5 | 1-2 years | Exterior only. Older system. |
| | Security System - Intrusion Detection | Entire Building | 61,160 | SF | 5 | 1-2 years | Device are old |
| | Exit Signs - Corridors and Stairs | Entire Building | 11 | EA | 4 | 0-1 year | Older signs, lighting dimmed. |
| | Exit Signs - Lunchroom | Entire Building | 4 | EA | 6 | 6-10 years | Chael Signs, lighting airlinea. |
| | Emergency Battery Packs - Corridors and | Entire Building | 8 | EA | 6 | 6-10 years | |
| | Stairs | Little Building | 0 | LA | 0 | 0-10 years | |
| | Emergency A/C Power - Corridors and | Entire Building | 9,506 | SF | 7 | 10+ years | |
| | Stairs | | - , | | | , | |
| | Emergency A/C Power - Lunchrooms | Entire Building | 1,886 | SF | 7 | 10+ years | |
| | Emergency A/C Power - Students Toilets | Entire Building | 1,732 | SF | 7 | 10+ years | Em Generator services the toilets |
| | Emergency Generator- Outdoor- Natural | Site - East | · 1 | EA | 6 | 6-10 years | |
| | Gas - 101 - 150 KW | | | | | | |
| Main Se | rvice | | | | | | |
| | Main Electrical Service - 2000 A 120/208/3PH | Electrical Room | 1 | EA | 6 | 10+ years | |
| | PA System | Entire Building | 61,160 | SF | 5 | 1-2 years | |
| | Independent Electrical Service for | Fire Pump Room | 1 | EA | 7 | 10+ years | |
| | emergency power | · | | | | | |
| | Independent Electrical Service for | Fire Pump Room | 1 | EA | 7 | 6-10 years | |
| | | | | | | | |



| \$?] | Schools | | | | | i i i u i i i i | 4257 N Tripp AVENUE, Chicago, IL 60641 |
|---------------|---|-----------------|----------|---------|--------|-----------------|--|
| Catego | ory : Electrical | | В | uilding | : Main | | |
| _ | | | - | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Power D | Distribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 2 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 6 | 2-5 years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 7 | 6-10 years | Missing breaker cover added |
| | Lighting and Power Panels - Above 100 A | Entire Building | 7 | EA | 7 | 10+ years | - |
| | Lighting and Power Panels - Above 100 A | Entire Building | 10 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 6 | 2-5 years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 2 | 0-1 year | Older panel with minor deterioration |
| | Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 2 | 0-1 year | Older than 40 years. |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 1 | EA | 7 | 6-10 years | - |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 1 | EA | 7 | 10+ years | |
| | Main Distribution Panels - Greater than 600 amp | Entire Building | 2 | EA | 7 | 6-10 years | |
| | | | | | | | |

2

1

ΕA

ΕA

7

6

10+ years

10+ years

Entire Building

Entire Building

| Category | 2 | Fire | Protection |
|----------|---|------|------------|
|----------|---|------|------------|

amp

amp

Main Distribution Panels - Greater than 600

Main Distribution Panels - Less than 400

| Catego | Category : Fire Protection | | | uilding | : Main | | |
|------------|--------------------------------------|-----------------|----------|---------|--------|-------------|---------------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Fire Alar | m | | | | | | |
| | Fire Alarm Panel | Entire Building | 1 | EA | 7 | 6-10 years | |
| | Fire Alarm Strobe Lights | Entire Building | 61,160 | SF | 6 | 6-10 years | |
| | Fire Alarm_System | Entire Building | 61,160 | SF | 7 | 10+ years | |
| | Fire Pump Controller | Entire Building | 1 | EA | 7 | 10+ years | |
| Pump Ro | oom Assembly Fire Pump - 25-50 hp | Fire Pump Room | 1 | EA | 4 | 1-2 years | Old motor, rusty pump body, and |
| | | | | | · |) ca. c | impeller. |
| _Sprinkler | System | | | | | | |
| | Dry Sprinkler System | Entire Building | 61,160 | SF | 6 | 6-10 years | |
| | Sprinkler Heads | Entire Building | 61,160 | SF | 2 | 2-5 years | Heads are older from 1960 |
| | Sprinkler Piping | Entire Building | 61,160 | SF | 6 | 10+ years | |



Hiram H Belding Elementary School 4257 N Tripp AVENUE, Chicago, IL 60641

| Catego | ry : Mechanical | | В | uilding | : Main | | |
|----------------|--|-------------------|----------|---------|--------|-------------|--|
| _ | W | | 0 | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Air Cond | | | | | | | |
| | Condensing Unit- Roof Mounted - Less than 5 tons | Roof | 1 | EA | 7 | 10+ years | |
| | Condensing Unit- Roof Mounted - Less than 5 tons | Roof | 1 | EA | 5 | 6-10 years | Unit mounted on curb. |
| Air Hand | ling Systems | | | | | | |
| | Fan Coil Unit- Celing Mounted - Electric | Entire Building | 1 | EA | 7 | 10+ years | |
| | Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 30001 - 45000 cfm | Mechanical Room | 1 | EA | 4 | 1-2 years | Fan motor has failed multiple times and caught fire per building enginee |
| | Air Intake | Mechanical Room | 1 | EA | 6 | 6-10 years | |
| | Auxiliaries - 45001 - 60000 cfm | Mechanical Room | 1 | EA | 4 | 1-2 years | Bypass damper actuators disconnected. One damper, one closed. |
| | Zone Dampers | Mechanical Room | 29 | EA | 4 | 0-1 year | Rusted zone Dampers |
| Boiler Sy | rstems | | | | | | |
| J | Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP | Boiler Room | 2 | EA | 6 | 10+ years | |
| | Chemical Feed System | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Combustion Dampers | Boiler Room | 2 | EA | 6 | 6-10 years | |
| | Condensate Pump | Boiler Room | 2 | EA | 6 | 6-10 years | |
| | Feed Water Pumps and Tank | Boiler Room | 1 | EA | 5 | 2-5 years | |
| | Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP | Boiler Room | 2 | EA | 6 | 10+ years | |
| | Piping - Condensate Pipe- Steel | Boiler Room | 300 | LF | 6 | 10+ years | |
| | Piping - Steam Pipe- Steel | Boiler Room | 300 | LF | 6 | 10+ years | |
| | Steam Traps | Boiler Room | 33 | EA | 6 | 10+ years | |
| -leating | Devices | | | | | | |
| 5 | Unit Heater - Gas | Basement | 1 | EA | 6 | 6-10 years | |
| | Cabinet Heaters - With Electric Coil | Basement | 2 | EA | 7 | 10+ years | |
| | PTAC - Electric Heating and Self Contained | Engineer's Office | 1 | EA | 4 | 1-2 years | Building up mold and difficult to |
| | Cooling | | | | | , | switch from hot to cold and cold to hot. |
| | Wall Heater - Electric | Entire Building | 12 | EA | 6 | 6-10 years | |
| | Wall Heater - Electric | Entire Building | 1 | EA | 2 | 0-1 year | Does not work. |
| | Radiators - Steam | Entire Building | 7 | EA | 5 | 2-5 years | Paint required. |
| | Fin Tube - Steam | Main Office | 15 | LF | 6 | 6-10 years | |
| <u>Tempera</u> | ture Control | | | | | | |
| | Electric Controls | Entire Building | 11 | SF | 7 | 10+ years | |



| | | | | | | | 4257 N Tripp AVENUE, Chicago, IL 6064 | |
|-----------|---|---|--|--|-----------------------|---|---------------------------------------|--|
| Catego | Category : Mechanical | | | uilding | : Main | | | |
| | | | | | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Pneumatic System | Entire Building | 61,160 | SF | 4 | 0-1 year | Most of the controls are inoperable. | |
| | Thermostats - Pneumatic | Entire Building | 29 | EA | 4 | 0-1 year | Most of the thermostats are | |
| | | | | | | | nonfunctional. | |
| Unit Ver | itilation | | | | | | | |
| | Unit Ventilators- Floor Mounted- Steam | Entire Building | 7 | EA | 7 | 10+ years | | |
| | Heating w/ DX Cooling Coil & w/ Self | | | | | | | |
| | Contained Compressors | | | | | | | |
| Ventilati | on | | | | | | | |
| | Exhaust Fans- Indoor - 1501 - 8000 CFM | Entire Building | 2 | EA | 5 | 6-10 years | Noisy | |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | Entire Building | 1 | EA | 6 | 6-10 years | | |
| | Exhaust Fans- Indoor - Less than 500 CFM | Entire Building | 1 | EA | 6 | 6-10 years | | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 | Entire Building | 1 | EA | 7 | 6-10 years | | |
| | CFM | Fatire Duilding | | F A | 0 | 0.40 | | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 4 | EA | 6 | 6-10 years | | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 | Entire Building | 1 | EA | 6 | 6-10 years | | |
| | CFM | Entire Duliding | I | LA | 0 | 0-10 years | | |
| | Type II Exhaust Hood- Warming Kitchen | Entire Building | 1 | EA | 6 | 6-10 years | | |
| Cotomo | n Dlumbing | | В | uilding | Main | | | |
| Catego | ry : Plumbing | | В | uilding | : Main | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | | | | | | | | |
| Hot Wat | er | | | | | | | |
| Hot Wat | er Gas Heater - 150000 - 300000 BTU/HR | Mechanical Room | 1 | EA | 3 | 2-5 years | | |
| | | Mechanical Room | 1 | EA | 3 | 2-5 years | | |
| Hot Wat | Gas Heater - 150000 - 300000 BTU/HR | | | | | - | | |
| | Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines | Entire Building | 61,160 | SF | 6 | 10+ years | | |
| | Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers | Entire Building Entire Building | 61,160 61,160 | SF SF | 6 6 | 10+ years 10+ years | | |
| | Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to | Entire Building | 61,160 | SF | 6 | 10+ years | | |
| | Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures | Entire Building Entire Building Entire Building | 61,160 61,160 61,160 | SF SF SF | 6 6 6 | 10+ years 10+ years 10+ years | | |
| | Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to | Entire Building Entire Building | 61,160 61,160 | SF SF | 6 6 | 10+ years 10+ years | | |
| | Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply | Entire Building Entire Building Entire Building | 61,160 61,160 61,160 | SF SF SF | 6 6 6 | 10+ years 10+ years 10+ years | | |
| | Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) | Entire Building Entire Building Entire Building Entire Building Entire Building | 61,160 61,160 61,160 61,160 61,160 | SF SF SF SF SF | 6 6 6 6 | 10+ years 10+ years 10+ years 10+ years | | |
| | Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply | Entire Building Entire Building Entire Building Entire Building | 61,160 61,160 61,160 61,160 | SF SF SF SF | 6 6 6 | 10+ years 10+ years 10+ years 10+ years | | |
| | Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) | Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building | 61,160 61,160 61,160 61,160 61,160 61,160 | SF SF SF SF SF SF | 6 6 6 6 | 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years | | |
| | Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping | Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building | 61,160 61,160 61,160 61,160 61,160 61,160 61,160 | SF SF SF SF SF SF SF | 6 6 6 6 6 | 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years | | |
| | Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) | Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building | 61,160 61,160 61,160 61,160 61,160 61,160 | SF SF SF SF SF SF | 6 6 6 6 | 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years | | |

Pumps



Building : Main Category : Plumbing Recommend Group Quantity UOM Rank Item - Type Location Replacement Comments Pumps - Domestic Booster Pump-Duplex 6-10 years Mechanical Room ΕA 1 6 Pumps - Sump-Simplex Mechanical Room 1 ΕA 6 6-10 years Pumps - Sump-Simplex 6-10 years Not access for photos - working Mechanical Room 1 ΕA 6 according to building engineer

| /cracking |
|-----------|
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| е |
| |
| |
| |
| |
| |
| |
| |
| |
| |



| atego | ry : Room | | R | uilding | • Main | | 4257 N Tripp AVENUE, Chicago, IL 60 | |
|-------|---------------------------------|---|----------|----------|--------|---|-------------------------------------|--|
| alego | | | | unung | | Recommend | d | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Ceiling - Plaster/Drywall | 1st flr-Rm 105 Conference Rm | 189 | SF | 6 | 10+ years | | |
| | Doors - Side-lite | 1st flr-Rm 105 Conference Rm | 32 | SF | 7 | 10+ years | | |
| | Doors - Transom Window | 1st flr-Rm 105 Conference Rm | 8 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 1st flr-Rm 105 Conference Rm | 1 | EA | 7 | 10+ years | | |
| | Floor - Tile | 1st flr-Rm 105 Conference Rm | 189 | SF | 6 | 10+ years | | |
| | Lighting - Pendent/Surface | 1st flr-Rm 105 Conference Rm | 2 | EA | 6 | 6-10 years | | |
| | Power Distribution | 1st flr-Rm 105 Conference Rm | 6 | EA | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | 1st flr-Rm 105 Conference Rm | 660 | SF | 6 | 10+ years | | |
| | Ceiling - Lay-in | Basement engineer office | 120 | SF | 6 | 10+ years | | |
| | Doors - Wood Doors inclu hw | Basement engineer office | 1 | ĒA | 7 | 10+ years | | |
| | Floor - Concrete Epoxy/ Painted | Basement engineer office | 120 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | Basement engineer office | 3 | EA | 6 | 6-10 years | | |
| | Power Distribution | Basement engineer office | 2 | EA | 7 | 10+ years | | |
| | Storage/ Closet | Basement engineer office | 44 | SF | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | Basement engineer office | 267 | SF | 6 | 10+ years | | |
| | Ceiling - Plaster/Drywall | Basement- Kitchen Manager Office | 41 | SF | 6 | 10+ years | | |
| | Centrig - Flaster/Drywan | & Storage | | 01 | 0 | TO+ years | | |
| | Floor - Concrete Epoxy/ Painted | Basement- Kitchen Manager Office | 41 | SF | 7 | 10+ years | | |
| | FIOU - CONCIELE EPOXy/ Fainled | & Storage | 41 | 36 | ' | IUT years | | |
| | Lighting - Pendent/Surface | Basement- Kitchen Manager Office | 1 | EA | 6 | 6-10 years | | |
| | Lighting - rendent/Surface | & Storage | | LA | 0 | 0-10 years | | |
| | Power Distribution | Basement- Kitchen Manager Office | 6 | EA | 7 | 10+ years | | |
| | Fower Distribution | & Storage | 0 | LA | ' | IUT years | | |
| | Storage/ Closet | Basement- Kitchen Manager Office | 216 | SF | 7 | 10+ years | | |
| | Storage/ Closet | | 210 | SF | 1 | 10+ years | | |
| | Walls Masanny | & Storage Basement- Kitchen Manager Office | 260 | SF | 6 | 10, 10, 10, 10, 10, 10, 10, 10, 10, 10, | | |
| | Walls - Masonry | | 260 | Sr | 6 | 10+ years | | |
| | AC Unit | & Storage | 4 | | 7 | 6 10 veere | | |
| | | Office 205 | 1 | EA SF | 7 | 6-10 years | | |
| | Ceiling - Plaster/Drywall | Office 205 | 196 | | 6 | 10+ years | | |
| | Doors - Side-lite | Office 205 | 30 | SF | 7 | 10+ years | | |
| | Doors - Transom Window | Office 205 | 45 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | Office 205 | 1 | EA | 7 | 10+ years | | |
| | Floor - Tile | Office 205 | 196 | SF | 6 | 10+ years | | |
| | Lighting - Pendent/Surface | Office 205 | 6 | EA | 6 | 6-10 years | | |
| | Power Distribution | Office 205 | 3 | EA | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | Office 205 | 370 | SF | 6 | 10+ years | | |
| | AC Unit | Room 208, Teacher lounge | 1 | EA | 7 | 6-10 years | | |
| | Ceiling - Plaster/Drywall | Room 208, Teacher lounge | 175 | SF | 6 | 10+ years | | |
| | Doors - Wood Doors inclu hw | Room 208, Teacher lounge | 2 | EA | 7 | 10+ years | | |
| | Floor - Tile | Room 208, Teacher lounge | 175 | SF | 6 | 10+ years | | |
| | Lighting - Pendent/Surface | Room 208, Teacher lounge | 3 | EA | 6 | 6-10 years | | |
| | Power Distribution | Room 208, Teacher lounge | 4 | EA | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | Room 208, Teacher lounge | 641 | SF | 6 | 10+ years | | |



| `atero | ategory : Room Building : Main | | | | | | 4257 N Tripp AVENUE, Chicago, IL 606 |
|-------------|---------------------------------|--|--------------|-------|-------|--------------------------|--------------------------------------|
| | | | D | unung | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| • | nem - Type | Location | Quantity | | naiin | Replacement | Comments |
| itchen | | D (1994) | | | | 4.0 | |
| | Ceiling - Plaster/Drywall | Basement NW corner | 911 | SF | 6 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | Basement NW corner | 911 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Basement NW corner | 15 | EA | 6 | 6-10 years | |
| | Serving Line | Basement NW corner | 15 | LF | 7 | 10+ years | |
| | Walls - Masonry | Basement NW corner | 1,205 | SF | 6 | 10+ years | |
| unch & | Multipurpose Room | | | | | | |
| unon a | Ceiling - Exposed | Basement - South of north stair | 1,156 | SF | 6 | 10+ years | |
| | Floor - Wood | Basement - South of north stair | 1,156 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Basement - South of north stair | 27 | EA | 6 | 6-10 years | |
| | Walls - Masonry | Basement - South of north stair | | SF | 6 | | |
| | | | 1,380 | | - | 10+ years | |
| | Ceiling - Exposed | Basement- Dining Room 2 | 1,156 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Basement- Dining Room 2 | 2 | EA | 7 | 10+ years | |
| | Floor - Wood | Basement- Dining Room 2 | 1,156 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Basement- Dining Room 2 | 12 | EA | 6 | 6-10 years | |
| | Power Distribution | Basement- Dining Room 2 | 12 | EA | 7 | 10+ years | |
| | Storage/ Closet | Basement- Dining Room 2 | 44 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Basement- Dining Room 2 | 2,177 | SF | 6 | 10+ years | |
| | Ceiling - Exposed | Basement- Overflow Lunch Rm (Girls Play Rm) | 530 | SF | 6 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | Basement- Overflow Lunch Rm (Girls Play Rm) | 530 | SF | 7 | 10+ years | Newly refinished |
| | Lighting - Pendent/Surface | Basement- Overflow Lunch Rm (Girls Play Rm) | 6 | EA | 6 | 10+ years | |
| | Walls - Masonry | Basement- Overflow Lunch Rm (Girls Play Rm) | 848 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | Basement- Overflow Lunch Rm (Girls Play Rm) | 240 | SF | 6 | 10+ years | |
| DF ID | F | | | | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Finishes | 2nd Floor | 150 | SF | 7 | 10+ years | |
| | Window AC Unit | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| echani | cal/ Service Rooms | | | | | | |
| _ 0. /0/ 11 | Janitor's Closet | 1st Floor | 6 | SF | 7 | 10+ years | |
| | Storage Room | 1st Floor | 115 | SF | 7 | 10+ years | |
| | Janitor's Closet | 2nd Floor | 43 | SF | 5 | 10+ years | Flooring needs repainting. |
| | Air Tunnel | Basement | 220 | SF | 7 | 10+ years | riconing needs repairtung. |
| | | | | SF | 7 | | |
| | Boiler Room | Basement | 1,210 200 | SF | 7 | 10+ years | |
| | Janitor's Closet | Basement | | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | Basement | 1,225 | 35 | 1 | 10+ years | |



| Catego | ry : Room | | R | uilding | : Main | | |
|----------|---|--------------------------------------|----------|---------|--------|-------------|----------|
| outogo | | | | anang | . mann | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| 0.00p | Storage Room | Basement | 1,146 | SF | 7 | 10+ years | |
| | Vaults | Basement | 150 | SF | 7 | 10+ years | |
| | | | | | | , | |
| Restroor | n | | | | | | |
| | Accessories | 110 | 54 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 110 | 54 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 110 | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 110 | 54 | SF | 6 | 10+ years | |
| | Hand Dryer | 110 | 1 | ĒA | 7 | 10+ years | |
| | Lavatory | 110 | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 110 | 1 | EA | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 110 | 150 | SF | 6 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 110 | 150 | SF | 6 | 10+ years | |
| | Water Closet | 110 | 100 | EA | 6 | 10+ years | |
| | Accessories | 1st Flr Unisex- In Main Office Suite | 63 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Fir Unisex- In Main Office Suite | 63 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st FIr Unisex- In Main Office Suite | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Flr Unisex- In Main Office Suite | 63 | SF | 6 | 10+ years | |
| | Lavatory | 1st Flr Unisex- In Main Office Suite | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Fir Unisex- In Main Office Suite | 1 | EA | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Fir Unisex- In Main Office Suite | 306 | SF | 6 | 10+ years | |
| | Walls - Flaster/Drywall Water Closet | 1st Fir Unisex- In Main Office Suite | 300 | EA | 6 | • | |
| | | | | SF | 6 7 | 10+ years | |
| | Accessories | 1st Flr Unisex- Next to 102 | 42 | | | 6-10 years | |
| | Ceiling - Lay-in | 1st Flr Unisex- Next to 102 | 42 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Flr Unisex- Next to 102 | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Flr Unisex- Next to 102 | 42 | SF | 6 | 10+ years | |
| | Floor Drain | 1st Flr Unisex- Next to 102 | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 1st Flr Unisex- Next to 102 | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 1st Flr Unisex- Next to 102 | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Flr Unisex- Next to 102 | 1 | EA | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st FIr Unisex- Next to 102 | 306 | SF | 6 | 10+ years | |
| | Water Closet | 1st FIr Unisex- Next to 102 | 1 | EA | 6 | 10+ years | |
| | Accessories | 2nd Floor Boy's Room | 313 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor Boy's Room | 313 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor Boy's Room | 2 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor Boy's Room | 313 | SF | 6 | 10+ years | |
| | Floor Drain | 2nd Floor Boy's Room | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 2nd Floor Boy's Room | 2 | EA | 7 | 6-10 years | |
| | Lavatory | 2nd Floor Boy's Room | 2 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor Boy's Room | 4 | EA | 6 | 6-10 years | |
| | Partitions | 2nd Floor Boy's Room | 2 | EA | 7 | 10+ years | |
| | Urinals | 2nd Floor Boy's Room | 5 | EA | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor Boy's Room | 868 | SF | 6 | 10+ years | |
| | Water Closet | 2nd Floor Boy's Room | 2 | EA | 7 | 10+ years | |



| Catego | ry : Room | | В | uilding | : Main | | 4257 N Tripp AVENUE, Chicago, IL 60641 |
|--------|---------------------------------|----------------------------|----------|---------|--------|-------------|--|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Accessories | 2nd Floor Girl's Room | 317 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor Girl's Room | 290 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor Girl's Room | 27 | SF | 5 | 1-2 years | Peeling paint |
| | Doors - Transom Window | 2nd Floor Girl's Room | 18 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor Girl's Room | 2 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor Girl's Room | 317 | SF | 6 | 10+ years | |
| | Floor Drain | 2nd Floor Girl's Room | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 2nd Floor Girl's Room | 1 | EA | 7 | 2-5 years | |
| | Lavatory | 2nd Floor Girl's Room | 2 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor Girl's Room | 4 | EA | 6 | 6-10 years | |
| | Partitions | 2nd Floor Girl's Room | 6 | EA | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor Girl's Room | 873 | SF | 6 | 10+ years | |
| | Water Closet | 2nd Floor Girl's Room | 6 | EA | 7 | 10+ years | |
| | Accessories | 2nd Floor Women's Staff | 37 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor Women's Staff | 27 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor Women's Staff | 10 | SF | 5 | 0-1 year | Water damage |
| | Doors - Wood Doors inclu hw | 2nd Floor Women's Staff | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor Women's Staff | 37 | SF | 6 | 10+ years | |
| | Lavatory | 2nd Floor Women's Staff | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor Women's Staff | 1 | EA | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor Women's Staff | 200 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor Women's Staff | 20 | SF | 5 | 0-1 year | Water damage |
| | Water Closet | 2nd Floor Women's Staff | 1 | EA | 7 | 10+ years | |
| | Accessories | 2nd Flr- Unisex Staff Room | 56 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | 2nd Flr- Unisex Staff Room | 56 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Flr- Unisex Staff Room | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd FIr- Unisex Staff Room | 56 | SF | 6 | 10+ years | |
| | Floor Drain | 2nd FIr- Unisex Staff Room | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 2nd FIr- Unisex Staff Room | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 2nd Flr- Unisex Staff Room | 1 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Flr- Unisex Staff Room | 1 | EA | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd FIr- Unisex Staff Room | 303 | SF | 6 | 10+ years | |
| | Water Closet | 2nd Flr- Unisex Staff Room | 1 | EA | 7 | 10+ years | |
| | Accessories | 3rd Floor | 55 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 55 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 3rd Floor | 55 | SF | 6 | 10+ years | |
| | Floor Drain | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 1 | EA | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 130 | SF | 6 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 3rd Floor | 130 | SF | 6 | 10+ years | |
| | Water Closet | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | | | | | | | |



| Catego | ry : Room | | B | uilding | : Main | | 4257 IN The AVENUE, Chicago, IL 60641 |
|--------|---------------------------------|------------------------|----------|---------|--------|-------------|---------------------------------------|
| Gulogo | | | | anang | · mann | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Accessories | Basement | 72 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Basement | 72 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Basement | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Basement | 72 | SF | 6 | 10+ years | |
| | Floor Drain | Basement | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | Basement | 1 | EA | 7 | 6-10 years | |
| | Lavatory | Basement | 1 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | Basement | 1 | EA | 5 | 0-1 year | The switch does not work |
| | Walls - Plaster/Drywall | Basement | 170 | SF | 6 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | Basement | 170 | SF | 6 | 10+ years | |
| | Water Closet | Basement | 1 | EA | 7 | 10+ years | |
| | Accessories | Basement | 72 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Basement | 72 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Basement | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Basement | 72 | SF | 6 | 10+ years | |
| | Floor Drain | Basement | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | Basement | 1 | EA | 7 | 10+ years | |
| | Lavatory | Basement | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Basement | 1 | EA | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | Basement | 170 | SF | 6 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | Basement | 170 | SF | 6 | 10+ years | |
| | Water Closet | Basement | 1 | EA | 6 | 10+ years | |
| | Accessories | Basement Girl's Room | 520 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Basement Girl's Room | 520 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Basement Girl's Room | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Basement Girl's Room | 520 | SF | 6 | 10+ years | |
| | Floor Drain | Basement Girl's Room | 2 | EA | 7 | 10+ years | |
| | Hand Dryer | Basement Girl's Room | 3 | EA | 7 | 6-10 years | |
| | Lavatory | Basement Girl's Room | 3 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | Basement Girl's Room | 6 | EA | 6 | 6-10 years | |
| | Partitions | Basement Girl's Room | 9 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Basement Girl's Room | 1,100 | SF | 6 | 10+ years | |
| | Water Closet | Basement Girl's Room | 9 | EA | 7 | 10+ years | |
| | Accessories | Boiler Room | 30 | SF | 7 | 6-10 years | |
| | Ceiling - Exposed | Boiler Room | 30 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Boiler Room | 1 | EA | 7 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | Boiler Room | 30 | SF | 5 | 2-5 years | Deteriorated. |
| | Lighting - Pendent/Surface | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Walls - Masonry | Boiler Room | 160 | SF | 6 | 10+ years | |
| | Water Closet | Boiler Room | 1 | EA | 7 | 10+ years | |
| | Accessories | Boy's Room in Basement | 450 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Boy's Room in Basement | 480 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Boy's Room in Basement | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Boy's Room in Basement | 480 | SF | 6 | 10+ years | |



| Catego | ry : Room | | B | uilding | : Main | | |
|--------|---------------------------------|------------------------|----------|---------|--------|-------------|----------|
| | | | | - | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Floor Drain | Boy's Room in Basement | 2 | EA | 7 | 10+ years | |
| | Hand Dryer | Boy's Room in Basement | 3 | EA | 7 | 6-10 years | |
| | Lavatory | Boy's Room in Basement | 3 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Boy's Room in Basement | 10 | EA | 6 | 6-10 years | |
| | Partitions | Boy's Room in Basement | 4 | EA | 7 | 10+ years | |
| | Urinals | Boy's Room in Basement | 7 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Boy's Room in Basement | 676 | SF | 6 | 10+ years | |
| | Water Closet | Boy's Room in Basement | 4 | EA | 7 | 10+ years | |
| | Accessories | In Rm 104 | 54 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | In Rm 104 | 54 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | In Rm 104 | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | In Rm 104 | 54 | SF | 6 | 10+ years | |
| | Hand Dryer | In Rm 104 | 1 | EA | 7 | 6-10 years | |
| | Lavatory | In Rm 104 | 1 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | In Rm 104 | 1 | EA | 6 | 10+ years | |
| | Walls - Plaster/Drywall | In Rm 104 | 150 | SF | 6 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | In Rm 104 | 150 | SF | 6 | 10+ years | |
| | Water Closet | In Rm 104 | 1 | EA | 7 | 10+ years | |
| | Accessories | Room 108 | 54 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Room 108 | 54 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Room 108 | 1 | EA | 7 | 10+ years | |
| | Floor - Epoxy/ Painted | Room 108 | 54 | SF | 7 | 10+ years | |
| | Lavatory | Room 108 | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Room 108 | 1 | EA | 6 | 6-10 years | |
| | Partitions | Room 108 | 1 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Room 108 | 300 | SF | 6 | 10+ years | |
| | Water Closet | Room 108 | 1 | EA | 7 | 10+ years | |

| lego | ry : Classroom | | D | uilding | | D | |
|---------|-----------------------------|-----------|----------|---------|------|--------------------------|------------------------|
| oup | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| lassroc | om #101 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 1,193 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 1,183 | SF | 6 | 6-10 years | |
| | Floor - Tile | 1st Floor | 10 | SF | 4 | 0-1 year | Cracking/peeling tiles |
| | Lighting - Pendent/Surface | 1st Floor | 14 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 35 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 182 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 2,343 | SF | 6 | 10+ years | |



| Catego | ry : Classroom | | R | uilding | • Main | | 4257 N Tripp AVENUE, Chicago, IL 6064 |
|---------|--|------------------------|------------|----------|--------|-------------|---------------------------------------|
| Jacogo | | | | anang | · man | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Teap | AC Units | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 915 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 910 | SF | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 5 | SF | 4 | 0-1 year | Broken tiles |
| | Lighting - Pendent/Surface | 1st Floor | 13 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 42 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 121 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,461 | SF | 6 | 10+ years | |
| lassroo | m #104 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 600 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 1st Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 600 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 16 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Floor | 700 | SF | 6 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | |
| lassro | m #106 (Regular Classroom) | | | | | | |
| 1000100 | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 895 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 9 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 1st Floor | 895 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 14 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 24 | | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 24 165 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,408 | SF | 6 | 10+ years | |
| laseror | m #107 (Regular Classroom) | | | | | | |
| 1400100 | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 11 | LF | 7 | 10+ years | |
| | Casework Ceiling - Plaster/Drywall | 1st Floor | 1,060 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 18 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 7 | | |
| | Floor - Wood Doors Inclu hw | 1st Floor | 2 1,060 | SF | 6 | 10+ years | |
| | | 1st Floor | | EA | | 10+ years | |
| | Lighting - Pendent/Surface Marker Board | 1st Floor 1st Floor | 14 32 | EA LF | 6 | 6-10 years | |
| | | | | LF SF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 170 | | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 2,064 | SF | 6 | 10+ years | |



Category : Classroom

| Oalcyo | ry . 01033100111 | | | unung | . Mani | Deserves | |
|----------|-----------------------------|----------------|-----------|-------|--------|--------------------------|---------------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| Group | item - Type | Location | Qualitity | | Ralik | Replacement | Comments |
| | | | | | | | |
| Classroc | om #108 (Kindergarten) | 4 . F I | | = . | _ | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 845 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 50 | SF | 5 | 0-1 year | Water damage |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 895 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 14 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 28 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 170 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,408 | SF | 6 | 10+ years | |
| Classroo | om #110 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 600 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 1st Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 600 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | ĒA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 16 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Floor | 700 | SF | 6 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | |
| Classroo | om #201 (Regular Classroom) | | | | | | |
| CIASSIOC | | | | | 7 | 0.40 | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 6 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 1,193 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 9 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 1,183 | SF | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 10 | SF | 5 | 1-2 years | Chipped tiles |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 214 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 2,346 | SF | 6 | 10+ years | |
| Classroo | om #202 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 12 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 915 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 9 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | | | | ~- | - | | |
| | Floor - Wood | 2nd Floor | 915 | SF | 6 | 10+ years | |

Building : Main



| Category : Classroom | | В | uilding | : Main | | | |
|----------------------|---|------------------------|----------|--------|------|-------------|---------------|
| | - | | | 3 | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Marker Board | 2nd Floor | 18 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 214 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,461 | SF | 6 | 10+ years | |
| | | 2.101.1001 | 1,101 | 0. | Ũ | let youro | |
| Classroo | m #203 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 11 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 1,060 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 9 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 1,060 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | ĒA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 18 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 214 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 2,064 | SF | 6 | 10+ years | |
| | | | 2,001 | 0. | Ũ | lot youro | |
| Classroo | m #204 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 8 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 615 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 615 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 13 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 24 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 45 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,054 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 2 | EA | 7 | 10+ years | |
| 01 | | | | | | | |
| Jassroo | m #205A (Special Education) AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 22 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 477 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 477 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor 2nd Floor | 477 | SF | 6 | • | |
| | | | | | | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 4 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,047 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| Classroo | m #206 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 885 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 10 | SF | 5 | 1-2 years | Peeling paint |



| Catego | ry : Classroom | | В | uilding | : Main | | ······································ |
|----------|-----------------------------|-----------|----------|---------|--------|-------------|--|
| | | | | Ŭ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Transom Window | 2nd Floor | 9 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 895 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 14 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 24 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 214 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,408 | SF | 6 | 10+ years | |
| Classroo | om #207 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 11 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 1,030 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 30 | SF | 5 | 1-2 years | Peeling paint |
| | Doors - Transom Window | 2nd Floor | 18 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 1,060 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 35 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 214 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 2,052 | SF | 6 | 10+ years | |
| Classro | om #210 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 8 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 625 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 625 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 15 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 24 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 50 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 920 | SF | 6 | 10+ years | |
| Classro | om #301 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 14 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 1,183 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 10 | SF | 5 | 0-1 year | Water damage |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 1,193 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 16 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 214 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 2,333 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 2,000 | SF | 5 | 0-1 year | Cracking |
| | | | 20 | 5 | 5 | U i yeai | Craciting |



| Category : Classroom | | | В | uilding | : Main | | |
|----------------------|--|-----------|----------|---------|--------|-------------|----------|
| J | | | | J | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | | | | | | | |
| lassroo | m #302 (Science Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 915 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 9 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 915 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 14 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 42 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 214 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,461 | SF | 6 | 10+ years | |
| lassroo | m #303 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 11 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 1.060 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 9 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 1,060 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 16 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 35 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 214 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 2,142 | SF | 6 | 10+ years | |
| lassroo | m #304 (Computer Lab) | | | | | | |
| 1455100 | Ceiling - Lay-in | 3rd Floor | 760 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 20 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 760 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 15 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 24 | LF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,050 | SF | 6 | , | |
| | Walls - Plastel/Drywall Wireless System | 3rd Floor | 1,050 | EA | 7 | 10+ years | |
| | Wileless System | 310 1001 | I | EA | / | 6-10 years | |
| lassroo | m #306 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 895 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 9 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 895 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 14 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 8 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 214 | SF | 7 | 10+ years | |



| Catego | ry : Classroom | | B | uilding | : Main | | |
|--------|---|-----------|----------|---------|--------|-------------|----------|
| | ., | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| noup | Walls - Plaster/Drywall | 3rd Floor | 1,396 | SF | 6 | 10+ years | Commente |
| | Wireless System | 3rd Floor | 1,000 | EA | 7 | 6-10 years | |
| | Wileless Oystem | | I. | LA | , | 0-10 years | |
| assroo | om #307 (Library) | | | | | | |
| | AC Units | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 8 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 1,516 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 27 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 3 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 1,521 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 24 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 8 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 214 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 2,749 | SF | 6 | 10+ years | |
| | Wireless System | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | (1000 (D. a. 1. a. 0. a. 1. a. 1.) | | | | | | |
| assroc | m #308 (Regular Classroom) | | | Ε. | 7 | 0.40 | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 895 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 895 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 14 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 214 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,408 | SF | 6 | 10+ years | |
| assroo | om #310 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 20 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 808 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 18 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 808 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 15 | ĒA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 24 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,010 | SF | 6 | 10+ years | |
| | - | | , | | | | |
| assroo | om #311 (Regular Classroom) Casework | 3rd Floor | 6 | LF | 7 | 10+ years | |
| | | 3rd Floor | | SF | | | |
| | Ceiling - Lay-in | | 101 | | 6 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 101 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 6 | EA | 6 | 6-10 years | |



| Category : Classroom | | В | uilding | : Main | | | |
|----------------------|--|-----------|----------|----------|--------|--------------------------|------------------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| | Marker Board | 3rd Floor | 12 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 365 | SF | 6 | 10+ years | |
| Catego | ry : Interior | | В | uilding | : Main | | |
| | - | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Corridor | | | | | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 2,018 | SF | 6 | 10+ years | |
| | Drinking Fountains - Single Fountain | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Floor - Tile/Sheet | 1st Floor | 1,928 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | 1st Floor | 90 | SF | 4 | 0-1 year | Broken tiles |
| | Lighting - Pendent/Surface | 1st Floor | 14 | ĒA | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Floor | 3,944 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 2,018 | SF | 6 | 10+ years | |
| | Drinking Fountains - Single Water Cooler | 2nd Floor | _,, | EA | 7 | 6-10 years | |
| | Floor - Tile/Sheet | 2nd Floor | 1,968 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | 2nd Floor | 50 | SF | 4 | 0-1 year | Peeling tiles |
| | Lighting - Pendent/Surface | 2nd Floor | 14 | EA | 6 | 6-10 years | i comiguico |
| | Walls - Plaster/Drywall | 2nd Floor | 3,948 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 2,018 | SF | 6 | 10+ years | |
| | Drinking Fountains - Double Fountain | 3rd Floor | 2,010 | EA | 7 | 6-10 years | |
| | Floor - Tile/Sheet | 3rd Floor | 2,018 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 16 | EA | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 3,932 | SF | 6 | 10+ years | |
| | Ceiling - Exposed | Basement | 2,836 | SF | 6 | 10+ years | |
| | Doors - Wood Doors include hw | Basement | 2,000 | EA | 7 | 10+ years | |
| | Drinking Fountains - Single Water Cooler | Basement | 6 | EA | 7 | 6-10 years | |
| | Floor - Concrete Epoxy/ Painted | Basement | 2,836 | SF | 7 | 10+ years | Newly refinished |
| | Lighting - Pendent/Surface | Basement | 2,830 | EA | 6 | | Newly lelinished |
| | Stairs - Concrete Stairs | | | LF | | 6-10 years | |
| | | Basement | 14 | | 7 | 10+ years | |
| | Walls - Masonry | Basement | 2,528 | SF SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | Basement | 2,120 | SF | 6 | 10+ years | |
| stairs | | | | | | | |
| | Ceiling - Plaster/Drywall | North | 802 | SF | 6 | 10+ years | |
| | Floor - Tile | North | 675 | SF | 7 | 10+ years | |
| | Handrails | North | 280 | LF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | North | 4 | EA | 6 | 6-10 years | |
| | Stairs - Tile | North | 74 | LF | 7 | 10+ years | Refurbished |
| | Walls - Plaster/Drywall | North | 1,614 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | South | 90 | SF | 6 | 10+ years | |
| | Floor - Tile | South | 675 | SF | 7 | 10+ years | Newly refinished |
| | Handrails | South | 280 | LF | 7 | 10+ years | - |
| | Lighting - Pendent/Surface | South | 6 | EA | 6 | 6-10 years | |



| Catego | ry : Interior | В | uilding | | | | |
|----------|-------------------------------|-------------------|----------|-----|------|--------------------------|------------------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| | Stairs - Tile | South | 74 | LF | 7 | 10+ years | Newly refinished |
| | Walls - Plaster/Drywall | South | 1,404 | SF | 6 | 10+ years | |
| Vertical | Conveyance | | | | | | |
| | Elevator - Hydraulic Elevator | 1st to 3rd floors | 1 | EA | 7 | 10+ years | |



| Catego | ry : Exterior | В | uilding | : Additi | on | | |
|-----------|---|-----------------------------|----------|----------|------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Intrance | | | | | | | |
| | Exterior Doors - Store Front | Door 4 - Southwest | 3 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | Door 4 - Southwest | 3 | EA | 7 | 10+ years | |
| | Ramp Handrail - Steel_Ramp Handrail | Door 4 - Southwest | 80 | LF | 7 | 10+ years | |
| | Ramps - Concrete | Door 4 - Southwest | 40 | LF | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Door 5 - Southeast | 1 | EA | 6 | 10+ years | |
| | Exterior Stairs - Concrete | Door 5 - Southeast | 4 | LF | 7 | 10+ years | |
| | Exterior Stairs - Stone | Door 5 - Southeast | 3 | LF | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Door 6 - Northeast | 1 | EA | 7 | 10+ years | |
| | Exterior Stairs - Stone | Door 6 - Northeast | 7 | LF | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Door 6.1 - First escape 1st | , 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Door 6.2 - Fire escape 2nd | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Door 6.3 - Fire escape gym | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Door 6.4 - Fire escape 3rd | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior Steer Door | Door 0.4 - File escape Sid | I | EA | 0 | 10+ years | |
| Fire Esca | аре | | | | | | |
| | Fire Escape | East Façade | 168 | LF | 7 | 10+ years | |
| | | | | | | | |
| Foundati | | | | | | | |
| | Foundation - Masonry | Entire Building | 217 | LF | 7 | 10+ years | |
| | Superstructure - Steel with Clay Tile Arch | Entire Building | 8,320 | SF | 7 | 10+ years | |
| | | | | | | | |
| ighting | Exterior Lighting Derenet or Deef Mounted | Entire Duilding | | EA | 7 | 6 10 years | |
| | Exterior Lighting - Parapet or Roof Mounted | Entire Building | 4 | EA | 7 | 6-10 years | |
| Roof Sys | stem | | | | | | |
| , | Coping - Clay Tile | Roof 1 | 26 | LF | 6 | 10+ years | |
| | Coping - Stone | Roof 1 | 160 | LF | 6 | 10+ years | |
| | Downspouts - Exterior Downspouts | Roof 1 | 60 | LF | 6 | 10+ years | |
| | Parapet - Parapet > 30" | Roof 1 | 186 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | Roof 1 | 3,121 | SF | 6 | 10+ years | |
| | Roof Structure - Steel with Clay Tile Arch | Roof 1 | 3,121 | SF | 6 | 10+ years | |
| | Coping - Stone | Roof 2 | 175 | LF | 6 | 10+ years | |
| | Downspouts - Exterior Downspouts | Roof 2 | 132 | LF | 6 | 10+ years | |
| | Parapet - Parapet > 30" | Roof 2 | 175 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | Roof 2 | 3,360 | SF | 6 | 10+ years | |
| | Roof Structure - Steel with Clay Tile Arch | Roof 2 | 3,360 | SF | 6 | 10+ years | |
| | Coping - Stone | Roof 3 | 57 | LF | 6 | 10+ years | |
| | Downspouts - Exterior Downspouts | Roof 3 | 34 | LF | 6 | 10+ years | |
| | Parapet - 16" - 30" Height | Roof 3 | 57 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | Roof 3 | 313 | SF | 6 | 10+ years | |
| | Roof Structure - Steel with Clay Tile Arch | Roof 3 | 313 | SF | 6 | 10+ years | |
| | Nooi Structure - Steel with Clay The Alth | | 313 | 3F | 0 | IUT years | |
| | | | | | | | |



| outoge. | ry : Exterior | | B | uilding | : Additi | on | |
|--------------------|--|--|---|--|----------------------------|--|---------------------|
| _ | - | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Coping - Stone | Roof 4 | 15 | LF | 6 | 10+ years | |
| | Downspouts - Exterior Downspouts | Roof 4 | 15 | LF | 6 | 10+ years | |
| | Parapet - Parapet < 16" Height | Roof 4 | 15 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | Roof 4 | 63 | SF | 6 | 10+ years | |
| | Roof Structure - Steel with Clay Tile Arch | Roof 4 | 63 | SF | 6 | 10+ years | |
| | Coping - Stone | Roof 5 | 32 | LF | 6 | 10+ years | |
| | Downspouts - Exterior Downspouts | Roof 5 | 15 | LF | 6 | 10+ years | |
| | Parapet - 16" - 30" Height | Roof 5 | 32 | LF | 6 | 10+ years | |
| | | | | SF | | | |
| | Roof - Modified Bitumen | Roof 5 | 160 | | 6 | 10+ years | |
| | Roof Structure - Steel with Clay Tile Arch | Roof 5 | 160 | SF | 6 | 10+ years | |
| Valls | | | | | | | |
| | Exterior Walls - Brick | Entire Building | 5,623 | SF | 7 | 10+ years | |
| | Exterior Walls - Stone-Cast | Entire Building | 534 | SF | 7 | 10+ years | |
| Vindows | | | | | | | |
| | Guard - Guards perforated | Entire Building | 456 | SF | 7 | 10+ years | |
| | Lintels - Steel | Entire Building | 5 | LF | 7 | 10+ years | |
| | Lintels - Stone | Entire Building | 108 | LF | 7 | 10+ years | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 990 | SF | 7 | 10+ years | |
| atego | ry : Electrical | | В | uildina | : Additi | on | |
| | | | | | | | |
| | | | | | | Recommend | |
| - | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| - | cy System | | | | | | |
| - | | Location Entire Building | Quantity 8,320 | UOM SF | Rank | | Comments Old. |
| - | cy System Security System - Intrusion Detection | Entire Building | | | | Replacement 1-2 years | |
| - | cy System Security System - Intrusion Detection Exit Signs - Auditoium | Entire Building Entire Building | 8,320 10 | SF EA | 5 | Replacement 1-2 years 6-10 years | Old. |
| - | cy System Security System - Intrusion Detection Exit Signs - Auditoium Exit Signs - Auditoium | Entire Building Entire Building Entire Building | 8,320 10 3 | SF EA EA | 5 6 4 | Replacement1-2 years6-10 years0-1 year | |
| - | cy System Security System - Intrusion Detection Exit Signs - Auditoium Exit Signs - Auditoium Exit Signs - Corridors and Stairs | Entire Building Entire Building Entire Building Entire Building | 8,320 10 3 3 | SF EA EA EA | 5 6 4 6 | Replacement1-2 years6-10 years0-1 year10+ years | Old. Poorly lit. |
| - | CY System Security System - Intrusion Detection Exit Signs - Auditoium Exit Signs - Auditoium Exit Signs - Corridors and Stairs Exit Signs - Gym | Entire Building Entire Building Entire Building Entire Building Entire Building | 8,320 10 3 3 2 | SF EA EA EA EA | 5 6 4 6 4 | Replacement1-2 years6-10 years0-1 year10+ years0-1 year | Old. |
| - | cy System Security System - Intrusion Detection Exit Signs - Auditoium Exit Signs - Auditoium Exit Signs - Corridors and Stairs | Entire Building Entire Building Entire Building Entire Building | 8,320 10 3 3 | SF EA EA EA | 5 6 4 6 | Replacement1-2 years6-10 years0-1 year10+ years | Old. Poorly lit. |
| - | Security System - Intrusion Detection Exit Signs - Auditoium Exit Signs - Auditoium Exit Signs - Corridors and Stairs Exit Signs - Gym Emergency Battery Packs - Auditoium and | Entire Building Entire Building Entire Building Entire Building Entire Building | 8,320 10 3 3 2 | SF EA EA EA EA | 5 6 4 6 4 | Replacement1-2 years6-10 years0-1 year10+ years0-1 year | Old. Poorly lit. |
| Group Emergen | Security System - Intrusion Detection Exit Signs - Auditoium Exit Signs - Auditoium Exit Signs - Corridors and Stairs Exit Signs - Gym Emergency Battery Packs - Auditoium and Aisle Lighting Emergency A/C Power - Auditoium and | Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building | 8,320 10 3 3 2 3 | SF EA EA EA EA EA | 5 6 4 6 4 6 | 1-2 years6-10 years0-1 year10+ years0-1 year6-10 years | Old. Poorly lit. |
| - | Security System - Intrusion Detection Exit Signs - Auditoium Exit Signs - Auditoium Exit Signs - Corridors and Stairs Exit Signs - Gym Emergency Battery Packs - Auditoium and Aisle Lighting Emergency A/C Power - Auditoium and Aisle Lighting | Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building | 8,320 10 3 2 3 4,305 | SF EA EA EA EA SF | 5 6 4 6 4 6 | 1-2 years6-10 years0-1 year10+ years0-1 year6-10 years10+ years10+ years | Old. Poorly lit. |
| - | Security System - Intrusion Detection Exit Signs - Auditoium Exit Signs - Auditoium Exit Signs - Corridors and Stairs Exit Signs - Gym Emergency Battery Packs - Auditoium and Aisle Lighting Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and | Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building | 8,320 10 3 3 2 3 | SF EA EA EA EA EA | 5 6 4 6 4 6 | 1-2 years6-10 years0-1 year10+ years0-1 year6-10 years | Old. Poorly lit. |
| - | Security System - Intrusion Detection Exit Signs - Auditoium Exit Signs - Auditoium Exit Signs - Corridors and Stairs Exit Signs - Gym Emergency Battery Packs - Auditoium and Aisle Lighting Emergency A/C Power - Auditoium and Aisle Lighting | Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building | 8,320 10 3 2 3 4,305 | SF EA EA EA EA SF | 5 6 4 6 4 6 | 1-2 years6-10 years0-1 year10+ years0-1 year6-10 years10+ years10+ years | Old. Poorly lit. |
| mergen | Security System - Intrusion Detection Exit Signs - Auditoium Exit Signs - Auditoium Exit Signs - Corridors and Stairs Exit Signs - Gym Emergency Battery Packs - Auditoium and Aisle Lighting Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym | Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building | 8,320 10 3 2 3 4,305 2,388 | SF EA EA EA EA SF SF | 5 6 4 6 6 6 | Replacement 1-2 years 6-10 years 0-1 year 10+ years 0-1 years 10+ years 10+ years 10+ years | Old. Poorly lit. |
| - | Security System - Intrusion Detection Exit Signs - Auditoium Exit Signs - Auditoium Exit Signs - Corridors and Stairs Exit Signs - Gym Emergency Battery Packs - Auditoium and Aisle Lighting Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym | Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building | 8,320 10 3 2 3 4,305 2,388 | SF EA EA EA EA SF SF | 5 6 4 6 6 6 | Replacement 1-2 years 6-10 years 0-1 year 10+ years 0-1 years 10+ years 10+ years 10+ years | Old. Poorly lit. |
| mergen lain Ser | Security System Security System - Intrusion Detection Exit Signs - Auditoium Exit Signs - Corridors and Stairs Exit Signs - Gym Emergency Battery Packs - Auditoium and Aisle Lighting Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym | Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building | 8,320 10 3 2 3 4,305 2,388 3,132 | SF EA EA EA EA SF SF SF | 5 6 4 6 6 6 | Replacement 1-2 years 6-10 years 0-1 year 10+ years 0-1 years 10+ years 10+ years 10+ years 10+ years | Old. Poorly lit. |
| mergen Iain Ser | Security System Security System - Intrusion Detection Exit Signs - Auditoium Exit Signs - Corridors and Stairs Exit Signs - Gym Emergency Battery Packs - Auditoium and Aisle Lighting Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym | Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building | 8,320 10 3 2 3 4,305 2,388 3,132 | SF EA EA EA EA SF SF SF | 5 6 4 6 6 6 | Replacement 1-2 years 6-10 years 0-1 year 10+ years 0-1 years 10+ years 10+ years 10+ years 10+ years | Old. Poorly lit. |



Category : Electrical

| | | | | | | Recommend | |
|-----------------------|--|---|--|--|--|---|---|
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting and Power Panels - 100 A | Auditorium | 1 | EA | 2 | 0-1 year | Older than 40 years. |
| | Lighting and Power Panels - Above 100 A | Auditorium | 1 | EA | 7 | 10+ years | 225A |
| | | | | | | | |
| atego | ory : Fire Protection | | В | uilding | : Additio | | |
| | | | | | | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| ire Ala | | | | | | | |
| | Fire Alarm Strobe Lights | Entire Building | 8,320 | SF | 6 | 6-10 years | |
| | Fire Alarm_System | Entire Building | 8,320 | SF | 7 | 6-10 years | |
| | | | | | | | |
| prinkle | r System | | | | | | |
| • | Sprinkler Heads | Entire Building | 8,320 | SF | 2 | 2-5 years | Older than 40 years. |
| | Sprinkler Piping | Entire Building | 8,320 | SF | 6 | 10+ years | |
| | | | 0,020 | 0. | Ŭ | 101 youro | |
| atego | ory : Mechanical | | В | uildina | : Additie | on | |
| | ., | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | | | | | | | |
| ir Conc | | | | | | | |
| ir Cono | 0 | Roof | 1 | FΔ | 5 | 10+ vears | Not securely mounted to roof cu |
| ir Conc | Condensing Unit- Roof Mounted - 5-10 | Roof | 1 | EA | 5 | 10+ years | Not securely mounted to roof cu |
| ir Conc | Condensing Unit- Roof Mounted - 5-10 tons | | 1 | | | · | Not securely mounted to roof cu |
| <u>air Conc</u> | Condensing Unit- Roof Mounted - 5-10 tons Condensing Unit- Roof Mounted - Less | Roof Roof | 1 | EA EA | 5 5 | 10+ years 10+ years | Not securely mounted to roof cu |
| ir Conc | Condensing Unit- Roof Mounted - 5-10 tons | | 1 | | | · | Not securely mounted to roof cu |
| | Condensing Unit- Roof Mounted - 5-10 tons Condensing Unit- Roof Mounted - Less than 5 tons | | 1 | | | · | Not securely mounted to roof cu |
| | Condensing Unit- Roof Mounted - 5-10 tons Condensing Unit- Roof Mounted - Less than 5 tons | Roof | 1 | EA | 5 | 10+ years | Not securely mounted to roof cu |
| | Condensing Unit- Roof Mounted - 5-10 tons Condensing Unit- Roof Mounted - Less than 5 tons Systems Fan Coil Unit- Celing Mounted - Electric | Roof Entire Building | 1 | EA | 5 | 10+ years 10+ years | |
| | Condensing Unit- Roof Mounted - 5-10 tons Condensing Unit- Roof Mounted - Less than 5 tons <u>Aling Systems</u> Fan Coil Unit- Celing Mounted - Electric Fan Coil Unit- Celing Mounted - Electric | Roof Entire Building Entire Building | 1 | EA EA EA | 5 7 6 | 10+ years 10+ years 10+ years 10+ years | Above drop ceiling. |
| | Condensing Unit- Roof Mounted - 5-10 tons Condensing Unit- Roof Mounted - Less than 5 tons Summer Systems Fan Coil Unit- Celing Mounted - Electric Fan Coil Unit- Celing Mounted - Electric Air Handling Unit- Built Up-Multi Zone- | Roof Entire Building | 1 1 1 1 1 1 | EA | 5 | 10+ years 10+ years | |
| | Condensing Unit- Roof Mounted - 5-10 tons Condensing Unit- Roof Mounted - Less than 5 tons Jling Systems Fan Coil Unit- Celing Mounted - Electric Fan Coil Unit- Celing Mounted - Electric Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm | Roof Entire Building Entire Building Mechanical Room | 1 1 1 1 1 1 1 | EA EA EA EA | 5 7 6 4 | 10+ years 10+ years 10+ years 1-2 years | Above drop ceiling. |
| | Condensing Unit- Roof Mounted - 5-10 tons Condensing Unit- Roof Mounted - Less than 5 tons Sean Coil Unit- Celing Mounted - Electric Fan Coil Unit- Celing Mounted - Electric Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm Air Intake | Roof Entire Building Entire Building Mechanical Room Mechanical Room | 1 1 1 1 1 1 1 | EA EA EA EA EA | 5 7 6 4 5 | 10+ years 10+ years 10+ years 1-2 years 6-10 years | Above drop ceiling. Rusted. |
| | Condensing Unit- Roof Mounted - 5-10 tons Condensing Unit- Roof Mounted - Less than 5 tons Jling Systems Fan Coil Unit- Celing Mounted - Electric Fan Coil Unit- Celing Mounted - Electric Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm | Roof Entire Building Entire Building Mechanical Room | 1 1 1 1 1 1 1 1 | EA EA EA EA | 5 7 6 4 | 10+ years 10+ years 10+ years 1-2 years | Above drop ceiling. Rusted. Plenum plaster crumbling, paint |
| | Condensing Unit- Roof Mounted - 5-10 tons Condensing Unit- Roof Mounted - Less than 5 tons | Roof Entire Building Entire Building Mechanical Room Mechanical Room | 1 1 1 1 1 1 1 1 | EA EA EA EA EA EA | 5 7 6 4 5 4 | 10+ years 10+ years 10+ years 1-2 years 6-10 years 1-2 years | Above drop ceiling. Rusted. Plenum plaster crumbling, paint peeling. |
| | Condensing Unit- Roof Mounted - 5-10 tons Condensing Unit- Roof Mounted - Less than 5 tons Sean Coil Unit- Celing Mounted - Electric Fan Coil Unit- Celing Mounted - Electric Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm Air Intake | Roof Entire Building Entire Building Mechanical Room Mechanical Room | 1 1 1 1 1 1 1 3 | EA EA EA EA EA | 5 7 6 4 5 | 10+ years 10+ years 10+ years 1-2 years 6-10 years | Above drop ceiling. Rusted. Plenum plaster crumbling, paint |
| ir Hand | Condensing Unit- Roof Mounted - 5-10 tons Condensing Unit- Roof Mounted - Less than 5 tons dling Systems Fan Coil Unit- Celing Mounted - Electric Fan Coil Unit- Celing Mounted - Electric Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Zone Dampers | Roof Entire Building Entire Building Mechanical Room Mechanical Room | 1 1 1 1 1 1 1 1 | EA EA EA EA EA EA | 5 7 6 4 5 4 | 10+ years 10+ years 10+ years 1-2 years 6-10 years 1-2 years | Above drop ceiling. Rusted. Plenum plaster crumbling, paint peeling. |
| ir Hand | Condensing Unit- Roof Mounted - 5-10 tons Condensing Unit- Roof Mounted - Less than 5 tons Source Steems Fan Coil Unit- Celing Mounted - Electric Fan Coil Unit- Celing Mounted - Electric Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Zone Dampers | Roof Entire Building Entire Building Mechanical Room Mechanical Room Mechanical Room | 1 1 1 1 1 1 3 | EA EA EA EA EA EA | 5 7 6 4 5 4 4 4 | 10+ years 10+ years 10+ years 1-2 years 6-10 years 1-2 years 0-1 year | Above drop ceiling. Rusted. Plenum plaster crumbling, paint peeling. |
| ir Hand | Condensing Unit- Roof Mounted - 5-10 tons Condensing Unit- Roof Mounted - Less than 5 tons Source Steam Coil Unit- Celing Mounted - Electric Fan Coil Unit- Celing Mounted - Electric Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Zone Dampers ystems Condensate Pump | Roof Entire Building Entire Building Mechanical Room Mechanical Room Mechanical Room Mechanical Room | 1 1 1 1 1 1 3 3 | EA EA EA EA EA EA | 5 7 6 4 5 4 4 4 | 10+ years 10+ years 10+ years 1-2 years 6-10 years 1-2 years 0-1 year 6-10 years | Above drop ceiling. Rusted. Plenum plaster crumbling, paint peeling. |
| ir Hand | Condensing Unit- Roof Mounted - 5-10 tons Condensing Unit- Roof Mounted - Less than 5 tons | Roof Entire Building Entire Building Mechanical Room Mechanical Room Mechanical Room Mechanical Room | 1 1 1 1 1 1 3 3 | EA EA EA EA EA EA EA LF | 5 7 6 4 5 4 4 4 6 6 | 10+ years 10+ years 10+ years 1-2 years 6-10 years 1-2 years 0-1 year 6-10 years 10+ years | Above drop ceiling. Rusted. Plenum plaster crumbling, paint peeling. |
| ir Hand | Condensing Unit- Roof Mounted - 5-10 tons Condensing Unit- Roof Mounted - Less than 5 tons | Roof Entire Building Entire Building Mechanical Room Mechanical Room Mechanical Room Mechanical Room | 1 1 1 1 1 1 1 3 3 | EA EA EA EA EA EA LF LF | 5 7 6 4 5 4 4 4 6 6 6 6 | 10+ years 10+ years 10+ years 1-2 years 6-10 years 1-2 years 0-1 year 6-10 years 10+ years 10+ years | Above drop ceiling. Rusted. Plenum plaster crumbling, paint peeling. Manually controlled. |
| ir Hand | Condensing Unit- Roof Mounted - 5-10 tons Condensing Unit- Roof Mounted - Less than 5 tons | Roof Entire Building Entire Building Mechanical Room Mechanical Room Mechanical Room Mechanical Room | 1 1 1 1 1 1 3 3 | EA EA EA EA EA EA EA LF | 5 7 6 4 5 4 4 4 6 6 | 10+ years 10+ years 10+ years 1-2 years 6-10 years 1-2 years 0-1 year 6-10 years 10+ years | Above drop ceiling. Rusted. Plenum plaster crumbling, paint peeling. |
| ir Hand | Condensing Unit- Roof Mounted - 5-10 tons Condensing Unit- Roof Mounted - Less than 5 tons | Roof Entire Building Entire Building Mechanical Room Mechanical Room Mechanical Room Mechanical Room | 1 1 1 1 1 1 1 3 3 | EA EA EA EA EA EA LF LF | 5 7 6 4 5 4 4 4 6 6 6 6 | 10+ years 10+ years 10+ years 1-2 years 6-10 years 1-2 years 0-1 year 6-10 years 10+ years 10+ years | Above drop ceiling. Rusted. Plenum plaster crumbling, paint peeling. Manually controlled. |
| oir Hand Boiler St | Condensing Unit- Roof Mounted - 5-10 tons Condensing Unit- Roof Mounted - Less than 5 tons Search Coil Unit- Celing Mounted - Electric Fan Coil Unit- Celing Mounted - Electric Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Zone Dampers ystems Condensate Pump Piping - Condensate Pipe- Steel Piping - Steam Pipe- Steel Steam Traps | Roof Entire Building Entire Building Mechanical Room Mechanical Room Mechanical Room Mechanical Room Entire Building Entire Building Entire Building Entire Building Entire Building | 1 1 1 1 1 1 1 1 3 3 1 100 100 7 | EA EA EA EA EA EA LF LF EA | 5 7 6 4 5 4 4 4 6 6 6 3 | 10+ years 10+ years 10+ years 1-2 years 6-10 years 1-2 years 0-1 year 6-10 years 10+ years 10+ years 10+ years 10+ years | Above drop ceiling. Rusted. Plenum plaster crumbling, paint peeling. Manually controlled. |
| oir Hand Boiler St | Condensing Unit- Roof Mounted - 5-10 tons Condensing Unit- Roof Mounted - Less than 5 tons | Roof Entire Building Entire Building Mechanical Room Mechanical Room Mechanical Room Mechanical Room | 1 1 1 1 1 1 1 3 3 | EA EA EA EA EA EA LF LF | 5 7 6 4 5 4 4 4 6 6 6 6 | 10+ years 10+ years 10+ years 1-2 years 6-10 years 1-2 years 0-1 year 6-10 years 10+ years 10+ years | Above drop ceiling. Rusted. Plenum plaster crumbling, paint peeling. Manually controlled. |

Building : Addition



6-10 years

4257 N Tripp AVENUE, Chicago, IL 60641 **Building : Addition Category : Mechanical** Recommend Group Item - Type Replacement Location Quantity UOM Rank Comments Entire Building Thermostats - Pneumatic 3 ΕA 4 0-1 year Most thermostats are not functioning. Ventilation 6-10 years Exhaust Fans- Indoor - 500 - 1500 CFM Roof 1 ΕA 7 6-10 years Exhaust Fans- Indoor - 500 - 1500 CFM Roof ΕA 6 1 Exhaust Fans- Roof Mounted - 1501 - 8000 ΕA 6-10 years Roof 1 6 CFM

1

ΕA

6

Building : Addition

Building : Addition

Category : Plumbing

CFM

Exhaust Fans- Roof Mounted - 500 - 1500

Roof

| Galogo | 'y i i annonig | | | ananig | . / | | |
|--------|-----------------|-----------------|----------|--------|------|--------------------------|----------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| Piping | | | | | | | |
| | Sanitary Piping | Entire Building | 8,320 | SF | 6 | 10+ years | |
| | Storm Piping | Entire Building | 8,320 | SF | 6 | 10+ years | |
| | Vent Piping | Entire Building | 8,320 | SF | 6 | 10+ years | |

Category : Room

| Sroup | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|----------|---------------------------------|------------------|----------|-----|------|--------------------------|---------------------------------|
| Group | | Location | Quantity | | nank | Replacement | Comments |
| Administ | rative Suites/Offices | | | | | | |
| | Ceiling - Exposed | 009 Staff Lounge | 695 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 009 Staff Lounge | 1 | EA | 7 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | 009 Staff Lounge | 695 | SF | 5 | 10+ years | No cracks, the epoxy is peeling |
| | Lighting - Pendent/Surface | 009 Staff Lounge | 3 | EA | 6 | 6-10 years | |
| | Power Distribution | 009 Staff Lounge | 4 | EA | 7 | 10+ years | |
| | Walls - Masonry | 009 Staff Lounge | 1,200 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 111 Balcony | 273 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 111 Balcony | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 111 Balcony | 273 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 111 Balcony | 1 | EA | 6 | 6-10 years | |
| | Power Distribution | 111 Balcony | 2 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 111 Balcony | 520 | SF | 6 | 10+ years | |
| uditoriu | m & Theater | | | | | | |
| | Balcony Seating | Basement | 55 | EA | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | Basement | 4,305 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Basement | 7 | EA | 7 | 10+ years | |
| | Floor - Wood | Basement | 4,305 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Basement | 32 | EA | 6 | 6-10 years | |
| | Lighting - Wall Mounted | Basement | 10 | EA | 6 | 6-10 years | |
| | Main Floor Seating | Basement | 344 | EA | 7 | 10+ years | |



| ALL A | | | | | | | 4257 N Tripp AVENUE, Chicago, IL 60641 |
|----------|--------------------------------------|-----------------|----------|---------|----------|-------------|--|
| Catego | ry : Room | | В | uilding | : Additi | | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Sound System | Basement | 1 | EA | 7 | 6-10 years | |
| | Stage | Basement | 1,091 | SF | 7 | 10+ years | |
| | Stage Curtain | Basement | 4 | EA | 7 | 10+ years | |
| | Stage Lift | Basement | 1 | EA | 7 | 10+ years | |
| | Stage Lighting System | Basement | 1 | EA | 7 | 6-10 years | |
| | Stage-Stairs - Wood | Basement | 10 | LF | 6 | 10+ years | |
| | Stairs - Asphalt | Basement | 44 | LF | 7 | 10+ years | |
| | Storage/ Closet | Basement | 408 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Basement | 6,011 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | Basement | 100 | SF | 5 | 0-1 year | Water damage |
| Gymnas | a | | | | | | |
| | Ceiling - Plaster/Drywall | 2nd Floor (211) | 3,132 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor (211) | 24 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor (211) | 2 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor (211) | 3,132 | SF | 6 | 10+ years | |
| | Lighting - Metal Halide/Sodium Vapor | 2nd Floor (211) | 8 | EA | 6 | 6-10 years | |
| | Scoreboards | 2nd Floor (211) | 1 | EA | 7 | 6-10 years | |
| | Sound System | 2nd Floor (211) | 1 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor (211) | 4,065 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor (211) | 20 | SF | 5 | 1-2 years | Water damage |
| Mechani | cal/ Service Rooms | | | | | | |
| | Air Intake Plenums | Basement | 135 | SF | 5 | 10+ years | |
| | Auditorium Plenums | Basement | 2,677 | SF | 7 | 10+ years | |
| Catego | ry : Classroom | | В | uilding | : Additi | on | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Classroo | m #012 (Special Education) | | | | | | |
| | Ceiling - Plaster/Drywall | Basement | 422 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Basement | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | Basement | 422 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Basement | 6 | EA | 6 | 6-10 years | |
| | Marker Board | Basement | 8 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | Basement | 400 | SF | 6 | 10+ years | |
| | Walls - Masonry | Basement | 434 | SF | 6 | 10+ years | |
| Classroo | m #014 (Special Education) | | | | | | |
| | AC Units | Basement | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Basement | 702 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Basement | 2 | EA | 7 | 10+ years | |
| | Floor - Carpet | Basement | 702 | SF | 6 | 6-10 years | |
| | · | | | | | - | |



| Catego | ry : Classroom | | В | uilding | : Additi | on | |
|---------|-----------------------------|-----------|----------|---------|----------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Pendent/Surface | Basement | 8 | EA | 6 | 6-10 years | |
| | Marker Board | Basement | 12 | LF | 7 | 6-10 years | |
| | Walls - Masonry | Basement | 1,046 | SF | 6 | 10+ years | |
| | · | | | | | · | |
| lassroc | m #109 (Kindergarten) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 7 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 1,104 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 18 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | ĒA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 1,104 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 14 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 28 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 136 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 2,079 | SF | 6 | 10+ years | |
| | Work Sink | 1st Floor | 2,079 | EA | 7 | 10+ years | |
| | WORK SINK | IST FIOOI | 1 | EA | 1 | 10+ years | |
| lassroc | m #112 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 875 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 1st Floor | 875 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 14 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 38 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 184 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,163 | SF | 6 | , | |
| | waiis - Plastel/Drywaii | | 1,103 | Эг | 0 | 10+ years | |
| lassroc | m #209 (Science) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 7 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 1,104 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 18 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 1,104 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 40 | | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 214 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 2,079 | SF | 6 | 10+ years | |
| | Walls - Flastel/Drywall | | 2,079 | эг | 0 | 10+ years | |
| lassroc | om #212 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 875 | SF | 6 | 10+ years | |



| | Schools | | | | | | 4257 N Tripp AVENUE, Chicago, IL 6064 |
|----------|-----------------------------|-----------|----------|---------|----------|-------------|---------------------------------------|
| Catego | ry : Classroom | | В | uilding | : Additi | on | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Transom Window | 2nd Floor | 9 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 875 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 14 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 24 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 214 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,408 | SF | 6 | 10+ years | |
| lassroo | om #309 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 14 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 1,104 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 18 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | ĒA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 1,104 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 16 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 22 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 214 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 2,079 | SF | 6 | 10+ years | |
| | - | | | | | - | |
| lassroc | om #312 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 875 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 9 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 875 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 14 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 18 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 214 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,408 | SF | 6 | 10+ years | |
| atego | ry : Interior | | В | uilding | : Additi | on | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Corridor | | | | | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 300 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 1st Floor | 300 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | 1st Floor | 20 | SF | 4 | 1-2 years | Broken tiles |
| | Lighting - Pendent/Surface | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Floor | 550 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 597 | SE | 6 | | |

Ceiling - Plaster/Drywall

Lighting - Pendent/Surface

Floor - Tile/Sheet

Campus Name: Belding

2nd Floor

2nd Floor

2nd Floor

SF

SF

ΕA

597

597

2

6

7

6

10+ years

10+ years

6-10 years



| Catego | ry : Interior | | В | uilding | : Additi | on | |
|--------|---------------------------------|-----------|----------|---------|----------|-------------|------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Walls - Plaster/Drywall | 2nd Floor | 1,245 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 597 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 3rd Floor | 597 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 2 | EA | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,245 | SF | 6 | 10+ years | |
| | Ceiling - Exposed | Basement | 300 | SF | 6 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | Basement | 300 | SF | 7 | 10+ years | Newly refinished |
| | Lighting - Pendent/Surface | Basement | 5 | EA | 6 | 6-10 years | |
| | Walls - Masonry | Basement | 406 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | Basement | 502 | SF | 6 | 10+ years | |



| Categor | y : Site | В | uilding | : Site | | | |
|-------------|---|-------------|----------|--------|--------|-------------|------------------------------|
| | Have Type | Location | Quentitu | | Denk | Recommend | Commonto |
| - | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| thletic | Surface - Asphalt | South | 13,937 | SF | 6 | 10+ years | |
| | Lighting | South | 13,937 | EA | 6 7 | 6-10 years | |
| | Surface - Synthetic including exc & retention | South | 17,301 | SF | 7 | 10+ years | |
| | Surface - Synthetic including exc & retention | South | 17,301 | ЗГ | 1 | 10+ years | |
| Civil/Drain | nage | | | | | | |
| | Civil/ Drainage - Catch Basin | Entire Site | 4 | EA | 7 | 10+ years | |
| | Civil/ Drainage - Site Manhole | Entire Site | 8 | EA | 7 | 10+ years | |
| | | | | | | | |
| encing | Fencing - Chain Link | Entire Site | 64 | LF | 6 | 10+ years | |
| | Fencing - New Standard Ornamental | Entire Site | 1,273 | LF | 6 | 10+ years | |
| | | | ., | | Ū | let yeare | |
| andscap | | | | | | | |
| | Benches | Entire Site | 17 | EA | 7 | 10+ years | |
| | Landscape - Crushed Stone | Entire Site | 800 | SF | 6 | 10+ years | |
| | Landscape - Grass | Entire Site | 2,340 | SF | 6 | 10+ years | |
| | Landscape - Hardscape- Concrete | Entire Site | 820 | SF | 6 | 10+ years | |
| | Landscape - Mulch | Entire Site | 6,800 | SF | 6 | 6-10 years | |
| | Parkway trees | Entire Site | 29 | EA | 6 | 10+ years | |
| | Planting Beds/ Area | Entire Site | 9,384 | SF | 6 | 10+ years | |
| | Play Area - Hardscape- Asphalt | Entire Site | 14,564 | SF | 6 | 10+ years | |
| | Trash Receptacles | Entire Site | 2 | EA | 7 | 10+ years | |
| Parking L | ot | | | | | | |
| | Surface - Concrete | South | 600 | SF | 6 | 10+ years | |
| | Trash Enclosure - Chain Links | South | 737 | SF | 7 | 10+ years | |
| laygrour | od | | | | | | |
| aygrout | Equipment - Pre K 3-5 | South | 1 | EA | 7 | 10+ years | |
| | Equipment - School Age 5-12 | South | 1 | EA | 7 | 10+ years | |
| | Surface - Poured Surface | South | 5,175 | SF | 7 | 10+ years | |
| | | | | | | | |
| idewalks | s Sidewalks - Internal Walks | Entire Site | 236 | LF | 7 | 10+ years | |
| | Sidewalks - Internal Walks | Entire Site | 230 | LF | 4 | 0-1 year | Cracking and uneven surface |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 14,315 | SF | 7 | 10+ years | Cracking and uneven suitable |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 14,315 | SF | 4 | 0-1 year | Cracking and uneven surface |
| | Oldewalks - I Chillerel Oldewalks | | 20 | 36 | 4 | 0-i yeai | Cracking and uneven suitable |
| Signage | | | | | | | |



| Catego | Category : Site | | | | : Site | | | |
|--------|--|----------|----------|-----|--------|--------------------------|----------|--|
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments | |
| | Flag Pole - Flag Pole | North | 1 | EA | 7 | 10+ years | | |
| | Marquee - Free Standing Back Lighted | North | 1 | EA | 6 | 10+ years | | |
| | Monument - Building Mounted Cut Letter | North | 2 | EA | 7 | 10+ years | | |

Sign

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

| | | | Room | Floor Plan Room | Area | Glazed Window | Operable Window | Window | Smart- |
|---------------------|-------------------|---------------|--------|--------------------|-------|------------------|--------------------|--------|--------|
| Current Usage | Intended Usage | Room Location | Number | Number | (SF) | Area | Area | Stop | Board |
| Building : Main | | | | | 1 | I | | I | 1 |
| Computer Lab | Computer Lab | 3rd Floor | 304 | | 760 | 96 | 48 | | Y |
| Kindergarten | Kindergarten | 1st Floor | 108 | 106 | 895 | 176 | 88 | N | Y |
| Library | Regular Classroom | 3rd Floor | 307 | 305 | 1,521 | 240 | 18 | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 101 | 101 | 1,193 | 150 | 75 | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 102 | 102 | 915 | 176 | 88 | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 104 | NA | 600 | 45 | 15 | | |
| Regular Classroom | Regular Classroom | 1st Floor | 106 | 104 | 895 | 176 | 88 | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 107 | 105 | 1,060 | 180 | 90 | N | Ν |
| Regular Classroom | Regular Classroom | 1st Floor | 110 | NA | 600 | 45 | 15 | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 201 | 201 | 1,193 | 150 | 75 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 202 | 202 | 915 | 176 | 88 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 203 | 203 | 1,060 | 180 | 90 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 204 | | 615 | 96 | 48 | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 206 | 204 | 895 | 176 | 88 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 207 | 205 | 1,060 | 180 | 90 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 210 | | 625 | 96 | 48 | | |
| Regular Classroom | Regular Classroom | 3rd Floor | 301 | 301 | 1,193 | 150 | 75 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 303 | 303 | 1,060 | 180 | 90 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 306 | 304 | 895 | 176 | 88 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 308 | 306 | 895 | 176 | 88 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 310 | | 808 | 96 | 48 | | |
| Regular Classroom | Regular Classroom | 3rd Floor | 311 | | 101 | 0 | 0 | | |
| Science Classroom | Regular Classroom | 3rd Floor | 302 | 302 | 915 | 176 | 88 | N | N |
| Special Education | Regular Classroom | 2nd Floor | 205A | 200 | 477 | 120 | 60 | N | N |
| Building : Addition | | | | | | | | | |
| Kindergarten | Kindergarten | 1st Floor | 109 | 107 | 1,104 | 180 | 90 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 112 | 108 | 875 | 176 | 88 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 212 | 208 | 875 | 176 | 88 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 309 | 307 | 1,104 | 180 | 90 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 312 | 308 | 875 | 176 | 88 | N | Ň |
| Science | Science | 2nd Floor | 209 | 207 | 1,104 | 180 | 90 | N | Y |
| Special Education | Special Education | Basement | 012 | NA | 422 | 20 | 6 | N | Ň |
| Special Education | Special Education | Basement | 014 | NA | 702 | 56 | 28 | N | N |